

ASBESTOS MANAGEMENT PLAN



at

Ben Furlong Education Center

Prepared for:

Kyrene School District No. 28

VOLUME I OF II

**FM GROUP INC
FM Project 08-202**

July 2008

ASBESTOS MANAGEMENT PLAN

Ben Furlong Education Center

July 2008

FM GROUP INC

FM Project 08-202

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY	1-1
2	INSPECTION REPORT.....	2-1
3	DESIGNATED PERSON IDENTIFICATION	3-1
4	RESPONSE ACTION	4-1
5	ACCREDITATION STATEMENTS	5-1
6	REMAINING ACBM.....	6-1
7	O&M PROGRAM.....	7-1
8	INITIAL NOTIFICATIONS.....	8-1
9	COST ESTIMATION	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON	10-1
11	ANNUAL NOTIFICATIONS	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT	12-1

APPENDIX A: ONGOING RECORDKEEPING

SECTION 1

GENERAL INVENTORY

General Inventory
763.93(e)(1)

Date: JULY 30, 2008

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: BEN FURLONG EDUCATION CENTER

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
A	N/A	X	X
B	N/A	X	X
C	N/A	X	X
D	N/A	X	X
E	N/A	X	X
F	N/A	X	X
G	N/A	X	X
I	N/A	X	X
K	N/A	X	X
L	N/A	X	X
M	N/A	X	X
R	N/A	X	X
T	N/A	X	X
U	N/A	X	X

Asbestos Management Plan
Ben Furlong Education Center, KSD
FM Project 08-202

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
W	N/A	X	X
CANOPY	N/A	X	X
RESIDENCE	N/A	X	X
STORAGE H	N/A	X	X
STORAGE J	N/A	X	X
STORAGE O	N/A	X	X
STORAGE P	N/A	X	X

SECTION 2

INSPECTION REPORT

INSPECTION REPORT

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:

Report of Findings
Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center

Prepared by: FM GROUP INC
Project No.: 08-202
Date: July 2008

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28
8700 South Kyrene Road
Tempe, Arizona 85284-2197

REPORT OF FINDINGS
(Abridged Version)



Comprehensive AHERA Asbestos Inspection

at

Ben Furlong Education Center

Prepared for:

Kyrene School District No. 28

FM GROUP INC
FM Project 08-202

July 2008

TABLE OF CONTENTS

Report of Findings
Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center
Kyrene School District No. 28

FM GROUP Project 08-202

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u>	1
1.1 Summary	1
1.2 Identified Asbestos-Containing Materials	1
1.3 Asbestos-Containing Building Materials (Table C)	3
1.4 ACBM/Location Plans	4
1.5 Critical Situations	5
1.6 Friable Asbestos-Containing Building Materials	5
1.7 Material Assessments	5
1.8 Recommendations	5
1.9 Qualifications of the Report.....	5
2.0 <u>PROJECT INFORMATION</u>	6
2.1 Background.....	6
2.2 Description of Construction	6
2.2.1 Buildings A, B, C, D, E, F, G, I, T, W and Residence	6
2.2.2 Buildings K, L and Storage H	7
2.2.3 Buildings M, U, Storage J and O	7
2.2.4 Building R.....	8
2.2.5 Canopy.....	8
2.2.6 Storage P	8
2.3 Building Materials/Systems List (Table A).....	10
2.3.1 Building A	11
2.3.2 Building B	52
2.3.3 Building C	58
2.3.4 Building D.....	60
2.3.5 Building E	65
2.3.6 Building F	69
2.3.7 Building G.....	71
2.3.8 Building I	73
2.3.9 Building K.....	75
2.3.10 Building L	78
2.3.11 Building M.....	80
2.3.12 Building R.....	81
2.3.13 Building T	82
2.3.14 Building U.....	101
2.3.15 Building W.....	102
2.3.16 Canopy.....	114
2.3.17 Residence	115
2.3.18 Storage H.....	119

<u>Section</u>	<u>Page</u>
2.3.19 Storage J.....	120
2.3.20 Storage O.....	121
2.3.21 Storage P.....	122
2.4 AHERA Inspection Procedures and Protocols.....	123
2.4.1 Inspection Procedures and Protocols.....	123
2.4.2 FM GROUP INC Inspection SOP.....	123
2.5 Visual Inspection.....	123
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B)..	124
2.6.1 Building A.....	125
2.6.2 Building B.....	127
2.6.3 Building C.....	129
2.6.4 Building D.....	130
2.6.5 Building E.....	132
2.6.6 Building F.....	134
2.6.7 Building G.....	135
2.6.8 Building I.....	136
2.6.9 Building K.....	137
2.6.10 Building L.....	138
2.6.11 Building M.....	139
2.6.12 Building R.....	140
2.6.13 Building T.....	141
2.6.14 Building U.....	143
2.6.15 Building W.....	144
2.6.16 Canopy.....	146
2.6.17 Residence.....	147
2.6.18 Storage H.....	148
2.6.19 Storage J.....	149
2.6.20 Storage O.....	150
2.6.21 Storage P.....	151
2.7 Physical Assessments.....	152
2.8 Sample Collection.....	152
2.9 Material Bulk Sample Analysis.....	153

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none"> • Chain-of-Custody • Laboratory Analysis
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the 21 buildings comprising the Ben Furlong Education Center (BFEC) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of June 23, 2008 through June 30, 2008. A total of 151 bulk-material samples were collected from 450 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Four Hundred one building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos-Containing Building Materials

The identified ACBM within the 21 buildings at BFEC are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

Asbestos Material-Bulk Samples Collected

Building	No. of Samples	No. HA	No. Assumed	Total No. ACM
A	30	55	45	45
B	18	44	38	38
C	6	25	23	23
D	15	33	28	28
E	12	29	25	25
F	0	17	17	17
G	0	15	15	15
I	0	16	16	16
K	6	28	26	26
L	6	17	15	15
M	0	2	2	2
R	0	11	11	11
T	27	56	47	47
U	0	3	3	3
W	25	56	49	49
Canopy	0	3	3	3
Residence	6	26	24	24
Storage H	0	2	2	2
Storage J	0	3	3	3
Storage O	0	3	3	3
Storage P	0	5	5	5

1.3 Asbestos-Containing Building Materials

**TABLE C
ASBESTOS CONTAINING BUILDING MATERIALS**

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING I
BUILDING K
BUILDING L
BUILDING M
BUILDING R
BUILDING T
BUILDING U
BUILDING W
CANOPY
RESIDENCE
STORAGE H
STORAGE J
STORAGE O
STORAGE P**

**TABLE C HAS BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN**

1.4 ACBM/Location Plans

BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING I
BUILDING K
BUILDING L
BUILDING M
BUILDING R
BUILDING T
BUILDING U
BUILDING W
CANOPY
RESIDENCE
STORAGE H
STORAGE J
STORAGE O
STORAGE P

**ACBM/LOCATION PLANS HAVE BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN**

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the 21 buildings at BFEC during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the 21 buildings at BFEC during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the 21 buildings at BFEC, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the 21 buildings at the BFEC campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the 21 buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 24, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 8700 South Kyrene Road in Tempe, Arizona and consists of 21 buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the single building.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of June 23, 2008 through June 30, 2008, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.

2.2 Description of Construction

2.2.1 Buildings A, B, C, D, E, F, G, I, T, W and Residence

The construction date of Buildings A, B, C, D, E, F, G, I, T, W and the Residence is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support concrete, wooden or metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete, vinyl composition tile and vinyl sheet flooring.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Buildings K, L and Storage H

The construction date of Buildings K, L and Storage H is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden or metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, vinyl composition tile and unfinished wood.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal and wood) or tackable wall panels. Original ceilings are wood or metal-framed and support suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.3 Buildings M, U, Storage J and O

The construction date of Buildings M, U, Storage J and O is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of wood or metal-framed construction, and support wooden or metal truss and deck systems finished with asphalt prepared roofing systems, paneling or spray-applied foam.

Floor finishes observed are unfinished concrete. Original walls are wood or metal-framed with metal and wood paneling and siding. There are no ceiling finishes or mechanical equipment for the buildings.

2.2.4 Building R

The construction date of Building R is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and support wooden or metal truss and deck systems finished with an asphalt prepared roofing system.

Floor finishes observed are unfinished concrete. Original walls are concrete masonry systems with stucco. There are no ceiling finishes associated with the building. Fire doors were observed to be associated with exterior entrances into the building.

Mechanical equipment for the building consists of roof-mounted mechanical units. The ductwork distribution systems are routed directly into the individual rooms.

2.2.5 Canopy

The construction date of the Canopy is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a on-grade asphalt foundation. Perimeter load bearing walls are of concrete masonry systems and support a wooden deck system finished with metal panels.

Floor finishes observed are asphalt. Original walls are concrete masonry systems and wood or metal-framed with metal siding. There are no ceiling finishes or mechanical equipment for the building.

2.2.6 Storage P

The construction date of Storage P is unknown. The construction appears to be consistent and uniform throughout.

Report of Findings
Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
FM Project 08-202

The building is built with a on-grade asphalt foundation. Perimeter load bearing walls are of concrete masonry systems and support a wooden deck system finished with a coating.

Floor finishes observed are asphalt. Original walls are concrete masonry systems and wood or metal-framed systems with metal and wood paneling and siding. There are no ceiling finishes or mechanical equipment for the building.

A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.

2.3 Building Materials/Systems List

**TABLE A
BUILDING MATERIAL SYSTEMS**

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING I
BUILDING K
BUILDING L
BUILDING M
BUILDING R
BUILDING T
BUILDING U
BUILDING W
CANOPY
RESIDENCE
STORAGE H
STORAGE J
STORAGE O
STORAGE P**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION	C	*	S
	RECEIVING	C	*	
	WAITING 01	C	*	
	OPEN OFFICE 01	C	*	
	OFFICE	C	*	
	OFFICE 02	C	*	
	OFFICE 03	C	*	
	OFFICE 04	C	*	
	CONFERENCE 02	C	*	
	HALL 06	C	*	
	VAULT 01	C	*	
	OPEN OFFICE 02	C	*	
	OFFICE 05	C	*	
	VAULT 02	C	*	
	COPY 01	C	*	
	HALL 04	C	*	
	HALL 05	C	*	
	OPEN OFFICE 03	C	*	
	OFFICE 06	C	*	
	OFFICE 07	C	*	
	CONFERENCE 03	C	*	
	OFFICE 08	C	*	
	OFFICE 09	C	*	
	OFFICE 10	C	*	
	STORAGE 01	C	*	
	HALL 03	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MULTI-USE	C	*	
	LOUNGE	C	*	
	HALL 01	C	*	
	CONFERENCE 01	C	*	
	BOARD ROOM	C	*	
	WAITING 02	C	*	
	STORAGE 04	C	*	
	BREAK-OUT 04	C	*	
	BREAK-OUT 03	C	*	
	VIDEO	C	*	
	BREAK-OUT 02	C	*	
	BREAK-OUT 01	C	*	
	TRAINING ROOM	C	*	
	OPEN OFFICE 06	C	*	
	OFFICE 24	C	*	
	OFFICE 23	C	*	
	OFFICE 22	C	*	
	STORAGE 03	C	*	
	HALL 07	C	*	
	OFFICE 21	C	*	
	RECORDS	C	*	
	OFFICE 20	C	*	
	OFFICE 19	C	*	
	OFFICE 18	C	*	
	OFFICE 17	C	*	
	CONFERENCE 05	C	*	
	OFFICE 16	C	*	
	COPY STORAGE	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	COPY 02	C	*	
	OPEN OFFICE 05	C	*	
	HALL 08	C	*	
	SUPERINTENDENT	C	*	
	BOARD OFFICE	C	*	
	CONFERENCE 04	C	*	
	STORAGE 02	C	*	
	OFFICE 15	C	*	
	OFFICE 14	C	*	
	OFFICE 11	C	*	
	OFFICE 12	C	*	
	OFFICE 13	C	*	
	OPEN OFFICE 04	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION	W	N, E, W, S	S
	RECEIVING	W	N, E, W, S	
	OFFICE 01	W	N, W	
	OFFICE 02	W	N	
	OFFICE 03	W	N	
	OFFICE 04	W	N, E, S	
	CONFERENCE 02	W	N, W, S	
	HALL 03	W	N, E, W, S	
	MULTI-USE	W	N, E, W, S	
	LOUNGE	W	N, E, W, S	
	KITCHEN	C, W	N, E, W	
	JANITOR 01	C, W	N, E, W, S	
	HALL 01	W	N, E, W, S	
	CONFERENCE 01	W	N, E, W, S	
	BOARD ROOM	W	N, E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	TABLE STORAGE	C, W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	BREAK-OUT 04	W	N, E, W, S	
	BREAK-OUT 03	W	N, E, W, S	
	VIDEO	W	N, E, W, S	
	BREAK-OUT 02	W	N, E, W, S	
	BREAK-OUT 01	W	N, E, W, S	
	TRAINING ROOM	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	RECORDS	W	N, E, W, S	
	OFFICE 16	W	N, E, W, S	
	COPY STORAGE	W	N, E, W, S	
	COPY 02	W	N, E, W, S	
	CHORAL	C, W	N, E, W, S	
	SUPERINTENDENT VESTIBULE	C, W	N, E, W, S	
	SUPERINTENDENT	W	N, E, W, S	
	BOARD OFFICE	W	N, E, W, S	
	CONFERENCE 04	W	N, E, W, S	
	STORAGE 02	W	W, S	
	OFFICE 15	W	W	
	OFFICE 14	W	W	
	OFFICE 11	W	N, W	
	OFFICE 12	W	N, E, S	
	OFFICE 13	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION	W	N, E, W, S	S
	RECEIVING	W	N, E, W, S	
	OFFICE 01	W	N, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	OFFICE 02	W	N	
	OFFICE 03	W	N	
	OFFICE 04	W	N, E, S	
	CONFERENCE 02	W	N, W, S	
	HALL 03	W	N, E, W, S	
	MULTI-USE	W	N, E, W, S	
	LOUNGE	W	N, E, W, S	
	KITCHEN	C, W	N, E, W	
	JANITOR 01	C, W	N, E, W, S	
	HALL 01	W	N, E, W, S	
	CONFERENCE 01	W	N, E, W, S	
	BOARD ROOM	W	N, E, W, S	
	TABLE STORAGE	C, W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	BREAK-OUT 04	W	N, E, W, S	
	BREAK-OUT 03	W	N, E, W, S	
	VIDEO	W	N, E, W, S	
	BREAK-OUT 02	W	N, E, W, S	
	BREAK-OUT 01	W	N, E, W, S	
	TRAINING ROOM	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	RECORDS	W	N, E, W, S	
	OFFICE 16	W	N, E, W, S	
	COPY STORAGE	W	N, E, W, S	
	COPY 02	W	N, E, W, S	
	CHORAL	C, W	N, E, W, S	
	SUPERINTENDENT VESTIBULE	C, W	N, E, W, S	
	SUPERINTENDENT	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOARD OFFICE	W	N, E, W, S	
	CONFERENCE 04	W	N, E, W, S	
	STORAGE 02	W	W, S	
	OFFICE 15	W	W	
	OFFICE 14	W	W	
	OFFICE 11	W	N, W	
	OFFICE 12	W	N, E, S	
	OFFICE 13	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION	W	N, E, W, S	S
	RECEIVING	W	N, E, W, S	
	OFFICE 01	W	N, W	
	OFFICE 02	W	N	
	OFFICE 03	W	N	
	OFFICE 04	W	N, E, S	
	CONFERENCE 02	W	N, W, S	
	HALL 03	W	N, E, W, S	
	MULTI-USE	W	N, E, W, S	
	LOUNGE	W	N, E, W, S	
	KITCHEN	C, W	N, E, W	
	JANITOR 01	C, W	N, E, W, S	
	HALL 01	W	N, E, W, S	
	CONFERENCE 01	W	N, E, W, S	
	BOARD ROOM	W	N, E, W, S	
	TABLE STORAGE	C, W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	BREAK-OUT 04	W	N, E, W, S	
	BREAK-OUT 03	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	VIDEO	W	N, E, W, S	
	BREAK-OUT 02	W	N, E, W, S	
	BREAK-OUT 01	W	N, E, W, S	
	TRAINING ROOM	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	RECORDS	W	N, E, W, S	
	OFFICE 16	W	N, E, W, S	
	COPY STORAGE	W	N, E, W, S	
	COPY 02	W	N, E, W, S	
	CHORAL	C, W	N, E, W, S	
	SUPERINTENDENT VESTIBULE	C, W	N, E, W, S	
	SUPERINTENDENT	W	N, E, W, S	
	BOARD OFFICE	W	N, E, W, S	
	CONFERENCE 04	W	N, E, W, S	
	STORAGE 02	W	W, S	
	OFFICE 15	W	W	
	OFFICE 14	W	W	
	OFFICE 11	W	N, W	
	OFFICE 12	W	N, E, S	
	OFFICE 13	W	N, E, W, S	
CARPET, TAN, FIBROUS, RED STREAKS	RECEPTION	F	*	S
	RECEIVING	F	*	
	WAITING 01	F	*	
	OPEN OFFICE 01	F	*	
	OFFICE 01	F	*	
	OFFICE 02	F	*	
	OFFICE 03	F	*	
	OFFICE 04	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	CONFERENCE 02	F	*	
	OPEN OFFICE 02	F	*	
	HALL 04	F	*	
	HALL 05	F	*	
	OPEN OFFICE 03	F	*	
	OFFICE 06	F	*	
	OFFICE 07	F	*	
	CONFERENCE 03	F	*	
	OFFICE 08	F	*	
	OFFICE 09	F	*	
	OFFICE 10	F	*	
	HALL 01	F	*	
	CONFERENCE 01	F	*	
	BOARD ROOM	F	*	
	TABLE STORAGE	F	*	
	CORRIDOR 01	F	*	
	WAITING 02	F	*	
	STORAGE 04	F	*	
	BREAK-OUT 04	F	*	
	BREAK-OUT 03	F	*	
	VIDEO	F	*	
	BREAK-OUT 02	F	*	
	BREAK-OUT 01	F	*	
	TRAINING ROOM	F	*	
	OPEN OFFICE 06	F	*	
	OFFICE 24	F	*	
	OFFICE 23	F	*	
	OFFICE 22	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 03	F	*	
	HALL 07	F	*	
	OFFICE 21	F	*	
	RECORDS	F	*	
	OFFICE 20	F	*	
	OFFICE 19	F	*	
	OFFICE 18	F	*	
	OFFICE 17	F	*	
	CONFERENCE 05	F	*	
	OFFICE 16	F	*	
	COPY 02	F	*	
	SUPERINTENDENT VESTIBULE	F	*	
	SUPERINTENDENT	F	*	
	BOARD OFFICE	F	*	
	CONFERENCE 04	F	*	
	STORAGE 02	F	*	
	OFFICE 15	F	*	
	OFFICE 14	F	*	
	OFFICE 11	F	*	
	OFFICE 12	F	*	
	OFFICE 13	F	*	
	OPEN OFFICE 04	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, TAN, FIBROUS, RED STREAKS	RECEPTION	F	*	S
	RECEIVING	F	*	
	WAITING 01	F	*	
	OPEN OFFICE 01	F	*	
	OFFICE	F	*	
	OFFICE 02	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 03	F	*	
	OFFICE 04	F	*	
	CONFERENCE 02	F	*	
	OPEN OFFICE 02	F	*	
	HALL 04	F	*	
	HALL 05	F	*	
	OPEN OFFICE 03	F	*	
	OFFICE 06	F	*	
	OFFICE 07	F	*	
	CONFERENCE 03	F	*	
	OFFICE 08	F	*	
	OFFICE 09	F	*	
	OFFICE 10	F	*	
	HALL 01	F	*	
	CONFERENCE 01	F	*	
	BOARD ROOM	F	*	
	TABLE STORAGE	F	*	
	CORRIDOR 01	F	*	
	WAITING 02	F	*	
	STORAGE 04	F	*	
	BREAK-OUT 04	F	*	
	BREAK-OUT 03	F	*	
	VIDEO	F	*	
	BREAK-OUT 02	F	*	
	BREAK-OUT 01	F	*	
	TRAINING ROOM	F	*	
	OPEN OFFICE 06	F	*	
	OFFICE 24	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	OFFICE 23	F	*	
	OFFICE 22	F	*	
	STORAGE 03	F	*	
	HALL 07	F	*	
	OFFICE 21	F	*	
	RECORDS	F	*	
	OFFICE 20	F	*	
	OFFICE 19	F	*	
	OFFICE 18	F	*	
	OFFICE 17	F	*	
	CONFERENCE 05	F	*	
	OFFICE 16	F	*	
	COPY 02	F	*	
	SUPERINTENDENT VESTIBULE	F	*	
	SUPERINTENDENT	F	*	
	BOARD OFFICE	F	*	
	CONFERENCE 04	F	*	
	STORAGE 02	F	*	
	OFFICE 15	F	*	
	OFFICE 14	F	*	
	OFFICE 11	F	*	
	OFFICE 12	F	*	
	OFFICE 13	F	*	
	OPEN OFFICE 04	F	*	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOBBY	O	N, E, W, S	S
	RECEIVING	O	W	
	OPEN OFFICE 02	O	W	
	VAULT 02	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HALL 04	O	E	
	OPEN COURT	O	N, W, S	
	HALL 05	O	S	
	ELECTRICAL 02	O	S	
	ELECTRICAL 03	O	S	
	OPEN OFFICE 03	O	N, E, W	
	STORAGE 01	O	E	
	HALL 03	O	W	
	MEN'S DRESS	O	E	
	WOMEN'S DRESS	O	E	
	WOMEN'S RESTROOM 02	O	N	
	MEN'S RESTROOM 02	O	N, E	
	JANITOR 02	O	W	
	LOUNGE	O	N, E	
	HALL 02	O	W, S	
	PHONE 01	O	N	
	ELECTRICAL 01	O	E, W	
	JANITOR 01	O	N, W, S	
	KITCHEN	O	N, E	
	VESTIBULE	O	W, S	
	BOARD ROOM	O	E, W	
	CORRIDOR 01	O	E, W	
	OPEN OFFICE 06	O	S	
	STORAGE 03	O	N	
	RECORDS	O	N, W	
	ELECTRICAL 05	O	S	
	OPEN OFFICE 05	O	N, E, S	
	HALL 08	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Ben Furlong Education Center, KSD
Building A

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WOMEN'S RESTROOM 04	O	N	
	MEN'S RESTROOM 04	O	N, E	
	JANITOR 03	O	W	
	PATIO 02	O	W	
	PHONE 02	O	N, S	
	ELECTRICAL 04	O	N	
	CHORAL	O	W	
	CONFERENCE 04	O	W	
	PATIO 01	O	E	
	OPEN OFFICE 04	O	E, S	
	EXTERIOR	O	N, E, W, S	
WALLBASE (CARPET), 4", BLACK, FIBROUS	RECEPTION	O	N, E, W, S	S
	WAITING 01	O	N, E, W	
	OFFICE	O	N, E, W, S	
	OFFICE 02	O	N, E, W, S	
	OFFICE 03	O	N, E, W, S	
	OFFICE 04	O	N, E, W, S	
	CONFERENCE 02	O	N, E, W, S	
	OPEN OFFICE 02	O	N, E, W, S	
	OFFICE 05	O	N, E, W, S	
	HALL 05	O	N	
	OPEN OFFICE 03	O	N, E, W, S	
	OFFICE 06	O	N, E, W, S	
	OFFICE 07	O	N, E, W, S	
	CONFERENCE 03	O	N, E, W, S	
	OFFICE 08	O	N, E, W, S	
	OFFICE 09	O	N, E, W, S	
	OFFICE 10	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	HALL 01	0	N, E, W, S	
	BOARD ROOM	0	N, E, W, S	
	CORRIDOR 01	0	N, E, W, S	
	WAITING 02	0	N, E, W	
	STORAGE 04	0	N, E, W, S	
	BREAK-OUT 04	0	N, E, W, S	
	BREAK-OUT 03	0	N, E, W, S	
	VIDEO	0	N, E, W, S	
	BREAK-OUT 02	0	N, E, W, S	
	BREAK-OUT 01	0	N, E, W, S	
	TRAINING ROOM	0	N, E, W, S	
	OPEN OFFICE 06	0	N, E, W, S	
	OFFICE 24	0	N, E, W, S	
	OFFICE 23	0	N, E, W, S	
	OFFICE 22	0	N, E, W, S	
	STORAGE 03	0	N, E, W, S	
	HALL 07	0	N, E, W	
	OFFICE 21	0	N, E, W, S	
	RECORDS	0	N, E, W, S	
	OFFICE 20	0	N, E, W, S	
	OFFICE 19	0	N, E, W, S	
	OFFICE 18	0	N, E, W, S	
	OFFICE 17	0	N, E, W, S	
	CONFERENCE 05	0	N, E, W, S	
	OFFICE 16	0	N, E, W, S	
	COPY 02	0	N, E, W, S	
	OPEN OFFICE 05	0	N, E, W, S	
	SUPERINTENDENT VESTIBULE	0	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	SUPERINTENDENT	O	N, E, W, S	
	BOARD OFFICE	O	N, E, W, S	
	CONFERENCE 04	O	N, E, W, S	
	STORAGE 02	O	N, E, W, S	
	OFFICE 15	O	N, E, W, S	
	OFFICE 14	O	N, E, W, S	
	OFFICE 11	O	N, E, W, S	
	OFFICE 12	O	N, E, W, S	
	OFFICE 13	O	N, E, W, S	
	OPEN OFFICE 04	O	N, E, W, S	
ADHESIVE, BLUE, PLIABLE, ASSOCIATED WITH WALLBASE (CARPET), 4", BLACK, FIBROUS	RECEPTION	O	N, E, W, S	S
	WAITING 01	O	N, E, W	
	OFFICE	O	N, E, W, S	
	OFFICE 02	O	N, E, W, S	
	OFFICE 03	O	N, E, W, S	
	OFFICE 04	O	N, E, W, S	
	CONFERENCE 02	O	N, E, W, S	
	OPEN OFFICE 02	O	N, E, W, S	
	OFFICE 05	O	N, E, W, S	
	HALL 05	O	N	
	OPEN OFFICE 03	O	N, E, W, S	
	OFFICE 06	O	N, E, W, S	
	OFFICE 07	O	N, E, W, S	
	CONFERENCE 03	O	N, E, W, S	
	OFFICE 08	O	N, E, W, S	
	OFFICE 09	O	N, E, W, S	
	OFFICE 10	O	N, E, W, S	
	HALL 01	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	BOARD ROOM	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	WAITING 02	O	N, E, W	
	STORAGE 04	O	N, E, W, S	
	BREAK-OUT 04	O	N, E, W, S	
	BREAK-OUT 03	O	N, E, W, S	
	VIDEO	O	N, E, W, S	
	BREAK-OUT 02	O	N, E, W, S	
	BREAK-OUT 01	O	N, E, W, S	
	TRAINING ROOM	O	N, E, W, S	
	OPEN OFFICE 06	O	N, E, W, S	
	OFFICE 24	O	N, E, W, S	
	OFFICE 23	O	N, E, W, S	
	OFFICE 22	O	N, E, W, S	
	STORAGE 03	O	N, E, W, S	
	HALL 07	O	N, E, W	
	OFFICE 21	O	N, E, W, S	
	RECORDS	O	N, E, W, S	
	OFFICE 20	O	N, E, W, S	
	OFFICE 19	O	N, E, W, S	
	OFFICE 18	O	N, E, W, S	
	OFFICE 17	O	N, E, W, S	
	CONFERENCE 05	O	N, E, W, S	
	OFFICE 16	O	N, E, W, S	
	COPY 02	O	N, E, W, S	
	OPEN OFFICE 05	O	N, E, W, S	
	SUPERINTENDENT VESTIBULE	O	N, E, W, S	
	SUPERINTENDENT	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOARD OFFICE	O	N, E, W, S	
	CONFERENCE 04	O	N, E, W, S	
	STORAGE 02	O	N, E, W, S	
	OFFICE 15	O	N, E, W, S	
	OFFICE 14	O	N, E, W, S	
	OFFICE 11	O	N, E, W, S	
	OFFICE 12	O	N, E, W, S	
	OFFICE 13	O	N, E, W, S	
	OPEN OFFICE 04	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	RECEIVING	O	N, E, S	S
	WAITING 01	O	N, W	
	OPEN OFFICE 01	O	S	
	OFFICE	O	N	
	OFFICE 02	O	N	
	OFFICE 03	O	N	
	OFFICE 04	O	N, S	
	CONFERENCE 02	O	N, S	
	HALL 06	O	N, S	
	VAULT 01	O	N, E	
	OPEN OFFICE 02	O	N, E, W	
	OFFICE 05	O	N, E	
	VAULT 02	O	E, W	
	COPY 01	O	N, E, S	
	HALL 04	O	E	
	HALL 05	O	N	
	ELECTRICAL 02	O	S	
	ELECTRICAL 03	O	S	
	OPEN OFFICE 03	O	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	OFFICE 06	O	S	
	OFFICE 07	O	S	
	CONFERENCE 03	O	S	
	OFFICE 08	O	S	
	OFFICE 09	O	S	
	STORAGE 01	O	E	
	HALL 03	O	N, W, S	
	MEN'S DRESS	O	N, E, W	
	MEN'S RESTROOM 03	O	E, W	
	WOMEN'S DRESS	O	E, W, S	
	WOMEN'S RESTROOM 03	O	E, W	
	MULTI-USE	O	N, W, S	
	WOMEN'S RESTROOM 02	O	W	
	MEN'S RESTROOM 02	O	E	
	LOUNGE	O	N, E, W, S	
	HALL 02	O	W, S	
	ELEVATOR EQUIPMENT	O	E	
	PHONE 01	O	N	
	ELECTRICAL 01	O	E, W	
	JANITOR 01	O	N, S	
	KITCHEN	O	N, E	
	VESTIBULE	O	N, S	
	MEN'S RESTROOM 01	O	E, W	
	WOMEN'S RESTROOM 01	O	E, W	
	HALL 01	O	N, E, W, S	
	CONFERENCE 01	O	E	
	BOARD ROOM	O	W, S	
	TABLE STORAGE	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CORRIDOR 01	O	E, W	
	WAITING 02	O	N, E	
	STORAGE 04	O	N, S	
	BREAK-OUT 04	O	N, S	
	BREAK-OUT 03	O	N, S	
	VIDEO	O	E, W	
	BREAK-OUT 02	O	N, S	
	BREAK-OUT 01	O	N, S	
	TRAINING ROOM	O	N, E, W, S	
	OPEN OFFICE 06	O	N, E, W, S	
	OFFICE 24	O	N	
	OFFICE 23	O	N, E	
	OFFICE 22	O	E	
	STORAGE 03	O	N, S	
	HALL 07	O	N, W, S	
	OFFICE 21	O	E	
	RECORDS	O	N, W	
	ELECTRICAL 05	O	S	
	OFFICE 20	O	E, S	
	OFFICE 19	O	S	
	OFFICE 18	O	S	
	OFFICE 17	O	S	
	CONFERENCE 05	O	S	
	OFFICE 16	O	E	
	COPY STORAGE	O	N	
	COPY 02	O	S	
	OPEN OFFICE 05	O	N, E, W, S	
	HALL 08	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WOMEN'S RESTROOM 04	O	W	
	MEN'S RESTROOM 04	O	E	
	CHORAL	O	W	
	SUPERINTENDENT RESTROOM	O	E, W, S	
	SUPERINTENDENT VESTIBULE	O	N, W, S	
	SUPERINTENDENT	O	N, E, W, S	
	BOARD OFFICE	O	E, W	
	CONFERENCE 04	O	W	
	OFFICE 15	O	W	
	OFFICE 14	O	W	
	OFFICE 11	O	N, W	
	OFFICE 12	O	N, S	
	OFFICE 13	O	N, S	
	OPEN OFFICE 04	O	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	LOUNGE	W	E	S
	BOARD ROOM	W	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S DRESS	C, W	N, E, W, S	S
	MEN'S RESTROOM 03	C, W	N, E, W, S	
	WOMEN'S DRESS	C, W	N, E, W, S	
	WOMEN'S RESTROOM 03	C, W	N, E, W, S	
	WOMEN'S RESTROOM 02	C	*	
	MEN'S RESTROOM 02	C	*	
	JANITOR 02	W	N, E, W, S	
	MEN'S RESTROOM 01	C	*	
	WOMEN'S RESTROOM 01	C	*	
	WOMEN'S RESTROOM 04	C	*	*
	MEN'S RESTROOM 04	C	*	
	JANITOR 03	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	SUPERINTENDENT RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S DRESS	C, W	N, E, W, S	S
	MEN'S RESTROOM 03	C, W	N, E, W, S	
	WOMEN'S DRESS	C, W	N, E, W, S	
	WOMEN'S RESTROOM 03	C, W	N, E, W, S	
	WOMEN'S RESTROOM 02	C	*	
	MEN'S RESTROOM 02	C	*	
	JANITOR 02	W	N, E, W, S	
	MEN'S RESTROOM 01	C	*	
	WOMEN'S RESTROOM 01	C	*	
	WOMEN'S RESTROOM 04	C	*	*
	MEN'S RESTROOM 04	C	*	
	JANITOR 03	W	N, E, W, S	
	SUPERINTENDENT RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S DRESS	C, W	N, E, W, S	S
	MEN'S RESTROOM 03	C, W	N, E, W, S	
	WOMEN'S DRESS	C, W	N, E, W, S	
	WOMEN'S RESTROOM 03	C, W	N, E, W, S	
	WOMEN'S RESTROOM 02	C	*	
	MEN'S RESTROOM 02	C	*	
	JANITOR 02	W	N, E, W, S	
	MEN'S RESTROOM 01	C	*	
	WOMEN'S RESTROOM 01	C	*	
	WOMEN'S RESTROOM 04	C	*	*
	MEN'S RESTROOM 04	C	*	
	JANITOR 03	W	N, E, W, S	
	SUPERINTENDENT RESTROOM	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
GLAZED WALL TILE, 2"X2", TAN, SMOOTH	MEN'S RESTROOM 03	W	W, S	S
	WOMEN'S RESTROOM 03	W	N, W	
	WOMEN'S RESTROOM 02	W	N, E, W, S	
	MEN'S RESTROOM 02	W	N, E, W, S	
	JANITOR 02	W	N, E	
	MEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 04	W	N, E, W, S	
	MEN'S RESTROOM 04	W	N, E, W, S	
	JANITOR 03	W	N, E	
GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	MEN'S RESTROOM 03	W	W, S	S
	WOMEN'S RESTROOM 03	W	N, W	
	WOMEN'S RESTROOM 02	W	N, E, W, S	
	MEN'S RESTROOM 02	W	N, E, W, S	
	JANITOR 02	W	N, E	
	MEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 04	W	N, E, W, S	
	MEN'S RESTROOM 04	W	N, E, W, S	
	JANITOR 03	W	N, E	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 2"X2", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	MEN'S RESTROOM 03	W	W, S	S
	WOMEN'S RESTROOM 03	W	N, W	
	WOMEN'S RESTROOM 02	W	N, E, W, S	
	MEN'S RESTROOM 02	W	N, E, W, S	
	JANITOR 02	W	N, E	
	MEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 04	W	N, E, W, S	
	MEN'S RESTROOM 04	W	N, E, W, S	
	JANITOR 03	W	N, E	
	MEN'S RESTROOM 03	W	W, S	S
	WOMEN'S RESTROOM 03	W	N, W	
	WOMEN'S RESTROOM 02	W	N, E, W, S	
	MEN'S RESTROOM 02	W	N, E, W, S	
	JANITOR 02	W	N, E	
	MEN'S RESTROOM 01	W	N, E, W, S	
	WOMEN'S RESTROOM 01	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WOMEN'S RESTROOM 04	W	N, E, W, S	
	MEN'S RESTROOM 04	W	N, E, W, S	
	JANITOR 03	W	N, E	
CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	MEN'S DRESS	F	*	S
	MEN'S RESTROOM 03	F	*	
	WOMEN'S DRESS	F	*	
	WOMEN'S RESTROOM 03	F	*	
	WOMEN'S RESTROOM 02	F	*	
	MEN'S RESTROOM 02	F	*	
	JANITOR 02	F	*	
	MEN'S RESTROOM 01	F	*	
	WOMEN'S RESTROOM 01	F	*	
	WOMEN'S RESTROOM 04	F	*	
	MEN'S RESTROOM 04	F	*	
	JANITOR 03	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	MEN'S DRESS	F	*	S
	MEN'S RESTROOM 03	F	*	
	WOMEN'S DRESS	F	*	
	WOMEN'S RESTROOM 03	F	*	
	WOMEN'S RESTROOM 02	F	*	
	MEN'S RESTROOM 02	F	*	
	JANITOR 02	F	*	
	MEN'S RESTROOM 01	F	*	
	WOMEN'S RESTROOM 01	F	*	
	WOMEN'S RESTROOM 04	F	*	
	MEN'S RESTROOM 04	F	*	
SINK ACOUSTICAL COATING, WHITE, ROUGH	KITCHEN	O	N	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CONFERENCE 01	O	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	RECEPTION	C, W	E, W	
	WAITING 01	W	N, E, W	
	OPEN OFFICE 02	C, W	N, E, W, S	
	OFFICE 05	W	N, E	
	COPY 01	W	N, E, W, S	
	HALL 04	W	E, W	
	HALL 05	C, W	N, E, W, S	
	STAIR WELL	C, W	N, E, W, S	
	ELECTRICAL 02	W	E, S	
	ELECTRICAL 03	W	N, E, W, S	
	BOOK	W	N, E, W	
	OPEN OFFICE 03	W	N, E, W, S	
	OFFICE 06	W	S	
	OFFICE 07	W	S	
	CONFERENCE 03	W	S	
	OFFICE 08	W	S	
	OFFICE 09	W	S	
	OFFICE 10	W	N, W, S	
	HALL 02	W	E, W, S	
	VESTIBULE	C, W	N, E, W, S	
	CORRIDOR 01	C, W	N, E, W, S	
	LANDING	C, W	N, E, W, S	
	WAITING 02	W	N, E, W	
	OPEN OFFICE 06	W	N, E, W, S	
	OFFICE 24	W	N, E, W, S	
	OFFICE 23	W	N, E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 22	W	E	
	HALL 07	W	N, E, W	
	OFFICE 21	W	E	
	ELECTRICAL 05	C, W	N, E, S	
	OFFICE 20	W	E, S	
	OFFICE 19	W	S	
	OFFICE 18	W	S	
	OFFICE 17	W	S	
	CONFERENCE 05	W	S	
	OPEN OFFICE 05	W	N, E, W, S	
	HALL 08	C, W	N, E, W, S	
	OPEN OFFICE 04	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	RECEPTION	C, W	E, W	
	WAITING 01	W	N, E, W	
	OPEN OFFICE 02	C, W	N, E, W, S	
	OFFICE 05	W	N, E	
	COPY 01	W	N, E, W, S	
	HALL 04	W	E, W	
	HALL 05	C, W	N, E, W, S	
	STAIR WELL	C, W	N, E, W, S	
	ELECTRICAL 02	W	E, S	
	ELECTRICAL 03	W	N, E, W, S	
	BOOK	W	N, E, W	
	OPEN OFFICE 03	W	N, E, W, S	
	OFFICE 06	W	S	
	OFFICE 07	W	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CONFERENCE 03	W	S	
	OFFICE 08	W	S	
	OFFICE 09	W	S	
	OFFICE 10	W	N, W, S	
	HALL 02	W	E, W, S	
	VESTIBULE	C, W	N, E, W, S	
	CORRIDOR 01	C, W	N, E, W, S	
	LANDING	C, W	N, E, W, S	
	WAITING 02	W	N, E, W	
	OPEN OFFICE 06	W	N, E, W, S	
	OFFICE 24	W	N, E, W, S	
	OFFICE 23	W	N, E	
	OFFICE 22	W	E	
	HALL 07	W	N, E, W	
	OFFICE 21	W	E	
	ELECTRICAL 05	C, W	N, E, S	
	OFFICE 20	W	E, S	
	OFFICE 19	W	S	
	OFFICE 18	W	S	
	OFFICE 17	W	S	
	CONFERENCE 05	W	S	
	OPEN OFFICE 05	W	N, E, W, S	
	HALL 08	C, W	N, E, W, S	
	OPEN OFFICE 04	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	RECEPTION	C, W	E, W	
	WAITING 01	W	N, E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OPEN OFFICE 02	C, W	N, E, W, S	
	OFFICE 05	W	N, E	
	COPY 01	W	N, E, W, S	
	HALL 04	W	E, W	
	HALL 05	C, W	N, E, W, S	
	STAIR WELL	C, W	N, E, W, S	
	ELECTRICAL 02	W	E, S	
	ELECTRICAL 03	W	N, E, W, S	
	BOOK	W	N, E, W	
	OPEN OFFICE 03	W	N, E, W, S	
	OFFICE 06	W	S	
	OFFICE 07	W	S	
	CONFERENCE 03	W	S	
	OFFICE 08	W	S	
	OFFICE 09	W	S	
	OFFICE 10	W	N, W, S	
	HALL 02	W	E, W, S	
	VESTIBULE	C, W	N, E, W, S	
	CORRIDOR 01	C, W	N, E, W, S	
	LANDING	C, W	N, E, W, S	
	WAITING 02	W	N, E, W	
	OPEN OFFICE 06	W	N, E, W, S	
	OFFICE 24	W	N, E, W, S	
	OFFICE 23	W	N, E	
	OFFICE 22	W	E	
	HALL 07	W	N, E, W	
	OFFICE 21	W	E	
	ELECTRICAL 05	C, W	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	OFFICE 20	W	E, S	
	OFFICE 19	W	S	
	OFFICE 18	W	S	
	OFFICE 17	W	S	
	CONFERENCE 05	W	S	
	OPEN OFFICE 05	W	N, E, W, S	
	HALL 08	C, W	N, E, W, S	
	OPEN OFFICE 04	W	N, E, W, S	
QUARRY/PAVER TILE, 4"X4", GRAY, SMOOTH	LOBBY	F, O	N, E, W, S	S
	HALL 05	F, O	N, S	
	OPEN OFFICE 03	F, O	N, S	
	HALL 02	F, O	E, W, S	
	VESTIBULE	F, O	N, E, W, S	
	ELEVATOR	F	*	
	LANDING	F, O	N, E, W, S	
	HALL 08	F, O	N, E, W, S	
QUARRY/PAVER TILE, 4"X4", TAN, SMOOTH, BLACK AND WHITE SPECKS	LOBBY	F, O	N, E, W, S	S
	HALL 05	F, O	N, S	
	OPEN OFFICE 03	F, O	N, S	
	HALL 02	F, O	E, W, S	
	VESTIBULE	F, O	N, E, W, S	
	ELEVATOR	F	*	
	LANDING	F, O	N, E, W, S	
	HALL 08	F, O	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 4"X4", GRAY, SMOOTH AND QUARRY/PAVER TILE, 4"X4", TAN, SMOOTH, BLACK AND WHITE SPECKS	LOBBY	F, O	N, E, W, S	S
	HALL 05	F, O	N, S	
	OPEN OFFICE 03	F, O	N, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	HALL 02	F, O	E, W, S	
	VESTIBULE	F, O	N, E, W, S	
	ELEVATOR	F	*	
	LANDING	F, O	N, E, W, S	
	HALL 08	F, O	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	LOBBY	C	*	S
	VESTIBULE	C	*	
	LANDING	C	*	
	HALL 08	C	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	VAULT 01	F	*	S
	VAULT 02	F	*	
	ELECTRICAL 02	F	*	
	STORAGE 01	F	*	
	HALL 03	F	*	
	LOUNGE	F	*	
	ELEVATOR EQUIPMENT	F	*	
	PHONE 01	F	*	
	ELECTRICAL 01	F	*	
	KITCHEN	F	*	
	PHONE 02	F	*	
	ELECTRICAL 04	F	*	
	CHORAL	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BLACK SPOTS	LOUNGE	F	*	S
	KITCHEN	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES AND VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BLACK SPOTS	VAULT 01	F	*	S
	VAULT 02	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ELECTRICAL 02	F	*	
	STORAGE 01	F	*	
	HALL 03	F	*	
	LOUNGE	F	*	
	ELEVATOR EQUIPMENT	F	*	
	PHONE 01	F	*	
	ELECTRICAL 01	F	*	
	KITCHEN	F	*	
	PHONE 02	F	*	
	ELECTRICAL 04	F	*	
	CHORAL	F	*	
WALLBASE (COVERED), 4", TAN, VINYL-LIKE	VAULT 01	O	N, E, W, S	S
	COPY 01	O	N, E, W, S	
	ELECTRICAL 02	O	N, E, W, S	
	ELECTRICAL 03	O	N, E, W, S	
	STORAGE 01	O	N, E, W, S	
	MULTI-USE	O	N, E, W, S	
	ELEVATOR EQUIPMENT	O	N, E, W, S	
	PHONE 01	O	N, E, W, S	
	ELECTRICAL 05	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", TAN, VINYL-LIKE	VAULT 01	O	N, E, W, S	S
	COPY 01	O	N, E, W, S	
	ELECTRICAL 02	O	N, E, W, S	
	ELECTRICAL 03	O	N, E, W, S	
	STORAGE 01	O	N, E, W, S	
	MULTI-USE	O	N, E, W, S	
	ELEVATOR EQUIPMENT	O	N, E, W, S	
	PHONE 01	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ELECTRICAL 05	O	N, E, W, S	
SEALANT (FIRE STOP), RED, PLIABLE	ELECTRICAL 01	O	S	S
PLASTER, GRAY, CEMENTITIOUS	LOBBY	O	E	S
	HALL 04	O	W	
	HALL 05	O	S	
	OPEN OFFICE 03	O	N	
	LANDING	O	E, W	
	OPEN OFFICE 06	O	S	
	HALL 07	O	S	
	OPEN OFFICE 05	O	N, W	
	HALL 08	O	N	
	OPEN OFFICE 04	O	E	
SEALANT (DOORS, WINDOWS), BLACK, GUMMY	RECEIVING	O	N	S
	EXTERIOR	O	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, VINYL COVER	OPEN OFFICE 01	W	N, E, W	S
	OFFICE	W	E, S	
	OFFICE 02	W	E, W, S	
	OFFICE 03	W	E, W, S	
	OFFICE 04	W	W	
	CONFERENCE 02	W	E	
	HALL 06	W	E, W	
	OPEN OFFICE 02	W	N, E, W	
	OFFICE 05	W	W, S	
	BOOK	W	S	
	OPEN OFFICE 03	W	N, W, S	
	OFFICE 06	W	N, E, W	
	OFFICE 07	W	N, E, W	
	CONFERENCE 03	W	N, E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 08	W	N, E, W	
	OFFICE 09	W	N, E, W	
	OFFICE 10	W	N, E	
	OPEN OFFICE 06	W	N, E, S	
	OFFICE 23	W	W, S	
	OFFICE 22	W	N, W, S	
	OFFICE 21	W	N, W, S	
	OFFICE 20	W	N, W	
	OFFICE 19	W	N, E, W	
	OFFICE 18	W	N, E, W	
	OFFICE 17	W	N, E, W	
	CONFERENCE 05	W	N, E, W	
	OPEN OFFICE 05	W	N, E, W, S	
	STORAGE 02	W	N, E	
	OFFICE 15	W	N, E, S	
	OFFICE 14	W	N, E, S	
	OFFICE 11	W	E, S	
	OFFICE 12	W	W	
	OPEN OFFICE 04	W	W	
CARPET, BLUE, FIBROUS, BROWN AND WHITE SPOTS	ELECTRICAL 03	F	*	S
	COPY STORAGE	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, BROWN AND WHITE SPOTS	ELECTRICAL 03	F	*	S
	COPY STORAGE	F	*	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	ELECTRICAL 03	W	N, W	S
	ELECTRICAL 05	W	W	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	ELECTRICAL 03	W	N, W	S
	ELECTRICAL 05	W	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
CARPET, PURPLE, FIBROUS, GRAY SPECKS	MULTI-USE	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, PURPLE, FIBROUS, GRAY SPECKS	MULTI-USE	F	*	S
VINYL STAIR TREAD, 12"X48", BLUE, CIRCLE PATTERN	STAIR WELL	F	*	S
VINYL COMPOSITION TILE, 18"X18", BLUE, CIRCLE PATTERN	STAIR WELL	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL STAIR TREAD, 12"X48", BLUE, CIRCLE PATTERN AND VINYL COMPOSITION TILE, 18"X18", BLUE, CIRCLE PATTERN	STAIR WELL	F	*	S
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	STAIR WELL	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	STAIR WELL	O	N, E, W, S	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC, (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE	ROOF	O	*	S
CONCRETE (TILT), GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
	ROOF	O	N, E, W, S	
STUCCO, GRAY, CEMENTITIOUS	PATIO 01	C, W	N, E, W, S	S
	EXTERIOR	C, W	E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LOBBY	F	*	S
	RECEPTION	F	*	
	RECEIVING	F	*	
	WAITING 01	F	*	
	OPEN OFFICE 01	F	*	
	OFFICE	F	*	
	OFFICE 02	F	*	
	OFFICE 03	F	*	
	OFFICE 04	F	*	
	CONFERENCE 02	F	*	
	HALL 06	F	*	
	VAULT 01	F	*	
	OPEN OFFICE 02	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 05	F	*	
	VAULT 02	F	*	
	COPY 01	F	*	
	HALL 04	F	*	
	OPEN COURT	F	*	
	HALL 05	F	*	
	STAIR WELL	F	*	
	ELECTRICAL 02	F	*	
	ELECTRICAL 03	F	*	
	BOOK	F	*	
	OPEN OFFICE 03	F	*	
	OFFICE 06	F	*	
	OFFICE 07	F	*	
	CONFERENCE 03	F	*	
	OFFICE 08	F	*	
	OFFICE 09	F	*	
	OFFICE 10	F	*	
	STORAGE 01	F	*	
	HALL 03	F	*	
	MEN'S DRESS	F	*	
	MEN'S RESTROOM 03	F	*	
	WOMEN'S DRESS	F	*	
	WOMEN'S RESTROOM 03	F	*	
	MULTI-USE	F	*	
	WOMEN'S RESTROOM 02	F	*	
	MEN'S RESTROOM 02	F	*	
	JANITOR 02	F	*	
	LOUNGE	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	HALL 02	F	*	
	ELEVATOR EQUIPMENT	F	*	
	PHONE 01	F	*	
	ELECTRICAL 01	F	*	
	JANITOR 01	F	*	
	KITCHEN	F	*	
	VESTIBULE	F	*	
	ELEVATOR	F	*	
	MEN'S RESTROOM 01	F	*	
	WOMEN'S RESTROOM 01	F	*	
	HALL 01	F	*	
	CONFERENCE 01	F	*	
	BOARD ROOM	F	*	
	TABLE STORAGE	F	*	
	CORRIDOR 01	F	*	
	LANDING	F	*	
	WAITING 02	F	*	
	STORAGE 04	F	*	
	BREAK-OUT 04	F	*	
	BREAK-OUT 03	F	*	
	VIDEO	F	*	
	BREAK-OUT 02	F	*	
	BREAK-OUT 01	F	*	
	TRAINING ROOM	F	*	
	OPEN OFFICE 06	F	*	
	OFFICE 24	F	*	
	OFFICE 23	F	*	
	OFFICE 22	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 03	F	*	
	HALL 07	F	*	
	OPEN COURT	F	*	
	OFFICE 21	F	*	
	RECORDS	F	*	
	ELECTRICAL 05	F	*	
	OFFICE 20	F	*	
	OFFICE 19	F	*	
	OFFICE 18	F	*	
	OFFICE 17	F	*	
	CONFERENCE 05	F	*	
	OFFICE 16	F	*	
	COPY STORAGE	F	*	
	COPY 02	F	*	
	OPEN OFFICE 05	F	*	
	HALL 08	F	*	
	WOMEN'S RESTROOM 04	F	*	
	MEN'S RESTROOM 04	F	*	
	JANITOR 03	F	*	
	PATIO 02	F	*	
	PHONE 02	F	*	
	ELECTRICAL 04	F	*	
	CHORAL	F	*	
	SUPERINTENDENT RESTROOM	F	*	
	SUPERINTENDENT VESTIBULE	F	*	
	SUPERINTENDENT	F	*	
	BOARD OFFICE	F	*	
	CONFERENCE 04	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	PATIO 01	F	*	
	STORAGE 02	F	*	
	OFFICE 15	F	*	
	OFFICE 14	F	*	
	OFFICE 11	F	*	
	OFFICE 12	F	*	
	OFFICE 13	F	*	
	OPEN OFFICE 04	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	N, E, W, S	S
SEALANT (DOORS, WINDOWS), GRAY, PLIABLE	EXTERIOR	O	N	S
GASKETS, 1"-3", BLACK/GREEN, PAPER-LIKE	LOBBY	O	*	S
	RECEPTION	O	*	
	RECEIVING	O	*	
	WAITING 01	O	*	
	OPEN OFFICE 01	O	*	
	OFFICE	O	*	
	OFFICE 02	O	*	
	OFFICE 03	O	*	
	OFFICE 04	O	*	
	CONFERENCE 02	O	*	
	HALL 06	O	*	
	VAULT 01	O	*	
	OPEN OFFICE 02	O	*	
	OFFICE 05	O	*	
	VAULT 02	O	*	
	COPY 01	O	*	
	HALL 04	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OPEN COURT	O	*	
	HALL 05	O	*	
	STAIR WELL	O	*	
	ELECTRICAL 02	O	*	
	ELECTRICAL 03	O	*	
	BOOK	O	*	
	OPEN OFFICE 03	O	*	
	OFFICE 06	O	*	
	OFFICE 07	O	*	
	CONFERENCE 03	O	*	
	OFFICE 08	O	*	
	OFFICE 09	O	*	
	OFFICE 10	O	*	
	STORAGE 01	O	*	
	HALL 03	O	*	
	MEN'S DRESS	O	*	
	MEN'S RESTROOM 03	O	*	
	WOMEN'S DRESS	O	*	
	WOMEN'S RESTROOM 03	O	*	
	MULTI-USE	O	*	
	WOMEN'S RESTROOM 02	O	*	
	MEN'S RESTROOM 02	O	*	
	JANITOR 02	O	*	
	LOUNGE	O	*	
	HALL 02	O	*	
	ELEVATOR EQUIPMENT	O	*	
	PHONE 01	O	*	
	ELECTRICAL 01	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	JANITOR 01	O	*	
	KITCHEN	O	*	
	VESTIBULE	O	*	
	ELEVATOR	O	*	
	MEN'S RESTROOM 01	O	*	
	WOMEN'S RESTROOM 01	O	*	
	HALL 01	O	*	
	CONFERENCE 01	O	*	
	BOARD ROOM	O	*	
	TABLE STORAGE	O	*	
	CORRIDOR 01	O	*	
	LANDING	O	*	
	WAITING 02	O	*	
	STORAGE 04	O	*	
	BREAK-OUT 04	O	*	
	BREAK-OUT 03	O	*	
	VIDEO	O	*	
	BREAK-OUT 02	O	*	
	BREAK-OUT 01	O	*	
	TRAINING ROOM	O	*	
	OPEN OFFICE 06	O	*	
	OFFICE 24	O	*	
	OFFICE 23	O	*	
	OFFICE 22	O	*	
	STORAGE 03	O	*	
	HALL 07	O	*	
	OPEN COURT	O	*	
	OFFICE 21	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	RECORDS	O	*	
	ELECTRICAL 05	O	*	
	OFFICE 20	O	*	
	OFFICE 19	O	*	
	OFFICE 18	O	*	
	OFFICE 17	O	*	
	CONFERENCE 05	O	*	
	OFFICE 16	O	*	
	COPY STORAGE	O	*	
	COPY 02	O	*	
	OPEN OFFICE 05	O	*	
	HALL 08	O	*	
	WOMEN'S RESTROOM 04	O	*	
	MEN'S RESTROOM 04	O	*	
	JANITOR 03	O	*	
	PATIO 02	O	*	
	PHONE 02	O	*	
	ELECTRICAL 04	O	*	
	CHORAL	O	*	
	SUPERINTENDENT RESTROOM	O	*	
	SUPERINTENDENT VESTIBULE	O	*	
	SUPERINTENDENT	O	*	
	BOARD OFFICE	O	*	
	CONFERENCE 04	O	*	
	PATIO 01	O	*	
	STORAGE 02	O	*	
	OFFICE 15	O	*	
	OFFICE 14	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	OFFICE 11	O	*	
	OFFICE 12	O	*	
	OFFICE 13	O	*	
	OPEN OFFICE 04	O	*	

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	IT ROOM	C	*	S
	INSTRUCTIONAL MATERIAL CENTER	C	*	
	HALL 1	C	*	
	HALL 2	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	SERVER ROOM	W	N, E, W, S	S
	IT ROOM	W	N, E, W, S	
	INSTRUCTIONAL MATERIAL CENTER	W	N, E, W, S	
	HALL 1	W	N, E, W, S	
	HALL 2	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	SERVER ROOM	W	N, E, W, S	S
	IT ROOM	W	N, E, W, S	
	INSTRUCTIONAL MATERIAL CENTER	W	N, E, W, S	
	HALL 1	W	N, E, W, S	
	HALL 2	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	SERVER ROOM	W	N, E, W, S	S
	IT ROOM	W	N, E, W, S	
	INSTRUCTIONAL MATERIAL CENTER	W	N, E, W, S	
	HALL 1	W	N, E, W, S	
	HALL 2	W	N, E, W, S	
CARPET, GRAY, FIBROUS	INSTRUCTIONAL MATERIAL CENTER	F	*	S
	HALL 1	F	*	
	HALL 2	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS	INSTRUCTIONAL MATERIAL CENTER	F	*	S
	HALL 1	F	*	
	HALL 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	INSTRUCTIONAL MATERIAL CENTER	O	N, E, W, S	S
	HALL 1	O	N, E, W, S	
	HALL 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	INSTRUCTIONAL MATERIAL CENTER	O	N, E, W, S	S
	HALL 1	O	N, E, W, S	
	HALL 2	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	SERVER ROOM	O	W	S
	IT ROOM	O	N, E	
	INSTRUCTIONAL MATERIAL CENTER	O	N	
	HALL 1	O	W	
	HALL 2	O	E, W	
	WOMEN'S RESTROOM 1	O	W	
	MEN'S RESTROOM 2	O	W	
	EXTERIOR	O	N, W	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	SERVER ROOM	F	*	S
	IT ROOM	F	*	
	INSTRUCTIONAL MATERIAL CENTER	F	*	
	HALL 1	F	*	
	HALL 2	F	*	
	MEN'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM 1	F	*	
	MEN'S RESTROOM 2	F	*	
	WOMEN'S RESTROOM 2	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	SERVER ROOM	C	*	S
	IT ROOM	C	*	
	INSTRUCTIONAL MATERIAL CENTER	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	HALL 1	C	*	
	HALL 2	C	*	
	MEN'S RESTROOM 1	C	*	
	WOMEN'S RESTROOM 1	C	*	
	MEN'S RESTROOM 2	C	*	
	WOMEN'S RESTROOM 2	C	*	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	SERVER ROOM	C	*	S
	IT ROOM	C	*	
	INSTRUCTIONAL MATERIAL CENTER	C	*	
	HALL 1	C	*	
	HALL 2	C	*	
	MEN'S RESTROOM 1	C	*	
	WOMEN'S RESTROOM 1	C	*	
	MEN'S RESTROOM 2	C	*	
	WOMEN'S RESTROOM 2	C	*	
GYPSON WALLBOARD, WHITE, CHALKY	SERVER ROOM	C	*	S
	IT ROOM	C	*	
	INSTRUCTIONAL MATERIAL CENTER	C	*	
	HALL 1	C	*	
	HALL 2	C	*	
	MEN'S RESTROOM 1	C	*	
	WOMEN'S RESTROOM 1	C	*	
	MEN'S RESTROOM 2	C	*	
	WOMEN'S RESTROOM 2	C	*	
SEALANT (DOORS, FIXTURES), WHITE, PLIABLE	SERVER ROOM	O	W	S
	IT ROOM	O	N, E	
	INSTRUCTIONAL MATERIAL CENTER	O	N, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	HALL 1	O	E, W	
	HALL 2	O	E, W	
	MEN'S RESTROOM 1	O	E, S	
	WOMEN'S RESTROOM 1	O	W, S	
	MEN'S RESTROOM 2	O	N, W	
	WOMEN'S RESTROOM 2	O	N, E	
SINK ACOUSTICAL COATING, WHITE, ROUGH	HALL 1	O	S	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	MEN'S RESTROOM 2	C, W	N, E, W, S	
	WOMEN'S RESTROOM 2	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	MEN'S RESTROOM 2	C, W	N, E, W, S	
	WOMEN'S RESTROOM 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	MEN'S RESTROOM 2	C, W	N, E, W, S	
	WOMEN'S RESTROOM 2	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	MEN'S RESTROOM 2	W	N, E, W, S	
	WOMEN'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	MEN'S RESTROOM 2	W	N, E, W, S	
	WOMEN'S RESTROOM 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	MEN'S RESTROOM 2	W	N, E, W, S	
	WOMEN'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH	MEN'S RESTROOM 1	F	*	S
	WOMEN'S RESTROOM 1	F	*	
	MEN'S RESTROOM 2	F	*	
	WOMEN'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH	MEN'S RESTROOM 1	F	*	S
	WOMEN'S RESTROOM 1	F	*	
	MEN'S RESTROOM 2	F	*	
	WOMEN'S RESTROOM 2	F	*	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	MEN'S RESTROOM 2	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	MEN'S RESTROOM 2	O	N, E, W, S	S
SEALANT (DUCT), GRAY, PLIABLE	SERVER ROOM	O	*	S
	IT ROOM	O	*	
	INSTRUCTIONAL MATERIAL CENTER	O	*	
	HALL 1	O	*	
	HALL 2	O	*	
	MEN'S RESTROOM 1	O	*	
	WOMEN'S RESTROOM 1	O	*	
	MEN'S RESTROOM 2	O	*	
	WOMEN'S RESTROOM 2	O	*	
	EXTERIOR	O	*	
GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	*	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
CARPET (SELF-STICK SQUARES), 2'X2', BLUE, FIBROUS, MULTI-COLORED SPECKS	IT ROOM	F	*	S
CARPET (COVE), 4", BLACK, FIBROUS	IT ROOM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH CARPET (COVE), 4", BLACK, FIBROUS	IT ROOM	O	N, E, W, S	S
VINYL COMPOSITION TILE, 12"X12", LIGHT GRAY, SMOOTH, GRAY MOTTLES	SERVER ROOM	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", LIGHT GRAY, SMOOTH, GRAY MOTTLES	SERVER ROOM	F	*	S
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	SERVER ROOM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE, 4", BLACK, VINYL-LIKE	SERVER ROOM	O	N, E, W, S	S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	SERVER ROOM	C	*	S
SEALANT (WINDOWS), BLACK, GUMMY	IT ROOM	O	N	S
BRICK, 3"X8", RED, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
BRICK, 4"X8", RED, CEMENTITIOUS	EXTERIOR	W	N	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X8", RED, CEMENTITIOUS	EXTERIOR	W	N	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building C*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	ROOM 01	C	*	S
	ROOM 02	C	*	
BRICK, 3"X8", RED, CEMENTITIOUS	ROOM 01	W	N, E, W, S	S
	ROOM 02	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	ROOM 01	W	N, E, W, S	S
	ROOM 02	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM 01	W	E	S
	ROOM 02	W	W	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM 01	W	E	S
	ROOM 02	W	W	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ROOM 01	W	E	S
	ROOM 02	W	W	
ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	ROOM 01	C	*	S
	ROOM 02	C	*	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	ROOM 01	C	*	S
	ROOM 02	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY	ROOM 01	C	*	S
	ROOM 02	C	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	ROOM 01	F	*	S
	ROOM 02	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	ROOM 01	F	*	S
	ROOM 02	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building C*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
WALLBASE (COVERED), 4", DARK BROWN, VINYL-LIKE	ROOM 01	O	N, E, W, S	S
	ROOM 02	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BROWN, VINYL-LIKE	ROOM 01	O	N, E, W, S	S
	ROOM 02	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	ROOM 01	O	N	S
	ROOM 02	O	N	
	EXTERIOR	O	N	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	ROOM 01	F	*	S
	ROOM 02	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
SEALANT (DOORS), WHITE, PLIABLE	ROOM 01	O	N	S
	ROOM 02	O	N	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	ROOM 01	W	N, E, W, S	S
WINDOW GLAZING PUTTY, WHITE, BRITTLE	ROOM 01	O	N	S
	ROOM 02	O	N	
SEALANT (DUCT), GRAY, PLIABLE	ROOM 01	O	*	S
	ROOM 02	O	*	
ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS), BLACK, TAR-LIKE	ROOF	O	*	S
GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	*	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	ROOM 01	C	*	
	ROOM 01A	C	*	
	ROOM 02	C	*	
	ROOM 03	C	*	
	WOMEN'S RESTROOM	C	*	
BRICK, 3"X8", RED, CEMENTITIOUS	ROOM 01	W	N, W, S	S
	ROOM 01A	W	S	
	ROOM 02	W	N, S	
	ROOM 03	W	N, S	
	MEN'S RESTROOM	W	N, E, W, S	
	JANITOR	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	ROOM 01	W	N, W, S	S
	ROOM 01A	W	S	
	ROOM 02	W	N, S	
	ROOM 03	W	N, S	
	MEN'S RESTROOM	W	N, E, W, S	
	JANITOR	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM 01	W	E	S
	ROOM 01A	W	E	
	ROOM 02	W	E, W	
	ROOM 03	W	W	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM 01	W	E	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM 01A	W	E	
	ROOM 02	W	E, W	
	ROOM 03	W	W	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ROOM 01	W	E	S
	ROOM 01A	W	E	
	ROOM 02	W	E, W	
	ROOM 03	W	W	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	ROOM 01	F	*	S
	ROOM 01A	F	*	
	ROOM 03	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	ROOM 01	F	*	S
	ROOM 01A	F	*	
	ROOM 03	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	ROOM 01	O	N, E, W, S	S
	ROOM 01A	O	N, E, W, S	
	ROOM 02	O	N, E, W, S	
	ROOM 03	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL- LIKE	ROOM 01	O	N, E, W, S	S
	ROOM 01A	O	N, E, W, S	
	ROOM 02	O	N, E, W, S	
	ROOM 03	O	N, E, W, S	
SEALANT (DOORS, MILLWORK), WHITE, PLIABLE	ROOM 01	O	N, W, S	
	ROOM 02	O	N	
	ROOM 03	O	N, W, S	
	MEN'S RESTROOM	O	E	
	JANITOR	O	E	
	WOMEN'S RESTROOM	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	ROOM 01	C	*	S
	ROOM 01A	C	*	
	ROOM 02	C	*	
	ROOM 03	C	*	
	MEN'S RESTROOM	C	*	
	JANITOR	C	*	
	WOMEN'S RESTROOM	C	*	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	ROOM 01	C	*	S
	ROOM 01A	C	*	
	ROOM 02	C	*	
	ROOM 03	C	*	
	MEN'S RESTROOM	C	*	
	JANITOR	C	*	
	WOMEN'S RESTROOM	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY	ROOM 01	C	*	S
	ROOM 01A	C	*	
	ROOM 02	C	*	
	ROOM 03	C	*	
	MEN'S RESTROOM	C	*	
	JANITOR	C	*	
	WOMEN'S RESTROOM	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY	ROOM 01	W	E, S	S
	ROOM 01A	W	N, W	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ROOM 01	W	E, S	S
	ROOM 01A	W	N, W	
FIRE DOOR INSULATION, METALWOOD CLADDING	ROOM 01	O	N	S
	ROOM 02	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM 03	O	N	
	MEN'S RESTROOM	O	E	
	JANITOR	O	E	
	WOMEN'S RESTROOM	O	E	
	EXTERIOR	O	N, E	
CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	ROOM 02	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	ROOM 02	F	*	S
VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
WINDOW GLAZING PUTTY, GRAY, BRITTLE	MEN'S RESTROOM	O	N	S
	WOMEN'S RESTROOM	O	S	
SEALANT (DUCT), GRAY, PLIABLE	ROOM 01	O	*	S
	ROOM 01A	O	*	
	ROOM 02	O	*	
	ROOM 03	O	*	
	MEN'S RESTROOM	O	*	
	JANITOR	O	*	
	WOMEN'S RESTROOM	O	*	
	EXTERIOR	O	*	
GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	N, S	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	N, S	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	ROOM 01	F	*	S
	ROOM 01A	F	*	
	ROOM 02	F	*	
	ROOM 03	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MEN'S RESTROOM	F	*	
	JANITOR	F	*	
	WOMEN'S RESTROOM	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	**	
SEALANT (FIRE STOP), RED, PLIABLE	JANITOR	O	*	S
ASPHALT PREPARED ROOFING (SHINGLE), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLE), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS), BLACK, TAR-LIKE	ROOF	O	*	S
GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM	C	*	S
	JANITOR	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM	C	*	S
	JANITOR	C	*	

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building E*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	PRINT SHOP	C	*	S
	COMPUTERS	C	*	
	DATA PROCESSING	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	OFFICE	W	N, E, W, S	S
	PRINT SHOP	W	N, E, W, S	
	STORAGE	C, W	N, E, W, S	
	COMPUTERS	W	N, E, W, S	
	DATA PROCESSING	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	OFFICE	W	N, E, W, S	S
	PRINT SHOP	W	N, E, W, S	
	STORAGE	C, W	N, E, W, S	
	COMPUTERS	W	N, E, W, S	
	DATA PROCESSING	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	OFFICE	W	N, E, W, S	S
	PRINT SHOP	W	N, E, W, S	
	STORAGE	C, W	N, E, W, S	
	COMPUTERS	W	N, E, W, S	
	DATA PROCESSING	W	N, E, W, S	
FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	STORAGE	W	N, E	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	STORAGE	W	N, E	S
VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, DARK GREEN MOTTLES	OFFICE	F	*	S
	PRINT SHOP	F	*	
	STORAGE	F	*	
	UNISEX RESTROOM	F	*	
VINYL COMPOSITION TILE (PATTERN), 12"X12", BLUE, SMOOTH, BLACK MOTTLES	OFFICE	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building E*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	PRINT SHOP	F	*	
	STORAGE	F	*	
	UNISEX RESTROOM	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, DARK GREEN MOTTLES AND VINYL COMPOSITION TILE (PATTERN), 12"X12", BLUE, SMOOTH, BLACK MOTTLES	OFFICE	F	*	S
	PRINT SHOP	F	*	
	STORAGE	F	*	
	UNISEX RESTROOM	F	*	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	OFFICE	O	N, E, W, S	S
	PRINT SHOP	O	N, E, W, S	
	STORAGE	O	N, E, W, S	
	COMPUTERS	O	N, E, W, S	
	DATA PROCESSING	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	OFFICE	O	N, E, W, S	S
	PRINT SHOP	O	N, E, W, S	
	STORAGE	O	N, E, W, S	
	COMPUTERS	O	N, E, W, S	
	DATA PROCESSING	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	PRINT SHOP	O	E, S	S
	STORAGE	O	E	
	COMPUTERS	O	E	
	DATA PROCESSING	O	E, W	
	EXTERIOR	O	E, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	OFFICE	F	*	S
	PRINT SHOP	F	*	
	STORAGE	F	*	
	UNISEX RESTROOM	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building E*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	COMPUTERS	F	*	
	DATA PROCESSING	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	E, S	S
SEALANT (DOORS, WINDOWS), WHITE, PLIABLE	OFFICE	O	E	S
	PRINT SHOP	O	N, E, W, S	
	STORAGE	O	E	
	UNISEX RESTROOM	O	W	
	COMPUTERS	O	E	
	DATA PROCESSING	O	E, W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	UNISEX RESTROOM	C, W	N, E, W, S	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	UNISEX RESTROOM	C, W	N, E, W, S	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	UNISEX RESTROOM	C, W	N, E, W, S	S
WALLBASE (COVERED), 4", DARK BROWN, VINYL-LIKE	UNISEX RESTROOM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BROWN, VINYL-LIKE	UNISEX RESTROOM	O	N, E, W, S	S
CARPET, BLUE, FIBROUS	DATA PROCESSING	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS	DATA PROCESSING	F	*	S
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	E, W, S	S
GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR	C	*	S
SEALANT (DUCT), GRAY, PLIABLE	EXTERIOR	O	*	S
COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	ROOF	O	*	S
MASTIC (PENETRATIONS), BLACK, TAR-LIKE	ROOF	O	*	S
WOVEN DUCT BOOT, 4", BLACK, RUBBER-LIKE	EXTERIOR	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building E*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
SEALANT (WINDOWS), GRAY, PLIABLE	EXTERIOR	O	N	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building F*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
CONCRETE MASONRY UNIT, 2"X16", GRAY, CEMENTITIOUS	ROOF	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	STORAGE 1	W	N, E, W	S
	STORAGE 2	W	E, W, S.	
	ROOF	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 2"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	STORAGE 1	W	N, E, W	S
	STORAGE 2	W	E, W, S	
	ROOF	W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	STORAGE 1	F	*	S
	STORAGE 2	F	*	
	EXTERIOR	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	STORAGE 1	O	W, S	S
	STORAGE 2	O	N, E, W	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	STORAGE 1	O	W	S
	STORAGE 2	O	E	
	EXTERIOR	O	E, W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 1	W	S	S
	STORAGE 2	W	N	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 1	W	S	S
	STORAGE 2	W	N	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 1	W	S	S
	STORAGE 2	W	N	
WALLBASE (COVERED), 4", TAN, VINYL-LIKE	STORAGE 1	O	N, E, W, S	S
	STORAGE 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", TAN, VINYL-LIKE	STORAGE 1	O	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building F*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	STORAGE 2	O	N, E, W, S	
EXPANSION JOINT, GRAY, PLIABLE	EXTERIOR	O	N, E, W, S	S
	ROOF	O	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	STORAGE 2	W	S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (FLASHINGS), WHITE, PLIABLE	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building G*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	SHOP	W	N, E, W, S	S
	STORAGE 01	C, W	N, E, W, S	
	STORAGE 02	C, W	N, E, W, S.	
	OFFICE	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	SHOP	W	N, E, W, S	S
	STORAGE 01	C, W	N, E, W, S	
	STORAGE 02	C, W	N, E, W, S	
	OFFICE	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	SHOP	W	N, E, W, S	S
	STORAGE 01	C, W	N, E, W, S	
	STORAGE 02	C, W	N, E, W, S	
	OFFICE	C, W	N, E, W, S	
CARPET, GREEN, FIBROUS	OFFICE	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GREEN, FIBROUS	OFFICE	F	*	S
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	STORAGE 01	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	STORAGE 01	O	N, E, W, S	S
SEALANT (DOORS, WINDOWS), WHITE, PLIABLE	STORAGE 01	O	N	S
	OFFICE	O	E, S	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	STORAGE 01	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	STORAGE 01	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	SHOP	F	*	S
	STORAGE 01	F	*	
	STORAGE 02	F	*	
	OFFICE	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building G*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	EXTERIOR	F	*	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS), BLACK, TAR-LIKE	ROOF	O	*	S
CEMENTITIOUS ROOF SHINGLES (S-PATTERN), RED, CEMENTITIOUS	EXTERIOR	O	N, E, W, S	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC; ASSOCIATED WITH CEMENTITIOUS ROOF SHINGLES (S-PATTERN), RED, CEMENTITIOUS	EXTERIOR	O	N, E, W, S	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building I*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WOMEN'S RESTROOM	C, W	N, E, W, S	S
	JANITOR 01	C, W	N, E, W, S	
	JANITOR 02	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WOMEN'S RESTROOM	C, W	N, E, W, S	S
	JANITOR 01	C, W	N, E, W, S	
	JANITOR 02	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	WOMEN'S RESTROOM	C, W	N, E, W, S	S
	JANITOR 01	C, W	N, E, W, S	
	JANITOR 02	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	MEN'S RESTROOM	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	MEN'S RESTROOM	F	*	S
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	MEN'S RESTROOM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	MEN'S RESTROOM	O	N, E, W, S	S
SEALANT (DOORS, MILLWORK, FIXTURES), WHITE, PLIABLE	WOMEN'S RESTROOM	O	E, W, S	S
	JANITOR 01	O	N, S	
	JANITOR 02	O	S	
	MEN'S RESTROOM	O	E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	WOMEN'S RESTROOM	O	W	S
	JANITOR 01	O	S	
	MEN'S RESTROOM	O	E	
	EXTERIOR	O	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building I*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH	WOMEN'S RESTROOM	F	*	S
	JANITOR 01	F	*	
	JANITOR 02	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH	WOMEN'S RESTROOM	F	*	S
	JANITOR 01	F	*	
	JANITOR 02	F	*	
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	WOMEN'S RESTROOM	O	N, E, W, S	S
	JANITOR 01	O	N, E, W, S	
	JANITOR 02	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	WOMEN'S RESTROOM	O	N, E, W, S	S
	JANITOR 01	O	N, E, W, S	
	JANITOR 02	O	N, E, W, S	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
ASPHALT (ENTRIES), BLACK, ASPHALTIC	EXTERIOR	F	*	S

* - Not Applicable

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building K*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	LOUNGE	C	*	S
	STORAGE	C	*	
TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER, MECHANICALLY ATTACHED	LOUNGE	W	N, E, W, S	S
	STORAGE	W	N, E, W, S	
CARPET, ORANGE, FIBROUS	STORAGE	F	*	S
MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH CARPET, ORANGE, FIBROUS	STORAGE	F	*	S
WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	UNISEX RESTROOM	O	N, E, W, S	S
	STORAGE	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	UNISEX RESTROOM	O	N, E, W, S	S
	STORAGE	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOUNGE	O	E	S
	STORAGE	O	E	
	EXTERIOR	O	E	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	LOUNGE	W	N	S
	STORAGE	W	S	
SINK ACOUSTICAL COATING, BLACK, ROUGH	UNISEX RESTROOM	O	S	S
	STORAGE	O	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOUNGE	W	N, E, W, S	S
	POISON STORAGE	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STORAGE	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOUNGE	W	N, E, W, S	S
	POISON STORAGE	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STORAGE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building K*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOUNGE	W	N, E, W, S	S
	POISON STORAGE	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STORAGE	W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	UNISEX RESTROOM	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	UNISEX RESTROOM	F	*	S
SEALANT (DOORS, FIXTURES), WHITE, PLIABLE	UNISEX RESTROOM	O	N, W, S	S
	EXTERIOR	O	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOUNGE	W	N, E, W, S	S
	STORAGE	W	N, E, W, S	
SINK ACOUSTICAL COATING, WHITE, ROUGH	LOUNGE	O	E	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOUNGE	W	N	S
	STORAGE	W	S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOUNGE	W	N	S
	STORAGE	W	S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOUNGE	W	N	S
	STORAGE	W	S	
CARPET, BLUE, FIBROUS	LOUNGE	F	*	S
MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH CARPET, BLUE, FIBROUS	LOUNGE	F	*	S
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	LOUNGE	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	LOUNGE	O	N, E, W, S	S
SIDING (WOOD), PAINTED	EXTERIOR	W	N, E, W, S	N
ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS), BLACK, TAR-LIKE	ROOF	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building K*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
ASPHALT (ENTRIES), BLACK, ASPHALTIC	EXTERIOR	F	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building L*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	STORAGE 1	C	*	S
	STORAGE 2	C	*	
TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER	STORAGE 1	W	N, E, W, S	S
	STORAGE 2	W	N, E, W, S	
CARPET, BROWN, FIBROUS	STORAGE 1	F	*	S
	STORAGE 2			
MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH CARPET, BROWN, FIBROUS	STORAGE 1	F	*	S
	STORAGE 2			
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	STORAGE 1	O	N, E, W, S	S
	STORAGE 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	STORAGE 1	O	N, E, W, S	S
	STORAGE 2	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	STORAGE 1	O	E	S
	STORAGE 2	O	E	
	EXTERIOR	O	E	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	STORAGE 1	W	N	S
	STORAGE 2	W	S	
SINK ACOUSTICAL COATING, BLACK, ROUGH	STORAGE 1	O	N	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 1	W	N	S
	STORAGE 2	W	S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 1	W	N	S
	STORAGE 2	W	S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 1	W	N	S
	STORAGE 2	W	S	
SIDING (WOOD), PAINTED	EXTERIOR	W	N, E, W, S	N

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building L*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (DOORS), WHITE, BRITTLE	EXTERIOR	O	E	S
ASPHALT (ENTRIES), BLACK, ASPHALTIC	EXTERIOR	F	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building M*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
PANELING (METAL), FACTORY FINISH	BUILDING M	W	N, E, W, S	S
FIRE DOOR INSULATION, METAL/WOOD CLADDING	BUILDING M	O	W, S	S
	EXTERIOR	O	W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	BUILDING M	F	*	S
	EXTERIOR	F	*	
SIDING (METAL), FACTORY FINISH	EXTERIOR	W	N, E, W, S	N
PANELING (METAL), FACTORY FINISH	ROOF	O	*	N

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building R*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	CHILLERS	W	N, E, W, S	S
	PUMPS	W	N, E, W, S	
	ELECTRICAL	W	E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED, WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	CHILLERS	W	N, E, W, S	S
	PUMPS	W	N, E, W, S	
	ELECTRICAL	W	E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CHILLERS	F	*	S
	PUMPS	F	*	
	ELECTRICAL	F	*	
	EXTERIOR	F	*	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CHILLERS	O	E	S
	PUMPS	O	N, W	
	EXTERIOR	O	N	
PIPE END SEALANT, WHITE, PLIABLE	PUMPS	O	*	S
SEALANT (EQUIPMENT), BLACK, GUMMY	CHILLERS	O	*	S
SEALANT (DOORS, FIXTURES), GRAY, PLIABLE	CHILLERS	O	N, E, W, S	S
	PUMPS	O	N, W	
	EXTERIOR	O	N	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (DUCT), GRAY, PLIABLE	ROOF	O	*	S
STUCCO, GRAY, CEMENTITIOUS	ELECTRICAL	W	N	S
	EXTERIOR	W	N, E, W, S	

* - *Not Applicable*

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (FLASHINGS), WHITE, PLIABLE	ROOF	O	*	S
WOVEN DUCT BOOT, 4", BLACK, RUBBER-LIKE	ROOF	O	*	S
SEALANT (DUCT), GRAY, PLIABLE	ROOF	O	*	S
DUCT SEAM TAPE, 4", WHITE, CANVAS	ROOF	O	*	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	EXTERIOR	W	W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	EXTERIOR	W	N, E, W, S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	W, S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	W, S	S
SEALANT (DOORS, WINDOWS, EXPANSION), GRAY, PLIABLE	DELIVERIES	O	N, S	S
	PATIO	O	W, S	
	VESTIBULE	O	W	
	BUS REPAIR AREA	O	E	
	OFFICE 02	O	N	
	ABYSS	O	E	
	BAY 03	O	W	
	STORAGE 05	O	E	
	BAY 05	O	E, W	
	BAY 06	O	E, W	
	CORRIDOR 02	O	S	
	CORRIDOR 03	O	N	
	EXTERIOR	O	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	WASH BAY	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	BUS REPAIR	F	*	
	TOOL CRIB 01	F	*	
	OFFICE 01	F	*	
	STORAGE 01	F	*	
	STORAGE 02	F	*	
	DELIVERIES	F	*	
	VESTIBULE	F	*	
	OFFICE 02	F	*	
	OFFICE 03	F	*	
	OFFICE 04	F	*	
	OFFICE 05	F	*	
	ROUTING	F	*	
	DISPATCH	F	*	
	RECEPTION 01	F	*	
	DIRECTOR	F	*	
	HALL 01	F	*	
	LOUNGE	F	*	
	PATIO	F	*	
	LOCKSMITH	F	*	
	JANITOR	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	TOOL CRIB 02	F	*	
	BENCH STOCK	F	*	
	PLAN ROOM	F	*	
	OFFICE 06	F	*	
	OFFICE 07	F	*	
	OFFICE 08	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 03	F	*	
	RECEPTION 02	F	*	
	LOBBY	F	*	
	CONFERENCE	F	*	
	BAY 01	F	*	
	OFFICE 09	F	*	
	ABYSS	F	*	
	BAY 02	F	*	
	TOOL CRIB 03	F	*	
	BAY 03	F	*	
	TOOL CRIB 04	F	*	
	BAY 04	F	*	
	STORAGE 04	F	*	
	STORAGE 05	F	*	
	BAY 05	F	*	
	OFFICE 10	F	*	
	OFFICE 11	F	*	
	BAY 06	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
	CORRIDOR 03	F	*	
	EXTERIOR	F	*	
CONCRETE, GRAY, CEMENTITIOUS	PATIO	F	*	S
ASPHALT (ENTRIES), BLACK, ASPHALTIC	EXTERIOR	F	*	S
FIRE DOOR INSULATION, METALWOOD CLADDING	VESTIBULE	O	E, W	S
	OFFICE 02	O	E, W	
	OFFICE 03	O	N	
	DIRECTOR	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM
		C/W/F/O	N/E/W/S	N/S
	LOUNGE	O	E	
	PATIO	O	W, S	
	LOCKSMITH	O	W	
	MEN'S RESTROOM	O	S	
	WOMEN'S RESTROOM	O	N	
	RECEPTION	O	W	
	LOBBY	O	E, S	
	BAY 01	O	N, S	
	BAY 02	O	N, S	
	BAY 03	O	N	
	BAY 04	O	S	
	STORAGE 05	O	E	
	BAY 05	O	N, E, W	
	BAY 06	O	E, W	
	CORRIDOR 01	O	N, E, W	
	CORRIDOR 02	O	N, S	
	CORRIDOR 03	O	N, S	
	EXTERIOR	O	N, E, W	
TROWELED-ON TEXTURE, WHITE, CHALKY	PATIO	C	*	S
	BAY 01	W	N, E, S	
	OFFICE 09	W	N, E, W, S	
	ABYSS	W	N, W, S	
	BAY 02	W	N, E, S	
	TOOL CRIB 03	W	N, W, S	
	BAY 03	W	N, E, S	
	TOOL CRIB 04	W	N, W, S	
	BAY 04	W	N, E, S	
	STORAGE 04	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 05	W	N, W, S	
	BAY 05	W	N, E, S	
	BAY 06	W	N	
	EXTERIOR	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROVELED-ON TEXTURE, WHITE, CHALKY	PATIO	C	*	S
	BAY 01	W	N, E, S	
	OFFICE 09	W	N, E, W, S	
	ABYSS	W	N, W, S	
	BAY 02	W	N, E, S	
	TOOL CRIB 03	W	N, W, S	
	BAY 03	W	N, E, S	
	TOOL CRIB 04	W	N, W, S	
	BAY 04	W	N, E, S	
	STORAGE 04	W	N, E, W, S	
	STORAGE 05	W	N, W, S	
	BAY 05	W	N, E, S	
	BAY 06	W	N	
	EXTERIOR	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	PATIO	C	*	S
	BAY 01	W	N, E, S	
	OFFICE 09	W	N, E, W, S	
	ABYSS	W	N, W, S	
	BAY 02	W	N, E, S	
	TOOL CRIB 03	W	N, W, S	
	BAY 03	W	N, E, S	
	TOOL CRIB 04	W	N, W, S	
	BAY 04	W	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	STORAGE 04	W	N, E, W, S	
	STORAGE 05	W	N, W, S	
	BAY 05	W	N, E, S	
	BAY 06	W	N	
	EXTERIOR	C	*	
SEALANT (DOORS, WINDOWS, FIXTURES), WHITE, PLIABLE	BUS REPAIR	O	N, E	S
	TOOL CRIB 01	O	S	
	OFFICE 01	O	S	
	STORAGE 01	O	N, S	
	STORAGE 02	O	S	
	DELIVERIES	O	S	
	VESTIBULE	O	E	
	OFFICE 02	O	N, W	
	OFFICE 03	O	N, E	
	OFFICE 04	O	S	
	OFFICE 05	O	W	
	ROUTING	O	W	
	DISPATCH	O	W	
	RECEPTION 01	O	N, E, S	
	DIRECTOR	O	S	
	HALL 01	O	N, E, W	
	LOUNGE	O	E, W, S	
	LOCKSMITH	O	E, W	
	JANITOR	O	E, W, S	
	MEN'S RESTROOM	O	N, S	
	WOMEN'S RESTROOM	O	N, E, S	
	TOOL CRIB 02	O	W	
	BENCH STOCK	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	PLAN ROOM	O	N, E	
	OFFICE 06	O	S	
	OFFICE 07	O	N	
	OFFICE 08	O	N	
	STORAGE 03	O	W	
	RECEPTION 02	O	E, S	
	LOBBY	O	W	
	CONFERENCE	O	N, E	
	BAY 01	O	N, E, S	
	OFFICE 09	O	N	
	ABYSS	O	W	
	BAY 02	O	N, E, S	
	TOOL CRIB 03	O	W	
	BAY 03	O	N, E	
	BAY 04	O	E, S	
	STORAGE 04	O	E, W	
	STORAGE 05	O	W	
	BAY 05	O	N	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	W	
	CORRIDOR 03	O	E, W, S	
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	TOOL CRIB 01	O	N, E, W, S	S
	OFFICE 01	O	N, E, W, S	
	STORAGE 01	O	N, E, W, S	
	STORAGE 02	O	N, E, W, S	
	DELIVERIES	O	N, E, W, S	
	OFFICE 02	O	N, E, W, S	
	LOUNGE	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	JANITOR	O	N, E, W, S	
	TOOL CRIB 02	O	N, E, W, S	
	BENCH STOCK	O	N, E, W, S	
	PLAN ROOM	O	N, E, W, S	
	OFFICE 06	O	N, E, W, S	
	OFFICE 07	O	N, E, W, S	
	OFFICE 08	O	N, E, W, S	
	STORAGE 03	O	N, E, W, S	
	RECEPTION 02	O	N, E, W, S	
	LOBBY	O	N, E, W, S	
	BAY 01	O	N, E, W, S	
	ABYSS	O	N, E, W, S	
	BAY 02	O	N, E, W, S	
	TOOL CRIB 03	O	N, E, W, S	
	BAY 03	O	N, E, W, S	
	TOOL CRIB 04	O	N, E, W, S	
	BAY 04	O	N, E, W, S	
	STORAGE 04	O	N, E, W, S	
	STORAGE 05	O	N, E, W, S	
	BAY 05	O	N, E, W, S	
	BAY 06	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	TOOL CRIB 01	O	N, E, W, S	S
	OFFICE 01	O	N, E, W, S	
	STORAGE 01	O	N, E, W, S	
	STORAGE 02	O	N, E, W, S	

JOB NAME: Comprehensive AHERA Asbestos Inspection
 Ben Furlong Education Center, KSD
 Building T

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/I/O	N/E/W/S	N/S
	DELIVERIES	O	N, E, W, S	
	OFFICE 02	O	N, E, W, S	
	LOUNGE	O	N, W, S	
	JANITOR	O	N, E, W, S	
	TOOL CRIB 02	O	N, E, W, S	
	BENCH STOCK	O	N, E, W, S	
	PLAN ROOM	O	N, E, W, S	
	OFFICE 06	O	N, E, W, S	
	OFFICE 07	O	N, E, W, S	
	OFFICE 08	O	N, E, W, S	
	STORAGE 03	O	N, E, W, S	
	RECEPTION 02	O	N, E, W, S	
	LOBBY	O	N, E, W, S	
	BAY 01	O	N, E, W, S	
	ABYSS	O	N, E, W, S	
	BAY 02	O	N, E, W, S	
	TOOL CRIB 03	O	N, E, W, S	
	BAY 03	O	N, E, W, S	
	TOOL CRIB 04	O	N, E, W, S	
	BAY 04	O	N, E, W, S	
	STORAGE 04	O	N, E, W, S	
	STORAGE 05	O	N, E, W, S	
	BAY 05	O	N, E, W, S	
	BAY 06	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	OFFICE 01	F	*	S
	DELIVERIES	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	VESTIBULE	F	*	
	OFFICE 02	F	*	
	LOUNGE	F	*	
	OFFICE 10	F	*	
MASTIC, YELLOW, PLIABLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	OFFICE 01	F	*	S
	DELIVERIES	F	*	
	VESTIBULE	F	*	
	OFFICE 02	F	*	
	LOUNGE	F	*	
	OFFICE 10	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	OFFICE 01	C, W	N, E, W, S	S
	DELIVERIES	C, W	E, S	
	VESTIBULE	C, W	N, E, W, S	
	OFFICE 02	C, W	N, E, W, S	
	OFFICE 03	W	N, E, W, S	
	OFFICE 04	W	N, E, W, S	
	OFFICE 05	W	N, E, W, S	
	ROUTING	W	N, E, W, S	
	DISPATCH	W	N, E, W, S	
	RECEPTION 01	W	N, E, W, S	
	DIRECTOR	C, W	N, E, W, S	
	HALL 01	W	N, E, W, S	
	LOUNGE	W	N, E, W, S	
	LOCKSMITH	W	N, E, W, S	
	TOOL CRIB 02	C, W	E, W, S	
	BENCH STOCK	W	N, E, W, S	
	PLAN ROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	OFFICE 06	W	N, E, W, S	
	OFFICE 07	W	N, E, W, S	
	OFFICE 08	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	RECEPTION 02	W	N, E, W, S	
	LOBBY	W	N, E, W, S	
	CONFERENCE	W	N, E, W, S	
	OFFICE 10	W	N, E, W, S	
	OFFICE 11	W	N, E, W, S	
	CORRIDOR 01	W	N, E, W, S	
	CORRIDOR 02	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	OFFICE 01	C, W	N, E, W, S	S
	DELIVERIES	C, W	E, S	
	VESTIBULE	C, W	N, E, W, S	
	OFFICE 02	C, W	N, E, W, S	
	OFFICE 03	W	N, E, W, S	
	OFFICE 04	W	N, E, W, S	
	OFFICE 05	W	N, E, W, S	
	ROUTING	W	N, E, W, S	
	DISPATCH	W	N, E, W, S	
	RECEPTION 01	W	N, E, W, S	
	DIRECTOR	C, W	N, E, W, S	
	HALL 01	W	N, E, W, S	
	LOUNGE	W	N, E, W, S	
	LOCKSMITH	W	N, E, W, S	
	TOOL CRIB 02	C, W	E, W, S	
	BENCH STOCK	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	PLAN ROOM	W	N, E, W, S	
	OFFICE 06	W	N, E, W, S	
	OFFICE 07	W	N, E, W, S	
	OFFICE 08	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	RECEPTION 02	W	N, E, W, S	
	LOBBY	W	N, E, W, S	
	CONFERENCE	W	N, E, W, S	
	OFFICE 10	W	N, E, W, S	
	OFFICE 11	W	N, E, W, S	
	CORRIDOR 01	W	N, E, W, S	
	CORRIDOR 02	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	OFFICE 01	C, W	N, E, W, S	S
	DELIVERIES	C, W	E, S	
	VESTIBULE	C, W	N, E, W, S	
	OFFICE 02	C, W	N, E, W, S	
	OFFICE 03	W	N, E, W, S	
	OFFICE 04	W	N, E, W, S	
	OFFICE 05	W	N, E, W, S	
	ROUTING	W	N, E, W, S	
	DISPATCH	W	N, E, W, S	
	RECEPTION 01	W	N, E, W, S	
	DIRECTOR	C, W	N, E, W, S	
	HALL 01	W	N, E, W, S	
	LOUNGE	W	N, E, W, S	
	LOCKSMITH	W	N, E, W, S	
	TOOL CRIB 02	C, W	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	BENCH STOCK	W	N, E, W, S	
	PLAN ROOM	W	N, E, W, S	
	OFFICE 06	W	N, E, W, S	
	OFFICE 07	W	N, E, W, S	
	OFFICE 08	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	RECEPTION 02	W	N, E, W, S	
	LOBBY	W	N, E, W, S	
	CONFERENCE	W	N, E, W, S	
	OFFICE 10	W	N, E, W, S	
	OFFICE 11	W	N, E, W, S	
	CORRIDOR 01	W	N, E, W, S	
	CORRIDOR 02	W	N, E, W, S	
WALLBASE (COVERED), 4", TAN, VINYL-LIKE	VESTIBULE	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", TAN, VINYL-LIKE	VESTIBULE	O	N, E, W, S	S
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	OFFICE 02	W	E, W	S
	PLAN ROOM	W	W	
	OFFICE 07	W	E	
	OFFICE 08	W	E	
	RECEPTION 02	W	S	
	OFFICE 10	W	N, E, W	
	OFFICE 11	W	E	
	CORRIDOR 01	W	E	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	OFFICE 03	C	*	S
	OFFICE 04	C	*	
	OFFICE 05	C	*	
	ROUTING	C	*	
	DISPATCH	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	RECEPTION 01	C	*	
	DIRECTOR	C	*	
	LOUNGE	C	*	
	LOCKSMITH	C	*	
	BENCH STOCK	C	*	
	PLAN ROOM	C	*	
	OFFICE 06	C	*	
	OFFICE 07	C	*	
	OFFICE 08	C	*	
	STORAGE 03	C	*	
	RECEPTION 02	C	*	
	LOBBY	C	*	
	CONFERENCE	C	*	
	CORRIDOR 01	C	*	
	CORRIDOR 02	C	*	
	CORRIDOR 03	C	*	
VINYL COMPOSITION TILE, 12"X12", LIGHT BROWN, SMOOTH, BROWN MOTTLES	RECEPTION 01	F	*	S
	LOCKSMITH	F	*	
	JANITOR	F	*	
	BENCH STOCK	F	*	
	RECEPTION 02	F	*	
	LOBBY	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
	CORRIDOR 03	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", LIGHT BROWN, SMOOTH, BROWN MOTTLES	RECEPTION 01	F	*	S
	LOCKSMITH	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	JANITOR	F	*	
	BENCH STOCK	F	*	
	RECEPTION 02	F	*	
	LOBBY	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
	CORRIDOR 03	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, SMALL PINHOLES AND WIDE FISSURES, WHITE	OFFICE 03	C	*	S
	OFFICE 04	C	*	
	OFFICE 05	C	*	
	ROUTING	C	*	
	DISPATCH	C	*	
	RECEPTION 01	C	*	
	DIRECTOR	C	*	
	LOUNGE	C	*	
	LOCKSMITH	C	*	
	BENCH STOCK	C	*	
	PLAN ROOM	C	*	
	OFFICE 06	C	*	
	OFFICE 07	C	*	
	OFFICE 08	C	*	
	STORAGE 03	C	*	
	RECEPTION 02	C	*	
	LOBBY	C	*	
	CONFERENCE	C	*	
	CORRIDOR 01	C	*	
	CORRIDOR 02	C	*	
	CORRIDOR 03	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, LARGE PINHOLES AND FISSURES, WHITE	OFFICE 03	C	*	S
	OFFICE 04	C	*	
	OFFICE 05	C	*	
	ROUTING	C	*	
	DISPATCH	C	*	
	RECEPTION 01	C	*	
	DIRECTOR	C	*	
	LOUNGE	C	*	
	LOCKSMITH	C	*	
	BENCH STOCK	C	*	
	PLAN ROOM	C	*	
	OFFICE 06	C	*	
	OFFICE 07	C	*	
	OFFICE 08	C	*	
	STORAGE 03	C	*	
	RECEPTION 02	C	*	
	LOBBY	C	*	
	CONFERENCE	C	*	
	CORRIDOR 01	C	*	
	CORRIDOR 02	C	*	
	CORRIDOR 03	C	*	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	CONFERENCE	F	*	S
	OFFICE 09	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	CONFERENCE	F	*	S
	OFFICE 09	F	*	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	RECEPTION 01	O	N, W	S
	CONFERENCE	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 09	O	N, E, W, S	
	CORRIDOR 03	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	RECEPTION 01	O	N, W	S
	CONFERENCE	O	N, E, W, S	
	OFFICE 09	O	N, E, W, S	
	CORRIDOR 03	O	N, E, W, S	
CARPET, TAN, FIBROUS, RED STRIPES	OFFICE 03	F	*	S
	OFFICE 04	F	*	
	OFFICE 05	F	*	
	ROUTING	F	*	
	DISPATCH	F	*	
	RECEPTION 01	F	*	
	DIRECTOR	F	*	
	HALL 01	F	*	
	PLAN ROOM	F	*	
	OFFICE 06	F	*	
	OFFICE 07	F	*	
	OFFICE 08	F	*	
	STORAGE 03	F	*	
	RECEPTION 02	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, TAN, FIBROUS, RED STRIPES	OFFICE 03	F	*	S
	OFFICE 04	F	*	
	OFFICE 05	F	*	
	ROUTING	F	*	
	DISPATCH	F	*	
	RECEPTION 01	F	*	
	DIRECTOR	F	*	
	HALL 01	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	PLAN ROOM	F	*	
	OFFICE 06	F	*	
	OFFICE 07	F	*	
	OFFICE 08	F	*	
	STORAGE 03	F	*	
	RECEPTION 02	F	*	
CARPET (COVED), 4", BLACK, FIBROUS	OFFICE 03	O	N, E, W, S	S
	OFFICE 04	O	N, E, W, S	
	OFFICE 05	O	N, E, W, S	
	ROUTING	O	N, E, W, S	
	DISPATCH	O	N, E, W, S	
	RECEPTION 01	O	N, E, W, S	
	DIRECTOR	O	N, E, W, S	
	HALL 01	O	N, E, W, S	
GLAZED WALL TILE, 4"x4", WHITE, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	JANITOR	W	E, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"x4", BLACK, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	JANITOR	W	E, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"x4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"x4", BLACK, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	JANITOR	W	E, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
QUARRY/PAVER TILE, 8"x8", BLACK, SMOOTH, GRAY SPECKS	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 8"x8", BLACK, SMOOTH, GRAY SPECKS	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	TOOL CRIB 02	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	TOOL CRIB 02	F	*	S
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	TOOL CRIB 02	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	TOOL CRIB 02	F	*	S
TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER	ABYSS	W	E	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM	C, W	N, E, W, S	S
	JANITOR	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM	C, W	N, E, W, S	S
	JANITOR	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM	C, W	N, E, W, S	S
	JANITOR	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", LIGHT BLUE, SMOOTH, WHITE MOTTLES	OFFICE 10	F	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building U*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	STORAGE 01	F	*	S
	STORAGE 02	F	*	
	STORAGE 03	F	*	
	EXTERIOR	F	*	
SIDING (METAL), FACTORY FINISH	EXTERIOR	W	N, E, W, S	N
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (DUCT), GRAY, PLIABLE	ROOF	O	*	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	O	N, E, W, S	S
	ROOF	O	N, E, W, S	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	WAREHOUSE 01	W	N, W	S
	OFFICE 01	W	N, E	
	OFFICE 03	W	W, S	
	STORAGE 01	W	W, S	
	OFFICE 05	W	E, S	
	STORAGE 02	W	W	
	WAREHOUSE 03	W	N, E	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	WAREHOUSE 01	W	N, W	S
	OFFICE 01	W	N, E	
	OFFICE 03	W	W, S	
	STORAGE 01	W	W, S	
	OFFICE 05	W	E, S	
	STORAGE 02	W	W	
	WAREHOUSE 03	W	N, E	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, WHITE, PLIABLE	WAREHOUSE 01	W	N, W	S
	OFFICE 01	W	N, E	
	OFFICE 03	W	W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 01	W	W, S	
	OFFICE 05	W	E, S	
	STORAGE 02	W	W	
	WAREHOUSE 03	W	N, E	
	EXTERIOR	W	N, E, W, S	
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LOBBY	F	*	S
	TELLER STORAGE	F	*	
	TELLERS	F	*	
	WAREHOUSE 01	F	*	
	OFFICE 01	F	*	
	FOOD STORAGE	F	*	
	FREEZER	F	*	
	OFFICE 02	F	*	
	CLERICAL	F	*	
	WAREHOUSE 02	F	*	
	UNISEX RESTROOM 01	F	*	
	UNISEX RESTROOM 02	F	*	
	OFFICE 03	F	*	
	OFFICE 04	F	*	
	SERVER ROOM	F	*	
	STORAGE 01	F	*	
	OFFICE 05	F	*	
	STORAGE 02	F	*	
	UNISEX RESTROOM 03	F	*	
	STORAGE 03	F	*	
	OPEN OFFICE	F	*	
	STORAGE 04	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STAIR WELL	F	*	
	STORAGE 05	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
SEALANT (DOORS), GRAY, PLIABLE	EXTERIOR	O	N, E, S	S
SEALANT (DOORS, WINDOWS), BLACK, PLIABLE	EXTERIOR	O	N, E, W, S	S
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOBBY	O	E	S
	WAREHOUSE 01	O	N, E, W	
	OFFICE 01	O	E, S	
	FOOD STORAGE	O	E	
	CLERICAL	O	E, W, S	
	WAREHOUSE 02	O	N, W, S	
	UNISEX RESTROOM 01	O	W	
	UNISEX RESTROOM 02	O	E	
	SERVER ROOM	O	N, S	
	OFFICE 05	O	S	
	UNISEX RESTROOM 03	O	S	
	OPEN OFFICE	O	W	
	STORAGE 04	O	E	
	STAIR WELL	O	W	
	HALL 01	O	E	
	OFFICE 06	O	W	
	EXTERIOR	O	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	WAREHOUSE 01	C	*	S
	OFFICE 01	C	*	
	OFFICE 02	C	*	
	UNISEX RESTROOM 02	C	*	
	OFFICE 04	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	SERVER ROOM	C	*	
	STORAGE 01	C	*	
	STAIR WELL	C	*	
	HALL 01	C	*	
	OFFICE 06	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WAREHOUSE 01	C, W	N, E, W, S	S
	OFFICE 01	W	E, W, S	
	FOOD STORAGE	W	E	
	FREEZER	W	E, S	
	WAREHOUSE 02	C, W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 02	W	N, E, W, S	
	OFFICE 03	C, W	N	
	SERVER ROOM	W	W	
	STORAGE 02	C, W	E, S	
	STAIR WELL	W	N, E, W, S	
	WAREHOUSE 03	W	W, S	
	HALL 01	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WAREHOUSE 01	C, W	N, E, W, S	S
	OFFICE 01	W	E, W, S	
	FOOD STORAGE	W	E	
	FREEZER	W	E, S	
	WAREHOUSE 02	C, W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 02	W	N, E, W, S	
	OFFICE 03	C, W	N	
	SERVER ROOM	W	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 02	C, W	E, S	
	STAIR WELL	W	N, E, W, S	
	WAREHOUSE 03	W	W, S	
	HALL 01	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	WAREHOUSE 01	C, W	N, E, W, S	S
	OFFICE 01	W	E, W, S	
	FOOD STORAGE	W	E	
	FREEZER	W	E, S	
	WAREHOUSE 02	C, W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 02	W	N, E, W, S	
	OFFICE 03	C, W	N	
	SERVER ROOM	W	W	
	STORAGE 02	C, W	E, S	
	STAIR WELL	W	N, E, W, S	
	WAREHOUSE 03	W	W, S	
	HALL 01	W	N, E, W, S	
BRICK, 3"X8", RED, CEMENTITIOUS	WAREHOUSE 01	W	S	S
	FOOD STORAGE	W	N, W, S	
	FREEZER	W	N	
	WAREHOUSE 02	W	N, E, W, S	
	OFFICE 03	W	E, W, S	
	SERVER ROOM	W	N, W	
	STORAGE 01	W	N	
	OFFICE 05	W	N	
	STORAGE 02	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	WAREHOUSE 01	W	S	S

JOB NAME: Comprehensive AHERA Asbestos Inspection
 Ben Furlong Education Center, KSD
 Building W

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	FOOD STORAGE	W	N, W, S	
	FREEZER	W	N	
	WAREHOUSE 02	W	N, E, W, S	
	OFFICE 03	W	E, W, S	
	SERVER ROOM	W	N, W	
	STORAGE 01	W	N	
	OFFICE 05	W	N	
	STORAGE 02	W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	OFFICE 01	F	*	S
	UNISEX RESTROOM 01	F	*	
	UNISEX RESTROOM 02	F	*	
	OFFICE 03	F	*	
	OFFICE 04	F	*	
	SERVER ROOM	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	OFFICE 01	F	*	S
	UNISEX RESTROOM 01	F	*	
	UNISEX RESTROOM 02	F	*	
	OFFICE 03	F	*	
	OFFICE 04	F	*	
	SERVER ROOM	F	*	
SEALANT (DOORS, WINDOWS, FIXTURES), WHITE, PLIABLE	WAREHOUSE 01	O	N, E	S
	OFFICE 01	O	E, W, S	
	FOOD STORAGE	O	E	
	OFFICE 02	O	W, S	
	WAREHOUSE 02	O	W, S	
	CLERICAL	O	N, E, W, S	
	UNISEX RESTROOM 01	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	UNISEX RESTROOM 02	O	E, W	
	OFFICE 03	O	S	
	OFFICE 04	O	N	
	OFFICE 05	O	N, E, S	
	STORAGE 02	O	N	
	STAIR WELL	O	W	
	WAREHOUSE 03	O	S	
	HALL 01	O	N, E	
	OFFICE 06	O	W	
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	WAREHOUSE 01	O	N, E, W	S
	OFFICE 01	O	N, E, W, S	
	FOOD STORAGE	O	E	
	FREEZER	O	E, S	
	OFFICE 02	O	N, E, W, S	
	OFFICE 03	O	N, E, W, S	
	OFFICE 04	O	N, E, W, S	
	SERVER ROOM	O	N, E, W, S	
	STORAGE 01	O	E	
	OFFICE 05	O	W	
	STAIR WELL	O	N, E, W, S	
	HALL 01	O	N, E, W, S	
	OFFICE 06	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	WAREHOUSE 01	O	N, E, W	S
	OFFICE 01	O	N, E, W, S	
	FOOD STORAGE	O	E	
	FREEZER	O	E, S	
	OFFICE 02	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 03	O	N, E, W, S	
	OFFICE 04	O	N, E, W, S	
	SERVER ROOM	O	N, E, W, S	
	STORAGE 01	O	E	
	OFFICE 05	O	W	
	STAIR WELL	O	N, E, W, S	
	HALL 01	O	N, E, W, S	
	OFFICE 06	O	N, E, W, S	
SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	FOOD STORAGE	C	*	S
	FREEZER	C	*	
	WAREHOUSE 02	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	FOOD STORAGE	C	*	S
	FREEZER	C	*	
	WAREHOUSE 02	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	FOOD STORAGE	C	*	S
	FREEZER	C	*	
	WAREHOUSE 02	C	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	STORAGE 01	C	*	S
	OFFICE 05	C	*	
CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED SPECKS	OFFICE 02	F	*	S
	CLERICAL	F	*	
	WAREHOUSE 02	F	*	
	STORAGE 01	F	*	
	OFFICE 05	F	*	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	STORAGE 01	O	N, W, S	S
	STORAGE 02	O	N, E, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	STORAGE 01	O	N, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 02	O	N, E, S	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	UNISEX RESTROOM 02	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	UNISEX RESTROOM 02	O	N, E, W, S	S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	CLERICAL	C	*	S
	WAREHOUSE 02	C	*	
	UNISEX RESTROOM 01	C	*	
WALLBASE (COVED), 4", LIGHT BROWN, VINYL-LIKE	CLERICAL	O	N, E, W, S	S
	WAREHOUSE 02	O	W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", LIGHT BROWN, VINYL-LIKE	CLERICAL	O	N, E, W, S	S
	WAREHOUSE 02	O	W, S	
SEALANT (MILLWORK), GRAY, PLIABLE	WAREHOUSE 02	O	W, S	S
CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	STAIR WELL	F	*	S
	HALL 01	F	*	
	OFFICE 06	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	STAIR WELL	F	*	S
	HALL 01	F	*	
	OFFICE 06	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	LOBBY	C	*	S
	TELLER STORAGE	C	*	
	TELLERS	C	*	
	STORAGE 03	C	*	
	OPEN OFFICE	C	*	
	STORAGE 04	C	*	
	STORAGE 05	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	W	N, E, W, S	S
	TELLER STORAGE	W	N, E, W, S	
	TELLERS	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 03	W	N, E, W, S	
	OPEN OFFICE	W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	STORAGE 05	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	W	N, E, W, S	S
	TELLER STORAGE	W	N, E, W, S	
	TELLERS	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	OPEN OFFICE	W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	STORAGE 05	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	W	N, E, W, S	S
	TELLER STORAGE	W	N, E, W, S	
	TELLERS	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	OPEN OFFICE	W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	STORAGE 05	W	N, E, W, S	
QUARRY/PAVER TILE, 18"X18", WHITE, SMOOTH	LOBBY	F	*	S
	STORAGE 03	F	*	
	OPEN OFFICE	F	*	
	STORAGE 04	F	*	
	STORAGE 05	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 18"X18", WHITE, SMOOTH	LOBBY	F	*	S
	STORAGE 03	F	*	
	OPEN OFFICE	F	*	
	STORAGE 04	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 05	F	*	
CARPET, TAN, FIBROUS, BROWN PATTERN	TELLER STORAGE	F	*	S
	TELLERS	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, TAN, FIBROUS, BROWN PATTERN	TELLER STORAGE	F	*	S
	TELLERS	F	*	
WALLBASE (COVERED), 4", PURPLE, VINYL-LIKE	LOBBY	O	N, E, W, S	S
	TELLER STORAGE	O	N, E, W, S	
	TELLERS	O	N, E, W, S	
	UNISEX RESTROOM 03	O	N, E, W, S	
	OPEN OFFICE	O	N, E, W, S	
	STORAGE 04	O	N, E, W, S	
	STORAGE 05	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", PURPLE, VINYL-LIKE	LOBBY	O	N, E, W, S	S
	TELLER STORAGE	O	N, E, W, S	
	TELLERS	O	N, E, W, S	
	UNISEX RESTROOM 03	O	N, E, W, S	
	OPEN OFFICE	O	N, E, W, S	
	STORAGE 04	O	N, E, W, S	
	STORAGE 05	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	LOBBY	O	E	S
	UNISEX RESTROOM 03	O	N, S	
	OPEN OFFICE	O	E, W, S	
SEALANT (WINDOWS), BLACK, PLIABLE	OPEN OFFICE	O	W	S
	STORAGE 05	O	E	
VINYL SHEET FLOORING, WHITE, SMOOTH, 4"X4" PATTERN, GRAY PAPER BACKING	UNISEX RESTROOM 03	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, 4"X4" PATTERN, GRAY PAPER BACKING	UNISEX RESTROOM 03	F	*	S
PANELING (WOOD), WHITE, SMOOTH	UNISEX RESTROOM 03	O	W, S	N

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH PANELING (WOOD), WHITE, SMOOTH	UNISEX RESTROOM 03	O	W, S	S
ASBESTOS CEMENT BOARD, GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	C	*	S

* - **Not Applicable**

. END OF TABLE .

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Canopy*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	CANOPY	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	CANOPY	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
ASPHALT (FOUNDATION), BLACK, ASPHALTIC	CANOPY	F	*	S
	EXTERIOR	W	N, E, W, S	
SIDING (METAL), FACTORY FINISH	EXTERIOR	W	N, E, W, S	N
PANELING (METAL), FACTORY FINISH	ROOF	O	*	N

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Residence*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM
		C/W/F/O	N/E/W/S	N/S
SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	LIVING ROOM	C	*	S
	LAUNDRY ROOM	C	*	
	HALLWAY	C	*	
	BEDROOM 02	C	*	
	BEDROOM 03	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	DINING ROOM	C	*	
	LIVING ROOM	C, W	N, E, S	S
	LAUNDRY ROOM	C	*	
	HALLWAY	C	*	
	BEDROOM 02	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	BEDROOM 03	C, W	N, E, W, S	
	DINING ROOM	C, W	N, E, W, S	
	LIVING ROOM	C, W	N, E, S	S
	LAUNDRY ROOM	C	*	
	HALLWAY	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BEDROOM 02	C, W	N, E, W, S	
	BEDROOM 03	C, W	N, E, W, S	
	DINING ROOM	C, W	N, E, W, S	
	LIVING ROOM	W	E	S
	RESTROOM 1	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM 2	C, W	N, E, W, S	
	KITCHEN	C, W	N, E, W, S	
	LIVING ROOM	W	E	S
	RESTROOM 1	C, W	N, E, W, S	
	RESTROOM 2	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Residence*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	KITCHEN	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LIVING ROOM	W	E	S
	RESTROOM 1	C, W	N, E, W, S	
	RESTROOM 2	C, W	N, E, W, S	
	KITCHEN	C, W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LIVING ROOM	C	*	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LIVING ROOM	C	*	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LIVING ROOM	C	*	S
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED GRID, GRAY PAPER BACKING	DINING ROOM	F	*	S
	KITCHEN	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED GRID, GRAY PAPER BACKING AND CARPET, BROWN, FIBROUS	DINING ROOM	F	*	S
	KITCHEN	F	*	
CARPET, BROWN, FIBROUS	LIVING ROOM	F	*	S
	BEDROOM 01	F	*	
	HALLWAY	F	*	
	BEDROOM 02	F	*	
	BEDROOM 03	F	*	
WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	LIVING ROOM	O	N, E, W, S	S
	BEDROOM 01	O	N, E, W, S	
	HALLWAY	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	LIVING ROOM	O	N, E, W, S	S
	BEDROOM 01	O	N, E, W, S	
	HALLWAY	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	BEDROOM 01	O	N, E, W, S	S
	RESTROOM 01	O	N, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Residence*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/I/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	BEDROOM 02	O	N, W	
	BEDROOM 03	O	N, E	
	RESTROOM 2	O	W	
	KITCHEN	O	N, E	
	DINING ROOM	O	S	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	RESTROOM 1	W	N, E, W	S
	RESTROOM 2	W	N, E, W	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	RESTROOM 1	W	N, E, W	S
	RESTROOM 2	W	N, E, W	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, OFF-WHITE MOTTLES	RESTROOM 1	F	*	S
	RESTROOM 2	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, OFF-WHITE MOTTLES	RESTROOM 1	F	*	S
	RESTROOM 2	F	*	
ACOUSTICAL CEILING TILE, 1'X1', GRAY, SMOOTH, WHITE, MECHANICALLY ATTACHED	BEDROOM 01	C	*	S
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	BEDROOM 01	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	BEDROOM 01	F	*	S
CARPET (SELF-STICK SQUARES), 18"X18", GRAY, FIBROUS	LAUNDRY ROOM	F	*	S
CARPET (SELF-STICK SQUARES), 18"X18", GREEN, FIBROUS	LAUNDRY ROOM	F	*	S
SIDING (WOOD), PAINTED	EXTERIOR	W	N, E, W, S	N
COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	ROOF	O	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LIVING ROOM	F	*	S
	BEDROOM 01	F	*	
	LAUNDRY ROOM	F	*	
	HALLWAY	F	*	
	RESTROOM 1	F	*	
	BEDROOM 02	F	*	
	BEDROOM 03	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Residence*

JOB NO. 08-202

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	RESTROOM 2	F	*	
	KITCHEN	F	*	
	DINING ROOM	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
ASPHALT (ENTRIES), BLACK, ASPHALTIC	EXTERIOR	F	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage H*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
SIDING (WOOD), PAINTED	EXTERIOR	W	N, E, W, S	N

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage J*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	STORAGE J	F	*	S
	EXTERIOR	F	*	
SIDING (WOOD), PAINTED	EXTERIOR	W	N, E, W, S	N

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage O*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ASPHALT PREPARED ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	STORAGE O	F	*	S
	EXTERIOR	F	*	
SIDING (WOOD), PAINTED	EXTERIOR	W	N, E, W, S	N

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage P*

JOB NO. 08-202

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	STORAGE P	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	STORAGE P	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
PANELING (WOOD), PAINTED	STORAGE P	W	N, E, W, S	
SEALANT (EXPANSION), WHITE, PLIABLE	EXTERIOR	O	N, E, W, S	S
SIDING (METAL), FACTORY FINISH	EXTERIOR	W	N, E, W, S	N
ASPHALT, BLACK, ASPHALTIC	STORAGE P	F	*	S
	EXTERIOR	F	*	
COATING (ROOF), WHITE, SMOOTH	ROOF	O	*	S

* - *Not Applicable*

END OF TABLE

Report of Findings

Comprehensive AHERA Asbestos Inspection

Ben Furlong Education Center, KSD

FM Project 08-202

2.4 AHERA Inspection Procedures and Protocols

2.4.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.4.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.5 Visual Inspection

A visual inspection of the 21 buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.

2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING I
BUILDING K
BUILDING L
BUILDING M
BUILDING R
BUILDING T
BUILDING U
BUILDING W
CANOPY
RESIDENCE
STORAGE H
STORAGE J
STORAGE O
STORAGE P**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	58,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	20,000	SF
M-GWB-03	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	21,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	2,100	SF
M-CPT-05	CARPET, TAN, FIBROUS, RED STREAKS	S	NF	50,000	SF
M-MAS-06	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, TAN, FIBROUS, RED STREAKS	S	NF	50,000	SF
M-FDI-07	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,134	SF
M-WAB-08	WALLBASE (CARPET), 4", BLACK, FIBROUS	A	NF	1,000	SF
M-ADH-09	ADHESIVE, BLUE, PLIABLE, ASSOCIATED WITH WALLBASE (CARPET), 4", BLACK, FIBROUS	A	NF	1,000	SF
M-SLT-10	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	100	SF
M-TWP-11	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	A	NF	100	SF
S-SAT-12	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,300	SF
M-GWB-13	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,300	SF
S-JTC-14	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	330	SF
M-GWT-15	GLAZED WALL TILE, 2"X2", TAN, SMOOTH	A	NF	4,000	SF
M-GWT-16	GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	A	NF	500	SF
M-GRT-17	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 2"X2", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	A	NF	450	SF
M-CMT-18	CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	A	NF	2,200	SF
M-GRT-19	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	A	NF	220	SF
S-SAT-21	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	28,000	SF
M-GWB-22	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	28,000	SF
S-JTC-23	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	2,800	SF
M-QPT-24	QUARRY/PAVER TILE, 4"X4", GRAY, SMOOTH	A	NF	1,000	SF
M-QPT-25	QUARRY/PAVER TILE, 4"X4", TAN, SMOOTH, BLACK AND WHITE SPECKS	A	NF	1,000	SF
M-GRT-26	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 4"X4", GRAY, SMOOTH AND QUARRY/PAVER TILE, 4"X4", TAN, SMOOTH, BLACK AND WHITE SPECKS	A	NF	200	SF
M-APL-27	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	5,400	SF
M-VCT-28	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	3,000	SF
M-VCT-29	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BLACK SPOTS	A	NF	300	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building A*

JOB NO. 08-202

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·MAS·30	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES AND VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BLACK SPOTS	A	NF	3,300	SF
M·WAB·31	WALLBASE (COVED), 4", TAN, VINYL-LIKE	A	NF	150	SF
M·ADH·32	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", TAN, VINYL-LIKE	A	NF	150	SF
M·SLT·33	SEALANT (FIRE STOP), RED, PLIABLE	A	NF	2	SF
S·PLA·34	PLASTER, GRAY, CEMENTITIOUS	A	NF	500	SF
M·SLT·35	SEALANT (DOORS, WINDOWS), BLACK, GUMMY	A	NF	50	SF
M·GWB·36	GYPSUM WALLBOARD, WHITE, CHALKY, VINYL COVER	A	NF	5,500	SF
M·CPT·37	CARPET, BLUE, FIBROUS, BROWN AND WHITE SPOTS	A	NF	300	SF
M·MAS·38	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, BROWN AND WHITE SPOTS	A	NF	300	SF
M·CMU·39	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	300	SF
M·MRT·40	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	30	SF
M·CPT·41	CARPET, PURPLE, FIBROUS, GRAY SPECKS	A	NF	600	SF
M·MAS·42	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, PURPLE, FIBROUS, GRAY SPECKS	A	NF	600	SF
M·VST·43	VINYL STAIR TREAD, 12"X48", BLUE, CIRCLE PATTERN	A	NF	100	SF
M·VCT·44	VINYL COMPOSITION TILE, 18"X18", BLUE, CIRCLE PATTERN	A	NF	80	SF
M·MAS·45	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL STAIR TREAD, 12"X48", BLUE, CIRCLE PATTERN AND VINYL COMPOSITION TILE, 18"X18", BLUE, CIRCLE PATTERN	A	NF	180	SF
M·WAB·46	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	30	SF
M·ADH·47	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	30	SF
M·BUR·48	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	36,000	SF
M·MAS·49	MASTIC, (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	1,500	SF
M·SLT·50	SEALANT (FLASHINGS), BLACK, PLIABLE	A	NF	50	SF
M·CON·51	CONCRETE (TILT), GRAY, CEMENTITIOUS	A	NF	20,000	SF
S·STU·52	STUCCO, GRAY, CEMENTITIOUS	A	NF	20,000	SF
M·CON·53	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	70,000	SF
M·CON·54	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	700	SF
M·SLT·55	SEALANT (DOORS, WINDOWS), GRAY, PLIABLE	A	NF	5	SF
M·GAS·56	GASKETS, 1"-3", BLACK/GREEN, PAPER-LIKE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,100	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	3,500	SF
M-GWB-03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	3,500	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	350	SF
M-CPT-05	CARPET, GRAY, FIBROUS	A	NF	1,500	SF
M-MAS-06	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS	A	NF	1,500	SF
M-WAB-07	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	80	SF
M-ADH-08	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	80	SF
M-FDI-09	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	147	SF
M-CON-10	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	3,000	SF
M-CON-11	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	300	SF
M-ACT-12	ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	S	F	3,000	SF
M-ADH-13	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	A	NF	750	SF
M-GWB-14	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	3,000	SF
M-SLT-15	SEALANT (DOORS, FIXTURES), WHITE, PLIABLE	A	NF	14	SF
M-SAC-16	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	2	SF
S-SAT-17	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,100	SF
M-GWB-18	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,100	SF
S-JTC-19	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	110	SF
M-GWT-20	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	800	SF
M-GWT-21	GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	50	SF
M-GRT-22	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	85	SF
M-CMT-23	CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH	A	NF	500	SF
M-GRT-24	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH	A	NF	50	SF
M-WAB-25	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	10	SF
M-ADH-26	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	10	SF
M-SLT-27	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-GWB-28	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	1,300	SF
S-JTC-29	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	130	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building B*

JOB NO. 08-202

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·CPT·30	CARPET (SELF-STICK SQUARES), 2'X2', BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	600	SF
M·CPT·31	CARPET (COVE), 4", BLACK, FIBROUS	A	NF	35	SF
M·ADH·32	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH CARPET (COVE), 4", BLACK, FIBROUS	A	NF	35	SF
M·VCT·33	VINYL COMPOSITION TILE, 12"X12", LIGHT GRAY, SMOOTH, GRAY MOTTLES	A	NF	375	SF
M·MAS·34	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", LIGHT GRAY, SMOOTH, GRAY MOTTLES	A	NF	375	SF
M·WAB·35	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	30	SF
M·ADH·36	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE, 4", BLACK, VINYL-LIKE	A	NF	30	SF
M·APL·37	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	375	SF
M·SLT·38	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	1	SF
M·BRK·39	BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	3,500	SF
M·MRT·40	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	350	SF
M·BRK·41	BRICK, 4"X8", RED, CEMENTITIOUS	A	NF	1,400	SF
M·MRT·42	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X8", RED, CEMENTITIOUS	A	NF	140	SF
M·BUR·43	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	3,000	SF
M·MAS·44	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	150	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building C*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,600	SF
M-BRK-02	BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	2,500	SF
M-MRT-03	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	250	SF
S-SAT-04	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	500	SF
M-GWB-05	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	500	SF
S-JTC-06	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	50	SF
M-ACT-07	ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	S	F	2,700	SF
M-ADH-08	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	A	NF	675	SF
M-GWB-09	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	2,700	SF
M-VCT-10	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	A	NF	2,600	SF
M-MAS-11	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	A	NF	2,600	SF
M-WAB-12	WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	A	NF	75	SF
M-ADH-13	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	A	NF	75	SF
M-FDI-14	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	63	SF
M-CON-15	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	2,700	SF
M-CON-16	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	600	SF
M-SLT-17	SEALANT (DOORS), WHITE, PLIABLE	A	NF	3	SF
M-TWP-18	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	750	SF
M-WGP-19	WINDOW GLAZING PUTTY, WHITE, BRITTLE	A	NF	20	SF
M-SLT-20	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-APR-21	ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	2,700	SF
M-VBF-22	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	2,700	SF
M-MAS-23	MASTIC (PENETRATIONS), BLACK, TAR-LIKE	A	NF	50	SF
M-GWB-24	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	1,200	SF
S-JTC-25	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	120	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,000	SF
M-BRK-02	BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	3,600	SF
M-MRT-03	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	360	SF
S-SAT-04	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	800	SF
M-GWB-05	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	800	SF
S-JTC-06	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	80	SF
M-CPT-07	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,200	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,200	SF
M-WAB-09	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	150	SF
M-ADH-10	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	150	SF
M-SLT-11	SEALANT (DOORS, MILLWORK), WHITE, PLIABLE	A	NF	8	SF
M-ACT-12	ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	S	F	2,200	SF
M-ADH-13	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', BROWN, RIBBED, TAN	A	NF	550	SF
M-GWB-14	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	2,200	SF
M-GWB-15	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
S-JTC-16	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	30	SF
M-FDI-17	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	126	SF
M-CPT-18	CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	A	NF	600	SF
M-MAS-19	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	A	NF	600	SF
M-VCT-20	VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	A	NF	170	SF
M-MAS-21	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	A	NF	170	SF
M-WGP-22	WINDOW GLAZING PUTTY, GRAY, BRITTLE	A	NF	4	SF
M-SLT-23	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-GWB-24	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	1,000	SF
S-JTC-25	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M-CON-26	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	2,200	SF
M-CON-27	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	700	SF
M-SLT-28	SEALANT (FIRE STOP), RED, PLIABLE	A	NF	10	SF
M-APR-29	ASPHALT PREPARED ROOFING (SHINGLE), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	2,200	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building D*

JOB NO. 08-202

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VBF-30	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLE), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	2,200	SF
M-MAS-31	MASTIC (PENETRATIONS), BLACK, TAR-LIKE	A	NF	100	SF
M-GWB-32	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	140	SF
S-JTC-33	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	14	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building E*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,900	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	3,000	SF
M-GWB-03	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	3,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	300	SF
M-ADH-05	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	50	SF
M-VCT-06	VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, DARK GREEN MOTTLES	A	NF	1,400	SF
M-VCT-07	VINYL COMPOSITION TILE (PATTERN), 12"X12", BLUE, SMOOTH, BLACK MOTTLES	A	NF	300	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, DARK GREEN MOTTLES AND VINYL COMPOSITION TILE (PATTERN), 12"X12", BLUE, SMOOTH, BLACK MOTTLES	A	NF	2,000	SF
M-WAB-09	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	125	SF
M-ADH-10	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	125	SF
M-FDI-11	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	126	SF
M-CON-12	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	2,200	SF
M-CON-13	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	750	SF
M-SLT-14	SEALANT (DOORS, WINDOWS), WHITE, PLIABLE	A	NF	10	SF
S-SAT-15	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	750	SF
M-GWB-16	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	750	SF
S-JTC-17	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	75	SF
M-WAB-18	WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	A	NF	10	SF
M-ADH-19	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	A	NF	10	SF
M-CPT-20	CARPET, BLUE, FIBROUS	A	NF	250	SF
M-MAS-21	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS	A	NF	250	SF
M-CMU-22	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	600	SF
M-MRT-23	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	60	SF
M-GWB-24	GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	160	SF
M-SLT-25	SEALANT (DUCT), GRAY, PLIABLE	A	NF	10	SF
M-CTG-26	COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	A	NF	2,200	SF
M-MAS-27	MASTIC (PENETRATIONS), BLACK, TAR-LIKE	A	NF	50	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building E*

JOB NO. 08-202

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-WDB-28	WOVEN DUCT BOOT, 4", BLACK, RUBBER-LIKE	A	NF	5	SF
M-SLT-29	SEALANT (WINDOWS), GRAY, PLIABLE	A	NF	1	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building F*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CMU-01	CONCRETE MASONRY UNIT, 2"X16", GRAY, CEMENTITIOUS	A	NF	700	SF
M-CMU-02	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-MRT-03	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 2"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	230	SF
M-CON-04	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	800	SF
M-SLT-05	SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	A	NF	5	SF
M-FDI-06	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	42	SF
S-SAT-07	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	400	SF
M-GWB-08	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	400	SF
S-JTC-09	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	40	SF
M-WAB-10	WALLBASE (COVED), 4", TAN, VINYL-LIKE	A	NF	50	SF
M-ADH-11	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", TAN, VINYL-LIKE	A	NF	50	SF
M-EXJ-12	EXPANSION JOINT, GRAY, PLIABLE	A	NF	10	SF
M-TWP-13	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	100	SF
S-STU-14	STUCCO, GRAY, CEMENTITIOUS	A	NF	500	SF
M-BUR-15	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	800	SF
M-MAS-16	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	50	SF
M-SLT-17	SEALANT (FLASHINGS), WHITE, PLIABLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building G*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-SAT-01	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,600	SF
M-GWB-02	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,600	SF
S-JTC-03	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	360	SF
M-CPT-04	CARPET, GREEN, FIBROUS	A	NF	200	SF
M-MAS-05	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GREEN, FIBROUS	A	NF	200	SF
M-WAB-06	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	50	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	50	SF
M-SLT-08	SEALANT (DOORS, WINDOWS), WHITE, PLIABLE	A	NF	2	SF
M-VCT-09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	A	NF	450	SF
M-MAS-10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	A	NF	450	SF
M-CON-11	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	1,200	SF
M-BUR-12	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	1,200	SF
M-MAS-13	MASTIC (PENETRATIONS), BLACK, TAR-LIKE	A	NF	25	SF
M-CRS-14	CEMENTITIOUS ROOF SHINGLES (S-PATTERN), RED, CEMENTITIOUS	A	NF	1,000	SF
M-VBF-15	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH CEMENTITIOUS ROOF SHINGLES (S-PATTERN), RED, CEMENTITIOUS	A	NF	1,000	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building I*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-SAT-01	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M-GWB-02	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S-JTC-03	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M-VCT-04	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	150	SF
M-MAS-05	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	150	SF
M-WAB-06	WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	20	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	20	SF
M-SLT-08	SEALANT (DOORS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	15	SF
M-FDI-09	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	63	SF
M-VCT-10	VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH	A	NF	175	SF
M-MAS-11	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH	A	NF	175	SF
M-WAB-12	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	30	SF
M-ADH-13	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	30	SF
M-BUR-14	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	350	SF
M-MAS-15	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	40	SF
M-ASP-16	ASPHALT (ENTRIES), BLACK, ASPHALTIC	A	NF	350	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building K*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,700	SF
M-TWP-02	TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER, MECHANICALLY ATTACHED	S	NF	1,400	SF
M-CPT-03	CARPET, ORANGE, FIBROUS	A	NF	800	SF
M-MAS-04	MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH CARPET, ORANGE, FIBROUS	A	NF	800	SF
M-WAB-05	WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	A	NF	50	SF
M-ADH-06	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BROWN, VINYL-LIKE	A	NF	50	SF
M-FDI-07	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	42	SF
M-TWP-08	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	150	SF
M-SAC-09	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
S-SAT-10	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,800	SF
M-GWB-11	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,800	SF
S-JTC-12	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	280	SF
M-VCT-13	VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	A	NF	100	SF
M-MAS-14	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", CREAM, SMOOTH, TAN MOTTLES	A	NF	100	SF
M-SLT-15	SEALANT (DOORS, FIXTURES), WHITE, PLIABLE	A	NF	5	SF
S-SAT-16	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M-SAC-17	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
S-SAT-18	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	150	SF
M-GWB-19	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	150	SF
S-JTC-20	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	15	SF
M-CPT-21	CARPET, BLUE, FIBROUS	A	NF	900	SF
M-MAS-22	MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH CARPET, BLUE, FIBROUS	A	NF	900	SF
M-WAB-23	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	40	SF
M-ADH-24	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	40	SF
M-APR-25	ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	1,800	SF
M-VBF-26	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	1,800	SF
M-MAS-27	MASTIC (PENETRATIONS), BLACK, TAR-LIKE	A	NF	50	SF
M-ASP-28	ASPHALT (ENTRIES), BLACK, ASPHALTIC	A	NF	1,500	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building L*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,600	SF
M-TWP-02	TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER	S	NF	2,000	SF
M-CPT-03	CARPET, BROWN, FIBROUS	A	NF	1,600	SF
M-MAS-04	MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH CARPET, BROWN, FIBROUS	A	NF	1,600	SF
M-WAB-05	WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	A	NF	80	SF
M-ADH-06	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	A	NF	80	SF
M-FDI-07	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	42	SF
M-TWP-08	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	150	SF
M-SAC-09	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	2	SF
S-SAT-10	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	150	SF
M-GWB-11	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	150	SF
S-JTC-12	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	15	SF
M-APR-13	ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	2,100	SF
M-VBF-14	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	2,100	SF
M-MAS-15	MASTIC (PENETRATIONS), BLACK, TAR-LIKE	A	NF	50	SF
M-SLT-16	SEALANT (DOORS), WHITE, BRITTLE	A	NF	2	SF
M-ASP-17	ASPHALT (ENTRIES), BLACK, ASPHALTIC	A	NF	500	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building M*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-FDI-01	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	54	SF
M-CON-02	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	2,800	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building R*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CMU-01	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	2,000	SF
M-MRT-01	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED, WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	200	SF
M-CON-03	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	1,500	SF
M-FDI-04	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	42	SF
M-PES-05	PIPE END SEALANT, WHITE, PLIABLE	A	NF	30	SF
M-SLT-06	SEALANT (EQUIPMENT), BLACK, GUMMY	A	NF	10	SF
M-SLT-07	SEALANT (DOORS, FIXTURES), GRAY, PLIABLE	A	NF	5	SF
M-BUR-08	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	1,500	SF
M-MAS-09	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	30	SF
M-SLT-10	SEALANT (DUCT), GRAY, PLIABLE	A	NF	10	SF
S-STU-11	STUCCO, GRAY, CEMENTITIOUS	A	NF	2,500	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	35,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	700	SF
M-SLT-03	SEALANT (FLASHINGS), WHITE, PLIABLE	A	NF	25	SF
M-WDB-04	WOVEN DUCT BOOT, 4", BLACK, RUBBER-LIKE	A	NF	20	SF
M-SLT-05	SEALANT (DUCT), GRAY, PLIABLE	A	NF	30	SF
M-DST-06	DUCT SEAM TAPE, 4", WHITE, CANVAS	S	F	30	SF
M-CMU-07	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	9,000	SF
M-CMU-08	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	A	NF	4,500	SF
M-MRT-09	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	A	NF	1,350	SF
S-STU-10	STUCCO, GRAY, CEMENTITIOUS	A	NF	7,000	SF
S-STU-11	STUCCO, GRAY, CEMENTITIOUS	A	NF	2,000	SF
M-SLT-12	SEALANT (DOORS, WINDOWS, EXPANSION), GRAY, PLIABLE	A	NF	50	SF
M-CON-13	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	35,000	SF
M-CON-14	CONCRETE, GRAY, CEMENTITIOUS	A	NF	2,000	SF
M-ASP-15	ASPHALT (ENTRIES), BLACK, ASPHALTIC	A	NF	10,000	SF
M-FDI-16	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	462	SF
S-TOT-17	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	10,000	SF
M-GWB-18	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	10,000	SF
S-JTC-19	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	1,000	SF
M-SLT-20	SEALANT (DOORS, WINDOWS, FIXTURES), WHITE, PLIABLE	A	NF	30	SF
M-WAB-21	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	400	SF
M-ADH-22	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	400	SF
M-VCT-23	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	A	NF	3,000	SF
M-MAS-24	MASTIC, YELLOW, PLIABLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY MOTTLES	A	NF	3,000	SF
S-SAT-25	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
M-GWB-26	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
S-JTC-27	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	1,000	SF
M-WAB-28	WALLBASE (COVED), 4", TAN, VINYL-LIKE	A	NF	5	SF
M-ADH-29	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", TAN, VINYL-LIKE	A	NF	5	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building T*

JOB NO. 08-202

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-TWP-30	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	1,000	SF
M-APL-31	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	4,000	SF
M-VCT-32	VINYL COMPOSITION TILE, 12"X12", LIGHT BROWN, SMOOTH, BROWN MOTTLES	A	NF	4,000	SF
M-MAS-33	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", LIGHT BROWN, SMOOTH, BROWN MOTTLES	A	NF	4,000	SF
M-APL-34	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, SMALL PINHOLES AND WIDE FISSURES, WHITE	S	F	1,000	SF
M-APL-35	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, LARGE PINHOLES AND FISSURES, WHITE	S	F	1,000	SF
M-CPT-36	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M-MAS-37	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M-WAB-38	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	80	SF
M-ADH-39	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	80	SF
M-CPT-46	CARPET, TAN, FIBROUS, RED STRIPES	A	NF	6,000	SF
M-MAS-41	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, TAN, FIBROUS, RED STRIPES	A	NF	6,000	SF
M-CPT-42	CARPET (COVED), 4", BLACK, FIBROUS	A	NF	160	SF
M-GWT-43	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	1,200	SF
M-GWT-44	GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	A	NF	400	SF
M-GRT-45	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	A	NF	120	SF
M-QPT-46	QUARRY/PAVER TILE, 8"X8", BLACK, SMOOTH, GRAY SPECKS	A	NF	750	SF
M-GRT-47	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 8"X8", BLACK, SMOOTH, GRAY SPECKS	A	NF	75	SF
M-CPT-48	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	500	SF
M-MAS-49	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	500	SF
M-VCT-50	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	A	NF	250	SF
M-MAS-51	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	A	NF	250	SF
M-TWP-52	TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER	S	NF	250	SF
S-SAT-53	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	250	SF
M-GWB-54	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S-JTC-55	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	250	SF
M-VCT-56	VINYL COMPOSITION TILE, 12"X12", LIGHT BLUE, SMOOTH, WHITE MOTTLES	A	NF	50	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building U*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CON-01	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	2,800	SF
M-CON-02	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-CTG-03	COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING.	A	NF	2,800	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	10,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	100	SF
M-CTG-03	COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	A	NF	5,000	SF
M-MAS-04	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	50	SF
M-SLT-05	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
S-STU-06	STUCCO, GRAY, CEMENTITIOUS	A	NF	7,000	SF
M-CMU-07	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	A	NF	7,500	SF
M-MRT-08	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 8"X8" PATTERN	A	NF	750	SF
M-EXJ-09	EXPANSION JOINT, WHITE, PLIABLE	A	NF	30	SF
S-STU-10	STUCCO, GRAY, CEMENTITIOUS	A	NF	3,500	SF
M-CON-11	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	18,000	SF
M-CON-12	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	1,500	SF
M-SLT-15	SEALANT (DOORS), GRAY, PLIABLE	A	NF	7	SF
M-SLT-14	SEALANT (DOORS, WINDOWS), BLACK, PLIABLE	A	NF	18	SF
M-FDI-15	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	420	SF
M-APL-16	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,000	SF
S-SAT-17	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
M-GWB-18	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
S-JTC-19	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	350	SF
M-BRK-20	BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	5,000	SF
M-MRT-21	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 3"X8", RED, CEMENTITIOUS	A	NF	500	SF
M-VCT-22	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,000	SF
M-MAS-25	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,000	SF
M-SLT-24	SEALANT (DOORS, WINDOWS, FIXTURES), WHITE, PLIABLE	A	NF	30	SF
M-WAB-25	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	150	SF
M-ADH-26	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	150	SF
S-SAT-27	SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	S	F	8,000	SF
M-GWB-28	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	S	NF	350	SF
S-JTC-29	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	35	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Building W*

JOB NO. 08-202

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-30	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	800	SF
M-CPT-31	CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	30	SF
M-WAB-32	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	30	SF
M-ADH-33	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	30	SF
M-WAB-35	WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	8	SF
M-ADH-36	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	8	SF
M-APL-37	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	700	SF
M-WAB-38	WALLBASE (COVED), 4", LIGHT BROWN, VINYL-LIKE	A	NF	20	SF
M-ADH-39	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", LIGHT BROWN, VINYL-LIKE	A	NF	20	SF
M-SLT-40	SEALANT (MILLWORK), GRAY, PLIABLE	A	NF	1	SF
M-CPT-41	CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	A	NF	900	SF
M-MAS-42	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BROWN, FIBROUS, MULTI-COLORED SPECKS	A	NF	900	SF
M-APL-43	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,700	SF
S-SAT-44	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
M-GWB-45	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
S-JTC-46	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
M-QPT-47	QUARRY/PAVER TILE, 18"X18", WHITE, SMOOTH	A	NF	1,500	SF
M-GRT-48	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 18"X18", WHITE, SMOOTH	A	NF	150	SF
M-CPT-49	CARPET, TAN, FIBROUS, BROWN PATTERN	A	NF	350	SF
M-MAS-50	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, TAN, FIBROUS, BROWN PATTERN	A	NF	350	SF
M-WAB-51	WALLBASE (COVED), 4", PURPLE, VINYL-LIKE	A	NF	125	SF
M-ADH-52	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", PURPLE, VINYL-LIKE	A	NF	125	SF
M-SLT-53	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	7	SF
M-SLT-54	SEALANT (WINDOWS), BLACK, PLIABLE	A	NF	4	SF
M-VSF-55	VINYL SHEET FLOORING, WHITE, SMOOTH, 4"X4" PATTERN, GRAY PAPER BACKING	A	NF	75	SF
M-MAS-56	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, 4"X4" PATTERN, GRAY PAPER BACKING	A	NF	75	SF
M-ADH-57	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH PANELING (WOOD), WHITE, SMOOTH	A	NF	50	SF
M-ACB-58	ASBESTOS CEMENT BOARD, GRAY, CEMENTITIOUS, SMOOTH	A	NF	1,500	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Canopy*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CMU-01	CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	A	NF	650	SF
M-MRT-02	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	A	NF	65	SF
M-ASP-03	ASPHALT (FOUNDATION), BLACK, ASPHALTIC	A	NF	6,000	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Residence*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-SAT-01	SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	S	F	800	SF
M-GWB-02	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE (POPCORN), WHITE, CHALKY	A	NF	1,600	SF
S-JTC-03	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	160	SF
S-SAT-04	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,200	SF
M-GWB-05	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,200	SF
S-JTC-06	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	120	SF
S-SAT-07	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	500	SF
M-GWB-08	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	500	SF
S-JTC-09	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	50	SF
M-VSF-10	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED GRID, GRAY PAPER BACKING	A	NF	500	SF
M-MAS-11	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED GRID, GRAY PAPER BACKING AND CARPET, BROWN, FIBROUS	A	NF	500	SF
M-CPT-12	CARPET, BROWN, FIBROUS	A	NF	1,500	SF
M-WAB-13	WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	40	SF
M-ADH-14	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	40	SF
M-SLT-15	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	15	SF
M-GWT-16	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	160	SF
M-GRT-17	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	16	SF
M-VCT-18	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, OFF-WHITE MOTTLES	A	NF	65	SF
M-MAS-19	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, OFF-WHITE MOTTLES	A	NF	65	SF
M-ACT-20	ACOUSTICAL CEILING TILE, 1'X1', GRAY, SMOOTH, WHITE, MECHANICALLY ATTACHED	S	F	400	SF
M-CPT-21	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	400	SF
M-MAS-22	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	400	SF
M-CPT-23	CARPET (SELF-STICK SQUARES), 18"X18", GRAY, FIBROUS	A	NF	75	SF
M-CPT-24	CARPET (SELF-STICK SQUARES), 18"X18", GREEN, FIBROUS	A	NF	75	SF
M-CTG-25	COATING, WHITE, PLIABLE, ASSOCIATED WITH SPRAY-APPLIED FOAM ROOFING	A	NF	2,200	SF
M-CON-26	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	2,200	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage H*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APR-01	ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	400	SF
M-VBF-02	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	400	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage J*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APR-01	ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	100	SF
M-VBF-02	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	100	SF
M-CON-03	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	100	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage O*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APR-01	ASPHALT PREPARED ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	90	SF
M-VBF-02	VAPOR BARRIER FELT, BLACK, ASPHALTIC, ASSOCIATED WITH ASPHALT PREPARED ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	90	SF
M-CON-03	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	90	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center, KSD
Storage P*

JOB NO. 08-202

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CMU-01	CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	A	NF	650	SF
M-MRT-02	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT (COLUMNS), 8"X16", GRAY, CEMENTITIOUS	A	NF	65	SF
M-SLT-03	SEALANT (EXPANSION), WHITE, PLIABLE	A	NF	25	SF
M-ASP-04	ASPHALT, BLACK, ASPHALTIC	A	NF	6,000	SF
M-CTG-05	COATING (ROOF), WHITE, SMOOTH	A	NF	6,000	SF

END OF TABLE

2.7 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **TWENTY-ONE** friable suspect ACBM (acoustical ceiling panels, duct seam tape and spray-applied texture (popcorn)) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.8 Sample Collection

Convenience sampling was performed on select identified suspect ACBM, except for the spray-applied texture (popcorn), which was random sampled. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
A	55 (45 Assumed)	30
B	44 (38 Assumed)	18
C	25 (23 Assumed)	6
D	33 (28 Assumed)	15
E	29 (25 Assumed)	12
F	17 (17 Assumed)	0
G	15 (15 Assumed)	0
I	16 (16 Assumed)	0
K	28 (26 Assumed)	6
L	17 (15 Assumed)	6
M	2 (2 Assumed)	0
R	11 (11 Assumed)	0
T	56 (47 Assumed)	27
U	3 (3 Assumed)	0
W	57 (50 Assumed)	25
Canopy	3 (3 Assumed)	0
Residence	26 (24 Assumed)	6
Storage H	2 (2 Assumed)	0

Building	Suspect ACBM	Samples Collected
Storage J	3 (3 Assumed)	0
Storage O	3 (3 Assumed)	0
Storage P	5 (5 Assumed)	0
TOTAL	450	151

Suspect ACM Designation and Sample Record Forms are presented in Appendix A.

2.9 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.

END OF REPORT

APPENDIX A

Suspect Asbestos-Containing Material Designation and Sample Record Forms

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-02 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: SPRAY APPLIED TEXTURE **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 20,000 SF / LF / EA **Estimated By:** Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	TABLE STORAGE	SW Corner	E 2"	N 0'	3"	F/W/I/C/O
B	LOUNGE	SW Corner	E 0'	N 3"	3"	F/W/I/C/O
C	BREAK OUT 04	NW Corner	E 3"	S 0"	3"	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Signature:** **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-6-WB-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 21,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	TABLE STORAGE	SW Corner	E 2"	N 0	3"	F W / C I O
B	LOUNGE	SW Corner	E 0	N 3"	3"	F W / C I O
C	BREAK OUT OH	NW Corner	E 3"	S 0	3"	F W / C I O
D		Corner				F W / C I O
E		Corner				F W / C I O
F		Corner				F W / C I O
G		Corner				F W / C I O

Comments: ASSOCIATED WITH S-SAT-02

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-JTC-04 Visible Damaged: Yes Friable
 Covered SAT No Non-Friable

General Description: JOINT COMPOUND **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 2100 LF / EA **Estimated By:** Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	TABLE STORAGE	SW Corner	E 2"	N 0	3"	F/W/C/O
B	LOUNGE	SW Corner	E 0	N 3"	3"	F/W/C/O
C	BREAK OUT 04	NW Corner	E 3"	S 0	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M-GWS-03

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *DM* **Signature:** *MR* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7677
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CPT-05 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: CARPET **Size:** N/A

Matrix/Primary Color: TAN **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** RED STREAKS
Quantity of Material: 50,000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	TABLE STORAGE	SW Corner	E O	N O	0	F / W / C / O
B	OFFICE OR	SE Corner	W O	N O	0	F / W / C / O
C	BREAK OUT 04	NW Corner	E O	S O	0	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MAS-06 Damaged: Yes No Friable Non-Friable
 Visible Covered CPT

General Description: MASTIC Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Matrix/Primary Color: Yellow Size: N/A

Quantity of Material: 50,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	TABLE STORAGE	SW Corner	E O	N O	0	F / W / C / O
B	OFFICE 09	SE Corner	W O	N O	0	F / W / C / O
C	BREAK OUT 04	NW Corner	E O	S O	0	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-05

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-FD1-07 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: FIRE DOOR ISSUATION **Size:** N/A
Matrix/Primary Color: N/A **Texture/Pattern:** PLATE/WOOD CLADDING **Cover/Secondary Color:** N/A

Quantity of Material: 1134 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 6/30/08 **Signature:** **Date:** 6/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-08 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: WALLBASE **Size:** 4" **Cover/Secondary Color:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** FIBROUS **Estimated By:** Drawing Field Measure
Quantity of Material: 1000 SD / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *DM* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-09 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: ADHESIVE **Size:** N/A
Matrix/Primary Color: BLUE **Texture/Pattern:** P1, R15, L **Cover/Secondary Color:** N/A
Quantity of Material: 1000 SP / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-08

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *ASSUMED*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 General Description: SEMIANT (DOORS, WINDOWS, MILLWORK, FUTURESS) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: PLASTER Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-TWP-11 Visible Covered Friable Non-Friable
Damaged: Yes No **Size:** N/A

General Description: TACKABLE WALL PANEL **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** VINYL COVER
Matrix/Primary Color: BROWN **Estimated By:** Drawing Field Measure
Quantity of Material: 100 LF / EA Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BOARD ROOM	NE Corner	W O	S 4'	2"	F/W/C/O
B	BOARD ROOM	NE Corner	W O	S 6'	2"	F/W/C/O
C	LOUNGE	NE Corner	W O	S 7'	6'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Mechanically Attached

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-12 Visible Covered Friable Non-Friable
General Description: SPRAY APPLIED TEXTURE **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A **Sampled**
Quantity of Material: 3300 SF / LF / EA **Estimated By:** Drawing Field Measure **Assumed**

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-13 Visible Covered: Visible Covered: SAT Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 3300 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC.

FIM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-JTC-14 Visible Covered SAT Damaged: Yes No Friable Non-Friable
General Description: Joint Compound **Size:** N/A

Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 330 SP / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-SWB-13

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWT-15 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 2" x 2"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWT-14 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"
 Matrix/Primary Color: BLUE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.cmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SWT-17 Material: GRAY
 General Description: GRAY
 Matrix/Primary Color: GRAY Texture/Pattern: Comestitious Cover/Secondary Color: N/A
 Quantity of Material: 450 Estimated By: [] Drawing [] Sampled [] Assumed
 [] Field Measure
 Homogeneous Material Location: [] Ceiling [] Floor [] Wall [] Other
 Manner of Sampling: [] Random [] Convenience [] N/A

Damaged: [] Yes [] No
 Visible [] Covered []
 Friable [] Non-Friable []
 Size: N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-SWT-15, M-SWT-16

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: [] No [] Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-5288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CMT-18 Visible Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Size: 2" x 2"

Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 2200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GET-19 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: GRAY Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 220 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-18

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SAC-20 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Sink Acoustical Coating
 Matrix/Primary Color: White Texture/Pattern: Rous-A Cover/Secondary Color: N/A
 Quantity of Material: Co Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-21 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 28,000 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 SF / LF / EA Field Measure

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LOBBY	NE Corner	W O	S O	2"	F / W / C / O
B	VESTIBULE	SW Corner	E O	N O	2"	F / W / C / O
C	OFFICE 24	NW Corner	E O	S O	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHIERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

F M GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-22 Visible Covered SAT Damaged: Yes No Friable Non-Friable
General Description: Gypsum Wallboard **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 28,000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Lobby	NE Corner	W O	S O	3"	F / W / C / O
B	Vestibule	SW Corner	E O	N O	3"	F / W / C / O
C	Office 24	NW Corner	E O	S O	11"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-21

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-JTC-23 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LOBBY	NE Corner	W	S	3"	F/W/C/O
B	VESTIBULE	SW Corner	E	N	3"	F/W/C/O
C	OFFICE 24	NW Corner	E	S	11"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M-GWB-22

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter

AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA

Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-0PT-24 Material Description: QUARRY PAVER TILE
 Matrix/Primary Color: GRAY Matrix/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: [] Drawing [x] Field Measure
 Homogeneous Material Location: [] Ceiling [x] Floor [] Wall [] Other
 Manner of Sampling: [] Random [] Convenience [x] N/A

Visible Covered [x] [] Damaged: [] Yes [x] No
 Friable Non-Friable [] [x]
 Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Size: 4" x 4"

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: [] No [x] Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-QPT-25 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: QUARRY PAVER TILE Size: 4" x 4"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: BLACK + WHITE SPECKS
 Quantity of Material: 1000 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHIERA Certificate No.: D12313 State License: EPA AHIERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GRT-26 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GROUT Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Matrix/Primary Color: Gray Estimated By: Drawing Field Measure
 Quantity of Material: 200 LF / EA SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-QPT-24, M-QPT-25

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-APL-27 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 2'
 Matrix/Primary Color: Grey Texture/Pattern: Pinholes + Fissures Cover/Secondary Color: White
 Quantity of Material: 5400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Vestibule	NW Corner	E 2'	S 2'	10'	F / W / C / O
B	Lobby	SW Corner	E 0	N 15'	10'	F / W / C / O
C	Hall 08	NW Corner	E 2'	S 2'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

F/M GROUP INC

FM GROUP/forms/SuspACIMDesigRecord.cfm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-28 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: Brown + White Mottles
 Quantity of Material: 3000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecordL.cmf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-29 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: VINYL COMPOSITION TILE **Size:** 12" x 12"

Matrix/Primary Color: TAN **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** BLACK SPOTS
Quantity of Material: 300 SP / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MAS-30 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TRACY Cover/Secondary Color: N/A
 Quantity of Material: 3300 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VCT-28, M-VCT-25

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-31 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: WALUBASE (COVERED) Size: 4"

Matrix/Primary Color: IAN Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.mrf

Project No.: 08-202 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-32 Visible Covered WAB Damaged: Yes No Friable Non-Friable

General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-31

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHJERA Certificate No.: D12313 State License: EPA AHJERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 Fax

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SI-33 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FIRE STOP) Size: N/A
 Matrix/Primary Color: RED Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHIERA Certificate No.: D12313 State License: EPA AHIERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (802) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-202 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: SPLA34 Damaged: Yes No Friable Non-Friable
 General Description: PLASTER Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHJERA Certificate No.: D12313 State License: EPA AHJERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.E.35 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOOR WINDOW) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: GUMMUM Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-30 Visible Damaged: Yes Non-Friable
 Covered No Friable
General Description: Gypsum wallboard **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** Vinyl Cover
Quantity of Material: 500 SF / LF / EA **Estimated By:** Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: **Signature:** **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCA-37 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered Size: N/A

Matrix/Primary Color: BLUE Texture/Pattern: FIBROUS Cover/Secondary Color: BROWN & WHITE SPOTS
 Quantity of Material: 300 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.MAS-38 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: STACKY Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.F. 37

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHJERA Certificate No.: D12313 State License: EPA AHJERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.cmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CMU-3A Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNK Size: 8"X16"
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MRT-40 Visible Covered: Damaged: Yes No Friable: Non-Friable:
 General Description: MORTAR Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled: Assumed:

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U. 39

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 Fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.cmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCHA-41 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CARPET Texture/Pattern: FIBEROUS Cover/Secondary Color: GRAY STRIPS
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 600 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.MAS.412 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: PACKY Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-41

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VST-43 Damaged: Yes No Friable Non-Friable
 General Description: VINYL STAIR TRED Size: 12" X 18"
 Matrix/Primary Color: Blue Texture/Pattern: CIRCLE PATTERN Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC.

FM GROUP/forms/SuspACM/DesignRecord.mrf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-44 Visible Covered Friable Non-Friable
General Description: VINYL COMPOSITION TILE **Size:** 18"x18"
Matrix/Primary Color: BLUE **Texture/Pattern:** CIRCLE PATTERN **Cover/Secondary Color:** N/A
Quantity of Material: 80 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 08-202 Project Name: AHJRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MAS-45 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TRACK Cover/Secondary Color: N/A
 Quantity of Material: 180 Estimated By: Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VSF-43, M-VSF-44

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHJRA Certificate No.: D12313 State License: EPA AHJRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MC-NAB-4U Damaged: Yes No Friable Non-Friable
 General Description: WALLBASE (COVERED) Size: 4"
 Matrix/Primary Color: GRAY Texture/Pattern: WALL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACM/DesignRecord.08mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-47 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: RIABLE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-ADH-47

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.BUR.48 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BULLS-UP ROOFING Cover/Secondary Color: GRAVEL CAP
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Estimated By: Drawing Field Measure
 Quantity of Material: 36,000 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MAS. 4A Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS & FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: TAR-LIKE (SF) LF / EA

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHIERA Certificate No.: D12313 State License: EPA AHIERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-50 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Visible Covered
 Matrix/Primary Color: BLACK Texture/Pattern: PLIABLE Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHIERA Certificate No.: D12313 State License: EPA AHIERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord1.mtf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CEN-51 Material Code: M-CEN-51
 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: CONCRETE (MILT) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A

Quantity of Material: 20,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O


Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACM/DesignRecord.ormf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-STA-52 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 20,000 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-53 Damaged: Yes Non-Friable
 Visible Covered Friable
 Covered No Non-Friable
 General Description: CONCRETE (FOUNDATION) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 70,000 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building A **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-5CT-55 Visible Covered Friable Non-Friable
General Description: SEALANT (DOORS, WINDOWS) **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: GRAY **Texture/Pattern:** PUMBLE **Cover/Secondary Color:** N/A
Quantity of Material: 5 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.cmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building A Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GAS-56 Damaged: Yes No Friable Non-Friable
 General Description: Gasket Size: 1" - 3"

Matrix/Primary Color: Black/Green Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: ACOUSTICAL CEILING PANEL Size: 2'X4'
 Matrix/Primary Color: GRAY Texture/Pattern: PINABLES & FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	<u>I.T. Room</u>	<u>NE Corner</u>	<u>W 3'</u>	<u>S 7'</u>	<u>10'</u>	<u>F / W / C / O</u>
B	<u>I.T. Room</u>	<u>NW Corner</u>	<u>E 5'</u>	<u>S 2'</u>	<u>10'</u>	<u>F / W / C / O</u>
C	<u>INSTRUCTIONAL MATERIAL ROOM</u>	<u>NW Corner</u>	<u>E 4'</u>	<u>S 8'</u>	<u>10'</u>	<u>F / W / C / O</u>
D		<u>Corner</u>				<u>F / W / C / O</u>
E		<u>Corner</u>				<u>F / W / C / O</u>
F		<u>Corner</u>				<u>F / W / C / O</u>
G		<u>Corner</u>				<u>F / W / C / O</u>

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.SAT.02 Damaged: Yes Non-Friable
 Visible Covered Friable
 Covered Size: N/A

General Description: SPRAY-APPLIED TEXTURE Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Estimated By: Drawing Sampled
 Quantity of Material: 3500 Field Measure Assumed
 Texture/Pattern: CHALK LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Hall 1	NE Corner	W 0'	S 0'	2"	F/W/C/O
B	I 2	NE Corner	W 0'	S 0'	2"	F/W/C/O
C	IT ROOM	NW Corner	E 0'	S 0'	2"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-03 Visible Covered Damaged: Yes No Friable Non-Friable
 Size: N/A

General Description: Gypsum wallboard **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Matrix/Primary Color: White **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 3500 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	HALL 1	NE Corner	W O	S O	2'	F (W) / C / O
B	L 2	NE Corner	W O	S O	2"	F (W) / C / O
C	I.S. Room	NE Corner	E O	S O	2"	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-02

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: CM **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.JTC.04 **Damaged:** Yes No Friable Non-Friable
 Visible Covered SAT **Size:** N/A

General Description: JOINT COMPOUND **Cover/Secondary Color:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CALKY
Quantity of Material: 350 **Estimated By:** Drawing Field Measure
 LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	HALL 1	NE Corner	W O	S O	2"	F W / C / O
B	1 2	NE Corner	W O	S O	2"	F W / C / O
C	I.T. Room	NW Corner	E O	S O	2"	F W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWB.03

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CPT-05 Visible Damaged: Yes No Friable Non-Friable
 Covered Size: N/A

General Description: CARPET **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** N/A
Matrix/Primary Color: GRAY **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 1500 SF / LF / EA Floor Wall Other

Homogeneous Material Location: Ceiling Convenience N/A
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *CSM* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MA5-00 Damaged: Yes No Friable Non-Friable
 Visible Covered CP Size: N/A

General Description: MASTIC Cover/Secondary Color: N/A
 Matrix/Primary Color: YELLOW Estimated By: Drawing Field Measure
 Quantity of Material: 1500 LF / EA SF

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MICAF-05

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-07 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: WALL BASE (COVERED) **Size:** 4" **Cover/Secondary Color:** ALKA
Matrix/Primary Color: BLUE **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** ALKA
Quantity of Material: 80 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *DM* **Date:** 06/30/08 **Signature:** *MR* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: KM-ADH-08 Visible Covered WAS Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE **Size:** N/A

Matrix/Primary Color: CREAM **Texture/Pattern:** PURPLE **Cover/Secondary Color:** N/A
Quantity of Material: 80 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAS-01

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-FD1-09 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: FIRE DOOR INSULATION Cover/Secondary Color: N/A Sampled
 Matrix/Primary Color: N/A Texture/Pattern: METAL/WOOD CLADDING Estimated By: Drawing Assumed
 Quantity of Material: 147 (SF) / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building-B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-10 **Damaged:** Yes No Friable Non-Friable
General Description: CONCRETE (FOUNDATION) **Size:** 15' x 15'
Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 3000 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. CON. 11 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CONCRETE (CRACKS) Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONOUS Estimated By: Drawing Field Measure
 Quantity of Material: 300 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MACT-12 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Tile **Size:** 1'x1'
Matrix/Primary Color: BROWN **Texture/Pattern:** RIBBED **Cover/Secondary Color:** TAN
Quantity of Material: 3000 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	I.T. ROOM	NE Corner	W 3'	S 6'	12'	F/W/O
B	↓	NW Corner	E 2'	S 1'	12'	F/W/O
C	SEWER RM	SE Corner	W 5'	N 4'	12'	F/W/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-13 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE **Size:** N/A
Matrix/Primary Color: BROWN **Texture/Pattern:** BRITTLE **Cover/Secondary Color:** N/A Sampled Assumed
Quantity of Material: 750 **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / O
B		Corner				F / W / O
C		Corner				F / W / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.A.C.T. 12

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-124 **Damaged:** Yes No Friable Non-Friable
General Description: Gypsum Wallboard **Visible Covered:** ACT **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 3000 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SL-15 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SEALANT (DOORS, EXPANES) **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** PLIABLE **Cover/Secondary Color:** N/A Sampled
Quantity of Material: 14 LF / EA Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SAC-16 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: SINK ACOUSTICAL COATING Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-1B Visible Covered **Damaged:** Yes No Friable Non-Friable
 Size: N/A

General Description: Gypsum Wallboard **Cover/Secondary Color:** SA/SA
Matrix/Primary Color: White **Texture/Pattern:** CHALKY **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 1100 LF / EA SF

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-17

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-3TC-19 Visible Covered SAT **Damaged:** Yes No **Size:** N/A
 Friable Non-Friable
General Description: POINT COMPOUND
Matrix/Primary Color: WHITE **Texture/Pattern:** FLAKY **Cover/Secondary Color:** N/A
Quantity of Material: 110 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.U.B.1B

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWT-20 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4" x 4"

General Description: GRAZED WAULTILE Texture/Pattern: SANDPAPER Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Estimated By: Drawing Field Measure
 Quantity of Material: 800 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *DN* Date: 06/30/08 Signature: *MR* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWT-21 Damaged: Yes No Friable Non-Friable
 General Description: GRAZED WALL TILE (PASTURE) Size: 4" x 4"
 Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GRT-22 Visible Covered Friable Non-Friable
 General Description: GROUT Damaged: Yes No Size: N/A

Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTIOUS **Cover/Secondary Color:** N/A Sampled Assumed
Quantity of Material: 85 Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-20, M-GWT-21

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AL-CMT-23 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: CERAMIC MOSAIC TILE **Size:** 2x2"
Matrix/Primary Color: GRAY **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** N/A

Quantity of Material: 500 (SF) / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. GRT. 24 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GRAYS Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: SD SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.S.T. 23

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W. WAB. 2S Visible Covered Damaged: Yes No Friable Non-Friable
General Description: WALLBASE (COVERED) **Size:** 4"

Matrix/Primary Color: BROWN **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 10 SFY LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.D.H. 210 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FLIPBLE Cover/Secondary Color: N/A
 Quantity of Material: 10 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.W.A.B.S

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-517-27 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (DUCT) Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 50 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



EMV GROUP INC

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. GWSB-28 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GYP SUM WALLBOARD Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Estimated By: Drawing Field Measure
 Quantity of Material: 1300 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-STC-29 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: JOINT COMPOUND Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Estimated By: Drawing Assumed
 Quantity of Material: 130 (SF) / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWB.28

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCP-30 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2x2'

General Description: CARPET (SELF SACK SQUARES) Cover/Secondary Color: MULTICOLORED SPECKS
 Matrix/Primary Color: BLUE Texture/Pattern: FIBROWS Estimated By: Drawing Field Measure
 Quantity of Material: 600 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AL-CP-31 Damaged: Yes Non-Friable
 Visible Coverer No Field Measure

General Description: CARPET (CONV) Size: 4" Sampled
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A Assumed
 Quantity of Material: 35 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9286 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-3Z Damaged: Yes No Friable Non-Friable
 Visible Covered CPA Size: N/A

General Description: ADHESIVE Texture/Pattern: PULABLE Cover/Secondary Color: N/A
 Matrix/Primary Color: CREAM Estimated By: Drawing Field Measure
 Quantity of Material: 35 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.W.A.B.31

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-33 Visible Covered Friable Non-Friable
 Damaged: Yes No Size: 2" x 12"

General Description: VINYL COMPOSITION SURFACE **Cover/Secondary Color:** GRAY MOTTLES
Matrix/Primary Color: LIGHT GRAY **Texture/Pattern:** SMOOTH Drawing Field Measure
Quantity of Material: 375 LF / EA Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *DM* **Date:** 06/30/08 **Signature:** *MR* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S. 34 Damaged: Yes No Friable Non-Friable
 Visible Covered NCI Size: N/A

General Description: M.ASTIC Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Estimated By: Drawing Field Measure
 Quantity of Material: 375 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.C.T. 33

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building: B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MC-WAB-35 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4"

General Description: WALL BASE (COVERED) Cover/Secondary Color: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Estimated By: Drawing Field Measure
 Quantity of Material: 30 (SF) LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.ADH.36 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: ADHESIVE **Size:** N/A
Matrix/Primary Color: CREAM **Texture/Pattern:** PULABLE **Cover/Secondary Color:** N/A
Quantity of Material: 30 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.WAB.35

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-APL-37 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x4'
 Matrix/Primary Color: GRAY Texture/Pattern: ANHOLES & FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 375 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SERVER ROOM	NE Corner	W 6'	S 0'	10'	F / W / C / O
B		NE Corner	W 2'	S 3'	10'	F / W / C / O
C		NW Corner	E 0'	S 4'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building: B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-38 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: SEALANT (window) **Size:** N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** GUMMY **Cover/Secondary Color:** N/A
Quantity of Material: 1 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes **Assumed**

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center. Tempe, AZ 85284

Material Code: M.BRK.39 **Damaged:** Yes No Friable Non-Friable
 Visible Covered **Size:** 3'x8"

General Description: BRICK **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Matrix/Primary Color: RED **Estimated By:** Drawing Field Measure
Quantity of Material: 3500 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

F:\M\GROU\IP\forms\SuspA\CM\DesigRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MRT-40 Visible Damaged: Yes No Friable Non-Friable
 Covered **Size:** N/A

General Description: MORTAR **Texture/Pattern:** CEMENTIOUS **Cover/Secondary Color:** N/A
Matrix/Primary Color: GRAY **Estimated By:** Drawing Field Measure Sampled Assumed

Quantity of Material: 350 LF / EA Wall Other
Homogeneous Material Location: Ceiling Floor Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MBRK-39

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. BRK. 41 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: BRICK **Size:** 4"x8"

Matrix/Primary Color: RED **Texture/Pattern:** CEMENTATIONS **Cover/Secondary Color:** N/A

Quantity of Material: 1400 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 06/30/08 **Signature:** _____ **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building-B Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.R.T.42 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MORTAR Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 140 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. BRK.41

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building B
 Campus Name: Ben Furlong Education Center Address: 8700 South Kyrene Road
 Tempe, AZ 85284

Material Code: M-BUR-43 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT-UP ROOFING Texture/Pattern: ASPHASTIC Cover/Secondary Color: GRAVEL CAP
 Matrix/Primary Color: BLACK Estimated By: Drawing Field Measure
 Quantity of Material: 3000 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building B **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S. 44 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: MASTIC (PENETRATIONS & FLASHING) **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** TAR-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 150 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

FM GROUP/Forms/SuspAcMDesigRecord.amf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C
Address: 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-APL-01 Visible Damaged: Yes No Friable Non-Friable
General Description: ACOUSTICAL CEILING PANEL **Size:** 2'x4'
Matrix/Primary Color: GRAY **Texture/Pattern:** HOLES & FISSURES **Cover/Secondary Color:** WHITE
Quantity of Material: 2000 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	RM 01	NE Corner	W 4	S 0'	10'	F / W / C / O
B	1	NE Corner	W 6	S 0'	10'	F / W / C / O
C	RM 02	NE Corner	W 2	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. BRK. OZ Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: BAILEY Size: 3" X 8"

Matrix/Primary Color: RED Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A

Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-3288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.MKT.03 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: W. BRICK Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A

Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 250 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W. BRK. 02

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.GWB.05 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GYPSUM WALL BOARD Cover/Secondary Color: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY

Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: SJTC-06 Visible Covered SAT **Damaged:** Yes No Friable Non-Friable
General Description: JOINT COMPOUND **Size:** N/A

Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 50 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWB.05

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-Act-07 Visible Damaged: Yes No Friable Non-Friable
 Covered Size: 1'x1'

General Description: Acoustical Ceiling Tile **Texture/Pattern:** Ribbed **Cover/Secondary Color:** Tan
Matrix/Primary Color: Brown **Estimated By:** Drawing Field Measure
Quantity of Material: 2700 SE / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Rm 01	NW Corner	E 4'	S 0'	12'	F / W / C / O
B	I	NE Corner	W 6'	S 0'	12'	F / W / C / O
C	Rm 02	NW Corner	E 7'	S 0'	12'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-08 Visible Covered ACT Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE **Size:** N/A

Matrix/Primary Color: BROWN **Texture/Pattern:** BRITTLE **Cover/Secondary Color:** N/A Sampling Assumed
Quantity of Material: 675 **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-ACT-07

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GRCI/Forms/SuspACM/DesignRecord1.cfm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-09 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: Gypsum Wallboard **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 2700 (SF) LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-10 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" X 12"
 Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: GRAY MOTTLES
 Quantity of Material: 2600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MAS-11 Damaged: Yes No Friable Non-Friable
 Visible Covered YES Size: N/A

General Description: WASIR Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: YELLOW Texture/Pattern: STACKY Estimated By: Drawing Field Measure
 Quantity of Material: 2600 (SF) L / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W-10

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-12 Visible Damaged: Yes No Friable Non-Friable
 Covered Other

General Description: WAUBASE (COVERED) **Size:** 4"
Matrix/Primary Color: DARK BROWN **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 75 **Estimated By:** Drawing Field Measure
 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: **Signature:** **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.ADH.13 Visible Covered WAB Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: PURPLE Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.WAB.12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.FD1.14 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: FIRE DOOR INSULATION Cover/Secondary Color: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL/WOOD CLADDING Estimated By: Drawing Field Measure
 Quantity of Material: 63 (SF) / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



11874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON.15 **Damaged:** Yes No Friable Non-Friable
General Description: CONCRETE (FOUNDATION) **Size:** N/A
Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 2700 **Estimated By:** Drawing Field Measure
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: **Signature:** **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

EM Group/Forms/SuspACMDesignRecord.pdf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON.1C0 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: CONCRETE (ENTRICES) Size: N/A

Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTATIONS **Cover/Secondary Color:** N/A
Quantity of Material: 600 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W-SLT-17 Damaged: Yes Non-Friable
 Visible Covered Friable

General Description: SEALANT (DOORS) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: RIABLE Cover/Secondary Color: N/A

Quantity of Material: 3 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building C **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-TWP-18 **Damaged:** Yes No Friable Non-Friable
 Visible Covered

General Description: TACKLE WALL PANEL **Size:** N/A
Matrix/Primary Color: BROWN **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** UNCL COVER
Quantity of Material: 750 **Estimated By:** Drawing Field Measure
 LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Rm 01	NW Corner	E 15'	S 15'	2"	F/W/C/O
B		NW Corner	E 14'	S 15'	3"	F/W/C/O
C		NW Corner	E 15'	S 15'	2"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-W-E-P-1a Damaged: Yes Non-Friable
 Visible Covered No Size: N/A
 General Description: Windows Glazing Panel Cover/Secondary Color: N/A
 Matrix/Primary Color: White Texture/Pattern: BRITTLE Estimated By: Drawing Sampled
 Quantity of Material: 20 (SF) LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHJERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignatRecord.pdf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-20 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (DUCT) Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 50 (SF) LF / EA Texture/Pattern: FLIABLE

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. APR. 21 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: ASPHALT PREPARED ROOFING (SHINGLES) Cover/Secondary Color: GRAY MINERAL CAP
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Estimated By: Drawing Field Measure
 Quantity of Material: 2700 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VBF-22 Damaged: Yes No Friable Non-Friable
 Visible Covered APR Size: N/A

General Description: VAPOR BARRIER FELT Cover/Secondary Color: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC
 Quantity of Material: 2700 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: A/W M. APR. 21

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben-Furlong Education Center Tempe, AZ 85284

Material Code: MMAS-23 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: WASTIC (PENETRATIONS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: JAR-LIKE Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.GWB.24 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1200 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *CA* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building C Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-3TC-25 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: JOINT COMPOUND Cover/Secondary Color: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKS Estimated By: Drawing Field Measure

Quantity of Material: 120 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.W.B. 24

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

EM.GROU...Forms/SuspACMDesigRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MAPL01 Damaged: Yes No Friable Non-Friable

General Description: ACUSTICAL CEILING PANEL Size: 2'x4'
 Matrix/Primary Color: GRAY Texture/Pattern: PUNCHES & FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	RM 01	NE Corner	W O	S O	10'	F / W / C / O
B	RM 02	NE Corner	W O	S O	10'	F / W / C / O
C	RM 03	NE Corner	W O	S O	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-BK-02 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 3" x 8"

General Description: BRICK Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Matrix/Primary Color: RED Estimated By: Drawing Field Measure
 Quantity of Material: 3600 (SF) LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.R. 03 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: NO FIBER Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Estimated By: Drawing Field Measure
 Quantity of Material: 360 (SB) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.B.R.K. 02

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 2.SAF.04 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SPRAY-APPLIED TEXTURE **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A

Quantity of Material: 800 SP / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Rm 01	NE Corner	W 0	S 1'	3"	F (W) C / O
B	Rm 02	NW Corner	E 0	S 1'	3"	F (W) C / O
C	Rm 03	NW Corner	E 0	S 1'	3"	F (W) C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-05 **Damaged:** Yes No **Friable:** Friable Non-Friable
General Description: Gypsum wallboard **Visible Covered:** SAT **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalk **Cover/Secondary Color:** N/A
Quantity of Material: 800 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	RM 01	NE Corner	W	S	3"	F/W/C/O
B	RM 02	NW Corner	E	S	3"	F/W/C/O
C	RM 03	NW Corner	E	S	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH S-SAT-04

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building-D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-EP-07 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: 15/14

Matrix/Primary Color: GRAY Texture/Pattern: FIBERS Cover/Secondary Color: MULTICOLORED SPECKS
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: _____ Building ID: _____ Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MMAS-08 Visible Covered CP Damaged: Yes No Friable Non-Friable
 General Description: MASSTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKLY Cover/Secondary Color: N/A
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.R.P. 07

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-07 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: WALL BASE (COVERED) **Size:** 4"
Matrix/Primary Color: BLACK **Texture/Pattern:** VERTICAL-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 150 SE / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D
Address: 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MC-ADH-10 Visible Covered WJAB Damaged: Yes No Friable Non-Friable
 Size: N/A

General Description: ADHESIVE **Texture/Pattern:** FLAKY **Cover/Secondary Color:** N/A
Matrix/Primary Color: CREAM **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 150 LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSUMED WITH M.W.JAB-DA

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 **Project Name:** AHRA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MACT-12 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: ACOUSTICAL CEILING TILE **Size:** 12"

Matrix/Primary Color: BROWN **Texture/Pattern:** RIBBED **Cover/Secondary Color:** TAN
Quantity of Material: 2200 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience | N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	RM 01	NE Corner	W O	S I'	12'	F / W / C / O
B	RM 02	NE Corner	W O	S I'	12'	F / W / C / O
C	RM 03	NE Corner	W O	S I'	12'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building ID Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.D.H. 13 Damaged: Yes No Friable Non-Friable
 Visible Covered ACT Size: N/A

General Description: ADHESIVE Cover/Secondary Color: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE
 Quantity of Material: 550 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.A.C.F. 12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 11-CWB-14 Visible Covered ACI Damaged: Yes No Friable Non-Friable
General Description: Chalkboard Wallboard **Size:** N/A

Matrix/Primary Color: White **Texture/Pattern:** Chalkboard **Cover/Secondary Color:** N/A Sampled Assumed
Quantity of Material: 2200 **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: A.GWB.15 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Gypsum Wallboard Cover/Secondary Color: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalk Estimated By: Drawing Field Measure
 Quantity of Material: 300 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-3TC-10 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Joint Compound Cover/Secondary Color: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Estimated By: Drawing Field Measure
 Quantity of Material: 30 Scaled LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. GURB. CS

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: U.FD117 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Fire Door (INSULATION) **Size:** N/A

Matrix/Primary Color: N/A **Texture/Pattern:** MATERIAL WITH CLADDING **Cover/Secondary Color:** N/A
Quantity of Material: 126 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CPT-18 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CARPET Cover/Secondary Color: MULTICOLORED SPECKLES
 Matrix/Primary Color: BROWN Texture/Pattern: FIBERS Estimated By: Drawing Field Measure
 Quantity of Material: 600 SP / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ML-MAS-19 Damaged: Yes No Friable Non-Friable
 Visible Covered CPT Size: N/A

General Description: Mastic Cover/Secondary Color: SLTA
 Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Estimated By: Drawing Assumed
 Quantity of Material: 600 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.F. (B)

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VET-20 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: VINYL COMPOSITION TILE Size: 12"X12"
 Matrix/Primary Color: CREAM Texture/Pattern: SMOOTH Cover/Secondary Color: TAN MOTTLES
 Quantity of Material: 170 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 11. MAS-21 Visible Covered UCT **Damaged:** Yes No Friable Non-Friable
General Description: Mastic **Size:** N/A

Matrix/Primary Color: Yellow **Texture/Pattern:** FLAKY **Cover/Secondary Color:** N/A
Quantity of Material: 170 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.E.T. 20

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Building ID Address: 8700 South Kyrene Road

Campus Name: Ben Fujiling Education Center Tempe, AZ 85284

Material Code: M.WCF.22 Damaged: Yes No Friable Non-Friable

General Description: WINDOW GLAZING PARTLY Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: BRITTLE Cover/Secondary Color: N/A

Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AL-SLT-23 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SEALANT (DMS) **Size:** N/A

Matrix/Primary Color: GRAY **Texture/Pattern:** PLAQUE **Cover/Secondary Color:** N/A
Quantity of Material: 50 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 06/30/08 **Signature:** _____ **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-24 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Gypsum Wallboard Cover/Secondary Color: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Estimated By: Drawing Field Measure
 Quantity of Material: 1000 SP / LF / EA Sampling

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-17C-25 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Joint Compound Cover/Secondary Color: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Estimated By: Drawing Field Measure
 Quantity of Material: 100 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Abandoned with M-GWB-24

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MICON-220 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: CONCRETE (FOUNDATION) **Size:** N/A

Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A Sampled Assumed
Quantity of Material: 2200 SF / LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 06/30/08 **Signature:** _____ **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON.27 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CONCRETE (ENTRYS) Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 700 Texture/Pattern: CEMENTATION LF / EA SF

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-2B Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (FIRE STOP) Cover/Secondary Color: N/A
 Matrix/Primary Color: Red Texture/Pattern: FLUABLE Estimated By: Drawing Field Measure
 Quantity of Material: 10 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben-Furlong Education Center Tempe, AZ 85284

Material Code: W.A.P.R. 29 Visible Covered Damaged: Yes No Friable Non-Friable
 Size: N/A

General Description: ASPHALT REPAIRED ROOFING (SHINGLES) Cover/Secondary Color: GRAY MONUMENTAL CAP
Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Estimated By: Drawing Field Measure
Quantity of Material: 2200 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 06/30/08 **Signature:** _____ **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.V.B.F. 20 Damaged: Yes No Friable Non-Friable
 Visible Covered APR Size: 2/A

General Description: VAPOR BARRIER FELT Cover/Secondary Color: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Estimated By: Drawing Assumed
 Quantity of Material: 2200 (SF) / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: A/W M.A.P.R. 29

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-9286 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S. 31 Damaged: Yes Non-Friable
 Visible Covered No Friable

General Description: MASTIC (PENETRATIONS) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building D **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-3Z Visible Covered Damaged: Yes No Friable Non-Friable
 Size: N/A

General Description: Gypsum Wallboard **Cover/Secondary Color:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Estimated By:** Drawing Field Measure
Quantity of Material: 140 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 06/30/08 **Signature:** _____ **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building D Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-ITC-33 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 14 Estimated By: Drawing Field Measure
 Texture/Pattern: Cracked Sampled Assumed
 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.W.B.SZ

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.P.L.O.I Visible Covered Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Panel **Size:** 2'x4'
Matrix/Primary Color: GRAY **Texture/Pattern:** Pinnacles & Fissures **Cover/Secondary Color:** White
Quantity of Material: 1900 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PRINT SHOP	NE Corner	W 0'	S 2'	10'	F / W / C / O
B	↓	SW Corner	E 0'	N 2'	10'	F / W / C / O
C	COMPUTERS	NE corner	W 0'	S 2'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Gypsum Wallboard Cover/Secondary Color: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky
 Quantity of Material: 3000 SF / LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PRINT SHOP	NE Corner	W O	S O	11'	F (W) / C / O
B	COMPUTERS	SE Corner	W O	N O	11'	F (W) / C / O
C	DATA PROCESSING	SE Corner	W O	N O	11'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SAT-02

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 06/30/08
 State License: EPA Date: 06/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.ADH.05 Visible Covered FRP Damaged: Yes No Friable Non-Friable

General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-04 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: VINYL COMPOSITION TILE Size: 12" x 12"

Matrix/Primary Color: GREEN **Cover/Secondary Color:** DARK GREEN MOTTLES

Quantity of Material: 1400 **Texture/Pattern:** Smooth **Estimated By:** Drawing Field Measure Sampled Assumed
 LF / EA SF

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.VCT.07 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: VINYL COMPOSITION TILE (PATTERN) **Size:** 12" x 12"
Matrix/Primary Color: BLUE **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** BLACK MOTTLES

Quantity of Material: 300 (SF) / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E
Address: 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.MAS.08 Visible Damaged: Yes Friable
 Covered No Non-Friable

General Description: Mastic Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A

Quantity of Material: 200 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.E.T. 06, M.V.E.T. 07

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-09 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: WALLBASE (COVERED) **Size:** 4"

Matrix/Primary Color: BLUE **Texture/Pattern:** UNGLAZED **Cover/Secondary Color:** N/A
Quantity of Material: 175 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MADH.10 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: ADHESIVE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Matrix/Primary Color: Cream Estimated By: Drawing Field Measure
 Quantity of Material: 125 (SF) / LF / EA Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WJAB-09

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No. D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.F.D.1.1 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: FIRE DOOR INSULATION **Size:** N/A

Matrix/Primary Color: N/A **Texture/Pattern:** METAL WOOD CLADDING **Cover/Secondary Color:** N/A
Quantity of Material: 126 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 06/30/08 **Signature:** **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Euphron Education Center Tempe, AZ 85284

Material Code: M.CON.12 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 2200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-13 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CONCRETE (ENTRIES) Cover/Secondary Color: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Estimated By: Drawing Field Measure Sampled Assumed

Quantity of Material: 750 (SF) / LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



EPA/600/P-03-001a (Rev. 11/99) Asbestos Record Form

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-14 Visible Covered Friable Non-Friable
 Damaged: Yes No Size: 1/4

General Description: SEALANT (DOORS, WINDOWS) Cover/Secondary Color: N/A
Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Estimated By: Drawing Field Measure
Quantity of Material: 10 (SF) / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.S.A.T.15 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SPRAY-APPLIED TEXTURE **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A

Quantity of Material: 750 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 06/30/08 **Signature:** **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-10 Visible Covered SAT Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboards Size: 2/4

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 750 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SAT. 15

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E
Address: 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.JTC.17 Visible Damaged: Yes No Friable Non-Friable
 Covered *SAT* **Size:** 2' x 6'

General Description: JOINT COMPONDS
Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKLY **Cover/Secondary Color:** N/A
Quantity of Material: 75 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASBESTOS WITH M-GRUB-16

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-18 Visible Damaged: Yes No Friable Non-Friable
 Covered Other Size: 4"

General Description: WALLBASE (COVERED)
Matrix/Primary Color: DARK BROWN **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 10 (SF) / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-19 Visible Damaged: Yes No Friable Non-Friable
 Covered WAB Size: N/A

General Description: ADHESIVE **Cover/Secondary Color:** N/A Sampled Assumed

Matrix/Primary Color: CRSAWA **Texture/Pattern:** RUBBLE **Estimated By:** Drawing Field Measure

Quantity of Material: 10 SE / LF / EA Ceiling Floor Wall Other

Homogeneous Material Location: Random Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.W.A.B. 10

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter

AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA

Signature: **Date:** 06/30/08 **Signature:** **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.C.P. 20 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered Size: N/A

Matrix/Primary Color: BLUE Texture/Pattern: FIBROUS Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MAS-ZI Damaged: Yes No Friable Non-Friable
 Visible Covered CPT Size: N/A

General Description: MASTIC Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Matrix/Primary Color: YELLOW Estimated By: Drawing Field Measure
 Quantity of Material: 250 LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.T. 20

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CMU-22 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2x16"

General Description: CONCRETE MASONRY UNIT Cover/Secondary Color: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Estimated By: Drawing Field Measure Sampled Assumed

Quantity of Material: 600 (SF / LF / EA) Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MMKT.23 Visible Covered **Damaged:** Yes No **Size:** N/A
 Friable Non-Friable

General Description: MORTAR
Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 60 **Estimated By:** Drawing Field Measure Sampled Assumed
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U. 22

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
ASHERA Certificate No.: D12313 **ASHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building E **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MGWB.24 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Gypsum Wallboard **Size:** N/A

Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 160 SF / LF / EA Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** _____ **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-4286 fax

FM GROUP/forms/SuspACM/DesignRecord.drmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Building E Address: 8700 South Kyrene Road

Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-25 Damaged: Yes No Friable Non-Friable

General Description: SEALANT (DUCT) Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

EM GROUP INC

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.C.T.S. 26 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: COATINGS Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLUABLE Estimated By: Drawing Field Measure
 Quantity of Material: 2200 (SF) / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: A/W SPRAY-APPLIED FOAM ROOFING

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S.27 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: MASTIC (PENETRATIONS) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure
 Sampling LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.WDB.2B Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4"

General Description: WOVEN DUCT BOOT Cover/Secondary Color: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: RUBBER-LIKE Estimated By: Drawing Field Measure
 Quantity of Material: 5 (SF) / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building E Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SCT-29 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (WINDOWS) Cover/Secondary Color: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PULBABLE Estimated By: Drawing Field Measure Sampled Assumed

Quantity of Material: 1 (SF) / LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

EM GEOID/Forms/SuspectAsbestosDesignationRecord.nmf



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-Cellul Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNITS Size: 2"x16"
 Matrix/Primary Color: GRAVEL Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DK Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CM-02 Damaged: Yes Non-Friable
 Visible Covered Size: 8" x 16"
 General Description: CONCRETE MASONRY UNIT Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Sampled
 Quantity of Material: 1000 (SF) LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building F **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: U.N.R.V.03 **Damaged:** Yes No Friable Non-Friable
General Description: Mortar **Size:** N/A
Matrix/Primary Color: Gray **Texture/Pattern:** CONCRETE **Cover/Secondary Color:** N/A
Quantity of Material: 230 **Estimated By:** Drawing Field Measure
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U.O.C. M.C.M.U.O.Z

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON.04 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE FOUNDATION Size: N/A
 Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure
 Texture/Pattern: CEMENT/TILE

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.5151.05 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PEBBLE Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building F **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: SPR-07 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: SPRINKLED APPLIED TEXTURE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: WHITE **Quantity of Material:** 400 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-302109 Damaged: Yes No Friable Non-Friable
 General Description: South Corridor Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: Chalky (SF) / LF / EA

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-D.B.

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DN* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-6288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-4AB-10 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Size: 24"
 Matrix/Primary Color: TAN Texture/Pattern: VIBBLE-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-4288 fax

FM GROUP/forms/SuspACMDesignRecord.arnf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MADHILL Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADRIANO Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: FLAKE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MADHILL

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



FM GROUP/forms/SuspACMDesigRecord1.nmf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building F **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-EXL-12 Visible Damaged: Yes No Friable Non-Friable
General Description: EXPANSION JOINT Covered **Size:** 2' x 4'
Matrix/Primary Color: GRAY **Texture/Pattern:** RABBLE **Cover/Secondary Color:** N/A
Quantity of Material: 10 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W. SWP. 13 Damaged: Yes No Friable Non-Friable
 General Description: PACKABLE WALL PANEL Visible Covered: Visible Covered Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

Project No.: 08-202 **Project Name:** AHRA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building F **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-Struc-F Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: BRICK **Size:** N/A

Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 500 **Estimated By:** Drawing Field Measure
 LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DM **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building F **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSB-15 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: BUCKET CAP ROOFING **Size:** 200
Matrix/Primary Color: BLACK **Texture/Pattern:** ASPHALTIC **Cover/Secondary Color:** GREEN MINERAL CAP
Quantity of Material: 800 (SF) LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-102-16 Damaged: Yes Non-Friable
 Visible No Friable
 Covered Size: 0.5A
 General Description: MASTIC PENETRATIONS & FRACTIONS
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-3288 fax

FIM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building F Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: U.S.E.F. 17 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (GLASSING) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: DIAPHRAGM Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-01 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 3600 Estimated By: Drawing Field Measure
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.GWB.OZ Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 3600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SISATOL

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-5TC-03 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: 2/A

General Description: JOINT COMPOUND

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A

Quantity of Material: 360 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M:GWB.DZ

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.C.P. 04 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: CARPET **Size:** 2/A

Matrix/Primary Color: GREEN **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** N/A
Quantity of Material: 200 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Random Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes **Assumed**

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AC-MAS-05 Visible Covered CPT **Damaged:** Yes No Friable Non-Friable
General Description: ELASTIC **Size:** N/A

Matrix/Primary Color: YELLOW **Texture/Pattern:** JACKY **Cover/Secondary Color:** N/A
Quantity of Material: 200 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MCAFOY

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DR **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.WAB.DC Visible Damaged: Yes No Friable Non-Friable
 Covered **Size:** 4"
General Description: WALLBASE (COVERED) **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A
Matrix/Primary Color: BROWN **Estimated By:** Drawing Field Measure
Quantity of Material: 50 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes **Assumed**

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MADH-07 Damaged: Yes No Friable Non-Friable
 Visible Covered WABS Size: N/A

General Description: ADHESIVE Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: CREAM Texture/Pattern: FLIABLE Estimated By: Drawing Field Measure
 Quantity of Material: 50 (SP) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH WABS-DG

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

EM GROUP INC

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-5LT-08 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SEALANT (DOORS, WINDOWS) **Size:** 2/4

Matrix/Primary Color: WHITE **Texture/Pattern:** PLIABLE **Cover/Secondary Color:** N/A
Quantity of Material: 2 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: VINYL COMPOSITION TILE Size: 12"X12"
 Matrix/Primary Color: TAN Cover/Secondary Color: TAN MOTTLES

Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 06/30/08 Signature: *MR* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ACMAS-10 Visible Covered ✓CT **Damaged:** Yes No Friable Non-Friable
General Description: MASTIC **Size:** N/A

Matrix/Primary Color: YELLOW **Texture/Pattern:** YACKY **Cover/Secondary Color:** N/A
Quantity of Material: 450 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.C.T.O.A

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AL-CON-11 **Damaged:** Yes No Friable Non-Friable
General Description: CONCRETE (FOUNDATION) **Visible Covered:** Visible Covered **Size:** N/A
Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 1200 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. BUR. 12 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT-UP ROOFING Cover/Secondary Color: GRAY MINERAL CAP
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Estimated By: Drawing Field Measure
 Quantity of Material: 1200 (SF) / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MAS-13 Damaged: Yes No Friable Non-Friable
 General Description: MASSTIC (PENETRATIONS) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure
 Texture/Pattern: TAR-LIKE

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building G Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CRS-14 Damaged: Yes No Friable Non-Friable
 General Description: CEMENTIOUS ROOF SHINGLES (S-PATIENT) Size: N/A
 Matrix/Primary Color: Red Texture/Pattern: CEMENT (TUMS) Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Cal* Date: 06/30/08 Signature: *Michael Richter* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building G **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VBF-15 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: VAPOR BARRIER FELT **Size:** N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** ASPHALTIC **Cover/Secondary Color:** N/A Sampled Assumed
Quantity of Material: 1000 LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CRS-14

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: **Signature:** **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SATO Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SPRAY-APPLIED TEXTURE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Estimated By: Drawing Field Measure
 Quantity of Material: 1000 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DK* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWB-DZ Material Code: Visible Covered SAT Friable Non-Friable
 General Description: GYPSUM WALLBOARD Size: N/A
 Matrix/Primary Color: White Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.S.A.F.-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building 1 **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-JTC-03 Visible Damaged: Yes No Friable Non-Friable
 Covered SAT **Size:** N/A

General Description: JOINT COMPOUND **Texture/Pattern:** GARKLY **Cover/Secondary Color:** N/A

Matrix/Primary Color: WHITE **Estimated By:** Drawing Field Measure Sampled Assumed

Quantity of Material: 100 SF LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWBOR

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *DM* **Signature:** *MR* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building 1 **Address:** 8700 South Kyrene Road
Campus Name: Ben. Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-04 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: VINYL COMPOSITION TILE **Size:** 12" X 12"

Matrix/Primary Color: WHITE **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** GRAY MOTTLES
Quantity of Material: 150 (SF) / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S.O.S Damaged: Yes No Friable Non-Friable
 Visible Covered VCT Size: N/A

General Description: MASTIC Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Estimated By: Drawing Field Measure
 Quantity of Material: 150 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.VCT.04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building 1 **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-06 Visible Damaged: Yes No Friable Non-Friable
 Covered Drawing Field Measure Sampled Assumed

General Description: WALLBASE (COVERED) **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A **Size:** 4"

Matrix/Primary Color: BLACK **Quantity of Material:** 20 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROI/Forms/SuspACMDesignatRecord.nmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADH-07 Damaged: Yes No Friable Non-Friable
 Visible Covered WAB Size: N/A

General Description: ADHESIVE Cover/Secondary Color: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Estimated By: Drawing Assumed
 Quantity of Material: 20 (SF) / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-06

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building 1 **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-08 Visible Damaged: Yes No Friable Non-Friable
General Description: SEALANT (DOES, MILDLY, FIXTURES) Size: N/A
Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
Quantity of Material: 15 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.F.D.09 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL/WOOD CLADDING Cover/Secondary Color: N/A

Quantity of Material: 63 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 06/30/08 Signature: *[Signature]* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-10 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12"x12"

Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 175 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 06/30/08 Signature: *MR* Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building 1 **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S. 11 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: ELASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
Quantity of Material: 175 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.C.T. 10

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WATS-12 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4"

General Description: WALLBASE (COVERED) Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Matrix/Primary Color: BROWN Estimated By: Drawing Field Measure
 Quantity of Material: 30 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CV Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ACADH-15 Damaged: Yes No Friable Non-Friable
 Visible Covered WAB Size: N/A

General Description: ADHESIVE Cover/Secondary Color: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: PLAIBLE Estimated By: Drawing Field Measure
 Quantity of Material: 30 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH WAB-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building 1 Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.BUR.14 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT-UP ROOFING Cover/Secondary Color: GRAY MINERAL CAP
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Estimated By: Drawing Field Measure
 Quantity of Material: 350 SF / LF / EA Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building I Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: N/MAS-15 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MASTIC (PENETRATIONS & FLASHINGS)

Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: N/A

Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building 1 **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ASP-10 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: ASPHALT (CENTRALS) **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** ASPHALTIC **Cover/Secondary Color:** N/A
Quantity of Material: 350 **Estimated By:** Drawing Field Measure Sampled Assumed
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **ASBESTOS-CONTAINING MATERIAL**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.H.C. 01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustic Ceiling Tiles Size: 2'x4'
 Matrix/Primary Color: GRAY Cover/Secondary Color: WHITE
 Quantity of Material: 1700 Estimated By: Drawing Field Measure Sampled Assumed
 Texture/Pattern: FAKES & FISSURES LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	EastWest Direction	North/South Direction	Height A.F.F.	Surface
A	LOUNGE	NE Corner	W O	S 2'	10'	F / W (C) / O
B	I	NW Corner	E O	S 2'	10'	F / W (C) / O
C	STORAGE	NE Corner	W O	S 2'	10'	F / W (C) / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 117MR02 Damaged: Yes No Friable Non-Friable
 General Description: PACKABLE WALL PANEL Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CORNER Cover/Secondary Color: BLACK COVER
 Quantity of Material: 1400 Estimated By: Drawing Field Measure
 Visible Covered
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LOUNGE	SE Corner	W 4'	N 6'	3"	F/W/C/O
B	I	SW Corner	E 3'	N 2'6"	3"	F/W/C/O
C	STORAGE	NE Corner	W 5'	S 7'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Mechanically Attached

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: _____ Visible Covered Friable Non-Friable
General Description: _____ **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: ORANGE **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** N/A
Quantity of Material: 800 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DR **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesig/Record.01mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.S-04 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: BRITCE Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.O.S

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.arnf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-4 AB-05 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE Size: 1 1/2"
 Matrix/Primary Color: MARK BROWN Texture/Pattern: JINGL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.D.A.T.O.L.O Visible Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE Covered W.A.S Drawing Field Measure
Matrix/Primary Color: CREAM 50 50 N/A N/A
Quantity of Material: 50 50 N/A N/A
Texture/Pattern: FRIABLE N/A N/A
Estimated By: N/A N/A

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.W.A.S.O.S

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.0mt

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.P.V. 07 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: FIRE DOOR **Size:** N/A
Matrix/Primary Color: N/A **Texture/Pattern:** MIXED WOOD GRAIN **Cover/Secondary Color:** N/A
Quantity of Material: 42 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.Y.W.P. 08 Damaged: Yes No Friable Non-Friable
 General Description: SACRIFICE WALL PANEL Visible Covered: Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: UNCL COVER
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesig/Record.orm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSAC-09 Visible Covered Friable Non-Friable
General Description: SINK ACOUSTICAL COATING **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** ROUGH **Cover/Secondary Color:** N/A
Quantity of Material: 4 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 215A1.10 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SPRAC APPLIED EXTERIOR **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 2800 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. GWS. 11 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wall board Size: 2' x 4'
 Matrix/Primary Color: WHITE Texture/Pattern: CATSKY Cover/Secondary Color: SLA
 Quantity of Material: 2800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH D.SAT. 10

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.ami

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: WAS-64 Visible Damaged: Yes No Friable Non-Friable
General Description: WAS-64 Covered JK8 **Size:** N/A
Matrix/Primary Color: YELLOW **Texture/Pattern:** FLACKY **Cover/Secondary Color:** N/A
Quantity of Material: 100 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Asesociated with M.V.C.R. 15

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ortm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.V. 15 Visible Covered Friable Non-Friable
General Description: GRAFFITI (DOORS, FIXTURES)
Matrix/Primary Color: WHITE **Texture/Pattern:** FRIABLE **Cover/Secondary Color:** N/A
Quantity of Material: 5 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: SEAF-210 **Damaged:** Yes No Friable Non-Friable
 Visible Covered
General Description: SPRAY APPLIED TEXTURE **Size:** N/A
Matrix/Primary Color: WHITE **Cover/Secondary Color:** N/A
Quantity of Material: 1900 **Estimated By:** Drawing Field Measure
 SF LF / EA **Texture/Pattern:** CRACKY

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-4288 fax

FM GROUP/Forms/SuspACMDesigRecord.01mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSAC.07 Damaged: Yes Non-Friable
 Visible Covered Friable
 Covered No Non-Friable
 General Description: SINK ABOVE STAIR CASE Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O


Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHRA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAF-18 Visible Covered Friable Non-Friable
Damaged: Yes No
General Description: SPAC APPLIED TEXTURE **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKS **Cover/Secondary Color:** N/A
Quantity of Material: 150 LF / EA **Estimated By:** Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Ben Furlong Education Center **Address:** 8700 South Kyrene Road
Campus Name: Building K Tempe, AZ 85284

Material Code: M-GWB-A Visible Covered Friable Non-Friable
General Description: GYPSUM WALLBOARD Damaged: Yes No **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 150 SF / LF / EA **Estimated By:** Drawing Field Measure
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-18

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: **Signature:** **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-15E-20 Visible Covered SAS Damaged: Yes No Friable Non-Friable
General Description: Suspect Contaminated
Matrix/Primary Color: White **Texture/Pattern:** Crack & Key **Cover/Secondary Color:** N/A **Size:** N/A
Quantity of Material: 15 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience NIA

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASBESTOS REMOVED WITH M.GUNB-20

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 271-7577
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCB.21 Visible Covered Friable Non-Friable
General Description: CARPET **Damaged:** Yes No **Size:** 1/2" x 1/4"
Matrix/Primary Color: BLUE **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** N/A
Quantity of Material: 700 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/terms/SuspACMDesigRecord.orm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MT. 22 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: WALL **Size:** N/A
Matrix/Primary Color: YELLOW **Texture/Pattern:** SPRINKLE **Cover/Secondary Color:** N/A
Quantity of Material: 900 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MICR-21

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-3288 fax

FM GROUP/forms/SuspACMDesigRecord.01mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building K **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.B-25 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: BASE **Size:** 40
Matrix/Primary Color: Blue **Texture/Pattern:** UNK-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 40 LF / EA **Estimated By:** Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MADAT-24 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Asbestos Texture/Pattern: Friable Cover/Secondary Color: N/A Size: 2 1/4"
 Matrix/Primary Color: CREAM Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 40 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MURB'23

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.A.P.R.25 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT PAVED ROOFING (ROOF) Size: 25' x 44'
 Matrix/Primary Color: BLACK Cover/Secondary Color: SPRAC MOUNTED CAP
 Quantity of Material: 1800 Estimated By: Drawing Field Measure
 Texture/Pattern: SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 221.BF.26 Damaged: Yes No Friable Non-Friable
 General Description: VAPOR BARRIER FEED Size: 1/4"
 Matrix/Primary Color: BLACK Cover/Secondary Color: W/A
 Quantity of Material: 1800 Estimated By: Drawing Field Measure
 Texture/Pattern: ASPHALTIC SFL / EA Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ALL N.A.P.R. 25

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MAS. 27 Damaged: Yes No Friable Non-Friable
 General Description: ASBESTIC (PENETRATIONS) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ASP-28 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT (ENTRIES) Visible Covered
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.H. 101 Damaged: Yes No Friable Non-Friable
 General Description: ACROBATIC CEILING PANEL Size: 24x4'
 Matrix/Primary Color: GRAY Texture/Pattern: PANORAMA FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 1600 Estimated By: Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STORAGE 1	NW Corner	E 6'	S 4'	10'	F/W/C/O
B	1	SE Corner	W 3'	N 0'	10'	F/W/C/O
C	2	NW Corner	E 0'	S 1'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DR Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.08mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSWP.02 Damaged: Yes No Friable Non-Friable
 General Description: PACKABLE WALL PANEL Visible Covered
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: SINGLE COVER Size: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SOPHIE 01	SE Corner	W 6'	N 0'	3"	F (W) / C / O
B	L 01	SW Corner	E 4'	N 6'	3"	F (W) / C / O
C	L 02	NW Corner	E 2'	S 6'	3"	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCPT-03 Visible Covered Friable Non-Friable
General Description: CAFFES **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: BROWN **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** N/A
Quantity of Material: 1000 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ortm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.S.D.F. Damaged: Yes Non-Friable
 Visible Covered CP No Size: N/A
 General Description: Asbestos Texture/Pattern: SPICE Cover/Secondary Color: N/A
 Matrix/Primary Color: Chelon Estimated By: Drawing Assumed
 Quantity of Material: 1600 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P. 03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: DT0790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: NWABOS Visible Covered Friable Non-Friable
General Description: NAC BASE COVER **Damaged:** Yes No **Size:** 4"
Matrix/Primary Color: BROWN **Texture/Pattern:** UNIF-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 80 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCADH.04E Visible Covered WAS Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.WABOS

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 4.F.D.1.07 Damaged: Yes No Friable Non-Friable
 General Description: FIRE SCOR (ASBESTOS) Size: 1/2" x 1/2"
 Matrix/Primary Color: N/A Texture/Pattern: WEEB CANNING COVER/SECONDARY COLOR: N/A
 Quantity of Material: 42 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/Forms/SuspACMDesigRecord.ortf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. 08-202 Visible Covered Friable Non-Friable
General Description: FRAGILE WALL PANEL **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: BROWN **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** WHITE COVER
Quantity of Material: 150 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSAC-09 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: SINK ACROUSTIC CEILING **Size:** 1/4
Matrix/Primary Color: Black **Texture/Pattern:** ROUGH **Cover/Secondary Color:** Black
Quantity of Material: 2 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 6-521-10 Visible Covered Friable Non-Friable
General Description: SPRAC ADHESIVE TEXTURE
Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKLY **Cover/Secondary Color:** N/A
Quantity of Material: 150 **Estimated By:** Drawing Field Measure Sampled Assumed
Size: 2 1/4

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: DK **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.GWB.11 Visible Covered SM Friable Non-Friable
General Description: CEILING WALLBOARD **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 150 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.S.A.T. 10

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DK **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.01mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.D.S.C. 12 Damaged: Yes No Friable Non-Friable
 General Description: SOIL COMPACTED SAND Size: 2 1/2"
 Matrix/Primary Color: WHITE Cover/Secondary Color: RED
 Quantity of Material: 15 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASBESTOS DESIGNATED WITH AN GUSB.C.I

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.R.C.B Visible Covered Friable Non-Friable
General Description: ASBESTOS REPAIRED ROOF (SHINGLES) Damaged: Yes No Size: N/A
Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY MINERAL CAP
Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7077
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. VBF. 104 Visible Covered Friable Non-Friable
General Description: VAPOR BARRIER Damaged: Yes No Sampled Assumed
Matrix/Primary Color: BLACK Drawing Field Measure Sampled Assumed
Quantity of Material: 2100 **Texture/Pattern:** SF / LF / EA **Cover/Secondary Color:** N/A **Size:** N/A

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ALW M. APR. 13

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7677
 (602) 277-4288 fax



 FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building L **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSET-100 Visible Covered Friable Non-Friable
General Description: SPRINKLER DOORS **Damaged:** Yes No **Size:** 2/14
Matrix/Primary Color: WHITE **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** W/14
Quantity of Material: 2 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP Forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.ASP.17 Visible Covered: Visible Covered Damaged: Yes No Friable Non-Friable

General Description: ASPHALT (CRACKS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: N/A

Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.08f

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building M Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MFD101 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: FIRE DOOR W/SEALANT Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: MERLINWOOD CADDISCOVER/SECONDARY COLOR: N/A
 Quantity of Material: 5K Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-4288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building M Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CONV.02 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE FOUNDATION Visible Covered: Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: HEMISPHERICAL Cover/Secondary Color: N/A
 Quantity of Material: 2800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building R Address: 8700 South Kyrene Road
 Campus Name: Ben Fujong Education Center Tempe, AZ 85284

Material Code: M.C.M.U.01 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT Size: 8"X10"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONOUS Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 06/30/08 Signature: _____ Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-6288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building R Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MKT-02 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MORTAR Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 200 LF / EA S

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MCMUOI

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building R **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON-03 Visible Friable
 Covered Non-Friable
General Description: CONCRETE (FOUNDATION) **Size:** N/A
Matrix/Primary Color: GRAY **Cover/Secondary Color:** N/A
Quantity of Material: 1500 **Estimated By:** Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 06/30/08 **Signature:** [Signature] **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building R **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.FD1.04 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: FIRE DOOR INSULATION Size: N/A
Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
Quantity of Material: 42 (SF) / LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building R Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.PES-05 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: PIPE-END SEALANT Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLAQUE Estimated By: Drawing Field Measure
 Quantity of Material: 30 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building R Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.T.O.L.O. Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (EQUIPMENT) Cover/Secondary Color: N/A Sampled Assumed
 Matrix/Primary Color: BLACK Texture/Pattern: GUMMI Estimated By: Drawing Field Measure
 Quantity of Material: 10 (SF) LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No. D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7077
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building R **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.T.07 **Damaged:** Yes No Friable Non-Friable
General Description: SEALANT (DOORS, EXTERIOR) **Visible Covered:** Visible Covered **Size:** N/A
Matrix/Primary Color: GRAY **Texture/Pattern:** FRIABLE **Cover/Secondary Color:** N/A
Quantity of Material: 5 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 06/30/08 **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building R Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.BAL.08 Damaged: Yes No Friable Non-Friable

General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAVEL CAP

Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 06/30/08 Signature: [Signature] Date: 06/30/08

Asbestos-Containing Material: No Yes Assumed

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building R **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSF.10 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SEALANT (DMST) **Size:** 1/4"

Matrix/Primary Color: GRAY **Texture/Pattern:** FRIABLE **Cover/Secondary Color:** 1/4" Sampling Assumed
Quantity of Material: 10 SF / LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 271-7877
 (602) 271-5288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building R **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-STU-11 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: STUCCO **Size:** N/A

Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 2500 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 06/30/08 **Signature:** *[Signature]* **Date:** 06/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8286 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-Bur.01 Visible Covered Friable Non-Friable
General Description: BUST UP ROOFING Damaged: Yes No **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** ASPHALTIC **Cover/Secondary Color:** CAROL UNIVERSAL CAP
Quantity of Material: 35,000 **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesig/Record.ormf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.C. 03 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: SOACANT (FEASIBILITY) Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W-WDBOX Visible Covered Friable Non-Friable
General Description: Woven Rubber Boot **Damaged:** Yes No **Size:** 24"
Matrix/Primary Color: Black **Texture/Pattern:** RUBBER-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 20 SF LF EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: DK **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.5157.05 Damaged: Yes Non-Friable
 Visible No Friable
 Covered Size: N/A
 General Description: SEALANT (Duct) Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Assumed
 Quantity of Material: 30 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-DST-010 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seams Vape Size: 4"
 Matrix/Primary Color: White Texture/Pattern: Canvas Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Roof	NW Corner	E 15'	S 10'	2'	F / W / I / C / O
B		Corner	E 15'	S 11'	3'	F / W / I / C / O
C		Corner	E 14'	S 10'	1'	F / W / I / C / O
D		Corner				F / W / I / C / O
E		Corner				F / W / I / C / O
F		Corner				F / W / I / C / O
G		Corner				F / W / I / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *CR* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CMM-07 Visible Covered Friable Non-Friable
General Description: Concrete Masonry Units Damaged: Yes No **Size:** 8' x 16"
Matrix/Primary Color: Gray **Texture/Pattern:** Cementitious **Cover/Secondary Color:** N/A
Quantity of Material: 9000 **Estimated By:** Drawing Field Measure
Homogeneous Material Location: Ceiling Floor Wall Other Sampled Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-0101-08 Visible Friable Non-Friable
 Covered
General Description: CONCRETE MASONRY UNIT **Size:** 8" x 16"
Matrix/Primary Color: GRAY **Texture/Pattern:** CONCRETE **Cover/Secondary Color:** B' & B' PATTERN
Quantity of Material: 4500 **Estimated By:** Drawing Sampled
 SE / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.K.T.09 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: Asbestos **Size:** N/A
Matrix/Primary Color: SP **Texture/Pattern:** SEMANTIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 1350 **Estimated By:** Drawing Field Measure
(SF) LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U. 08, M.C.M.U. 09

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.55U.10 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: GRAY Size: 1/4
 Matrix/Primary Color: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 7000 Estimated By: Drawing Field Measure
 LF / EA Sampling

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-3288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.orm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-57U-11 Damaged: Yes Friable
 Visible No Non-Friable
 Covered
 General Description: Plaster Size: 2 1/2"
 Matrix/Primary Color: Gray Cover/Secondary Color: White
 Quantity of Material: 2000 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S. 112 Damaged: Yes Non-Friable
 Visible No
 Covered
 General Description: SEALANT (DOORS, WINDOWS, EXPANSION) Size: 2 1/2"
 Matrix/Primary Color: Gray Cover/Secondary Color: White
 Texture/Pattern: FLAKY Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON.13 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Foundation Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Cementitious Cover/Secondary Color: White
 Quantity of Material: 35,000 Estimated By: [Signature] Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FMI
GROUP INC

FM GROUP/forms/SuspACMDesigRecord.amm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCON-14 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: Concrete **Size:** N/A
Matrix/Primary Color: Gray **Texture/Pattern:** CEMENT TILES **Cover/Secondary Color:** N/A
Quantity of Material: 2000 LF / EA Drawing Assumed
 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesignRecord.01mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.S.P.-15 Visible Covered Friable Non-Friable
General Description: ASBESTOS CENTERS Yes No **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** ASBESTIC **Cover/Secondary Color:** N/A
Quantity of Material: 10,000 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.S.F. 17 Visible Covered Friable Non-Friable
General Description: TRONELLED ON FURNITURE Damaged: Yes No Drawing Assumed
Matrix/Primary Color: W/WHITE LF / EA Field Measure **Size:** N/A
Quantity of Material: 10,000 **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/Forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: NA-GWB-B Visible Covered YOF Friable Non-Friable
General Description: CEILING ASBESTOS BOARD **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKED **Cover/Secondary Color:** N/A
Quantity of Material: 10,000 **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH B.Y.O.F. 17

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-57E-19 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: POINT COMPOUND **Texture/Pattern:** CRACKS **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: White/BE **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 1000 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.W.B. (B)

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 6/30/08 **Signature:** **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 11-568-20 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SEALANT (DOORS, WINDOWS, FIXTURES) **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** FLAKE **Cover/Secondary Color:** N/A
Quantity of Material: 30 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-21 Visible Covered Friable Non-Friable
General Description: WALLBASE (COND) Damaged: Yes No Sampled Assumed
Matrix/Primary Color: BROWN **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 400 SF / LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: _____ **Date:** 6/30/08 **Signature:** _____ **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M1-ADH-22 Visible Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE Covered NAB **Size:** 2 1/2"
Matrix/Primary Color: CHALK **Texture/Pattern:** PELLE **Cover/Secondary Color:** N/A
Quantity of Material: 400 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.W.A.S.-21

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AL-108-23 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12"x12"
 Matrix/Primary Color: YAN Texture/Pattern: SANDY Cover/Secondary Color: GRAY MOTTED
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.P.A.S.-24 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: WASPIC **Texture/Pattern:** FRIABLE **Estimated By:** Drawing Field Measure **Size:** 2 1/4"
Matrix/Primary Color: YELLOW **Cover/Secondary Color:** N/A
Quantity of Material: 300 **SP / LF / EA**

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASBOCATED WITH M. VGT. 25 M-VCT. 50

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesigRecord.orm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-27 Visible Covered: SAT Damaged: Yes No Friable: Non-Friable:
 General Description: JOINT COMPOUND Size: 2 1/2"
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Conference	NE Corner	W 3'	S 0'	4'	F/W/C/O
B	Office 02	SW Corner	E 3'	N 0'	4'	F/W/C/O
C	Tool Crib 02	NW Corner	E 0'	S 3'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASBESTOS-CONTAINING MATERIAL IDENTIFIED

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC.

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-28 Visible Covered Friable Non-Friable
General Description: WALL BASE (COND) **Texture/Pattern:** WIND-LIKE **Estimated By:** [Signature] **Size:** 4" x 4"
Matrix/Primary Color: TAN **Cover/Secondary Color:** N/A
Quantity of Material: 5 LF / EA Drawing Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W-ADH-29 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: PILABLE Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH ADHESIVE

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 6/30/08
 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. AH. S1 Damaged: Yes No Friable Non-Friable
 General Description: ARRESTICAL CEILING PANEL Size: 2'x4'
 Matrix/Primary Color: Green Texture/Pattern: Polished Fibrous Cover/Secondary Color: White
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 01	SW Corner	E 20'	N 1'	8'	F/W/C/O
B	Reception 01	SE Corner	W 10'	N 2'	8'	F/W/C/O
C	Office 06	NE Corner	W 2'	S 1'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.V.C.F. 32 Visible Covered: Visible Covered
 General Description: WINDY CARPENTRY FICE Damaged: Yes No Friable Non-Friable
 Matrix/Primary Color: Light Brown Texture/Pattern: Smooth Cover/Secondary Color: Brown Nobs Size: 12" x 12"
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.M.A.S.-33 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: WALLS **Texture/Pattern:** TACKY **Estimated By:** Drawing Field Measure Sampled Assumed
Matrix/Primary Color: YELLOW **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 4000 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other Sampled Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.V.C.T.-32

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 11. A.M. 34 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2x2'
 Matrix/Primary Color: GRAY Texture/Pattern: SMALL PINHOLE AND WIDE FISSURES over/Secondary Color: WHITE
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 01	SE Corner	W 20'	N 2'	8'	F / W / <u>(C)</u> / O
B	Conference	NW Corner	E 2'	S 6'	8'	F / W / <u>(C)</u> / O
C	Plan Room	SE Corner	W 4'	N 2'	8'	F / W / <u>(C)</u> / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesignRecord.ami

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CH-32 Visible Damaged: Yes No Friable Non-Friable
 Covered **Size:** N/A

General Description: Carpet **Cover/Secondary Color:** Multicolored Stripes
Matrix/Primary Color: Blue **Texture/Pattern:** Ribbed
Quantity of Material: 1500 **Estimated By:** Drawing Field Measure
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed



SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W. M. S. 21 **Damaged:** Yes No Friable Non-Friable
General Description: Yellow **Visible Covered:** CP **Size:** N/A
Matrix/Primary Color: Yellow **Texture/Pattern:** PACKED **Cover/Secondary Color:** N/A
Quantity of Material: 1500 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. C. B. 36

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ALCUB-58 Visible Covered Friable Non-Friable
General Description: WALLBASE (CONC) Damaged: Yes No Sampled Assumed
Matrix/Primary Color: BUNE Drawing Field Measure **Size:** 4"
Quantity of Material: 80 **Texture/Pattern:** SINGLE-LIKE **Cover/Secondary Color:** N/A

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: WADA-39 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: 2' x 1'
 Matrix/Primary Color: CREAM Texture/Pattern: PILASTR Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH WADA-39

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCB-40 Visible Covered Friable Non-Friable
General Description: CARPET **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: TAN **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** RED STRIPES
Quantity of Material: 6000 **Estimated By:** Drawing Field Measure
 SF LF EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MAS-41 Damaged: Yes No Friable Non-Friable
 General Description: Masonry Visible Covered Size: N/A
 Matrix/Primary Color: CREW Texture/Pattern: BRICK Cover/Secondary Color: N/A
 Quantity of Material: 6000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P. 40, M.W.A.B. 42

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. opt. 42 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: CARPET (covered) **Size:** 4" **Cover/Secondary Color:** N/A

Matrix/Primary Color: BEACK **Texture/Pattern:** FIBROUS **Estimated By:** Drawing Field Measure Sampled Assumed

Quantity of Material: 160 LF / EA Floor Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other


Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 6/30/08 **Signature:** _____ **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed



**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MC-ENV-43 **Damaged:** Yes Non-Friable
 Visible No
 Covered
General Description: GRAVED WALLACE **Size:** 4" x 4"
Matrix/Primary Color: WHITE **Cover/Secondary Color:** N/A
Quantity of Material: 1200 **Estimated By:** Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Signature:** _____ **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ami

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GINT-44 Visible Covered Friable Non-Friable
General Description: GLAZED WALL TILE (PATTERN) Size: 4"X4"
Matrix/Primary Color: BLACK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
Quantity of Material: 400 LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 6/30/08 **Signature:** **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. GWT-43 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: GRASS Size: 2 1/4
 Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 120 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASBESTOS DESIGNATED WITH M. GWT-43, M. GWT-44

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9286 fax

FM GROUP, INC.

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. Q.P. 41c Visible Covered Friable Non-Friable
General Description: QUARRY PAVEMENT Damaged: Yes No **Size:** 8" x 8"
Matrix/Primary Color: BLACK **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** GRAY SPECKS
Quantity of Material: 750 (SF) / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesig/Record.ormf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CR-AT7 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GROUT Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Quantity of Material: 75 Estimated By: Drawing Field Measure
 SF LF / EA Floor Wall Other Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.D.P.T. 46

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.C.P. 48 Visible Covered Friable Non-Friable
 Damaged: Yes No Size: N/A

General Description: CRACK **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** MECHANICALLY SPECKLED
Matrix/Primary Color: GRAY **Estimated By:** Drawing Field Measure
Quantity of Material: 500 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed



**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**

19574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MA5-49 Damaged: Yes No Friable Non-Friable
 General Description: MASIC Texture/Pattern: SACKED Size: N/A
 Matrix/Primary Color: Yellow Estimated By: Drawing Field Measure
 Quantity of Material: 500 Cover/Secondary Color: N/A

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MCHS

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 11-VK-50 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: VINYL COMPOSITION TILE **Size:** 12" X 12"
Matrix/Primary Color: WHITE **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** BROWN MOSES
Quantity of Material: 250 SE / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ort

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MAS-51 Visible Covered Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASSTIC Size: N/A
 Matrix/Primary Color: YELLOW Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.K.G. 50

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

F M
GROUP INC.

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building T Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.SMP.52 Damaged: Yes Non-Friable
 Visible Covered No Size: N/A
 General Description: FRIABLE WALL PANEL Cover/Secondary Color: VINYL COVER
 Matrix/Primary Color: WHITE Texture/Pattern: GRAY Estimated By: Drawing Sampled
 Assumed
 Quantity of Material: 250 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	<u>Abyss</u>	NE Corner	W 0'	S 5'	4'	F <input checked="" type="checkbox"/> W <input type="checkbox"/> I <input type="checkbox"/> C <input type="checkbox"/> O
B		NE Corner	W 0'	S 10'	4'	F <input checked="" type="checkbox"/> W <input type="checkbox"/> I <input type="checkbox"/> C <input type="checkbox"/> O
C		NE Corner	W 0'	S 15'	4'	F <input checked="" type="checkbox"/> W <input type="checkbox"/> I <input type="checkbox"/> C <input type="checkbox"/> O
D		Corner				F / W / I / C / O
E		Corner				F / W / I / C / O
F		Corner				F / W / I / C / O
G		Corner				F / W / I / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-53 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SPRAY APPLIED TEXTURE **Size:** N/A

Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKS **Cover/Secondary Color:** N/A

Quantity of Material: 250 SE / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building T **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VCT-5C Visible Covered Friable Non-Friable
General Description: Vinyl Composition Tile (PATTERN) **Size:** 12" X 12"
Matrix/Primary Color: Light Blue **Texture/Pattern:** Smooth **Cover/Secondary Color:** White Mottles
Quantity of Material: SD **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 6/30/08 **Signature:** **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 **Project Name:** AHRA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building U **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCON-01 Visible Covered Friable Non-Friable
General Description: CORPSE FOUNDATION Damaged: Yes No **Size:** N/A
Matrix/Primary Color: SPRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A
Quantity of Material: 2800 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *DM* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building U Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CON.02 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE CORNERS Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A Size: 25A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage U Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.CTG.03 Damaged: Yes Non-Friable
 Visible No Friable
 Covered Size: N/A
 General Description: COATING Cover/Secondary Color: N/A Sampled
 Matrix/Primary Color: WHITE Estimated By: Drawing Assumed
 Quantity of Material: 2800 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SPRAY APPLIED FOAM ROOFING

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSOCIATED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CTG-03 Damaged: Yes Non-Friable
 Visible No
 Covered
 General Description: Coating Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Spray Applied Foam Roofing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-AS-04 Visible Covered Friable Non-Friable
General Description: BACK (PENTAGON) STAIRWAYS **Damaged:** Yes No **Size:** 1/2
Matrix/Primary Color: BLACK **Texture/Pattern:** FLAKE **Cover/Secondary Color:** SLY
Quantity of Material: 50 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ASBESTOS Damaged: Yes No Friable Non-Friable
 General Description: CEILING DUCT Size: 2x12
 Matrix/Primary Color: GRAY Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 812313 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 2x4
 Matrix/Primary Color: GRAY Cover/Secondary Color: RED
 Quantity of Material: 7000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: SP/ LF / EA

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. C. M. W. 07 Damaged: Yes Friable
 Visible Non-Friable
 Covered
 General Description: CONCRETE W/ FLOOR ANTS Size: 0" x 1/4"
 Matrix/Primary Color: SPAC Texture/Pattern: CONCRETE Cover/Secondary Color: B&B FERRA
 Quantity of Material: 7500 Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ALEXS-09 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-3211-10 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SAUCCO **Size:** 2 1/2" x 1 1/2"
Matrix/Primary Color: GREEN **Texture/Pattern:** GRAIN **Cover/Secondary Color:** NR

Quantity of Material: 3500 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MC0011 Visible Covered Friable Non-Friable
General Description: CONCRETE FOUNDATION Yes No **Size:** AS/A
Matrix/Primary Color: GRAY **Texture/Pattern:** SMOOTH **Cover/Secondary Color:** SLA
Quantity of Material: 18,000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DR **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP Forms/SuspACM/DesigRecord.d.mfm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSY-13 **Damaged:** Yes No Friable Non-Friable
General Description: SEALANT (DOORS) **Size:** N/A
Matrix/Primary Color: GRAY **Texture/Pattern:** FLAKY **Cover/Secondary Color:** N/A
Quantity of Material: 7 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSB.KF Visible Covered Friable Non-Friable
General Description: SEALANT (DOORS, WINDOWS)
Matrix/Primary Color: BLACK **Texture/Pattern:** FLAKY **Cover/Secondary Color:** N/A
Quantity of Material: 18 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D18790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSD1-15 Visible Covered Friable Non-Friable
General Description: FIRE DOOR Damaged: Yes No Drawing Field Measure
Matrix/Primary Color: N/A Estimated By: Sampling Assumed
Quantity of Material: 420 SF/ LF / EA Drawing Field Measure
Texture/Pattern: BRICK/WOOD CLADDING Drawing Field Measure
Size: N/A Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ARC-100 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panels Size: 2'x4'
 Matrix/Primary Color: Gray Texture/Pattern: Randomly Placed Cover/Secondary Color: White
 Quantity of Material: 2000 Estimated By: [Signature] Drawing Sampled Assumed
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	OFFICE 01	SW Corner	E O	N 1'	10'	F / W / C / O
B	OFFICE 02	SE Corner	W O	N O	10'	F / W / C / O
C	STORAGE 01	NE Corner	W O	S O	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC.

FIM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 03A-07 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SPACE ABOVE CEILING **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKS **Cover/Secondary Color:** N/A
Quantity of Material: 3500 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.amf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building WV Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MSBIB Damaged: Yes No Friable Non-Friable
 General Description: Asbestos Wallboard Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 3500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Asbestos on Wall S.S.A.P. 17

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACM/DesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building VV Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 5:SR.1P Damaged: Yes No Friable Non-Friable
 General Description: SOUTH CAMPUS Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 350 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: CHALKY

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASBESTOS REMOVED WITH M-GUR-B

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DR Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP/forms/SuspACIMDesigRecord.cmf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MA-BLK-20 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Black **Size:** 5' x 8'
Matrix/Primary Color: Red **Texture/Pattern:** GREEN ANTOUR **Cover/Secondary Color:** N/A
Quantity of Material: 5000 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

FM GROUP/forms/SuspACM/DesignRecord.omi

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-NK-2 Damaged: Yes No Friable Non-Friable
 General Description: MORPH Size: N/A
 Matrix/Primary Color: GRAVEL Texture/Pattern: CONCRETE Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. BKK-20

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MT-VCT.72 Damaged: Yes No Friable Non-Friable
 General Description: UNK COMP. RTION Size: 12" x 12"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: GRAY MORTAR
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCWAS-ES Damaged: Yes No Friable Non-Friable
 Visible Covered Drawing Field Measure
 General Description: MASONIC Size: N/A
 Matrix/Primary Color: YELLOW Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V. 22

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.T. 24 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, FIXTURES) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.orm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 11-11A-B-25 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE COVERED Visible Covered
 Matrix/Primary Color: BROWN Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A Size: 1/2"
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.D.H. 26 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: CREAM Estimated By: Drawing Field Measure
 Quantity of Material: 150 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.A.D.H. 26

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.04P.21 Visible Covered Friable Non-Friable
General Description: SPRINKLER TEXTURE POPCORN **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CRACKY **Cover/Secondary Color:** N/A
Quantity of Material: 8000 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	WAREHOUSE	NW Corner	E 10'	S 5'	15'	F/W/C/O
B		NE Corner	W 15'	S 10'	15'	F/W/C/O
C		SW Corner	E 20'	N 15'	15'	F/W/C/O
D		SE Corner	W 5'	N 5'	15'	F/W/C/O
E		SE Corner	W 7'	N 16'	15'	F/W/C/O
F		NE Corner	W 0'	S 20'	15'	F/W/C/O
G		NE Corner	W 4'	S 3'	15'	F/W/C/O

Comments: _____
Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16674 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.orm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.GWB.28 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Cracks Cover/Secondary Color: N/A
 Quantity of Material: 350 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	WAREHOUSE	NW Corner	E 10'	S 5'	15'	F/W (C) O
B		NE Corner	W 15'	S 10'	15'	F/W (C) O
C		SW Corner	E 20'	N 15'	15'	F/W (C) O
D		Corner				F/W .)
E		Corner				F/W O
F		Corner				F/W O
G		Corner				F/W . O

Comments: ASSOCIATED WITH S.S.A.T. 27

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-32C-29 Visible Damaged: Yes No Friable Non-Friable
General Description: JOINT COMPOUND Covered SAT No N/A **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 35 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	WAREHOUSE	NW Corner	E 10'	S 5'	15'	F / W / C / O
B	I	NE Corner	W 15'	S 10'	15'	F / W / C / O
C	I	SW Corner	E 20'	N 15'	15'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: DM **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MAH.30 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: ACROUSTICAL CEILING PANEL **Size:** 2'x4'
Matrix/Primary Color: GRAY **Texture/Pattern:** Random Fibrous **Cover/Secondary Color:** WHITE
Quantity of Material: 800 **Estimated By:** [Signature] Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STORAGE 01	NE Corner	W 5'	S 10'	10'	F / W / C / O
B	OFFICE 05	NE Corner	W 0'	S 2'	10'	F / W / C / O
C	I	SE Corner	W 2'	N 4'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7077
(602) 277-8286 fax

FM GROUP/forms/SuspACIMDesigRecord.cfm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 31 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: CARPET (SELF STICK) Size: N/A
 Matrix/Primary Color: Grey Cover/Secondary Color: Unrecorded Sticks

Quantity of Material: 30 Estimated By: Drawing Field Measure
 Texture/Pattern: SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building WV Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M1-WAB-32 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A Size: 4"
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.D.H. 33 Visible Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE Covered **Size:** N/A
Matrix/Primary Color: CREAM **Texture/Pattern:** FRIABLE **Cover/Secondary Color:** N/A
Quantity of Material: 30 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.A.D.H. 33

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *DK* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP/Forms/SuspACM/DesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W-67AS-35 Visible Friable
 Covered Non-Friable
General Description: WALL BASE COVER **Damaged:** Yes No **Size:** 4' x 2'
Matrix/Primary Color: BLACK **Texture/Pattern:** VINYL-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 8 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/Forms/SuspACM/DesigRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: A.A.A.36 Visible Covered WAB **Damaged:** Yes No Friable Non-Friable
General Description: ADHESIVE **Texture/Pattern:** FRABLE **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: CREAM **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 8 SP / LF / EA Floor Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.W.A.S.35

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DR **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: ACAH.37 Visible Covered Friable Non-Friable
General Description: ACoustical Ceilings Panel **Damaged:** Yes No **Size:** 2x2x1
Matrix/Primary Color: Gray **Texture/Pattern:** Smooth & Fibrous **Cover/Secondary Color:** White
Quantity of Material: 700 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLEARING	NE Corner	W 2'	S 0'	10'	F / W / C / O
B	I	SW Corner	E 5'	N 0'	10'	F / W / C / O
C	KITCHEN	SW Corner	E 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M1-WAB-30 Visible Covered Friable Non-Friable
General Description: Under Floor (covered) **Damaged:** Yes No **Size:** 4"

Matrix/Primary Color: Light Brown **Texture/Pattern:** Wrinkle-Like **Cover/Secondary Color:** N/A
Quantity of Material: 20 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MADH-39 Visible Damaged: Yes No Friable Non-Friable
General Description: ADHESIVE Covered WAB N/A N/A
Matrix/Primary Color: CREAM RELEASE N/A N/A
Quantity of Material: 20 SF / LF / EA Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ADHESIVE WAB MADH-39

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SCT-40 Damaged: Yes No Friable Non-Friable
 General Description: SEARCH WORK Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: FLAKE Cover/Secondary Color: N/A
 Quantity of Material: 1 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building WV **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCFA-41 Visible Covered Friable Non-Friable
General Description: Carpet **Damaged:** Yes No **Size:** SHA
Matrix/Primary Color: SPROWN **Texture/Pattern:** FBRAW **Cover/Secondary Color:** MULTICOLORED STRIPS
Quantity of Material: 900 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: DM **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: W.M.P.S. 4R Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ASBESTOS Size: N/A
 Matrix/Primary Color: YELLOW Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.H.A.

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9286 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MA-APR-43 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: ACOUSITIC CEILING PANEL **Size:** 2'x4'
Matrix/Primary Color: GRACY **Texture/Pattern:** Knobby / fissured **Cover/Secondary Color:** White
Quantity of Material: 1700 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LOBBY	SE Corner	W 2'	N 2'	10'	F / W (C) / O
B	OPEN OFFICE	NE Corner	W 4'	S 4'	10'	F / W (C) / O
C	STORAGE 04	SE Corner	W 2'	N 2'	10'	F / W (C) / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Signature:** [Signature] **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: SSTC-46 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALK Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWB-45

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DK Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FMA GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 0808-477 Visible Covered Friable Non-Friable
General Description: QUARRY PAVEMENT 18" x 18" Size: Yes No
Matrix/Primary Color: WHITE SP/ LF / EA Texture/Pattern: N/A Cover/Secondary Color: Sampled Assumed
Quantity of Material: 1500 SP / LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.07mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. GR. 2/B Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2/8A
 General Description: CEILING Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 150 (SF) / LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. GR. 2/B

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MCB-4A Visible Covered: Visible Covered
 General Description: CARPET Damaged: Yes No Friable Non-Friable
 Matrix/Primary Color: BROWN Cover/Secondary Color: BROWN PATTERN Size: N/A
 Quantity of Material: 350 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MAS. 50 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Mastic **Texture/Pattern:** PACKED **Estimated By:** Drawing Field Measure Sampled Assumed
Matrix/Primary Color: Yellow **Cover/Secondary Color:** N/A
Quantity of Material: 350 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.F. 49

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-51 **Damaged:** Yes No Friable Non-Friable
General Description: WALBASE COVERED **Visible Covered:** Visible Covered **Size:** 4' x 4'
Matrix/Primary Color: PURPLE **Texture/Pattern:** UNH-L-LIKE **Cover/Secondary Color:** N/A
Quantity of Material: 125 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.07mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.H.52 Damaged: Yes No Friable Non-Friable
 Visible Covered WAS Size: N/A
 General Description: Asbestos Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Matrix/Primary Color: CREAM Estimated By: Drawing Field Measure
 Quantity of Material: 125 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MINOR 'S'

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DR Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.S.V.53 Damaged: Yes No Friable Non-Friable
 General Description: SEALED COOKS, WINDOWS, MINOR FIXTURES Size: R/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: R/A
 Quantity of Material: 7 Estimated By: Drawing Field Measure Sampled Assumed
 Texture/Pattern: FLAKY SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5286 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-S-V-54 Damaged: Yes No Friable Non-Friable
 General Description: SEACANT WINDOW Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Sampled Assumed
 Texture/Pattern: RIABLE Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MVSF.55 Damaged: Yes No Friable Non-Friable
 General Description: VINYL SHEET FLOORING Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: 4"X4" PATTERN
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Texture/Pattern: SANDOYA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: GRAY PAPER BACKING

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-202 **Project Name:** AHRA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Building W **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. MRS. 56 Visible Covered VSF **Damaged:** Yes No Friable Non-Friable
General Description: WASBK **Size:** N/A
Matrix/Primary Color: CELCOAD **Texture/Pattern:** SAERY **Cover/Secondary Color:** N/A
Quantity of Material: 75 SF LF EA **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.H.S.T Visible Covered MASONRY Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A Sampled Assumed
 Quantity of Material: SD Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH PANELING (WOOD) WITH SMUSH

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 6/30/08 Signature: _____ Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building W Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.ACB.SB Damaged: Yes No Friable Non-Friable
 General Description: ASBESTOS CEMENT BOARD Size: 2/4

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: SPRINKLE
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: PREVIOUSLY IDENTIFIED AS K18-12-D20

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



1697A N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Canopy Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CM-01 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit (COLUMNS) Size: 8" X 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 650 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Date: 6/30/08 Signature: Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Canopy **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-MRT-02 Visible Covered Friable Non-Friable
General Description: Mortar **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: Gray **Texture/Pattern:** Combinations **Cover/Secondary Color:** N/A
Quantity of Material: 65 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMU-01

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.orm

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Canopy **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ASP-03 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Asphalt **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: Black **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 6000 SF / LF / EA Floor Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-01 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY APPLIED POLYMER (POPCORN) Visible Covered
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	HALL WAY	NW Corner	E O	S O	8'	F / W C / O
B	DINING ROOM	SE Corner	W O	N O	8'	F / W C / O
C	BEDROOM 03	NE Corner	W O	S O	8'	F / W C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *GR* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7077
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S.J.R.08 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SOLITE COMPOUND **Size:** 2' x 4'
Matrix/Primary Color: WHITE **Texture/Pattern:** CHALKY **Cover/Secondary Color:** N/A
Quantity of Material: 160 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWBOR

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *DM* **Date:** 6/30/08 **Signature:** *MR* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SAT-04 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: SPRAY APPLIED TEXTURE Size: A/A
Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: A/A
Quantity of Material: 1200 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *DK* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.ornf

Project No.: 08-202 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M. GIBBONS Visible Damaged: Yes No Friable Non-Friable
General Description: CRACKED WALL BOARD Covered SAT No Size: N/A
Matrix/Primary Color: WHITE CRACKED Drawing Assumed
Quantity of Material: 1200 LF / EA Field Measure Assumed
Texture/Pattern: CRACKED Cover/Secondary Color: N/A

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.04

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: DN **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesigRecord.ortmf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: S-SYC-000 Damaged: Yes No Friable Non-Friable
 General Description: GOING CARPENTRY Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 120 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GAB'S

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: OK Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 08-202 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben-Furlong Education Center Tempe, AZ 85284

Material Code: S.SAF.07 Damaged: Yes No Friable Non-Friable
 General Description: SPRAEL APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHIERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DK* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.GWB.OB Damaged: Yes No Friable Non-Friable
 General Description: CAPSON WALL BOARD Size: 2/0
 Matrix/Primary Color: WHITE Texture/Pattern: CHECKY Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.S.A.T. 07

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: 2-SIC-08 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W. ENB-08

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AM-VSF-10 Damaged: Yes No Friable NonFriable
 General Description: SINGLE SLOPED FLOORING Visible Covered
 Matrix/Primary Color: WHITE Texture/Pattern: OMDORA Cover/Secondary Color: MARbled GRID Size: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Cray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: OR Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-1105-11 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: 2/1A
 Matrix/Primary Color: Yellow Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure
 Texture/Pattern: TACKY
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-1105-10, M-CPT-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: AC-CBF-12 Visible Covered **Damaged:** Yes No Friable Non-Friable

General Description: CARPET **Size:** N/A
Matrix/Primary Color: BROWN **Texture/Pattern:** FIBRED **Cover/Secondary Color:** N/A
Quantity of Material: 1500 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 6/30/08 **Signature:** [Signature] **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecordL.mfm

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-WAB-13 Damaged: Yes No Friable Non-Friable
 General Description: WALLBASE (COVERED) Size: 4"
 Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ADP-124 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: 2' x 6'
 Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSESSMENT WITH M.W.A.B. 13

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.08Y.15 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DK* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-4286 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GWT-16 Damaged: Yes No Friable Non-Friable
 General Description: CHAISED WALL PAPER Size: 4' x 4'
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 160 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Or* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-GUST-17 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: GROUT **Size:** N/A
Matrix/Primary Color: GRAY **Texture/Pattern:** CEMENTitious Cover/Secondary Color: N/A Sampled
Quantity of Material: 16 SF LF / EA **Estimated By:** Drawing Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: A w/ M-GUST-16

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: MA-VCSF-18 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: off-white & marbled
 Quantity of Material: 65 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.MAS.19 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: 2/4
 Matrix/Primary Color: Yellow Texture/Pattern: PACKED Cover/Secondary Color: N/A
 Quantity of Material: 65 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.VCT. 8

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.A.C.T. 20 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING TILE Size: 6x6
 Matrix/Primary Color: GRAY Cover/Secondary Color: WHITE
 Quantity of Material: 400 Estimated By: Drawing Field Measure
 Texture/Pattern: SMOOTH LF / EA SF

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	<u>BE D 01</u>	<u>NE Corner</u>	<u>W 0</u>	<u>S 0</u>	<u>8'</u>	<u>F / W / C / O</u>
B	<u>I</u>	<u>NE Corner</u>	<u>W 4'</u>	<u>S 0</u>	<u>8'</u>	<u>F / W / C / O</u>
C		<u>NE Corner</u>	<u>W 6</u>	<u>S 0</u>	<u>8'</u>	<u>F / W / C / O</u>
D		Corner				<u>F / W / C / O</u>
E		Corner				<u>F / W / C / O</u>
F		Corner				<u>F / W / C / O</u>
G		Corner				<u>F / W / C / O</u>

Comments: Mechanically Attached

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ami

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CR-21 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: MUSHROOMED SPECKS Size: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9286 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.M.A.S.-22 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: MASSIC Covered No Size: 2 1/4
Matrix/Primary Color: Yellow Texture/Pattern: FACKY Cover/Secondary Color: N/A
Quantity of Material: 400 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.R. 21

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9286 fax

FM GROUP/Forms/SuspACMDesigRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.C.P. 23 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: CARPET SELF STICK SQUARES **Size:** 6' x 18"
Matrix/Primary Color: GRAY **Texture/Pattern:** FIBROUS **Cover/Secondary Color:** N/A
Quantity of Material: 75 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 6/30/08 **Signature:** **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.01mf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.C.T. 22 Damaged: Yes No Friable Non-Friable
 General Description: CARPETS (SEE SACK SQUARES) Size: 18" X 18"
 Matrix/Primary Color: GREEN Texture/Pattern: FIBROUS Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 6/30/08 Signature: [Signature] Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.Lamf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Residence Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CTG-25 Damaged: Yes No Friable Non-Friable
 General Description: Coating Size: 2/4
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 2200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Spray Applied Foam Roofing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0.mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-26 Visible Damaged: Yes No Friable Non-Friable
General Description: Concrete (Foundation) Covered Size: N/A
Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
Quantity of Material: 2200 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesigRecord.08mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-27 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Concrete (Entries) **Size:** N/A

Matrix/Primary Color: Gray **Texture/Pattern:** Cementitious **Cover/Secondary Color:** N/A
Quantity of Material: 100 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *DM* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Residence **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ASP-28 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: Asphalt (encl(ies)) **Size:** N/A
Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** N/A
Quantity of Material: 75 **Estimated By:** Drawing Field Measure
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

FIM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage H **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-APR-01 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: ASPHALT PREPARED ROOFING (SHINGLES) **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** ASPHALTIC **Cover/Secondary Color:** GRAY MINERAL CAP
Quantity of Material: 400 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: _____ **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877 fax
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage H **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.VBF.OZ Visible Covered APR Damaged: Yes No Friable Non-Friable
General Description: VAPOR BARRIER FELT Size: N/A
Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: N/A
Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Assoc w/ Ft. Apache

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: _____ **Signature:** _____ **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage J Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-ARR-01 Damaged: Yes No Friable Non-Friable
 General Description: Asphalt Prepared Roofing (Shingles) Size: N/A
 Matrix/Primary Color: Black Cover/Secondary Color: Gray Mineral Col
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: Asphaltic SF / LF / EA

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *CSL* Date: 6/30/08 Signature: *MR* Date: 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7077
 (602) 277-9288 fax



Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage J **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-VBF-02 Visible Damaged: Yes Non-Friable
 Covered No Friable
General Description: Vapor Barrier Felt **Size:** N/A
Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** N/A
Quantity of Material: 100 SF / LF / EA **Estimated By:** Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-APR-01

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage J **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-03 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Concrete (Foundation) **Texture/Pattern:** Cementitious **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: Gray **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 100 SF / LF / EA Floor Wall Other

Homogeneous Material Location: Ceiling Random Convenience N/A
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage O **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-APR-01 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Asphalt Prepared Roofing **Size:** N/A

Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** Gray Mineral Cap
Quantity of Material: 90 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord1.0mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage O **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-UBF-02 Visible Damaged: Yes Friable
 Covered No Non-Friable
General Description: VADP BARRIER FELT **Size:** N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** N/A
Quantity of Material: 90 **Estimated By:** Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: AHS R. Appoi

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 6/30/08 **Signature:** *[Signature]* **Date:** 6/30/08

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ont

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage O **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CON-03 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: CONCRETE FOUNDATION **Texture/Pattern:** CONCRETE **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: GRAY **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 90 **SP / LF / EA** Floor Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage P Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CMU.01 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: Concrete Masonry Unit (COLUMNS) Size: 8" X 16"

Matrix/Primary Color: Gray Texture/Pattern: N/A Cover/Secondary Color: N/A

Quantity of Material: 6SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage P Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M.MRT-02 Material: Mortar Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 65 Estimated By: Drawing Field Measure Sampled Assumed

Texture/Pattern: Cementitious
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-000-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: *DK* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-9288 fax



FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage P Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-SLT-03 Damaged: Yes Non-Friable
 Visible Covered Friable
 Covered
 General Description: Sealant (EXPANSION) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Assumed
 Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 6/30/08 Signature: *[Signature]* Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecordL.mf

Project No.: 08-202 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Storage P **Address:** 8700 South Kyrene Road
Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-Asp-04 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Asphaltic **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: Black **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 6000 SF / LF / EA Ceiling Floor Wall Other
Homogeneous Material Location: Random Convenience N/A

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 6/30/08 **Date:** 6/30/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-202 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage P Address: 8700 South Kyrene Road
 Campus Name: Ben Furlong Education Center Tempe, AZ 85284

Material Code: M-CTG-05 Damaged: Yes No Friable Non-Friable
 General Description: Coating (ROOF) Texture/Pattern: Smooth Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 600 (SF / LF / EA) Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 6/30/08 Date: 6/30/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

APPENDIX B

Bulk-Material Sample Documents

- **Chain-of-Custody**
- **Laboratory Analysis**



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806165

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 30 PLM **Rec:** 7/2/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Ben Furlong-Bldg A **PO Number:** 08-202
Report Date: 7/22/2008 **Date Analyzed:** 7/22/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - In the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200806165

Ben Furlong-Bldg A

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color	Apparent Layer Type *	Asbestos Results	
Sample # M-APL-01A Layer # 1 off-white	2008-06165- 1	Ceiling Tile no asbestos detected	Positive Layer? No
Sample # M-APL-01B Layer # 1 off-white	2008-06165- 2	Ceiling Tile no asbestos detected	Positive Layer? No
Sample # M-APL-01C Layer # 1 off-white	2008-06165- 3	Ceiling Tile no asbestos detected	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white	2008-06165- 4	Wall System no asbestos detected	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white	2008-06165- 5	Wall System no asbestos detected	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white	2008-06165- 6	Wall System no asbestos detected	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white	2008-06165- 7	Wall System no asbestos detected	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white	2008-06165- 8	Wall System no asbestos detected	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white	2008-06165- 9	Wall System no asbestos detected	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white	2008-06165- 10	Wall System no asbestos detected	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white	2008-06165- 11	Wall System no asbestos detected	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white	2008-06165- 12	Wall System no asbestos detected	Positive Layer? No
Sample # M-CPT-05A Layer # 1 various	2008-06165- 13	Carpet no asbestos detected	Positive Layer? No
Sample # M-CPT-05B Layer # 1 various	2008-06165- 14	Carpet no asbestos detected	Positive Layer? No
Sample # M-CPT-05C Layer # 1 various	2008-06165- 15	Carpet no asbestos detected	Positive Layer? No
Sample # M-MAS-06A Layer # 1 Orange	2008-06165- 16	Adhesive/caulk no asbestos detected	Positive Layer? No
Sample # M-MAS-06B Layer # 1 Orange	2008-06165- 17	Adhesive/caulk no asbestos detected	Positive Layer? No
Sample # M-MAS-06C Layer # 1 Orange	2008-06165- 18	Adhesive/caulk no asbestos detected	Positive Layer? No
Sample # S-SAT-21A Layer # 1 white	2008-06165- 19	Wall System no asbestos detected	Positive Layer? No
Sample # S-SAT-21B Layer # 1 white	2008-06165- 20	Wall System no asbestos detected	Positive Layer? No
Sample # S-SAT-21C Layer # 1 white	2008-06165- 21	Wall System no asbestos detected	Positive Layer? No
Sample # M-GWB-22A Layer # 1 white	2008-06165- 22	Wall System no asbestos detected	Positive Layer? No
Sample # M-GWB-22B Layer # 1 white	2008-06165- 23	Wall System no asbestos detected	Positive Layer? No
Sample # M-GWB-22C Layer # 1 white	2008-06165- 24	Wall System no asbestos detected	Positive Layer? No
Sample # S-JTC-23A Layer # 1 white	2008-06165- 25	Wall System no asbestos detected	Positive Layer? No
Sample # S-JTC-23B Layer # 1 white	2008-06165- 26	Wall System no asbestos detected	Positive Layer? No
Sample # S-JTC-23C Layer # 1 white	2008-06165- 27	Wall System no asbestos detected	Positive Layer? No
Sample # M-APL-27A Layer # 1 off-white	2008-06165- 28	Ceiling Tile no asbestos detected	Positive Layer? No
Sample # M-APL-27B Layer # 1 off-white	2008-06165- 29	Ceiling Tile no asbestos detected	Positive Layer? No
Sample # M-APL-27C Layer # 1 off-white	2008-06165- 30	Ceiling Tile no asbestos detected	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample M-APL-01A Lab Number 2008-06165-1 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B Lab Number 2008-06165-2 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C Lab Number 2008-06165-3 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample S-SAT-02A **Lab Number** 2008-06165- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-06165- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-06165- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample M-GWB-03A Lab Number 2008-06165- 7 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B Lab Number 2008-06165- 8 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C Lab Number 2008-06165- 9 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806165

Ben Furlong-Bldg A

Sample S-JTC-04A Lab Number 2008-06165-10 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B Lab Number 2008-06165-11 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C Lab Number 2008-06165-12 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample M-CPT-05A Lab Number 2008-06165- 13 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Carpet Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	5-10%	-	-	-	-
Total %		100	Average %		40-50%	5-10%	-	-	-	-
Fiber Identification:					synthetic fiber (extr) glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	V	E	N	N	H	+	P	synthetic fiber (extruded)					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-05B Lab Number 2008-06165- 14 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Carpet Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	5-10%	-	-	-	-
Total %		100	Average %		40-50%	5-10%	-	-	-	-
Fiber Identification:					synthetic fiber (extr) glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	V	E	N	N	H	+	P	synthetic fiber (extruded)					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-05C Lab Number 2008-06165- 15 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Carpet Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	5-10%	-	-	-	-
Total %		100	Average %		40-50%	5-10%	-	-	-	-
Fiber Identification:					synthetic fiber (extr) glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	V	E	N	N	H	+	P	synthetic fiber (extruded)					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample M-MAS-06A Lab Number 2008-06165- 16 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Orange	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-06B Lab Number 2008-06165- 17 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Orange	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-06C Lab Number 2008-06165- 18 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Orange	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample S-SAT-21A Lab Number 2008-06165-19 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-21B Lab Number 2008-06165-20 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-21C Lab Number 2008-06165-21 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample M-GWB-22A Lab Number 2008-06165- 22 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-22B Lab Number 2008-06165- 23 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-22C Lab Number 2008-06165- 24 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample S-JTC-23A Lab Number 2008-06165- 25 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations						
								Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-23B Lab Number 2008-06165- 26 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations						
								Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-23C Lab Number 2008-06165- 27 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations						
								Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806165 Ben Furlong-Bldg A

Sample M-APL-27A Lab Number 2008-06165- 28 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-27B Lab Number 2008-06165- 29 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-27C Lab Number 2008-06165- 30 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806170

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Ben Furlong-Bldg B PO Number: 08-202
Report Date: 7/22/2008 Date Analyzed: 7/22/2008 Routing Number: -
Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $>1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $>1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200806170

Ben Furlong-Bldg B

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color	Apparent Layer Type *	Asbestos Results	
Sample # M-APL-01A Layer # 1 off-white	2008-06170- 1	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 off-white	2008-06170- 2	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 off-white	2008-06170- 3	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white	2008-06170- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white	2008-06170- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white	2008-06170- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white	2008-06170- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white	2008-06170- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white	2008-06170- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white	2008-06170- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white	2008-06170- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white	2008-06170- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ACT-12A Layer # 1 Yellow	2008-06170- 13	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ACT-12B Layer # 1 Yellow	2008-06170- 14	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ACT-12C Layer # 1 Yellow	2008-06170- 15	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-37A Layer # 1 off-white	2008-06170- 16	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-37B Layer # 1 off-white	2008-06170- 17	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-37C Layer # 1 off-white	2008-06170- 18	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806170 Ben Furlong-Bldg B

Sample M-APL-01A **Lab Number** 2008-06170-1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-06170-2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-06170-3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number:

200806170

Ben Furlong-Bldg B

Sample S-SAT-02A Lab Number 2008-06170-4 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dlssolution of matrix using dilute HCl acid.

Sample S-SAT-02B Lab Number 2008-06170-5 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dlssolution of matrix using dilute HCl acid.

Sample S-SAT-02C Lab Number 2008-06170-6 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dlssolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806170 Ben Furlong-Bldg B

Sample M-GWB-03A **Lab Number** 2008-06170- 7 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. No drywall core is present; sample is joint tape and joint compound.

Sample M-GWB-03B **Lab Number** 2008-06170- 8 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. No drywall core is present; sample is joint tape and joint compound.

Sample M-GWB-03C **Lab Number** 2008-06170- 9 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. No drywall core is present; sample is joint tape and joint compound.

PLM Analysis Details

Job Number:

200806170

Ben Furlong-Bldg B

Sample S-JTC-04A **Lab Number** 2008-06170- 10 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-06170- 11 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-06170- 12 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806170 Ben Furlong-Bldg B

Sample M-ACT-12A **Lab Number** 2008-06170- 13 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An? OK** **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer? No** **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-ACT-12B **Lab Number** 2008-06170- 14 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An? OK** **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer? No** **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-ACT-12C **Lab Number** 2008-06170- 15 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An? OK** **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer? No** **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806170 Ben Furlong-Bldg B

Sample M-APL-37A **Lab Number** 2008-06170- 16 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37B **Lab Number** 2008-06170- 17 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37C **Lab Number** 2008-06170- 18 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, slenwy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may

taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon

yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

Job Number: 200806171

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Ben Furlong-Bldg C

PO Number: 08-202

Report Date: 7/22/2008

Date Analyzed: 7/22/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200806171 Ben Furlong-Bldg C

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-06171- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-06171- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-06171- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white		<i>no asbestos detected</i>	
Sample #	M-ACT-07A	2008-06171- 4	Ceiling Tile	Positive Layer? No
Layer # 1	Yellow		<i>no asbestos detected</i>	
Sample #	M-ACT-07B	2008-06171- 5	Ceiling Tile	Positive Layer? No
Layer # 1	Yellow		<i>no asbestos detected</i>	
Sample #	M-ACT-07C	2008-06171- 6	Ceiling Tile	Positive Layer? No
Layer # 1	Yellow		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806171 Ben Furlong-Bldg C

Sample M-APL-01A **Lab Number** 2008-06171-1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-

Fiber Identification: cellulose fiber glass fiber

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations					
								Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-06171-2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-

Fiber Identification: cellulose fiber glass fiber

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations					
								Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-06171-3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-

Fiber Identification: cellulose fiber glass fiber

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations					
								Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806171 Ben Furlong-Bldg C

Sample M-ACT-07A **Lab Number** 2008-06171- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-ACT-07B **Lab Number** 2008-06171- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.


Sample M-ACT-07C **Lab Number** 2008-06171- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.


Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

Job Number: 200806172

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 15 **PLM Rec:** 7/2/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Ben Furlong-Bldg D

PO Number: 08-202

Report Date: 7/22/2008

Date Analyzed: 7/22/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200806172 Ben Furlong-Bldg D

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-06172- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-06172- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-06172- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	S-SAT-04A	2008-06172- 4	Wall System	Positive Layer? No
Layer # 1	Off-white	paint	<i>no asbestos detected</i>	
Sample #	S-SAT-04B	2008-06172- 5	Wall System	Positive Layer? No
Layer # 1	Off-white	paint	<i>no asbestos detected</i>	
Sample #	S-SAT-04C	2008-06172- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-05A	2008-06172- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-05B	2008-06172- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-05C	2008-06172- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-06A	2008-06172- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-06B	2008-06172- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-06C	2008-06172- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-ACT-12A	2008-06172- 13	Ceiling Tile	Positive Layer? No
Layer # 1	Yellow	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-ACT-12B	2008-06172- 14	Ceiling Tile	Positive Layer? No
Layer # 1	Yellow	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-ACT-12C	2008-06172- 15	Ceiling Tile	Positive Layer? No
Layer # 1	Yellow	ceiling tile	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806172 Ben Furlong-Bldg D

Sample M-APL-01A **Lab Number** 2008-06172- 1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleco	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-06172- 2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleco	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-06172- 3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleco	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806172 Ben Furlong-Bldg D

Sample S-SAT-04A **Lab Number** 2008-06172- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	paint	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. No texture was present between the paint and the paper wrap of the drywall.

Sample S-SAT-04B **Lab Number** 2008-06172- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	paint	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. No texture was present between the paint and the paper wrap of the drywall.

Sample S-SAT-04C **Lab Number** 2008-06172- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806172 Ben Furlong-Bldg D

Sample M-GWB-05A Lab Number 2008-06172-7 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-05B Lab Number 2008-06172-8 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-05C Lab Number 2008-06172-9 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806172 Ben Furlong-Bldg D

Sample S-JTC-06A Lab Number 2008-06172- 10 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-06B Lab Number 2008-06172- 11 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-06C Lab Number 2008-06172- 12 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806172 Ben Furlong-Bldg D

Sample M-ACT-12A **Lab Number** 2008-06172- 13 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-ACT-12B **Lab Number** 2008-06172- 14 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-ACT-12C **Lab Number** 2008-06172- 15 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Yellow	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806173

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 12 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Ben Furlong-Bldg E

PO Number: 08-202

Report Date: 7/22/2008

Date Analyzed: 7/22/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphoto-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary: Job Number: **200806173** Ben Furlong-Bldg E

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-06173- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-01B	2008-06173- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-01C	2008-06173- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	S-SAT-02A	2008-06173- 4	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-02B	2008-06173- 5	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-02C	2008-06173- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-03A	2008-06173- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-03B	2008-06173- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-03C	2008-06173- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-04A	2008-06173- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-04B	2008-06173- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-04C	2008-06173- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806173 Ben Furlong-Bldg E

Sample M-APL-01A **Lab Number** 2008-06173- 1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-06173- 2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-06173- 3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806173 Ben Furlong-Bldg E

Sample S-SAT-02A **Lab Number** 2008-06173- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-06173- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-06173- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number:

200806173

Ben Furlong-Bldg E

Sample M-GWB-03A Lab Number 2008-06173-7 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B Lab Number 2008-06173-8 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C Lab Number 2008-06173-9 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806173 Ben Furlong-Bldg E

Sample S-JTC-04A **Lab Number** 2008-06173- 10 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-06173- 11 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-06173- 12 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=plnk; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806174

Client:
FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Ben Furlong-Bldg K

PO Number: 08-202

Report Date: 7/22/2008

Date Analyzed: 7/22/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphoto-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

PLM Analysis Details

Job Number: 200806174 Ben Furlong-Bldg K

Sample M-APL-01A **Lab Number** 2008-06174-1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-06174-2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-06174-3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806174 Ben Furlong-Bldg K

Sample M-TWP-02A **Lab Number** 2008-06174- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid. Appears to be drywall board used as a panel.

Sample M-TWP-02B **Lab Number** 2008-06174- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid. Appears to be drywall board used as a panel.

Sample M-TWP-02C **Lab Number** 2008-06174- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid. Appears to be drywall board used as a panel.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806175

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Ben Furlong-Bldg L

PO Number: 08-202

Report Date: 7/22/2008

Date Analyzed: 7/22/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in Interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

PLM Analysis Details

Job Number: 200806175 Ben Furlong-Bldg L

Sample M-APL-01A Lab Number 2008-06175- 1 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B Lab Number 2008-06175- 2 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C Lab Number 2008-06175- 3 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/22/2008 An? OK Apparent Smp Type Ceiling Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806175

200806175

Ben Furlong-Bldg L

Sample M-TWP-02A **Lab Number** 2008-06175- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	W	F	N	N	H	+	U							
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid. Appears to be drywall used as a panel.

Sample M-TWP-02B **Lab Number** 2008-06175- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	W	F	N	N	H	+	U							
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid. Appears to be drywall used as a panel.

Sample M-TWP-02C **Lab Number** 2008-06175- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/22/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	W	F	N	N	H	+	U							
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid. Appears to be drywall used as a panel.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may

taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon

yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 22-Jul-2008

Original Print Date: 22-Jul-2008

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

Job Number: 200806176

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 27 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Ben Furlong-Bldg T PO Number: 08-202
Report Date: 7/24/2008 Date Analyzed: 7/24/2008 Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - In the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200806176

Ben Furlong-Bldg T

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-DST-06A Layer # 1 Silver duct tape	2008-06176- 1	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-06B Layer # 1 Silver duct tape	2008-06176- 2	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-06B Layer # 1 Silver duct tape	2008-06176- 3	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-25A Layer # 1 white texture/joint compound	2008-06176- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-25B Layer # 1 white texture/joint compound	2008-06176- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-25C Layer # 1 white texture/joint compound	2008-06176- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-26A Layer # 1 white drywall core	2008-06176- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-26B Layer # 1 white drywall core	2008-06176- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-26C Layer # 1 white drywall core	2008-06176- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-27A Layer # 1 white texture/joint compound	2008-06176- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-27B Layer # 1 white texture/joint compound	2008-06176- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-27C Layer # 1 white texture/joint compound	2008-06176- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-30A Layer # 1 Various panel	2008-06176- 13	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-30B Layer # 1 Various panel	2008-06176- 14	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-30C Layer # 1 Various panel	2008-06176- 15	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-31A Layer # 1 off-white ceiling tile	2008-06176- 16	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-31B Layer # 1 off-white ceiling tile	2008-06176- 17	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-31C Layer # 1 off-white ceiling tile	2008-06176- 18	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-34A Layer # 1 off-white ceiling tile	2008-06176- 19	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-34B Layer # 1 off-white ceiling tile	2008-06176- 20	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-34C Layer # 1 off-white ceiling tile	2008-06176- 21	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-35A Layer # 1 off-white ceiling tile	2008-06176- 22	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-35B Layer # 1 off-white ceiling tile	2008-06176- 23	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-35C Layer # 1 off-white ceiling tile	2008-06176- 24	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-52A Layer # 1 Various panel	2008-06176- 25	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-52B Layer # 1 Various panel	2008-06176- 26	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-52C Layer # 1 Various panel	2008-06176- 27	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample M-DST-06A Lab Number 2008-06176-1 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): bitumen, metal, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Silver	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-06B Lab Number 2008-06176-2 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): bitumen, metal, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Silver	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-06B Lab Number 2008-06176-3 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): bitumen, metal, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Silver	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200806176

Ben Furlong-Bldg T

Sample S-SAT-25A Lab Number 2008-06176- 4 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-25B Lab Number 2008-06176- 5 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-25C Lab Number 2008-06176- 6 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806176

Ben Furlong-Bldg T

Sample M-GWB-26A **Lab Number** 2008-06176- 7 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y										
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Note: sample size was too small - analysis may not be representative of whole.

Sample M-GWB-26B **Lab Number** 2008-06176- 8 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y										
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Note: sample size was too small - analysis may not be representative of whole.

Sample M-GWB-26C **Lab Number** 2008-06176- 9 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y										
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Note: sample size was too small - analysis may not be representative of whole.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample S-JTC-27A **Lab Number** 2008-06176- 10 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. Note: sample size was too small - analysis may not be representative of whole.

Sample S-JTC-27B **Lab Number** 2008-06176- 11 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. Note: sample size was too small - analysis may not be representative of whole.

Sample S-JTC-27C **Lab Number** 2008-06176- 12 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid. Note: sample size was too small - analysis may not be representative of whole.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample M-TWP-30A Lab Number 2008-06176- 13 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Various	3	40-50%	10-20%	-	-	-	-
Total %		100	Average %		40-50%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
i	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-30B Lab Number 2008-06176- 14 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Various	3	40-50%	10-20%	-	-	-	-
Total %		100	Average %		40-50%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
1	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-30C Lab Number 2008-06176- 15 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Various	3	40-50%	10-20%	-	-	-	-
Total %		100	Average %		40-50%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
1	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample M-APL-31A **Lab Number** 2008-06176- 16 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	>1-2%	-	-	-	-
Total %		100	Average %		30-40%	>1-2%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
i		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-31B **Lab Number** 2008-06176- 17 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	>1-2%	-	-	-	-
Total %		100	Average %		30-40%	>1-2%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
i		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-31C **Lab Number** 2008-06176- 18 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	>1-2%	-	-	-	-
Total %		100	Average %		30-40%	>1-2%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
i		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample M-APL-34A **Lab Number** 2008-06176- 19 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext			Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U							
2	glass fiber	CL	D	Y											
3															
4															
5															
6															

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-34B **Lab Number** 2008-06176- 20 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext			Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U							
2	glass fiber	CL	D	Y											
3															
4															
5															
6															

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-34C **Lab Number** 2008-06176- 21 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext			Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U							
2	glass fiber	CL	D	Y											
3															
4															
5															
6															

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample M-APL-35A **Lab Number** 2008-06176- 22 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-35B **Lab Number** 2008-06176- 23 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-35C **Lab Number** 2008-06176- 24 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By LSP 7/24/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	2-5%	-	-	-	-
Total %		100	Average %		20-30%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806176 Ben Furlong-Bldg T

Sample M-TWP-52A Lab Number 2008-06176- 25 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Various	3	40-50%	10-20%	-	-	-	-
Total %		100	Average %		40-50%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-52B Lab Number 2008-06176- 26 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Various	3	40-50%	10-20%	-	-	-	-
Total %		100	Average %		40-50%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.


Sample M-TWP-52C Lab Number 2008-06176- 27 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By LSP 7/24/2008 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Various	3	40-50%	10-20%	-	-	-	-
Total %		100	Average %		40-50%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; OI=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 24-Jul-2008

Original Print Date: 24-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806177

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 25 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116 PLM analysis for asbestos In bulk smp
Client Job: Ben Furlong-Bldg W PO Number: 08-202
Report Date: 7/23/2008 Date Analyzed: 7/23/2008 Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

PLM Analysis Summary:

Job Number: 200806177

Ben Furlong-Bldg W

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-APL-16A Layer # 1 Tan	2008-06177- 1	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-16B Layer # 1 Tan	2008-06177- 2	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-16C Layer # 1 Tan	2008-06177- 3	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27A Layer # 1 white	2008-06177- 4	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27B Layer # 1 white	2008-06177- 5	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27C Layer # 1 white	2008-06177- 6	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-28A Layer # 1 white	2008-06177- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-28B Layer # 1 white	2008-06177- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-28C Layer # 1 white	2008-06177- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-29A Layer # 1 white	2008-06177- 10	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-29B Layer # 1 white	2008-06177- 11	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-29C Layer # 1 white	2008-06177- 12	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-30A Layer # 1 Tan	2008-06177- 13	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-30B Layer # 1 Tan	2008-06177- 14	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-30C Layer # 1 Tan	2008-06177- 15	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-37A Layer # 1 Tan	2008-06177- 16	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-37B Layer # 1 Tan	2008-06177- 17	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-37C Layer # 1 Tan	2008-06177- 18	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-43A Layer # 1 Tan	2008-06177- 19	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-43B Layer # 1 Tan	2008-06177- 20	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-43C Layer # 1 Tan	2008-06177- 21	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27D Layer # 1 white	2008-06177- 22	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27E Layer # 1 white	2008-06177- 23	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27F Layer # 1 white	2008-06177- 24	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-27G Layer # 1 white	2008-06177- 25	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample M-APL-16A **Lab Number** 2008-06177- 1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	2-5%	-	-	-	-
Total %		100	Average %		50-60%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-16B **Lab Number** 2008-06177- 2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-16C **Lab Number** 2008-06177- 3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	2-5%	-	-	-	-
Total %		100	Average %		50-60%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample S-SAT-27A **Lab Number** 2008-06177- 4 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-27B **Lab Number** 2008-06177- 5 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-27C **Lab Number** 2008-06177- 6 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample M-GWB-28A **Lab Number** 2008-06177- 7 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-28B **Lab Number** 2008-06177- 8 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-28C **Lab Number** 2008-06177- 9 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample S-JTC-29A **Lab Number** 2008-06177- 10 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-29B **Lab Number** 2008-06177- 11 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-29C **Lab Number** 2008-06177- 12 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample M-APL-30A **Lab Number** 2008-06177- 13 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-30B **Lab Number** 2008-06177- 14 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	2-5%	-	-	-	-
Total %		100	Average %		50-60%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-30C **Lab Number** 2008-06177- 15 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample M-APL-37A **Lab Number** 2008-06177- 16 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	30-40%	-	-	-	-
Total %		100	Average %		30-40%	30-40%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37B **Lab Number** 2008-06177- 17 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	30-40%	-	-	-	-
Total %		100	Average %		30-40%	30-40%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37C **Lab Number** 2008-06177- 18 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	30-40%	-	-	-	-
Total %		100	Average %		30-40%	30-40%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample M-APL-43A **Lab Number** 2008-06177- 19 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	2-5%	-	-	-	-
Total %		100	Average %		50-60%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-43B **Lab Number** 2008-06177- 20 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-43C **Lab Number** 2008-06177- 21 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W

Sample S-SAT-27D **Lab Number** 2008-06177- 22 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-27E **Lab Number** 2008-06177- 23 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-27F **Lab Number** 2008-06177- 24 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806177 Ben Furlong-Bldg W


Sample S-SAT-27G **Lab Number** 2008-06177- 25 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow;
 vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 23-Jul-2008

Original Print Date: 23-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200806178

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 PLM Rec: 7/2/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Ben Furlong-Residence

PO Number: 08-202

Report Date: 7/23/2008

Date Analyzed: 7/23/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200806178

Ben Furlong-Residence

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	S-SAT-01A	2008-06178- 1	Sprayed Material	Positive Layer? No
Layer # 1	white		<i>no asbestos detected</i>	
Sample #	S-SAT-01B	2008-06178- 2	Sprayed Material	Positive Layer? No
Layer # 1	white		<i>no asbestos detected</i>	
Sample #	S-SAT-01C	2008-06178- 3	Sprayed Material	Positive Layer? No
Layer # 1	white		<i>no asbestos detected</i>	
Sample #	M-ACT-20A	2008-06178- 4	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-ACT-20B	2008-06178- 5	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-ACT-20C	2008-06178- 6	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200806178 Ben Furlong-Residence

Sample S-SAT-01A **Lab Number** 2008-06178- 1 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-01B **Lab Number** 2008-06178- 2 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-01C **Lab Number** 2008-06178- 3 **Sampled:** 7/1/2008 **Condition:** acceptable
Analyzed By MAC 7/23/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200806178 Ben Furlong-Residence

Sample M-ACT-20A Lab Number 2008-06178- 4 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By MAC 7/23/2008 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-ACT-20B Lab Number 2008-06178- 5 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By MAC 7/23/2008 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.


Sample M-ACT-20C Lab Number 2008-06178- 6 Sampled: 7/1/2008 Condition: acceptable
 Analyzed By MAC 7/23/2008 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow;
 vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 23-Jul-2008

Original Print Date: 23-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory

APPENDIX C

Building Inspectors' Signature Sheet

BUILDING INSPECTOR'S SIGNATURE SHEET

Report of Findings
Comprehensive AHERA Asbestos Inspection
Ben Furlong Education Center
Kyrene School District No. 28

FM Project 08-202

The individual(s) whose signature(s) is/are shown below is/are EPA Accredited Building Inspector(s) who participated in one or more of the following activities:

- A. Visual Inspection of Facilities
- B. Identification of Homogenous Areas of Asbestos-Containing Materials
- C. Development of Sampling Plan and Protocols
- D. Bulk Sampling Activities/Material Identifications
- E. Assessing ACBM/ACM
- F. Preparing Report of Findings


<u>INSPECTOR</u>	<u>ACTIVITIES</u>	<u>DATES</u>
Paul Anger Printed Name D 11441 Accreditation No. Signature	PA Initials EPA State	F 7/30/08
Michael Richter Printed Name D 10790 Accreditation No. Signature	MR Initials EPA State	A, B, D, E 6/23/08 – 6/30/08
Cliff Rolle Printed Name D 12516 Accreditation No. Signature	CR Initials EPA State	A, B, C, D, E, F 6/23/08 – 7/30/08
Dane Thompson Printed Name D 12313 Accreditation No. Signature	DT Initials EPA State	A, B, D, E 6/23/08 – 6/30/08

APPENDIX D

Personnel and Laboratory Accreditations

D 11441

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course


**AHERA Refresher
Building Inspector
January 4, 2008**

and successfully passed the competency exam

Date of Examination: **January 4, 2008**

Date of Expiration: **January 4, 2009**



 Director


 Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue
 Suite A
 Phoenix, AZ 85021-4962
 602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

AHJERA
Building Inspector

September 10-12, 2007

and successfully passed the competency exam.

Date of Examination: **September 12, 2007**

Date of Expiration: **September 12, 2008**

Director

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12516

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector**

May 30, 2008


and successfully passed the competency exam.

Date of Examination: **May 30, 2008**

Date of Expiration: **May 30, 2009**

Director

Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12313

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AIHERA Refresher
Building Inspector**

May 2, 2008

and successfully passed the competency exam.


Date of Examination: **May 2, 2008**

Date of Expiration: **May 2, 2009**

[Signature]
Director

Director

Approved Instructor



THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:1999

NVLAP LAB CODE: 101031-0

Fiberquant, Inc.
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in
NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS

2007-07-01 through 2008-06-30

Effective dates



Dolly S. Bruce
For the National Institute of Standards and Technology

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the 21 buildings comprising the Ben Furlong Education Center (BFEC) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of June 23, 2008 through June 30, 2008. A total of 151 bulk-material samples were collected from 450 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Four Hundred one building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos Containing Building Material

The identified ACBM within the 21 buildings at BFEC are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

1.3 Asbestos-Containing Building Materials

(Table "C" has been moved to Section 6 of the Management Plan.)

1.4 ACBM/Location Plans

(Drawings have been moved to Section 6 of the Management Plan.)

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the 21 buildings at BFEC during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the 21 buildings at BFEC during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the 21 buildings at BFEC, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the 21 buildings at the BFEC campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the 21 buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 24, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 8700 South Kyrene Road in Tempe, Arizona and consists of 21 buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the single building.

At the request of KSD, select identified suspect ACM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of June 23, 2008 through June 30, 2008, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

2.2 Description of Construction

2.2.1 Buildings A, B, C, D, E, F, G, I, T, W and Residence

The construction date of Buildings A, B, C, D, E, F, G, I, T, W and the Residence is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support concrete, wooden or metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete, vinyl composition tile and vinyl sheet flooring.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Buildings K, L and Storage H

The construction date of Buildings K, L and Storage H is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden or metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, vinyl composition tile and unfinished wood.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal and wood) or tackable wall panels. Original ceilings are wood or metal-framed and support suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.3 Buildings M, U, Storage J and O

The construction date of Buildings M, U, Storage J and O is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of wood or metal-framed construction, and support wooden or metal truss and deck systems finished with asphalt prepared roofing systems, paneling or spray-applied foam.

Floor finishes observed are unfinished concrete. Original walls are wood or metal-framed with metal and wood paneling and siding. There are no ceiling finishes or mechanical equipment for the buildings.

2.2.4 Building R

The construction date of Building R is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and support wooden or metal truss and deck systems finished with an asphalt prepared roofing system.

Floor finishes observed are unfinished concrete. Original walls are concrete masonry systems with stucco. There are no ceiling finishes associated with the building. Fire doors were observed to be associated with exterior entrances into the building.

Mechanical equipment for the building consists of roof-mounted mechanical units. The ductwork distribution systems are routed directly into the individual rooms.

2.2.5 Canopy

The construction date of the Canopy is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a on-grade asphalt foundation. Perimeter load bearing walls are of concrete masonry systems and support a wooden deck system finished with metal panels.

Floor finishes observed are asphalt. Original walls are concrete masonry systems and wood or metal-framed with metal siding. There are no ceiling finishes or mechanical equipment for the building.

2.2.6 Storage P

The construction date of Storage P is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a on-grade asphalt foundation. Perimeter load bearing walls are of concrete masonry systems and support a wooden deck system finished with a coating.

Floor finishes observed are asphalt. Original walls are concrete masonry systems and wood or metal-framed systems with metal and wood paneling and siding. There are no ceiling finishes or mechanical equipment for the building.

2.3 AHERA Inspection Procedures and Protocols

2.3.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;

- ◇ date accomplished and,
- ◇ identification and qualification of individuals conducting each activity.

2.3.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step by step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.4 Visual Inspection

A visual inspection of the 21 buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

2.5 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, TWENTY-ONE friable suspect ACBM (acoustical ceiling panels, duct seam tape and spray-applied texture (popcorn)) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.6 Sample Collection

Convenience sampling was performed on select identified suspect ACBM, except for the spray-applied texture (popcorn), which was random sampled. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
A	55 (45 Assumed)	30
B	44 (38 Assumed)	18
C	25 (23 Assumed)	6
D	33 (28 Assumed)	15
E	29 (25 Assumed)	12
F	17 (17 Assumed)	0
G	15 (15 Assumed)	0
I	16 (16 Assumed)	0
K	28 (26 Assumed)	6
L	17 (15 Assumed)	6
M	2 (2 Assumed)	0
R	11 (11 Assumed)	0
T	56 (47 Assumed)	27
U	3 (3 Assumed)	0
W	57 (50 Assumed)	25
Canopy	3 (3 Assumed)	0
Residence	26 (24 Assumed)	6
Storage H	2 (2 Assumed)	0
Storage J	3 (3 Assumed)	0
Storage O	3 (3 Assumed)	0
Storage P	5 (5 Assumed)	0
TOTAL	450	151

2.7 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

END OF REPORT

SECTION 3

DESIGNATED PERSON IDENTIFICATION

AHERA Designated Person
796.93(e)(4)

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: BEN FURLONG EDUCATION CENTER

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284

LEA Designated Person

Print Name: Giacomo Musella, Facilities Supervisor

Address: 8700 South Kyrene Road
Tempe, Arizona 85284-2197

Phone: 480.783-4200

Training Course Name: AHERA Building Inspector Refresher

Dates of Training: October 5, 2008 **Hours of Training:** 4

Training Course Name: AHERA Management Planner Refresher

Dates of Training: October 5, 2008 **Hours of Training:** 4

Training Course Name: _____

Dates of Training: _____ **Hours of Training:** _____

Signature

Date

D 10910

THE ASBESTOS INSTITUTE


Certifies that

Giacomo Jack Musella

has attended the EPA approved course

AHERA Refresher
Building Inspector
October 5, 2007

and successfully passed the competency exam.



Date of Examination: October 5, 2007

Date of Expiration: October 5, 2008

Director

Approved Instructor

THE ASBESTOS INSTITUTE
8102 North 23rd Avenue
Suite A
Phoenix, AZ 85021-4962
602-864-6564

This training meets all requirements for asbestos accreditation under TSCA Title II.

D 10936

THE ASBESTOS INSTITUTE

Certifies that
Giacomo Jack Musella

has attended the EPA approved course
**AHERA Refresher
Management Planner
October 5, 2007**
and successfully passed the competency exam.

COPY

Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE
8102 North 23rd Avenue
Suite A
Phoenix, AZ 85021-4962
602-864-6564

This training meets all requirements for asbestos accreditation under TSCA Title II.

SECTION 4

RESPONSE ACTION(S)

THERE ARE NO RESPONSE ACTIONS REQUIRED AT THIS FACILITY.

SECTION 5

ACCREDITATION STATEMENTS

**Assurance of Accreditation
Under this Management Plan
763.93(e)(7)**

Inspector(s):

Name: MICHAEL RICHTER
State of Accreditation or EPA: EPA
Accreditation Date(s): SEPTEMBER 12, 2008
Accreditation Number(s): D 10790

Name: CLIFF ROLLE
State of Accreditation or EPA: EPA
Accreditation Date(s): MAY 30, 2009
Accreditation Number(s): D 12516

Name: DANE THOMPSON
State of Accreditation or EPA: EPA
Accreditation Date(s): MAY 2, 2009
Accreditation Number(s): D 12313


Management Planner:

Name: PAUL ANGER
State of Accreditation or EPA: EPA
Accreditation Date(s): JANUARY 4, 2008
Accreditation Number(s): D 11466

Any Project Designer, Contractor/Supervisor or Worker who performs work on response actions under this Management Plan shall be accredited by either an EPA approved state contractor accreditation plan or an EPA approved course under Section 206(b) to Title II of the Toxic Substance Control Act.

D 10790

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

and successfully passed the competency exam

Michael Allen Richter
 Director

Director

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12516

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector**

May 30, 2008


and successfully passed the competency exam

Date of Examination: **May 30, 2008**

Date of Expiration: **May 30, 2009**

Director

Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12313

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course:

**AHERA Refresher
Building Inspector
May 2, 2008**


and successfully passed the competency exam.

Date of Examination: **May 2, 2008**

Date of Expiration: **May 2, 2009**

[Signature]
 Director

[Signature]
 Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 11466

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

ASBESTOS Management Refresher
January 4, 2008.

and successfully passed the competency exam.

Date of Examination: January 4, 2008

Date of Expiration: January 4, 2009

Paul Anger
Director

[Signature]
Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564