

# **ASBESTOS MANAGEMENT PLAN**



**at**

**Kyrene Aprende Middle School**

**Prepared for:**

**Kyrene School District No. 28**

**VOLUME I OF II**

**FM GROUP INC  
FM Project 08-166**

**June 2008**

# **ASBESTOS MANAGEMENT PLAN**

**Kyrene Aprende Middle School**

**June 2008**

**FM GROUP INC**

**FM Project 08-166**

## TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY .....	1-1
2	INSPECTION REPORT.....	2-1
3	DESIGNATED PERSON IDENTIFICATION.....	3-1
4	RESPONSE ACTION.....	4-1
5	ACCREDITATION STATEMENTS .....	5-1
6	REMAINING ACBM.....	6-1
7	O&M PROGRAM.....	7-1
8	INITIAL NOTIFICATIONS.....	8-1
9	COST ESTIMATION .....	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON .....	10-1
11	ANNUAL NOTIFICATIONS .....	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT .....	12-1

### APPENDIX A: ONGOING RECORDKEEPING

**SECTION 1**

**GENERAL INVENTORY**

---

**General Inventory**  
**763.93(e)(1)**

**Date:** JUNE 19, 2008

**Owner:** KYRENE SCHOOL DISTRICT NO. 28

**Address:** 8700 SOUTH KYRENE ROAD  
TEMPE, ARIZONA 85284-2197

**Property:** KYRENE APRENDE MIDDLE SCHOOL

**Address:** 777 NORTH DESERT BREEZE BOULEVARD EAST #2  
CHANDLER, ARIZONA 85226

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
MAIN	N/A	X	X
MEDIA CENTER	N/A	X	X
MULTI-PURPOSE	N/A	X	X

## **SECTION 2**

### **INSPECTION REPORT**

---

## **INSPECTION REPORT**

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:


Report of Findings  
Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School

Prepared by: FM GROUP INC  
Project No.: 08-166  
Date: June 2008

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28  
8700 South Kyrene Road  
Tempe, Arizona 85284-2197

**REPORT OF FINDINGS**  
*(Abridged Version)*



**Comprehensive AHERA Asbestos Inspection**

**at**

**Kyrene Aprende Middle School**

**Prepared for:**

**Kyrene School District No. 28**

**FM GROUP INC**  
**FM Project 08-166**

**June 2008**



TABLE OF CONTENTS

**Report of Findings**  
Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School  
Kyrene School District No. 28

FM GROUP Project 08-166

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u> .....	1
1.1 Summary .....	1
1.2 Identified Asbestos-Containing Materials .....	1
1.3 Asbestos-Containing Building Materials (Table C) .....	2
1.4 ACBM/Location Plans .....	3
1.5 Critical Situations .....	4
1.6 Friable Asbestos-Containing Building Materials .....	4
1.7 Material Assessments .....	4
1.8 Recommendations .....	4
1.9 Qualifications of the Report.....	4
2.0 <u>PROJECT INFORMATION</u> .....	5
2.1 Background.....	5
2.2 Description of Construction .....	5
2.2.1 Main, Media Center and Multi-Purpose Buildings .....	5
2.3 Building Materials/Systems List (Table A) .....	7
2.3.1 Main Building.....	8
2.3.2 Media Center Building .....	81
2.3.3 Multi-Purpose Building.....	101
2.4 AHERA Inspection Procedures and Protocols.....	126
2.4.1 Inspection Procedures and Protocols .....	126
2.4.2 FM GROUP INC Inspection SOP .....	126
2.5 Visual Inspection.....	126
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B) .	127
2.6.1 Main Building.....	128
2.6.2 Media Center Building .....	131
2.6.3 Multi-Purpose Building.....	133
2.7 Physical Assessments .....	136
2.8 Sample Collection .....	136
2.9 Material Bulk Sample Analysis .....	136

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none"><li>• Chain-of-Custodies</li><li>• Laboratory Analysis</li></ul>
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

## **1.0 SURVEY RESULTS AND RECOMMENDATIONS**

### **1.1 Summary**

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the three buildings comprising the Kyrene Aprende Middle School (KAMS) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of May 19, 2008 through May 21, 2008. A total of 150 bulk-material samples were collected from 172 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

One Hundred Twenty-two building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

### **1.2 Identified Asbestos-Containing Building Materials**

The identified ACBM within the three buildings at KAMS are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

**Asbestos Material-Bulk Samples Collected**

<b><i>Building</i></b>	<b><i>No. of Samples</i></b>	<b><i>No. HA</i></b>	<b><i>No. Assumed</i></b>	<b><i>Total No. ACM</i></b>
Main	45	57	42	42
Media Center	45	44	29	29
Multi-Purpose	60	71	51	51

**1.3 Asbestos-Containing Building Materials**

**TABLE C  
ASBESTOS CONTAINING BUILDING MATERIALS**

**MAIN BUILDING  
MEDIA CENTER BUILDING  
MULTI-PURPOSE BUILDING**

**TABLE C HAS BEEN MOVED TO  
SECTION 6 OF ASBESTOS MANAGEMENT PLAN**

**1.4 ACBM/Location Plans**

**MAIN BUILDING  
MEDIA CENTER BUILDING  
MULTI-PURPOSE BUILDING**

***ACBM/LOCATION PLANS HAVE BEEN MOVED TO  
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

## **1.5 Critical Situations**

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the three buildings at KAMS during this inspection.**

## **1.6 Friable Asbestos-Containing Building Materials**

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Miscellaneous or Surfacing Building Materials, or Asbestos-Containing Thermal System Insulation in the three buildings at KAMS during this inspection.**

## **1.7 Material Assessments**

Due to the fact that **NO friable Asbestos-Containing Miscellaneous or Surfacing Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the three buildings at KAMS, **NO** formal assessments are included in this report.

## **1.8 Recommendations**

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

## **1.9 Qualifications of Report**

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

## **2.0 PROJECT INFORMATION**

### **2.1 Background**

KSD intends to determine if there are any ACBM associated with the three buildings at the KAMS campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the three buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 24, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 777 North Desert Breeze Boulevard East #2 in Chandler, Arizona and consists of three buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the three buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of May 19, 2008 through May 21, 2008, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

*Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.*

### **2.2 Description of Construction**

#### **2.2.1 Main, Media Center and Multi-Purpose Buildings**

The construction date of the Main, Media Center and Multi-Purpose Buildings is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support a wood, metal or concrete deck system finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, fiberglass reinforced panel, glazed wall tile or stucco. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

*A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.*

**2.3 Building Materials/Systems List**

**TABLE A**  
**BUILDING MATERIAL SYSTEMS**

**MAIN BUILDING**  
**MEDIA CENTER BUILDING**  
**MULTI-PURPOSE BUILDING**



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP, SILVER	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, GUMMY	ROOF	O	*	S
SEALANT (FLASHINGS), TAN, PLIABLE	ROOF	O	*	S
SEALANT (WINDOWS), WHITE, BRITTLE	ROOF	O	*	S
CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (FLASHINGS), TAN, PLIABLE	ROOF	O	*	S
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	SECRETARY/RECEPTION	F	*	S
	OFFICE 1	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	OFFICE 4	F	*	
	STUDENT SERVICES	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	ELECTRICAL 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	OFFICE 5	F	*	
	OFFICE 6	F	*	
	CONFERENCE ROOM	F	*	
	OFFICE 7	F	*	
	OFFICE 8	F	*	
	STAFF MEN'S RESTROOM	F	*	
	BREAK	F	*	
	NURSE RESTROOM	F	*	
	TEST	F	*	
	COTS	F	*	
	COTS CLOSET	F	*	
	TREATMENT	F	*	
	PRINCIPAL	F	*	
	WAIT	F	*	
	NURSE'S OFFICE	F	*	
	CLASSROOM 100	F	*	
	CLASSROOM 101	F	*	
	CLASSROOM 102	F	*	
	CLASSROOM 103	F	*	
	CLASSROOM 104	F	*	
	CLASSROOM 105	F	*	
	CLASSROOM 106	F	*	
	SCIENCE CLASSROOM 107	F	*	
	STORAGE 09	F	*	
	STAFF LOUNGE 04	F	*	
	SCIENCE CLASSROOM 108	F	*	
	CLASSROOM 109	F	*	
	CLASSROOM 110	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 111	F	*	
	BOY'S RESTROOM 5	F	*	
	STORAGE 07	F	*	
	STORAGE 08	F	*	
	LOBBY 04	F	*	
	CLASSROOM 112	F	*	
	CLASSROOM 113	F	*	
	CLASSROOM 114	F	*	
	CLASSROOM 115	F	*	
	LOBBY 05	F	*	
	COMPUTER CLASSROOM 116	F	*	
	SPECIAL ED 117	F	*	
	SPECIAL ED 118	F	*	
	STAFF WOMEN'S RESTROOM 4	F	*	
	JANITOR 3	F	*	
	GIRL'S RESTROOM 7	F	*	
	BOY'S RESTROOM 7	F	*	
	STAFF MEN'S RESTROOM 4	F	*	
	ELECTRICAL 3	F	*	
	GIRL'S RESTROOM 6	F	*	
	BOY'S RESTROOM 6	F	*	
	CLASSROOM 200	F	*	
	CLASSROOM 201	F	*	
	CLASSROOM 202	F	*	
	CLASSROOM 203	F	*	
	GIRL'S RESTROOM 5	F	*	
	CLASSROOM 204	F	*	
	CLASSROOM 205	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 206	F	*	
	SCIENCE CLASSROOM 207	F	*	
	STORAGE 06	F	*	
	STAFF LOUNGE 03	F	*	
	STORAGE 05	F	*	
	SCIENCE CLASSROOM 208	F	*	
	CLASSROOM 209	F	*	
	CLASSROOM 210	F	*	
	CLASSROOM 211	F	*	
	STORAGE 04	F	*	
	STAFF WOMEN'S RESTROOM 2	F	*	
	STAFF LOUNGE 02	F	*	
	STAFF MEN'S RESTROOM 2	F	*	
	STORAGE 03	F	*	
	STORAGE 02	F	*	
	LOBBY 02	F	*	
	CLASSROOM 212	F	*	
	CLASSROOM 213	F	*	
	CLASSROOM 214	F	*	
	CLASSROOM 215	F	*	
	LOBBY 03	F	*	
	COMPUTER CLASSROOM 216	F	*	
	SPECIAL ED 217	F	*	
	SPECIAL ED 218	F	*	
	STAFF MEN'S RESTROOM 3	F	*	
	JANITOR 2	F	*	
	GIRL'S RESTROOM 4	F	*	
	BOY'S RESTROOM 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STAFF WOMEN'S RESTROOM 3	F	*	
	ELECTRICAL 2	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	
	CLASSROOM 300	F	*	
	CLASSROOM 301	F	*	
	CLASSROOM 302	F	*	
	CLASSROOM 303	F	*	
	CLASSROOM 304	F	*	
	CLASSROOM 305	F	*	
	CLASSROOM 306	F	*	
	SCIENCE CLASSROOM 307	F	*	
	STORAGE 01	F	*	
	STAFF LOUNGE 01	F	*	
	SCIENCE CLASSROOM 308	F	*	
	CLASSROOM 309	F	*	
	CLASSROOM 310	F	*	
	CLASSROOM 311	F	*	
	CLASSROOM 312	F	*	
	CLASSROOM 313	F	*	
	CLASSROOM 314	F	*	
	CLASSROOM 315	F	*	
	LOBBY 01	F	*	
	COMPUTER CLASSROOM 316	F	*	
	SPECIAL ED 317	F	*	
	SPECIAL ED 318	F	*	
	STAFF WOMEN'S RESTROOM 1	F	*	
	JANITOR 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 1	F	*	
	ELECTRICAL 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
	CORRIDOR 03	F	*	
	CORRIDOR 04	F	*	
	CORRIDOR 05	F	*	
	CORRIDOR 06	F	*	
	CORRIDOR 07	F	*	
	CORRIDOR 08	F	*	
	CORRIDOR 09	F	*	
	CORRIDOR 10	F	*	
	CORRIDOR 11	F	*	
	CORRIDOR 12	F	*	
	CORRIDOR 13	F	*	
	CORRIDOR 14	F	*	
	CORRIDOR 15	F	*	
	CORRIDOR 16	F	*	
	CORRIDOR 17	F	*	
	CORRIDOR 18	F	*	
	CORRIDOR 19	F	*	
	CORRIDOR 20	F	*	
	EXTERIOR	F	*	
CONCRETE (COLUMNS), GRAY, CEMENTITIOUS	EXTERIOR	O	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	SECRETARY/RECEPTION	O	N, E, W, S	S
	OFFICE 1	O	W, S	
	OFFICE 2	O	E, W	
	OFFICE 3	O	S	
	OFFICE 4	O	W, S	
	STUDENT SERVICES	O	N, E, S	
	STAFF WOMEN'S RESTROOM	O	E, W	
	ELECTRICAL 4	O	W	
	OFFICE 5	O	E	
	OFFICE 6	O	S	
	CONFERENCE ROOM	O	N, W	
	OFFICE 7	O	N	
	OFFICE 8	O	N	
	STAFF MEN'S RESTROOM	O	N	
	BREAK	O	W	
	NURSE RESTROOM	O	E, W	
	TEST	O	S	
	COTS	O	N, E, W	
	COTS CLOSET	O	E	
	TREATMENT	O	E	
	PRINCIPAL	O	W, S	
	WAIT	O	N, E, W, S	
	NURSE'S OFFICE	O	E, W, S	
	CLASSROOM 100	O	N, W, S	
	CLASSROOM 101	O	N, W, S	
	CLASSROOM 102	O	N, W, S	
	CLASSROOM 103	O	N, W, S	
	CLASSROOM 104	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 105	O	N, E	
	CLASSROOM 106	O	E, W	
	SCIENCE CLASSROOM 107	O	E	
	STORAGE 09	O	N	
	STAFF LOUNGE 04	O	E, W, S	
	SCIENCE CLASSROOM 108	O	N, W	
	CLASSROOM 109	O	N, E	
	CLASSROOM 110	O	E, W	
	CLASSROOM 111	O	N, E	
	BOY'S RESTROOM 5	O	W	
	STORAGE 07	O	N, E, W	
	STORAGE 08	O	E	
	CLASSROOM 112	O	E, S	
	CLASSROOM 113	O	E, W, S	
	CLASSROOM 114	O	E, W, S	
	CLASSROOM 115	O	W, S	
	COMPUTER CLASSROOM 116	O	S	
	SPECIAL ED 117	O	S	
	SPECIAL ED 118	O	S	
	STAFF WOMEN'S RESTROOM 4	O	S	
	JANITOR 3	O	S	
	GIRL'S RESTROOM 7	O	N	
	BOY'S RESTROOM 7	O	S	
	STAFF MEN'S RESTROOM 4	O	S	
	ELECTRICAL 3	O	S	
	GIRL'S RESTROOM 6	O	N	
	BOY'S RESTROOM 6	O	S	
	CLASSROOM 200	O	N, W	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM 201	O	N, E, W	
	CLASSROOM 202	O	N, E, W	
	CLASSROOM 203	O	N, E	
	GIRL'S RESTROOM 5	O	S	
	CLASSROOM 204	O	N, E, S	
	CLASSROOM 205	O	E, S	
	CLASSROOM 206	O	N, E	
	SCIENCE CLASSROOM 207	O	E, S	
	STORAGE 06	O	E	
	STAFF LOUNGE 03	O	E, W	
	STORAGE 05	O	W	
	SCIENCE CLASSROOM 208	O	N, E	
	CLASSROOM 209	O	E, S	
	CLASSROOM 210	O	E	
	STORAGE 04	O	W	
	STAFF WOMEN'S RESTROOM 2	O	W	
	STAFF LOUNGE 02	O	N	
	STAFF MEN'S RESTROOM 2	O	E	
	STORAGE 03	O	N	
	STORAGE 02	O	N	
	CLASSROOM 211	O	E	
	CLASSROOM 212	O	W, S	
	CLASSROOM 213	O	N, W, S	
	CLASSROOM 214	O	N, W, S	
	CLASSROOM 215	O	N, W	
	COMPUTER CLASSROOM 216	O	W	
	SPECIAL ED 217	O	W	
	SPECIAL ED 218	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STAFF MEN'S RESTROOM 3	O	W	
	JANITOR 2	O	W	
	GIRL'S RESTROOM 4	O	E	
	BOY'S RESTROOM 4	O	W	
	STAFF WOMEN'S RESTROOM 3	O	W	
	ELECTRICAL 2	O	W	
	GIRL'S RESTROOM 3	O	E	
	BOY'S RESTROOM 3	O	W	
	CLASSROOM 300	O	N, E	
	CLASSROOM 301	O	N, E, S	
	CLASSROOM 302	O	N, E, S	
	CLASSROOM 303	O	E, S	
	CLASSROOM 304	O	S	
	CLASSROOM 305	O	S	
	CLASSROOM 306	O	E, S	
	SCIENCE CLASSROOM 307	O	W, S	
	STORAGE 01	O	S	
	STAFF LOUNGE 01	O	N, S	
	SCIENCE CLASSROOM 308	O	E, S	
	CLASSROOM 309	O	W, S	
	CLASSROOM 310	O	W, S	
	CLASSROOM 311	O	N	
	CLASSROOM 312	O	N, W	
	CLASSROOM 313	O	N, E, W	
	CLASSROOM 314	O	N, E, W	
	CLASSROOM 315	O	N, E	
	COMPUTER CLASSROOM 316	O	N	
	SPECIAL ED 317	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	SPECIAL ED 318	O	N	
	STAFF WOMEN'S RESTROOM 1	O	N	
	JANITOR 1	O	N	
	GIRL'S RESTROOM 2	O	S	
	BOY'S RESTROOM 2	O	N	
	STAFF MEN'S RESTROOM 1	O	N	
	ELECTRICAL 1	O	N	
	GIRL'S RESTROOM 1	O	S	
	BOY'S RESTROOM 1	O	N	
	CORRIDOR 03	O	W, S	
	CORRIDOR 05	O	N	
	CORRIDOR 17	O	N, E	
	CORRIDOR 18	O	E	
	CORRIDOR 19	O	S	
	CORRIDOR 20	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
GLASS BLOCK, 8"X8", CLEAR	SECRETARY/RECEPTION	O	E, S	N
	LOBBY 02	O	W	
	CORRIDOR 03	O	S	
	CORRIDOR 06	O	N	
	CORRIDOR 17	O	E	
	EXTERIOR	O	N, E, W, S	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	SECRETARY/RECEPTION	O	E, S	S
	LOBBY 02	O	W	
	CORRIDOR 03	O	S	
	CORRIDOR 06	O	N	
	CORRIDOR 17	O	E	
	EXTERIOR	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FIXTURES, WHITE	SECRETARY/RECEPTION	C	*	S
	OFFICE 1	C	*	
	OFFICE 2	C	*	
	OFFICE 3	C	*	
	OFFICE 4	C	*	
	STUDENT SERVICES	C	*	
	ELECTRICAL 4	C	*	
	OFFICE 5	C	*	
	OFFICE 6	C	*	
	CONFERENCE ROOM	C	*	
	OFFICE 7	C	*	
	OFFICE 8	C	*	
	BREAK	C	*	
	TEST	C	*	
	COTS	C	*	
	TREATMENT	C	*	
	PRINCIPAL	C	*	
	WAIT	C	*	
	CLASSROOM 100	C	*	
	CLASSROOM 101	C	*	
	CLASSROOM 102	C	*	
	CLASSROOM 103	C	*	
	CLASSROOM 104	C	*	
	CLASSROOM 105	C	*	
	CLASSROOM 106	C	*	
	SCIENCE CLASSROOM 107	C	*	
	STORAGE 09	C	*	
	STAFF LOUNGE 04	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	SCIENCE CLASSROOM 108	C	*	
	CLASSROOM 109	C	*	
	CLASSROOM 110	C	*	
	CLASSROOM 111	C	*	
	STORAGE 07	C	*	
	STORAGE 08	C	*	
	LOBBY 04	C	*	
	CLASSROOM 112	C	*	
	CLASSROOM 113	C	*	
	CLASSROOM 114	C	*	
	CLASSROOM 115	C	*	
	LOBBY 05	C	*	
	COMPUTER CLASSROOM 116	C	*	
	SPECIAL ED 117	C	*	
	SPECIAL ED 118	C	*	
	CLASSROOM 200	C	*	
	CLASSROOM 201	C	*	
	CLASSROOM 202	C	*	
	CLASSROOM 203	C	*	
	CLASSROOM 204	C	*	
	CLASSROOM 205	C	*	
	CLASSROOM 206	C	*	
	SCIENCE CLASSROOM 207	C	*	
	STORAGE 06	C	*	
	STAFF LOUNGE 03	C	*	
	STORAGE 05	C	*	
	SCIENCE CLASSROOM 208	C	*	
	CLASSROOM 209	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 210	C	*	
	STAFF LOUNGE 02	C	*	
	LOBBY 02	C	*	
	CLASSROOM 211	C	*	
	CLASSROOM 212	C	*	
	CLASSROOM 213	C	*	
	CLASSROOM 214	C	*	
	CLASSROOM 215	C	*	
	LOBBY 03	C	*	
	COMPUTER CLASSROOM 216	C	*	
	SPECIAL ED 217	C	*	
	SPECIAL ED 218	C	*	
	CLASSROOM 300	C	*	
	CLASSROOM 301	C	*	
	CLASSROOM 302	C	*	
	CLASSROOM 303	C	*	
	CLASSROOM 304	C	*	
	CLASSROOM 305	C	*	
	CLASSROOM 306	C	*	
	SCIENCE CLASSROOM 307	C	*	
	STORAGE 01	C	*	
	STAFF LOUNGE 01	C	*	
	SCIENCE CLASSROOM 308	C	*	
	CLASSROOM 309	C	*	
	CLASSROOM 310	C	*	
	CLASSROOM 311	C	*	
	CLASSROOM 312	C	*	
	CLASSROOM 313	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 314	C	*	
	CLASSROOM 315	C	*	
	LOBBY 01	C	*	
	COMPUTER CLASSROOM 316	C	*	
	SPECIAL ED 317	C	*	
	SPECIAL ED 318	C	*	
	CORRIDOR 01	C	*	
	CORRIDOR 02	C	*	
	CORRIDOR 03	C	*	
	CORRIDOR 04	C	*	
	CORRIDOR 05	C	*	
	CORRIDOR 06	C	*	
	CORRIDOR 07	C	*	
	CORRIDOR 08	C	*	
	CORRIDOR 09	C	*	
	CORRIDOR 10	C	*	
	CORRIDOR 11	C	*	
	CORRIDOR 12	C	*	
	CORRIDOR 13	C	*	
	CORRIDOR 14	C	*	
	CORRIDOR 15	C	*	
	CORRIDOR 16	C	*	
	CORRIDOR 17	C	*	
	CORRIDOR 18	C	*	
	CORRIDOR 19	C	*	
	CORRIDOR 20	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	SECRETARY/RECEPTION	C, W	N, E, W, S	S
	OFFICE 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	OFFICE 2	W	N, E, W, S	
	OFFICE 3	W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	STUDENT SERVICES	W	N, E, W, S	
	OFFICE 5	W	N, E, W, S	
	OFFICE 6	W	N, E, W, S	
	CONFERENCE ROOM	W	N, E, W, S	
	OFFICE 7	W	N, E, W, S	
	OFFICE 8	W	N, E, W, S	
	BREAK	W	N, E, W, S	
	TEST	W	N, E, W, S	
	COTS	W	N, E, W, S	
	COTS CLOSET	C	*	
	TREATMENT	W	N, E, W, S	
	PRINCIPAL	W	N, E, W, S	
	WAIT	W	N, E, W, S	
	NURSE'S OFFICE	W	N, E, W, S	
	CLASSROOM 100	C, W	N, E, W, S	
	CLASSROOM 101	C, W	N, E, W, S	
	CLASSROOM 102	C, W	N, E, W, S	
	CLASSROOM 103	C, W	N, E, W, S	
	CLASSROOM 104	C, W	N, E, W, S	
	CLASSROOM 105	C, W	N, E, W, S	
	CLASSROOM 106	C, W	N, E, W, S	
	SCIENCE CLASSROOM 107	W	N, E, W, S	
	STORAGE 09	W	N, E, W, S	
	STAFF LOUNGE 04	C, W	N, E, W, S	
	SCIENCE CLASSROOM 108	W	N, E, W, S	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CLASSROOM 109	C, W	N, E, W, S	
	CLASSROOM 110	W	N, E, W, S	
	CLASSROOM 111	W	N, E, W, S	
	STORAGE 07	W	N, E, W, S	
	STORAGE 08	W	N, E, W, S	
	CLASSROOM 112	C, W	N, E, W, S	
	CLASSROOM 113	C, W	N, E, W, S	
	CLASSROOM 114	C, W	N, E, W, S	
	CLASSROOM 115	C, W	N, E, W, S	
	COMPUTER CLASSROOM 116	W	N, E, W, S	
	SPECIAL ED 117	C, W	N, E, W, S	
	SPECIAL ED 118	C, W	N, E, W, S	
	CLASSROOM 200	C, W	N, E, W, S	
	CLASSROOM 201	C, W	N, E, W, S	
	CLASSROOM 202	C, W	N, E, W, S	
	CLASSROOM 203	C, W	N, E, W, S	
	CLASSROOM 204	W	N, E, W, S	
	CLASSROOM 205	W	N, E, W, S	
	CLASSROOM 206	C, W	N, E, W, S	
	SCIENCE CLASSROOM 207	W	N, E, W, S	
	STORAGE 06	W	N, E, W, S	
	STAFF LOUNGE 03	C, W	N, E, W, S	
	STORAGE 05	W	N, E, W, S	
	SCIENCE CLASSROOM 208	W	N, E, W, S	
	CLASSROOM 209	C, W	N, E, W, S	
	CLASSROOM 210	W	N, E, W, S	
	STORAGE 02	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF LOUNGE 02	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	CLASSROOM 211	W	N, E, W, S	
	CLASSROOM 212	C, W	N, E, W, S	
	CLASSROOM 213	C, W	N, E, W, S	
	CLASSROOM 214	C, W	N, E, W, S	
	CLASSROOM 215	C, W	N, E, W, S	
	COMPUTER CLASSROOM 216	W	N, E, W, S	
	SPECIAL ED 217	C, W	N, E, W, S	
	SPECIAL ED 218	C, W	N, E, W, S	
	CLASSROOM 300	C, W	N, E, W, S	
	CLASSROOM 301	C, W	N, E, W, S	
	CLASSROOM 302	C, W	N, E, W, S	
	CLASSROOM 303	C, W	N, E, W, S	
	CLASSROOM 304	W	N, E, W, S	
	CLASSROOM 305	W	N, E, W, S	
	CLASSROOM 306	C, W	N, E, W, S	
	SCIENCE CLASSROOM 307	W	N, E, W, S	
	STORAGE 01	W	N, E, W, S	
	STAFF LOUNGE 01	C, W	N, E, W, S	
	SCIENCE CLASSROOM 308	W	N, E, W, S	
	CLASSROOM 309	C, W	N, E, W, S	
	CLASSROOM 310	C, W	N, E, W, S	
	CLASSROOM 311	C, W	N, E, W, S	
	CLASSROOM 312	C, W	N, E, W, S	
	CLASSROOM 313	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 314	C, W	N, E, W, S	
	CLASSROOM 315	C, W	N, E, W, S	
	COMPUTER CLASSROOM 316	W	N, E, W, S	
	SPECIAL ED 317	C, W	N, E, W, S	
	SPECIAL ED 318	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	SECRETARY/RECEPTION	C, W	N, E, W, S	S
	OFFICE 1	W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	OFFICE 3	W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	STUDENT SERVICES	W	N, E, W, S	
	OFFICE 5	W	N, E, W, S	
	OFFICE 6	W	N, E, W, S	
	CONFERENCE ROOM	W	N, E, W, S	
	OFFICE 7	W	N, E, W, S	
	OFFICE 8	W	N, E, W, S	
	BREAK	W	N, E, W, S	
	TEST	W	N, E, W, S	
	COTS	W	N, E, W, S	
	COTS CLOSET	C	*	
	TREATMENT	W	N, E, W, S	
	PRINCIPAL	W	N, E, W, S	
	WAIT	W	N, E, W, S	
	NURSE'S OFFICE	W	N, E, W, S	
	CLASSROOM 100	C, W	N, E, W, S	
	CLASSROOM 101	C, W	N, E, W, S	
	CLASSROOM 102	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CLASSROOM 103	C, W	N, E, W, S	
	CLASSROOM 104	C, W	N, E, W, S	
	CLASSROOM 105	C, W	N, E, W, S	
	CLASSROOM 106	C, W	N, E, W, S	
	SCIENCE CLASSROOM 107	W	N, E, W, S	
	STORAGE 09	W	N, E, W, S	
	STAFF LOUNGE 04	C, W	N, E, W, S	
	SCIENCE CLASSROOM 108	W	N, E, W, S	
	CLASSROOM 109	C, W	N, E, W, S	
	CLASSROOM 110	W	N, E, W, S	
	CLASSROOM 111	W	N, E, W, S	
	STORAGE 07	W	N, E, W, S	
	STORAGE 08	W	N, E, W, S	
	CLASSROOM 112	C, W	N, E, W, S	
	CLASSROOM 113	C, W	N, E, W, S	
	CLASSROOM 114	C, W	N, E, W, S	
	CLASSROOM 115	C, W	N, E, W, S	
	COMPUTER CLASSROOM 116	W	N, E, W, S	
	SPECIAL ED 117	C, W	N, E, W, S	
	SPECIAL ED 118	C, W	N, E, W, S	
	CLASSROOM 200	C, W	N, E, W, S	
	CLASSROOM 201	C, W	N, E, W, S	
	CLASSROOM 202	C, W	N, E, W, S	
	CLASSROOM 203	C, W	N, E, W, S	
	CLASSROOM 204	W	N, E, W, S	
	CLASSROOM 205	W	N, E, W, S	
	CLASSROOM 206	C, W	N, E, W, S	
	SCIENCE CLASSROOM 207	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STORAGE 06	W	N, E, W, S	
	STAFF LOUNGE 03	C, W	N, E, W, S	
	STORAGE 05	W	N, E, W, S	
	SCIENCE CLASSROOM 208	W	N, E, W, S	
	CLASSROOM 209	C, W	N, E, W, S	
	CLASSROOM 210	W	N, E, W, S	
	STORAGE 02	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF LOUNGE 02	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	CLASSROOM 211	W	N, E, W, S	
	CLASSROOM 212	C, W	N, E, W, S	
	CLASSROOM 213	C, W	N, E, W, S	
	CLASSROOM 214	C, W	N, E, W, S	
	CLASSROOM 215	C, W	N, E, W, S	
	COMPUTER CLASSROOM 216	W	N, E, W, S	
	SPECIAL ED 217	C, W	N, E, W, S	
	SPECIAL ED 218	C, W	N, E, W, S	
	CLASSROOM 300	C, W	N, E, W, S	
	CLASSROOM 301	C, W	N, E, W, S	
	CLASSROOM 302	C, W	N, E, W, S	
	CLASSROOM 303	C, W	N, E, W, S	
	CLASSROOM 304	W	N, E, W, S	
	CLASSROOM 305	W	N, E, W, S	
	CLASSROOM 306	C, W	N, E, W, S	
	SCIENCE CLASSROOM 307	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STORAGE 01	W	N, E, W, S	
	STAFF LOUNGE 01	C, W	N, E, W, S	
	SCIENCE CLASSROOM 308	W	N, E, W, S	
	CLASSROOM 309	C, W	N, E, W, S	
	CLASSROOM 310	C, W	N, E, W, S	
	CLASSROOM 311	C, W	N, E, W, S	
	CLASSROOM 312	C, W	N, E, W, S	
	CLASSROOM 313	C, W	N, E, W, S	
	CLASSROOM 314	C, W	N, E, W, S	
	CLASSROOM 315	C, W	N, E, W, S	
	COMPUTER CLASSROOM 316	W	N, E, W, S	
	SPECIAL ED 317	C, W	N, E, W, S	
	SPECIAL ED 318	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	SECRETARY/RECEPTION	C, W	N, E, W, S	S
	OFFICE 1	W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	OFFICE 3	W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	STUDENT SERVICES	W	N, E, W, S	
	OFFICE 5	W	N, E, W, S	
	OFFICE 6	W	N, E, W, S	
	CONFERENCE ROOM	W	N, E, W, S	
	OFFICE 7	W	N, E, W, S	
	OFFICE 8	W	N, E, W, S	
	BREAK	W	N, E, W, S	
	TEST	W	N, E, W, S	
	COTS	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	COTS CLOSET	C	*	
	TREATMENT	W	N, E, W, S	
	PRINCIPAL	W	N, E, W, S	
	WAIT	W	N, E, W, S	
	NURSE'S OFFICE	W	N, E, W, S	
	CLASSROOM 100	C, W	N, E, W, S	
	CLASSROOM 101	C, W	N, E, W, S	
	CLASSROOM 102	C, W	N, E, W, S	
	CLASSROOM 103	C, W	N, E, W, S	
	CLASSROOM 104	C, W	N, E, W, S	
	CLASSROOM 105	C, W	N, E, W, S	
	CLASSROOM 106	C, W	N, E, W, S	
	SCIENCE CLASSROOM 107	W	N, E, W, S	
	STORAGE 09	W	N, E, W, S	
	STAFF LOUNGE 04	C, W	N, E, W, S	
	SCIENCE CLASSROOM 108	W	N, E, W, S	
	CLASSROOM 109	C, W	N, E, W, S	
	CLASSROOM 110	W	N, E, W, S	
	CLASSROOM 111	W	N, E, W, S	
	STORAGE 07	W	N, E, W, S	
	STORAGE 08	W	N, E, W, S	
	CLASSROOM 112	C, W	N, E, W, S	
	CLASSROOM 113	C, W	N, E, W, S	
	CLASSROOM 114	C, W	N, E, W, S	
	CLASSROOM 115	C, W	N, E, W, S	
	COMPUTER CLASSROOM 116	W	N, E, W, S	
	SPECIAL ED 117	C, W	N, E, W, S	
	SPECIAL ED 118	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CLASSROOM 200	C, W	N, E, W, S	
	CLASSROOM 201	C, W	N, E, W, S	
	CLASSROOM 202	C, W	N, E, W, S	
	CLASSROOM 203	C, W	N, E, W, S	
	CLASSROOM 204	W	N, E, W, S	
	CLASSROOM 205	W	N, E, W, S	
	CLASSROOM 206	C, W	N, E, W, S	
	SCIENCE CLASSROOM 207	W	N, E, W, S	
	STORAGE 06	W	N, E, W, S	
	STAFF LOUNGE 03	C, W	N, E, W, S	
	STORAGE 05	W	N, E, W, S	
	SCIENCE CLASSROOM 208	W	N, E, W, S	
	CLASSROOM 209	C, W	N, E, W, S	
	CLASSROOM 210	W	N, E, W, S	
	STORAGE 02	W	N, E, W, S	
	STORAGE 03	W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF LOUNGE 02	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	
	STORAGE 04	W	N, E, W, S	
	CLASSROOM 211	W	N, E, W, S	
	CLASSROOM 212	C, W	N, E, W, S	
	CLASSROOM 213	C, W	N, E, W, S	
	CLASSROOM 214	C, W	N, E, W, S	
	CLASSROOM 215	C, W	N, E, W, S	
	COMPUTER CLASSROOM 216	W	N, E, W, S	
	SPECIAL ED 217	C, W	N, E, W, S	
	SPECIAL ED 218	C, W	N, E, W, S	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 300	C, W	N, E, W, S	
	CLASSROOM 301	C, W	N, E, W, S	
	CLASSROOM 302	C, W	N, E, W, S	
	CLASSROOM 303	C, W	N, E, W, S	
	CLASSROOM 304	W	N, E, W, S	
	CLASSROOM 305	W	N, E, W, S	
	CLASSROOM 306	C, W	N, E, W, S	
	SCIENCE CLASSROOM 307	W	N, E, W, S	
	STORAGE 01	W	N, E, W, S	
	STAFF LOUNGE 01	C, W	N, E, W, S	
	SCIENCE CLASSROOM 308	W	N, E, W, S	
	CLASSROOM 309	C, W	N, E, W, S	
	CLASSROOM 310	C, W	N, E, W, S	
	CLASSROOM 311	C, W	N, E, W, S	
	CLASSROOM 312	C, W	N, E, W, S	
	CLASSROOM 313	C, W	N, E, W, S	
	CLASSROOM 314	C, W	N, E, W, S	
	CLASSROOM 315	C, W	N, E, W, S	
	COMPUTER CLASSROOM 316	W	N, E, W, S	
	SPECIAL ED 317	C, W	N, E, W, S	
	SPECIAL ED 318	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	OFFICE 1	W	N, E	S
	STUDENT SERVICES	W	W, S	
	CLASSROOM 100	W	E, W, S	
	CLASSROOM 101	W	N, E, W	
	CLASSROOM 102	W	E, W, S	
	CLASSROOM 103	W	N, E, W	
	CLASSROOM 104	W	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	CLASSROOM 105	W	W, S	
	CLASSROOM 106	W	N, E, W, S	
	SCIENCE CLASSROOM 107	W	N, E, S	
	SCIENCE CLASSROOM 108	W	N, W, S	
	CLASSROOM 109	W	N, E, S	
	CLASSROOM 110	W	E, W	
	CLASSROOM 111	W	E, W	
	CLASSROOM 112	W	N, S	
	CLASSROOM 113	W	N, S	
	CLASSROOM 114	W	N, S	
	CLASSROOM 115	W	N, S	
	SPECIAL ED 117	W	N, W	
	SPECIAL ED 118	W	N, E	
	CLASSROOM 200	W	N, S	
	CLASSROOM 201	W	N, S	
	CLASSROOM 202	W	N, S	
	CLASSROOM 203	W	N, S	
	CLASSROOM 204	W	N, S	
	CLASSROOM 205	W	N, S	
	CLASSROOM 206	W	E, W	
	SCIENCE CLASSROOM 207	W	N, E, W	
	SCIENCE CLASSROOM 208	W	E, W, S	
	CLASSROOM 209	W	E, W	
	CLASSROOM 210	W	N, W	
	CLASSROOM 211	W	W, S	
	CLASSROOM 212	W	E, W, S	
	CLASSROOM 213	W	N, E, S	
	CLASSROOM 214	W	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 215	W	N, E, W	
	SPECIAL ED 217	W	N, E	
	SPECIAL ED 218	W	E, S	
	CLASSROOM 300	W	N, E, W	
	CLASSROOM 301	W	E, W, S	
	CLASSROOM 302	W	N, E, W	
	CLASSROOM 303	W	E, W, S	
	CLASSROOM 304	W	N, E	
	CLASSROOM 305	W	N, W	
	CLASSROOM 306	W	N, E, S	
	SCIENCE CLASSROOM 307	W	N, E, S	
	SCIENCE CLASSROOM 308	W	N, W, S	
	CLASSROOM 309	W	N, W, S	
	CLASSROOM 310	W	N, W	
	CLASSROOM 311	W	E, S	
	CLASSROOM 312	W	N, W, S	
	CLASSROOM 313	W	N, E, S	
	CLASSROOM 314	W	N, W, S	
	CLASSROOM 315	W	N, E, S	
	SPECIAL ED 317	W	E, S	
	SPECIAL ED 318	W	W, S	
CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	CLASSROOM 100	F	*	S
	CLASSROOM 101	F	*	
	CLASSROOM 102	F	*	
	CLASSROOM 103	F	*	
	CLASSROOM 104	F	*	
	CLASSROOM 105	F	*	
	CLASSROOM 106	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	SCIENCE CLASSROOM 107	F	*	
	STAFF LOUNGE 04	F	*	
	SCIENCE CLASSROOM 108	F	*	
	CLASSROOM 109	F	*	
	CLASSROOM 110	F	*	
	CLASSROOM 111	F	*	
	STORAGE 07	F	*	
	LOBBY 04	F	*	
	CLASSROOM 112	F	*	
	CLASSROOM 113	F	*	
	CLASSROOM 114	F	*	
	CLASSROOM 115	F	*	
	LOBBY 05	F	*	
	CLASSROOM 200	F	*	
	CLASSROOM 201	F	*	
	CLASSROOM 202	F	*	
	CLASSROOM 203	F	*	
	CLASSROOM 204	F	*	
	CLASSROOM 205	F	*	
	CLASSROOM 206	F	*	
	SCIENCE CLASSROOM 207	F	*	
	SCIENCE CLASSROOM 208	F	*	
	CLASSROOM 209	F	*	
	CLASSROOM 210	F	*	
	CLASSROOM 211	F	*	
	LOBBY 02	F	*	
	CLASSROOM 212	F	*	
	CLASSROOM 213	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 214	F	*	
	CLASSROOM 215	F	*	
	LOBBY 03	F	*	
	CLASSROOM 300	F	*	
	CLASSROOM 301	F	*	
	CLASSROOM 302	F	*	
	CLASSROOM 303	F	*	
	CLASSROOM 304	F	*	
	CLASSROOM 305	F	*	
	CLASSROOM 306	F	*	
	SCIENCE CLASSROOM 307	F	*	
	SCIENCE CLASSROOM 308	F	*	
	CLASSROOM 309	F	*	
	CLASSROOM 310	F	*	
	CLASSROOM 311	F	*	
	CLASSROOM 312	F	*	
	CLASSROOM 313	F	*	
	CLASSROOM 314	F	*	
	CLASSROOM 315	F	*	
	LOBBY 01	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
	CORRIDOR 03	F	*	
	CORRIDOR 04	F	*	
	CORRIDOR 05	F	*	
	CORRIDOR 06	F	*	
	CORRIDOR 07	F	*	
	CORRIDOR 08	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR 09	F	*	
	CORRIDOR 10	F	*	
	CORRIDOR 11	F	*	
	CORRIDOR 12	F	*	
	CORRIDOR 13	F	*	
	CORRIDOR 14	F	*	
	CORRIDOR 15	F	*	
	CORRIDOR 16	F	*	
	CORRIDOR 17	F	*	
	CORRIDOR 18	F	*	
	CORRIDOR 19	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	COTS CLOSET	F	*	S
	TREATMENT	F	*	
	CLASSROOM 100	F	*	
	CLASSROOM 101	F	*	
	CLASSROOM 102	F	*	
	CLASSROOM 103	F	*	
	CLASSROOM 104	F	*	
	CLASSROOM 105	F	*	
	CLASSROOM 106	F	*	
	SCIENCE CLASSROOM 107	F	*	
	SCIENCE CLASSROOM 108	F	*	
	CLASSROOM 109	F	*	
	CLASSROOM 110	F	*	
	CLASSROOM 111	F	*	
	STORAGE 08	F	*	
	CLASSROOM 112	F	*	
	CLASSROOM 113	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 114	F	*	
	CLASSROOM 115	F	*	
	CLASSROOM 200	F	*	
	CLASSROOM 201	F	*	
	CLASSROOM 202	F	*	
	CLASSROOM 203	F	*	
	CLASSROOM 204	F	*	
	CLASSROOM 205	F	*	
	CLASSROOM 206	F	*	
	SCIENCE CLASSROOM 207	F	*	
	SCIENCE CLASSROOM 208	F	*	
	CLASSROOM 209	F	*	
	CLASSROOM 210	F	*	
	STORAGE 04	F	*	
	STORAGE 02	F	*	
	STORAGE 03	F	*	
	CLASSROOM 211	F	*	
	CLASSROOM 212	F	*	
	CLASSROOM 213	F	*	
	CLASSROOM 214	F	*	
	CLASSROOM 215	F	*	
	CLASSROOM 300	F	*	
	CLASSROOM 301	F	*	
	CLASSROOM 302	F	*	
	CLASSROOM 303	F	*	
	CLASSROOM 304	F	*	
	CLASSROOM 305	F	*	
	CLASSROOM 306	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	SCIENCE CLASSROOM 307	F	*	
	SCIENCE CLASSROOM 308	F	*	
	CLASSROOM 309	F	*	
	CLASSROOM 310	F	*	
	CLASSROOM 311	F	*	
	CLASSROOM 312	F	*	
	CLASSROOM 313	F	*	
	CLASSROOM 314	F	*	
	CLASSROOM 315	F	*	
MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	COTS CLOSET	F	*	S
	TREATMENT	F	*	
	CLASSROOM 100	F	*	
	CLASSROOM 101	F	*	
	CLASSROOM 102	F	*	
	CLASSROOM 103	F	*	
	CLASSROOM 104	F	*	
	CLASSROOM 105	F	*	
	CLASSROOM 106	F	*	
	SCIENCE CLASSROOM 107	F	*	
	SCIENCE CLASSROOM 108	F	*	
	CLASSROOM 109	F	*	
	CLASSROOM 110	F	*	
	CLASSROOM 111	F	*	
	STORAGE 08	F	*	
	CLASSROOM 112	F	*	
	CLASSROOM 113	F	*	
	CLASSROOM 114	F	*	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 115	F	*	
	CLASSROOM 200	F	*	
	CLASSROOM 201	F	*	
	CLASSROOM 202	F	*	
	CLASSROOM 203	F	*	
	CLASSROOM 204	F	*	
	CLASSROOM 205	F	*	
	CLASSROOM 206	F	*	
	SCIENCE CLASSROOM 207	F	*	
	SCIENCE CLASSROOM 208	F	*	
	CLASSROOM 209	F	*	
	CLASSROOM 210	F	*	
	STORAGE 04	F	*	
	STORAGE 02	F	*	
	STORAGE 03	F	*	
	CLASSROOM 211	F	*	
	CLASSROOM 212	F	*	
	CLASSROOM 213	F	*	
	CLASSROOM 214	F	*	
	CLASSROOM 215	F	*	
	CLASSROOM 300	F	*	
	CLASSROOM 301	F	*	
	CLASSROOM 302	F	*	
	CLASSROOM 303	F	*	
	CLASSROOM 304	F	*	
	CLASSROOM 305	F	*	
	CLASSROOM 306	F	*	
	SCIENCE CLASSROOM 307	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	SCIENCE CLASSROOM 308	F	*	
	CLASSROOM 309	F	*	
	CLASSROOM 310	F	*	
	CLASSROOM 311	F	*	
	CLASSROOM 312	F	*	
	CLASSROOM 313	F	*	
	CLASSROOM 314	F	*	
	CLASSROOM 315	F	*	
WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	SECRETARY/RECEPTION	O	N, E, W, S	S
	OFFICE 2	O	N, E, W, S	
	OFFICE 3	O	N, E, W, S	
	OFFICE 4	O	N, E, W, S	
	STUDENT SERVICES	O	N, E, W, S	
	OFFICE 6	O	N, E, W, S	
	CONFERENCE ROOM	O	N, E, W, S	
	OFFICE 7	O	N, E, W, S	
	OFFICE 8	O	N, E, W, S	
	BREAK	O	N, W, S	
	COTS	O	N, E, W, S	
	TREATMENT	O	N, E, W, S	
	PRINCIPAL	O	N, E, W, S	
	WAIT	O	N, E, W, S	
	NURSE'S OFFICE	O	N, E, W, S	
	CLASSROOM 100	O	N, E, W, S	
	CLASSROOM 101	O	N, E, W, S	
	CLASSROOM 102	O	N, E, W, S	
	CLASSROOM 103	O	N, E, W, S	
	CLASSROOM 104	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 105	O	N, E, W, S	
	CLASSROOM 106	O	N, E, W, S	
	SCIENCE CLASSROOM 107	O	N, E, W, S	
	STORAGE 09	O	N, E, W, S	
	STAFF LOUNGE 04	O	N, E, W, S	
	SCIENCE CLASSROOM 108	O	N, E, W, S	
	CLASSROOM 109	O	N, E, W, S	
	CLASSROOM 110	O	N, E, W, S	
	CLASSROOM 111	O	N, E, W, S	
	STORAGE 07	O	N, E, W, S	
	STORAGE 08	O	N, E, W, S	
	LOBBY 04	O	N, E, W, S	
	CLASSROOM 112	O	N, E, W, S	
	CLASSROOM 113	O	N, E, W, S	
	CLASSROOM 114	O	N, E, W, S	
	CLASSROOM 115	O	N, E, W, S	
	LOBBY 05	O	E, W	
	COMPUTER CLASSROOM 116	O	N, E, W, S	
	SPECIAL ED 117	O	N, W, S	
	SPECIAL ED 118	O	N, E, S	
	CLASSROOM 200	O	N, E, W, S	
	CLASSROOM 201	O	N, E, W, S	
	CLASSROOM 202	O	N, E, W, S	
	CLASSROOM 203	O	N, E, W, S	
	CLASSROOM 204	O	N, E, W, S	
	CLASSROOM 205	O	N, E, W, S	
	CLASSROOM 206	O	N, E, W, S	
	SCIENCE CLASSROOM 207	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STORAGE 06	O	N, E, W, S	
	STAFF LOUNGE 03	O	N, E, W, S	
	SCIENCE CLASSROOM 208	O	N, E, W, S	
	CLASSROOM 209	O	N, E, W, S	
	CLASSROOM 210	O	N, E, W, S	
	STORAGE 04	O	N, E, W, S	
	STAFF LOUNGE 02	O	N, E, W, S	
	STORAGE 03	O	N, E, W, S	
	STORAGE 02	O	N, E, W, S	
	LOBBY 02	O	N, E, W, S	
	CLASSROOM 211	O	N, E, W, S	
	CLASSROOM 212	O	N, E, W, S	
	CLASSROOM 213	O	N, E, W, S	
	CLASSROOM 214	O	N, E, W, S	
	CLASSROOM 215	O	N, E, W, S	
	LOBBY 03	O	N, S	
	COMPUTER CLASSROOM 216	O	N, E, W, S	
	SPECIAL ED 217	O	N, E, W	
	SPECIAL ED 218	O	E, W, S	
	CLASSROOM 300	O	N, E, W, S	
	CLASSROOM 301	O	N, E, W, S	
	CLASSROOM 302	O	N, E, W, S	
	CLASSROOM 303	O	N, E, W, S	
	CLASSROOM 304	O	N, E, W, S	
	CLASSROOM 305	O	N, E, W, S	
	CLASSROOM 306	O	N, E, W, S	
	SCIENCE CLASSROOM 307	O	N, E, W, S	
	STORAGE 01	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	STAFF LOUNGE 01	O	N, E, W, S	
	SCIENCE CLASSROOM 308	O	N, E, W, S	
	CLASSROOM 309	O	N, E, W, S	
	CLASSROOM 310	O	N, E, W, S	
	CLASSROOM 311	O	N, E, W, S	
	CLASSROOM 312	O	N, E, W, S	
	CLASSROOM 313	O	N, E, W, S	
	CLASSROOM 314	O	N, E, W, S	
	CLASSROOM 315	O	N, E, W, S	
	LOBBY 01	O	N, E, W, S	
	COMPUTER CLASSROOM 316	O	N, E, W, S	
	SPECIAL ED 317	O	N, E, S	
	SPECIAL ED 318	O	N, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
	CORRIDOR 03	O	N, E, W, S	
	CORRIDOR 04	O	N, E, W, S	
	CORRIDOR 05	O	N, E, W, S	
	CORRIDOR 06	O	N, E, W, S	
	CORRIDOR 07	O	N, E, W, S	
	CORRIDOR 08	O	N, E, W, S	
	CORRIDOR 09	O	N, E, W, S	
	CORRIDOR 10	O	N, E, W, S	
	CORRIDOR 11	O	N, E, W, S	
	CORRIDOR 12	O	N, E, W, S	
	CORRIDOR 13	O	N, E, W, S	
	CORRIDOR 14	O	N, E, W, S	
	CORRIDOR 15	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	CORRIDOR 16	O	N, E, W, S	
	CORRIDOR 17	O	N, E, W, S	
	CORRIDOR 18	O	N, E, W, S	
	CORRIDOR 19	O	N, E, W, S	
	CORRIDOR 20	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	SECRETARY/RECEPTION	O	N, E, W, S	S
	OFFICE 2	O	N, E, W, S	
	OFFICE 3	O	N, E, W, S	
	OFFICE 4	O	N, E, W, S	
	STUDENT SERVICES	O	N, E, W, S	
	OFFICE 6	O	N, E, W, S	
	CONFERENCE ROOM	O	N, E, W, S	
	OFFICE 7	O	N, E, W, S	
	OFFICE 8	O	N, E, W, S	
	BREAK	O	N, W, S	
	COTS	O	N, E, W, S	
	TREATMENT	O	N, E, W, S	
	PRINCIPAL	O	N, E, W, S	
	WAIT	O	N, E, W, S	
	NURSE'S OFFICE	O	N, E, W, S	
	CLASSROOM 100	O	N, E, W, S	
	CLASSROOM 101	O	N, E, W, S	
	CLASSROOM 102	O	N, E, W, S	
	CLASSROOM 103	O	N, E, W, S	
	CLASSROOM 104	O	N, E, W, S	
	CLASSROOM 105	O	N, E, W, S	
	CLASSROOM 106	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	SCIENCE CLASSROOM 107	O	N, E, W, S	
	STORAGE 09	O	N, E, W, S	
	STAFF LOUNGE 04	O	N, E, W, S	
	SCIENCE CLASSROOM 108	O	N, E, W, S	
	CLASSROOM 109	O	N, E, W, S	
	CLASSROOM 110	O	N, E, W, S	
	CLASSROOM 111	O	N, E, W, S	
	STORAGE 07	O	N, E, W, S	
	STORAGE 08	O	N, E, W, S	
	LOBBY 04	O	N, E, W, S	
	CLASSROOM 112	O	N, E, W, S	
	CLASSROOM 113	O	N, E, W, S	
	CLASSROOM 114	O	N, E, W, S	
	CLASSROOM 115	O	N, E, W, S	
	LOBBY 05	O	E, W	
	COMPUTER CLASSROOM 116	O	N, E, W, S	
	SPECIAL ED 117	O	N, W, S	
	SPECIAL ED 118	O	N, E, S	
	CLASSROOM 200	O	N, E, W, S	
	CLASSROOM 201	O	N, E, W, S	
	CLASSROOM 202	O	N, E, W, S	
	CLASSROOM 203	O	N, E, W, S	
	CLASSROOM 204	O	N, E, W, S	
	CLASSROOM 205	O	N, E, W, S	
	CLASSROOM 206	O	N, E, W, S	
	SCIENCE CLASSROOM 207	O	N, E, W, S	
	STORAGE 06	O	N, E, W, S	
	STAFF LOUNGE 03	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	SCIENCE CLASSROOM 208	O	N, E, W, S	
	CLASSROOM 209	O	N, E, W, S	
	CLASSROOM 210	O	N, E, W, S	
	STORAGE 04	O	N, E, W, S	
	STAFF LOUNGE 02	O	N, E, W, S	
	STORAGE 03	O	N, E, W, S	
	STORAGE 02	O	N, E, W, S	
	LOBBY 02	O	N, E, W, S	
	CLASSROOM 211	O	N, E, W, S	
	CLASSROOM 212	O	N, E, W, S	
	CLASSROOM 213	O	N, E, W, S	
	CLASSROOM 214	O	N, E, W, S	
	CLASSROOM 215	O	N, E, W, S	
	LOBBY 03	O	N, S	
	COMPUTER CLASSROOM 216	O	N, E, W, S	
	SPECIAL ED 217	O	N, E, W	
	SPECIAL ED 218	O	E, W, S	
	CLASSROOM 300	O	N, E, W, S	
	CLASSROOM 301	O	N, E, W, S	
	CLASSROOM 302	O	N, E, W, S	
	CLASSROOM 303	O	N, E, W, S	
	CLASSROOM 304	O	N, E, W, S	
	CLASSROOM 305	O	N, E, W, S	
	CLASSROOM 306	O	N, E, W, S	
	SCIENCE CLASSROOM 307	O	N, E, W, S	
	STORAGE 01	O	N, E, W, S	
	STAFF LOUNGE 01	O	N, E, W, S	
	SCIENCE CLASSROOM 308	O	N, E, W, S	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM 309	O	N, E, W, S	
	CLASSROOM 310	O	N, E, W, S	
	CLASSROOM 311	O	N, E, W, S	
	CLASSROOM 312	O	N, E, W, S	
	CLASSROOM 313	O	N, E, W, S	
	CLASSROOM 314	O	N, E, W, S	
	CLASSROOM 315	O	N, E, W, S	
	LOBBY 01	O	N, E, W, S	
	COMPUTER CLASSROOM 316	O	N, E, W, S	
	SPECIAL ED 317	O	N, E, S	
	SPECIAL ED 318	O	N, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
	CORRIDOR 03	O	N, E, W, S	
	CORRIDOR 04	O	N, E, W, S	
	CORRIDOR 05	O	N, E, W, S	
	CORRIDOR 06	O	N, E, W, S	
	CORRIDOR 07	O	N, E, W, S	
	CORRIDOR 08	O	N, E, W, S	
	CORRIDOR 09	O	N, E, W, S	
	CORRIDOR 10	O	N, E, W, S	
	CORRIDOR 11	O	N, E, W, S	
	CORRIDOR 12	O	N, E, W, S	
	CORRIDOR 13	O	N, E, W, S	
	CORRIDOR 14	O	N, E, W, S	
	CORRIDOR 15	O	N, E, W, S	
	CORRIDOR 16	O	N, E, W, S	
	CORRIDOR 17	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CORRIDOR 18	O	N, E, W, S	
	CORRIDOR 19	O	N, E, W, S	
	CORRIDOR 20	O	N, E, W, S	
FIRE DOOR INSULATION, METALWOOD CLADDING	SECRETARY/RECEPTION	O	E, W, S	S
	OFFICE 1	O	E, W	
	OFFICE 2	O	E, W	
	STUDENT SERVICES	O	E	
	ELECTRICAL 4	O	W	
	CONFERENCE ROOM	O	W	
	BREAK	O	E	
	PRINCIPAL	O	W, S	
	WAIT	O	E, S	
	CLASSROOM 100	O	W	
	CLASSROOM 101	O	W	
	CLASSROOM 102	O	W	
	CLASSROOM 103	O	W	
	CLASSROOM 104	O	W	
	CLASSROOM 106	O	N	
	SCIENCE CLASSROOM 107	O	N	
	STAFF LOUNGE 04	O	N	
	SCIENCE CLASSROOM 108	O	N	
	CLASSROOM 109	O	N	
	CLASSROOM 110	O	N	
	CLASSROOM 111	O	N	
	BOY'S RESTROOM 5	O	N	
	STORAGE 07	O	E	
	LOBBY 04	O	W, S	
	CLASSROOM 112	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CLASSROOM 113	O	S	
	CLASSROOM 114	O	S	
	CLASSROOM 115	O	S	
	COMPUTER CLASSROOM 116	O	S	
	SPECIAL ED 117	O	W	
	SPECIAL ED 118	O	E	
	STAFF WOMEN'S RESTROOM 4	O	S	
	JANITOR 3	O	S	
	GIRL'S RESTROOM 7	O	E	
	BOY'S RESTROOM 7	O	N	
	STAFF MEN'S RESTROOM 4	O	S	
	ELECTRICAL 3	O	S	
	GIRL'S RESTROOM 6	O	W	
	BOY'S RESTROOM 6	O	N	
	CLASSROOM 200	O	N	
	CLASSROOM 201	O	N	
	CLASSROOM 202	O	N	
	CLASSROOM 203	O	N	
	GIRL'S RESTROOM 5	O	E	
	CLASSROOM 204	O	E	
	CLASSROOM 205	O	E	
	CLASSROOM 206	O	E	
	SCIENCE CLASSROOM 207	O	E	
	STAFF LOUNGE 03	O	E	
	SCIENCE CLASSROOM 208	O	E	
	CLASSROOM 209	O	E	
	CLASSROOM 210	O	E	
	STORAGE 04	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF WOMEN'S RESTROOM 2	O	N	
	STAFF LOUNGE 02	O	N	
	STAFF MEN'S RESTROOM 2	O	N	
	LOBBY 02	O	N, E, W	
	CLASSROOM 211	O	E	
	CLASSROOM 212	O	W	
	CLASSROOM 213	O	W	
	CLASSROOM 214	O	W	
	CLASSROOM 215	O	W	
	COMPUTER CLASSROOM 216	O	W	
	SPECIAL ED 217	O	N	
	SPECIAL ED 218	O	S	
	STAFF MEN'S RESTROOM 3	O	W	
	JANITOR 2	O	W	
	GIRL'S RESTROOM 4	O	S	
	BOY'S RESTROOM 4	O	E	
	STAFF WOMEN'S RESTROOM 3	O	W	
	ELECTRICAL 2	O	W	
	GIRL'S RESTROOM 3	O	N	
	BOY'S RESTROOM 3	O	E	
	CLASSROOM 300	O	E	
	CLASSROOM 301	O	E	
	CLASSROOM 302	O	E	
	CLASSROOM 303	O	E	
	CLASSROOM 304	O	S	
	CLASSROOM 305	O	S	
	CLASSROOM 306	O	S	
	SCIENCE CLASSROOM 307	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STAFF LOUNGE 01	O	S	
	SCIENCE CLASSROOM 308	O	S	
	CLASSROOM 309	O	S	
	CLASSROOM 311	O	N	
	CLASSROOM 312	O	N	
	CLASSROOM 313	O	N	
	CLASSROOM 314	O	N	
	CLASSROOM 315	O	N	
	COMPUTER CLASSROOM 316	O	N	
	SPECIAL ED 317	O	E	
	SPECIAL ED 318	O	W	
	STAFF WOMEN'S RESTROOM 1	O	N	
	JANITOR 1	O	N	
	GIRL'S RESTROOM 2	O	W	
	BOY'S RESTROOM 2	O	S	
	STAFF MEN'S RESTROOM 1	O	N	
	ELECTRICAL 1	O	N	
	GIRL'S RESTROOM 1	O	E	
	BOY'S RESTROOM 1	O	S	
	CORRIDOR 01	O	N, E, S	
	CORRIDOR 02	O	N, E, W	
	CORRIDOR 03	O	W, S	
	CORRIDOR 04	O	N, S	
	CORRIDOR 05	O	N, E, S	
	CORRIDOR 06	O	N, S	
	CORRIDOR 07	O	E, W	
	CORRIDOR 08	O	E, W, S	
	CORRIDOR 09	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CORRIDOR 10	O	N, W, S	
	CORRIDOR 11	O	E, W, S	
	CORRIDOR 12	O	N, W, S	
	CORRIDOR 13	O	N, E, S	
	CORRIDOR 14	O	N, S	
	CORRIDOR 15	O	N, E, S	
	CORRIDOR 16	O	E, W, S	
	CORRIDOR 17	O	N, E	
	CORRIDOR 18	O	E, S	
	CORRIDOR 19	O	E, W	
	CORRIDOR 20	O	N, W	
SINK ACOUSTICAL COATING, GRAY, ROUGH	BREAK	O	W	S
	COTS	O	W	
	TREATMENT	O	E	
	CLASSROOM 100	O	N	
	CLASSROOM 101	O	S	
	CLASSROOM 102	O	N	
	CLASSROOM 103	O	S	
	CLASSROOM 104	O	W	
	CLASSROOM 105	O	N	
	CLASSROOM 106	O	E	
	STAFF LOUNGE 04	O	E	
	CLASSROOM 109	O	W	
	CLASSROOM 110	O	W	
	CLASSROOM 111	O	E	
	CLASSROOM 112	O	S	
	CLASSROOM 113	O	N	
	CLASSROOM 114	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 115	O	N	
	SPECIAL ED 117	O	S	
	SPECIAL ED 118	O	S	
	CLASSROOM 200	O	E	
	CLASSROOM 201	O	W	
	CLASSROOM 202	O	E	
	CLASSROOM 203	O	W	
	CLASSROOM 204	O	N	
	CLASSROOM 205	O	S	
	CLASSROOM 206	O	S	
	STAFF LOUNGE 03	O	N	
	CLASSROOM 209	O	N	
	CLASSROOM 210	O	E	
	CLASSROOM 211	O	E	
	CLASSROOM 212	O	N	
	CLASSROOM 213	O	S	
	CLASSROOM 214	O	N	
	CLASSROOM 215	O	S	
	CLASSROOM 217	O	W	
	CLASSROOM 218	O	W	
	CLASSROOM 300	O	S	
	CLASSROOM 301	O	N	
	CLASSROOM 302	O	S	
	CLASSROOM 303	O	N	
	CLASSROOM 304	O	S	
	CLASSROOM 305	O	S	
	CLASSROOM 306	O	W	
	STAFF LOUNGE 01	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CLASSROOM 309	O	E	
	CLASSROOM 310	O	S	
	CLASSROOM 311	O	N	
	CLASSROOM 312	O	E	
	CLASSROOM 313	O	W	
	CLASSROOM 314	O	E	
	CLASSROOM 315	O	W	
SEALANT (DUCT), LIGHT GRAY, PLIABLE	SECRETARY/RECEPTION	O	*	S
	OFFICE 1	O	*	
	OFFICE 2	O	*	
	OFFICE 3	O	*	
	OFFICE 4	O	*	
	STUDENT SERVICES	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	ELECTRICAL 4	O	*	
	OFFICE 5	O	*	
	OFFICE 6	O	*	
	CONFERENCE ROOM	O	*	
	OFFICE 7	O	*	
	OFFICE 8	O	*	
	STAFF MEN'S RESTROOM	O	*	
	BREAK	O	*	
	NURSE RESTROOM	O	*	
	TEST	O	*	
	COTS	O	*	
	COTS CLOSET	O	*	
	TREATMENT	O	*	
	PRINCIPAL	O	*	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	WAIT	O	*	
	NURSE'S OFFICE	O	*	
	CLASSROOM 100	O	*	
	CLASSROOM 101	O	*	
	CLASSROOM 102	O	*	
	CLASSROOM 103	O	*	
	CLASSROOM 104	O	*	
	CLASSROOM 105	O	*	
	CLASSROOM 106	O	*	
	SCIENCE CLASSROOM 107	O	*	
	STORAGE 09	O	*	
	STAFF LOUNGE 04	O	*	
	SCIENCE CLASSROOM 108	O	*	
	CLASSROOM 109	O	*	
	CLASSROOM 110	O	*	
	CLASSROOM 111	O	*	
	BOY'S RESTROOM 5	O	*	
	STORAGE 07	O	*	
	STORAGE 08	O	*	
	LOBBY 04	O	*	
	CLASSROOM 112	O	*	
	CLASSROOM 113	O	*	
	CLASSROOM 114	O	*	
	CLASSROOM 115	O	*	
	LOBBY 05	O	*	
	COMPUTER CLASSROOM 116	O	*	
	SPECIAL ED 117	O	*	
	SPECIAL ED 118	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STAFF WOMEN'S RESTROOM 4	O	*	
	JANITOR 3	O	*	
	GIRL'S RESTROOM 7	O	*	
	BOY'S RESTROOM 7	O	*	
	STAFF MEN'S RESTROOM 4	O	*	
	ELECTRICAL 3	O	*	
	GIRL'S RESTROOM 6	O	*	
	BOY'S RESTROOM 6	O	*	
	CLASSROOM 200	O	*	
	CLASSROOM 201	O	*	
	CLASSROOM 202	O	*	
	CLASSROOM 203	O	*	
	GIRL'S RESTROOM 5	O	*	
	CLASSROOM 204	O	*	
	CLASSROOM 205	O	*	
	CLASSROOM 206	O	*	
	SCIENCE CLASSROOM 207	O	*	
	STORAGE 06	O	*	
	STAFF LOUNGE 03	O	*	
	STORAGE 05	O	*	
	SCIENCE CLASSROOM 208	O	*	
	CLASSROOM 209	O	*	
	CLASSROOM 210	O	*	
	STORAGE 04	O	*	
	STAFF WOMEN'S RESTROOM 2	O	*	
	STAFF LOUNGE 02	O	*	
	STAFF MEN'S RESTROOM 2	O	*	
	STORAGE 03	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	STORAGE 02	O	*	
	LOBBY 02	O	*	
	CLASSROOM 211	O	*	
	CLASSROOM 212	O	*	
	CLASSROOM 213	O	*	
	CLASSROOM 214	O	*	
	CLASSROOM 215	O	*	
	LOBBY 03	O	*	
	COMPUTER CLASSROOM 216	O	*	
	SPECIAL ED 217	O	*	
	SPECIAL ED 218	O	*	
	STAFF MEN'S RESTROOM 3	O	*	
	JANITOR 2	O	*	
	GIRL'S RESTROOM 4	O	*	
	BOY'S RESTROOM 4	O	*	
	STAFF WOMEN'S RESTROOM 3	O	*	
	ELECTRICAL 2	O	*	
	GIRL'S RESTROOM 3	O	*	
	BOY'S RESTROOM 3	O	*	
	CLASSROOM 300	O	*	
	CLASSROOM 301	O	*	
	CLASSROOM 302	O	*	
	CLASSROOM 303	O	*	
	CLASSROOM 304	O	*	
	CLASSROOM 305	O	*	
	CLASSROOM 306	O	*	
	SCIENCE CLASSROOM 307	O	*	
	STORAGE 01	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	STAFF LOUNGE 01	O	*	
	SCIENCE CLASSROOM 308	O	*	
	CLASSROOM 309	O	*	
	CLASSROOM 310	O	*	
	CLASSROOM 311	O	*	
	CLASSROOM 312	O	*	
	CLASSROOM 313	O	*	
	CLASSROOM 314	O	*	
	CLASSROOM 315	O	*	
	LOBBY 01	O	*	
	COMPUTER CLASSROOM 316	O	*	
	SPECIAL ED 317	O	*	
	SPECIAL ED 318	O	*	
	STAFF WOMEN'S RESTROOM 1	O	*	
	JANITOR 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	STAFF MEN'S RESTROOM 1	O	*	
	ELECTRICAL 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	CORRIDOR 01	O	*	
	CORRIDOR 02	O	*	
	CORRIDOR 03	O	*	
	CORRIDOR 04	O	*	
	CORRIDOR 05	O	*	
	CORRIDOR 06	O	*	
	CORRIDOR 07	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CORRIDOR 08	O	*	
	CORRIDOR 09	O	*	
	CORRIDOR 10	O	*	
	CORRIDOR 11	O	*	
	CORRIDOR 12	O	*	
	CORRIDOR 13	O	*	
	CORRIDOR 14	O	*	
	CORRIDOR 15	O	*	
	CORRIDOR 16	O	*	
	CORRIDOR 17	O	*	
	CORRIDOR 18	O	*	
	CORRIDOR 19	O	*	
	CORRIDOR 20	O	*	
SEALANT (WINDOWS), BLACK, GUMMY	SECRETARY/RECEPTION	O	N	
	OFFICE 1	O	S	
	OFFICE 3	O	S	
	OFFICE 4	O	W	
	STUDENT SERVICES	O	N	
	OFFICE 5	O	E	
	COTS	O	S	
	NURSE'S OFFICE	O	N, S	
	WAIT	O	N	
	CLASSROOM 111	O	N	
	STORAGE 07	O	N, E, S	
	LOBBY 04	O	W, S	
	CLASSROOM 204	O	E	
	LOBBY 02	O	N, E	
	CORRIDOR 02	O	N, E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR 04	O	S	
	CORRIDOR 05	O	N, S	
	CORRIDOR 07	O	W	
	CORRIDOR 08	O	E, W	
	CORRIDOR 09	O	E, W	
	CORRIDOR 10	O	W, S	
	CORRIDOR 11	O	W	
	CORRIDOR 12	O	W	
	CORRIDOR 13	O	N, S	
	CORRIDOR 14	O	N, S	
	CORRIDOR 15	O	E, S	
	CORRIDOR 16	O	N, S	
	CORRIDOR 18	O	E	
	CORRIDOR 19	O	S	
	CORRIDOR 20	O	E, W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	S
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	NURSE'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	C, W	N, E, W, S	
	JANITOR 3	C, W	N, E, W, S	
	GIRL'S RESTROOM 7	C, W	N, E, W, S	
	BOY'S RESTROOM 7	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	C, W	N, E, W, S	
	GIRL'S RESTROOM 6	C, W	N, E, W, S	
	BOY'S RESTROOM 6	C, W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	STAFF MEN'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	C, W	N, E, W, S	
	JANITOR 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 4	C, W	N, E, W, S	
	BOY'S RESTROOM 4	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	C, W	N, E, W, S	
	GIRL'S RESTROOM 3	C, W	N, E, W, S	
	BOY'S RESTROOM 3	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	JANITOR 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	BOY'S RESTROOM 1	C, W	N, E, W, S	
GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	S
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	NURSE'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	C, W	N, E, W, S	
	JANITOR 3	C, W	N, E, W, S	
	GIRL'S RESTROOM 7	C, W	N, E, W, S	
	BOY'S RESTROOM 7	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	C, W	N, E, W, S	
	GIRL'S RESTROOM 6	C, W	N, E, W, S	
	BOY'S RESTROOM 6	C, W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	STAFF WOMEN'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	C, W	N, E, W, S	
	JANITOR 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 4	C, W	N, E, W, S	
	BOY'S RESTROOM 4	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	C, W	N, E, W, S	
	GIRL'S RESTROOM 3	C, W	N, E, W, S	
	BOY'S RESTROOM 3	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	JANITOR 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	BOY'S RESTROOM 1	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	S
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	NURSE'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	C, W	N, E, W, S	
	JANITOR 3	C, W	N, E, W, S	
	GIRL'S RESTROOM 7	C, W	N, E, W, S	
	BOY'S RESTROOM 7	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	C, W	N, E, W, S	
	GIRL'S RESTROOM 6	C, W	N, E, W, S	
	BOY'S RESTROOM 6	C, W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	GIRL'S RESTROOM 5	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	C, W	N, E, W, S	
	JANITOR 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 4	C, W	N, E, W, S	
	BOY'S RESTROOM 4	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	C, W	N, E, W, S	
	GIRL'S RESTROOM 3	C, W	N, E, W, S	
	BOY'S RESTROOM 3	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	JANITOR 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	BOY'S RESTROOM 1	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	STAFF WOMEN'S RESTROOM	W	N, E, W, S	S
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	NURSE'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 7	W	N, E, W, S	
	BOY'S RESTROOM 7	W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 4	W	N, E, W, S	
	BOY'S RESTROOM 4	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	BOY'S RESTROOM 1	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	STAFF WOMEN'S RESTROOM	W	N, E, W, S	S
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	NURSE'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 7	W	N, E, W, S	
	BOY'S RESTROOM 7	W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 4	W	N, E, W, S	
	BOY'S RESTROOM 4	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	BOY'S RESTROOM 1	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	STAFF WOMEN'S RESTROOM	F	*	S
	STAFF MEN'S RESTROOM	F	*	
	NURSE'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM 4	F	*	
	GIRL'S RESTROOM 7	F	*	
	BOY'S RESTROOM 7	F	*	
	STAFF MEN'S RESTROOM 4	F	*	
	GIRL'S RESTROOM 6	F	*	
	BOY'S RESTROOM 6	F	*	
	BOY'S RESTROOM 5	F	*	
	GIRL'S RESTROOM 5	F	*	
	STAFF WOMEN'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 3	F	*	
	GIRL'S RESTROOM 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	BOY'S RESTROOM 4	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	
	STAFF WOMEN'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	STAFF WOMEN'S RESTROOM	F	*	S
	STAFF MEN'S RESTROOM	F	*	
	NURSE'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM 4	F	*	
	GIRL'S RESTROOM 7	F	*	
	BOY'S RESTROOM 7	F	*	
	STAFF MEN'S RESTROOM 4	F	*	
	GIRL'S RESTROOM 6	F	*	
	BOY'S RESTROOM 6	F	*	
	BOY'S RESTROOM 5	F	*	
	GIRL'S RESTROOM 5	F	*	
	STAFF WOMEN'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 3	F	*	
	GIRL'S RESTROOM 4	F	*	
	BOY'S RESTROOM 4	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	STAFF WOMEN'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
	STAFF MEN'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY 01	C, W	N, E, W, S	S
	LOBBY 05	C, W	N, E, W, S	
	ELECTRICAL 3	C	*	
	LOBBY 02	C, W	N, E, W, S	
	LOBBY 03	C, W	N, E, W, S	
	ELECTRICAL 2	C	*	
	LOBBY 04	C, W	N, E, W, S	
	ELECTRICAL 1	C	*	
	CORRIDOR 01	W	N, E, W, S	
	CORRIDOR 02	C, W	N, E, W, S	
	CORRIDOR 03	W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
	CORRIDOR 05	C, W	N, E, W, S	
	CORRIDOR 06	W	N, E, W, S	
	CORRIDOR 07	W	N, E, W, S	
	CORRIDOR 08	C, W	N, E, W, S	
	CORRIDOR 09	W	N, E, W, S	
	CORRIDOR 10	C, W	N, E, W, S	
	CORRIDOR 11	W	N, E, W, S	
	CORRIDOR 12	W	N, E, W, S	
	CORRIDOR 13	C, W	N, E, W, S	
	CORRIDOR 14	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	CORRIDOR 16	C, W	N, E, W, S	
	CORRIDOR 17	W	N, E, W, S	
	CORRIDOR 18	W	N, E, W, S	
	CORRIDOR 19	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY 01	C, W	N, E, W, S	S
	LOBBY 05	C, W	N, E, W, S	
	ELECTRICAL 3	C	*	
	LOBBY 02	C, W	N, E, W, S	
	LOBBY 03	C, W	N, E, W, S	
	ELECTRICAL 2	C	*	
	LOBBY 04	C, W	N, E, W, S	
	ELECTRICAL 1	C	*	
	CORRIDOR 01	W	N, E, W, S	
	CORRIDOR 02	C, W	N, E, W, S	
	CORRIDOR 03	W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
	CORRIDOR 05	C, W	N, E, W, S	
	CORRIDOR 06	W	N, E, W, S	
	CORRIDOR 07	W	N, E, W, S	
	CORRIDOR 08	C, W	N, E, W, S	
	CORRIDOR 09	W	N, E, W, S	
	CORRIDOR 10	C, W	N, E, W, S	
	CORRIDOR 11	W	N, E, W, S	
	CORRIDOR 12	W	N, E, W, S	
	CORRIDOR 13	C, W	N, E, W, S	
	CORRIDOR 14	W	N, E, W, S	
	CORRIDOR 16	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CORRIDOR 17	W	N, E, W, S	
	CORRIDOR 18	W	N, E, W, S	
	CORRIDOR 19	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY 01	C, W	N, E, W, S	S
	LOBBY 05	C, W	N, E, W, S	
	ELECTRICAL 3	C	*	
	LOBBY 02	C, W	N, E, W, S	
	LOBBY 03	C, W	N, E, W, S	
	ELECTRICAL 2	C	*	
	LOBBY 04	C, W	N, E, W, S	
	ELECTRICAL 1	C	*	
	CORRIDOR 01	W	N, E, W, S	
	CORRIDOR 02	C, W	N, E, W, S	
	CORRIDOR 03	W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
	CORRIDOR 05	C, W	N, E, W, S	
	CORRIDOR 06	W	N, E, W, S	
	CORRIDOR 07	W	N, E, W, S	
	CORRIDOR 08	C, W	N, E, W, S	
	CORRIDOR 09	W	N, E, W, S	
	CORRIDOR 10	C, W	N, E, W, S	
	CORRIDOR 11	W	N, E, W, S	
	CORRIDOR 12	W	N, E, W, S	
	CORRIDOR 13	C, W	N, E, W, S	
	CORRIDOR 14	W	N, E, W, S	
	CORRIDOR 16	C, W	N, E, W, S	
	CORRIDOR 17	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR 18	W	N, E, W, S	
	CORRIDOR 19	W	N, E, W, S	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	ELECTRICAL 3	O	N, E, W, S	S
	ELECTRICAL 2	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	CORRIDOR 08	O	W, S	
	CORRIDOR 09	O	E	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	ELECTRICAL 3	O	N, E, W, S	S
	ELECTRICAL 2	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	CORRIDOR 08	O	W, S	
	CORRIDOR 09	O	E	
QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	JANITOR 3	F	*	S
	JANITOR 2	F	*	
	JANITOR 1	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	JANITOR 3	F	*	S
	JANITOR 2	F	*	
	JANITOR 1	F	*	
VINYL COMPOSITION TILE, 18"X18", GRAY, TEXTURED, CIRCLE PATTERN	LOBBY 02	F	*	S
	CORRIDOR 01	F	*	
	CORRIDOR 06	F	*	
	CORRIDOR 11	F	*	
	CORRIDOR 12	F	*	
MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 18"X18", GRAY, TEXTURED, CIRCLE PATTERN	LOBBY 02	F	*	S
	CORRIDOR 01	F	*	
	CORRIDOR 06	F	*	
	CORRIDOR 11	F	*	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CORRIDOR 12	F	*	
WALLBASE (COVERED), 4", GREEN, VINYL-LIKE	OFFICE 1	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GREEN, VINYL-LIKE	OFFICE 1	O	N, E, W, S	S
TACKABLE WALL PANEL (MOVEABLE), BROWN, FIBROUS, VINYL COVER	SPECIAL ED 117	W	E	S
	SPECIAL ED 118	W	W	
	SPECIAL ED 217	W	S	
	SPECIAL ED 218	W	N	
	SPECIAL ED 317	W	W	
	SPECIAL ED 318	W	E	
SEALANT (DUCT), DARK GRAY, PLIABLE	SECRETARY/RECEPTION	O	*	S
	OFFICE 1	O	*	
	OFFICE 2	O	*	
	OFFICE 3	O	*	
	OFFICE 4	O	*	
	STUDENT SERVICES	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	ELECTRICAL 4	O	*	
	OFFICE 5	O	*	
	OFFICE 6	O	*	
	CONFERENCE ROOM	O	*	
	OFFICE 7	O	*	
	OFFICE 8	O	*	
	STAFF MEN'S RESTROOM	O	*	
	BREAK	O	*	
	NURSE RESTROOM	O	*	
	TEST	O	*	
	COTS	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	COTS CLOSET	O	*	
	TREATMENT	O	*	
	PRINCIPAL	O	*	
	WAIT	O	*	
	NURSE'S OFFICE	O	*	
	CLASSROOM 100	O	*	
	CLASSROOM 101	O	*	
	CLASSROOM 102	O	*	
	CLASSROOM 103	O	*	
	CLASSROOM 104	O	*	
	CLASSROOM 105	O	*	
	CLASSROOM 106	O	*	
	SCIENCE CLASSROOM 107	O	*	
	STORAGE 09	O	*	
	STAFF LOUNGE 04	O	*	
	SCIENCE CLASSROOM 108	O	*	
	CLASSROOM 109	O	*	
	CLASSROOM 110	O	*	
	CLASSROOM 111	O	*	
	BOY'S RESTROOM 5	O	*	
	STORAGE 07	O	*	
	STORAGE 08	O	*	
	LOBBY 04	O	*	
	CLASSROOM 112	O	*	
	CLASSROOM 113	O	*	
	CLASSROOM 114	O	*	
	CLASSROOM 115	O	*	
	LOBBY 05	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	COMPUTER CLASSROOM 116	O	*	
	SPECIAL ED 117	O	*	
	SPECIAL ED 118	O	*	
	STAFF WOMEN'S RESTROOM 4	O	*	
	JANITOR 3	O	*	
	GIRL'S RESTROOM 7	O	*	
	BOY'S RESTROOM 7	O	*	
	STAFF MEN'S RESTROOM 4	O	*	
	ELECTRICAL 3	O	*	
	GIRL'S RESTROOM 6	O	*	
	BOY'S RESTROOM 6	O	*	
	CLASSROOM 200	O	*	
	CLASSROOM 201	O	*	
	CLASSROOM 202	O	*	
	CLASSROOM 203	O	*	
	GIRL'S RESTROOM 5	O	*	
	CLASSROOM 204	O	*	
	CLASSROOM 205	O	*	
	CLASSROOM 206	O	*	
	SCIENCE CLASSROOM 207	O	*	
	STORAGE 06	O	*	
	STAFF LOUNGE 03	O	*	
	STORAGE 05	O	*	
	SCIENCE CLASSROOM 208	O	*	
	CLASSROOM 209	O	*	
	CLASSROOM 210	O	*	
	STORAGE 04	O	*	
	STAFF WOMEN'S RESTROOM 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF LOUNGE 02	O	*	
	STAFF MEN'S RESTROOM 2	O	*	
	STORAGE 03	O	*	
	STORAGE 02	O	*	
	LOBBY 02	O	*	
	CLASSROOM 211	O	*	
	CLASSROOM 212	O	*	
	CLASSROOM 213	O	*	
	CLASSROOM 214	O	*	
	CLASSROOM 215	O	*	
	LOBBY 03	O	*	
	COMPUTER CLASSROOM 216	O	*	
	SPECIAL ED 217	O	*	
	SPECIAL ED 218	O	*	
	STAFF MEN'S RESTROOM 3	O	*	
	JANITOR 2	O	*	
	GIRL'S RESTROOM 4	O	*	
	BOY'S RESTROOM 4	O	*	
	STAFF WOMEN'S RESTROOM 3	O	*	
	ELECTRICAL 2	O	*	
	GIRL'S RESTROOM 3	O	*	
	BOY'S RESTROOM 3	O	*	
	CLASSROOM 300	O	*	
	CLASSROOM 301	O	*	
	CLASSROOM 302	O	*	
	CLASSROOM 303	O	*	
	CLASSROOM 304	O	*	
	CLASSROOM 305	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CLASSROOM 306	O	*	
	SCIENCE CLASSROOM 307	O	*	
	STORAGE 01	O	*	
	STAFF LOUNGE 01	O	*	
	SCIENCE CLASSROOM 308	O	*	
	CLASSROOM 309	O	*	
	CLASSROOM 310	O	*	
	CLASSROOM 311	O	*	
	CLASSROOM 312	O	*	
	CLASSROOM 313	O	*	
	CLASSROOM 314	O	*	
	CLASSROOM 315	O	*	
	LOBBY 01	O	*	
	COMPUTER CLASSROOM 316	O	*	
	SPECIAL ED 317	O	*	
	SPECIAL ED 318	O	*	
	STAFF WOMEN'S RESTROOM 1	O	*	
	JANITOR 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	STAFF MEN'S RESTROOM 1	O	*	
	ELECTRICAL 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	CORRIDOR 01	O	*	
	CORRIDOR 02	O	*	
	CORRIDOR 03	O	*	
	CORRIDOR 04	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	CORRIDOR 05	O	*	
	CORRIDOR 06	O	*	
	CORRIDOR 07	O	*	
	CORRIDOR 08	O	*	
	CORRIDOR 09	O	*	
	CORRIDOR 10	O	*	
	CORRIDOR 11	O	*	
	CORRIDOR 12	O	*	
	CORRIDOR 13	O	*	
	CORRIDOR 14	O	*	
	CORRIDOR 15	O	*	
	CORRIDOR 16	O	*	
	CORRIDOR 17	O	*	
	CORRIDOR 18	O	*	
	CORRIDOR 19	O	*	
	CORRIDOR 20	O	*	
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	STAFF WOMEN'S RESTROOM	W	N, E, W, S	S
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	NURSE'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 7	W	N, E, W, S	
	BOY'S RESTROOM 7	W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 4	W	N, E, W, S	
	BOY'S RESTROOM 4	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	BOY'S RESTROOM 1	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	STAFF WOMEN'S RESTROOM	W	N, E, W, S	S
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	NURSE'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 7	W	N, E, W, S	
	BOY'S RESTROOM 7	W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 4	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	BOY'S RESTROOM 4	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	BOY'S RESTROOM 1	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	STAFF WOMEN'S RESTROOM	W	N, E, W, S	S
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	NURSE'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 7	W	N, E, W, S	
	BOY'S RESTROOM 7	W	N, E, W, S	
	STAFF MEN'S RESTROOM 4	W	N, E, W, S	
	GIRL'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 6	W	N, E, W, S	
	BOY'S RESTROOM 5	W	N, E, W, S	
	GIRL'S RESTROOM 5	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 4	W	N, E, W, S	
	BOY'S RESTROOM 4	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 3	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Main Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	BOY'S RESTROOM 3	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	STAFF MEN'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	BOY'S RESTROOM 1	W	N, E, W, S	

\* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHING), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
SEALANT (DOORS, WINDOWS, FLASHINGS), WHITE, PLIABLE	CHILD DEV SERVICE YARD	O	N, E, W, S	S
	TECH SERVICE YARD	O	N, E, W, S	
	EXTERIOR STORAGE	O	N, E, W, S	
	ART STORAGE 01	O	N, E, W, S	
	ART SERVICE YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	N, E, W, S	
CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH	CHILD DEV SERVICE YARD	O	N, E, W, S	S
	TECH SERVICE YARD	O	N, E, W, S	
	EXTERIOR STORAGE	O	N, E, W, S	
	ART STORAGE 01	O	N, E, W, S	
	ART SERVICE YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	N, E, W, S	
CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH	CHILD DEV SERVICE YARD	O	N, E, W, S	S
	TECH SERVICE YARD	O	N, E, W, S	
	EXTERIOR STORAGE	O	N, E, W, S	
	ART STORAGE 01	O	N, E, W, S	
	ART SERVICE YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	N, E, W, S	
CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS	CHILD DEV SERVICE YARD	O	N, E, W, S	S
	TECH SERVICE YARD	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	EXTERIOR STORAGE	O	N, E, W, S	
	ART STORAGE 01	O	N, E, W, S	
	ART SERVICE YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16" PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH, AND CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS	CHILD DEV SERVICE YARD	O	N, E, W, S	S
	TECH SERVICE YARD	O	N, E, W, S	
	EXTERIOR STORAGE	O	N, E, W, S	
	ART STORAGE 01	O	N, E, W, S	
	ART SERVICE YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	N, E, W, S	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	CHILD DEV SERVICE YARD	F	*	S
	TECH SERVICE YARD	F	*	
	EXTERIOR STORAGE	F	*	
	ART STORAGE 01	F	*	
	ART SERVICE YARD	F	*	
	EXTERIOR	F	*	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LIBRARY	F	*	S
	BREAK OUT 01	F	*	
	BREAK OUT 02	F	*	
	LIBRARY STORAGE 02	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	BREAK OUT 03	F	*	
	BREAK OUT 04	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BREAK OUT 05	F	*	
	BREAK OUT 06	F	*	
	WORK ROOM	F	*	
	LIBRARY STORAGE 01	F	*	
	STAFF LOUNGE	F	*	
	N.W. STORAGE	F	*	
	ELECTRICAL 2	F	*	
	WORK ROOM 426	F	*	
	T.O.	F	*	
	UNISEX RESTROOM	F	*	
	STAFF RESTROOM	F	*	
	426 STORAGE	F	*	
	LIBRARY STORAGE 03	F	*	
	MULTI MEDIA	F	*	
	RECEIVING STORAGE	F	*	
	RECEIVING	F	*	
	CONFERENCE	F	*	
	CADD CLASSROOM	F	*	
	FOOD CHILD DEV LAB	F	*	
	FOOD STORAGE	F	*	
	CART STORAGE	F	*	
	H.E. RESTROOM	F	*	
	W/D	F	*	
	ROOM 429	F	*	
	429 STORAGE	F	*	
	DARK ROOM	F	*	
	424 ART	F	*	
	ART STORAGE 03	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	ELECTRICAL 1	F	*	
	ART STORAGE 02	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
	EXTERIOR	F	*	
CONCRETE (COLUMNS), GRAY, CEMENTITIOUS	EXTERIOR	O	N, E, W, S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LIBRARY	O	N, E, W	S
	MEN'S RESTROOM	O	N	
	WOMEN'S RESTROOM	O	N	
	BREAK OUT 03	O	W, S	
	STAFF LOUNGE	O	N, E, S	
	N.W. STORAGE	O	N	
	ELECTRICAL 2	O	S	
	WORK ROOM 426	O	N, W, S	
	UNISEX RESTROOM	O	N	
	STAFF RESTROOM	O	N	
	426 STORAGE	O	E	
	RECEIVING STORAGE	O	W	
	RECEIVING	O	W	
	CONFERENCE	O	N	
	CADD CLASSROOM	O	N, S	
	FOOD CHILD DEV LAB	O	N, W, S	
	CHILD DEV SERVICE YARD	O	S	
	H.E. RESTROOM	O	E	
	ROOM 429	O	N, E, S	
	TECH SERVICE YARD	O	W, S	
	EXTERIOR STORAGE	O	E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	429 STORAGE	O	N, E	
	424 ART	O	N, S	
	ART STORAGE 01	O	W	
	ART SERVICE YARD	O	E, S	
	CORRIDOR 01	O	N, E; W; S	
	CORRIDOR 02	O	E, W	
GLASS BLOCK, 8"X8", CLEAR	LIBRARY	W	N, E, S	N
	CORRIDOR 01	W	E, W	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	LIBRARY	W	N, E, S	S
	CORRIDOR 01	W	E, W	
	EXTERIOR	W	E, W, S	
SEALANT (WINDOWS), BLACK, GUMMY	LIBRARY	O	N, E	S
	EXTERIOR	O	E, W, S	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	BREAK OUT 01	C	*	S
	BREAK OUT 02	C	*	
	BREAK OUT 03	C	*	
	BREAK OUT 04	C	*	
	BREAK OUT 05	C	*	
	BREAK OUT 06	C	*	
	WORK ROOM	C	*	
	LIBRARY STORAGE 01	C	*	
	STAFF LOUNGE	C	*	
	ELECTRICAL 2	C	*	
	WORK ROOM 426	C	*	
	426 STORAGE	C	*	
	LIBRARY STORAGE 03	C	*	
	MULTI MEDIA	C	*	
	RECEIVING STORAGE	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	RECEIVING	C	*	
	CONFERENCE	C	*	
	CADD CLASSROOM	C	*	
	FOOD CHILD DEV LAB	C	*	
	424 ART	C	*	
	CORRIDOR 01	C	*	
	CORRIDOR 02	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LIBRARY	C, W	N, E, W, S	S
	BREAK OUT 01	W	N, E, W, S	
	BREAK OUT 02	W	N, E, W, S	
	LIBRARY STORAGE 02	C, W	N, E, W, S	
	BREAK OUT 03	W	N, E, W, S	
	BREAK OUT 04	W	N, E, W, S	
	BREAK OUT 05	W	N, E, W, S	
	BREAK OUT 06	W	N, E, W, S	
	WORK ROOM	W	N, E, W, S	
	LIBRARY STORAGE 01	W	N, E, W, S	
	STAFF LOUNGE	W	N, E, W, S	
	N.W. STORAGE	C, W	N, E, W, S	
	WORK ROOM 426	W	N, E, W, S	
	T.O.	C, W	N, E, W, S	
	426 STORAGE	W	N, E, W, S	
	LIBRARY STORAGE 03	W	N, E, W, S	
	MULTI MEDIA	W	N, E, W, S	
	RECEIVING STORAGE	W	N, E, W, S	
	RECEIVING	W	N, E, W, S	
	CONFERENCE	W	N, E, W, S	
	CADD CLASSROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	FOOD CHILD DEV LAB	W	N, E, W, S	
	FOOD STORAGE	C, W	N, E, W, S	
	CART STORAGE	C, W	N, E, W, S	
	ROOM 429	W	N, E, W, S	
	429 STORAGE	C, W	N, E, W, S	
	DARK ROOM	C, W	N, E, W, S	
	424 ART	W	N, E, W, S	
	ART STORAGE 03	C, W	N, E, W, S	
	ART STORAGE 02	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LIBRARY	C, W	N, E, W, S	S
	BREAK OUT 01	W	N, E, W, S	
	BREAK OUT 02	W	N, E, W, S	
	LIBRARY STORAGE 02	C, W	N, E, W, S	
	BREAK OUT 03	W	N, E, W, S	
	BREAK OUT 04	W	N, E, W, S	
	BREAK OUT 05	W	N, E, W, S	
	BREAK OUT 06	W	N, E, W, S	
	WORK ROOM	W	N, E, W, S	
	LIBRARY STORAGE 01	W	N, E, W, S	
	STAFF LOUNGE	W	N, E, W, S	
	N.W. STORAGE	C, W	N, E, W, S	
	WORK ROOM 426	W	N, E, W, S	
	T.O.	C, W	N, E, W, S	
	426 STORAGE	W	N, E, W, S	
	LIBRARY STORAGE 03	W	N, E, W, S	
	MULTI MEDIA	W	N, E, W, S	
	RECEIVING STORAGE	W	N, E, W, S	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	RECEIVING	W	N, E, W, S	
	CONFERENCE	W	N, E, W, S	
	CADD CLASSROOM	W	N, E, W, S	
	FOOD CHILD DEV LAB	W	N, E, W, S	
	FOOD STORAGE	C, W	N, E, W, S	
	CART STORAGE	C, W	N, E, W, S	
	ROOM 429	W	N, E, W, S	
	429 STORAGE	C, W	N, E, W, S	
	DARK ROOM	C, W	N, E, W, S	
	424 ART	W	N, E, W, S	
	ART STORAGE 03	C, W	N, E, W, S	
	ART STORAGE 02	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LIBRARY	C, W	N, E, W, S	S
	BREAK OUT 01	W	N, E, W, S	
	BREAK OUT 02	W	N, E, W, S	
	LIBRARY STORAGE 02	C, W	N, E, W, S	
	BREAK OUT 03	W	N, E, W, S	
	BREAK OUT 04	W	N, E, W, S	
	BREAK OUT 05	W	N, E, W, S	
	BREAK OUT 06	W	N, E, W, S	
	WORK ROOM	W	N, E, W, S	
	LIBRARY STORAGE 01	W	N, E, W, S	
	STAFF LOUNGE	W	N, E, W, S	
	N.W. STORAGE	C, W	N, E, W, S	
	WORK ROOM 426	W	N, E, W, S	
	T.O.	C, W	N, E, W, S	
	426 STORAGE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	LIBRARY STORAGE 03	W	N, E, W, S	
	MULTI MEDIA	W	N, E, W, S	
	RECEIVING STORAGE	W	N, E, W, S	
	RECEIVING	W	N, E, W, S	
	CONFERENCE	W	N, E, W, S	
	CADD CLASSROOM	W	N, E, W, S	
	FOOD CHILD DEV LAB	W	N, E, W, S	
	FOOD STORAGE	C, W	N, E, W, S	
	CART STORAGE	C, W	N, E, W, S	
	ROOM 429	W	N, E, W, S	
	429 STORAGE	C, W	N, E, W, S	
	DARK ROOM	C, W	N, E, W, S	
	424 ART	W	N, E, W, S	
	ART STORAGE 03	C, W	N, E, W, S	
	ART STORAGE 02	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	LIBRARY	W	N, E, W	S
	CONFERENCE	W	W	
	FOOD CHILD DEV LAB	W	E, W, S	
	424 ART	W	N, E, S	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	WORK ROOM	F	*	S
	LIBRARY STORAGE 01	F	*	
	STAFF LOUNGE	F	*	
	WORK ROOM 426	F	*	
	T.O.	F	*	
	426 STORAGE	F	*	
	LIBRARY STORAGE 03	F	*	
	MULTI MEDIA	F	*	
	FOOD CHILD DEV LAB	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	FOOD STORAGE	F	*	
	CART STORAGE	F	*	
	W/D	F	*	
	429 STORAGE	F	*	
	DARK ROOM	F	*	
	424 ART	F	*	
	ART STORAGE 03	F	*	
	ART STORAGE 02	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	WORK ROOM	F	*	S
	LIBRARY STORAGE 01	F	*	
	STAFF LOUNGE	F	*	
	WORK ROOM 426	F	*	
	T.O.	F	*	
	426 STORAGE	F	*	
	LIBRARY STORAGE 03	F	*	
	MULTI MEDIA	F	*	
	FOOD CHILD DEV LAB	F	*	
	FOOD STORAGE	F	*	
	CART STORAGE	F	*	
	W/D	F	*	
	429 STORAGE	F	*	
	DARK ROOM	F	*	
	424 ART	F	*	
	ART STORAGE 03	F	*	
	ART STORAGE 02	F	*	
WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	LIBRARY	O	N, E, W, S	S
	BREAK OUT 01	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	BREAK OUT 02	O	N, E, W, S	
	LIBRARY STORAGE 02	O	N, E, W, S	
	BREAK OUT 03	O	N, E, W, S	
	BREAK OUT 04	O	N, E, W, S	
	BREAK OUT 05	O	N, E, W, S	
	BREAK OUT 06	O	N, E, W, S	
	WORK ROOM	O	N, E, W, S	
	LIBRARY STORAGE 01	O	N, E, W, S	
	STAFF LOUNGE	O	N, E, W, S	
	N.W. STORAGE	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
	426 STORAGE	O	N, E, W, S	
	LIBRARY STORAGE 03	O	N, E, W, S	
	MULTI MEDIA	O	N, E, W, S	
	RECEIVING STORAGE	O	N, E, W, S	
	RECEIVING	O	N, E, W, S	
	CONFERENCE	O	N, E, W, S	
	CADD CLASSROOM	O	N, E, W, S	
	FOOD CHILD DEV LAB	O	N, E, W, S	
	FOOD STORAGE	O	N, E, W, S	
	CART STORAGE	O	N, E, W, S	
	W/D	O	N, E, W, S	
	ROOM 429	O	N, E, W, S	
	429 STORAGE	O	N, E, W, S	
	DARK ROOM	O	N, E, W, S	
	424 ART	O	N, E, W, S	
	ART STORAGE 03	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Media Center Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ART STORAGE 02	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	LIBRARY	O	N, E, W, S	S
	BREAK OUT 01	O	N, E, W, S	
	BREAK OUT 02	O	N, E, W, S	
	LIBRARY STORAGE 02	O	N, E, W, S	
	BREAK OUT 03	O	N, E, W, S	
	BREAK OUT 04	O	N, E, W, S	
	BREAK OUT 05	O	N, E, W, S	
	BREAK OUT 06	O	N, E, W, S	
	WORK ROOM	O	N, E, W, S	
	LIBRARY STORAGE 01	O	N, E, W, S	
	STAFF LOUNGE	O	N, E, W, S	
	N.W. STORAGE	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
	426 STORAGE	O	N, E, W, S	
	LIBRARY STORAGE 03	O	N, E, W, S	
	MULTI MEDIA	O	N, E, W, S	
	RECEIVING STORAGE	O	N, E, W, S	
	RECEIVING	O	N, E, W, S	
	CONFERENCE	O	N, E, W, S	
	CADD CLASSROOM	O	N, E, W, S	
	FOOD CHILD DEV LAB	O	N, E, W, S	
	FOOD STORAGE	O	N, E, W, S	
	CART STORAGE	O	N, E, W, S	
	W/D	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	ROOM 429	O	N, E, W, S	
	429 STORAGE	O	N, E, W, S	
	DARK ROOM	O	N, E, W, S	
	424 ART	O	N, E, W, S	
	ART STORAGE 03	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	ART STORAGE 02	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	LIBRARY	O	N, E, W, S	S
	BREAK OUT 01	O	N, W	
	BREAK OUT 02	O	N	
	BREAK OUT 03	O	E, W, S	
	BREAK OUT 04	O	E	
	BREAK OUT 05	O	E	
	BREAK OUT 06	O	E, S	
	WORK ROOM	O	N, E, W	
	LIBRARY STORAGE 01	O	W, S	
	STAFF LOUNGE	O	N, E, W, S	
	N.W. STORAGE	O	N	
	ELECTRICAL 2	O	S	
	WORK ROOM 426	O	N, E, W, S	
	T.O.	O	N	
	UNISEX RESTROOM	O	N, W	
	STAFF RESTROOM	O	E	
	426 STORAGE	O	E	
	LIBRARY STORAGE 03	O	W	
	MULTI MEDIA	O	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	RECEIVING STORAGE	O	N, W	
	RECEIVING	O	E, W, S	
	CONFERENCE	O	N, S	
	CADD CLASSROOM	O	N, W	
	FOOD CHILD DEV LAB	O	N, E, W, S	
	FOOD STORAGE	O	W	
	CART STORAGE	O	E, W	
	H.E. RESTROOM	O	E, W	
	W/D	O	E	
	ROOM 429	O	N, W, S	
	429 STORAGE	O	N, E	
	DARK ROOM	O	E	
	424 ART	O	N, E, W, S	
	ART STORAGE 03	O	S	
	ELECTRICAL 1	O	W	
	ART STORAGE 02	O	S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	E, W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL 2	W	N, E, W, S	S
	ELECTRICAL 1	C, W	N, E, W, S	
	CORRIDOR 02	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL 2	W	N, E, W, S	S
	ELECTRICAL 1	C, W	N, E, W, S	
	CORRIDOR 02	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ELECTRICAL 2	W	N, E, W, S	S
	ELECTRICAL 1	C, W	N, E, W, S	
	CORRIDOR 02	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM	C, W	N, E, W, S	S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	UNISEX RESTROOM	C, W	N, E, W, S	
	STAFF RESTROOM	C, W	N, E, W, S	
	H.E. RESTROOM	C, W	N, E, W, S	
	W/D	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM	C, W	N, E, W, S	S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	UNISEX RESTROOM	C, W	N, E, W, S	
	STAFF RESTROOM	C, W	N, E, W, S	
	H.E. RESTROOM	C, W	N, E, W, S	
	W/D	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM	C, W	N, E, W, S	S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	UNISEX RESTROOM	C, W	N, E, W, S	
	STAFF RESTROOM	C, W	N, E, W, S	
	H.E. RESTROOM	C, W	N, E, W, S	
	W/D	C, W	N, E, W, S	
SINK ACOUSTICAL COATING, GRAY, ROUGH	STAFF LOUNGE	O	W	
	WORK ROOM 426	O	E, W	
	MULTI MEDIA	O	E	
	RECEIVING	O	E	
	CONFERENCE	O	S	
	424 ART	O	W	
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	LIBRARY	O	*	S
	BREAK OUT 01	O	*	
	BREAK OUT 02	O	*	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	LIBRARY STORAGE 02	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	BREAK OUT 03	O	*	
	BREAK OUT 04	O	*	
	BREAK OUT 05	O	*	
	BREAK OUT 06	O	*	
	WORK ROOM	O	*	
	LIBRARY STORAGE 01	O	*	
	STAFF LOUNGE	O	*	
	N.W. STORAGE	O	*	
	ELECTRICAL 2	O	*	
	WORK ROOM 426	O	*	
	T.O.	O	*	
	UNISEX RESTROOM	O	*	
	STAFF RESTROOM	O	*	
	426 STORAGE	O	*	
	LIBRARY STORAGE 03	O	*	
	MULTI MEDIA	O	*	
	RECEIVING STORAGE	O	*	
	RECEIVING	O	*	
	CONFERENCE	O	*	
	CADD CLASSROOM	O	*	
	FOOD CHILD DEV LAB	O	*	
	FOOD STORAGE	O	*	
	CART STORAGE	O	*	
	H.E. RESTROOM	O	*	
	W/D	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	ROOM 429	O	*	
	429 STORAGE	O	*	
	DARK ROOM	O	*	
	424 ART	O	*	
	ART STORAGE 03	O	*	
	ELECTRICAL 1	O	*	
	ART STORAGE 02	O	*	
	CORRIDOR 01	O	*	
	CORRIDOR 02	O	*	
CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	LIBRARY	F	*	S
	BREAK OUT 01	F	*	
	BREAK OUT 02	F	*	
	LIBRARY STORAGE 02	F	*	
	BREAK OUT 03	F	*	
	BREAK OUT 04	F	*	
	BREAK OUT 05	F	*	
	BREAK OUT 06	F	*	
	STAFF LOUNGE	F	*	
	WORK ROOM 426	F	*	
	CONFERENCE	F	*	
	CADD CLASSROOM	F	*	
	FOOD CHILD DEV LAB	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STAFF RESTROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	H.E. RESTROOM	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STAFF RESTROOM	W	N, E, W, S	
	H.E. RESTROOM	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
	UNISEX RESTROOM	F	*	
	STAFF RESTROOM	F	*	
	H.E. RESTROOM	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
	UNISEX RESTROOM	F	*	
	STAFF RESTROOM	F	*	
	H.E. RESTROOM	F	*	
ACOUSTICAL CEILING PANEL, 2'X2', YELLOW, FIBROUS GLASS, CLOTH COVER	LIBRARY	C	*	S
TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER	BREAK OUT 03	W	N	S
	BREAK OUT 04	W	S	
SEALANT (DUCT), GRAY, PLIABLE	LIBRARY	O	*	S
	BREAK OUT 01	O	*	
	BREAK OUT 02	O	*	
	LIBRARY STORAGE 02	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	BREAK OUT 03	O	*	
	BREAK OUT 04	O	*	
	BREAK OUT 05	O	*	
	BREAK OUT 06	O	*	
	WORK ROOM	O	*	
	LIBRARY STORAGE 01	O	*	
	STAFF LOUNGE	O	*	
	N.W. STORAGE	O	*	
	ELECTRICAL 2	O	*	
	WORK ROOM 426	O	*	
	T.O.	O	*	
	UNISEX RESTROOM	O	*	
	STAFF RESTROOM	O	*	
	426 STORAGE	O	*	
	LIBRARY STORAGE 03	O	*	
	MULTI MEDIA	O	*	
	RECEIVING STORAGE	O	*	
	RECEIVING	O	*	
	CONFERENCE	O	*	
	CADD CLASSROOM	O	*	
	FOOD CHILD DEV LAB	O	*	
	FOOD STORAGE	O	*	
	CART STORAGE	O	*	
	H.E. RESTROOM	O	*	
	W/D	O	*	
	ROOM 429	O	*	
	429 STORAGE	O	*	
	DARK ROOM	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	424 ART	O	*	
	ART STORAGE 03	O	*	
	ELECTRICAL 1	O	*	
	ART STORAGE 02	O	*	
	CORRIDOR 01	O	*	
	CORRIDOR 02	O	*	
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STAFF RESTROOM	W	N, E, W, S	
	H.E. RESTROOM	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STAFF RESTROOM	W	N, E, W, S	
	H.E. RESTROOM	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
	UNISEX RESTROOM	W	N, E, W, S	
	STAFF RESTROOM	W	N, E, W, S	
	H.E. RESTROOM	W	N, E, W, S	

\* - Not Applicable

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
SEALANT (DOORS, WINDOWS, WALLS), WHITE, PLIABLE	LOBBY	O	N, E, W, S	S
	GYMNASIUM	O	N, E, W, S	
	MECHANICAL OFFICE	O	N, E, W, S	
	KITCHEN SERVICE YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	*	
CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH	LOBBY	W	N, E, W, S	S
	GYMNASIUM	W	N, E, W, S	
	MECHANICAL OFFICE	W	N, E, W, S	
	KITCHEN SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	*	
CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH	LOBBY	W	N, E, W, S	S
	GYMNASIUM	W	N, E, W, S	
	MECHANICAL OFFICE	W	N, E, W, S	
	KITCHEN SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	*	
CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, SMOOTH	LOBBY	W	N, E, W, S	S
	GYMNASIUM	W	N, E, W, S	
	MECHANICAL OFFICE	W	N, E, W, S	
	ELECTRICAL 03	W	N, E, W, S	
	WATER/HEATER ROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	KITCHEN SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	*	
CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, SMOOTH	LOBBY	W	N, E, W, S	S
	GYMNASIUM	W	N, E, W, S	
	MECHANICAL OFFICE	W	N, E, W, S	
	ELECTRICAL 03	W	N, E, W, S	
	WATER/HEATER ROOM	W	N, E, W, S	
	KITCHEN SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	*	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT (PATTERN), 12"X12", GRAY, CEMENTITIOUS	LOBBY	W	N, E, W, S	S
	GYMNASIUM	W	N, E, W, S	
	MECHANICAL OFFICE	W	N, E, W, S	
	ELECTRICAL 03	W	N, E, W, S	
	WATER/HEATER ROOM	W	N, E, W, S	
	KITCHEN SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	*	
SEALANT (DUCT), GRAY, PLIABLE	ROOF	O	*	S
SEALANT (DUCT), WHITE, PLIABLE	ROOF	O	*	S
PIPE END SEALANT, GRAY, PLIABLE	ROOF	O	*	S
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	ROOF	O	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP, SILVER	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	N, E, W, S	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LOBBY	F	*	S
	STRINGS 401	F	*	
	GYMNASIUM	F	*	
	GYM STORAGE	F	*	
	BOY'S LOCKERS 01	F	*	
	BOY'S STORAGE	F	*	
	BOY'S SHOWER	F	*	
	BOY'S RESTROOM 02	F	*	
	BOY'S LOCKERS 02	F	*	
	BOY'S COACH OFFICE	F	*	
	BOY'S COACH RESTROOM	F	*	
	ELECTRICAL 03	F	*	
	WATER/HEATER ROOM	F	*	
	P.E. STORAGE	F	*	
	JANITOR 01	F	*	
	GIRL'S LOCKERS 01	F	*	
	GIRL'S STORAGE	F	*	
	GIRL'S SHOWER	F	*	
	GIRL'S RESTROOM 02	F	*	
	GIRL'S LOCKERS 02	F	*	
	GIRL'S COACH OFFICE	F	*	
	GIRL'S COACH RESTROOM	F	*	
	BOY'S RESTROOM 01	F	*	
	GIRL'S RESTROOM 01	F	*	
	KITCHEN	F	*	
	SERVING AREA	F	*	
	ELECTRICAL 02	F	*	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	OFFICE 01	F	*	
	CHEMICAL ROOM	F	*	
	UNISEX RESTROOM 01	F	*	
	FOOD STORAGE	F	*	
	FREEZER 1	F	*	
	FREEZER 2	F	*	
	MULTI-PURPOSE	F	*	
	SNACK BAR	F	*	
	STAGE	F	*	
	DRESS 01	F	*	
	UNISEX RESTROOM 02	F	*	
	DRESS 02	F	*	
	SOUND ROOM	F	*	
	ELECTRICAL 01	F	*	
	BAND ROOM 353	F	*	
	GIRL'S RESTROOM	F	*	
	BOY'S RESTROOM	F	*	
	LIVING ROOM	F	*	
	KITCHEN	F	*	
	KITCHEN CLOSET	F	*	
	PANTRY	F	*	
	BEDROOM 1	F	*	
	BEDROOM 1 CLOSET	F	*	
	RESTROOM	F	*	
	MASTER BEDROOM	F	*	
	MASTER BATH	F	*	
	MASTER CLOSET	F	*	
	CORRIDOR 01	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR 02	F	*	
	CORRIDOR 03	F	*	
	CORRIDOR 04	F	*	
	CORRIDOR 05	F	*	
	CORRIDOR 06	F	*	
	CORRIDOR 07	F	*	
CONCRETE (COLUMNS), GRAY, CEMENTITIOUS	EXTERIOR	W	E, W, S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
GLASS BLOCK, 8"X8", CLEAR	MULTI-PURPOSE	W	W	N
	EXTERIOR	W	W	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	MULTI-PURPOSE	W	W	S
	EXTERIOR	W	W	
CONCRETE MASONRY UNIT (PATTERN), 12"X12", GRAY, CEMENTITIOUS	MECHANICAL 02	W	N	S
	EXTERIOR	W	N	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	LOBBY	C	*	S
	STRINGS 401	C	*	
	BOY'S STORAGE	C	*	
	BOY'S COACH OFFICE	C	*	
	P.E. STORAGE	C	*	
	GIRL'S STORAGE	C	*	
	GIRL'S COACH OFFICE	C	*	
	OFFICE 01	C	*	
	MULTI-PURPOSE	C	*	
	STAGE	C	*	
	BAND ROOM 353	C	*	
	CORRIDOR 01	C	*	
	CORRIDOR 02	C	*	
	CORRIDOR 05	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CORRIDOR 06	C	*	
	CORRIDOR 07	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STRINGS 401	W	N, E, W, S	S
	GYM STORAGE	W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	BOY'S LOCKERS 01	W	N, E, W, S	
	BOY'S STORAGE	W	N, E, W, S	
	BOY'S COACH OFFICE	W	N, E, W, S	
	GIRL'S STORAGE	W	N, E, W, S	
	GIRL'S COACH OFFICE	W	N, E, W, S	
	ELECTRICAL 02	C, W	N, E, W, S	
	OFFICE 01	W	N, E, W, S	
	FOOD STORAGE	C, W	N, E, W, S	
	MULTI-PURPOSE	C, W	N, E, W, S	
	STAGE	C, W	N, E, W, S	
	DRESS 01	C, W	N, E, W, S	
	DRESS 02	C, W	N, E, W, S	
	BAND ROOM 353	C, W	N, E, W, S	
	LIVING ROOM	C, W	N, E, W, S	
	KITCHEN	C, W	N, E, W, S	
	KITCHEN CLOSET	C, W	N, E, W, S	
	PANTRY	C, W	N, E, W, S	
	BEDROOM 1	C, W	N, E, W, S	
	BEDROOM 1 CLOSET	C, W	N, E, W, S	
	RESTROOM	C, W	N, E, W, S	
	MASTER BEDROOM	C, W	N, E, W, S	
	MASTER BATH	C, W	N, E, W, S	
	MASTER CLOSET	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STRINGS 401	W	N, E, W, S	S
	GYM STORAGE	W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	BOY'S LOCKERS 01	W	N, E, W, S	
	BOY'S STORAGE	W	N, E, W, S	
	BOY'S COACH OFFICE	W	N, E, W, S	
	GIRL'S STORAGE	W	N, E, W, S	
	GIRL'S COACH OFFICE	W	N, E, W, S	
	ELECTRICAL 02	C, W	N, E, W, S	
	OFFICE 01	W	N, E, W, S	
	FOOD STORAGE	C, W	N, E, W, S	
	MULTI-PURPOSE	C, W	N, E, W, S	
	STAGE	C, W	N, E, W, S	
	DRESS 01	C, W	N, E, W, S	
	DRESS 02	C, W	N, E, W, S	
	BAND ROOM 353	C, W	N, E, W, S	
	LIVING ROOM	C, W	N, E, W, S	
	KITCHEN	C, W	N, E, W, S	
	KITCHEN CLOSET	C, W	N, E, W, S	
	PANTRY	C, W	N, E, W, S	
	BEDROOM 1	C, W	N, E, W, S	
	BEDROOM 1 CLOSET	C, W	N, E, W, S	
	RESTROOM	C, W	N, E, W, S	
	MASTER BEDROOM	C, W	N, E, W, S	
	MASTER BATH	C, W	N, E, W, S	
	MASTER CLOSET	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STRINGS 401	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	GYM STORAGE	W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	BOY'S LOCKERS 01	W	N, E, W, S	
	BOY'S STORAGE	W	N, E, W, S	
	BOY'S COACH OFFICE	W	N, E, W, S	
	GIRL'S STORAGE	W	N, E, W, S	
	GIRL'S COACH OFFICE	W	N, E, W, S	
	ELECTRICAL 02	C, W	N, E, W, S	
	OFFICE 01	W	N, E, W, S	
	FOOD STORAGE	C, W	N, E, W, S	
	MULTI-PURPOSE	C, W	N, E, W, S	
	STAGE	C, W	N, E, W, S	
	DRESS 01	C, W	N, E, W, S	
	DRESS 02	C, W	N, E, W, S	
	BAND ROOM 353	C, W	N, E, W, S	
	LIVING ROOM	C, W	N, E, W, S	
	KITCHEN	C, W	N, E, W, S	
	KITCHEN CLOSET	C, W	N, E, W, S	
	PANTRY	C, W	N, E, W, S	
	BEDROOM 1	C, W	N, E, W, S	
	BEDROOM 1 CLOSET	C, W	N, E, W, S	
	RESTROOM	C, W	N, E, W, S	
	MASTER BEDROOM	C, W	N, E, W, S	
	MASTER BATH	C, W	N, E, W, S	
	MASTER CLOSET	C, W	N, E, W, S	
TACKABLE WALL PANEL, YELLOW, FIBROUS GLASS, CLOTH COVER	BAND ROOM 353	W	N, E, W, S	S
CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	LOBBY	F	*	S
	STRINGS 401	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	BOY'S STORAGE	F	*	
	BOY'S COACH OFFICE	F	*	
	GIRL'S COACH OFFICE	F	*	
	DRESS 01	F	*	
	DRESS 02	F	*	
	SOUND ROOM	F	*	
	BAND ROOM 353	F	*	
	CORRIDOR 01	F	*	
	CORRIDOR 02	F	*	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	LOBBY	O	N, E, W, S	S
	STRINGS 401	O	N, E, W, S	
	GYM STORAGE	O	N, E, W, S	
	P.E. STORAGE	O	N, E, W, S	
	JANITOR 01	O	N, E, W, S	
	BOY'S STORAGE	O	N, E, W, S	
	BOY'S COACH OFFICE	O	N, E, W, S	
	BOY'S COACH RESTROOM	O	N, E, W, S	
	GIRL'S STORAGE	O	N, E, W, S	
	GIRL'S COACH OFFICE	O	N, E, W, S	
	GIRL'S COACH RESTROOM	O	N, E, W, S	
	ELECTRICAL 02	O	N, E, W, S	
	OFFICE 01	O	N, E, W, S	
	CHEMICAL ROOM	O	N, E, W, S	
	FOOD STORAGE	O	N, E, W, S	
	MULTI-PURPOSE	O	N, E, W, S	
	STAGE	O	N, E, W, S	
	DRESS 01	O	N, E, W, S	
	DRESS 02	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	ELECTRICAL 01	O	N, E, W, S	
	BAND ROOM 353	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	
ADHESIVE, YELLOW, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	LOBBY	O	N, E, W, S	S
	STRINGS 401	O	N, E, W, S	
	GYM STORAGE	O	N, E, W, S	
	P.E. STORAGE	O	N, E, W, S	
	JANITOR 01	O	N, E, W, S	
	BOY'S STORAGE	O	N, E, W, S	
	BOY'S COACH OFFICE	O	N, E, W, S	
	BOY'S COACH RESTROOM	O	N, E, W, S	
	GIRL'S STORAGE	O	N, E, W, S	
	GIRL'S COACH OFFICE	O	N, E, W, S	
	GIRL'S COACH RESTROOM	O	N, E, W, S	
	ELECTRICAL 02	O	N, E, W, S	
	OFFICE 01	O	N, E, W, S	
	CHEMICAL ROOM	O	N, E, W, S	
	FOOD STORAGE	O	N, E, W, S	
	MULTI-PURPOSE	O	N, E, W, S	
	STAGE	O	N, E, W, S	
	DRESS 01	O	N, E, W, S	
	DRESS 02	O	N, E, W, S	
	ELECTRICAL 01	O	N, E, W, S	
	BAND ROOM 353	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
SINK ACOUSTICAL COATING, GRAY, ROUGH	STRINGS 401	O	N	S
	STAGE	O	W	
	BAND ROOM 353	O	E	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	LOBBY	O	N, S	S
	STRINGS 401	O	N, E, S	
	GYM STORAGE	O	N, W, S	
	BOY'S LOCKERS 01	O	W	
	BOY'S STORAGE	O	S	
	BOY'S RESTROOM 02	O	E	
	BOY'S LOCKERS 02	O	S	
	BOY'S COACH OFFICE	O	N, E	
	BOY'S COACH RESTROOM	O	W	
	P.E. STORAGE	O	N, S	
	JANITOR 01	O	S	
	GIRL'S STORAGE	O	W	
	GIRL'S RESTROOM 02	O	W	
	GIRL'S COACH OFFICE	O	N, W	
	GIRL'S COACH RESTROOM	O	E	
	BOY'S RESTROOM 01	O	N, S	
	GIRL'S RESTROOM 01	O	N, S	
	SERVING AREA	O	W, S	
	ELECTRICAL 02	O	N	
	OFFICE 01	O	E	
	CHEMICAL ROOM	O	E	
	UNISEX RESTROOM 01	O	E	
	FOOD STORAGE	O	W	
	MULTI-PURPOSE	O	N, E, W, S	
	SNACK BAR	O	E	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Aprende Middle School, KSD*  
*Multi-Purpose Building*

JOB NO. 08-166

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAGE	O	N, W	
	DRESS 01	O	S	
	UNISEX RESTROOM 02	O	E, S	
	DRESS 02	O	W	
	ELECTRICAL 01	O	N	
	BAND ROOM 353	O	E, S	
	GIRL'S RESTROOM	O	N, E, W	S
	BOY'S RESTROOM	O	N, E, W	
	LIVING ROOM	O	W	
	KITCHEN	O	N, E, W, S	
	BEDROOM 1	O	N	
	RESTROOM	O	N, E, W, S	
	MASTER BEDROOM	O	S	
	MASTER BATH	O	W	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, W, S	
	CORRIDOR 03	O	N, E	
	CORRIDOR 04	O	N, E, W	
	CORRIDOR 05	O	W, S	
	CORRIDOR 06	O	N, W, S	
	CORRIDOR 07	O	E, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOBBY	O	N, E, W, S	S
	STRINGS 401	O	N, E, S	
	GYMNASIUM	O	N, E, W, S	
	GYM STORAGE	O	N, W, S	
	BOY'S LOCKERS 01	O	E, W	
	BOY'S STORAGE	O	S	
	BOY'S LOCKERS 02	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	BOY'S COACH OFFICE	O	E, S	
	MECHANICAL 01	O	W	
	MECHANICAL 02	O	E	
	ELECTRICAL 03	O	E	
	WATER/HEATER ROOM	O	E	
	P.E. STORAGE	O	N, S	
	JANITOR 01	O	S	
	GIRL'S LOCKERS 01	O	E, W	
	GIRL'S STORAGE	O	W	
	GIRL'S LOCKERS 02	O	N	
	GIRL'S COACH OFFICE	O	W, S	
	BOY'S RESTROOM 01	O	W	
	GIRL'S RESTROOM 01	O	W	
	SERVING AREA	O	W, S	
	ELECTRICAL 02	O	N	
	CHEMICAL ROOM	O	W	
	UNISEX RESTROOM 01	O	W	
	KITCHEN SERVICE YARD	O	E, S	
	FOOD STORAGE	O	W	
	MULTI-PURPOSE	O	N, E, W, S	
	SNACK BAR	O	E	
	STAGE	O	N	
	DRESS 01	O	S	
	UNISEX RESTROOM 02	O	S	
	DRESS 02	O	W	
	SOUND ROOM	O	N	
	ELECTRICAL 01	O	N	
	BAND ROOM 353	O	E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	GIRL'S RESTROOM	O	N	
	BOY'S RESTROOM	O	N	
	LIVING ROOM	O	W	
	KITCHEN	O	E	
	CORRIDOR 01	O	N, E, W, S	
	CORRIDOR 02	O	N, W, S	
	CORRIDOR 03	O	N, E	
	CORRIDOR 04	O	N, E, W	
	CORRIDOR 05	O	W, S	
	CORRIDOR 06	O	N, E, W, S	
	CORRIDOR 07	O	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	STRINGS 401	C, W	N, E, W, S	
	CHEMICAL ROOM	C, W	N, E, W, S	
	ELECTRICAL 01	W	N, E, W, S	
	CORRIDOR 01	C, W	N, E, W, S	
	CORRIDOR 02	C, W	N, E, W, S	
	CORRIDOR 05	W	N, E, W, S	
	CORRIDOR 06	C, W	N, E, W, S	
	CORRIDOR 07	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	STRINGS 401	C, W	N, E, W, S	
	CHEMICAL ROOM	C, W	N, E, W, S	
	ELECTRICAL 01	W	N, E, W, S	
	CORRIDOR 01	C, W	N, E, W, S	
	CORRIDOR 02	C, W	N, E, W, S	
	CORRIDOR 05	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	CORRIDOR 06	C, W	N, E, W, S	
	CORRIDOR 07	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	STRINGS 401	C, W	N, E, W, S	
	CHEMICAL ROOM	C, W	N, E, W, S	
	ELECTRICAL 01	W	N, E, W, S	
	CORRIDOR 01	C, W	N, E, W, S	
	CORRIDOR 02	C, W	N, E, W, S	
	CORRIDOR 05	W	N, E, W, S	
	CORRIDOR 06	C, W	N, E, W, S	
	CORRIDOR 07	C, W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BOY'S LOCKERS 01	C, W	N, E	S
	BOY'S SHOWER	C	*	
	BOY'S RESTROOM 02	C	*	
	BOY'S LOCKERS 02	C	*	
	BOY'S COACH RESTROOM	C, W	N, E, W, S	
	JANITOR 01	W	N, E, W, S	
	GIRL'S LOCKERS 01	C, W	N, W	
	GIRL'S SHOWER	C	*	
	GIRL'S RESTROOM 02	C	*	
	GIRL'S LOCKERS 02	C	*	
	GIRL'S COACH RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 01	C	*	
	GIRL'S RESTROOM 01	C	*	
	KITCHEN	W	N, E, W, S	
	SERVING AREA	W	N, E, W, S	
	SNACK BAR	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	UNISEX RESTROOM 02	C	*	
	GIRL'S RESTROOM	C	*	
	BOY'S RESTROOM	C	*	
	CORRIDOR 03	C, W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BOY'S LOCKERS 01	C, W	N, E	S
	BOY'S SHOWER	C	*	
	BOY'S RESTROOM 02	C	*	
	BOY'S LOCKERS 02	C	*	
	BOY'S COACH RESTROOM	W	N, E, W, S	
	JANITOR 01	W	N, E, W, S	
	GIRL'S LOCKERS 01	C, W	N, W	
	GIRL'S SHOWER	C	*	
	GIRL'S RESTROOM 02	C	*	
	GIRL'S LOCKERS 02	C	*	
	GIRL'S COACH RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 01	C	*	
	GIRL'S RESTROOM 01	C	*	
	KITCHEN	W	N, E, W, S	
	SERVING AREA	W	N, E, W, S	
	SNACK BAR	C, W	N, E, W, S	
	UNISEX RESTROOM 02	C	*	
	GIRL'S RESTROOM	C	*	
	BOY'S RESTROOM	C	*	
	CORRIDOR 03	C, W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	BOY'S LOCKERS 01	C, W	N, E	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	BOY'S SHOWER	C	*	
	BOY'S RESTROOM 02	C	*	
	BOY'S LOCKERS 02	C	*	
	BOY'S COACH RESTROOM	W	N, E, W, S	
	JANITOR 01	W	N, E, W, S	
	GIRL'S LOCKERS 01	C, W	N, W	
	GIRL'S SHOWER	C	*	
	GIRL'S RESTROOM 02	C	*	
	GIRL'S LOCKERS 02	C	*	
	GIRL'S COACH RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 01	C	*	
	GIRL'S RESTROOM 01	C	*	
	KITCHEN	W	N, E, W, S	
	SERVING AREA	W	N, E, W, S	
	SNACK BAR	C, W	N, E, W, S	
	UNISEX RESTROOM 02	C	*	
	GIRL'S RESTROOM	C	*	
	BOY'S RESTROOM	C	*	
	CORRIDOR 03	C, W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
GLAZED WALL TILE, 4"x4", TAN, SMOOTH	BOY'S LOCKER 01	W	N, E, W, S	S
	BOY'S SHOWER	W	N, E, W, S	
	BOY'S RESTROOM 02	W	N, E, W, S	
	BOY'S LOCKERS 02	W	N, E, W, S	
	GIRL'S LOCKERS 01	W	N, E, W, S	
	GIRL'S SHOWER	W	N, E, W, S	
	GIRL'S RESTROOM 02	W	N, E, W, S	
	GIRL'S LOCKERS 02	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	BOY'S RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH AND GLAZED WALL TILE, 4"X4", BLUE, SMOOTH	BOY'S LOCKER 01	W	N, E, W, S	S
	BOY'S SHOWER	W	N, E, W, S	
	BOY'S RESTROOM 02	W	N, E, W, S	
	BOY'S LOCKERS 02	W	N, E, W, S	
	GIRL'S LOCKERS 01	W	N, E, W, S	
	GIRL'S SHOWER	W	N, E, W, S	
	GIRL'S RESTROOM 02	W	N, E, W, S	
	GIRL'S LOCKERS 02	W	N, E, W, S	
	BOY'S RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	BOY'S RESTROOM 01	F	*	S
	GIRL'S RESTROOM 01	F	*	
	UNISEX RESTROOM 02	F	*	
	GIRL'S RESTROOM	F	*	
	BOY'S RESTROOM	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	BOY'S RESTROOM 01	F	*	S
	GIRL'S RESTROOM 01	F	*	
	UNISEX RESTROOM 02	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	GIRL'S RESTROOM	F	*	
	BOY'S RESTROOM	F	*	
ACOUSTICAL CEILING PANEL, 2'X2', WHITE, CHALKY, VINYL COVER	KITCHEN	C	*	S
	SERVING AREA	C	*	
	CORRIDOR 04	C	*	
GLAZED WALL TILE (COVED), 4"X8", GRAY, SMOOTH, MULTI-COLORED	KITCHEN	W	N, E, W, S	S
	SERVING AREA	W	N, E, W, S	
	SNACK BAR	W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
	CORRIDOR 05	W	N, E, W, S	
	CORRIDOR 06	W	N, E, W, S	
	CORRIDOR 07	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE (COVED), 4"X8", GRAY, SMOOTH, MULTI-COLORED	KITCHEN	W	N, E, W, S	S
	SERVING AREA	W	N, E, W, S	
	SNACK BAR	W	N, E, W, S	
	CORRIDOR 04	W	N, E, W, S	
	CORRIDOR 05	W	N, E, W, S	
	CORRIDOR 06	W	N, E, W, S	
	CORRIDOR 07	W	N, E, W, S	
QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	KITCHEN	F	*	S
	SERVING AREA	F	*	
	CORRIDOR 04	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	KITCHEN	F	*	S
	SERVING AREA	F	*	
	CORRIDOR 04	F	*	
SEALANT (WINDOWS), BLACK, GUMMY	MECHANICAL 01	O	W, S	S
	CORRIDOR 04	O	W	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	BOY'S LOCKERS 01	O	N, E	N
	KITCHEN	O	N, S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	BOY'S LOCKERS 01	O	N, E	S
	KITCHEN	O	N, S	
QUARRY/PAVER TILE, 12"X12", GRAY, TEXTURED, BLACK STREAKS	BOY'S LOCKERS 01	F	*	S
	BOY'S SHOWER	F	*	
	BOY'S RESTROOM 02	F	*	
	BOY'S LOCKERS 02	F	*	
	GIRL'S LOCKERS 01	F	*	
	GIRL'S SHOWER	F	*	
	GIRL'S RESTROOM 02	F	*	
	GIRL'S LOCKERS 02	F	*	
	FOOD STORAGE	F	*	
	SNACK BAR	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, TEXTURED, BLACK STREAKS	BOY'S LOCKERS 01	F	*	S
	BOY'S SHOWER	F	*	
	BOY'S RESTROOM 02	F	*	
	BOY'S LOCKERS 02	F	*	
	GIRL'S LOCKERS 01	F	*	
	GIRL'S SHOWER	F	*	
	GIRL'S RESTROOM 02	F	*	
	GIRL'S LOCKERS 02	F	*	
	FOOD STORAGE	F	*	
	SNACK BAR	F	*	
VINYL STAIR TREAD, 12"X48", GRAY, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE	F	*	S
MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X48", GRAY, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE	F	*	S
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	STRINGS 401	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	P.E. STORAGE	F	*	
	JANITOR 01	F	*	
	GIRL'S STORAGE	F	*	
	OFFICE 01	F	*	
	CHEMICAL ROOM	F	*	
	MULTI-PURPOSE	F	*	
MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	STRINGS 401	F	*	S
	P.E. STORAGE	F	*	
	JANITOR 01	F	*	
	GIRL'S STORAGE	F	*	
	OFFICE 01	F	*	
	CHEMICAL ROOM	F	*	
	MULTI-PURPOSE	F	*	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	STRINGS 401	W	E, W, S	S
WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	GYMNASIUM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	GYMNASIUM	O	N, E, W, S	S
SEALANT (FIRE STOP), RED, PLIABLE	ELECTRICAL 03	O	W	S
	WATER/HEATER ROOM	O	W	
SEALANT (EQUIPMENT), BLACK, GUMMY	MECHANICAL 02	O	*	S
SEALANT (EQUIPMENT), GRAY, PLIABLE	LOBBY	O	*	S
	STRINGS 401	O	*	
	GYMNASIUM	O	*	
	GYM STORAGE	O	*	
	BOY'S LOCKERS 01	O	*	
	BOY'S STORAGE	O	*	
	BOY'S SHOWER	O	*	
	BOY'S RESTROOM 02	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	BOY'S LOCKERS 02	O	*	
	BOY'S COACH OFFICE	O	*	
	BOY'S COACH RESTROOM	O	*	
	ELECTRICAL 03	O	*	
	WATER/HEATER ROOM	O	*	
	P.E. STORAGE	O	*	
	JANITOR 01	O	*	
	GIRL'S LOCKERS 01	O	*	
	GIRL'S STORAGE	O	*	
	GIRL'S SHOWER	O	*	
	GIRL'S RESTROOM 02	O	*	
	GIRL'S LOCKERS 02	O	*	
	GIRL'S COACH OFFICE	O	*	
	GIRL'S COACH RESTROOM	O	*	
	BOY'S RESTROOM 01	O	*	
	GIRL'S RESTROOM 01	O	*	
	KITCHEN	O	*	
	SERVING AREA	O	*	
	ELECTRICAL 02	O	*	
	OFFICE 01	O	*	
	CHEMICAL ROOM	O	*	
	UNISEX RESTROOM 01	O	*	
	FOOD STORAGE	O	*	
	FREEZER 1	O	*	
	FREEZER 2	O	*	
	MULTI-PURPOSE	O	*	
	SNACK BAR	O	*	
	STAGE	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S</b>
	DRESS 01	O	*	
	UNISEX RESTROOM 02	O	*	
	DRESS 02	O	*	
	SOUND ROOM	O	*	
	ELECTRICAL 01	O	*	
	BAND ROOM 353	O	*	
	GIRL'S RESTROOM	O	*	
	BOY'S RESTROOM	O	*	
	CORRIDOR 01	O	*	
	CORRIDOR 02	O	*	
	CORRIDOR 03	O	*	
	CORRIDOR 04	O	*	
	CORRIDOR 05	O	*	
	CORRIDOR 06	O	*	
	CORRIDOR 07	O	*	
CARPET, BROWN, FIBROUS	LIVING ROOM	F	*	S
	BEDROOM 1	F	*	
	BEDROOM 1 CLOSET	F	*	
	MASTER BEDROOM	F	*	
	MASTER BATH	F	*	
	MASTER CLOSET	F	*	
QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPECKS	LIVING ROOM	F	*	S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPECKS	LIVING ROOM	F	*	S
VINYL SHEET FLOORING, TAN, SMOOTH, BROWN MOTTLES, GRAY PAPER BACKING	KITCHEN	F	*	S
	KITCHEN CLOSET	F	*	
	PANTRY	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, TAN, SMOOTH, BROWN MOTTLES, GRAY PAPER BACKING	KITCHEN	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT C/W/F/O</b>	<b>COMPONENT LOCATION N/E/W/S</b>	<b>ACM N/S N/S</b>
	KITCHEN CLOSET	F	*	
	PANTRY	F	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	RESTROOM	W	N, W, S	S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	RESTROOM	W	N, W, S	S
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	BOY'S LOCKER 01	W	N, E, W, S	S
	BOY'S RESTROOM 02	W	N, E, W, S	
	BOY'S LOCKERS 02	W	N, E, W, S	
	GIRL'S LOCKERS 01	W	N, E, W, S	
	GIRL'S SHOWER	W	N, E, W, S	
	GIRL'S RESTROOM 02	W	N, E, W, S	
	GIRL'S LOCKERS 02	W	N, E, W, S	
	BOY'S RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	BOY'S LOCKER 01	W	N, E, W, S	S
	BOY'S RESTROOM 02	W	N, E, W, S	
	BOY'S LOCKERS 02	W	N, E, W, S	
	GIRL'S LOCKERS 01	W	N, E, W, S	
	GIRL'S SHOWER	W	N, E, W, S	
	GIRL'S RESTROOM 02	W	N, E, W, S	
	GIRL'S LOCKERS 02	W	N, E, W, S	
	BOY'S RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATION</b>	<b>MATERIAL COMPONENT</b>	<b>COMPONENT LOCATION</b>	<b>ACM N/S</b>
		<b>C/W/F/O</b>	<b>N/E/W/S</b>	<b>N/S</b>
	BOY'S RESTROOM	W	N, E, W, S	
GLAZED WALL TILE, 4"X4", BLUE, SMOOTH	BOY'S LOCKER 01	W	N, E, W, S	S
	BOY'S RESTROOM 02	W	N, E, W, S	
	BOY'S LOCKERS 02	W	N, E, W, S	
	GIRL'S LOCKERS 01	W	N, E, W, S	
	GIRL'S SHOWER	W	N, E, W, S	
	GIRL'S RESTROOM 02	W	N, E, W, S	
	GIRL'S LOCKERS 02	W	N, E, W, S	
	BOY'S RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM 01	W	N, E, W, S	
	UNISEX RESTROOM 01	W	N, E, W, S	
	GIRL'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM	W	N, E, W, S	

**\* - Not Applicable**

END OF TABLE

## **2.4 AHERA Inspection Procedures and Protocols**

### **2.4.1 Inspection Procedures and Protocols**

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
  - ◊ natural friability and,
  - ◊ physical condition and,
  - ◊ if damaged or thermal systems insulation;
    - \* be identified for an immediate response action or,
    - \* be identified for possible future disturbance and
    - \* have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
  - ◊ date accomplished and,
  - ◊ identification and qualification of individuals conducting each activity.

### **2.4.2 FM GROUP INC Inspection SOP**

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

## **2.5 Visual Inspection**

A visual inspection of the three buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

*A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.*

**2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials**

**TABLE B**  
**HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

**MAIN BUILDING**  
**MEDIA CENTER BUILDING**  
**MULTI-PURPOSE BUILDING**



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP, SILVER	A	NF	105,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	1,500	SF
M-SLT-03	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	20	SF
M-SLT-04	SEALANT (FLASHINGS), BLACK, GUMMY	A	NF	30	SF
M-SLT-05	SEALANT (FLASHINGS), TAN, PLIABLE	A	NF	100	SF
M-SLT-06	SEALANT (WINDOWS), WHITE, BRITTLE	A	NF	36	SF
M-CMU-07	CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH	A	NF	10,000	SF
M-CMU-08	CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH	A	NF	3,000	SF
M-CMU-09	CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS	A	NF	17,000	SF
M-CMU-10	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-MRT-11	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	3,000	SF
S-STU-12	STUCCO, GRAY, CEMENTITIOUS	A	NF	6,000	SF
M-BUR-13	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	10,000	SF
M-MAS-14	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	250	SF
M-SLT-15	SEALANT (FLASHINGS), TAN, PLIABLE	A	NF	10	SF
M-CON-16	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-CON-17	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	105,000	SF
M-CON-18	CONCRETE (COLUMNS), GRAY, CEMENTITIOUS	A	NF	400	SF
M-SLT-19	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	S	NF	200	SF
M-MRT-20	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	50	SF
M-APL-21	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FIXTURES, WHITE	S	F	80,000	SF
S-SAT-22	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	85,000	SF
M-GWB-23	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	85,000	SF
S-JTC-24	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	8,500	SF
M-TWP-25	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	15,000	SF
M-CPT-26	CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	S	NF	80,000	SF
M-VCT-27	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	S	NF	20,000	SF
M-MAS-28	MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	S	NF	20,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-WAB-29	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	S	NF	4,000	SF
M-ADH-30	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	S	NF	4,000	SF
M-FDI-31	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	3,087	SF
M-SAC-32	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	108	SF
M-SLT-33	SEALANT (DUCT), LIGHT GRAY, PLIABLE	A	NF	1,000	SF
M-SLT-34	SEALANT (WINDOWS), BLACK, GUMMY	S	NF	100	SF
S-SAT-35	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	20,000	SF
M-GWB-36	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	20,000	SF
S-JTC-37	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	2,000	SF
M-GWT-38	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	20,000	SF
M-GRT-39	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	A	NF	2,000	SF
M-CMT-40	CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	7,000	SF
M-GRT-41	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	700	SF
S-SAT-42	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	30,000	SF
M-GWB-43	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	30,000	SF
S-JTC-44	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	3,000	SF
M-WAB-45	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	100	SF
M-ADH-46	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	100	SF
M-QPT-47	QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	400	SF
M-GRT-48	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	40	SF
M-VCT-49	VINYL COMPOSITION TILE, 18"X18", GRAY, TEXTURED, CIRCLE PATTERN	A	NF	500	SF
M-MAS-50	MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 18"X18", GRAY, TEXTURED, CIRCLE PATTERN	A	NF	500	SF
M-WAB-51	WALLBASE (COVED), 4", GREEN, VINYL-LIKE	A	NF	20	SF
M-ADH-52	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GREEN, VINYL-LIKE	A	NF	20	SF
M-TWP-53	TACKABLE WALL PANEL (MOVEABLE), BROWN, FIBROUS, VINYL COVER	A	NF	1,000	SF
M-SLT-54	SEALANT (DUCT), DARK GRAY, PLIABLE	A	NF	1,000	SF
M-GWT-55	GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	1,000	SF
M-GWT-56	GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	A	NF	1,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Main Building*

JOB NO. 08-166

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
M-GWT-57	GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	A	NF	1,000	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	46,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHING), BLACK, TAR-LIKE, SILVER	A	NF	1,000	SF
M-SLT-03	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	250	SF
M-SLT-04	SEALANT (DOORS, WINDOWS, FLASHINGS), WHITE, PLIABLE	A	NF	300	SF
M-CMU-05	CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH	A	NF	25,000	SF
M-CMU-06	CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH	A	NF	1,000	SF
M-CMU-07	CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS	A	NF	1,000	SF
M-MRT-08	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16" PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH, AND CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS	A	NF	2,600	SF
M-CON-09	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	6,000	SF
M-CON-10	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	43,000	SF
M-CON-11	CONCRETE (COLUMNS), GRAY, CEMENTITIOUS	A	NF	500	SF
S-STU-12	STUCCO, GRAY, CEMENTITIOUS	A	NF	4,400	SF
M-FDI-13	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,029	SF
M-MRT-14	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	50	SF
M-SLT-15	SEALANT (WINDOWS), BLACK, GUMMY	S	NF	15	SF
M-APL-16	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	NF	28,000	SF
S-SAT-17	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	20,000	SF
M-GWB-18	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	20,000	SF
S-JTC-19	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	2,000	SF
M-TWP-20	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	1,500	SF
M-VCT-21	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	S	NF	5,000	SF
M-MAS-22	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	S	NF	5,000	SF
M-WAB-23	WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	S	NF	1,400	SF
M-ADH-24	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	S	NF	1,400	SF
M-SLT-25	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	S	NF	100	SF
S-SAT-26	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,500	SF
M-GWB-27	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,500	SF
S-JTC-28	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	150	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Media Center Building*

JOB NO. 08-166

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
S-SAT-29	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
M-GWB-30	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
S-JTC-31	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
M-SAC-32	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	18	SF
M-WDB-33	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	100	SF
M-CPT-34	CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	S	NF	34,000	SF
M-GWT-35	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF		SF
M-GRT-36	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	A	NF	300	SF
M-CMT-37	CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	1,600	SF
M-GRT-38	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	160	SF
M-APL-39	ACOUSTICAL CEILING PANEL, 2'X2', YELLOW, FIBROUS GLASS, CLOTH COVER	A	NF	3,600	SF
M-TWP-40	TACKABLE WALL PANEL, WHITE, CHALKY, VINYL COVER	A	NF	300	SF
M-SLT-41	SEALANT (DUCT), GRAY, PLIABLE	A	NF	150	SF
M-GWT-42	GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	250	SF
M-GWT-43	GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	A	NF	250	SF
M-GWT-44	GLAZED WALL TILE (PATTERN), 4"X4", BLUE, SMOOTH	A	NF	250	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	30,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	1,500	SF
M-SLT-03	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	125	SF
M-SLT-04	SEALANT (DOORS, WINDOWS, WALLS), WHITE, PLIABLE	S	NF	300	SF
M-CMU-05	CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH	A	NF	20,000	SF
M-CMU-06	CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH	A	NF	10,000	SF
M-CMU-07	CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, SMOOTH	A	NF	10,000	SF
M-CMU-08	CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, SMOOTH	A	NF	9,500	SF
M-MRT-09	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", PINK, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT (PATTERN), 12"X12", GRAY, CEMENTITIOUS	A	NF	12,000	SF
M-SLT-10	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-SLT-11	SEALANT (DUCT), WHITE, PLIABLE	A	NF	50	SF
M-PES-12	PIPE END SEALANT, GRAY, PLIABLE	A	NF	20	SF
M-WDB-13	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	20	SF
M-BUR-14	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP, SILVER	A	NF	2,000	SF
M-MAS-15	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	100	SF
M-CON-16	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-CON-17	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	S	NF	35,000	SF
M-CON-18	CONCRETE (COLUMNS), GRAY, CEMENTITIOUS	A	NF	200	SF
M-STU-19	STUCCO, GRAY, CEMENTITIOUS	A	NF	3,300	SF
M-MRT-20	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	5	SF
M-CMU-21	CONCRETE MASONRY UNIT (PATTERN), 12"X12", GRAY, CEMENTITIOUS	A	NF	800	SF
M-APL-22	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	NF	16,000	SF
S-SAT-23	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
M-GWB-24	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
S-JTC-25	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	1,000	SF
M-TWP-26	TACKABLE WALL PANEL, YELLOW, FIBROUS GLASS, CLOTH COVER	A	NF	1,200	SF
M-CPT-27	CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	S	NF	5,500	SF
M-WAB-28	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	S	NF	400	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
M-ADH-29	ADHESIVE, YELLOW, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	S	NF	400	SF
M-SAC-30	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	6	SF
M-SLT-31	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	S	NF	100	SF
M-FDI-32	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	2,484	SF
S-SAT-33	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	9,000	SF
M-GWB-34	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	9,000	SF
S-JTC-35	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	900	SF
S-SAT-36	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	14,000	SF
M-GWB-37	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	14,000	SF
S-JTC-38	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	1,400	SF
M-GWT-39	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	7,000	SF
M-GRT-40	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH AND GLAZED WALL TILE, 4"X4", BLUE, SMOOTH	A	NF	700	SF
M-CMT-41	CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	2,000	SF
M-GRT-42	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	200	SF
M-APL-43	ACOUSTICAL CEILING PANEL, 2'X2', WHITE, CHALKY, VINYL COVER	S	NF	2,500	SF
M-GWT-44	GLAZED WALL TILE (COVED), 4"X8", GRAY, SMOOTH, MULTI-COLORED	A	NF	2,000	SF
M-GRT-45	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE (COVED), 4"X8", GRAY, SMOOTH, MULTI-COLORED	A	NF	200	SF
M-QPT-46	QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	2,500	SF
M-GRT-47	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPOTS	A	NF	250	SF
M-SLT-48	SEALANT (WINDOWS), BLACK, GUMMY	S	NF	3	SF
M-ADH-49	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	20	SF
M-QPT-50	QUARRY/PAVER TILE, 12"X12", GRAY, TEXTURED, BLACK STREAKS	A	NF	6,000	SF
M-GRT-51	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, TEXTURED, BLACK STREAKS	A	NF	600	SF
M-VST-52	VINYL STAIR TREAD, 12"X48", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF
M-MAS-53	MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X48", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF
M-VCT-54	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	S	NF	6,000	SF
M-MAS-55	MASTIC, YELLOW, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	S	NF	6,000	SF
M-TWP-56	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	750	SF
M-WAB-57	WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	S	NF	150	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
Multi-Purpose Building*

JOB NO. 08-166

<b>MATERIAL CODE</b>	<b>MATERIAL DESCRIPTION</b>	<b>CLSS MTHD</b>	<b>F/NF</b>	<b>MTL QUAN</b>	<b>UNITS</b>
M-ADH-58	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	S	NF	150	SF
M-SLT-59	SEALANT (FIRE STOP), RED, PLIABLE	A	NF	10	SF
M-SLT-60	SEALANT (EQUIPMENT), BLACK, GUMMY	A	NF	10	SF
M-SLT-61	SEALANT (EQUIPMENT), GRAY, PLIABLE	A	NF	50	SF
M-CPT-62	CARPET, BROWN, FIBROUS	A	NF	750	SF
M-QPT-63	QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPECKS	A	NF	50	SF
M-GRT-64	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH, MULTI-COLORED SPECKS	A	NF	5	SF
M-VSF-65	VINYL SHEET FLOORING, TAN, SMOOTH, BROWN MOTTLES, GRAY PAPER BACKING	A	NF	500	SF
M-MAS-66	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, TAN, SMOOTH, BROWN MOTTLES, GRAY PAPER BACKING	A	NF	500	SF
M-GWT-67	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	100	SF
M-GRT-68	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	10	SF
M-GWT-69	GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	300	SF
M-GWT-70	GLAZED WALL TILE (PATTERN), 4"X4", BLACK, SMOOTH	A	NF	300	SF
M-GWT-71	GLAZED WALL TILE, 4"X4", BLUE, SMOOTH	A	NF	300	SF

END OF TABLE



**Report of Findings**

Comprehensive AHERA Asbestos Inspection

Kyrene Aprende Middle School, KSD

FM Project 08-166

**2.7 Physical Assessments**

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **FOUR** friable suspect ACBM (acoustical ceiling panels) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

**2.8 Sample Collection**

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

<b>Building</b>	<b>Suspect ACBM</b>	<b>Samples Collected</b>
Main	57 (42 Assumed)	45
Media Center	44 (29 Assumed)	45
Multi-Purpose	71 (51 Assumed)	60
<b>TOTAL</b>	<b>172</b>	<b>150</b>

*Suspect ACM Designation and Sample Record Forms are presented in Appendix A.*

**2.9 Bulk-Material Sample Analysis**

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

**Report of Findings**

Comprehensive AHERA Asbestos Inspection  
Kyrene Aprende Middle School, KSD  
FM Project 08-166

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

*Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.*

**END OF REPORT**

## **APPENDIX A**

### **Suspect Asbestos-Containing Material Designation and Sample Record Forms**

Project No.: 08-1066 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-BR-01 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Built-up Roofing Visible Covered    
 Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap Size: N/A  
 Quantity of Material: 105,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Silver

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-MA5-02 Damaged:  Yes  No  Friable  Non-Friable

General Description: Mastic (Penetrations & Flashings) Visible Covered

Matrix/Primary Color: Black Texture/Pattern: Tar-Like Cover/Secondary Color: N/A Size: N/A

Quantity of Material: 1500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Silver

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main 1 Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-03 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant (Flashing) Visible  Covered   
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 20 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-04 Damaged:  Yes  No Friable  Non-Friable

General Description: Sealant (Flashing) Visible  Covered  Size: N/A

Matrix/Primary Color: Black Texture/Pattern: GUMM Cover/Secondary Color: N/A

Quantity of Material: 30 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-106 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SCT-05 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Flashing) Visible Covered  No  Size: N/A

Matrix/Primary Color: Tan Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-06 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Section (WINDOWS) Size: N/A  
 Visible  Covered

Matrix/Primary Color: White Texture/Pattern: BRITTLE Cover/Secondary Color: N/A  
 Quantity of Material: 36 Estimated By:  Drawing  Field Measure  
 SF / LF / EA  Wall  Other

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CMU-07 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete Masonry Unit Visible Covered

Matrix/Primary Color: Pink Texture/Pattern: Cementitious Cover/Secondary Color: Rough Size: 8" X 16"

Quantity of Material: 10,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 377-7877  
 (602) 277-6288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CMU-08 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete Masonry Unit Size: 4" X 16"

Matrix/Primary Color: Pink Cover/Secondary Color: Rough  
 Quantity of Material: 3,000 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-106s Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CMU-09 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete Masonry Unit Size: 8" X 16"

Matrix/Primary Color: Pink Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 17,000 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-C-M-V-10 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete Masonry Unit Size: 8" X 16"

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-MRT-11 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mortar Visible  Covered  Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 300 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CM-07, M-CM-08, M-CM-09, M-CM-10,  
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-STU-12 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sheds Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A  
 Quantity of Material: 6000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-BUR-13 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: Built-up Roofing Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: Gravel Cap

Quantity of Material: 10,000 Estimated By:  Drawing  Sampled  Assumed  
 Texture/Pattern: Asphaltic  
 SF / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: CR Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.M.A.S-14 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic (Penetrations & Flashing) Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Tar-Like Cover/Secondary Color: N/A  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-S.T-15 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: Sealant (Flashings) Size: N/A

Matrix/Primary Color: Tan Texture/Pattern: Pliable Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-60N-16 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete (Entires) Size: N/A

Matrix/Primary Color: Gray 5,000 Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: SF / LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecord.ornf

Project No.: 08-16b Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CON-17 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete (Foundation) Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 105,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *DK* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CON-18 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete (columns) Visible  Covered  Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 400 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-1c6 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.S.C.T-19 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant (Doors, Windows, Millwork, Fixtures) Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 200 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	317	SE Corner	W 3'	N 3'	3'	F/W/C/O
B	Office 2	SE Corner	W 0'	N 1'	2'	F/W/C/O
C	114	SW Corner	E 0'	N 1'	3'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-106 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-MRT-20 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mortar Visible Covered:   Size: N/A

Matrix/Primary Color: White Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 50 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Glassblock, 8" x 8", Clear

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28  
 Building No.: Main **Address:** 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-ACL-21  Visible  Covered  Damaged:  Yes  No  Friable  Non-Friable

General Description: Acoustical Ceiling Panel **Size:** 2' X 4'

Matrix/Primary Color: Gray **Texture/Pattern:** Pinholes & Fixtures **Cover/Secondary Color:** White

Quantity of Material: 90,000 **Estimated By:**  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	300	NE Corner	W 6'	S 10'	8'	F/W/C/O
B	101	NW Corner	E 10'	S 10'	8'	F/W/C/O
C	201	NE Corner	W 8'	S 12'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter  
 AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA  
 Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/19/08 **Date:** 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax







Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: 5-SAT.22 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray-Applied Texture Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 85,000 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	301	SE Corner	W 0'	N 4'	4'	F/W/C/O
B	114	SE Corner	W 0'	N 4'	4'	F/W/C/O
C	103	NW Corner	E 4'	S 0'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature:  Date: 05/19/08  
 Signature:  Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.cmf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-LWB-23 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A  
 Quantity of Material: 85,000 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	301	SE Corner	W 0'	N 4'	4'	F/W/C/O
B	114	SE Corner	W 0'	N 4'	4'	F/W/C/O
C	103	NW Corner	E 4'	S 0'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-SAT-22

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S.JTC-24 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Joint Compound Visible Covered SAT Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 8500 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed  
 Homogeneous Material Location:  Random  Ceiling  Floor  Wall  Other

Manner of Sampling:  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	301	SE Corner	W 0'	N 4'	4'	F/W/C/O
B	114	SE Corner	W 0'	N 4'	4'	F/W/C/O
C	103	NW Corner	E 4'	50'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6013-23

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: GR Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-TWP-25 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Tackable Wall Panel Visible Covered:   Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 1500 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	203	NE Corner	W 3'	S 0'	2'	F (W) / C / O
B	301	SE Corner	W 0'	N 2'	2'	F (W) / C / O
C	101	NW Corner	E 0'	S 2'	2'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord1.mxf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CPT-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Carpet (Self-Stick) Visible Covered    
 Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored Size: N/A  
 Quantity of Material: 80,000 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	315	NE Corner	W 6"	S 0'	0'	F/W/I/C/O
B	214	SW Corner	E 0'	N 6"	0'	F/W/I/C/O
C	203	NE Corner	W 6"	E 0'	0'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: Date: 05/19/08 Signature: Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.V.C.T. 27 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Composition Tile Size: 12" X 12"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Brown Mothles  
 Quantity of Material: 20,000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	311	NW Corner	E 8'	S 0'	0'	F/W/C/O
B	208	SE Corner	W 0'	S 0'	0'	F/W/C/O
C	104	NW Corner	E 0'	S 8'	6'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-MAS-28 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mastic Visible  Covered  UCT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 20,000 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	311	NW Corner	E 8'	S 0'	0'	F/W/C/O
B	208	SE Corner	W 0'	S 0'	0'	F/W/C/O
C	1041	NW Corner	E 0'	S 8'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-UCT.27

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-WAS-29 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Wallbase (covered) Visible Covered  
 Matrix/Primary Color: Gray Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A  
 Quantity of Material: 4,000 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other Size: 4"

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	100	SW Corner	E 0'	N 4'	3"	F I C I O
B	Corridor 10	SW Corner	E 10'	N 0'	3"	F W I C I O
C	303	SE Corner	W 0'	N 6"	3"	F W I C I O
D		Corner				F W I C I O
E		Corner				F W I C I O
F		Corner				F W I C I O
G		Corner				F W I C I O

Comments: \_\_\_\_\_  
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08  
 Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

18974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8286 fax





Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-ADH-30 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Visible Covered WAS Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 4,000 (SF / LF / EA) Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	100	SW Corner	E 0'	N 4'	3'	F/W/C/O
B	Corridor 10	SW Corner	E 10	N 6'	3'	F/W/C/O
C	303	SE Corner	W 0'	N 6"	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-WAS-29

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-FD1-31 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Fire Door Insulation Visible Covered   Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Metal Wood Cladding Cover/Secondary Color: N/A  
 Quantity of Material: 3087 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesig/Record.ortf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main I Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SAC-32 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sink Acoustical Coating Visible  Covered  No  Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A  
 Quantity of Material: 108 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-33 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant (Duct) Visible Covered   Size: N/A

Matrix/Primary Color: LIGHT GRAY Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 1000 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-34 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Suspect (windows) Visible Covered   
 Matrix/Primary Color: Black Texture/Pattern: GUMMY Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 100 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 02	SE Corner	W 20'	N 15	4'	F I C I O
B	16	SE Corner	W 0'	N 45'	4'	F I W I C I O
C	10	SE Corner	W 20'	N 0'	4'	F I W I C I O
D		Corner				F I W I C I O
E		Corner				F I W I C I O
F		Corner				F I W I C I O
G		Corner				F I W I C I O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-SAT-35 Damaged:  Yes  No Friable  Non-Friable

General Description: Spray Applied Texture Visible  Covered  Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8286 fax

Project No.: 08-166  
 Building No.: Main  
 Campus Name: Kyrene Aprende Middle School  
 Project Name: AHERA-Compliance Asbestos Inspection  
 Address: 777 N. Desert Breeze Boulevard East #2  
 Chandler, AZ 85226  
 Owner: Kyrene School District No. 28

Material Code: M-6WB-3C  
 General Description: Gypsum Wallboard  
 Matrix/Primary Color: White  
 Quantity of Material: 22.000  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A  
 Visible Covered:  SAT  
 Damaged:  Yes  No  
 Texture/Pattern: Chalky  
 Estimated By:  Drawing  Field Measure  
 Cover/Secondary Color: N/A  
 Size: N/A  
 Friable  Non-Friable  
 Sampled  Assumed

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with SAT-35

Lead Inspector: Dane Thompson  
 Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313  
 State License: EPA  
 Signature: *[Signature]*  
 Date: 05/19/08  
 AHERA Certificate No.: D10790  
 State License: EPA  
 Signature: *[Signature]*  
 Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: 5-37C-37 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: White Quantity of Material: 200 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.6WB.36

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MAM Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.G.T. 38 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Glazed Wall Tile Size: 4"x4"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A  
 Quantity of Material: 20,000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-106 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MAIN Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GAT-39 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Grest Visible Covered   Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Granular Cover/Secondary Color: N/A  
 Quantity of Material: 2000 SF / LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-38, M-GWT-SS, M-GRE-SB & M-GWT-57

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: CR Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: 141N Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CM7-40 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Ceramic Mosaic Tile Visible  Covered  Size: 2"X2"

Matrix/Primary Color: Gray Texture/Pattern: Smooth Cover/Secondary Color: Multi-colored spots  
 Quantity of Material: 7,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord1.mcf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: M41N Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-627-41 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: GROUT Visible Covered  No  Yes Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 700 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMS-40

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-SAT-42 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray Applied Texture Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Chalky Size: N/A  
 Quantity of Material: 30,000 (SF) / LF / EA Cover/Secondary Color: N/A  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other Estimated By:  Drawing  Field Measure  Sampled Assumed

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 02	NE Corner	W 30'	S 30'	9'	F / W / C / O
B	16	SE Corner	W 20'	N 20'	9'	F / W / C / O
C	08	NW Corner	E 15'	S 15'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *GR* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-6WB.43 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Gross Wallboard Visible Covered SAT  
 Matrix/Primary Color: White Texture/Pattern: Chalky Size: N/A  
 Quantity of Material: 30,000 Estimated By:  Drawing  Field Measure  Sampled Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other Cover/Secondary Color: N/A

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 02	NE Corner	W 30'	S 30'	9'	F/W/C/O
B	16	SE Corner	W 20'	N 20'	9'	F/W/C/O
C	08	NW Corner	E 15'	S 15'	9'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Ascertained with S-SAT-47

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FIM GROUP INC**

FIM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-5cc-44 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Joint Compound Visible  Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 3000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 02	NE Corner	W 30'	S 30'	9'	F/W/C/O
B	16	SE Corner	W 20'	N 20'	9'	F/W/C/O
C	08	NW Corner	E 15'	S 15'	9'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6-w-B-4'S

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28  
 Building No.: Main **Address:** 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.W AS-45  Visible  Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Wallboard (over)  Covered  No  Size: 4"

Matrix/Primary Color: Gray **Texture/Pattern:** Vinyl-Like **Cover/Secondary Color:** N/A  
 Quantity of Material: 100 **Estimated By:**  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
**Manner of Sampling:**  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter  
 AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA  
 Signature: *DM* **Signature:** *[Signature]* **Date:** 05/19/08 **Date:** 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-ADH-46 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Visible Covered WAS Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAS-45

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-166      Project Name: AHERA-Compliance Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Main      Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School      Chandler, AZ 85226

Material Code: M-QPT-47      Damaged:  Yes       No      Friable       Non-Friable   
 General Description: Grey/Power Tile      Visible       Covered   
 Matrix/Primary Color: Grey      Texture/Pattern: Smooth      Cover/Secondary Color: Multi-Colored Spots  
 Quantity of Material: 400      Estimated By:  Drawing       Field Measure      Size: 12" X 12"       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313      State License: EPA      AHERA Certificate No.: D10790      State License: EPA  
 Signature: [Signature]      Date: 05/19/08      Signature: [Signature]      Date: 05/19/08

Asbestos-Containing Material:  No       Yes      Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166  
 Building No.: Main  
 Campus Name: Kyrene Aprende Middle School  
 Project Name: AHERA-Compliance Asbestos Inspection  
 Address: 777 N. Desert Breeze Boulevard East #2  
 Chandler, AZ 85226  
 Owner: Kyrene School District No. 28

Material Code: M-GAT-48  
 General Description: GROUT  
 Matrix/Primary Color: Gray  
 Quantity of Material: 40  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Visible Covered    
 Damaged:  Yes  No  
 Size: N/A  
 Texture/Pattern: Cementitious  
 Cover/Secondary Color: N/A  
 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GAT-47

Lead Inspector: Dane Thompson  
 Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313  
 State License: EPA  
 Signature: [Signature]  
 Date: 05/19/08  
 AHERA Certificate No.: D10790  
 State License: EPA  
 Signature: [Signature]  
 Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-UCT-49 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Composition Tile Visible Covered   Size: 18" X 18"

Matrix/Primary Color: Gray Texture/Pattern: Textured Cover/Secondary Color: Circle Pattern  
 Quantity of Material: 500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-MAS-50 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Masked visible Covered  No Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 500 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-49

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-WAS-51 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Wall base (ceiling) Visible  Covered  Size: 4"

Matrix/Primary Color: Green Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A  
 Quantity of Material: 20 (SF) / LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166      Project Name: AHERA-Compliance Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Main      Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School      Chandler, AZ 85226

Material Code: M-A914-52      Visible  Covered       Damaged:  Yes  No      Friable  Non-Friable   
 General Description: Adhesive      Texture/Pattern: Pliable      Cover/Secondary Color: N/A      Size: N/A

Matrix/Primary Color: Cream      Quantity of Material: 20      Estimated By:  Drawing  Field Measure       Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-S1

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313      State License: EPA      AHERA Certificate No.: D10790      State License: EPA  
 Signature: *DM*      Date: 05/19/08      Signature: *[Signature]*      Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: A-TWP-53 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Tackable Wall Panel (MOVABLE) Size: N/A

Matrix/Primary Color: Brown Cover/Secondary Color: Vinyl  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No. D10790 State License: EPA  
 Signature: Date: 05/19/08 Signature: Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M. S.C.T. 54 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant (Duct) Visible  Covered  Size: ~1A

Matrix/Primary Color: DARK GRAY Texture/Pattern: Pliable Cover/Secondary Color: ~1A  
 Quantity of Material: 1000 SF / LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *GM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-G-UT-SS Damaged:  Yes  No Friable  Non-Friable   
 General Description: GARAZED WALL BLUE PATTERN Size: 4' x 4'  
 Matrix/Primary Color: GRAY Texture/Pattern: Smooth Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-657-56 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GLAZED WALL-TILE (PATTERN) Size: 4x4  
 Matrix/Primary Color: BLACK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GUST. S7 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: GLAZED WALL TILE (PATTERN) Size: 4'x4'  
 Matrix/Primary Color: BLUE Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Texture/Pattern: SF / LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-BUR-01 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Built-up Roofing Visible Covered Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap  
 Quantity of Material: 46,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Silver

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DN* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-MA5-02 Damaged:  Yes  No Friable  Non-Friable

General Description: Matrix (Penetrations & Flashing) Visible  Covered  Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Tar-Like Cover/Secondary Color: SILVER

Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-SLT-03 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Flashing) Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/21/08 Signature: *MR* Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M.SCT-04 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Sealant (Doors, Windows, Flashings) Size: N/A

Matrix/Primary Color: White Texture/Pattern: Plaque Cover/Secondary Color: N/A

Quantity of Material: 300 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax



**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-CMU-05     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Concrete Masonry Unit    **Size:** 8" X 16"

**Matrix/Primary Color:** Pink    **Texture/Pattern:** Laminations    **Cover/Secondary Color:** Rough  
**Quantity of Material:** 25,000     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
 AHERA Certificate No.: D12313    State License: EPA    AHERA Certificate No.: D10790    State License: EPA  
 Signature: *DM*    Date: 05/21/08    Signature: *MR*    Date: 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-CMU-06     Visible     Covered    **Damaged:**  Yes     No     Friable     Non-Friable

**General Description:** Concrete Masonry Unit    **Size:** 4" X 16"    **Cover/Secondary Color:** Rough

**Matrix/Primary Color:** Pink    **Texture/Pattern:** Cementitious    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Quantity of Material:** 1,000    **SF / LF / EA**    **Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *DM*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-CM-07     Visible     Covered    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Concrete Masonry Unit    **Size:** 8" X 16"

**Matrix/Primary Color:** Pink    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 1000     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7677  
(602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-MRT-08 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 2,600 (SF) / LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMV-05 M-CMV-06, M-CMV-07

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790  
 Signature: *GR* Date: 05/21/08 State License: EPA Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-COV-09     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Concrete (Entries)     Covered     No     Yes     Field Measure     Sampling     Assumed  
**Matrix/Primary Color:** Gray     Drawing     Field Measure     Sampling     Assumed  
**Quantity of Material:** 600     Drawing     Field Measure     Sampling     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A  
**Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Estimated By:**  Drawing     Field Measure     Sampling     Assumed

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.orm

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-CON-10     Visible     Covered    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Concrete (Foundation)    **Size:** N/A  
**Matrix/Primary Color:** Gray    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 43,000    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-CON-V     Visible     Covered    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Concrete (columns)    **Size:** N/A

**Matrix/Primary Color:** Gray    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 500    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **AHERA Certificate No.:** D10790    **State License:** EPA    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 05/21/08    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes    **Assumed**

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-9288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: 5-500-12 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Stucco Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 4400 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax





**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** A-FDI-13     Visible     Covered     Friable     Non-Friable  
**General Description:** Fire Door Insulation    **Damaged:**  Yes     No    **Size:** N/A

**Matrix/Primary Color:** N/A    **Texture/Pattern:** Metal/Wood Cladding    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 1029     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:**    **Date:** 05/21/08    **Signature:**    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

FIM GROUP/forms/SuspACMDesigRecord.ormf

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-MBT-14     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Mortar    **Size:** N/A

**Matrix/Primary Color:** White    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 50     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with Glassblock, 8"x8", Clear

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Building Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-SCT-15 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealed (windows) Visible Covered Size: N/A

Matrix/Primary Color: Black Texture/Pattern: GUMM Cover/Secondary Color: N/A  
 Quantity of Material: 15 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	WORK ROOM 424	NW Corner	E S'	S O'	3"	F W I C I O
B	MULTI MEDIA	NW Corner	E O	S S'	3"	F W I C I O
C	EXTERIOR	NW Corner	E O'	S S O'	3"	F W I C I O
D		Corner				F W I C I O
E		Corner				F W I C I O
F		Corner				F W I C I O
G		Corner				F W I C I O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-APL-16 Damaged:  Yes  No Friable  Non-Friable  
 Visible  Covered Size: 2' x 2'

General Description: Acoustical Ceiling Panel Texture/Pattern: Pinholes & Fissures Cover/Secondary Color: White  
 Matrix/Primary Color: Gray Estimated By:  Drawing  Field Measure  
 Quantity of Material: 28000 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BREAK OUT OS	SE Corner	W 0'	N 0'	10'	F / W / C / O
B	424 ART	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	WORK ROOM 426	SW Corner	E 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACM/DesigRecord.0mf

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** S-SAT-17     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Spray Applied Texture    **Size:** N/A

**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** approx    **Estimated By:**  Drawing     Field Measure     Sampled Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CADD CLASSROOM	NW Corner	E 0'	S 0'	4"	F / W / C / O
B	479 STORAGE	NW Corner	E 0'	S 0'	4"	F / W / C / O
C	BREAK DUST 01	SW Corner	E 0'	N 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **AHERA Certificate No.:** D10790    **State License:** EPA    **State License:** EPA  
**Signature:** *DR*    **Signature:** *[Signature]*    **Date:** 05/21/08    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-6wb-18     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Gypsum Wallboard     Covered    SAT    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 20,000     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CADD CLASSROOM	NW Corner	E 0'	S 0'	4"	F/W/C/O
B	429 STORAGE	NW Corner	E 0'	S 0'	4"	F/W/C/O
C	BREAK OUT 01	SW Corner	E 0'	N 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:** Associated with S-SAT-17

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:**    **Date:** 05/21/08    **Signature:**    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: 5-5TC-19 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered SAT Size: N/A

General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By:  Drawing  Field Measure  
 Quantity of Material: 2000 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CADD CLASSROOM	NW Corner	E 0'	S 0'	4"	F / W / C / O
B	429 STORAGE	NW Corner	E 0'	S 0'	4"	F / W / C / O
C	BREAK OUT 01	SW Corner	E 0'	N 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWB-18

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-TWP.20 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Tackable Wall Panel Visible  Covered  Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 1500 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LIBRARY	NW Corner	E 10'	SO'	1'	F/W/C/O
B	CONFERENCE	NW Corner	E 0'	SO'	1'	F/W/C/O
C	424 AREA	SW Corner	E 0'	NO'	1'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax





**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-VCT-21     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Vinyl Composition Tile    **Size:** 12" X 12"

**Matrix/Primary Color:** Tan    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** Brown Mottles  
**Quantity of Material:** 500    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	424 ART	NE Corner	W 0'	S 0'	0'	F/W/C/O
B	FOOD STORAGE	NE Corner	W 0'	S 0'	0'	F/W/C/O
C	429 STORAGE	SE Corner	W 0'	N 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 05/21/08    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-MA5-22 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mastic Covered  Visible  Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 500 (SF) / LF / EA Estimated By:  Drawing  Sampled Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	424 ART	NE Corner	W 0'	S 0'	0'	F/W/C/O
B	FOOD STORAGE	NE Corner	W 0'	S 0'	0'	F/W/C/O
C	429 STORAGE	SE Corner	W 0'	N 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-VCT-21

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-W AB-23 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Wallbase (ceiling) Visible  Covered  Size: 4"

Matrix/Primary Color: Gray Texture/Pattern: Vinyl-like Cover/Secondary Color: N/A  
 Quantity of Material: 1400 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CONFERENCE	NW Corner	E 0'	S 0'	3"	F W I C I O
B	BREAK OUT 03	SE Corner	W 0'	N 0'	3"	F W I C I O
C	429	SE Corner	W 0'	N 0'	3"	F W I C I O
D		Corner				F W I C I O
E		Corner				F W I C I O
F		Corner				F W I C I O
G		Corner				F W I C I O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-ADH-24 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Visible Covered WAS Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 1400 (SF) / LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CONFERENCE	NW Corner	E 0'	S 0'	3"	F / W / C / O
B	BREAK OUT 03	SE Corner	W 0'	N 0'	3"	F / W / C / O
C	429	SE Corner	W 0'	N 0'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.WAS.23

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHJERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DK* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-SLT-25 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Doors, Windows, Millwork, Fixtures) Visible  Covered   
 Matrix/Primary Color: White Texture/Pattern: Stippled Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LIBRARY	NW Corner	E S'	SO'	3"	F W / C / O
B	DARK ROOM	NE Corner	W O'	SO'	3"	F W / C / O
C	W/D	SE Corner	W O'	NO'	3"	F W / C / O
D		Corner				F W / C / O
E		Corner				F W / C / O
F		Corner				F W / C / O
G		Corner				F W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: S-SAT-26 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 1500 Estimated By:  Drawing  Sampled  
 Field Measure Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ELEC OZ	NW Corner	E 0'	S 0'	4"	F/W/C/O
B	ELEC O1	NW Corner	E 0'	S 0'	4"	F/W/C/O
C	CORR OZ	SE Corner	W 0'	N 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-GWD-27 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 1500 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ELEC OZ	NW Corner	E 0'	S 0'	4"	F / W / C / O
B	ELEC OI	NW Corner	E 0'	S 0'	4"	F / W / C / O
C	CORR OZ	SE Corner	W 0'	N 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-26

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: Date: 05/21/08 Signature: Date: 05/21/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** S.JTC-28     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Joint Compound     Covered    SAT    Size: N/A

**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 1SD     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ELEC 02	NW Corner	E 0'	S 0'	4"	F/W/C/O
B	ELEC 01	NW Corner	E 0'	S 0'	4"	F/W/C/O
C	CORR 02	SE Corner	W 0'	N 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:** Associated with M.GWB-27

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 05/21/08    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.omf



**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** S. SAT-29     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Spray Applied Texture     Covered     No     Drawing     Assumed  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A    **Size:** N/A  
**Quantity of Material:** 3,000     SF / LF / EA    **Estimated By:**  Drawing     Field Measure

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:**    **Date:** 05/21/08    **Signature:**    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-60B-30 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable  Size: N/A

General Description: exposed wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By:  Drawing  Field Measure

Quantity of Material: 3,000 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-29

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** S-2TC-31     Visible     Damaged:  Yes     No     Friable     Non-Friable  
 Covered    SAT    Size: N/A

**General Description:** Joint Compound    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Matrix/Primary Color:** White    **Estimated By:**  Drawing     Field Measure  
**Quantity of Material:** 300     SF / LF / EA     Sampling     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-6WB-30

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **AHERA Certificate No.:** D10790    **State License:** EPA    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 05/21/08    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft



**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center  
**Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-WDB-33     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Woven Duct Boot    Size: 2"

**Matrix/Primary Color:** Black    **Texture/Pattern:** Rubber-Like    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 100     (SF) / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-CPT-34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Carpet (self-stick) Size: 1(A)

Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored  
 Quantity of Material: 34,000 (SF) / LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BREAK OUT DLG	NW Corner	E 0'	S 0'	0'	F/W/C/O
B	CONFERENCE	SE Corner	W 0'	N 0'	0'	F/W/C/O
C	STAFF LOUNGE	NE Corner	W 0'	S 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-6WT-35 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Glazed Wall Tile Size: 4" x 4"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A  
 Quantity of Material: 3000 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790  
 Signature: *DK* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-GR-3C Visible Covered   Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Grout Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 300 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GR-35, M-GR-40, M-GR-43 and M-GR-44

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-CMT-37     Visible     Covered     Damaged: Yes     No     Friable     Non-Friable  
**General Description:** Ceramic Mosaic Tile    **Size:** 2" x 2"

**Matrix/Primary Color:** Gray    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** Multi-colored Spots  
**Quantity of Material:** 1600     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:**    **Date:** 05/21/08    **Signature:**    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-GR-38 Material Code:  Friable  Non-Friable  
 General Description: Grout Damaged:  Yes  No Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 160 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-37

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/21/08 Signature: [Signature] Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Media Center Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Phoenix, AZ 85226

Material Code: M-APL-39 Damaged:  Yes  No Friable  Non-Friable

General Description: Acoustical Ceiling Panel Visible  Covered  Size: 2' x 2'

Matrix/Primary Color: Yellow Texture/Pattern: Fibrous Glass Cover/Secondary Color: Cloth Cover

Quantity of Material: 3,600 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/21/08 Signature: *[Signature]* Date: 05/21/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center Building    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-Twp-410     Visible     Damaged:  Yes     No     Friable     Non-Friable  
 Covered

**General Description:** Tackable Wall Panel    **Size:** N/A

**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** Vinyl-Cover

**Quantity of Material:** 300     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 08-166    **Project Name:** AHERA-Compliance Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Media Center Building    **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School    Phoenix, AZ 85226

**Material Code:** M-SCT-41     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Sealant (Duct)    **Size:** N/A

**Matrix/Primary Color:** Gray    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 150    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313    **State License:** EPA    **AHERA Certificate No.:** D10790    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 05/21/08    **Signature:** *[Signature]*    **Date:** 05/21/08

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MEDIA CENTER Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.G.H.42 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: GLAZED WALL TILE (PARTIAL) Size: 4"x4"

Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *SM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MEDIA CENTER Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GWT-43 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"

Matrix/Primary Color: BLACK Texture/Pattern: SMOOTH Cover/Secondary Color: NA  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MEDIA CENTER Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GLAZ-44 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"  
 Matrix/Primary Color: BLUE Texture/Pattern: STRIATA Cover/Secondary Color: N/A  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-BUR-01 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY MINERAL CAP  
 Quantity of Material: 20,000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Silver

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.MAS.02 Damaged:  Yes  No Friable  Non-Friable

General Description: MASTIC (PENETRATIONS & FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: SILVER

Quantity of Material: 1500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: CM Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-03 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: SEALANT (FLASHING) Visible  Covered  Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A  
 Quantity of Material: 125 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-04 Damaged:  Yes  No Friable  Non-Friable   
 General Description: SEALANT (Doors, Windows, Walls) Visible  Covered  Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A  
 Quantity of Material: 300 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	EXTERIOR	NE Corner	W 0'	S 5'	3"	F / W / C / O
B	EXTERIOR	SE Corner	W 0'	N 5'	3"	F / W / C / O
C	EXTERIOR	NW Corner	E 0'	S 2'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CMULOS Damaged:  Yes  No Friable  Non-Friable   
 General Description: CONCRETE MASONRY UNIT Visible  Covered  Size: 8" x 16"

Matrix/Primary Color: PINK Texture/Pattern: CEMENTIOUS Cover/Secondary Color: ROUGH  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CMU-06 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE MASONRY UNIT Size: 4" x 16"

Matrix/Primary Color: PINK Texture/Pattern: CEMENTIOUS Cover/Secondary Color: ROUGH  
 Quantity of Material: 10,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CMU-07 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE MASONRY UNIT Size: 8"x16"

Matrix/Primary Color: PINK Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: SMOOTH  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: MCMU-08 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE MASONRY UNIT Size: 4" x 16"

Matrix/Primary Color: PINK Cover/Secondary Color: SMOOTH  
 Quantity of Material: 9,500 Estimated By:  Drawing  Field Measure  
 Texture/Pattern: CEMENTIOUS  Sampled  Assumed  
 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-WRT-09 Material Code: M-WRT-09  
 Damaged:  Yes  No Friable  Non-Friable   
 Visible Covered   Size: N/A

General Description: MORTAR  
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 12,000 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U.O.S, M.C.M.U.O.S, M.C.M.U.O.S, M.C.M.U.Z1

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: CR Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose / Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SCT-10 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: SEALANT (Duct) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: +SD Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: W-SLT-11 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: SEALANT (Duct) Texture/Pattern: PLAIN Size: N/A  
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A  
 Quantity of Material: 50 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-PES-12 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: PIPE-END SEALANT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: 20 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: W-WDB-13 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: WOVEN DUCT BOOT Size: 2"

Matrix/Primary Color: BLACK Texture/Pattern: RUBBER-LIKE Cover/Secondary Color: N/A

Quantity of Material: 20 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-BUR-14 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: BUILT-UP ROOFING Size: N/A  
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY/BLACK  
 Quantity of Material: 2000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Silver

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-WAS-15 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: MASTIC (PENETRATIONS & FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By:  Drawing  Field Measure  
 Texture/Pattern: IAR-LIKE  LF / EA  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Silver

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *Cal* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.CON.16 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE (ENTRIES) Visible  Covered  Size: N/A  
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 08-1066 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28  
**Building No.:** Multipurpose 1 **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School Chandler, AZ 85226

**Material Code:** M-CON-17 **Damaged:**  Yes  No  Friable  Non-Friable  
**General Description:** CONCRETE (FOUNDATION) **Visible Covered:**  Visible  Covered **Size:** 2 1/4  
**Matrix/Primary Color:** GRAY **Texture/Pattern:** CEMENTITIOUS **Cover/Secondary Color:** N/A  
**Quantity of Material:** 35,000 **Estimated By:**  Drawing  Field Measure  Sampled  Assumed  
**Homogeneous Material Location:**  Ceiling  Floor  Wall  Other

**Manner of Sampling:**  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	EXTERIOR	NE Corner	W 0'	S 0'	0'	F/W/C/O
B	EXTERIOR	NW Corner	E 0'	S 0'	0'	F/W/C/O
C	EXTERIOR	SE Corner	W 0'	N 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:**

**Lead Inspector:** Dane Thompson **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA  
**Signature:** *[Signature]* **Date:** 05/19/08 **Signature:** *[Signature]* **Date:** 05/19/08

**Asbestos-Containing Material:**  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CON-18 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE (COLUMNS) Visible Covered:  Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-STU-19 Damaged:  Yes  No Friable  Non-Friable   
 Visible Covered   Size: N/A

General Description: STUCCO Texture/Pattern: CEMENTITIONS Cover/Secondary Color: N/A  
 Matrix/Primary Color: GRAY Estimated By:  Drawing  Field Measure  
 Quantity of Material: 3300 (SF) / LF / EA  Sampling Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-MRT-20 Damaged:  Yes  No Friable  Non-Friable   
 General Description: MORTAR Visible  Covered  Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 5 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.C.M.U. 21 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE MASONRY UNIT (PATTERN) Size: 12" X 12"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 800 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-APL-22 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: ACOUSTICAL CEILING PANELS Size: 2'X2'

Matrix/Primary Color: GRAY Texture/Pattern: PINHOLES & FISSURES Cover/Secondary Color: WHITE  
 Quantity of Material: 16000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	OFFICE 01	NE Corner	W 0'	S 0'	10'	F / W / C / O
B	CORRIDOR 01	SW Corner	E 0'	N 0'	10'	F / W / C / O
C	P.E. STORAGE	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-1066 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-SAT-23 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: SPRAY-APPLIED TEXTURE Size: N/A

Matrix/Primary Color: WHITE Cover/Secondary Color: N/A

Quantity of Material: 10.000 Estimated By:  Drawing  Sampled  Assumed  
 Texture/Pattern: CHALKY  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BAND ROOM	SE Corner	W 0'	N 7'	3'	F/W/C/O
B	OFFICE 01	SE Corner	W 0'	N 4'	3'	F/W/C/O
C	BOYS COACH OFFICE	SW Corner	E 0'	N 6'	3'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GLOB-24 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GYPSUM WALLBOARDS Visible  Covered  Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A  
 Quantity of Material: 10,000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BAND ROOM	SE Corner	W 0'	N 7'	3'	F / W / C / O
B	OFFICE 01	SE Corner	W 0'	N 4'	3'	F / W / C / O
C	BOYS COACH OFFICE	SW Corner	E 0'	N 6'	3'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.23

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S.JC.25 Damaged:  Yes  No Friable  Non-Friable   
 General Description: JOINT COMPOUND Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A  
 Quantity of Material: 1,000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BAND ROOM	SE Corner	W 0'	N 7'	3'	F / W / C / O
B	OFFICE 01	SE Corner	W 0'	N 4'	3'	F / W / C / O
C	BOYS COACH OFFICE	SW Corner	E 0'	N 6'	3'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWB.24

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-TWP-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: TACKABLE WALLPANEL Visible Covered  Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FIBERS GLASS Cover/Secondary Color: CLOTH COVER  
 Quantity of Material: 200 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.CPT.27 Damaged:  Yes  No Friable  Non-Friable   
 General Description: CARPET (SELF-STICK) Visible Covered  Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: MULTICOLORED  
 Quantity of Material: 5500 Estimated By:  Drawing  Sampled   
 SF / LF / EA  Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR 02	NE Corner	W 0'	S 5'	0'	(F) W / C / O
B	HEALTH CLASS ROOM	NW Corner	E 3'	S 0'	0'	(F) W / C / O
C	LOBBY	SW Corner	E 0'	N 0'	0'	(F) W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-WAB-28 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: WAUBASE (COVERED) Size: 4"

Matrix/Primary Color: GRAY Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A  
 Quantity of Material: 400 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BAND ROOM	SE Corner	W O'	N O'	4"	F / W / C / O
B	P.E. STORAGE	SW Corner	E O'	N O'	4"	F / W / C / O
C	BOYS STORAGE	SE Corner	W O'	N O'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DN* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-ADH-29 Damaged:  Yes  No Friable  Non-Friable   
 General Description: ADHESIVE Visible Covered  WAB Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: BRITTLE Cover/Secondary Color: N/A  
 Quantity of Material: 400 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BAND ROOM	SE Corner	W 0'	N 0'	4"	F / W / C / O
B	P.E. STORAGE	SW Corner	E 0'	N 0'	4"	F / W / C / O
C	BOYS STORAGE	SE Corner	W 0'	N 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-28

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15574 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 08-106 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SAC-30 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: SINK ACOUSTICAL COATING Size: N/A  
 Matrix/Primary Color: GRAY Texture/Pattern: ROUGH Cover/Secondary Color: N/A  
 Quantity of Material: 6 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-1166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-31 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: SEALANT (Doors, Windows, Millwork, Fixtures) Size: N/A  
 Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	BAND ROOM	SE Corner	W 0' 0'	N 0'	3"	F / W / C / O
B	GYM STORAGE	SW Corner	E 0' 0'	N 0'	3"	F / W / C / O
C	CORRIDOR 010	NE Corner	W 0' 0'	S 0'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.FD1.3Z Damaged:  Yes  No  Friable  Non-Friable  
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL/WOOD CLADDING Cover/Secondary Color: N/A  
 Quantity of Material: 2484 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S.SAS.33 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: SPRAY-APPLIED TEXTURE Size: N/A

Matrix/Primary Color: WHITE Cover/Secondary Color: N/A  
 Quantity of Material: 900 Estimated By:  Drawing  Sampled  
 Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR 05	SW Corner	E 0'	N 0'	3"	F/W/C/O
B	CORRIDOR 02	NE Corner	W 0'	S 0'	3"	F/W/C/O
C	CORRIDOR 06	SW Corner	E 0'	N 0'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GWB-34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: GYPSUM WALLBOARD Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A  
 Quantity of Material: 900 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR 05	SW Corner	E 0'	N 0'	3"	F / W / C / O
B	CORRIDOR 02	NE Corner	W 0'	S 0'	3"	F / W / C / O
C	CORRIDOR 06	SW Corner	E 0'	N 0'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-33

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-35 Damaged:  Yes  No Friable  Non-Friable   
 General Description: JOINT COMPOUND Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A  
 Quantity of Material: 900 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR 05	SW Corner	0'	0'	3"	F/W/C/O
B	CORRIDOR 02	NE Corner	0'	0'	3"	F/W/C/O
C	CORRIDOR 06	SW Corner	0'	0'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH W.G.W.B.34

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: CM Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-DAT-36 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: SPRAY-APPLIED TEXTURE Size: 1/4

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A

Quantity of Material: 1400 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 (SF) LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GWJB-57 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Gypsum Wallboard Size: 1/4

Matrix/Primary Color: White Texture/Pattern: Stalky Cover/Secondary Color: 1/4  
 Quantity of Material: 1400 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH 5-SAT-34

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose I Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: S-JIC-38 Material Code:  Visible  Covered SAT Damaged:  Yes  No  Friable  Non-Friable  
 General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A  
 Quantity of Material: 1400 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.GWB-37

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-106 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GWT.39 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: NK  
 Quantity of Material: 700 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Pattern

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: *GM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.cmf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GRT-40 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: GRAB Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A

Quantity of Material: 700 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-69, M-GWT-70 & M-GWT-71

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: W.C.M.T. 41 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CERAMIC MOSAIC TILE Size: 2"X2"

Matrix/Primary Color: GRAY Cover/Secondary Color: MULTICOLORED SPOTS  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GRI.42 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GROWS Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 200 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CMT-41

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-APL-43 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x2'

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: VINYL COVER  
 Quantity of Material: 2500 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN	SE Corner	W 0'	N 0'	10'	F / W / C / O
B	SERVING AREA	SW Corner	E 0'	N 0'	10'	F / W / C / O
C	CORRIDOR D4	NE Corner	W 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

19974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GUOT-44 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GLAZED WALL TILE (COVERED) Size: 4" X 8"

Matrix/Primary Color: GRAY Cover/Secondary Color: MULTICOLORED SPOTS  
 Quantity of Material: 200 Estimated By:  Drawing  Field Measure  
 Texture/Pattern: SMOOTH (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GRT.415 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GROUT Visible  Covered  Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 200 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWT.444

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: CA Date: 05/19/08 Signature: MW Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 08-166 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28  
**Building No.:** Multipurpose **Address:** 777 N. Desert Breeze Boulevard East #2  
**Campus Name:** Kyrene Aprende Middle School Chandler, AZ 85226

**Material Code:** M-QPT-46 **Damaged:**  Yes  No  Friable  Non-Friable  
**General Description:** QUARRY/PAVER TILE **Size:** 12"X12"

**Matrix/Primary Color:** GRAY **Cover/Secondary Color:** MULTICOLORED SPOTS  
**Quantity of Material:** 2500 **Estimated By:**  Drawing  Field Measure  
**Texture/Pattern:** SMOOTH **Cover/Secondary Color:** MULTICOLORED SPOTS

**Homogeneous Material Location:**  Ceiling  Floor  Wall  Other

**Manner of Sampling:**  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson **Secondary Inspector:** Michael Richter  
**AHERA Certificate No.:** D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA  
**Signature:** *[Signature]* **Date:** 05/19/08 **Signature:** *[Signature]* **Date:** 05/19/08

**Asbestos-Containing Material:**  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GRT.47 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered   Size: N/A

General Description: GROUT Texture/Pattern: GRANULOUS Cover/Secondary Color: N/A  
 Matrix/Primary Color: GRAY Estimated By:  Drawing  Field Measure  
 Quantity of Material: 250 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.OPT.46

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-48 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered:   Size: N/A

General Description: SEALANT (WINDOWS) Texture/Pattern GUMM Cover/Secondary Color: N/A  
 Matrix/Primary Color: BLACK Estimated By:  Drawing  Field Measure  
 Quantity of Material: 3 (SF / LF / EA)

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Windows

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: CR Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: MADH.49 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered  No

General Description: ADHESIVE Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A

Quantity of Material: 20 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH FIBER GLASS REINFORCED PANEL, WHITE, TEXTURED

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-QPT-50 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: QUARRY / PAVER TILE Size: 12" X 12"  
 Matrix/Primary Color: GRAY Texture/Pattern: TEXTURED Cover/Secondary Color: BLACK STREAKS  
 Quantity of Material: 6000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GRT.SJ Damaged:  Yes  No Friable  Non-Friable   
 Visible  Covered  Size: N/A

General Description: GROUT Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Matrix/Primary Color: GRAY Estimated By:  Drawing  Field Measure  
 Quantity of Material: 600 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W. OPT. 50

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-VST-SZ Damaged:  Yes  No  Friable  Non-Friable  
 General Description: VINYL STAIR TRAIL Size: 12" X 48"

Matrix/Primary Color: GRAY Texture/Pattern: Vinyl-Like Cover/Secondary Color: Circle Pattern  
 Quantity of Material: 50 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.omf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: MAS-53 Visible Covered  Visible Covered  Damaged:  Yes  No  Friable  Non-Friable

General Description: Mastic Size: 2/4

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-UST-52

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: DM Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-VCT-54 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: VINYL COMPOSITION TILE Size: 12"X12"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: BROWN MOTTLES  
 Quantity of Material: 600 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STAGE	SW Corner	E 3'	N 0'	0'	F/W/C/O
B	MULTIPURPOSE	SW Corner	E 0'	N 0'	0'	F/W/C/O
C	JANITOR 01	SW Corner	E 0'	N 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.MAS.55 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: MASTIC Visible Covered  YCT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Br. + Gb Cover/Secondary Color: N/A  
 Quantity of Material: 6000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STAGE	SW Corner	E 3'	N 0'	0'	F/W/C/O
B	MULTIPURPOSE	SW Corner	E 0'	N 0'	0'	F/W/C/O
C	JANITOR 01	SW Corner	E 0'	N 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH W.VCT.54

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-106 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.TWP.56 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: TACKABLE WALL PANEL Visible Covered   Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER  
 Quantity of Material: 750 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STRINGS 401	NE Corner	W 0'	S 5'	5"	F/W/C/O
B	STRINGS 401	SE Corner	W 5'	N 0'	5"	F/W/C/O
C	STRINGS 401	SW Corner	E 0'	N 5'	5"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-WAB-57 Damaged:  Yes  No Friable  Non-Friable   
 General Description: WALL BASE (L-SHAPED) Visible Covered   Size: 4"

Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A  
 Quantity of Material: 1SD Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	GYMNASIUM	NE Corner	W 0'	S 0'	4"	F/W/C/O
B	GYMNASIUM	SE Corner	W 0'	N 0'	4"	F/W/C/O
C	GYMNASIUM	NW Corner	E 0'	S 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15574 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-ADH-SB Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered WAS Size: N/A

General Description: ADHESIVE Texture/Pattern: PUABLE Cover/Secondary Color: N/A  
 Matrix/Primary Color: CREAM Estimated By:  Drawing  Field Measure  
 Quantity of Material: 150 (SF) LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	GYMNASIUM	NE Corner	W O'	S O'	4"	F / W / C / O
B	GYMNASIUM	SE Corner	W O'	N O'	4"	F / W / C / O
C	GYMNASIUM	NW Corner	E O'	S O'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. WAS-57

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: CM Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-59 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: Sealant (Fire stop) Size: N/A  
 Matrix/Primary Color: Red Cover/Secondary Color: N/A  
 Quantity of Material: 10 Estimated By:  Drawing  Field Measure  
 Texture/Pattern:  LF / EA  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *DM* Date: 05/19/08 Signature: *MR* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



19974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-60 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant (Equipment) Visible Covered:   Size: N/A

Matrix/Primary Color: Black Texture/Pattern: GUMMY Cover/Secondary Color: N/A  
 Quantity of Material: 10 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: *[Signature]* Date: 05/19/08 Signature: *[Signature]* Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-SLT-61 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: SEALANT (EQUIPMENT) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FRIABLE Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-CPT-62 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered   Size: N/A

General Description: CARPET Texture/Pattern: FIBROUS Cover/Secondary Color: N/A  
 Matrix/Primary Color: BROWN Estimated By:  Drawing  Field Measure  
 Quantity of Material: 750 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: \_\_\_\_\_ Date: 05/19/08 Signature: \_\_\_\_\_ Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.OPT. 003 Damaged:  Yes  No Friable  Non-Friable

General Description: QUARRY PAVEMENT Size: 12" x 12"

Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: MULTICOLORED SPECKS

Quantity of Material: 50 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GRT.64 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GROUT Visible Covered   Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 5 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.O.P.T. 03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.omf



Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: MVSF-65 Damaged:  Yes  No Friable  Non-Friable   
 General Description: VINYL SHEET FLOORING Size: N/A

Matrix/Primary Color: TAN Cover/Secondary Color: BROWN MOTILES  
 Quantity of Material: 500 Estimated By:  Drawing  Field Measure  
 Texture/Pattern: SMOOTH (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: GRAY PAPER BACKING

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



19974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-116 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.M.A.S.L.C.L.C. Damaged:  Yes  No  Friable  Non-Friable  
 General Description: MASTIC Visible Covered  VSF Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A  
 Quantity of Material: 500 (SF) LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.S.F.C.S

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHJERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GWT-67 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A  
 Quantity of Material: 100 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



19974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.amf

Project No.: 08-116 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Multipurpose Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M.GRT.608 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered:   Size: N/A

General Description: GROUT Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A  
 Matrix/Primary Color: GRAY Estimated By:  Drawing  Field Measure  
 Quantity of Material: 10 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.GWT.607

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MULLER-PURPOSE Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GUST-69 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: GLAZED WALL TILE (PATTERN) Size: 4'x4'

Matrix/Primary Color: GRAY Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 300 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-166 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: 1051-POPPS Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-657.70 Damaged:  Yes  No Friable  Non-Friable   
 General Description: GLAZED WALL TILE (PATTERN) Size: 4' x 4'  
 Matrix/Primary Color: BLACK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A  
 Quantity of Material: 300 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 08-1466 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: MJA1 - PURPOSE Address: 777 N. Desert Breeze Boulevard East #2  
 Campus Name: Kyrene Aprende Middle School Chandler, AZ 85226

Material Code: M-GUST-71 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: GLAZED WALL TILE Size: 4'x4'

Matrix/Primary Color: BLUE Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 300 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter  
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA  
 Signature: [Signature] Date: 05/19/08 Signature: [Signature] Date: 05/19/08

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

## **APPENDIX B**

### **Bulk-Material Sample Documents**

- **Chain-of-Custodies**
- **Laboratory Analysis**





15974 N. 77<sup>th</sup> Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

3

PA

# chain of custody

Date: 5/22/08  
 Project No: 08-166  
 Initials: Dave Thom  
 Page: 1 of 1

Job: Kyrone Apronche Middle School  
 Client: KSD  
 Address: 777 N. Desert Bruce Blvd  
Chandler, AZ 85225

Test: PLM 10-15  
 Rush:  Normal:  Extended:   
 Stop at 1st Positive:  UNO  
 Read all samples:   
 Call with results:   
 Fax results:

Main Building

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-SLT-19	Sealant	A - C	S
M. APL-21	Acoustical Ceiling Panel		
S-SAT-22	Spray-Applied Texture		
M. GWB-23	Gypsum Wallboard		
S-JTC-24	Joint Compound		
M-TWP-25	Tackable Wall Panel		
M-CPT-26	Carpet		
M-VCT-27	Vinyl Composition Tile		
M-MAS-28	Mastic		
M-WAB-29	Wallbase		
M-ADH-30	Adhesive		
M-SLT-34	Sealant		
S-SAT-42	Spray-Applied Texture		
M-LWB-43	Gypsum Wallboard		
S-JTC-44	Joint Compound		

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
	5/22/08		5/22/08
	5/28/08		5-28-08



**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200804816

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

**# Samples:** 47 PLM **Rec:** 5/28/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

**Client Job:** Kyrene Aprende Middle Sch-Main Bldg

**PO Number:** 08-166

**Report Date:** 6/17/2008

**Date Analyzed:** 6/16/2008

**Routing Number:** -

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.  
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200804816**

Kyrene Aprende Middle Sch-Main Bldg

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # <b>M-SLT-19A</b> Layer # 1 white caulk	2008-04816- 1	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-19B</b> Layer # 1 white caulk	2008-04816- 2	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-19C</b> Layer # 1 white caulk	2008-04816- 3	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-21A</b> Layer # 1 off-white ceiling tile	2008-04816- 4	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-21B</b> Layer # 1 off-white ceiling tile	2008-04816- 5	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-21C</b> Layer # 1 off-white ceiling tile	2008-04816- 6	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-22A</b> Layer # 1 white texture/joint compound	2008-04816- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-22B</b> Layer # 1 white texture/joint compound	2008-04816- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-22C</b> Layer # 1 white texture/joint compound	2008-04816- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-23A</b> Layer # 1 white drywall core	2008-04816- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-23B</b> Layer # 1 white drywall core	2008-04816- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-23C</b> Layer # 1 white drywall core	2008-04816- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-24A</b> Layer # 1 white texture/joint compound	2008-04816- 13	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-24B</b> Layer # 1 white texture/joint compound	2008-04816- 14	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-24C</b> Layer # 1 white texture/joint compound	2008-04816- 15	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-TWP-25A</b> Layer # 1 Tan surface	2008-04816- 16	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-TWP-25B</b> Layer # 1 Tan surface	2008-04816- 17	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-TWP-25C</b> Layer # 1 Tan panel	2008-04816- 18	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-26A</b> Layer # 1 various carpet	2008-04816- 19	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-26B</b> Layer # 1 various carpet	2008-04816- 20	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-26C</b> Layer # 1 various carpet	2008-04816- 21	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-27A</b> Layer # 1 off-white floor tile	2008-04816- 22	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-27B</b> Layer # 1 off-white floor tile	2008-04816- 23	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-27C</b> Layer # 1 off-white floor tile	2008-04816- 24	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-28A</b> Layer # 1 tan mastic	2008-04816- 25	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-28B</b> Layer # 1 tan mastic	2008-04816- 26	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-28C</b> Layer # 1 tan mastic	2008-04816- 27	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-29A</b> Layer # 1 Gray base cove	2008-04816- 28	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-29B</b> Layer # 1 Gray base cove	2008-04816- 29	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-29C</b> Layer # 1 Gray base cove	2008-04816- 30	Wall System <i>no asbestos detected</i>	Positive Layer? No

Sample #	<b>M-ADH-30A</b>	2008-04816- 31	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Off-white mastic			
Sample #	<b>M-ADH-30B</b>	2008-04816- 32	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Off-white mastic			
Sample #	<b>M-ADH-30C</b>	2008-04816- 33	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Off-white mastic			
Sample #	<b>M-SLT-34A</b>	2008-04816- 34	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Black caulk			
Sample #	<b>M-SLT-34B</b>	2008-04816- 35	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Black caulk			
Sample #	<b>M-SLT-34C</b>	2008-04816- 36	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Black caulk			
Sample #	<b>S-SAT-42A</b>	2008-04816- 37	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white texture/joint compound			
Sample #	<b>S-SAT-42B</b>	2008-04816- 38	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white texture/joint compound			
Sample #	<b>S-SAT-42C</b>	2008-04816- 39	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white texture/joint compound			
Sample #	<b>M-GWB-43A</b>	2008-04816- 40	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white drywall core			
Sample #	<b>M-GWB-43B</b>	2008-04816- 41	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white drywall core			
Sample #	<b>M-GWB-43C</b>	2008-04816- 42	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white drywall core			
Sample #	<b>S-JTC-44A</b>	2008-04816- 43	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white texture/joint compound			
Sample #	<b>S-JTC-44B</b>	2008-04816- 44	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white texture/joint compound			
Sample #	<b>S-JTC-44C</b>	2008-04816- 45	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white texture/joint compound			
Sample #	<b>M-TWP-25A-2</b>	2008-04816- 46	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Tan panel			
Sample #	<b>M-TWP-25B-2</b>	2008-04816- 47	Wall System <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Tan panel			

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**Sample** M-SLT-19A      **Lab Number** 2008-04816- 1      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/16/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-19B      **Lab Number** 2008-04816- 2      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/16/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-19C      **Lab Number** 2008-04816- 3      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/16/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-APL-21A      **Lab Number** 2008-04816- 4      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>			<b>Average %</b>					
Fiber Identification:					cellulose fiber	glass fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-21B      **Lab Number** 2008-04816- 5      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>			<b>Average %</b>					
Fiber Identification:					cellulose fiber	glass fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-21C      **Lab Number** 2008-04816- 6      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>			<b>Average %</b>					
Fiber Identification:					cellulose fiber	glass fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** S-SAT-22A      **Lab Number** 2008-04816-7      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-22B      **Lab Number** 2008-04816-8      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-22C      **Lab Number** 2008-04816-9      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-GWB-23A      **Lab Number** 2008-04816- 10      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** M-GWB-23B      **Lab Number** 2008-04816- 11      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** M-GWB-23C      **Lab Number** 2008-04816- 12      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps.



**Sample** S-JTC-24A      **Lab Number** 2008-04816- 13      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-24B      **Lab Number** 2008-04816- 14      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-24C      **Lab Number** 2008-04816- 15      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-TWP-25A      **Lab Number** 2008-04816- 16      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Tan	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		10-20%	10-20%	-	-	-	-

Fiber Identification: synthetic fiber (extr cellulose fiber

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	synthetic fiber (extruded)	W	E	N	N	H	+	P						
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core is analyzed as sample M-TWP-25A-2.

**Sample** M-TWP-25B      **Lab Number** 2008-04816- 17      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Tan	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		10-20%	10-20%	-	-	-	-

Fiber Identification: synthetic fiber (extr cellulose fiber

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	synthetic fiber (extruded)	W	E	N	N	H	+	P						
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core is analyzed as sample M-TWP-25B-2.

**Sample** M-TWP-25C      **Lab Number** 2008-04816- 18      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/16/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		90-100%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. No surface on this sample.

**Sample** M-CPT-26A      **Lab Number** 2008-04816- 19      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	50-60%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	-	-	-	-	-
<b>Fiber Identification:</b>					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CPT-26B      **Lab Number** 2008-04816- 20      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	50-60%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	-	-	-	-	-
<b>Fiber Identification:</b>					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CPT-26C      **Lab Number** 2008-04816- 21      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	50-60%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	-	-	-	-	-
<b>Fiber Identification:</b>					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200804816**

Kyrene Aprende Middle Sch-Main Bldg

**Sample** M-VCT-27A      **Lab Number** 2008-04816- 22      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-27B      **Lab Number** 2008-04816- 23      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-27C      **Lab Number** 2008-04816- 24      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-28A      **Lab Number** 2008-04816- 25      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	>1-2%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		>1-2%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-28B      **Lab Number** 2008-04816- 26      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	>1-2%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		>1-2%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-28C      **Lab Number** 2008-04816- 27      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	2-5%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		2-5%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-29A      **Lab Number** 2008-04816- 28      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-29B      **Lab Number** 2008-04816- 29      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-29C      **Lab Number** 2008-04816- 30      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-30A      **Lab Number** 2008-04816- 31      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-30B      **Lab Number** 2008-04816- 32      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-30C      **Lab Number** 2008-04816- 33      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-34A      **Lab Number** 2008-04816- 34      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-34B      **Lab Number** 2008-04816- 35      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-34C      **Lab Number** 2008-04816- 36      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	2-5%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		2-5%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U				
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



**PLM Analysis Details**

**Job Number: 200804816**

Kyrene Aprende Middle Sch-Main Bldg

**Sample** S-SAT-42A      **Lab Number** 2008-04816- 37      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-42B      **Lab Number** 2008-04816- 38      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-42C      **Lab Number** 2008-04816- 39      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-GWB-43A      **Lab Number** 2008-04816- 40      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** M-GWB-43B      **Lab Number** 2008-04816- 41      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** M-GWB-43C      **Lab Number** 2008-04816- 42      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** S-JTC-44A      **Lab Number** 2008-04816- 43      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-44B      **Lab Number** 2008-04816- 44      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-44C      **Lab Number** 2008-04816- 45      **Sampled:** 5/22/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-TWP-25A-2 Lab Number 2008-04816- 46 Sampled: 5/22/2008 Condition: acceptable  
 Analyzed By RAM 6/16/2008 An? OK Apparent Smp Type Wall System Fibrous Mat  
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		90-100%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweazed apart using forceps.

Sample M-TWP-25B-2 Lab Number 2008-04816- 47 Sampled: 5/22/2008 Condition: acceptable  
 Analyzed By RAM 6/16/2008 An? OK Apparent Smp Type Wall System Fibrous Mat  
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		90-100%	-	-	-	-	-


Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweazed apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable  
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various  
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;  
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper  
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High  
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining  
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.  
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 17-Jun-08

Original Print Date: 17-Jun-08



Larry S. Pierce, Approved Accreditation Signatory





**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200804817

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ

85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

**# Samples:** 47 PLM **Rec:** 5/28/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

**Client Job:** Kyrene Aprende Middle Sch/Media Ctr Bldg

**PO Number:** 08-166

**Report Date:** 6/17/2008

**Date Analyzed:** 6/17/2008

**Routing Number:** -

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.  
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200804817**

Kyrene Aprende Middle Sch/Media Ctr B

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # <b>M-SLT-15A</b> Layer # 1 Black caulk	2008-04817- 1	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-15B</b> Layer # 1 Black caulk	2008-04817- 2	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-15C</b> Layer # 1 Black caulk	2008-04817- 3	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-16A</b> Layer # 1 off-white ceiling tile	2008-04817- 4	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-16B</b> Layer # 1 off-white ceiling tile	2008-04817- 5	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-16C</b> Layer # 1 off-white ceiling tile	2008-04817- 6	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-17A</b> Layer # 1 white texture/joint compound	2008-04817- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-17B</b> Layer # 1 white texture/joint compound	2008-04817- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-17C</b> Layer # 1 white texture/joint compound	2008-04817- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-18A</b> Layer # 1 white drywall core	2008-04817- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-18B</b> Layer # 1 white drywall core	2008-04817- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-18C</b> Layer # 1 white drywall core	2008-04817- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-19A</b> Layer # 1 white texture/joint compound	2008-04817- 13	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-19B</b> Layer # 1 white texture/joint compound	2008-04817- 14	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-19C</b> Layer # 1 white texture/joint compound	2008-04817- 15	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-TWP-20A</b> Layer # 1 Various surface	2008-04817- 16	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-TWP-20B</b> Layer # 1 Tan panel	2008-04817- 17	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-TWP-20C</b> Layer # 1 Various surface	2008-04817- 18	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-21A</b> Layer # 1 off-white floor tile	2008-04817- 19	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-21B</b> Layer # 1 off-white floor tile	2008-04817- 20	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-21C</b> Layer # 1 off-white floor tile	2008-04817- 21	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-22A</b> Layer # 1 tan mastic	2008-04817- 22	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-22B</b> Layer # 1 tan mastic	2008-04817- 23	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-22C</b> Layer # 1 tan mastic	2008-04817- 24	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-23A</b> Layer # 1 Gray base cove	2008-04817- 25	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-23B</b> Layer # 1 Gray base cove	2008-04817- 26	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-23C</b> Layer # 1 Gray base cove	2008-04817- 27	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-24A</b> Layer # 1 Off-white mastic	2008-04817- 28	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-24B</b> Layer # 1 Off-white mastic	2008-04817- 29	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-24C</b> Layer # 1 Off-white mastic	2008-04817- 30	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No



Sample #	<b><u>M-SLT-25A</u></b>	2008-04817- 31	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>M-SLT-25B</u></b>	2008-04817- 32	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>M-SLT-25C</u></b>	2008-04817- 33	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>S-SAT-26A</u></b>	2008-04817- 34	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>S-SAT-26B</u></b>	2008-04817- 35	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>S-SAT-26C</u></b>	2008-04817- 36	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>M-GWB-27A</u></b>	2008-04817- 37	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>M-GWB-27B</u></b>	2008-04817- 38	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>M-GWB-27C</u></b>	2008-04817- 39	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>S-JTC-28A</u></b>	2008-04817- 40	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>S-JTC-28B</u></b>	2008-04817- 41	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>S-JTC-28C</u></b>	2008-04817- 42	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	white			
Sample #	<b><u>M-CPT-34A</u></b>	2008-04817- 43	Carpet <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	various			
Sample #	<b><u>M-CPT-34B</u></b>	2008-04817- 44	Carpet <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	various			
Sample #	<b><u>M-CPT-34C</u></b>	2008-04817- 45	Carpet <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	various			
Sample #	<b><u>M-TWP-20A-2</u></b>	2008-04817- 46	Wall System panel <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Tan			
Sample #	<b><u>M-TWP-20C-2</u></b>	2008-04817- 47	Wall System panel <i>no asbestos detected</i>	Positive Layer? No
Layer # 1	Tan			

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**Sample** M-SLT-15A      **Lab Number** 2008-04817- 1      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-15B      **Lab Number** 2008-04817- 2      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-15C      **Lab Number** 2008-04817- 3      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-APL-16A      **Lab Number** 2008-04817- 4      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-16B      **Lab Number** 2008-04817- 5      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-16C      **Lab Number** 2008-04817- 6      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** S-SAT-17A      **Lab Number** 2008-04817-7      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-17B      **Lab Number** 2008-04817-8      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-17C      **Lab Number** 2008-04817-9      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-GWB-18A      **Lab Number** 2008-04817- 10      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers								Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** M-GWB-18B      **Lab Number** 2008-04817- 11      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers								Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** M-GWB-18C      **Lab Number** 2008-04817- 12      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers								Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps.

**Sample** S-JTC-19A      **Lab Number** 2008-04817- 13      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-19B      **Lab Number** 2008-04817- 14      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-19C      **Lab Number** 2008-04817- 15      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200804817**

Kyrene Aprende Middle Sch/Media Ctr

**Sample** M-TWP-20A      **Lab Number** 2008-04817- 16      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Various	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		10-20%	10-20%	-	-	-	-

**Fiber Identification:** synthetic fiber (extr cellulose fiber)

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P						
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core ls analyzed as sample M-TWP-20A-2.

**Sample** M-TWP-20B      **Lab Number** 2008-04817- 17      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		90-100%	-	-	-	-	-

**Fiber Identification:** cellulose fiber

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. No surface.

**Sample** M-TWP-20C      **Lab Number** 2008-04817- 18      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Various	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		10-20%	10-20%	-	-	-	-

**Fiber Identification:** synthetic fiber (extr cellulose fiber)

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P						
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core is analyzed as sample M-TWP-20A-2.

**Sample** M-VCT-21A      **Lab Number** 2008-04817- 19      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-21B      **Lab Number** 2008-04817- 20      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-21C      **Lab Number** 2008-04817- 21      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



**PLM Analysis Details**

**Job Number: 200804817**

Kyrene Aprende Middle Sch/Media Ctr

**Sample** M-MAS-22A      **Lab Number** 2008-04817- 22      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>

Fiber Identification: hair

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	hair	BR	E	N									
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-22B      **Lab Number** 2008-04817- 23      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-22C      **Lab Number** 2008-04817- 24      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	>1-2%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&gt;1-2%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-23A      **Lab Number** 2008-04817- 25      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-23B      **Lab Number** 2008-04817- 26      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-23C      **Lab Number** 2008-04817- 27      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-24A      **Lab Number** 2008-04817- 28      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-24B      **Lab Number** 2008-04817- 29      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-24C      **Lab Number** 2008-04817- 30      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-25A      **Lab Number** 2008-04817- 31      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-25B      **Lab Number** 2008-04817- 32      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-25C      **Lab Number** 2008-04817- 33      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** S-SAT-26A      **Lab Number** 2008-04817- 34      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-26B      **Lab Number** 2008-04817- 35      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-26C      **Lab Number** 2008-04817- 36      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-GWB-27A      **Lab Number** 2008-04817- 37      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-
<b>Fiber Identification:</b>					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps.

**Sample** M-GWB-27B      **Lab Number** 2008-04817- 38      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-
<b>Fiber Identification:</b>					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps.

**Sample** M-GWB-27C      **Lab Number** 2008-04817- 39      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-
<b>Fiber Identification:</b>					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps.

**PLM Analysis Details**

**Job Number: 200804817**

Kyrene Aprende Middle Sch/Media Ctr

**Sample** S-JTC-28A      **Lab Number** 2008-04817- 40      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-28B      **Lab Number** 2008-04817- 41      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-28C      **Lab Number** 2008-04817- 42      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-CPT-34A      **Lab Number** 2008-04817- 43      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	50-60%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	-	-	-	-	-

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CPT-34B      **Lab Number** 2008-04817- 44      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	50-60%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	-	-	-	-	-

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CPT-34C      **Lab Number** 2008-04817- 45      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	50-60%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	-	-	-	-	-

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



**Sample** M-TWP-20A-2      **Lab Number** 2008-04817- 46      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		90-100%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweazed apart using forceps.

**Sample** M-TWP-20C-2      **Lab Number** 2008-04817- 47      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		90-100%	-	-	-	-	-


Fiber Identification: cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweazed apart using forceps.


Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable  
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various  
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;  
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper  
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High  
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining  
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.  
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 17-Jun-08

Original Print Date: 17-Jun-08



Larry S. Pierce, Approved Accreditation Signatory



15974 N. 77<sup>th</sup> Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**chain of custody**

PA

Date: 5/21/08  
 Project No: 08-166  
 Initials: Dave Thomas  
 Page: 1 of 1

Job: Kyrene Aprende Middle School  
 Client: KSD  
 Address: 777 N Desert Breeze Blvd  
Chandler AZ 85225

Test: PLM 10-15  
 Rush:      Normal:      Extended: X  
 Stop at 1st Positive: X NO  
 Read all samples:       
 Call with results:       
 Fax results:     

Multi-purpose Blg

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-SLT-04	SEALANT	A-C	S
M-CON-17	CONCRETE		
M-APL-22	ACOUSTICAL CEILING PANEL	RA	
S-SAT-23	SPRAY APPLIED TEXTURE	RA	
M-GWB-24	GYP SUM WALLBOARD	RA	
S-JTC-25	JOINT COMPOUND	RA	
M-CPT-27	CARPET		
M-WAB-28	WALLBASE		
M-ADH-29	ADHESIVE		
M-SLT-31	SEALANT		
S-SAT-33	SPRAY APPLIED TEXTURE	RA	
M-GWB-34	GYP SUM WALLBOARD	RA	
S-JTC-35	JOINT COMPOUND	RA	
M-APL-43	ACOUSTICAL CEILING PANEL	RA	
M-SLT-48	SEALANT		
M-VCT-54	VINYL COMPOSITION TILE		
M-MAS-55	MASTIC		
M-TWP-56	TACKABLE WALL PANEL	RA	
M-WAB-57	WALLBASE		
M-ADH-58	ADHESIVE		

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
<u>Dave Thomas</u>	<u>5/21/08</u>	<u>[Signature]</u>	<u>5/22/08</u>
<u>[Signature]</u>	<u>5/22/08</u>	<u>K. Townsend</u>	<u>5.28.08</u>



**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200804818

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

**# Samples:** 63 PLM **Rec:** 5/28/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

**Client Job:** Kyrene Aprende Middle Sch/MP Bldg

**PO Number:** 08-166

**Report Date:** 6/17/2008

**Date Analyzed:** 6/17/2008

**Routing Number:** -

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.  
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # <b>M-SLT-04A</b> Layer # 1 Off-white caulk	2008-04818- 1	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-04B</b> Layer # 1 Off-white caulk	2008-04818- 2	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-04C</b> Layer # 1 Off-white caulk	2008-04818- 3	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CON-17A</b> Layer # 1 gray concrete	2008-04818- 4	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CON-17B</b> Layer # 1 gray concrete	2008-04818- 5	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CON-17C</b> Layer # 1 gray concrete	2008-04818- 6	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-22A</b> Layer # 1 off-white ceiling tile	2008-04818- 7	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-22B</b> Layer # 1 off-white ceiling tile	2008-04818- 8	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-22C</b> Layer # 1 off-white ceiling tile	2008-04818- 9	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-23A</b> Layer # 1 white texture/joint compound	2008-04818- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-23B</b> Layer # 1 white texture/joint compound	2008-04818- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-23C</b> Layer # 1 white texture/joint compound	2008-04818- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-24A</b> Layer # 1 white drywall core	2008-04818- 13	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-24B</b> Layer # 1 white drywall core	2008-04818- 14	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-24C</b> Layer # 1 white drywall core	2008-04818- 15	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-25A</b> Layer # 1 white texture/joint compound	2008-04818- 16	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-25B</b> Layer # 1 white texture/joint compound	2008-04818- 17	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-25C</b> Layer # 1 white texture/joint compound	2008-04818- 18	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-27A</b> Layer # 1 various carpet	2008-04818- 19	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-27B</b> Layer # 1 various carpet	2008-04818- 20	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-27C</b> Layer # 1 various carpet	2008-04818- 21	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-28A</b> Layer # 1 Gray base cove	2008-04818- 22	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-28B</b> Layer # 1 Gray base cove	2008-04818- 23	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-28C</b> Layer # 1 Gray base cove	2008-04818- 24	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-29A</b> Layer # 1 tan mastic	2008-04818- 25	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-29B</b> Layer # 1 tan mastic	2008-04818- 26	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-29C</b> Layer # 1 tan mastic	2008-04818- 27	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-31A</b> Layer # 1 white caulk	2008-04818- 28	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-31B</b> Layer # 1 white caulk	2008-04818- 29	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-SLT-31C</b> Layer # 1 white caulk	2008-04818- 30	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No

Sample #	<b>S-SAT-33A</b>	2008-04818- 31	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	<b>S-SAT-33B</b>	2008-04818- 32	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	<b>S-SAT-33C</b>	2008-04818- 33	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	<b>M-GWB-34A</b>	2008-04818- 34	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	<b>M-GWB-34B</b>	2008-04818- 35	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	<b>M-GWB-34C</b>	2008-04818- 36	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	<b>S-JTC-35A</b>	2008-04818- 37	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	<b>S-JTC-35B</b>	2008-04818- 38	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	<b>S-JTC-35C</b>	2008-04818- 39	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	<b>M-APL-43A</b>	2008-04818- 40	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	<b>M-APL-43B</b>	2008-04818- 41	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	<b>M-APL-43C</b>	2008-04818- 42	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	<b>M-SLT-48A</b>	2008-04818- 43	Adhesive/caulk	Positive Layer? No
Layer # 1	Black	caulk	<i>no asbestos detected</i>	
Sample #	<b>M-SLT-48B</b>	2008-04818- 44	Adhesive/caulk	Positive Layer? No
Layer # 1	Black	caulk	<i>no asbestos detected</i>	
Sample #	<b>M-SLT-48C</b>	2008-04818- 45	Adhesive/caulk	Positive Layer? No
Layer # 1	Black	caulk	<i>no asbestos detected</i>	
Sample #	<b>M-VCT-54A</b>	2008-04818- 46	Flooring	Positive Layer? No
Layer # 1	off-white	floor tile	<i>no asbestos detected</i>	
Sample #	<b>M-VCT-54B</b>	2008-04818- 47	Flooring	Positive Layer? No
Layer # 1	off-white	floor tile	<i>no asbestos detected</i>	
Sample #	<b>M-VCT-54C</b>	2008-04818- 48	Flooring	Positive Layer? No
Layer # 1	off-white	floor tile	<i>no asbestos detected</i>	
Sample #	<b>M-MAS-55A</b>	2008-04818- 49	Adhesive/caulk	Positive Layer? No
Layer # 1	Yellow	mastic	<i>no asbestos detected</i>	
Sample #	<b>M-MAS-55B</b>	2008-04818- 50	Adhesive/caulk	Positive Layer? No
Layer # 1	Yellow	mastic	<i>no asbestos detected</i>	
Sample #	<b>M-MAS-55C</b>	2008-04818- 51	Adhesive/caulk	Positive Layer? No
Layer # 1	Yellow	mastic	<i>no asbestos detected</i>	
Sample #	<b>M-TWP-56A</b>	2008-04818- 52	Miscellaneous	Positive Layer? No
Layer # 1	Various	surface	<i>no asbestos detected</i>	
Sample #	<b>M-TWP-56B</b>	2008-04818- 53	Miscellaneous	Positive Layer? No
Layer # 1	Various	surface	<i>no asbestos detected</i>	
Sample #	<b>M-TWP-56C</b>	2008-04818- 54	Miscellaneous	Positive Layer? No
Layer # 1	Various	surface	<i>no asbestos detected</i>	
Sample #	<b>M-WAB-57A</b>	2008-04818- 55	Wall System	Positive Layer? No
Layer # 1	Black	base cove	<i>no asbestos detected</i>	
Sample #	<b>M-WAB-57B</b>	2008-04818- 56	Wall System	Positive Layer? No
Layer # 1	Black	base cove	<i>no asbestos detected</i>	
Sample #	<b>M-WAB-57C</b>	2008-04818- 57	Wall System	Positive Layer? No
Layer # 1	Black	base cove	<i>no asbestos detected</i>	
Sample #	<b>M-ADH-58A</b>	2008-04818- 58	Adhesive/caulk	Positive Layer? No
Layer # 1	tan	mastic	<i>no asbestos detected</i>	
Sample #	<b>M-ADH-58B</b>	2008-04818- 59	Adhesive/caulk	Positive Layer? No
Layer # 1	tan	mastic	<i>no asbestos detected</i>	
Sample #	<b>M-ADH-58C</b>	2008-04818- 60	Adhesive/caulk	Positive Layer? No
Layer # 1	tan	mastic	<i>no asbestos detected</i>	
Sample #	<b>M-TWP-56A-2</b>	2008-04818- 61	Wall System	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	<b>M-TWP-56B-2</b>	2008-04818- 62	Wall System	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	<b>M-TWP-56C-2</b>	2008-04818- 63	Wall System	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number: 200804818** Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-SLT-04A **Lab Number** 2008-04818- 1 **Sampled:** 5/21/2008 **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Rubbery  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-04B **Lab Number** 2008-04818- 2 **Sampled:** 5/21/2008 **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Rubbery  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-04C **Lab Number** 2008-04818- 3 **Sampled:** 5/21/2008 **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Rubbery  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CON-17A      **Lab Number** 2008-04818- 4      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Cementitious      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	concrete	100	gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-CON-17B      **Lab Number** 2008-04818- 5      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Cementitious      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	concrete	100	gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-CON-17C      **Lab Number** 2008-04818- 6      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Cementitious      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	concrete	100	gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.



**Sample** M-APL-22A      **Lab Number** 2008-04818- 7      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-22B      **Lab Number** 2008-04818- 8      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-22C      **Lab Number** 2008-04818- 9      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** S-SAT-23A      **Lab Number** 2008-04818- 10      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-23B      **Lab Number** 2008-04818- 11      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-23C      **Lab Number** 2008-04818- 12      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-GWB-24A      **Lab Number** 2008-04818- 13      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<= 1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<= 1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-24B      **Lab Number** 2008-04818- 14      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<= 1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<= 1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-24C      **Lab Number** 2008-04818- 15      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<= 1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<= 1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** S-JTC-25A      **Lab Number** 2008-04818- 16      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-25B      **Lab Number** 2008-04818- 17      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-25C      **Lab Number** 2008-04818- 18      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-CPT-27A      **Lab Number** 2008-04818- 19      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		40-50%	-	-	-	-	-
<b>Fiber Identification:</b>					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CPT-27B      **Lab Number** 2008-04818- 20      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		40-50%	-	-	-	-	-
<b>Fiber Identification:</b>					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-CPT-27C      **Lab Number** 2008-04818- 21      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Carpet      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		40-50%	-	-	-	-	-
<b>Fiber Identification:</b>					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-WAB-28A      **Lab Number** 2008-04818- 22      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-28B      **Lab Number** 2008-04818- 23      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-28C      **Lab Number** 2008-04818- 24      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-ADH-29A      **Lab Number** 2008-04818- 25      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-29B      **Lab Number** 2008-04818- 26      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-29C      **Lab Number** 2008-04818- 27      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-31A      **Lab Number** 2008-04818- 28      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-31B      **Lab Number** 2008-04818- 29      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-31C      **Lab Number** 2008-04818- 30      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



**Sample** S-SAT-33A      **Lab Number** 2008-04818- 31      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-33B      **Lab Number** 2008-04818- 32      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-33C      **Lab Number** 2008-04818- 33      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-GWB-34A      **Lab Number** 2008-04818- 34      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps.

**Sample** M-GWB-34B      **Lab Number** 2008-04818- 35      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps.

**Sample** M-GWB-34C      **Lab Number** 2008-04818- 36      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** S-JTC-35A      **Lab Number** 2008-04818- 37      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-35B      **Lab Number** 2008-04818- 38      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-35C      **Lab Number** 2008-04818- 39      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-APL-43A      **Lab Number** 2008-04818- 40      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-

Fiber Identification: cellulose fiber | glass fiber

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-43B      **Lab Number** 2008-04818- 41      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-

Fiber Identification: cellulose fiber | glass fiber

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-43C      **Lab Number** 2008-04818- 42      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Ceiling Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		30-40%	2-5%	-	-	-	-

Fiber Identification: cellulose fiber | glass fiber

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-SLT-48A      **Lab Number** 2008-04818- 43      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-48B      **Lab Number** 2008-04818- 44      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-SLT-48C      **Lab Number** 2008-04818- 45      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Sticky  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200804818**

Kyrene Aprende Middle Sch/MP Bldg

**Sample** M-VCT-54A      **Lab Number** 2008-04818- 46      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-54B      **Lab Number** 2008-04818- 47      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-54C      **Lab Number** 2008-04818- 48      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Flooring      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-55A      **Lab Number** 2008-04818- 49      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Yellow	1	>1-2%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		>1-2%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-55B      **Lab Number** 2008-04818- 50      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Yellow	1	>1-2%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		>1-2%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-55C      **Lab Number** 2008-04818- 51      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Yellow	1	>1-2%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		>1-2%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-TWP-56A      **Lab Number** 2008-04818- 52      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Miscellaneous      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Various	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		10-20%	10-20%	-	-	-	-

**Fiber Identification:** synthetic fiber (extr) cellulose fiber

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core was analyzed as sample M-TWP-56A-2.

**Sample** M-TWP-56B      **Lab Number** 2008-04818- 53      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Miscellaneous      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Various	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		10-20%	10-20%	-	-	-	-

**Fiber Identification:** synthetic fiber (extr) cellulose fiber

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core was analyzed as sample M-TWP-56B-2.

**Sample** M-TWP-56C      **Lab Number** 2008-04818- 54      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Miscellaneous      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	100	Various	1	10-20%	10-20%	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		10-20%	10-20%	-	-	-	-

**Fiber Identification:** synthetic fiber (extr) cellulose fiber

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

**Sample Analytical Note**

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent. Core was analyzed as sample M-TWP-56B-2.



**Sample** M-WAB-57A      **Lab Number** 2008-04818- 55      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-57B      **Lab Number** 2008-04818- 56      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-57C      **Lab Number** 2008-04818- 57      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Non-fibrous Solid**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-58A      **Lab Number** 2008-04818- 58      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-58B      **Lab Number** 2008-04818- 59      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-58C      **Lab Number** 2008-04818- 60      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM    6/17/2008      **An?** OK      **Apparent Smp Type** Adhesive/caulk      Non-fibrous Solid  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, polymer,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**

Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-TWP-56A-2      **Lab Number** 2008-04818- 61      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		90-100%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-TWP-56B-2      **Lab Number** 2008-04818- 62      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		90-100%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-TWP-56C-2      **Lab Number** 2008-04818- 63      **Sampled:** 5/21/2008      **Condition:** acceptable  
**Analyzed By** RAM 6/17/2008      **An?** OK      **Apparent Smp Type** Wall System      **Fibrous Mat**  
**Homogeneous** No      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		90-100%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oli=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 17-Jun-08

Original Print Date: 17-Jun-08



Larry S. Pierce, Approved Accreditation Signatory

## **APPENDIX C**

### **Building Inspectors' Signature Sheet**






**BUILDING INSPECTOR'S SIGNATURE SHEET**

**Report of Findings**  
**Comprehensive AHERA Asbestos Inspection**  
**Kyrene Aprende Middle School**  
**Kyrene School District No. 28**

**FM Project 08-166**

The individual(s) whose signature(s) is/are shown below is/are EPA Accredited Building Inspector(s) who participated in one or more of the following activities:


- A. Visual Inspection of Facilities
- B. Identification of Homogenous Areas of Asbestos-Containing Materials
- C. Development of Sampling Plan and Protocols
- D. Bulk Sampling Activities/Material Identifications
- E. Assessing ACBM/ACM
- F. Preparing Report of Findings

<u>INSPECTOR</u>	<u>ACTIVITIES</u>	<u>DATES</u>
<u>Paul Anger</u> Printed Name <u>D 11441</u> Accreditation No.  Signature	<u>PA</u> Initials <u>EPA</u> State	<u>F</u>    
<u>Michael Richter</u> Printed Name <u>D 10790</u> Accreditation No.  Signature	<u>MR</u> Initials <u>EPA</u> State	<u>A, B, D, E</u>    
<u>Cliff Rolle</u> Printed Name <u>D 12516</u> Accreditation No.  Signature	 Initials <u>EPA</u> State	<u>A, B, C, D, E, F</u>    
<u>Dane Thompson</u> Printed Name <u>D 12313</u> Accreditation No.  Signature	<u>DT</u> Initials <u>EPA</u> State	<u>A, B, D, E</u>    

## **APPENDIX D**

### **Personnel and Laboratory Accreditations**

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher  
Building Inspector  
January 4, 2008**

and successfully passed the competency exam.

Date of Examination: **January 4, 2008**

Date of Expiration: **January 4, 2009**

*[Signature]*  
 \_\_\_\_\_  
 Director

*[Signature]*  
 \_\_\_\_\_  
 Approved Instructor

**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564



# THE ASBESTOS INSTITUTE




Certifies that

has attended the EPA approved course

and successfully passed the competency exam.



Director



Approved Instructor

**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12516

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher  
Building Inspector  
May 30, 2008**


and successfully passed the competency exam

Date of Examination: **May 30, 2008**

Date of Expiration: **May 30, 2009**

Director

Approved Instructor



**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12313

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher  
Building Inspector**

**May 2, 2008**

and successfully passed the competency exam

Date of Examination: **May 2, 2008**

Date of Expiration: **May 2, 2009**

Director

Approved Instructor


**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564



United States Department of Commerce  
National Institute of Standards and Technology



---

## Certificate of Accreditation to ISO/IEC 17025:1999

---

NVLAP LAB CODE: 101031-0

**Fiberquant, Inc.**  
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in  
*NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.*  
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

**BULK ASBESTOS FIBER ANALYSIS**

2007-07-01 through 2008-06-30

Effective dates

---



*Cheryl S. Buces*

For the National Institute of Standards and Technology

## **1.0 SURVEY RESULTS AND RECOMMENDATIONS**

### **1.1 Summary**

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the three buildings comprising the Kyrene Aprende Middle School (KAMS) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of May 19, 2008 through May 21, 2008. A total of 150 bulk-material samples were collected from 172 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

One Hundred Twenty-two building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

### **1.2 Identified Asbestos Containing Building Material**

The identified ACBM within the three buildings at KAMS are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

### **1.3 Asbestos-Containing Building Materials**

(Table "C" has been moved to Section 6 of the Management Plan.)

### **1.4 ACBM/Location Plans**

(Drawings have been moved to Section 6 of the Management Plan.)

### **1.5 Critical Situations**

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the three buildings at KAMS during this inspection.**

## **1.6 Friable Asbestos-Containing Building Materials**

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Miscellaneous or Surfacing Building Materials, or Asbestos-Containing Thermal System Insulation in the three buildings at KAMS during this inspection.**

## **1.7 Material Assessments**

Due to the fact that **NO friable Asbestos-Containing Miscellaneous or Surfacing Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the three buildings at KAMS, **NO** formal assessments are included in this report.

## **1.8 Recommendations**

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

## **1.9 Qualifications of Report**

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

## **2.0 PROJECT INFORMATION**

### **2.1 Background**

KSD intends to determine if there are any ACBM associated with the three buildings at the KAMS campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the three buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 24, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 777 North Desert Breeze Boulevard East #2 in Chandler, Arizona and consists of three buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the three buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of May 19, 2008 through May 21, 2008, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

## **2.2 Description of Construction**

### **2.2.1 Main, Media Center and Multi-Purpose Buildings**

The construction date of the Main, Media Center and Multi-Purpose Buildings is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support a wood, metal or concrete deck system finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, fiberglass reinforced panel, glazed wall tile or stucco. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

## **2.3 AHERA Inspection Procedures and Protocols**

### **2.3.1 Inspection Procedures and Protocols**

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located.
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
  - ◊ natural friability and,
  - ◊ physical condition and,
  - ◊ if damaged or thermal systems insulation;
    - \* be identified for an immediate response action or,
    - \* be identified for possible future disturbance and
    - \* have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
  - ◊ date accomplished and,
  - ◊ identification and qualification of individuals conducting each activity.

### **2.3.2 FM GROUP INC Inspection SOP**

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

## **2.4 Visual Inspection**

A visual inspection of the three buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

## **2.5 Physical Assessments**

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.



At the time of this inspection, **FOUR** friable suspect ACBM (acoustical ceiling panels) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

## 2.6 Sample Collection

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

<b>Building</b>	<b>Suspect ACBM</b>	<b>Samples Collected</b>
Main	57 (42 Assumed)	45
Media Center	44 (29 Assumed)	45
Multi-Purpose	71 (51 Assumed)	60
<b>TOTAL</b>	<b>172</b>	<b>150</b>

## 2.7 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

**END OF REPORT**

**SECTION 3**

**DESIGNATED PERSON IDENTIFICATION**

---

**AHERA Designated Person**  
**796.93(e)(4)**

**Owner:** KYRENE SCHOOL DISTRICT NO. 28

**Address:** 8700 SOUTH KYRENE ROAD  
TEMPE, ARIZONA 85284-2197

**Property:** KYRENE APRENDE MIDDLE SCHOOL

**Address:** 777 NORTH DESERT BREEZE BOULEVARD EAST #2  
CHANDLER, ARIZONA 85226

**LEA Designated Person**

**Print Name:** Giacomo Musella, Facilities Supervisor

**Address:** 8700 South Kyrene Road  
Tempe, Arizona 85284-2197

**Phone:** 480.783-4200

**Training Course Name:** AHERA Building Inspector Refresher

**Dates of Training:** October 5, 2008      **Hours of Training:** 4

**Training Course Name:** AHERA Management Planner Refresher

**Dates of Training:** October 5, 2008      **Hours of Training:** 4

**Training Course Name:** \_\_\_\_\_

**Dates of Training:** \_\_\_\_\_      **Hours of Training:** \_\_\_\_\_

\_\_\_\_\_  
**Signature**

\_\_\_\_\_  
**Date**

D 10910

# THE ASBESTOS INSTITUTE


Certifies that  
**Giacomo Jack Musella**


has attended the EPA approved course  
AHERA Refresher  
Building Inspector  
October 5, 2007  
and successfully passed the competency exam.

COPY

Date of Examination: October 5, 2007.

Date of Expiration: October 5, 2008

  
Director

  
Approved Instructor

THE ASBESTOS INSTITUTE  
8102 North 23rd Avenue  
Suite A  
Phoenix, AZ 85021-4962  
602-864-6564

This training meets all requirements for asbestos accreditation under TSCA Title II.

D 10936

# THE ASBESTOS INSTITUTE

Certifies that  
**Giacomo Jack Musella**

has attended the EPA approved course  
**AHERA Refresher  
Management Planner  
October 5, 2007**  
and successfully passed the competency exam.

**COPY**

Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**



Director



Approved instructor

**THE ASBESTOS INSTITUTE**  
8102 North 25th Avenue  
Suite A  
Phoenix, AZ 85021-4962  
602-864-6564

*This training meets all requirements for asbestos accreditation under TSCA Title II.*

**SECTION 4**

**RESPONSE ACTION(S)**

---

**THERE ARE NO RESPONSE ACTIONS REQUIRED AT THIS FACILITY.**

**SECTION 5**

**ACCREDITATION STATEMENTS**

---

**Assurance of Accreditation  
Under this Management Plan  
763.93(e)(7)**

**Inspector(s):**

**Name:** MICHAEL RICHTER  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** SEPTEMBER 12, 2008  
**Accreditation Number(s):** D 10790

**Name:** CLIFF ROLLE  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** MAY 30, 2009  
**Accreditation Number(s):** D 12516

**Name:** DANE THOMPSON  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** MAY 2, 2009  
**Accreditation Number(s):** D 12313


**Management Planner:**

**Name:** PAUL ANGER  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** JANUARY 4, 2009  
**Accreditation Number(s):** D 11466

Any Project Designer, Contractor/Supervisor or Worker who performs work on response actions under this Management Plan shall be accredited by either an EPA approved state contractor accreditation plan or an EPA approved course under Section 206(b) to Title II of the Toxic Substance Control Act.



**THE ASBESTOS INSTITUTE**



Certifies that

has attended the EPA approved course

and successfully passed the competency exam

Director

Approved Instructor

**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12516

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHRA Refresher  
Building Inspector  
May 30, 2008**

and successfully passed the competency exam

Date of Examination: **May 30, 2008**


Date of Expiration: **May 30, 2009**

*[Signature]*

Director

*[Signature]*

Approved Instructor




**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue  
Suite A

Phoenix, AZ 85021-4962  
602-864-6564

D 12313

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHJRA Refresher  
Building Inspector**

**May 2, 2008**

and successfully passed the competency exam

Date of Examination: **May 2, 2008**

Date of Expiration: **May 2, 2009**

Director

Approved Instructor


**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue

Suite A


Phoenix, AZ 85021-4962

602-864-6564



D 11466

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course:

HERA Refresher  
Management Planner  
January 4, 2008.

and successfully passed the competency exam.

Date of Examination: January 4, 2008

Date of Expiration: January 4, 2009

*[Handwritten Signature]*

Director

*[Handwritten Signature]*

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564