


ASBESTOS MANAGEMENT PLAN



at

Kyrene Centennial Middle School

Prepared for:

Kyrene School District No. 28

VOLUME I OF II

**FM GROUP INC
FM Project 08-192**

July 2008

TABLE OF CONTENTS

Report of Findings Comprehensive AHERA Asbestos Inspection Kyrene Centennial Middle School Kyrene School District No. 28

FM GROUP Project 08-192

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u>	1
1.1 Summary	1
1.2 Identified Asbestos-Containing Materials	1
1.3 Asbestos-Containing Building Materials (Table C)	2
1.4 ACBM/Location Plans	3
1.5 Critical Situations	4
1.6 Friable Asbestos-Containing Building Materials	4
1.7 Material Assessments	4
1.8 Recommendations	4
1.9 Qualifications of the Report.....	4
2.0 <u>PROJECT INFORMATION</u>	5
2.1 Background.....	5
2.2 Description of Construction	5
2.2.1 Buildings A, B, C, D, E, F, G and H	5
2.2.2 Ramada.....	6
2.2.3 Storage Building	6
2.3 Building Materials/Systems List (Table A).....	7
2.3.1 Building A	8
2.3.2 Building B	26
2.3.3 Building C.....	45
2.3.4 Building D.....	65
2.3.5 Building E.....	85
2.3.6 Building F	109
2.3.7 Building G.....	121
2.3.8 Building H.....	132
2.3.9 Ramada.....	161
2.3.10 Storage Building	162
2.4 AHERA Inspection Procedures and Protocols.....	163
2.4.1 Inspection Procedures and Protocols	163
2.4.2 FM GROUP INC Inspection SOP	163
2.5 Visual Inspection.....	163
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B) .	164
2.6.1 Building A	165
2.6.2 Building B	167
2.6.3 Building C.....	169
2.6.4 Building D.....	171

<u>Section</u>	<u>Page</u>
2.6.5 Building E	173
2.6.6 Building F	176
2.6.7 Building G	178
2.6.8 Building H	180
2.6.9 Ramada Building	182
2.6.10 Storage Building	183
2.7 Physical Assessments	184
2.8 Sample Collection	184
2.9 Material Bulk Sample Analysis	184

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none"> • Chain-of-Custodies • Laboratory Analyses
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

ENVKSD\08-192 Centennial MP\2.0\2.3\2.3.1\TOC.doc

ASBESTOS MANAGEMENT PLAN

Kyrene Centennial Middle School

July 2008

FM GROUP INC

FM Project 08-192

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY	1-1
2	INSPECTION REPORT.....	2-1
3	DESIGNATED PERSON IDENTIFICATION.....	3-1
4	RESPONSE ACTION	4-1
5	ACCREDITATION STATEMENTS	5-1
6	REMAINING ACBM.....	6-1
7	O&M PROGRAM.....	7-1
8	INITIAL NOTIFICATIONS.....	8-1
9	COST ESTIMATION	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON	10-1
11	ANNUAL NOTIFICATIONS	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT	12-1

APPENDIX A: ONGOING RECORDKEEPING

SECTION 1

GENERAL INVENTORY

General Inventory
763.93(e)(1)

Date: JULY 13, 2008

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: KYRENE CENTENNIAL MIDDLE SCHOOL

Address: 13808 SOUTH 36TH STREET
PHOENIX, ARIZONA 85044

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
A	N/A	X	X
B	N/A	X	X
C	N/A	X	X
D	N/A	X	X
E	N/A	X	X
F	N/A	X	X
G	N/A	X	X
H	N/A	X	X
RAMADA	N/A	X	X
STORAGE	N/A	X	X

SECTION 2

INSPECTION REPORT

INSPECTION REPORT

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School

Prepared by: FM GROUP INC
Project No.: 08-192
Date: July 2008

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28
8700 South Kyrene Road
Tempe, Arizona 85284-2197



REPORT OF FINDINGS
(Abridged Version)

Comprehensive AHERA Asbestos Inspection

at

Kyrene Centennial Middle School

Prepared for:

Kyrene School District No. 28

FM GROUP INC
FM Project 08-192

July 2008

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the ten buildings comprising the Kyrene Centennial Middle School (KCMS) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of June 9, 2008 through June 13, 2008. A total of 149 bulk-material samples were collected from 433 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Three Hundred Eighty-six building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos-Containing Building Materials

The identified ACBM within the ten buildings at KCMS are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

Asbestos Material-Bulk Samples Collected

<i>Building</i>	<i>No. of Samples</i>	<i>No. HA</i>	<i>No. Assumed</i>	<i>Total No. ACM</i>
A	21	42	35	35
B	18	52	46	46
C	18	57	51	51
D	18	49	43	43
E	27	82	73	73
F	18	41	35	35
G	18	45	39	39
H	11	55	52	52
Ramada	0	5	5	5
Storage	0	5	5	5

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Centennial Middle School, KSD

FM Project 08-192

1.3 Asbestos-Containing Building Materials

**TABLE C
ASBESTOS CONTAINING BUILDING MATERIALS**

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING H
RAMADA
STORAGE BUILDING**

**TABLE C HAS BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN**

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Centennial Middle School, KSD

FM Project 08-192

1.4 ACBM/Location Plans

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING H
RAMADA
STORAGE BUILDING**

***ACBM/LOCATION PLANS HAVE BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Centennial Middle School, KSD

FM Project 08-192

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the ten buildings at KCMS during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the ten buildings at KCMS during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the ten buildings at KCMS, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the ten buildings at the KCMS campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the ten buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 24, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 13808 South 36th Street in Phoenix, Arizona and consists of ten buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the ten buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of June 9, 2008 through June 13, 2008, by Michael Coleman and Paul Massey, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.

2.2 Description of Construction

2.2.1 Buildings A, B, C, D, E, F, G and H

The construction date of the Buildings A, B, C, D, E, F, G and H is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support concrete, wooden or metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes, stucco and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Ramada

The construction date the Ramada is unknown. The construction appears to be consistent and uniform throughout.

The structure is built with a slab on-grade foundation. Perimeter load bearing columns are of concrete masonry systems and support a metal roofing system.

2.2.3 Storage Building

The construction date of the Storage Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter load bearing walls are of concrete masonry systems and support a metal roofing system.

A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.

2.3 Building Materials/Systems List

**TABLE A
BUILDING MATERIAL SYSTEMS**

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING H
RAMADA
STORAGE BUILDING**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building A*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION	C	*	S
	PSYCHOLOGY	C	*	
	PRINCIPAL	C	*	
	SCHOOL ASSISTANT	C	*	
	STUDENT ADVISOR	C	*	
	HALL 1	C	*	
	OFFICE 1	C	*	
	OFFICE 2	C	*	
	OFFICE 3	C	*	
	OFFICE 4	C	*	
	HALL 2	C	*	
	MAIL	C	*	
	STORAGE 3	C	*	
	TEACHER'S LOUNGE	C	*	
	ISOLATED CLASSROOM	C	*	
	HEALTH	C	*	
	HEALTH OFFICE	C	*	
	TEST	C	*	
	HEALTH STORAGE	C	*	
	NURSE	C	*	
	WAITING	C	*	
	CORRIDOR 1	C	*	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, RIBBED, WHITE	RECEPTION	C	*	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION	C, W	N, E, W, S	S
	PSYCHOLOGY	C, W	N, E, W, S	
	PRINCIPAL	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	SCHOOL ASSISTANT	C, W	N, E, W, S	
	STUDENT ADVISOR	C, W	N, E, W, S	
	OFFICE 1	C, W	N, E, W, S	
	OFFICE 2	C, W	N, E, W, S	
	OFFICE 3	C, W	N, E, W, S	
	OFFICE 4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	MAIL	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	TELE 1	C	*	
	TELE 2	C	*	
	TEACHER'S LOUNGE	W	N, E, W, S	
	ISOLATED CLASSROOM	W	N, E, W, S	
	HEALTH	W	N, E, W, S	
	HEALTH OFFICE	W	N, E, W, S	
	HEALTH STORAGE	W	N, E, W, S	
	NURSE	W	N, E, W, S	
	WAITING	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION	C, W	N, E, W, S	S
	PSYCHOLOGY	C, W	N, E, W, S	
	PRINCIPAL	C, W	N, E, W, S	
	SCHOOL ASSISTANT	C, W	N, E, W, S	
	STUDENT ADVISOR	C, W	N, E, W, S	
	OFFICE 1	C, W	N, E, W, S	
	OFFICE 2	C, W	N, E, W, S	
	OFFICE 3	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	OFFICE 4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	MAIL	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	TELE 1	C	*	
	TELE 2	C	*	
	TEACHER'S LOUNGE	W	N, E, W, S	
	ISOLATED CLASSROOM	W	N, E, W, S	
	HEALTH	W	N, E, W, S	
	HEALTH OFFICE	W	N, E, S	
	HEALTH STORAGE	W	N, E, W, S	
	NURSE	W	N, E, W, S	
	WAITING	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION	C, W	N, E, W, S	S
	PSYCHOLOGY	C, W	N, E, W, S	
	PRINCIPAL	C, W	N, E, W, S	
	SCHOOL ASSISTANT	C, W	N, E, W, S	
	STUDENT ADVISOR	C, W	N, E, W, S	
	OFFICE 1	C, W	N, E, W, S	
	OFFICE 2	C, W	N, E, W, S	
	OFFICE 3	C, W	N, E, W, S	
	OFFICE 4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	MAIL	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	TELE 1	C	*	
	TELE 2	C	*	
	TEACHER'S LOUNGE	W	N, E, W, S	
	ISOLATED CLASSROOM	W	N, E, W, S	
	HEALTH	W	N, E, W, S	
	HEALTH OFFICE	W	N, E, S	
	HEALTH STORAGE	W	N, E, W, S	
	NURSE	W	N, E, W, S	
	WAITING	W	N, E, W, S	
BRICK, 4"X16", TAN, CEMENTITIOUS	RECEPTION	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	RECEPTION	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	RECEPTION	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	RECEPTION	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	RECEPTION	W	E, W,	S
	TEACHER'S LOUNGE	W	S	
	ISOLATED CLASSROOM	W	E, W, S	
	NURSE	W	E	
GLASS BLOCK, 8"X8", CLEAR	RECEPTION	W	W	N
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	RECEPTION	W	W	S
FIRE DOOR INSULATION, METAL/WOOD CLADDING	RECEPTION	O	N, W	S
	PRINCIPAL	O	N	
	CUSTODIAL	O	E	
	HALL 1	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WOMEN'S RESTROOM	O	E	
	MEN'S RESTROOM	O	E	
	OFFICE 3	O	S	
	OFFICE 4	O	S	
	HALL 2	O	N, E, S	
	STORAGE 1	O	N, W, S	
	SERVER ROOM	O	E	
	STORAGE 2	O	N, S	
	MAIL	O	N	
	STORAGE 3	O	E	
	TELE 1	O	S	
	TELE 2	O	S	
	TEACHER'S LOUNGE	O	N, W, S	
	ISOLATED CLASSROOM	O	N, E	
	GIRL'S RESTROOM	O	S	
	BOY'S RESTROOM	O	S	
	ELECTRICAL	O	E	
	HEALTH	O	E, W	
	HEALTH OFFICE	O	E	
	TEST	O	E	
	HEALTH STORAGE	O	E	
	NURSE	O	W	
	WAITING	O	N	
	HEALTH RESTROOM	O	W	
	CORRIDOR 1	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	RECEPTION	O	N, E, W, S	S
	PSYCHOLOGY	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	PRINCIPAL	O	N, E, W, S	
	SCHOOL ASSISTANT	O	N, E, W, S	
	STUDENT ADVISOR	O	N, E, W, S	
	HALL 1	O	N, E, S	
	OFFICE 1	O	N, E, W, S	
	OFFICE 2	O	N, E, W, S	
	OFFICE 3	O	N, E, W, S	
	OFFICE 4	O	N, E, W, S	
	HALL 2	O	N, E, S	
	STORAGE 1	O	N, E, W, S	
	MAIL	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	TELE 1	O	N, E, W, S	
	TELE 2	O	N, E, W, S	
	TEACHER'S LOUNGE	O	N, E, W, S	
	ISOLATED CLASSROOM	O	N, E, W, S	
	HEALTH	O	N, E, W, S	
	HEALTH OFFICE	O	N, E, W, S	
	TEST	O	N, E, W, S	
	NURSE	O	N, E, W, S	
	WAITING	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	RECEPTION	O	N, E, W, S	S
	PSYCHOLOGY	O	N, E, W, S	
	PRINCIPAL	O	N, E, W, S	
	SCHOOL ASSISTANT	O	N, E, W, S	
	STUDENT ADVISOR	O	N, E, W, S	
	HALL 1	O	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	OFFICE 1	O	N, E, W, S	
	OFFICE 2	O	N, E, W, S	
	OFFICE 3	O	N, E, W, S	
	OFFICE 4	O	N, E, W, S	
	HALL 2	O	N, E, S	
	STORAGE 1	O	N, E, W, S	
	MAIL	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	TELE 1	O	N, E, W, S	
	TELE 2	O	N, E, W, S	
	TEACHER'S LOUNGE	O	N, E, W, S	
	ISOLATED CLASSROOM	O	N, E, W, S	
	HEALTH	O	N, E, W, S	
	HEALTH OFFICE	O	N, E, W, S	
	TEST	O	N, E, W, S	
	NURSE	O	N, E, W, S	
	WAITING	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	RECEPTION	F	*	S
	PSYCHOLOGY	F	*	
	PRINCIPAL	F	*	
	SCHOOL ASSISTANT	F	*	
	STUDENT ADVISOR	F	*	
	HALL 1	F	*	
	OFFICE 1	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	OFFICE 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HALL 2	F	*	
	MAIL	F	*	
	STORAGE 3	F	*	
	TELE 1	F	*	
	TELE 2	F	*	
	TEACHER'S LOUNGE	F	*	
	ISOLATED CLASSROOM	F	*	
	HEALTH	F	*	
	HEALTH OFFICE	F	*	
	TEST	F	*	
	NURSE	F	*	
	WAITING	F	*	
	CORRIDOR 1	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	RECEPTION	F	*	S
	PSYCHOLOGY	F	*	
	PRINCIPAL	F	*	
	SCHOOL ASSISTANT	F	*	
	STUDENT ADVISOR	F	*	
	HALL 1	F	*	
	OFFICE 1	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	OFFICE 4	F	*	
	HALL 2	F	*	
	MAIL	F	*	
	STORAGE 3	F	*	
	TELE 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	TELE 2	F	*	
	TEACHER'S LOUNGE	F	*	
	ISOLATED CLASSROOM	F	*	
	HEALTH	F	*	
	HEALTH OFFICE	F	*	
	TEST	F	*	
	NURSE	F	*	
	WAITING	F	*	
	CORRIDOR 1	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	RECEPTION	O	N	S
	PSYCHOLOGY	O	N, S	
	PRINCIPAL	O	N, S	
	SCHOOL ASSISTANT	O	N, S	
	STUDENT ADVISOR	O	N, S	
	CUSTODIAL	O	E	
	HALL 1	O	N, E, S	
	WOMEN'S RESTROOM	O	E, W	
	MEN'S RESTROOM	O	E, W	
	OFFICE 1	O	N	
	OFFICE 2	O	N	
	OFFICE 3	O	S	
	OFFICE 4	O	S	
	HALL 2	O	N, E, S	
	STORAGE 1	O	N, W, S	
	SERVER ROOM	O	E	
	STORAGE 2	O	N, S	
	MAIL	O	N, E	
	STORAGE 3	O	E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	TELE 1	O	S	
	TELE 2	O	S	
	TEACHER'S LOUNGE	O	N, W, S	
	ISOLATED CLASSROOM	O	N, E, W	
	GIRL'S RESTROOM	O	E, S	
	BOY'S RESTROOM	O	W, S	
	ELECTRICAL	O	E	
	HEALTH	O	N, E, W	
	HEALTH OFFICE	O	E	
	TEST	O	E	
	HEALTH STORAGE	O	E	
	NURSE	O	N, W, S	
	WAITING	O	N	
	HEALTH RESTROOM	O	N, W	
	CORRIDOR 1	O	N, E, W, S	
SEALANT (WINDOWS), BLACK, GUMMY	RECEPTION	O	N	S
	HALL 1	O	N, S	
	HALL 2	O	N	
	NURSE	O	E, S	
	EXTERIOR	O	N, E, S	
SEALANT (DOORS, WINDOWS, FIXTURES), TAN, Pliable	RECEPTION	O	W	S
	EXTERIOR	O	N, E, W, S	
DUCT SEAM TAPE, 2", WHITE, CANVAS	RECEPTION	O	*	S
	PSYCHOLOGY	O	*	
	PRINCIPAL	O	*	
	SCHOOL ASSISTANT	O	*	
	STUDENT ADVISOR	O	*	
	CUSTODIAL	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HALL 1	O	*	
	WOMEN'S RESTROOM	O	*	
	MEN'S RESTROOM	O	*	
	OFFICE 1	O	*	
	OFFICE 2	O	*	
	OFFICE 3	O	*	
	OFFICE 4	O	*	
	HALL 2	O	*	
	STORAGE 1	O	*	
	SERVER ROOM	O	*	
	STORAGE 2	O	*	
	MAIL	O	*	
	STORAGE 3	O	*	
	TELE 1	O	*	
	TELE 2	O	*	
	TEACHER'S LOUNGE	O	*	
	ISOLATED CLASSROOM	O	*	
	GIRL'S RESTROOM	O	*	
	BOY'S RESTROOM	O	*	
	ELECTRICAL	O	*	
	HEALTH	O	*	
	HEALTH OFFICE	O	*	
	TEST	O	*	
	HEALTH STORAGE	O	*	
	NURSE	O	*	
	WAITING	O	*	
	HEALTH RESTROOM	O	*	
	CORRIDOR 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	RECEPTION	O	*	S
	PSYCHOLOGY	O	*	
	PRINCIPAL	O	*	
	SCHOOL ASSISTANT	O	*	
	STUDENT ADVISOR	O	*	
	CUSTODIAL	O	*	
	HALL 1	O	*	
	WOMEN'S RESTROOM	O	*	
	MEN'S RESTROOM	O	*	
	OFFICE 1	O	*	
	OFFICE 2	O	*	
	OFFICE 3	O	*	
	OFFICE 4	O	*	
	HALL 2	O	*	
	STORAGE 1	O	*	
	SERVER ROOM	O	*	
	STORAGE 2	O	*	
	MAIL	O	*	
	STORAGE 3	O	*	
	TELE 1	O	*	
	TELE 2	O	*	
	TEACHER'S LOUNGE	O	*	
	ISOLATED CLASSROOM	O	*	
	GIRL'S RESTROOM	O	*	
	BOY'S RESTROOM	O	*	
	ELECTRICAL	O	*	
	HEALTH	O	*	
	HEALTH OFFICE	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building A*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	TEST	O	*	
	HEALTH STORAGE	O	*	
	NURSE	O	*	
	WAITING	O	*	
	HEALTH RESTROOM	O	*	
	CORRIDOR 1	O	*	
TROWELED-ON TEXTURE, WHITE, CHALKY	CUSTODIAL	C, W	N, E, W, S	S
	SERVER ROOM	C, W	N, E, W, S	
	ELECTRICAL	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	CUSTODIAL	C, W	N, E, W, S	S
	SERVER ROOM	C, W	N, E, W, S	
	ELECTRICAL	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CUSTODIAL	C, W	N, E, W, S	S
	SERVER ROOM	C, W	N, E, W, S	
	ELECTRICAL	C, W	N, E, W, S	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	CUSTODIAL	O	N, E, W, S	S
	WOMEN'S RESTROOM	O	N, E, W, S	
	MEN'S RESTROOM	O	N, E, W, S	
	SERVER ROOM	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	GIRL'S RESTROOM	O	N, E, W, S	
	BOY'S RESTROOM	O	N, E, W, S	
	ELECTRICAL	O	N, E, W, S	
	HEALTH STORAGE	O	N, E, W, S	
	HEALTH RESTROOM	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	CUSTODIAL	O	N, E, W, S	S
	WOMEN'S RESTROOM	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	MEN'S RESTROOM	O	N, E, W, S	
	SERVER ROOM	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	GIRL'S RESTROOM	O	N, E, W, S	
	BOY'S RESTROOM	O	N, E, W, S	
	ELECTRICAL	O	N, E, W, S	
	HEALTH STORAGE	O	N, E, W, S	
	HEALTH RESTROOM	O	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	CUSTODIAL	F	*	S
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	STORAGE 1	F	*	
	SERVER ROOM	F	*	
	STORAGE 2	F	*	
	TEACHER'S LOUNGE	F	*	
	GIRL'S RESTROOM	F	*	
	BOY'S RESTROOM	F	*	
	ELECTRICAL	F	*	
	HEALTH STORAGE	F	*	
	HEALTH RESTROOM	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	CUSTODIAL	F	*	S
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	STORAGE 1	F	*	
	SERVER ROOM	F	*	
	STORAGE 2	F	*	
	TEACHER'S LOUNGE	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	GIRL'S RESTROOM	F	*	
	BOY'S RESTROOM	F	*	
	ELECTRICAL	F	*	
	HEALTH STORAGE	F	*	
	HEALTH RESTROOM	F	*	
GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION	W	N, E, S	S
	HALL 1	W	N, E, S	
	HALL 2	W	N, E, S	
	TELE 1	W	N, E, W, S	
	TELE 2	W	N, E, W, S	
	HEALTH OFFICE	W	W	
	TEST	W	N, E, W, S	
	WAITING	W	E	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION	W	N, E, S	S
	HALL 1	W	N, E, S	
	HALL 2	W	N, E, S	
	TELE 1	W	N, E, W, S	
	TELE 2	W	N, E, W, S	
	HEALTH OFFICE	W	W	
	TEST	W	N, E, W, S	
	WAITING	W	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WOMEN'S RESTROOM	C, W	N, E, W, S	S
	MEN'S RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM	C, W	N, E, W, S	
	HEALTH RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WOMEN'S RESTROOM	C, W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building A*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MEN'S RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM	C, W	N, E, W, S	
	HEALTH RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	WOMEN'S RESTROOM	C, W	N, E, W, S	S
	MEN'S RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM	C, W	N, E, W, S	
	HEALTH RESTROOM	C, W	N, E, W, S	
SINK ACOUSTICAL COATING, BLACK, ROUGH	MAIL	O	E	S
	TEACHER'S LOUNGE	O	N	
	ISOLATED CLASSROOM	O	N	
	WAITING	O	W	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	RECEPTION	F	*	S
	PSYCHOLOGY	F	*	
	PRINCIPAL	F	*	
	SCHOOL ASSISTANT	F	*	
	STUDENT ADVISOR	F	*	
	CUSTODIAL	F	*	
	HALL 1	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	OFFICE 1	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	OFFICE 4	F	*	
	HALL 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building A*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 1	F	*	
	SERVER ROOM	F	*	
	STORAGE 2	F	*	
	MAIL	F	*	
	STORAGE 3	F	*	
	TELE 1	F	*	
	TELE 2	F	*	
	TEACHER'S LOUNGE	F	*	
	ISOLATED CLASSROOM	F	*	
	GIRL'S RESTROOM	F	*	
	BOY'S RESTROOM	F	*	
	ELECTRICAL	F	*	
	HEALTH	F	*	
	HEALTH OFFICE	F	*	
	TEST	F	*	
	HEALTH STORAGE	F	*	
	NURSE	F	*	
	WAITING	F	*	
	HEALTH RESTROOM	F	*	
	CORRIDOR 1	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building A

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
PIPE END SEALANT, GRAY, PLIABLE	ROOF	O	*	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM B-1	C	*	S
	CLASSROOM B-2	C	*	
	CLASSROOM B-3	C	*	
	CLASSROOM B-4	C	*	
	CLASSROOM B-5	C	*	
	CLASSROOM B-6	C	*	
	OFFICE 1	C	*	
	CLASSROOM B-7	C	*	
	CLASSROOM B-8	C	*	
	WORKROOM	C	*	
	DISCOVER LAB B-9	C	*	
	CLASSROOM B-10	C	*	
	CLASSROOM B-11	C	*	
CLASSROOM B-12	C	*		
CLASSROOM B-13	C	*		
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM B-1	C, W	N, E, W, S	S
	CLASSROOM B-2	C, W	N, E, W, S	
	CLASSROOM B-3	C, W	N, E, W, S	
	CLASSROOM B-4	C, W	N, E, W, S	
	CLASSROOM B-5	C, W	N, E, W, S	
	CLASSROOM B-6	C, W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	STORAGE 7	C, W	N, E, W, S	
	CLASSROOM B-7	W	N, E, S	
CLASSROOM B-8	W	N, W, S		

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WORKROOM	W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	DISCOVER LAB B-9	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM B-10	C, W	N, E, W, S	
	CLASSROOM B-11	C, W	N, E, W, S	
	CLASSROOM B-12	C, W	N, E, W, S	
	CLASSROOM B-13	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM B-1	C, W	N, E, W, S	S
	CLASSROOM B-2	C, W	N, E, W, S	
	CLASSROOM B-3	C, W	N, E, W, S	
	CLASSROOM B-4	C, W	N, E, W, S	
	CLASSROOM B-5	C, W	N, E, W, S	
	CLASSROOM B-6	C, W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	STORAGE 7	C, W	N, E, W, S	
	CLASSROOM B-7	W	N, E, S	
	CLASSROOM B-8	W	N, W, S	
	WORKROOM	W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	DISCOVER LAB B-9	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM B-10	C, W	N, E, W, S	
	CLASSROOM B-11	C, W	N, E, W, S	
	CLASSROOM B-12	C, W	N, E, W, S	
	CLASSROOM B-13	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM B-1	C, W	N, E, W, S	S
	CLASSROOM B-2	C, W	N, E, W, S	
	CLASSROOM B-3	C, W	N, E, W, S	
	CLASSROOM B-4	C, W	N, E, W, S	
	CLASSROOM B-5	C, W	N, E, W, S	
	CLASSROOM B-6	C, W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	STORAGE 7	C, W	N, E, W, S	
	CLASSROOM B-7	W	N, E, S	
	CLASSROOM B-8	W	N, W, S	
	WORKROOM	W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	DISCOVER LAB B-9	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM B-10	C, W	N, E, W, S	
	CLASSROOM B-11	C, W	N, E, W, S	
	CLASSROOM B-12	C, W	N, E, W, S	
	CLASSROOM B-13	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	CLASSROOM B-1	W	N, W	S
	CLASSROOM B-2	W	W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building B

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM B-3	W	W, S	
	CLASSROOM B-4	W	W, S	
	CLASSROOM B-5	W	W, S	
	CLASSROOM B-6	W	S	
	CLASSROOM B-7	W	E	
	CLASSROOM B-8	W	W	
	WORKROOM	W	N	
	DISCOVER LAB B-9	W	N, E	
	CLASSROOM B-10	W	E, S	
	CLASSROOM B-11	W	E, S	
	CLASSROOM B-12	W	E, S	
	CLASSROOM B-13	W	N, E	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM B-1	O	N, E, W, S	S
	CLASSROOM B-2	O	N, E, W, S	
	CLASSROOM B-3	O	N, E, W, S	
	CLASSROOM B-4	O	N, E, W, S	
	CLASSROOM B-5	O	N, E, W, S	
	CLASSROOM B-6	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	CLASSROOM B-7	O	N, E, S	
	CLASSROOM B-8	O	N, W, S	
	WORKROOM	O	N, E, W, S	
	DISCOVER LAB B-9	O	N, E, W, S	
	CLASSROOM B-10	O	N, E, W, S	
	CLASSROOM B-11	O	N, E, W, S	
	CLASSROOM B-12	O	N, E, W, S	
	CLASSROOM B-13	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM B-1	O	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM B-2	O	N, E, W, S	
	CLASSROOM B-3	O	N, E, W, S	
	CLASSROOM B-4	O	N, E, W, S	
	CLASSROOM B-5	O	N, E, W, S	
	CLASSROOM B-6	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	CLASSROOM B-7	O	N, E, S	
	CLASSROOM B-8	O	N, W, S	
	WORKROOM	O	N, E, W, S	
	DISCOVER LAB B-9	O	N, E, W, S	
	CLASSROOM B-10	O	N, E, W, S	
	CLASSROOM B-11	O	N, E, W, S	
	CLASSROOM B-12	O	N, E, W, S	
	CLASSROOM B-13	O	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	CLASSROOM B-1	F	*	S
	CLASSROOM B-2	F	*	
	CLASSROOM B-3	F	*	
	CLASSROOM B-4	F	*	
	CLASSROOM B-5	F	*	
	CLASSROOM B-6	F	*	
	OFFICE 1	F	*	
	CLASSROOM B-7	F	*	
	CLASSROOM B-8	F	*	
	WORKROOM	F	*	
	DISCOVER LAB B-9	F	*	
	CLASSROOM B-10	F	*	
	CLASSROOM B-11	F	*	
	CLASSROOM B-12	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM B-13	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	CLASSROOM B-1	F	*	S
	CLASSROOM B-2	F	*	
	CLASSROOM B-3	F	*	
	CLASSROOM B-4	F	*	
	CLASSROOM B-5	F	*	
	CLASSROOM B-6	F	*	
	OFFICE 1	F	*	
	CLASSROOM B-7	F	*	
	CLASSROOM B-8	F	*	
	WORKROOM	F	*	
	DISCOVER LAB B-9	F	*	
	CLASSROOM B-10	F	*	
	CLASSROOM B-11	F	*	
	CLASSROOM B-12	F	*	
	CLASSROOM B-13	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	CLASSROOM B-1	O	N, W	S
	CLASSROOM B-2	O	W, S	
	CLASSROOM B-3	O	W, S	
	CLASSROOM B-4	O	W, S	
	CLASSROOM B-5	O	N, E	
	CLASSROOM B-6	O	N	
	GIRL'S RESTROOM 1	O	N, E	
	BOY'S RESTROOM 1	O	N, E, S	
	CUSTODIAL 1	O	E	
	GIRL'S RESTROOM 2	O	N, W	
	BOY'S RESTROOM 2	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CUSTODIAL 2	O	W	
	OFFICE 1	O	N, E, W	
	STORAGE 6	O	N	
	STORAGE 7	O	N	
	CLASSROOM B-7	O	E, S	
	CLASSROOM B-8	O	W, S	
	WORKROOM	O	N, E, W, S	
	STORAGE 4	O	S	
	MEN'S RESTROOM	O	E, S	
	WOMEN'S RESTROOM	O	W, S	
	STORAGE 5	O	S	
	DISCOVER LAB B-9	O	N, E, W, S	
	STORAGE 1	O	E	
	CLASSROOM B-10	O	E, S	
	CLASSROOM B-11	O	E, S	
	CLASSROOM B-12	O	E, S	
	CLASSROOM B-13	O	N, E	
SEALANT (WINDOWS), BLACK, GUMMY	CLASSROOM B-7	O	S	S
	CLASSROOM B-8	O	S	
	COURTYARD 1	O	E, W, S	
	COURTYARD 2	O	E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CLASSROOM B-1	O	W	S
	CLASSROOM B-2	O	W	
	ELECTRICAL 1	O	E	
	CLASSROOM B-3	O	W	
	CLASSROOM B-4	O	W	
	CLASSROOM B-5	O	E	
	CLASSROOM B-6	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building B

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 1	O	E	
	BOY'S RESTROOM 1	O	E	
	CUSTODIAL 1	O	E, W	
	GIRL'S RESTROOM 2	O	W	
	BOY'S RESTROOM 2	O	W	
	CUSTODIAL 2	O	E, W	
	PIPE CHASE	O	E, W	
	OFFICE 1	O	E, W	
	CLASSROOM B-7	O	E	
	CLASSROOM B-8	O	W	
	WORKROOM	O	N, E, W	
	STORAGE 4	O	S	
	MEN'S RESTROOM	O	S	
	WOMEN'S RESTROOM	O	S	
	STORAGE 5	O	S	
	DISCOVER LAB B-9	O	E, W	
	STORAGE 1	O	E	
	STORAGE 2	O	W	
	CLASSROOM B-10	O	E	
	CLASSROOM B-11	O	E	
	FIRE RISER	O	N	
	ELECTRICAL 2	O	W, S	
	CLASSROOM B-12	O	E	
	CLASSROOM B-13	O	E	
	STORAGE 3	O	N, W	
	COURTYARD 1	O	E, W, S	
	COURTYARD 2	O	E, W	
	EXTERIOR	O	N, E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
SEALANT (DOORS, WINDOWS), TAN, PLIABLE	ELECTRICAL 1	O	E	S
	ELECTRICAL 2	O	W	
	STORAGE 3	O	N, W	
	COURTYARD 1	O	E, W, S	
	COURTYARD 2	O	E, W, S	
	EXTERIOR	O	N, E, W	
SINK ACOUSTICAL COATING, BLACK, ROUGH	CLASSROOM B-1	O	N	S
	CLASSROOM B-2	O	S	
	CLASSROOM B-3	O	S	
	CLASSROOM B-4	O	S	
	CLASSROOM B-5	O	N	
	CLASSROOM B-6	O	N	
	WORKROOM	O	S	
	DISCOVER LAB B-9	O	N, W, S	
	CLASSROOM B-10	O	S	
	CLASSROOM B-11	O	S	
	CLASSROOM B-12	O	S	
	CLASSROOM B-13	O	N	
DUCT SEAM TAPE, 2", WHITE, CANVAS	CLASSROOM B-1	O	*	S
	CLASSROOM B-2	O	*	
	LOCKERS 1	O	*	
	ELECTRICAL 1	O	*	
	CLASSROOM B-3	O	*	
	CLASSROOM B-4	O	*	
	CLASSROOM B-5	O	*	
	CLASSROOM B-6	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CUSTODIAL 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	CUSTODIAL 2	O	*	
	PIPE CHASE	O	*	
	OFFICE 1	O	*	
	STORAGE 6	O	*	
	STORAGE 7	O	*	
	CLASSROOM B-7	O	*	
	CLASSROOM B-8	O	*	
	WORKROOM	O	*	
	STORAGE 4	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	STORAGE 5	O	*	
	DISCOVER LAB B-9	O	*	
	STORAGE 1	O	*	
	STORAGE 2	O	*	
	CLASSROOM B-10	O	*	
	CLASSROOM B-11	O	*	
	FIRE RISER	O	*	
	ELECTRICAL 2	O	*	
	LOCKERS 2	O	*	
	CLASSROOM B-12	O	*	
	CLASSROOM B-13	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	CLASSROOM B-1	O	*	S
	CLASSROOM B-2	O	*	
	LOCKERS 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ELECTRICAL 1	O	*	
	CLASSROOM B-3	O	*	
	CLASSROOM B-4	O	*	
	CLASSROOM B-5	O	*	
	CLASSROOM B-6	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	CUSTODIAL 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	CUSTODIAL 2	O	*	
	PIPE CHASE	O	*	
	OFFICE 1	O	*	
	STORAGE 6	O	*	
	STORAGE 7	O	*	
	CLASSROOM B-7	O	*	
	CLASSROOM B-8	O	*	
	WORKROOM	O	*	
	STORAGE 4	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	STORAGE 5	O	*	
	DISCOVER LAB B-9	O	*	
	STORAGE 1	O	*	
	STORAGE 2	O	*	
	CLASSROOM B-10	O	*	
	CLASSROOM B-11	O	*	
	FIRE RISER	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ELECTRICAL 2	O	*	
	LOCKERS 2	O	*	
	CLASSROOM B-12	O	*	
	CLASSROOM B-13	O	*	
	STORAGE 3	O	*	
PLASTER, GRAY, CEMENTITIOUS	LOCKERS 1	C	*	S
	LOCKERS 2	C	*	
BRICK, 4"X16", TAN, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	W, S	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	COURTYARD 1	W	E, W, S	
	COURTYARD 2	W	E, W, S	
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	W, S	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	COURTYARD 1	W	E, W, S	
	COURTYARD 2	W	E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	FIRE RISER	W	W, S	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	COURTYARD 1	W	E, W, S	
	COURTYARD 2	W	E, W, S	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	W, S	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	COURTYARD 1	W	E, W, S	
	COURTYARD 2	W	E, W, S	
	EXTERIOR	W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CLASSROOM B-1	F	*	S
	CLASSROOM B-2	F	*	
	LOCKERS 1	F	*	
	ELECTRICAL 1	F	*	
	CLASSROOM B-3	F	*	
	CLASSROOM B-4	F	*	
	CLASSROOM B-5	F	*	
	CLASSROOM B-6	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
	CUSTODIAL 1	F	*	
	GIRL'S RESTROOM 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building B

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	BOY'S RESTROOM 2	F	*	
	CUSTODIAL 2	F	*	
	PIPE CHASE	F	*	
	OFFICE 1	F	*	
	STORAGE 6	F	*	
	STORAGE 7	F	*	
	CLASSROOM B-7	F	*	
	CLASSROOM B-8	F	*	
	WORKROOM	F	*	
	STORAGE 4	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	STORAGE 5	F	*	
	DISCOVER LAB B-9	F	*	
	STORAGE 1	F	*	
	STORAGE 2	F	*	
	CLASSROOM B-10	F	*	
	CLASSROOM B-11	F	*	
	FIRE RISER	F	*	
	ELECTRICAL 2	F	*	
	LOCKERS 2	F	*	
	CLASSROOM B-12	F	*	
	CLASSROOM B-13	F	*	
	STORAGE 3	F	*	
	EXTERIOR	F	*	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE 6	F	*	S
	STORAGE 7	F	*	
	STORAGE 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	STORAGE 5	F	*	
	STORAGE 1	F	*	
	STORAGE 2	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE 6	F	*	S
	STORAGE 7	F	*	
	STORAGE 4	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	STORAGE 5	F	*	
	STORAGE 1	F	*	
	STORAGE 2	F	*	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	ELECTRICAL 1	O	N, E, W, S	S
	CUSTODIAL 1	O	N, E, W, S	
	CUSTODIAL 2	O	N, E, W, S	
	STORAGE 6	O	N, E, W, S	
	STORAGE 7	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	MEN'S RESTROOM	O	N, E, W, S	
	WOMEN'S RESTROOM	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	FIRE RISER	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	ELECTRICAL 1	O	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CUSTODIAL 1	O	N, E, W, S	
	CUSTODIAL 2	O	N, E, W, S	
	STORAGE 6	O	N, E, W, S	
	STORAGE 7	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	MEN'S RESTROOM	O	N, E, W, S	
	WOMEN'S RESTROOM	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	FIRE RISER	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 3	C	*	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 3	C	*	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 3	C	*	S
TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER	C	*	
	ELECTRICAL 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER	C	*	
	ELECTRICAL 2	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER	C	*	
	ELECTRICAL 2	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM 1	C	*	S
	BOY'S RESTROOM 1	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CUSTODIAL 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C	*	
	BOY'S RESTROOM 2	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM 1	C	*	S
	BOY'S RESTROOM 1	C	*	
	CUSTODIAL 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C	*	
	BOY'S RESTROOM 2	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM 1	C	*	S
	BOY'S RESTROOM 1	C	*	
	CUSTODIAL 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C	*	
	BOY'S RESTROOM 2	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	COURTYARD 1	F	*	S
	COURTYARD 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	EXTERIOR	F	*	
CONCRETE (COURTYARDS), GRAY, CEMENTITIOUS, GRAVEL FINISH	COURTYARD 1	F	*	S
	COURTYARD 2	F	*	
BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	COURTYARD 1	O	*	S
	COURTYARD 2	O	*	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	COURTYARD 1	O	*	S
	COURTYARD 2	O	*	
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
PIPE END SEALANT, GRAY, PLIABLE	ROOF	O	*	S

* - *Not Applicable*

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING TILE, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM C-1	C	*	S
	CLASSROOM C-2	C	*	
	CLASSROOM C-3	C	*	
	CLASSROOM C-4	C	*	
	CLASSROOM C-5	C	*	
	WORKROOM	C	*	
	CLASSROOM C-6	C	*	
	OFFICE	C	*	
	SCIENCE LAB C-8	C	*	
	CLASSROOM C-9	C	*	
	CLASSROOM C-10	C	*	
	CLASSROOM C-11	C	*	
	CLASSROOM C-12	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM C-1	C, W	N, E, W, S	S
	CLASSROOM C-2	C, W	N, E, W, S	
	CLASSROOM C-3	C, W	N, E, W, S	
	CLASSROOM C-4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM C-5	C, W	N, E, W, S	
	WORKROOM	W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	STORAGE 3	C, W	N, E, W, S	
	CLASSROOM C-6	W	N, E, W, S	
	TO 1	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	OFFICE	W	N, E, W, S	
	TO 2	C, W	N, E, W, S	
	SCIENCE LAB C-8	C, W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	CLASSROOM C-9	C, W	N, E, W, S	
	CLASSROOM C-10	C, W	N, E, W, S	
	CLASSROOM C-11	C, W	N, E, W, S	
	CLASSROOM C-12	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM C-1	C, W	N, E, W, S	S
	CLASSROOM C-2	C, W	N, E, W, S	
	CLASSROOM C-3	C, W	N, E, W, S	
	CLASSROOM C-4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM C-5	C, W	N, E, W, S	
	WORKROOM	W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	STORAGE 3	C, W	N, E, W, S	
	CLASSROOM C-6	W	N, E, W, S	
	TO 1	C, W	N, E, W, S	
	OFFICE	W	N, E, W, S	
	TO 2	C, W	N, E, W, S	
	SCIENCE LAB C-8	C, W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
 Kyrene Centennial Middle School, KSD
 Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	HALL 2	C, W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	CLASSROOM C-9	C, W	N, E, W, S	
	CLASSROOM C-10	C, W	N, E, W, S	
	CLASSROOM C-11	C, W	N, E, W, S	
	CLASSROOM C-12	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM C-1	C, W	N, E, W, S	S
	CLASSROOM C-2	C, W	N, E, W, S	
	CLASSROOM C-3	C, W	N, E, W, S	
	CLASSROOM C-4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM C-5	C, W	N, E, W, S	
	WORKROOM	W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	STORAGE 3	C, W	N, E, W, S	
	CLASSROOM C-6	W	N, E, W, S	
	TO 1	C, W	N, E, W, S	
	OFFICE	W	N, E, W, S	
	TO 2	C, W	N, E, W, S	
	SCIENCE LAB C-8	C, W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	CLASSROOM C-9	C, W	N, E, W, S	
	CLASSROOM C-10	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM C-11	C, W	N, E, W, S	
	CLASSROOM C-12	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	CLASSROOM C-1	W	N, W	S
	CLASSROOM C-2	W	N, E	
	CLASSROOM C-3	W	N, E	
	CLASSROOM C-4	W	W, S	
	CLASSROOM C-5	W	N, W, S	
	WORKROOM	W	W	
	CLASSROOM C-6	W	N, S	
	SCIENCE LAB C-8	W	N, E, S	
	CLASSROOM C-9	W	N, E	
	CLASSROOM C-10	W	W, S	
	CLASSROOM C-11	W	W, S	
	CLASSROOM C-12	W	E, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	CLASSROOM C-1	F	*	S
	CLASSROOM C-2	F	*	
	CLASSROOM C-3	F	*	
	CLASSROOM C-4	F	*	
	CLASSROOM C-5	F	*	
	WORKROOM	F	*	
	CLASSROOM C-6	F	*	
	SCIENCE LAB C-8	F	*	
	CLASSROOM C-9	F	*	
	CLASSROOM C-10	F	*	
	CLASSROOM C-11	F	*	
	CLASSROOM C-12	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	CLASSROOM C-1	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM C-2	F	*	
	CLASSROOM C-3	F	*	
	CLASSROOM C-4	F	*	
	CLASSROOM C-5	F	*	
	WORKROOM	F	*	
	CLASSROOM C-6	F	*	
	SCIENCE LAB C-8	F	*	
	CLASSROOM C-9	F	*	
	CLASSROOM C-10	F	*	
	CLASSROOM C-11	F	*	
	CLASSROOM C-12	F	*	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM C-1	O	N, E, W, S	S
	CLASSROOM C-2	O	N, E, W, S	
	CLASSROOM C-3	O	N, E, W, S	
	CLASSROOM C-4	O	N, E, W, S	
	HALL 1	O	N, E, W, S	
	CLASSROOM C-5	O	N, E, W, S	
	WORKROOM	O	N, E, W, S	
	CLASSROOM C-6	O	N, E, W, S	
	OFFICE	O	N, E, W, S	
	SCIENCE LAB C-8	O	N, E, W, S	
	HALL 2			
	CLASSROOM C-9	O	N, E, W, S	
	CLASSROOM C-10	O	N, E, W, S	
	CLASSROOM C-11	O	N, E, W, S	
	CLASSROOM C-12	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM C-1	O	N, E, W, S	S
	CLASSROOM C-2	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM C-3	O	N, E, W, S	
	CLASSROOM C-4	O	N, E, W, S	
	HALL 1	O	N, E, W, S	
	CLASSROOM C-5	O	N, E, W, S	
	WORKROOM	O	N, E, W, S	
	CLASSROOM C-6	O	N, E, W, S	
	OFFICE	O	N, E, W, S	
	SCIENCE LAB C-8	O	N, E, W, S	
	HALL 2			
	CLASSROOM C-9	O	N, E, W, S	
	CLASSROOM C-10	O	N, E, W, S	
	CLASSROOM C-11	O	N, E, W, S	
	CLASSROOM C-12	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	CLASSROOM C-1	O	N, W	S
	CLASSROOM C-2	O	N, E	
	CLASSROOM C-3	O	N, E	
	CLASSROOM C-4	O	N, W	
	STORAGE 1	O	E	
	HALL 1	O	N, E, W, S	
	STORAGE 2	O	W	
	CLASSROOM C-5	O	N, E, W	
	BOY'S RESTROOM 1	O	N, E, W	
	GIRL'S RESTROOM 1	O	N, E, W	
	CUSTODIAL 1	O	N	
	WORKROOM	O	N, E, W, S	
	STORAGE 4	O	E	
	WOMEN'S RESTROOM	O	E, S	
	MEN'S RESTROOM	O	N, E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 3	O	E	
	CLASSROOM C-6	O	N, E, W, S	
	TO 1	O	E	
	OFFICE	O	E, S	
	TO 2	O	E	
	GIRL'S RESTROOM 3	O	E, S	
	BOY'S RESTROOM 3	O	W, S	
	CUSTODIAL 2	O	S	
	SCIENCE LAB C-8	O	N, E, W, S	
	STORAGE 5	O	E	
	HALL 2	O	N, E, W, S	
	STORAGE 6	O	W	
	CLASSROOM C-9	O	E, S	
	CLASSROOM C-10	O	E, S	
	CLASSROOM C-11	O	W, S	
	CLASSROOM C-12	O	E, S	
	BOY'S RESTROOM 2	O	N	
	GIRL'S RESTROOM 2	O	N	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CLASSROOM C-1	O	N	S
	CLASSROOM C-2	O	N	
	ELECTRICAL 1	O	S	
	CLASSROOM C-3	O	N	
	CLASSROOM C-4	O	W	
	STORAGE 1	O	E	
	HALL 1	O	E, W	
	STORAGE 2	O	W	
	CLASSROOM C-5	O	E, W	
	BOY'S RESTROOM 1	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 1	O	N	
	CUSTODIAL 1	O	N, S	
	PIPE CHASE 1	O	N	
	WORKROOM	O	N, W, S	
	STORAGE 4	O	E	
	WOMEN'S RESTROOM	O	E	
	MEN'S RESTROOM	O	E	
	STORAGE 3	O	E	
	CLASSROOM C-6	O	N, S	
	OFFICE	O	N, S	
	GIRL'S RESTROOM 3	O	S	
	BOY'S RESTROOM 3	O	S	
	PIPE CHASE 2	O	S	
	CUSTODIAL 2	O	N, S	
	SCIENCE LAB C-8	O	E, W	
	STORAGE 5	O	E	
	HALL 2	O	E, W	
	STORAGE 6	O	W	
	CLASSROOM C-9	O	E	
	CLASSROOM C-10	O	S	
	ELECTRICAL 2	O	N	
	CLASSROOM C-11	O	S	
	CLASSROOM C-12	O	S	
	BOY'S RESTROOM 2	O	N	
	GIRL'S RESTROOM 2	O	N	
	EXTERIOR	O	N, E, W, S	
SEALANT (WINDOWS), BLACK, GUMMY	CLASSROOM C-6	O	W	S
	EXTERIOR	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building C

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	CLASSROOM C-1	O	W	
	CLASSROOM C-2	O	E	
	CLASSROOM C-3	O	E	
	CLASSROOM C-4	O	W	
	WORKROOM	O	E	
	CLASSROOM C-9	O	E	
	CLASSROOM C-10	O	W	
	CLASSROOM C-11	O	W	
	CLASSROOM C-12	O	E	
DUCT SEAM TAPE, 2", WHITE, CANVAS	CLASSROOM C-1	O	*	S
	CLASSROOM C-2	O	*	
	LOCKERS 1	O	*	
	ELECTRICAL 1	O	*	
	CLASSROOM C-3	O	*	
	CLASSROOM C-4	O	*	
	STORAGE 1	O	*	
	HALL 1	O	*	
	STORAGE 2	O	*	
	CLASSROOM C-5	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	CUSTODIAL 1	O	*	
	PIPE CHASE 1	O	*	
	WORKROOM	O	*	
	STORAGE 4	O	*	
	WOMEN'S RESTROOM	O	*	
	MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building C

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM C-6	O	*	
	TO 1	O	*	
	OFFICE	O	*	
	TO 2	O	*	
	GIRL'S RESTROOM 3	O	*	
	BOY'S RESTROOM 3	O	*	
	PIPE CHASE 2	O	*	
	CUSTODIAL 2	O	*	
	SCIENCE LAB C-8	O	*	
	STORAGE 5	O	*	
	HALL 2	O	*	
	STORAGE 6	O	*	
	CLASSROOM C-9	O	*	
	CLASSROOM C-10	O	*	
	FIRE RISER	O	*	
	ELECTRICAL 2	O	*	
	LOCKERS 2	O	*	
	CLASSROOM C-11	O	*	
	CLASSROOM C-12	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	CLASSROOM C-1	O	*	S
	CLASSROOM C-2	O	*	
	LOCKERS 1	O	*	
	ELECTRICAL 1	O	*	
	CLASSROOM C-3	O	*	
	CLASSROOM C-4	O	*	
	STORAGE 1	O	*	
	HALL 1	O	*	
	STORAGE 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM C-5	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	CUSTODIAL 1	O	*	
	PIPE CHASE 1	O	*	
	WORKROOM	O	*	
	STORAGE 4	O	*	
	WOMEN'S RESTROOM	O	*	
	MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	CLASSROOM C-6	O	*	
	TO 1	O	*	
	OFFICE	O	*	
	TO 2	O	*	
	GIRL'S RESTROOM 3	O	*	
	BOY'S RESTROOM 3	O	*	
	PIPE CHASE 2	O	*	
	CUSTODIAL 2	O	*	
	SCIENCE LAB C-8	O	*	
	STORAGE 5	O	*	
	HALL 2	O	*	
	STORAGE 6	O	*	
	CLASSROOM C-9	O	*	
	CLASSROOM C-10	O	*	
	FIRE RISER	O	*	
	ELECTRICAL 2	O	*	
	LOCKERS 2	O	*	
	CLASSROOM C-11	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building C

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM C-12	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CLASSROOM C-1	F	*	S
	CLASSROOM C-2	F	*	
	LOCKERS 1	F	*	
	ELECTRICAL 1	F	*	
	CLASSROOM C-3	F	*	
	CLASSROOM C-4	F	*	
	STORAGE 1	F	*	
	HALL 1	F	*	
	STORAGE 2	F	*	
	CLASSROOM C-5	F	*	
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	CUSTODIAL 1	F	*	
	PIPE CHASE 1	F	*	
	WORKROOM	F	*	
	STORAGE 4	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	STORAGE 3	F	*	
	CLASSROOM C-6	F	*	
	TO 1	F	*	
	OFFICE	F	*	
	TO 2	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building C

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	PIPE CHASE 2	F	*	
	CUSTODIAL 2	F	*	
	SCIENCE LAB C-8	F	*	
	STORAGE 5	F	*	
	HALL 2	F	*	
	STORAGE 6	F	*	
	CLASSROOM C-9	F	*	
	CLASSROOM C-10	F	*	
	FIRE RISER	F	*	
	ELECTRICAL 2	F	*	
	LOCKERS 2	F	*	
	CLASSROOM C-11	F	*	
	CLASSROOM C-12	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
	EXTERIOR	F	*	
BRICK, 4"X16", TAN, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, W	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, W	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, W	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, W	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
PLASTER, GRAY, CEMENTITIOUS	LOCKERS 1	C	*	S
	LOCKERS 2	C	*	
TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER	C, W	E, S	
	ELECTRICAL 2	C, W	N, W	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER	C, W	E, S	
	ELECTRICAL 2	C, W	N, W	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER	C, W	E, S	
	ELECTRICAL 2	C, W	N, W	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	ELECTRICAL 1	O	N, E, W, S	S
	STORAGE 1	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 4	O	N, E, W, S	
	WOMEN'S RESTROOM	O	N, E, W, S	
	MEN'S RESTROOM	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	TO 1	O	N, E, W, S	
	TO 2	O	N, E, W, S	
	CUSTODIAL 2	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	
	STORAGE 6	O	N, E, W, S	
	FIRE RISER	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	ELECTRICAL 1	O	N, E, W, S	S
	STORAGE 1	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	WOMEN'S RESTROOM	O	N, E, W, S	
	MEN'S RESTROOM	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	TO 1	O	N, E, W, S	
	TO 2	O	N, E, W, S	
	CUSTODIAL 2	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	
	STORAGE 6	O	N, E, W, S	
	FIRE RISER	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	ELECTRICAL 1	O	S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ELECTRICAL 2	O	N	
	EXTERIOR	O	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE 1	F	*	S
	HALL 1	F	*	
	STORAGE 2	F	*	
	STORAGE 4	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	STORAGE 3	F	*	
	TO 1	F	*	
	TO 2	F	*	
	STORAGE 5	F	*	
	HALL 2	F	*	
	STORAGE 6	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE 1	F	*	S
	HALL 1	F	*	
	STORAGE 2	F	*	
	STORAGE 4	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	STORAGE 3	F	*	
	TO 1	F	*	
	TO 2	F	*	
	STORAGE 5	F	*	
	HALL 2	F	*	
	STORAGE 6	F	*	
SINK ACOUSTICAL COATING, GRAY, ROUGH	CLASSROOM C-5	O	N	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	SCIENCE LAB C-8	O	S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CUSTODIAL 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM 3	C	*	
	BOY'S RESTROOM 3	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C	*	
	GIRL'S RESTROOM 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CUSTODIAL 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM 3	C	*	
	BOY'S RESTROOM 3	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C	*	
	GIRL'S RESTROOM 2	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CUSTODIAL 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM 3	C	*	
	BOY'S RESTROOM 3	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C	*	
	GIRL'S RESTROOM 2	C	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	BOY'S RESTROOM 1	W	N, E, W, S	S
	GIRL'S RESTROOM 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	BOY'S RESTROOM 1	W	N, E, W, S	S
	GIRL'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	BOY'S RESTROOM 1	W	N, E, W, S	S
	GIRL'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 3	W	N, E, W, S	
	BOY'S RESTROOM 3	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	BOY'S RESTROOM 1	F	*	S
	GIRL'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH	BOY'S RESTROOM 1	F	*	S
	GIRL'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	BOY'S RESTROOM 1	F	*	S
	GIRL'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 3	F	*	
	BOY'S RESTROOM 3	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	BOY'S RESTROOM 1	F	*	S
	GIRL'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 3	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 3	F	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	BOY'S RESTROOM 2	W	N, E, W, S	S
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	BOY'S RESTROOM 2	W	N, E, W, S	S
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	BOY'S RESTROOM 2	W	N, E, W, S	S
	GIRL'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	BOY'S RESTROOM 2	W	N, E, W, S	S
	GIRL'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH	BOY'S RESTROOM 2	F	*	S
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH	BOY'S RESTROOM 2	F	*	S
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	BOY'S RESTROOM 2	F	*	S
	GIRL'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	BOY'S RESTROOM 2	F	*	S
	GIRL'S RESTROOM 2	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
CONCRETE (COURTYARDS), GRAY, CEMENTITIOUS, GRAVEL FINISH	EXTERIOR	F	*	S
BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	EXTERIOR	O	*	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	EXTERIOR	O	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building C

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
PIPE END SEALANT, GRAY, PLIABLE	ROOF	O	*	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM D-1	C	*	S
	CLASSROOM D-2	C	*	
	CLASSROOM D-3	C	*	
	CLASSROOM D-4	C	*	
	CLASSROOM D-5	C	*	
	OFFICE	C	*	
	CLASSROOM D-6	C	*	
	CLASSROOM D-7	C	*	
	TEACHER WORKROOM	C	*	
	DISCOVERY LAB D-8	C	*	
	CLASSROOM D-9	C	*	
	CLASSROOM D-10	C	*	
	CLASSROOM D-11	C	*	
	CLASSROOM D-12	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM D-1	C, W	N, E, W, S	S
	CLASSROOM D-2	C, W	N, E, W, S	
	CLASSROOM D-3	C, W	N, E, W, S	
	CLASSROOM D-4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM D-5	C, W	N, E, W, S	
	OFFICE	W	N, E, W, S	
	TO 1	C, W	N, E, W, S	
	TO 2	C, W	N, E, W, S	
	CLASSROOM D-6	W	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM D-7	W	N, W, S	
	TEACHER WORKROOM	W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	DISCOVERY LAB D-8	C, W	N, E, W, S	
	STORAGE 3	C, W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	CLASSROOM D-9	C, W	N, E, W, S	
	CLASSROOM D-10	C, W	N, E, W, S	
	CLASSROOM D-11	C, W	N, E, W, S	
	CLASSROOM D-12	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM D-1	C, W	N, E, W, S	S
	CLASSROOM D-2	C, W	N, E, W, S	
	CLASSROOM D-3	C, W	N, E, W, S	
	CLASSROOM D-4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM D-5	W	N, E, W, S	
	OFFICE	W	N, E, W, S	
	TO 1	C, W	N, E, W, S	
	TO 2	C, W	N, E, W, S	
	CLASSROOM D-6	W	N, E, S	
	CLASSROOM D-7	W	N, W, S	
	TEACHER WORKROOM	W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STORAGE 6	C, W	N, E, W, S	
	DISCOVERY LAB D-8	C, W	N, E, W, S	
	STORAGE 3	C, W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	CLASSROOM D-9	C, W	N, E, W, S	
	CLASSROOM D-10	C, W	N, E, W, S	
	CLASSROOM D-11	C, W	N, E, W, S	
	CLASSROOM D-12	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM D-1	C, W	N, E, W, S	S
	CLASSROOM D-2	C, W	N, E, W, S	
	CLASSROOM D-3	C, W	N, E, W, S	
	CLASSROOM D-4	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM D-5	C, W	N, E, W, S	
	OFFICE	W	N, E, W, S	
	TO 1	C, W	N, E, W, S	
	TO 2	C, W	N, E, W, S	
	CLASSROOM D-6	W	N, E, S	
	CLASSROOM D-7	W	N, W, S	
	TEACHER WORKROOM	W	N, E, W, S	
	STORAGE 5	C, W	N, E, W, S	
	STORAGE 6	C, W	N, E, W, S	
	DISCOVERY LAB D-8	C, W	N, E, W, S	
	STORAGE 3	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HALL 2	C, W	N, E, W, S	
	STORAGE 4	C, W	N, E, W, S	
	CLASSROOM D-9	C, W	N, E, W, S	
	CLASSROOM D-10	C, W	N, E, W, S	
	CLASSROOM D-11	C, W	N, E, W, S	
	CLASSROOM D-12	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	CLASSROOM D-1	W	W, S	S
	CLASSROOM D-2	W	N, W	
	CLASSROOM D-3	W	N, W	
	CLASSROOM D-4	W	E, S	
	CLASSROOM D-5	W	E, W, S	
	CLASSROOM D-6	W	E	
	CLASSROOM D-7	W	W	
	TEACHER WORKROOM	W	S	
	DISCOVER LAB D-8	W	E, W, S	
	CLASSROOM D-9	W	W, S	
	CLASSROOM D-10	W	N, E	
	CLASSROOM D-11	W	N, E	
	CLASSROOM D-12	W	E, S	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	CLASSROOM D-1	O	N, E, W, S	S
	CLASSROOM D-2	O	N, E, W, S	
	CLASSROOM D-3	O	N, E, W, S	
	CLASSROOM D-4	O	N, E, W, S	
	HALL 1	O	N, E, W, S	
	CLASSROOM D-5	O	N, E, W, S	
	CLASSROOM D-6	O	N, E, S	
	CLASSROOM D-7	O	N, W, S	
	TEACHER WORKROOM	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	DISCOVER LAB D-8	O	N, E, W, S	
	HALL 2	O	N, E, W, S	
	CLASSROOM D-9	O	N, E, W, S	
	CLASSROOM D-10	O	N, E, W, S	
	CLASSROOM D-11	O	N, E, W, S	
	CLASSROOM D-12	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM D-1	O	N, E, W, S	S
	CLASSROOM D-2	O	N, E, W, S	
	CLASSROOM D-3	O	N, E, W, S	
	CLASSROOM D-4	O	N, E, W, S	
	HALL 1	O	N, E, W, S	
	CLASSROOM D-5	O	N, E, W, S	
	CLASSROOM D-6	O	N, E, S	
	CLASSROOM D-7	O	N, W, S	
	TEACHER WORKROOM	O	N, E, W, S	
	DISCOVER LAB D-8	O	N, E, W, S	
	HALL 2	O	N, E, W, S	
	CLASSROOM D-9	O	N, E, W, S	
	CLASSROOM D-10	O	N, E, W, S	
	CLASSROOM D-11	O	N, E, W, S	
	CLASSROOM D-12	O	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	CLASSROOM D-1	F	*	S
	CLASSROOM D-2	F	*	
	CLASSROOM D-3	F	*	
	CLASSROOM D-4	F	*	
	CLASSROOM D-5	F	*	
	CLASSROOM D-6	F	*	
	CLASSROOM D-7	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	TEACHER WORKROOM	F	*	
	DISCOVER LAB D-8	F	*	
	CLASSROOM D-9	F	*	
	CLASSROOM D-10	F	*	
	CLASSROOM D-11	F	*	
	CLASSROOM D-12	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	CLASSROOM D-1	F	*	S
	CLASSROOM D-2	F	*	
	CLASSROOM D-3	F	*	
	CLASSROOM D-4	F	*	
	CLASSROOM D-5	F	*	
	CLASSROOM D-6	F	*	
	CLASSROOM D-7	F	*	
	TEACHER WORKROOM	F	*	
	DISCOVER LAB D-8	F	*	
	CLASSROOM D-9	F	*	
	CLASSROOM D-10	F	*	
	CLASSROOM D-11	F	*	
	CLASSROOM D-12	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	CLASSROOM D-1	O	W, S	S
	CLASSROOM D-2	O	N, W	
	CLASSROOM D-3	O	N, W	
	CLASSROOM D-4	O	E, W	
	STORAGE 1	O	N	
	HALL 1	O	N, E, W, S	
	STORAGE 2	O	S	
	CLASSROOM D-5	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 1	O	E, S	
	BOY'S RESTROOM 1	O	N, E, S	
	CUSTODIAL 1	O	E	
	GIRL'S RESTROOM 2	O	W, S	
	BOY'S RESTROOM 2	O	N, W, S	
	CUSTODIAL 2	O	W	
	OFFICE	O	E, W, S	
	TO 1	O	S	
	TO 2	O	S	
	CLASSROOM D-6	O	N, E	
	CLASSROOM D-7	O	N, W	
	TEACHER WORKROOM	O	E, W, S	
	STORAGE 5	O	N	
	MEN'S RESTROOM	O	N, E	
	WOMEN'S RESTROOM	O	N, W	
	STORAGE 6	O	N	
	DISCOVERY LAB D-8	O	N, E, W, S	
	STORAGE 3	O	N	
	HALL 2	O	N, E, W, S	
	STORAGE 4	O	S	
	CLASSROOM D-9	O	E, W	
	CLASSROOM D-10	O	N, E	
	ELECTRICAL 2	O	W	
	CLASSROOM D-11	O	N, E	
	CLASSROOM D-12	O	E, S	
SINK ACOUSTICAL COATING, BLACK, ROUGH	CLASSROOM D-1	O	S	S
	CLASSROOM D-2	O	N	
	CLASSROOM D-3	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM D-4	O	E	
	TEACHER WORKROOM	O	E, W	
	CLASSROOM D-9	O	W	
	CLASSROOM D-10	O	E	
	CLASSROOM D-11	O	N	
	CLASSROOM D-12	O	S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CLASSROOM D-1	O	W	S
	CLASSROOM D-2	O	W	
	ELECTRICAL 1	O	E	
	CLASSROOM D-3	O	W	
	CLASSROOM D-4	O	W	
	STORAGE 1	O	N	
	HALL 1	O	N, S	
	STORAGE 2	O	S	
	CLASSROOM D-5	O	E, W	
	GIRL'S RESTROOM 1	O	E	
	BOY'S RESTROOM 1	O	E	
	CUSTODIAL 1	O	E, W	
	GIRL'S RESTROOM 2	O	W	
	BOY'S RESTROOM 2	O	W	
	CUSTODIAL 2	O	E, W	
	PIPE CHASE	O	E, W	
	OFFICE	O	E, W	
	CLASSROOM D-6	O	E	
	CLASSROOM D-7	O	W	
	TEACHER WORKROOM	O	E, W, S	
	STORAGE 5	O	N	
	MEN'S RESTROOM	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WOMEN'S RESTROOM	O	N	
	STORAGE 6	O	N	
	DISCOVERY LAB D-8	O	E, W	
	STORAGE 3	O	N	
	HALL 2	O	N, S	
	STORAGE 4	O	S	
	CLASSROOM D-9	O	E	
	CLASSROOM D-10	O	E	
	ELECTRICAL 2	O	W	
	CLASSROOM D-11	O	E	
	CLASSROOM D-12	O	E	
DUCT SEAM TAPE, 2", WHITE, CANVAS	CLASSROOM D-1	O	*	S
	CLASSROOM D-2	O	*	
	LOCKERS 1	O	*	
	ELECTRICAL 1	O	*	
	FIRE RISER	O	*	
	CLASSROOM D-3	O	*	
	CLASSROOM D-4	O	*	
	STORAGE 1	O	*	
	HALL 1	O	*	
	STORAGE 2	O	*	
	CLASSROOM D-5	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	CUSTODIAL 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	CUSTODIAL 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	PIPE CHASE	O	*	
	OFFICE	O	*	
	TO 1	O	*	
	TO 2	O	*	
	CLASSROOM D-6	O	*	
	CLASSROOM D-7	O	*	
	TEACHER WORKROOM	O	*	
	STORAGE 5	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	STORAGE 6	O	*	
	DISCOVERY LAB D-8	O	*	
	STORAGE 3	O	*	
	HALL 2	O	*	
	STORAGE 4	O	*	
	CLASSROOM D-9	O	*	
	CLASSROOM D-10	O	*	
	ELECTRICAL 2	O	*	
	LOCKERS 2	O	*	
	CLASSROOM D-11	O	*	
	CLASSROOM D-12	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	CLASSROOM D-1	O	*	S
	CLASSROOM D-2	O	*	
	LOCKERS 1	O	*	
	ELECTRICAL 1	O	*	
	FIRE RISER	O	*	
	CLASSROOM D-3	O	*	
	CLASSROOM D-4	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 1	O	*	
	HALL 1	O	*	
	STORAGE 2	O	*	
	CLASSROOM D-5	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	CUSTODIAL 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	CUSTODIAL 2	O	*	
	PIPE CHASE	O	*	
	OFFICE	O	*	
	TO 1	O	*	
	TO 2	O	*	
	CLASSROOM D-6	O	*	
	CLASSROOM D-7	O	*	
	TEACHER WORKROOM	O	*	
	STORAGE 5	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	STORAGE 6	O	*	
	DISCOVERY LAB D-8	O	*	
	STORAGE 3	O	*	
	HALL 2	O	*	
	STORAGE 4	O	*	
	CLASSROOM D-9	O	*	
	CLASSROOM D-10	O	*	
	ELECTRICAL 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	LOCKERS 2	O	*	
	CLASSROOM D-11	O	*	
	CLASSROOM D-12	O	*	
SEALANT (WINDOWS), BLACK, GUMMY	EXTERIOR	O	N, E, W	S
PIPE END SEALANT, WHITE, PLIABLE	CLASSROOM D-1	O	*	S
	CLASSROOM D-2	O	*	
	LOCKERS 1	O	*	
	ELECTRICAL 1	O	*	
	FIRE RISER	O	*	
	CLASSROOM D-3	O	*	
	CLASSROOM D-4	O	*	
	STORAGE 1	O	*	
	HALL 1	O	*	
	STORAGE 2	O	*	
	CLASSROOM D-5	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	CUSTODIAL 1	O	*	
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	CUSTODIAL 2	O	*	
	PIPE CHASE	O	*	
	OFFICE	O	*	
	TO 1	O	*	
	TO 2	O	*	
	CLASSROOM D-6	O	*	
	CLASSROOM D-7	O	*	
	TEACHER WORKROOM	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 5	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	STORAGE 6	O	*	
	DISCOVERY LAB D-8	O	*	
	STORAGE 3	O	*	
	HALL 2	O	*	
	STORAGE 4	O	*	
	CLASSROOM D-9	O	*	
	CLASSROOM D-10	O	*	
	ELECTRICAL 2	O	*	
	LOCKERS 2	O	*	
	CLASSROOM D-11	O	*	
	CLASSROOM D-12	O	*	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CLASSROOM D-1	F	*	S
	CLASSROOM D-2	F	*	
	LOCKERS 1	F	*	
	ELECTRICAL 1	F	*	
	FIRE RISER	F	*	
	CLASSROOM D-3	F	*	
	CLASSROOM D-4	F	*	
	STORAGE 1	F	*	
	HALL 1	F	*	
	STORAGE 2	F	*	
	CLASSROOM D-5	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
	CUSTODIAL 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
	CUSTODIAL 2	F	*	
	PIPE CHASE	F	*	
	OFFICE	F	*	
	TO 1	F	*	
	TO 2	F	*	
	CLASSROOM D-6	F	*	
	CLASSROOM D-7	F	*	
	TEACHER WORKROOM	F	*	
	STORAGE 5	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	STORAGE 6	F	*	
	DISCOVERY LAB D-8	F	*	
	STORAGE 3	F	*	
	HALL 2	F	*	
	STORAGE 4	F	*	
	CLASSROOM D-9	F	*	
	CLASSROOM D-10	F	*	
	ELECTRICAL 2	F	*	
	LOCKERS 2	F	*	
	CLASSROOM D-11	F	*	
	CLASSROOM D-12	F	*	
	EXTERIOR	F	*	
PLASTER, GRAY, CEMENTITIOUS	LOCKERS 1	C	*	S
	LOCKERS 2	C	*	
BRICK, 4"X16", TAN, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, E	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N; E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, E	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, E	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	LOCKERS 1	W	N, E, W, S	S
	ELECTRICAL 1	W	N, E, W, S	
	FIRE RISER	W	N, E	
	ELECTRICAL 2	W	N, E, W, S	
	LOCKERS 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE 1	F	*	S
	HALL 1	F	*	
	STORAGE 2	F	*	
	TO 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building D

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	TO 2	F	*	
	STORAGE 5	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	STORAGE 6	F	*	
	STORAGE 3	F	*	
	HALL 2	F	*	
	STORAGE 4	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE 1	F	*	S
	HALL 1	F	*	
	STORAGE 2	F	*	
	TO 1	F	*	
	TO 2	F	*	
	STORAGE 5	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	STORAGE 6	F	*	
	STORAGE 3	F	*	
	HALL 2	F	*	
	STORAGE 4	F	*	
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	STORAGE 1	O	N, E, W, S	S
	STORAGE 2	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	
	CUSTODIAL 2	O	N, E, W, S	
	TO 1	O	N, E, W, S	
	TO 2	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MEN'S RESTROOM	O	N, E, W, S	
	WOMEN'S RESTROOM	O	N, E, W, S	
	STORAGE 6	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	STORAGE 1	O	N, E, W, S	S
	STORAGE 2	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	
	CUSTODIAL 2	O	N, E, W, S	
	TO 1	O	N, E, W, S	
	TO 2	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	
	MEN'S RESTROOM	O	N, E, W, S	
	WOMEN'S RESTROOM	O	N, E, W, S	
	STORAGE 6	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
SINK ACOUSTICAL COATING, GRAY, ROUGH	CLASSROOM D-5	O	W	S
	DISCOVERY LAB D-6	O	E	
TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER 1	C	*	
	ELECTRICAL 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER 1	C	*	
	ELECTRICAL 2	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ELECTRICAL 1	C	*	S
	FIRE RISER 1	C	*	
	ELECTRICAL 2	C	*	
SEALANT (DOORS, WINDOWS), TAN, PLIABLE	ELECTRICAL 1	O	E	S
	ELECTRICAL 2	O	W	
	EXTERIOR	O	N, E, W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL 1	W	N, E	S
	FIRE RISER	W	W, S	
	GIRL'S RESTROOM 1	C	*	
	BOY'S RESTROOM 1	C	*	
	CUSTODIAL 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	C	*	
	BOY'S RESTROOM 2	C	*	
	CUSTODIAL 2	W	N, E, W, S	
	MEN'S RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL 1	W	N, E	S
	FIRE RISER	W	W, S	
	GIRL'S RESTROOM 1	C	*	
	BOY'S RESTROOM 1	C	*	
	CUSTODIAL 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	C	*	
	BOY'S RESTROOM 2	C	*	
	CUSTODIAL 2	W	N, E, W, S	
	MEN'S RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ELECTRICAL 1	W	N, E	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	FIRE RISER	W	W, S	
	GIRL'S RESTROOM 1	C	*	
	BOY'S RESTROOM 1	C	*	
	CUSTODIAL 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	C	*	
	BOY'S RESTROOM 2	C	*	
	CUSTODIAL 2	W	N, E, W, S	
	MEN'S RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (COURTYARDS), GRAY, CEMENTITIOUS, GRAVEL FINISH	EXTERIOR	F	*	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
PIPE END SEALANT, GRAY, PLIABLE	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

TABLE A
BUILDING MATERIAL SYSTEMS

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	MUSIC	C	*	S
	MUSIC OFFICE	C	*	
	MUSIC STORAGE E-3	C	*	
	MUSIC STORAGE E-4	C	*	
	STORAGE E-5	C	*	
	MULTI-PURPOSE	C	*	
	STAGE	C	*	
	NORTH WING	C	*	
	SOUTH WING	C	*	
	KITCHEN STORAGE	C	*	
	LOBBY	C	*	
	P.E. OFFICE 1	C	*	
	P.E. OFFICE 2	C	*	
	UTILITY	C	*	
	P.E. STORAGE	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MUSIC	W	N, E, W, S	S
	MUSIC OFFICE	W	N, E, W, S	
	MUSIC STORAGE E-3	W	E, W, S	
	MUSIC STORAGE E-4	W	N, E, W	
	STORAGE E-5	W	N, E, W, S	
	SNACK BAR	C, W	N, E, W, S	
	MULTI-PURPOSE	C, W	N, E, W, S	
	STAGE	W	N, E, W, S	
	NORTH WING	W	E, W, S	
	SOUTH WING	W	N, E, W, S	
	LOBBY	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CUSTODIAL 2	C, W	N, E, W, S	
	GYM	W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	BOY'S LOCKER 1	W	N, E, W, S	
	P.E. OFFICE 1	W	N, E, W, S	
	P.E. OFFICE 2	W	N, E, W, S	
	UTILITY	W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	GIRL'S LOCKER 1	W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 3	C, W	N, E, W	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MUSIC	W	N, E, W, S	S
	MUSIC OFFICE	W	N, E, W, S	
	MUSIC STORAGE E-3	W	E, W, S	
	MUSIC STORAGE E-4	W	N, E, W	
	STORAGE E-5	W	N, E, W, S	
	SNACK BAR	C, W	N, E, W, S	
	MULTI-PURPOSE	C, W	N, E, W, S	
	STAGE	W	N, E, W, S	
	NORTH WING	W	E, W, S	
	SOUTH WING	W	N, E, W, S	
	LOBBY	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	GYM	W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	BOY'S LOCKER 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	P.E. OFFICE 1	W	N, E, W, S	
	P.E. OFFICE 2	W	N, E, W, S	
	UTILITY	W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	GIRL'S LOCKER 1	W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 3	C, W	N, E, W	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MUSIC	W	N, E, W, S	S
	MUSIC OFFICE	W	N, E, W, S	
	MUSIC STORAGE E-3	W	E, W, S	
	MUSIC STORAGE E-4	W	N, E, W	
	STORAGE E-5	W	N, E, W, S	
	SNACK BAR	C, W	N, E, W, S	
	MULTI-PURPOSE	C, W	N, E, W, S	
	STAGE	W	N, E, W, S	
	NORTH WING	W	E, W, S	
	SOUTH WING	W	N, E, W, S	
	LOBBY	C	*	
	CUSTODIAL 2	C, W	N, E, W, S	
	GYM	W	N, E, W, S	
	HALL 1	C, W	N, E, W, S	
	BOY'S LOCKER 1	W	N, E, W, S	
	P.E. OFFICE 1	W	N, E, W, S	
	P.E. OFFICE 2	W	N, E, W, S	
	UTILITY	W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S LOCKER 1	W	N, E, W, S	
	HALL 2	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	HALL 3	C, W	N, E, W	
SINK ACOUSTICAL COATING, BLACK, ROUGH	MUSIC	O	N	S
	MUSIC STORAGE E-4	O	N	
	STAGE	O	N	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	MUSIC	W	N, E, W, S	S
	MUSIC OFFICE	W	N, E, W, S	
	MUSIC STORAGE E-3	W	E, W, S	
	MUSIC STORAGE E-4	W	N, E, W	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	MUSIC	W	N, E, W, S	S
	MUSIC OFFICE	W	N, E, W, S	
	MUSIC STORAGE E-3	W	E, W, S	
	MUSIC STORAGE E-4	W	N, E, W	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	MUSIC	F	*	S
	MUSIC OFFICE	F	*	
	MUSIC STORAGE E-3	F	*	
	MUSIC STORAGE E-4	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	MUSIC	F	*	S
	MUSIC OFFICE	F	*	
	MUSIC STORAGE E-3	F	*	
	MUSIC STORAGE E-4	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	MUSIC	O	N, E, W, S	S
	GIRL'S RESTROOM 2	O	E, S	
	BOY'S RESTROOM 2	O	W, S	
	MUSIC OFFICE	O	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MUSIC STORAGE E-3	O	E, S	
	MUSIC STORAGE E-4	O	E	
	SNACK BAR	O	W	
	MULTI-PURPOSE	O	E, S	
	STAGE	O	S	
	NORTH WING	O	W	
	SOUTH WING	O	N, W, S	
	KITCHEN	O	N, E, S	
	CUSTODIAL 1	O	W, S	
	KITCHEN STORAGE	O	W	
	KITCHEN OFFICE	O	S	
	KITCHEN LOCKERS	O	S	
	KITCHEN RESTROOM	O	S	
	GIRL'S RESTROOM 1	O	S	
	BOY'S RESTROOM 1	O	W, S	
	LOBBY	O	N, W, S	
	HALL 1	O	N, E, S	
	BOY'S LOCKER 1	O	N, E, S	
	P.E. OFFICE 1	O	N, E, W, S	
	MEN'S RESTROOM 1	O	S	
	WOMEN'S RESTROOM 1	O	N	
	P.E. OFFICE 2	O	N, E, W, S	
	UTILITY	O	E	
	P.E. STORAGE	O	W	
	GIRL'S LOCKER 1	O	N, E, S	
	ELECTRICAL 2	O	W	
	HALL 2	O	E, S	
	STORAGE 1	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	HALL 3	O	E, W	
SEALANT (WINDOWS), BLACK, GUMMY	BOY'S LOCKER 1	O	N, E	S
	GIRL'S LOCKER 1	O	E, S	
TACKABLE WALL PANEL (MOVEABLE), WHITE, CHALKY, VINYL COVER	MUSIC STORAGE E-3	W	N	S
	MUSIC STORAGE E-4	W	S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	MUSIC	O	N, E, S	S
	GIRL'S RESTROOM 2	O	S	
	BOY'S RESTROOM 2	O	S	
	MUSIC OFFICE	O	S	
	MUSIC STORAGE E-4	O	N	
	STORAGE E-5	O	N	
	SNACK BAR	O	W	
	MULTI-PURPOSE	O	N, E, S	
	NORTH WING	O	N, E, W	
	SOUTH WING	O	W, S	
	KITCHEN	O	N, E, S	
	CUSTODIAL 1	O	W, S	
	KITCHEN STORAGE	O	W	
	ELECTRICAL 1	O	N	
	MECHANICAL 1	O	N	
	LOBBY	O	N, W, S	
	CUSTODIAL 2	O	S	
	GYM	O	N, E, W, S	
	HALL 1	O	N, E, S	
	BOY'S LOCKER 1	O	S	
	UTILITY	O	E	
	P.E. STORAGE	O	W	
	GIRL'S LOCKER 1	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HALL 2	O	E, S	
	HALL 3	O	W	
	EXTERIOR	O	N, E, W, S	
DUCT SEAM TAPE, 2", WHITE, CANVAS	MUSIC	O	*	S
	MUSIC OFFICE	O	*	
	MUSIC STORAGE E-3	O	*	
	MUSIC STORAGE E-4	O	*	
	STORAGE E-5	O	*	
	SNACK BAR	O	*	
	MULTI-PURPOSE	O	*	
	STAGE	O	*	
	NORTH WING	O	*	
	SOUTH WING	O	*	
	KITCHEN	O	*	
	CUSTODIAL 1	O	*	
	KITCHEN STORAGE	O	*	
	FREEZER	O	*	
	FRIDGE	O	*	
	KITCHEN OFFICE	O	*	
	ELECTRICAL 1	O	*	
	KITCHEN LOCKERS	O	*	
	KITCHEN RESTROOM	O	*	
	MECHANICAL 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	LOBBY	O	*	
	CUSTODIAL 2	O	*	
	GYM	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HALL 1	O	*	
	BOY'S LOCKER 1	O	*	
	P.E. OFFICE 1	O	*	
	MEN'S RESTROOM 1	O	*	
	WOMEN'S RESTROOM 1	O	*	
	P.E. OFFICE 2	O	*	
	UTILITY	O	*	
	P.E. STORAGE	O	*	
	GIRL'S LOCKER 1	O	*	
	HALL 2	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	MUSIC	O	*	S
	MUSIC OFFICE	O	*	
	MUSIC STORAGE E-3	O	*	
	MUSIC STORAGE E-4	O	*	
	STORAGE E-5	O	*	
	SNACK BAR	O	*	
	MULTI-PURPOSE	O	*	
	STAGE	O	*	
	NORTH WING	O	*	
	SOUTH WING	O	*	
	KITCHEN	O	*	
	CUSTODIAL 1	O	*	
	KITCHEN STORAGE	O	*	
	FREEZER	O	*	
	FRIDGE	O	*	
	KITCHEN OFFICE	O	*	
	ELECTRICAL 1	O	*	
	KITCHEN LOCKERS	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	KITCHEN RESTROOM	O	*	
	MECHANICAL 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	LOBBY	O	*	
	CUSTODIAL 2	O	*	
	GYM	O	*	
	HALL 1	O	*	
	BOY'S LOCKER 1	O	*	
	P.E. OFFICE 1	O	*	
	MEN'S RESTROOM 1	O	*	
	WOMEN'S RESTROOM 1	O	*	
	P.E. OFFICE 2	O	*	
	UTILITY	O	*	
	P.E. STORAGE	O	*	
	GIRL'S LOCKER 1	O	*	
	HALL 2	O	*	
	STORAGE 1	O	*	
	HALL 3	O	*	
PIPE END SEALANT, WHITE, PLIABLE	MUSIC	O	*	S
	MUSIC OFFICE	O	*	
	MUSIC STORAGE E-3	O	*	
	MUSIC STORAGE E-4	O	*	
	STORAGE E-5	O	*	
	SNACK BAR	O	*	
	MULTI-PURPOSE	O	*	
	STAGE	O	*	
	NORTH WING	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	SOUTH WING	O	*	
	KITCHEN	O	*	
	CUSTODIAL 1	O	*	
	KITCHEN STORAGE	O	*	
	FREEZER	O	*	
	FRIDGE	O	*	
	KITCHEN OFFICE	O	*	
	ELECTRICAL 1	O	*	
	KITCHEN LOCKERS	O	*	
	KITCHEN RESTROOM	O	*	
	MECHANICAL 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	LOBBY	O	*	
	CUSTODIAL 2	O	*	
	GYM	O	*	
	HALL 1	O	*	
	BOY'S LOCKER 1	O	*	
	P.E. OFFICE 1	O	*	
	MEN'S RESTROOM 1	O	*	
	WOMEN'S RESTROOM 1	O	*	
	P.E. OFFICE 2	O	*	
	UTILITY	O	*	
	P.E. STORAGE	O	*	
	GIRL'S LOCKER 1	O	*	
	HALL 2	O	*	
	STORAGE 1	O	*	
	HALL 3	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	STORAGE E-5	O	N, E, W, S	S
	SNACK BAR	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CUSTODIAL 2	O	N, S	
	HALL 1	O	N, E, W, S	
	P.E. OFFICE 1	O	N, E, W, S	
	MEN'S RESTROOM 1	O	N, E, W, S	
	WOMEN'S RESTROOM 1	O	N, E, W, S	
	UTILITY	O	N, E, W, S	
	P.E. OFFICE 2	O	N, E, W, S	
	P.E. STORAGE	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
	HALL 2	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	HALL 3	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	STORAGE E-5	O	N, E, W, S	S
	SNACK BAR	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CUSTODIAL 2	O	N, S	
	HALL 1	O	N, E, W, S	
	P.E. OFFICE 1	O	N, E, W, S	
	MEN'S RESTROOM 1	O	N, E, W, S	
	WOMEN'S RESTROOM 1	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	UTILITY	O	N, E, W, S	
	P.E. OFFICE 2	O	N, E, W, S	
	P.E. STORAGE	O	N, E, W, S	
	ELECTRICAL 2	O	N, E, W, S	
	HALL 2	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	HALL 3	O	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	STORAGE E-5	F	*	S
	SNACK BAR	F	*	
	MULTI-PURPOSE	F	*	
	NORTH WING	F	*	
	CUSTODIAL 1	F	*	
	LOBBY	F	*	
	CUSTODIAL 2	F	*	
	HALL 1	F	*	
	P.E. OFFICE 1	F	*	
	MEN'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM 1	F	*	
	P.E. OFFICE 2	F	*	
	UTILITY	F	*	
	P.E. STORAGE	F	*	
	HALL 2	F	*	
	STORAGE 1	F	*	
	HALL 3	F	*	
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES AND VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	STORAGE E-5	F	*	S
	SNACK BAR	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MULTI-PURPOSE	F	*	
	NORTH WING	F	*	
	CUSTODIAL 1	F	*	
	LOBBY	F	*	
	CUSTODIAL 2	F	*	
	HALL 1	F	*	
	P.E. OFFICE 1	F	*	
	MEN'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM 1	F	*	
	P.E. OFFICE 2	F	*	
	UTILITY	F	*	
	P.E. STORAGE	F	*	
	HALL 2	F	*	
	STORAGE 1	F	*	
	HALL 3	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	MULTI-PURPOSE	F	*	S
	LOBBY	F	*	
WALLBASE (COVERED), 6", BLUE, VINYL-LIKE	MULTI-PURPOSE	W	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 6", BLUE, VINYL-LIKE	MULTI-PURPOSE	W	N, E, W, S	S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, RIBBED, WHITE	MULTI-PURPOSE	C	*	S
BRICK, 4"X16", TAN, CEMENTITIOUS	NORTH WING	W	N	S
	SOUTH WING	W	S	
	KITCHEN	W	S	
	GYM	W	N, E, W, S	
	BOY'S LOCKER 1	W	E	
	GIRL'S LOCKER 1	W	E	
	MAINTENANCE YARD	W	N, E, W, S	
	ELECTRICAL 3	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ELECTRICAL 2	W	N, E, W, S	
	SERVICE YARD 1	W	N, E, W, S	
	SERVICE YARD 2	W	N, E, W, S	
	COURTYARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	NORTH WING	W	N	S
	SOUTH WING	W	S	
	KITCHEN	W	S	
	GYM	W	N, E, W, S	
	BOY'S LOCKER 1	W	E	
	GIRL'S LOCKER 1	W	E	
	MAINTENANCE YARD	W	N, E, W, S	
	ELECTRICAL 3	W	N, E, W, S	
	ELECTRICAL 2	W	N, E, W, S	
	SERVICE YARD 1	W	N, E, W, S	
	SERVICE YARD 2	W	N, E, W, S	
	COURTYARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	NORTH WING	W	N	S
	SOUTH WING	W	S	
	KITCHEN	W	S	
	GYM	W	N, E, W, S	
	BOY'S LOCKER 1	W	E	
	GIRL'S LOCKER 1	W	E	
	MAINTENANCE YARD	W	N, E, W, S	
	ELECTRICAL 3	W	N, E, W, S	
	ELECTRICAL 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	SERVICE YARD 1	W	N, E, W, S	
	SERVICE YARD 2	W	N, E, W, S	
	COURTYARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	NORTH WING	W	N	S
	SOUTH WING	W	S	
	KITCHEN	W	S	
	GYM	W	N, E, W, S	
	BOY'S LOCKER 1	W	E	
	GIRL'S LOCKER 1	W	E	
	MAINTENANCE YARD	W	N, E, W, S	
	ELECTRICAL 3	W	N, E, W, S	
	ELECTRICAL 2	W	N, E, W, S	
	SERVICE YARD 1	W	N, E, W, S	
	SERVICE YARD 2	W	N, E, W, S	
	COURTYARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
SEALANT (DOORS), TAN, PLIABLE	MULTI-PURPOSE	O	N, S	S
	GYM	O	N, E, W, S	
	MAINTENANCE	O	W	
	ELECTRICAL 3	O	W	
	SERVICE YARD 1	O	E	
	EXTERIOR	O	N, E, W, S	
GLASS BLOCK, 8"X8", CLEAR	MULTI-PURPOSE	O	S	N
	LOBBY	O	N	
	EXTERIOR	O	N, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	MULTI-PURPOSE	O	S	S
	LOBBY	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	EXTERIOR	O	N, S	
VINYL STAIR TREAD, 12"X36", RED, TEXTURED, CIRCLE PATTERN	MULTI-PURPOSE	F	*	S
	NORTHWING	F	*	
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X36", RED, TEXTURED, CIRCLE PATTERN	MULTI-PURPOSE	F	*	S
	NORTHWING	F	*	
VINYL COMPOSITION TILE, 24"X24", RED, TEXTURED, CIRCLE PATTERN	SOUTH WING	F	*	S
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", RED, TEXTURED, CIRCLE PATTERN	SOUTH WING	F	*	S
WALLBASE (COVED), 6", BROWN, VINYL-LIKE	NORTH WING	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 6", BROWN, VINYL-LIKE	NORTH WING	O	N, E, W, S	S
WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	GYM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	GYM	O	N, E, W, S	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	KITCHEN	C, W	N, E, W, S	S
	CUSTODIAL 1	C, W	N, E, W, S	
	KITCHEN STORAGE	W	N, E, W, S	
	KITCHEN LOCKERS	C, W	N, E, W, S	
	KITCHEN RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C	*	
	BOY'S RESTROOM 1	C	*	
	BOY'S LOCKER 1	C	*	
	MEN'S RESTROOM 1	C, W	N, E, W, S	
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S LOCKER 1	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	KITCHEN	C, W	N, E, W, S	S
	CUSTODIAL 1	C, W	N, E, W, S	
	KITCHEN STORAGE	W	N, E, W, S	
	KITCHEN LOCKERS	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building E

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	KITCHEN RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C	*	
	BOY'S RESTROOM 1	C	*	
	BOY'S LOCKER 1	C	*	
	MEN'S RESTROOM 1	C, W	N, E, W, S	
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S LOCKER 1	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	KITCHEN	C, W	N, E, W, S	S
	CUSTODIAL 1	C, W	N, E, W, S	
	KITCHEN STORAGE	W	N, E, W, S	
	KITCHEN LOCKERS	C, W	N, E, W, S	
	KITCHEN RESTROOM	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C	*	
	BOY'S RESTROOM 1	C	*	
	BOY'S LOCKER 1	C	*	
	MEN'S RESTROOM 1	C, W	N, E, W, S	
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S LOCKER 1	C	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, CHALKY, VINYL-COVER	KITCHEN	C	*	S
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	STAGE	W	E, S	S
QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	KITCHEN	F, O	N, E, W, S	S
	KITCHEN STORAGE	F, O	N, E, W, S	
	KITCHEN OFFICE	F, O	N, E, W, S	
	KITCHEN LOCKERS	F, O	N, E, W, S	
	KITCHEN RESTROOM	F, O	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	KITCHEN	F, O	N, E, W, S	S
	KITCHEN STORAGE	F, O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	KITCHEN OFFICE	F, O	N, E, W, S	
	KITCHEN LOCKERS	F, O	N, E, W, S	
	KITCHEN RESTROOM	F, O	N, E, W, S	
TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C, W	N, E, W, S	S
	MECHANICAL 1	C, W	N, E, W, S	
GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	ELECTRICAL 1	C, W	N, E, W, S	S
	MECHANICAL 1	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	ELECTRICAL 1	C, W	N, E, W, S	S
	MECHANICAL 1	C, W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	MUSIC	F	*	S
	GIRL'S RESTROOM 2	F	*	
	BOY'S RESTROOM 2	F	*	
	MUSIC OFFICE	F	*	
	MUSIC STORAGE E-3	F	*	
	MUSIC STORAGE E-4	F	*	
	STORAGE E-5	F	*	
	SNACK BAR	F	*	
	MULTI-PURPOSE	F	*	
	STAGE	F	*	
	NORTH WING	F	*	
	SOUTH WING	F	*	
	KITCHEN	F	*	
	CUSTODIAL 1	F	*	
	KITCHEN STORAGE	F	*	
	FREEZER	F	*	
	FRIDGE	F	*	
	KITCHEN OFFICE	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ELECTRICAL 1	F	*	
	KITCHEN LOCKERS	F	*	
	KITCHEN RESTROOM	F	*	
	MECHANICAL 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
	LOBBY	F	*	
	CUSTODIAL 2	F	*	
	GYM	F	*	
	HALL 1	F	*	
	BOY'S LOCKER 1	F	*	
	P.E. OFFICE 1	F	*	
	MEN'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM 1	F	*	
	P.E. OFFICE 2	F	*	
	UTILITY	F	*	
	P.E. STORAGE	F	*	
	GIRL'S LOCKER 1	F	*	
	HALL 2	F	*	
	STORAGE 1	F	*	
	HALL 3	F	*	
	ENTRY	F	*	
	ENTRY CLOSET	F	*	
	LIVING ROOM	F	*	
	HALL CLOSET 1	F	*	
	HALL	F	*	
	MASTER BEDROOM	F	*	
	MASTER BEDROOM CLOSET	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MASTER BEDROOM RESTROOM	F	*	
	GUEST RESTROOM	F	*	
	HALL CLOSET 2	F	*	
	BEDROOM	F	*	
	LAUNDRY	F	*	
	PANTRY	F	*	
	APT KITCHEN	F	*	
	DINING	F	*	
	EXTERIOR	F	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	LOBBY	W	N, E, W, S	
	BOY'S LOCKER 1	W	N, E, W, S	
	GIRL'S LOCKER 1	W	N, E, W, S	
GLAZED WALL TILE, 4"X4", PINK, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	LOBBY	W	N, E, W, S	
	BOY'S LOCKER 1	W	N, E, W, S	
	GIRL'S LOCKER 1	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE, 4"X4", PINK, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	LOBBY	W	N, E, W, S	
	BOY'S LOCKER 1	W	N, E, W, S	
	GIRL'S LOCKER 1	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	BOY'S LOCKER 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	GIRL'S LOCKER 1	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	BOY'S LOCKER 1	F	*	
	GIRL'S LOCKER 1	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	BOY'S LOCKER 1	F	*	
	GIRL'S LOCKER 1	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	BOY'S LOCKER 1	F	*	
	GIRL'S LOCKER 1	F	*	
SEALANT (DUCT), WHITE, PLIABLE	MUSIC	O	*	S
	GIRL'S RESTROOM 2	O	*	
	BOY'S RESTROOM 2	O	*	
	MUSIC OFFICE	O	*	
	MUSIC STORAGE E-3	O	*	
	MUSIC STORAGE E-4	O	*	
	STORAGE E-5	O	*	
	SNACK BAR	O	*	
	MULTI-PURPOSE	O	*	
	STAGE	O	*	
	NORTH WING	O	*	
	SOUTH WING	O	*	
	KITCHEN	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CUSTODIAL 1	0	*	
	KITCHEN STORAGE	0	*	
	FREEZER	0	*	
	FRIDGE	0	*	
	KITCHEN OFFICE	0	*	
	ELECTRICAL 1	0	*	
	KITCHEN LOCKERS	0	*	
	KITCHEN RESTROOM	0	*	
	MECHANICAL 1	0	*	
	GIRL'S RESTROOM 1	0	*	
	BOY'S RESTROOM 1	0	*	
	LOBBY	0	*	
	CUSTODIAL 2	0	*	
	GYM	0	*	
	HALL 1	0	*	
	BOY'S LOCKER 1	0	*	
	P.E. OFFICE 1	0	*	
	MEN'S RESTROOM 1	0	*	
	WOMEN'S RESTROOM 1	0	*	
	P.E. OFFICE 2	0	*	
	UTILITY	0	*	
	P.E. STORAGE	0	*	
	GIRL'S LOCKER 1	0	*	
	HALL 2	0	*	
	STORAGE 1	0	*	
	HALL 3	0	*	
	ENTRY	0	*	
	ENTRY CLOSET	0	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	LIVING ROOM	O	*	
	HALL CLOSET 1	O	*	
	HALL	O	*	
	MASTER BEDROOM	O	*	
	MASTER BEDROOM CLOSET	O	*	
	MASTER BEDROOM RESTROOM	O	*	
	GUEST RESTROOM	O	*	
	HALL CLOSET 2	O	*	
	BEDROOM	O	*	
	LAUNDRY	O	*	
	PANTRY	O	*	
	APT KITCHEN	O	*	
	DINING	O	*	
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	N	S
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
SEALANT (WINDOWS), BLACK, PLIABLE	EXTERIOR	O	N, E, W	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM 2	C	*	S
	BOY'S RESTROOM 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM 2	C	*	S
	BOY'S RESTROOM 2	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM 2	C	*	S
	BOY'S RESTROOM 2	C	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	GIRL'S RESTROOM 2	W	N, E, W, S	S
	BOY'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	GIRL'S RESTROOM 2	W	N, E, W, S	S
	BOY'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	GIRL'S RESTROOM 2	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	BOY'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	GIRL'S RESTROOM 2	W	N, E, W, S	S
	BOY'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	GIRL'S RESTROOM 2	F	*	S
	BOY'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH, PEPPERED	GIRL'S RESTROOM 2	F	*	S
	BOY'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", GRAY, SMOOTH	GIRL'S RESTROOM 2	F	*	S
	BOY'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", GRAY, SMOOTH	GIRL'S RESTROOM 2	F	*	S
	BOY'S RESTROOM 2	F	*	
CONCRETE (EQUIPMENT PADS), GRAY, CEMENTITIOUS	MAINTENANCE YARD	F	*	S
	ELECTRICAL 3	F	*	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, TAN MINERAL CAP	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
PIPE SEALANT, GRAY, PLIABLE	ROOF	O	*	S
WOVEN DUCT BOOT, 4", BLACK, VINYL-LIKE	ROOF	O	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (DUCT), GRAY, BRITTLE	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	DRAMA	C	*	S
	HOME ECONOMICS	C	*	
	OFFICE 1	C	*	
	HOME ECONOMICS STORAGE	C	*	
	ART	C	*	
	ART OFFICE 1	C	*	
	ART STORAGE 1	C	*	
	ART STORAGE 2	C	*	
	OFFICE 2	C	*	
	CLASSROOM F-4	C	*	
	CLASSROOM F-5	C	*	
	CLASSROOM F-6	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	DRAMA	W	N, E, W, S	S
	DRAMA LAUNDRY	C, W	N, E, W, S	
	DRAMA STORAGE	C, W	N, E, W, S	
	HOME ECONOMICS	W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	HOME ECONOMICS STORAGE	W	N, E, W, S	
	ART	W	N, E, W, S	
	ART OFFICE 1	W	N, E, W, S	
	ART STORAGE 1	W	N, E, W, S	
	ART STORAGE 2	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	CLASSROOM F-4	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F-5	W	N, E, W, S	
	CLASSROOM F-6	W	N, E, W, S	
	WEIGHT ROOM	W	N, E, W, S	
	WOOD SHOP	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	DRAMA	W	N, E, W, S	S
	DRAMA LAUNDRY	C, W	N, E, W, S	
	DRAMA STORAGE	C, W	N, E, W, S	
	HOME ECONOMICS	W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	HOME ECONOMICS STORAGE	W	N, E, W, S	
	ART	W	N, E, W, S	
	ART OFFICE 1	W	N, E, W, S	
	ART STORAGE 1	W	N, E, W, S	
	ART STORAGE 2	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	CLASSROOM F-4	W	N, E, W, S	
	CLASSROOM F-5	W	N, E, W, S	
	CLASSROOM F-6	W	N, E, W, S	
	WEIGHT ROOM	W	N, E, W, S	
	WOOD SHOP	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	DRAMA	W	N, E, W, S	S
	DRAMA LAUNDRY	C, W	N, E, W, S	
	DRAMA STORAGE	C, W	N, E, W, S	
	HOME ECONOMICS	W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HOME ECONOMICS STORAGE	W	N, E, W, S	
	ART	W	N, E, W, S	
	ART OFFICE 1	W	N, E, W, S	
	ART STORAGE 1	W	N, E, W, S	
	ART STORAGE 2	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	CLASSROOM F-4	W	N, E, W, S	
	CLASSROOM F-5	W	N, E, W, S	
	CLASSROOM F-6	W	N, E, W, S	
	WEIGHT ROOM	W	N, E, W, S	
	WOOD SHOP	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	DRAMA	W	N, S	S
	HOME ECONOMICS	W	N, S	
	ART	W	N, S	
	CLASSROOM F-4	W	E, S	
	CLASSROOM F-5	W	N, E, S	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	DRAMA	O	N, E, W, S	S
	HOME ECONOMICS	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	ART	O	N, E, W, S	
	ART OFFICE 1	O	N, E, W, S	
	CLASSROOM F-4	O	N, W, S	
	CLASSROOM F-5	O	N, W, S	
	CLASSROOM F-6	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	DRAMA	O	N, E, W, S	S
	HOME ECONOMICS	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	OFFICE 1	O	N, E, W, S	
	ART	O	N, E, W, S	
	ART OFFICE 1	O	N, E, W, S	
	CLASSROOM F-4	O	N, W, S	
	CLASSROOM F-5	O	N, W, S	
	CLASSROOM F-6	O	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	DRAMA	F	*	S
	HOME ECONOMICS	F	*	
	OFFICE 1	F	*	
	ART	F	*	
	ART OFFICE 1	F	*	
	CLASSROOM F-4	F	*	
	CLASSROOM F-5	F	*	
	CLASSROOM F-6	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	DRAMA	F	*	S
	HOME ECONOMICS	F	*	
	OFFICE 1	F	*	
	ART	F	*	
	ART OFFICE 1	F	*	
	CLASSROOM F-4	F	*	
	CLASSROOM F-5	F	*	
	CLASSROOM F-6	F	*	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	DRAMA	O	W, S	S
	MAINTENANCE	O	E	
	HOME ECONOMICS	O	E, W	
	JANITOR	O	E	
	HOME ECONOMICS RESTROOM	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ART	O	N, E, W	
	STORAGE 1	O	N, E	
	CLASSROOM F-4	O	W, S	
	CLASSROOM F-5	O	W	
	CLASSROOM F-6	O	W	
	WEIGHT ROOM	O	E, S	
	WOOD SHOP	O	E	
	MAINTENANCE YARD	O	W	
	HOME ECONOMICS SERVICE YARD	O	W	
	ART SERVICE YARD	O	W	
	SERVICE YARD	O	W	
	EXTERIOR	O	W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	DRAMA	O	E, W, S	S
	DRAMA RESTROOM	O	W	
	DRAMA LAUNDRY	O	N	
	DRAMA STORAGE	O	N	
	MAINTENANCE	O	E	
	HOME ECONOMICS	O	N, E, W, S	
	OFFICE 1	O	W	
	JANITOR	O	N, E, W	
	HOME ECONOMICS RESTROOM	O	E	
	HOME ECONOMICS STORAGE	O	S	
	ART	O	N, E, W, S	
	ART OFFICE 1	O	N, W	
	ART STORAGE 1	O	W	
	ART STORAGE 2	O	W	
	STORAGE 2	O	N, S	
	OFFICE 2	O	N, E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM F-4	O	E, W, S	
	CLASSROOM F-5	O	N, E, W	
	CLASSROOM F-6	O	E, W, S	
	WEIGHT ROOM	O	N, W, S	
	WOOD SHOP	O	E, W, S	
SINK ACOUSTICAL COATING, BLACK, ROUGH	DRAMA	O	N	S
	HOME ECONOMICS	O	N, S	
	ART	O	S	
	CLASSROOM F-5	O	W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	DRAMA RESTROOM	C, W	N, E, W, S	S
	JANITOR	C, W	N, E, W, S	
	HOME ECONOMICS RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	DRAMA RESTROOM	C, W	N, E, W, S	S
	JANITOR	C, W	N, E, W, S	
	HOME ECONOMICS RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	DRAMA RESTROOM	C, W	N, E, W, S	S
	JANITOR	C, W	N, E, W, S	
	HOME ECONOMICS RESTROOM	C, W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	DRAMA RESTROOM	F	*	S
	DRAMA LAUNDRY	F	*	
	DRAMA STORAGE	F	*	
	MAINTENANCE	F	*	
	HOME ECONOMICS	F	*	
	JANITOR	F	*	
	HOME ECONOMICS RESTROOM	F	*	
	HOME ECONOMICS STORAGE	F	*	
	ART	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ART STORAGE 1	F	*	
	ART STORAGE 2	F	*	
	STORAGE 2	F	*	
	OFFICE 2	F	*	
	CLASSROOM F-6	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	DRAMA RESTROOM	F	*	S
	DRAMA LAUNDRY	F	*	
	DRAMA STORAGE	F	*	
	MAINTENANCE	F	*	
	HOME ECONOMICS	F	*	
	JANITOR	F	*	
	HOME ECONOMICS RESTROOM	F	*	
	HOME ECONOMICS STORAGE	F	*	
	ART	F	*	
	ART STORAGE 1	F	*	
	ART STORAGE 2	F	*	
	STORAGE 2	F	*	
	OFFICE 2	F	*	
	CLASSROOM F-6	F	*	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	DRAMA RESTROOM	O	N, E, W, S	S
	DRAMA LAUNDRY	O	N, E, W, S	
	DRAMA STORAGE	O	N, E, W, S	
	MAINTENANCE	O	N, E, W, S	
	HOME ECONOMICS	O	N, E, W, S	
	JANITOR	O	N, E, W, S	
	HOME ECONOMICS RESTROOM	O	N, E, W, S	
	HOME ECONOMICS STORAGE	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ART STORAGE 1	O	N, E, W, S	
	ART STORAGE 2	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	OFFICE 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	DRAMA RESTROOM	O	N, E, W, S	S
	DRAMA LAUNDRY	O	N, E, W, S	
	DRAMA STORAGE	O	N, E, W, S	
	MAINTENANCE	O	N, E, W, S	
	HOME ECONOMICS	O	N, E, W, S	
	JANITOR	O	N, E, W, S	
	HOME ECONOMICS RESTROOM	O	N, E, W, S	
	HOME ECONOMICS STORAGE	O	N, E, W, S	
	ART STORAGE 1	O	N, E, W, S	
	ART STORAGE 2	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	OFFICE 2	O	N, E, W, S	
SEALANT (WINDOWS), BLACK, GUMMY	DRAMA	O	E	
	HOME ECONOMICS	O	E	
	ART OFFICE 1	O	W	
	OFFICE 2	O	N, E, W	
	CLASSROOM F-6	O	E	
	EXTERIOR	O	W	
DUCT SEAM TAPE, 2", WHITE, CANVAS	DRAMA	O	*	S
	DRAMA RESTROOM	O	*	
	DRAMA LAUNDRY	O	*	
	DRAMA STORAGE	O	*	
	MAINTENANCE	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HOME ECONOMICS	O	*	
	OFFICE 1	O	*	
	JANITOR	O	*	
	HOME ECONOMICS RESTROOM	O	*	
	HOME ECONOMICS STORAGE	O	*	
	ART	O	*	
	ART OFFICE 1	O	*	
	ART STORAGE 1	O	*	
	ART STORAGE 2	O	*	
	STORAGE 1	O	*	
	STORAGE 2	O	*	
	OFFICE 2	O	*	
	CLASSROOM F-4	O	*	
	CLASSROOM F-5	O	*	
	CLASSROOM F-6	O	*	
	WEIGHT ROOM	O	*	
	WOOD SHOP	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	DRAMA	O	*	S
	DRAMA RESTROOM	O	*	
	DRAMA LAUNDRY	O	*	
	DRAMA STORAGE	O	*	
	MAINTENANCE	O	*	
	HOME ECONOMICS	O	*	
	OFFICE 1	O	*	
	JANITOR	O	*	
	HOME ECONOMICS RESTROOM	O	*	
	HOME ECONOMICS STORAGE	O	*	
	ART	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ART OFFICE 1	O	*	
	ART STORAGE 1	O	*	
	ART STORAGE 2	O	*	
	STORAGE 1	O	*	
	STORAGE 2	O	*	
	OFFICE 2	O	*	
	CLASSROOM F-4	O	*	
	CLASSROOM F-5	O	*	
	CLASSROOM F-6	O	*	
	WEIGHT ROOM	O	*	
	WOOD SHOP	O	*	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	DRAMA	F	*	S
	DRAMA RESTROOM	F	*	
	DRAMA LAUNDRY	F	*	
	DRAMA STORAGE	F	*	
	MAINTENANCE	F	*	
	HOME ECONOMICS	F	*	
	OFFICE 1	F	*	
	JANITOR	F	*	
	HOME ECONOMICS RESTROOM	F	*	
	HOME ECONOMICS STORAGE	F	*	
	ART	F	*	
	ART OFFICE 1	F	*	
	ART STORAGE 1	F	*	
	ART STORAGE 2	F	*	
	STORAGE 1	F	*	
	STORAGE 2	F	*	
	OFFICE 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F-4	F	*	
	CLASSROOM F-5	F	*	
	CLASSROOM F-6	F	*	
	WEIGHT ROOM	F	*	
	WOOD SHOP	F	*	
	EXTERIOR	F	*	
WOVEN DUCT BOOT, 4", BLACK, VINYL-LIKE	STORAGE 1	O	S	S
	ROOF	O	*	
TACKABLE WALL PANEL (MOVEABLE), BROWN, FIBROUS, VINYL-COVER	CLASSROOM F-6	W	W	S
	WEIGHT ROOM	W	N	
	WOOD SHOP	W	W, S	
BRICK, 4"X16", TAN, CEMENTITIOUS	MAINTENANCE YARD	W	N, E, W, S	S
	HOME ECONOMICS SERVICE YARD	W	N, E, W, S	
	ART SERVICE YARD	W	N, E, W, S	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	MAINTENANCE YARD	W	N, E, W, S	S
	HOME ECONOMICS SERVICE YARD	W	N, E, W, S	
	ART SERVICE YARD	W	N, E, W, S	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	MAINTENANCE YARD	W	N, E, W, S	S
	HOME ECONOMICS SERVICE YARD	W	N, E, W, S	
	ART SERVICE YARD	W	N, E, W, S	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	MAINTENANCE YARD	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	HOME ECONOMICS SERVICE YARD	W	N, E, W, S	
	ART SERVICE YARD	W	N, E, W, S	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	MAINTENANCE YARD	O	W	S
	HOME ECONOMICS SERVICE YARD	O	W	
	ART SERVICE YARD	O	W	
	SERVICE YARD	O	W	
	EXTERIOR	O	W, S	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
	MAINTENANCE YARD	F	*	
	HOME ECONOMICS SERVICE YARD	F	*	
	ART SERVICE YARD	F	*	
	SERVICEYARD	F	*	
QUARRY/PAVER TILE, 4"X8", GRAY, CEMENTITIOUS, SAND FILLED	EXTERIOR	F	*	S
CONCRETE (EQUIPMENT PADS), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
TROWELED-ON TEXTURE, WHITE, CHALKY	MAINTENANCE	C, W	N, E, W, S	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	MAINTENANCE	C, W	N, E, W, S	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MAINTENANCE	C, W	N, E, W, S	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (CANOPIES), GRAY, PLIABLE	ROOF	O	*	S
PIPE SEALANT, GRAY, PLIABLE	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	MEDIA OFFICE	C	*	S
	MEDIA WORKSHOP	C	*	
	MEDIA STORAGE	C	*	
	NETWORK	C	*	
	COMPUTER LAB 1	C	*	
	SPEECH	C	*	
	OFFICE 1	C	*	
	MUSIC	C	*	
	COMPUTER LAB 2	C	*	
	COMPUTER LAB 3	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEDIA CENTER	C, W	N, E, W, S	S
	MEDIA OFFICE	W	N, E, W, S	
	SERVER ROOM	C, W	N, E, W, S	
	RECORD	C, W	N, E, W, S	
	MEDIA WORKSHOP	W	N, E, W, S	
	MEDIA STORAGE	W	N, E, W, S	
	NETWORK	W	N, E, W, S	
	COMPUTER LAB 1 STORAGE	C, W	N, E, W, S	
	COMPUTER LAB 1	W	N, E, W, S	
	SPEECH	W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	MUSIC	W	N, E, W, S	
	MUSIC STORAGE	C, W	N, E, W, S	
	COMPUTER LAB 2	W	N, E, W, S	
	COMPUTER LAB 3	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEDIA CENTER	C, W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MEDIA OFFICE	W	N, E, W, S	
	SERVER ROOM	C, W	N, E, W, S	
	RECORD	C, W	N, E, W, S	
	MEDIA WORKSHOP	W	N, E, W, S	
	MEDIA STORAGE	W	N, E, W, S	
	NETWORK	W	N, E, W, S	
	COMPUTER LAB 1 STORAGE	C, W	N, E, W, S	
	COMPUTER LAB 1	W	N, E, W, S	
	SPEECH	W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	MUSIC	W	N, E, W, S	
	MUSIC STORAGE	C, W	N, E, W, S	
	COMPUTER LAB 2	W	N, E, W, S	
	COMPUTER LAB 3	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEDIA CENTER	C, W	N, E, W, S	S
	MEDIA OFFICE	W	N, E, W, S	
	SERVER ROOM	C, W	N, E, W, S	
	RECORD	C, W	N, E, W, S	
	MEDIA WORKSHOP	W	N, E, W, S	
	MEDIA STORAGE	W	N, E, W, S	
	NETWORK	W	N, E, W, S	
	COMPUTER LAB 1 STORAGE	C, W	N, E, W, S	
	COMPUTER LAB 1	W	N, E, W, S	
	SPEECH	W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	MUSIC	W	N, E, W, S	
	MUSIC STORAGE	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	COMPUTER LAB 2	W	N, E, W, S	
	COMPUTER LAB 3	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	MEDIA CENTER	W	N, E, W, S	S
	COMPUTER LAB 1	W	N, E	
	SPEECH	W	W	
	MUSIC	W	E, S	
	COMPUTER LAB 2	W	N, E	
	COMPUTER LAB 3	W	N, E, S	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	MEDIA CENTER	O	N, E, W, S	S
	MEDIA OFFICE	O	N, E, W, S	
	RECORD	O	N, E, W, S	
	MEDIA WORKSHOP	O	N, E, W, S	
	MEDIA STORAGE	O	N, E, W, S	
	COMPUTER LAB 1	O	N, E, W, S	
	SPEECH	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	MUSIC	O	N, E, W, S	
	COMPUTER LAB 2	O	N, E, W, S	
	COMPUTER LAB 3	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	MEDIA CENTER	O	N, E, W, S	S
	MEDIA OFFICE	O	N, E, W, S	
	RECORD	O	N, E, W, S	
	MEDIA WORKSHOP	O	N, E, W, S	
	MEDIA STORAGE	O	N, E, W, S	
	COMPUTER LAB 1	O	N, E, W, S	
	SPEECH	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	MUSIC	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	COMPUTER LAB 2	O	N, E, W, S	
	COMPUTER LAB 3	O	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	MEDIA CENTER	F	*	S
	MEDIA OFFICE	F	*	
	RECORD	F	*	
	MEDIA WORKSHOP	F	*	
	MEDIA STORAGE	F	*	
	COMPUTER LAB 1	F	*	
	SPEECH	F	*	
	OFFICE 1	F	*	
	MUSIC	F	*	
	COMPUTER LAB 2	F	*	
	COMPUTER LAB 3	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	MEDIA CENTER	F	*	S
	MEDIA OFFICE	F	*	
	RECORD	F	*	
	MEDIA WORKSHOP	F	*	
	MEDIA STORAGE	F	*	
	COMPUTER LAB 1	F	*	
	SPEECH	F	*	
	OFFICE 1	F	*	
	MUSIC	F	*	
	COMPUTER LAB 2	F	*	
	COMPUTER LAB 3	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	MEDIA CENTER	O	N, E, W, S	S
	MEDIA OFFICE	O	N, E, S	
	JANITOR	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
 Kyrene Centennial Middle School, KSD
 Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	RECORD	O	W, S	
	MEDIA WORKSHOP	O	N, S	
	MEDIA STORAGE	O	S	
	NETWORK	O	N	
	COMPUTER LAB 1 STORAGE	O	N, E	
	COMPUTER LAB 1	O	N, E, W, S	
	SPEECH	O	E, W	
	OFFICE 1	O	E, W	
	ELECTRICAL 1	O	N	
	MUSIC RESTROOM	O	E, S	
	MUSIC	O	E, W, S	
	MUSIC STORAGE	O	E	
	COMPUTER LAB 2	O	E, W	
	COMPUTER LAB 3	O	E, W, S	
	GIRL'S RESTROOM 1	O	E, S	
	BOY'S RESTROOM 1	O	W, S	
SEALANT (WINDOWS), BLACK, GUMMY	MEDIA WORKSHOP	O	S	S
	COMPUTER LAB 1	O	E, S	
	OFFICE 1	O	E, W	
	MUSIC	O	W	
	COMPUTER LAB 3	O	S	
	EXTERIOR	O	E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	MEDIA CENTER	O	E, W	S
	JANITOR	O	W	
	COMPUTER LAB 1 STORAGE	O	N	
	COMPUTER LAB 1	O	W, S	
	SPEECH	O	W	
	ELECTRICAL 1	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MUSIC	O	E	
	COMPUTER LAB 2	O	E	
	COMPUTER LAB 3	O	E	
	EXTERIOR	O	N, E, W	
SINK ACOUSTICAL COATING, BLACK, ROUGH	MEDIA WORKSHOP	O	N	S
	COMPUTER LAB 1	O	N	
	SPEECH	O	N	
	MUSIC	O	S	
	COMPUTER LAB 2	O	W	
	COMPUTER LAB 3	O	W	
DUCT SEAM TAPE, 2", WHITE, CANVAS	MEDIA CENTER	O	*	S
	MEDIA OFFICE	O	*	
	SERVER ROOM	O	*	
	JANITOR	O	*	
	RECORD	O	*	
	MEDIA WORKSHOP	O	*	
	MEDIA STORAGE	O	*	
	NETWORK	O	*	
	COMPUTER LAB 1 STORAGE	O	*	
	COMPUTER LAB 1	O	*	
	SPEECH	O	*	
	OFFICE 1	O	*	
	ELECTRICAL 1	O	*	
	MUSIC RESTROOM	O	*	
	MUSIC	O	*	
	MUSIC STORAGE	O	*	
	COMPUTER LAB 2	O	*	
	COMPUTER LAB 3	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	MEDIA CENTER	O	*	S
	MEDIA OFFICE	O	*	
	SERVER ROOM	O	*	
	JANITOR	O	*	
	RECORD	O	*	
	MEDIA WORKSHOP	O	*	
	MEDIA STORAGE	O	*	
	NETWORK	O	*	
	COMPUTER LAB 1 STORAGE	O	*	
	COMPUTER LAB 1	O	*	
	SPEECH	O	*	
	OFFICE 1	O	*	
	ELECTRICAL 1	O	*	
	MUSIC RESTROOM	O	*	
	MUSIC	O	*	
	MUSIC STORAGE	O	*	
	COMPUTER LAB 2	O	*	
	COMPUTER LAB 3	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	SERVER ROOM	F	*	S
	NETWORK	F	*	
	COMPUTER LAB 1 STORAGE	F	*	
	MUSIC RESTROOM	F	*	
	MUSIC STORAGE	F	*	
	GIRL'S RESTROOM 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 1	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	SERVER ROOM	F	*	S
	NETWORK	F	*	
	COMPUTER LAB 1 STORAGE	F	*	
	MUSIC RESTROOM	F	*	
	MUSIC STORAGE	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	SERVER ROOM	O	N, E, W, S	S
	JANITOR	O	N, E, W, S	
	NETWORK	O	N, E, W, S	
	COMPUTER LAB 1 STORAGE	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	MUSIC RESTROOM	O	N, E, W, S	
	MUSIC STORAGE	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	SERVER ROOM	O	N, E, W, S	S
	JANITOR	O	N, E, W, S	
	NETWORK	O	N, E, W, S	
	COMPUTER LAB 1 STORAGE	O	N, E, W, S	
	ELECTRICAL 1	O	N, E, W, S	
	MUSIC RESTROOM	O	N, E, W, S	
	MUSIC STORAGE	O	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MUSIC RESTROOM	C, W	N, E, W, S	S
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	BOY'S RESTROOM 1	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MUSIC RESTROOM	C, W	N, E, W, S	S
	GIRL'S RESTROOM 1	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MUSIC RESTROOM	C, W	N, E, W, S	S
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	BOY'S RESTROOM 1	C, W	N, E, W, S	
SEALANT (DUCT), WHITE, PLIABLE	MEDIA CENTER	O	*	S
	MEDIA OFFICE	O	*	
	SERVER ROOM	O	*	
	JANITOR	O	*	
	RECORD	O	*	
	MEDIA WORKSHOP	O	*	
	MEDIA STORAGE	O	*	
	NETWORK	O	*	
	COMPUTER LAB 1 STORAGE	O	*	
	COMPUTER LAB 1	O	*	
	SPEECH	O	*	
	OFFICE 1	O	*	
	ELECTRICAL 1	O	*	
	MUSIC RESTROOM	O	*	
	MUSIC	O	*	
	MUSIC STORAGE	O	*	
	COMPUTER LAB 2	O	*	
	COMPUTER LAB 3	O	*	
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
GLASS BLOCK, 8"X8", CLEAR	EXTERIOR	O	W	N
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	EXTERIOR	O	W	S
TROWELED-ON TEXTURE, WHITE, CHALKY	JANITOR	C, W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROVELED-ON TEXTURE, WHITE, CHALKY	JANITOR	C, W	N, E, W, S	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	JANITOR	C, W	N, E, W, S	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	MEDIA CENTER	F	*	S
	MEDIA OFFICE	F	*	
	SERVER ROOM	F	*	
	JANITOR	F	*	
	RECORD	F	*	
	MEDIA WORKSHOP	F	*	
	MEDIA STORAGE	F	*	
	NETWORK	F	*	
	COMPUTER LAB 1 STORAGE	F	*	
	COMPUTER LAB 1	F	*	
	SPEECH	F	*	
	OFFICE 1	F	*	
	ELECTRICAL 1	F	*	
	MUSIC RESTROOM	F	*	
	MUSIC	F	*	
	MUSIC STORAGE	F	*	
	COMPUTER LAB 2	F	*	
	COMPUTER LAB 3	F	*	
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
	EXTERIOR	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MUSIC RESTROOM	C, W	N, E, W, S	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MUSIC RESTROOM	C, W	N, E, W, S	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH	MUSIC RESTROOM	C, W	N, E, W, S	S
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
EXPANSION JOINT, GRAY, PLIABLE	EXTERIOR	F	*	S
BRICK, 4"X16", RED, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
BRICK, 4"X16", TAN, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND BRICK, 4"X16", TAN, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
EXPANSION JOINT, BROWN, PLIABLE	EXTERIOR	W	N, E, W, S	S
SEALANT (DOORS, WINDOWS), TAN, PLIABLE	EXTERIOR	O	N, E, W, S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	C	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, TAN MINERAL CAP	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (FLASHING), GRAY, PLIABLE	ROOF	O	*	S
PIPE SEALANT, GRAY, PLIABLE	ROOF	O	*	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	LOBBY	C	*	S
	H-1 STORAGE	C	*	
	CLASSROOM H-1	C	*	
	CLASSROOM H-2	C	*	
	CLASSROOM H-3	C	*	
	CLASSROOM H-4	C	*	
	CLASSROOM H-5	C	*	
	CLASSROOM H-6	C	*	
	CLASSROOM H-7A	C	*	
	CLASSROOM H-7B	C	*	
	CLASSROOM H-8	C	*	
	H-8 STORAGE	C	*	
	CLASSROOM H-9	C	*	
	CLASSROOM H-10A	C	*	
	CLASSROOM H-10B	C	*	
	STORAGE 3	C	*	
	CLASSROOM H-11	C	*	
	CLASSROOM H-12	C	*	
	CLASSROOM H-13	C	*	
	CLASSROOM H-14	C	*	
	CLASSROOM H-15	C	*	
	H-16 STORAGE	C	*	
	CLASSROOM H-16	C	*	
	CLASSROOM H-17	C	*	
	STORAGE 4	C	*	
	CLASSROOM H-18	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STORAGE 5	C	*	
	CLASSROOM H-19	C	*	
	CORRIDOR 1	C	*	
	CORRIDOR 2	C	*	
	CORRIDOR 3	C	*	
	CORRIDOR 4	C	*	
	CORRIDOR 5	C	*	
	CORRIDOR 6	C	*	
	CORRIDOR 7	C	*	
	CORRIDOR 8	C	*	
	CORRIDOR 9	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	H-1 STORAGE	W	N, E, W, S	
	CLASSROOM H-1	W	N, E, W, S	
	CLASSROOM H-2	C, W	N, E, W, S	
	CLASSROOM H-3	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	CLASSROOM H-4	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM H-5	C, W	N, E, W, S	
	CLASSROOM H-6	C, W	N, E, W, S	
	CLASSROOM H-7A	W	N, E, W, S	
	CLASSROOM H-7B	W	N, E, W, S	
	CLASSROOM H-8	C, W	N, E, W, S	
	H-8 TO	C, W	N, E, W, S	
	H-8 STORAGE	W	N, E, W, S	
	CLASSROOM H-9	C, W	N, E, W, S	
	H-9 TO	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	H-9 KITCHEN	W	N, E, W, S	
	CLASSROOM H-10A	W	N, E, W, S	
	CLASSROOM H-10B	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	CLASSROOM H-11	C, W	N, E, W, S	
	CLASSROOM H-12	C, W	N, E, W, S	
	CLASSROOM H-13	C, W	N, E, W, S	
	CLASSROOM H-14	C, W	N, E, W, S	
	CLASSROOM H-15	C, W	N, E, W, S	
	H-16 STORAGE	W	N, E, W, S	
	CLASSROOM H-16	W	N, E, W, S	
	CLASSROOM H-17	C, W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	CLASSROOM H-18	W	N, E, W, S	
	STORAGE 5	W	N, E, W, S	
	CLASSROOM H-19	C, W	N, E, W, S	
	CORRIDOR 1	C, W	N, E, W, S	
	CORRIDOR 2	C, W	E, W, S	
	CORRIDOR 3	W	N, E, W, S	
	CORRIDOR 4	W	N, E, W, S	
	CORRIDOR 5	C, W	N, E, W, S	
	CORRIDOR 6	W	N, E, W, S	
	CORRIDOR 7	W	N, E, W, S	
	CORRIDOR 8	C, W	N, E, W, S	
	CORRIDOR 9	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	H-1 STORAGE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H-1	W	N, E, W, S	
	CLASSROOM H-2	C, W	N, E, W	
	CLASSROOM H-3	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	CLASSROOM H-4	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM H-5	C, W	N, E, W, S	
	CLASSROOM H-6	C, W	N, E, W, S	
	CLASSROOM H-7A	W	N, E, W, S	
	CLASSROOM H-7B	W	N, E, W, S	
	CLASSROOM H-8	C, W	N, E, W, S	
	H-8 TO	C, W	N, E, W, S	
	H-8 STORAGE	W	N, E, W, S	
	CLASSROOM H-9	C, W	N, E, W, S	
	H-9 TO	C	*	
	H-9 KITCHEN	W	N, E, W, S	
	CLASSROOM H-10A	W	N, E, W, S	
	CLASSROOM H-10B	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	CLASSROOM H-11	C, W	N, E, W, S	
	CLASSROOM H-12	C, W	N, E, W, S	
	CLASSROOM H-13	C, W	N, E, W, S	
	CLASSROOM H-14	C, W	N, E, W, S	
	CLASSROOM H-15	C, W	N, E, W, S	
	H-16 STORAGE	W	N, E, W, S	
	CLASSROOM H-16	W	N, E, W, S	
	CLASSROOM H-17	C, W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H-18	W	N, E, W, S	
	STORAGE 5	W	N, E, W, S	
	CLASSROOM H-19	C, W	N, E, W, S	
	CORRIDOR 1	C, W	N, E, W, S	
	CORRIDOR 2	C, W	E, W, S	
	CORRIDOR 3	W	N, E, W, S	
	CORRIDOR 4	W	N, E, W, S	
	CORRIDOR 5	C, W	N, E, W, S	
	CORRIDOR 6	W	N, E, W, S	
	CORRIDOR 7	W	N, E, W, S	
	CORRIDOR 8	C, W	N, E, W, S	
	CORRIDOR 9	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	C, W	N, E, W, S	S
	H-1 STORAGE	W	N, E, W, S	
	CLASSROOM H-1	W	N, E, W, S	
	CLASSROOM H-2	C, W	N, E, W	
	CLASSROOM H-3	C, W	N, E, W, S	
	STORAGE 1	C, W	N, E, W, S	
	CLASSROOM H-4	C, W	N, E, W, S	
	STORAGE 2	C, W	N, E, W, S	
	CLASSROOM H-5	C, W	N, E, W, S	
	CLASSROOM H-6	C, W	N, E, W, S	
	CLASSROOM H-7A	W	N, E, W, S	
	CLASSROOM H-7B	W	N, E, W, S	
	CLASSROOM H-8	C, W	N, E, W, S	
	H-8 TO	C, W	N, E, W, S	
	H-8 STORAGE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H-9	C, W	N, E, W, S	
	H-9 TO	C	*	
	H-9 KITCHEN	W	N, E, W, S	
	CLASSROOM H-10A	W	N, E, W, S	
	CLASSROOM H-10B	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	CLASSROOM H-11	C, W	N, E, W, S	
	CLASSROOM H-12	C, W	N, E, W, S	
	CLASSROOM H-13	C, W	N, E, W, S	
	CLASSROOM H-14	C, W	N, E, W, S	
	CLASSROOM H-15	C, W	N, E, W, S	
	H-16 STORAGE	W	N, E, W, S	
	CLASSROOM H-16	W	N, E, W, S	
	CLASSROOM H-17	C, W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	CLASSROOM H-18	W	N, E, W, S	
	STORAGE 5	W	N, E, W, S	
	CLASSROOM H-19	C, W	N, E, W, S	
	CORRIDOR 1	C, W	N, E, W, S	
	CORRIDOR 2	C, W	E, W, S	
	CORRIDOR 3	W	N, E, W, S	
	CORRIDOR 4	W	N, E, W, S	
	CORRIDOR 5	C, W	N, E, W, S	
	CORRIDOR 6	W	N, E, W, S	
	CORRIDOR 7	W	N, E, W, S	
	CORRIDOR 8	C, W	N, E, W, S	
	CORRIDOR 9	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	LOBBY	W	S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H-1	W	E	
	CLASSROOM H-10A	W	W	
	CLASSROOM H-10B	W	W	
	CLASSROOM H-13	W	S	
	CLASSROOM H-14	W	E	
	CORRIDOR 5	W	N, S	
	CORRIDOR 8	W	N, W	
TACKABLE WALL PANEL (MOVEABLE), WHITE, CHALKY	CLASSROOM H-2	W	E, S	S
	CLASSROOM H-3	W	W, S	
	CLASSROOM H-4	W	N, W, S	
	CLASSROOM H-7A	W	S	
	CLASSROOM H-7B	W	N	
	CLASSROOM H-8	W	W	
	CLASSROOM H-9	W	E	
	CLASSROOM H-10A	W	S	
	CLASSROOM H-10B	W	N	
	CLASSROOM H-17	W	N, W, S	
	CLASSROOM H-19	W	N, E, S	
	CORRIDOR 1	W	S	
	CORRIDOR 2	W	W	
	CORRIDOR 3	W	N	
	CORRIDOR 7	W	N	
	CORRIDOR 8	W	E	
	CORRIDOR 9	W	S	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	LOBBY	O	N, E, W, S	S
	H-1 STORAGE	O	N, E, W, S	
	CLASSROOM H-1	O	N, E, W, S	
	CLASSROOM H-2	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
 Kyrene Centennial Middle School, KSD
 Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H-3	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	CLASSROOM H-4	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	CLASSROOM H-5	O	N, E, W, S	
	CLASSROOM H-6	O	N, E, W, S	
	CLASSROOM H-7A	O	N, E, W, S	
	CLASSROOM H-7B	O	N, E, W, S	
	CLASSROOM H-8	O	N, E, W, S	
	H-8 STORAGE	O	N, E, W, S	
	CLASSROOM H-9	O	N, E, W, S	
	H-9 KITCHEN	O	N, E, W, S	
	H-9 RESTROOM	O	N, E, W, S	
	CUSTODIAL 1	O	N, E, W, S	
	CLASSROOM H-10A	O	N, E, W, S	
	CLASSROOM H-10B	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	CLASSROOM H-11	O	N, E, W, S	
	CLASSROOM H-12	O	N, E, W, S	
	CLASSROOM H-13	O	N, E, W, S	
	CLASSROOM H-14	O	N, E, W, S	
	CLASSROOM H-15	O	N, E, W, S	
	H-16 STORAGE	O	N, E, W, S	
	CLASSROOM H-16	O	N, E, W, S	
	CLASSROOM H-17	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	CLASSROOM H-18	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H-19	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CORRIDOR 2	O	E, W, S	
	CORRIDOR 3	O	N, E, W, S	
	CORRIDOR 4	O	E, W, S	
	CORRIDOR 5	O	N, E, W, S	
	CORRIDOR 6	O	N, E, W, S	
	CORRIDOR 7	O	N, E, W, S	
	CORRIDOR 8	O	N, E, W, S	
	CORRIDOR 9	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	LOBBY	O	N, E, W, S	S
	H-1 STORAGE	O	N, E, W, S	
	CLASSROOM H-1	O	N, E, W, S	
	CLASSROOM H-2	O	N, E, W, S	
	CLASSROOM H-3	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	CLASSROOM H-4	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	CLASSROOM H-5	O	N, E, W, S	
	CLASSROOM H-6	O	N, E, W, S	
	CLASSROOM H-7A	O	N, E, W, S	
	CLASSROOM H-7B	O	N, E, W, S	
	CLASSROOM H-8	O	N, E, W, S	
	H-8 STORAGE	O	N, E, W, S	
	CLASSROOM H-9	O	N, E, W, S	
	H-9 KITCHEN	O	N, E, W, S	
	H-9 RESTROOM	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CUSTODIAL 1	O	N, E, W, S	
	CLASSROOM H-10A	O	N, E, W, S	
	CLASSROOM H-10B	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	CLASSROOM H-11	O	N, E, W, S	
	CLASSROOM H-12	O	N, E, W, S	
	CLASSROOM H-13	O	N, E, W, S	
	CLASSROOM H-14	O	N, E, W, S	
	CLASSROOM H-15	O	N, E, W, S	
	H-16 STORAGE	O	N, E, W, S	
	CLASSROOM H-16	O	N, E, W, S	
	CLASSROOM H-17	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	CLASSROOM H-18	O	N, E, W, S	
	STORAGE 5	O	N, E, W, S	
	CLASSROOM H-19	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W	
	CORRIDOR 3	O	N, E, W, S	
	CORRIDOR 4	O	E, W, S	
	CORRIDOR 5	O	N, E, W, S	
	CORRIDOR 6	O	N, E, W, S	
	CORRIDOR 7	O	N, E, W, S	
	CORRIDOR 8	O	N, E, W, S	
	CORRIDOR 9	O	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	LOBBY	F	*	S
	CLASSROOM H-2	F	*	
	CLASSROOM H-3	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM H-4	F	*	
	CLASSROOM H-5	F	*	
	CLASSROOM H-6	F	*	
	CLASSROOM H-7A	F	*	
	CLASSROOM H-7B	F	*	
	CLASSROOM H-8	F	*	
	CLASSROOM H-9	F	*	
	CLASSROOM H-10A	F	*	
	CLASSROOM H-10B	F	*	
	CLASSROOM H-11	F	*	
	CLASSROOM H-12	F	*	
	CLASSROOM H-13	F	*	
	CLASSROOM H-14	F	*	
	CLASSROOM H-15	F	*	
	CLASSROOM H-17	F	*	
	CLASSROOM H-18	F	*	
	CORRIDOR 1	F	*	
	CORRIDOR 2	F	*	
	CORRIDOR 3	F	*	
	CORRIDOR 4	F	*	
	CORRIDOR 5	F	*	
	CORRIDOR 6	F	*	
	CORRIDOR 7	F	*	
	CORRIDOR 8	F	*	
	CORRIDOR 9	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED, WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	LOBBY	F	*	S
	CLASSROOM H-2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building H

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H-3	F	*	
	CLASSROOM H-4	F	*	
	CLASSROOM H-5	F	*	
	CLASSROOM H-6	F	*	
	CLASSROOM H-7A	F	*	
	CLASSROOM H-7B	F	*	
	CLASSROOM H-8	F	*	
	CLASSROOM H-9	F	*	
	CLASSROOM H-10A	F	*	
	CLASSROOM H-10B	F	*	
	CLASSROOM H-11	F	*	
	CLASSROOM H-12	F	*	
	CLASSROOM H-13	F	*	
	CLASSROOM H-14	F	*	
	CLASSROOM H-15	F	*	
	CLASSROOM H-17	F	*	
	CLASSROOM H-18	F	*	
	CORRIDOR 1	F	*	
	CORRIDOR 2	F	*	
	CORRIDOR 3	F	*	
	CORRIDOR 4	F	*	
	CORRIDOR 5	F	*	
	CORRIDOR 6	F	*	
	CORRIDOR 7	F	*	
	CORRIDOR 8	F	*	
	CORRIDOR 9	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	LOBBY	O	N, E, W, S	S
	GIRL'S RESTROOM 1	O	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building H

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 1	O	E, W, S	
	H-1 STORAGE	O	S	
	CLASSROOM H-1	O	N, E, W, S	
	H-1 RESTROOM	O	E, W	
	CLASSROOM H-2	O	N, W	
	CLASSROOM H-3	O	N, E	
	STORAGE 1	O	N	
	WOMEN'S RESTROOM	O	N, E, W	
	CLASSROOM H-4	O	E	
	MEN'S RESTROOM	O	E, W, S	
	STORAGE 2	O	E	
	CLASSROOM H-5	O	E, S	
	CLASSROOM H-6	O	S	
	CLASSROOM H-7A	O	N, W	
	CLASSROOM H-7B	O	W, S	
	CLASSROOM H-8	O	N, E, S	
	H-8 TO	O	N	
	H-8 STORAGE	O	N, S	
	CLASSROOM H-9	O	N, E, W, S	
	H-9 TO	O	W	
	H-9 KITCHEN	O	N, W, S	
	H-9 RESTROOM	O	E	
	CUSTODIAL 1	O	W	
	CLASSROOM H-10A	O	N, E	
	CLASSROOM H-10B	O	E, S	
	STORAGE 3	O	E	
	CLASSROOM H-11	O	N, W, S	
	CLASSROOM H-12	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building H

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM H-13	O	N, E, W, S	
	CLASSROOM H-14	O	N, E, W, S	
	CLASSROOM H-15	O	N, E, W, S	
	H-16 STORAGE	O	S	
	CLASSROOM H-16	O	N, E, W, S	
	H-16 RESTROOM	O	E, W	
	BOY'S RESTROOM 2	O	E, W, S	
	GIRL'S RESTROOM 2	O	E, W, S	
	CLASSROOM H-17	O	N, E	
	STORAGE 4	O	S	
	CLASSROOM H-18	O	N, S	
	STORAGE 5	O	N, E, S	
	CLASSROOM H-19	O	N, W	
	CORRIDOR 1	O	N, W	
	CORRIDOR 3	O	N, W, S	
	CORRIDOR 4	O	E, W, S	
	CORRIDOR 5	O	N, E, W	
	CORRIDOR 6	O	N, E, W, S	
	CORRIDOR 7	O	N, E, W, S	
	CORRIDOR 8	O	N, W, S	
	CORRIDOR 9	O	N, E	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOBBY	O	N, E, W, S	S
	GIRL'S RESTROOM 1	O	S	
	BOY'S RESTROOM 1	O	S	
	H-1 STORAGE	O	S	
	CLASSROOM H-1	O	N, E, S	
	CLASSROOM H-2	O	W	
	CLASSROOM H-3	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 1	O	N	
	WOMEN'S RESTROOM	O	E	
	MEN'S RESTROOM	O	E	
	STORAGE 2	O	E	
	CLASSROOM H-5	O	E	
	CLASSROOM H-7A	O	N	
	CLASSROOM H-7B	O	W	
	CLASSROOM H-8	O	N, E, S	
	H-8 TO	O	N	
	CLASSROOM H-9	O	N	
	H-9 KITCHEN	O	W	
	H-9 RESTROOM	O	E	
	CLASSROOM H-10A	O	N	
	CLASSROOM H-10B	O	E	
	STORAGE 3	O	E, S	
	CLASSROOM H-12	O	W	
	CLASSROOM H-14	O	W	
	H-16 STORAGE	O	S	
	CLASSROOM H-16	O	N, S	
	BOY'S RESTROOM 2	O	S	
	GIRL'S RESTROOM 2	O	S	
	CLASSROOM H-17	O	E	
	STORAGE 4	O	W, S	
	CLASSROOM H-18	O	N, S	
	STORAGE 5	O	E, S	
	CLASSROOM H-19	O	W	
	CORRIDOR 1	O	N, W	
	CORRIDOR 3	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CORRIDOR 4	O	E, W, S	
	CORRIDOR 5	O	N, E, W	
	CORRIDOR 6	O	N, W, S	
	CORRIDOR 7	O	N, E, S	
	CORRIDOR 9	O	N, E	
	SERVICE YARD	O	N	
	EXTERIOR	O	N, E, W, S	
SINK ACOUSTICAL COATING, BLACK, ROUGH	CLASSROOM H-1	O	W	S
	CLASSROOM H-2	O	N	
	CLASSROOM H-3	O	N	
	CLASSROOM H-4	O	E	
	CLASSROOM H-5	O	S	
	CLASSROOM H-6	O	S	
	CLASSROOM H-7B	O	S	
	CLASSROOM H-8	O	E	
	H-8 STORAGE	O	S	
	CLASSROOM H-9	O	N, W	
	H-9 KITCHEN	O	S	
	CLASSROOM H-10B	O	S	
	CLASSROOM H-11	O	S	
	CLASSROOM H-12	O	S	
	CLASSROOM H-13	O	W	
	CLASSROOM H-14	O	N	
	CLASSROOM H-15	O	N	
	CLASSROOM H-16	O	E	
	CLASSROOM H-18	O	S	
	STORAGE 5	O	N	
SEALANT (WINDOWS), BLACK, GUMMY	CLASSROOM H-2	O	W	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H-15	O	E	
	CORRIDOR 1	O	N	
	CORRIDOR 3	O	S	
	CORRIDOR 4	O	E, W	
	CORRIDOR 6	O	E	
	CORRIDOR 7	O	W, S	
	CORRIDOR 9	O	N	
TROWELED-ON TEXTURE, WHITE, CHALKY	CORRIDOR 2	W	N, E, W, S	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	CORRIDOR 2	W	N, E, W, S	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR 2	W	N, E, W, S	S
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	H-1 STORAGE	F	*	S
	CLASSROOM H-1	F	*	
	CLASSROOM H-8	F	*	
	H-8 TO	F	*	
	H-8 STORAGE	F	*	
	CLASSROOM H-9	F	*	
	H-9 TO	F	*	
	H-9 KITCHEN	F	*	
	H-9 RESTROOM	F	*	
	CUSTODIAL 1	F	*	
	STORAGE 3	F	*	
	H-16 STORAGE	F	*	
	CLASSROOM H-16	F	*	
	STORAGE 4	F	*	
	STORAGE 5	F	*	
	CLASSROOM H-19	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	H-1 STORAGE	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building H

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H-1	F	*	
	CLASSROOM H-8	F	*	
	H-8 TO	F	*	
	H-8 STORAGE	F	*	
	CLASSROOM H-9	F	*	
	H-9 TO	F	*	
	H-9 KITCHEN	F	*	
	H-9 RESTROOM	F	*	
	CUSTODIAL 1	F	*	
	STORAGE 3	F	*	
	H-16 STORAGE	F	*	
	CLASSROOM H-16	F	*	
	STORAGE 4	F	*	
	STORAGE 5	F	*	
	CLASSROOM H-19	F	*	
DUCT SEAM TAPE, 2", WHITE, CANVAS	LOBBY	O	*	S
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	H-1 STORAGE	O	*	
	CLASSROOM H-1	O	*	
	H-1 RESTROOM	O	*	
	CLASSROOM H-2	O	*	
	CLASSROOM H-3	O	*	
	STORAGE 1	O	*	
	WOMEN'S RESTROOM	O	*	
	CLASSROOM H-4	O	*	
	MEN'S RESTROOM	O	*	
	STORAGE 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H-5	O	*	
	CLASSROOM H-6	O	*	
	CLASSROOM H-7A	O	*	
	CLASSROOM H-7B	O	*	
	CLASSROOM H-8	O	*	
	H-8 TO	O	*	
	H-8 STORAGE	O	*	
	CLASSROOM H-9	O	*	
	H-9 TO	O	*	
	H-9 KITCHEN	O	*	
	H-9 RESTROOM	O	*	
	CUSTODIAL 1	O	*	
	CLASSROOM H-10A	O	*	
	CLASSROOM H-10B	O	*	
	STORAGE 3	O	*	
	CLASSROOM H-11	O	*	
	CLASSROOM H-12	O	*	
	CLASSROOM H-13	O	*	
	CLASSROOM H-14	O	*	
	CLASSROOM H-15	O	*	
	H-16 STORAGE	O	*	
	CLASSROOM H-16	O	*	
	H-16 RESTROOM	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CLASSROOM H-17	O	*	
	STORAGE 4	O	*	
	CLASSROOM H-18	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building H

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	STORAGE 5	O	*	
	CLASSROOM H-19	O	*	
	CORRIDOR 1	O	*	
	CORRIDOR 2	O	*	
	CORRIDOR 3	O	*	
	CORRIDOR 4	O	*	
	CORRIDOR 5	O	*	
	CORRIDOR 6	O	*	
	CORRIDOR 7	O	*	
	CORRIDOR 8	O	*	
	CORRIDOR 9	O	*	
PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	LOBBY	O	*	S
	GIRL'S RESTROOM 1	O	*	
	BOY'S RESTROOM 1	O	*	
	H-1 STORAGE	O	*	
	CLASSROOM H-1	O	*	
	H-1 RESTROOM	O	*	
	CLASSROOM H-2	O	*	
	CLASSROOM H-3	O	*	
	STORAGE 1	O	*	
	WOMEN'S RESTROOM	O	*	
	CLASSROOM H-4	O	*	
	MEN'S RESTROOM	O	*	
	STORAGE 2	O	*	
	CLASSROOM H-5	O	*	
	CLASSROOM H-6	O	*	
	CLASSROOM H-7A	O	*	
	CLASSROOM H-7B	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Centennial Middle School, KSD
Building H

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM H-8	O	*	
	H-8 TO	O	*	
	H-8 STORAGE	O	*	
	CLASSROOM H-9	O	*	
	H-9 TO	O	*	
	H-9 KITCHEN	O	*	
	H-9 RESTROOM	O	*	
	CUSTODIAL 1	O	*	
	CLASSROOM H-10A	O	*	
	CLASSROOM H-10B	O	*	
	STORAGE 3	O	*	
	CLASSROOM H-11	O	*	
	CLASSROOM H-12	O	*	
	CLASSROOM H-13	O	*	
	CLASSROOM H-14	O	*	
	CLASSROOM H-15	O	*	
	H-16 STORAGE	O	*	
	CLASSROOM H-16	O	*	
	H-16 RESTROOM	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CLASSROOM H-17	O	*	
	STORAGE 4	O	*	
	CLASSROOM H-18	O	*	
	STORAGE 5	O	*	
	CLASSROOM H-19	O	*	
	CORRIDOR 1	O	*	
	CORRIDOR 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CORRIDOR 3	O	*	
	CORRIDOR 4	O	*	
	CORRIDOR 5	O	*	
	CORRIDOR 6	O	*	
	CORRIDOR 7	O	*	
	CORRIDOR 8	O	*	
	CORRIDOR 9	O	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM 1	C	*	S
	BOY'S RESTROOM 1	C	*	
	H-1 RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
	MEN'S RESTROOM	C	*	
	H-9 RESTROOM	C, W	N, E, W, S	
	H-16 RESTROOM	C	*	
	BOY'S RESTROOM 2	C	*	
	GIRL'S RESTROOM 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM 1	C	*	S
	BOY'S RESTROOM 1	C	*	
	H-1 RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
	MEN'S RESTROOM	C	*	
	H-9 RESTROOM	C, W	N, E, W, S	
	H-16 RESTROOM	C	*	
	BOY'S RESTROOM 2	C	*	
	GIRL'S RESTROOM 2	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM 1	C	*	S
	BOY'S RESTROOM 1	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	H-1 RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
	MEN'S RESTROOM	C	*	
	H-9 RESTROOM	C, W	N, E, W, S	
	H-16 RESTROOM	C	*	
	BOY'S RESTROOM 2	C	*	
	GIRL'S RESTROOM 2	C	*	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	H-1 RESTROOM	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	MEN'S RESTROOM	W	N, E, W, S	
	H-16 RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	MEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	MEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	GIRL'S RESTROOM 1	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	H-1 RESTROOM	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	MEN'S RESTROOM	W	N, E, W, S	
	H-16 RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	H-1 RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	H-16 RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	GIRL'S RESTROOM 1	F	*	S
	BOY'S RESTROOM 1	F	*	
	H-1 RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	MEN'S RESTROOM	F	*	
	H-16 RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
BRICK, 4"X16", TAN, CEMENTITIOUS	LOBBY	W	N, E, W	S
	CORRIDOR 1	W	N	
	CORRIDOR 9	W	N	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	LOBBY	W	N, E, W	S
	CORRIDOR 1	W	N	
	CORRIDOR 9	W	N	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	LOBBY	W	N, E, W	S
	CORRIDOR 1	W	N	
	CORRIDOR 9	W	N	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
EXPANSION JOINT, BROWN, PLIABLE	LOBBY	W	N, E, W	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR 1	W	N	
	CORRIDOR 9	W	N	
	SERVICE YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	LOBBY	O	N	S
	CORRIDOR 1	O	N	
	CORRIDOR 9	O	N	
	SERVICE YARD	O	N	
	EXTERIOR	O	N, E, W, S	
CEMENTITIOUS BUILDING BOARD, GRAY, BRITTLE	CLASSROOM H-17	O	N, E, W	S
	CLASSROOM H-19	O	N, E, W	
GLASS BLOCK, 8"X8", CLEAR	LOBBY	O	N	N
	EXTERIOR	O	N	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	LOBBY	O	N	S
	EXTERIOR	O	N	
QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH	LOBBY	F	*	S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH	LOBBY	F	*	S
SPRAY-APPLIED FIREPROOFING, GRAY, FIBROUS	LOBBY	C	*	S
VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, CIRCLE PATTERN	CORRIDOR 4	F	*	S
	CORRIDOR 6	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, CIRCLE PATTERN	CORRIDOR 4	F	*	S
	CORRIDOR 6	F	*	
GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM H-9	W	E, W, S	S
	H-9 TO	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM H-9	W	E, W, S	S
	H-9 TO	W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LOBBY	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	GIRL'S RESTROOM 1	F	*	
	BOY'S RESTROOM 1	F	*	
	H-1 STORAGE	F	*	
	CLASSROOM H-1	F	*	
	H-1 RESTROOM	F	*	
	CLASSROOM H-2	F	*	
	CLASSROOM H-3	F	*	
	STORAGE 1	F	*	
	WOMEN'S RESTROOM	F	*	
	CLASSROOM H-4	F	*	
	MEN'S RESTROOM	F	*	
	STORAGE 2	F	*	
	CLASSROOM H-5	F	*	
	CLASSROOM H-6	F	*	
	CLASSROOM H-7A	F	*	
	CLASSROOM H-7B	F	*	
	CLASSROOM H-8	F	*	
	H-8 TO	F	*	
	H-8 STORAGE	F	*	
	CLASSROOM H-9	F	*	
	H-9 TO	F	*	
	H-9 KITCHEN	F	*	
	H-9 RESTROOM	F	*	
	CUSTODIAL 1	F	*	
	CLASSROOM H-10A	F	*	
	CLASSROOM H-10B	F	*	
	STORAGE 3	F	*	
	CLASSROOM H-11	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM H-12	F	*	
	CLASSROOM H-13	F	*	
	CLASSROOM H-14	F	*	
	CLASSROOM H-15	F	*	
	H-16 STORAGE	F	*	
	CLASSROOM H-16	F	*	
	H-16 RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
	CLASSROOM H-17	F	*	
	STORAGE 4	F	*	
	CLASSROOM H-18	F	*	
	STORAGE 5	F	*	
	CLASSROOM H-19	F	*	
	CORRIDOR 1	F	*	
	CORRIDOR 2	F	*	
	CORRIDOR 3	F	*	
	CORRIDOR 4	F	*	
	CORRIDOR 5	F	*	
	CORRIDOR 6	F	*	
	CORRIDOR 7	F	*	
	CORRIDOR 8	F	*	
	CORRIDOR 9	F	*	
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	SERVICE YARD	F	*	S
	EXTERIOR	F	*	
STUCCO, GRAY, CEMENTITIOUS	SERVICE YARD	O	*	S
	EXTERIOR	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	ROOF	O	*	S
ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, TAN MINERAL CAP	ROOF	O	*	S
SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	ROOF	O	*	S
SEALANT (DUCT), GRAY, BRITTLE	ROOF	O	*	S
WOVEN DUCT BOOT, 4", BLACK, VINYL-LIKE	ROOF	O	*	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Ramada*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BRICK, 4"X16", TAN, CEMENTITIOUS	RAMADA	W	N, E, W, S	S
BRICK, 4"X16", RED, CEMENTITIOUS	RAMADA	W	N, E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	RAMADA	W	N, E, W, S	S
EXPANSION JOINT, BROWN, PLIABLE	RAMADA	W	N, E, W, S	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	RAMADA	F	*	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Storage*

JOB NO. 08-192

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BRICK, 4"X16", TAN, CEMENTITIOUS	STORAGE	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
BRICK, 4"X16", RED, CEMENTITIOUS	STORAGE	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	STORAGE	W	N, E, W, S	S
	EXTERIOR	W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	STORAGE	F	*	S
	EXTERIOR	F	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S

*** - Not Applicable**

END OF TABLE

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Centennial Middle School, KSD

FM Project 08-192

2.4 AHERA Inspection Procedures and Protocols

2.4.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.4.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.5 Visual Inspection

A visual inspection of the ten buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Centennial Middle School, KSD

FM Project 08-192

2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

**BUILDING A
BUILDING B
BUILDING C
BUILDING D
BUILDING E
BUILDING F
BUILDING G
BUILDING H
RAMADA
STORAGE BUILDING**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building A*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	8,000	SF
M-APL-02	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, RIBBED, WHITE	S	F	200	SF
S-SAT-03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	9,000	SF
M-GWB-04	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	9,000	SF
S-JTC-05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	S	NF	900	SF
M-BRK-06	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	4,000	SF
M-BRK-07	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	4,000	SF
M-MRT-08	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	800	SF
M-EXJ-09	EXPANSION JOINT, BROWN, PLIABLE	A	NF	40	SF
M-TWP-10	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	S	NF	600	SF
M-MRT-11	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	30	SF
M-FDI-12	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	714	SF
M-WAB-13	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	400	SF
M-ADH-14	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	400	SF
M-CPT-15	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	9,000	SF
M-MAS-16	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	9,000	SF
M-SLT-17	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	50	SF
M-SLT-18	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	20	SF
M-SLT-19	SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	A	NF	25	SF
M-DST-20	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	75	SF
M-PSL-21	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	50	SF
S-TOT-22	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	800	SF
M-GWB-23	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	800	SF
S-JTC-24	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	80	SF
M-WAB-25	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	150	SF
M-ADH-26	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	150	SF
M-VCT-27	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,200	SF
M-MAS-28	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,200	SF
M-GWB-29	GYPSON WALLBOARD, WHITE, CHALKY	A	NF	3,200	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building A*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-JTC-30	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	320	SF
S-SAT-31	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M-GWB-32	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S-JTC-33	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M-SAC-34	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	8	SF
M-CON-35	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	9,500	SF
M-CON-36	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	3,500	SF
S-STU-37	STUCCO, GRAY, CEMENTITIOUS	A	NF	100	SF
M-BUR-38	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	9,500	SF
M-MAS-39	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	450	SF
M-SLT-40	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	50	SF
M-SLT-41	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	100	SF
M-PES-42	PIPE END SEALANT, GRAY, PLIABLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	17,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	12,000	SF
M-GWB-03	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	12,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	1,200	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	S	NF	1,800	SF
M-WAB-06	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	600	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	600	SF
M-CPT-08	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	17,000	SF
M-MAS-09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	17,000	SF
M-SLT-10	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	50	SF
M-SLT-11	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	20	SF
M-FDI-12	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	819	SF
M-SLT-13	SEALANT (DOORS, WINDOWS), TAN, PLIABLE	A	NF	25	SF
M-SAC-14	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	40	SF
M-DST-15	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	75	SF
M-PSL-16	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	50	SF
S-PLA-17	PLASTER, GRAY, CEMENTITIOUS	A	NF	700	SF
M-BRK-18	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	12,000	SF
M-BRK-19	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	12,000	SF
M-MRT-20	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	2,400	SF
M-EXJ-21	EXPANSION JOINT, BROWN, PLIABLE	A	NF	50	SF
M-CON-22	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	21,500	SF
M-VCT-23	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,000	SF
M-MAS-24	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,000	SF
M-WAB-25	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-ADH-26	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
S-SAT-27	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M-GWB-28	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S-JTC-29	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building B*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-TOT-30	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	250	SF
M-GWB-31	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	250	SF
S-JTC-32	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	25	SF
S-SAT-33	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M-GWB-34	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S-JTC-35	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M-GWT-36	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	2,000	SF
M-GWT-37	GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	A	NF	250	SF
M-GRT-38	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	A	NF	250	SF
M-CMT-39	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	A	NF	1,400	SF
M-CMT-40	CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH	A	NF	75	SF
M-CMT-41	CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	A	NF	75	SF
M-GRT-42	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	A	NF	150	SF
M-CON-43	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	10,000	SF
M-CON-44	CONCRETE (COURTYARD), GRAY, CEMENTITIOUS, GRAVEL FINISH	A	NF	3,000	SF
M-BRK-45	BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	A	NF	1,200	SF
M-MRT-46	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	A	NF	120	SF
S-STU-47	STUCCO, GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-BUR-48	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	21,500	SF
M-MAS-49	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	1,200	SF
M-SLT-50	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	50	SF
M-SLT-51	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	50	SF
M-PES-52	PIPE END SEALANT, GRAY, PLIABLE	A	NF	20	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·APL·01	ACOUSTICAL CEILING TILE, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	19,000	SF
S·SAT·02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	18,500	SF
M·GWB·03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	18,500	SF
S·JTC·04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	1,850	SF
M·TWP·05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	S	NF	2,500	SF
M·CPT·06	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	15,000	SF
M·MAS·07	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	15,000	SF
M·WAB·08	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	650	SF
M·ADH·09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	650	SF
M·SLT·10	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	75	SF
M·FDI·11	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	798	SF
M·SLT·12	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	20	SF
M·SAC·13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	20	SF
M·DST·14	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	100	SF
M·PSL·15	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	75	SF
M·CON·16	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	20,000	SF
M·BRK·17	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	17,000	SF
M·BRK·18	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	17,000	SF
M·MRT·19	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	3,400	SF
M·EXJ·20	EXPANSION JOINT, BROWN, PLIABLE	A	NF	60	SF
S·PLA·21	PLASTER, GRAY, CEMENTITIOUS	A	NF	800	SF
S·TOT·22	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	600	SF
M·GWB·23	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	600	SF
S·JTC·24	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	60	SF
M·WAB·25	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	200	SF
M·ADH·26	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	200	SF
M·SLT·27	SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	A	NF	25	SF
M·VCT·28	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	2,000	SF
M·MAS·29	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	2,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building C*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-SAC-30	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	4	SF
S-SAT-31	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
M-GWB-32	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S-JTC-33	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	250	SF
M-GWT-34	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	2,000	SF
M-GWT-35	GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	A	NF	300	SF
M-GRT-36	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	A	NF	230	SF
M-CMT-37	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	A	NF	2,000	SF
M-CMT-38	CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH	A	NF	50	SF
M-CMT-39	CERAMIC MOSAIC TILE (PATTTERN), 2"X2", BLUE, SMOOTH	A	NF	50	SF
M-GRT-40	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	A	NF	200	SF
M-GWT-41	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	1,600	SF
M-GWT-42	GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	A	NF	100	SF
M-GRT-44	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	180	SF
M-CMT-45	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH	A	NF	850	SF
M-CMT-46	CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH	A	NF	25	SF
M-CMT-47	CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	A	NF	25	SF
M-GRT-48	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	A	NF	100	SF
M-CON-49	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	13,000	SF
S-STU-50	STUCCO, GRAY, CEMENTITIOUS	A	NF	2,000	SF
M-CON-51	CONCRETE (COURTYARDS), GRAY, CEMENTITIOUS, GRAVEL FINISH	A	NF	10,000	SF
M-BRK-52	BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	A	NF	400	SF
M-MRT-53	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK (PLANTERS), 4"X16", RED, CEMENTITIOUS, WHITE	A	NF	40	SF
M-BUR-54	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	25,000	SF
M-MAS-55	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	2,000	SF
M-SLT-56	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	100	SF
M-SLT-57	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	100	SF
M-PES-58	PIPE END SEALANT, GRAY, PLIABLE	A	NF	20	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	17,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	12,000	SF
M-GWB-03	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	12,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	1,200	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER, MECHANICALLY ATTACHED	S	NF	1,800	SF
M-WAB-06	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	600	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	600	SF
M-CPT-08	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	17,000	SF
M-MAS-09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	17,000	SF
M-SLT-10	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	75	SF
M-SAC-11	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	20	SF
M-FDI-12	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	756	SF
M-DST-13	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	200	SF
M-PSL-14	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	100	SF
M-SLT-15	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	20	SF
M-PES-16	PIPE END SEALANT, WHITE, PLIABLE	A	NF	100	SF
M-CON-17	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	22,000	SF
S-PLA-18	PLASTER, GRAY, CEMENTITIOUS	A	NF	700	SF
M-BRK-19	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	12,000	SF
M-BRK-20	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	12,000	SF
M-MRT-21	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	2,400	SF
M-EXJ-22	EXPANSION JOINT, BROWN, PLIABLE	A	NF	50	SF
M-VCT-23	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,000	SF
M-MAS-24	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,000	SF
M-WAB-25	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-ADH-26	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-SAC-27	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	4	SF
S-TOT-28	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	200	SF
M-GWB-29	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	200	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building D*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-JTC-30	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	20	SF
M-SLT-31	SEALANT (DOORS, WINDOWS), TAN, PLIABLE	A	NF	25	SF
S-SAT-32	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M-GWB-33	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S-JTC-34	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M-GWT-35	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	2,000	SF
M-GWT-36	GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	A	NF	250	SF
M-GRT-37	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", PINK, SMOOTH	A	NF	250	SF
M-CMT-38	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	A	NF	1,400	SF
M-CMT-39	CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH	A	NF	75	SF
M-CMT-40	CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	A	NF	75	SF
M-GRT-41	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", PINK, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH	A	NF	150	SF
M-CON-42	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	10,000	SF
M-CON-43	CONCRETE (COURTYARDS), GRAY, CEMENTITIOUS, GRAVEL FINISH	A	NF	3,000	SF
S-STU-44	STUCCO, GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-BUR-45	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	22,000	SF
M-MAS-46	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	1,200	SF
M-SLT-47	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	75	SF
M-SLT-48	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	75	SF
M-PES-49	PIPE END SEALANT, GRAY, PLIABLE	A	NF	25	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	11,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	21,000	SF
M-GWB-03	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	21,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	2,100	SF
M-SAC-05	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	6	SF
M-WAB-06	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-CPT-08	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	3,000	SF
M-MAS-09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	3,000	SF
M-SLT-10	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	50	SF
M-SLT-11	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	10	SF
M-TWP-12	TACKABLE WALL PANEL (MOVEABLE), WHITE, CHALKY, VINYL COVER	S	NF	250	SF
M-FDI-13	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,386	SF
M-DST-14	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	200	SF
M-PES-15	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	50	SF
M-PES-16	PIPE END SEALANT, WHITE, PLIABLE	A	NF	50	SF
M-WAB-17	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	300	SF
M-ADH-18	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	300	SF
M-VCT-19	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	6,000	SF
M-MAS-20	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES AND VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	7,500	SF
M-VCT-21	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	1,500	SF
M-WAB-22	WALLBASE (COVED), 6", BLUE, VINYL-LIKE	A	NF	75	SF
M-ADH-23	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 6", BLUE, VINYL-LIKE	A	NF	75	SF
M-APL-24	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, RIBBED, WHITE	S	F	1,500	SF
M-BRK-25	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	20,000	SF
M-BRK-26	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	25,000	SF
M-MRT-27	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	4,500	SF
M-EXJ-28	EXPANSION JOINT, BROWN, PLIABLE	A	NF	100	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·SLT·29	SEALANT (DOORS), TAN, PLIABLE	A	NF	50	SF
M·MRT·30	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	10	SF
M·VST·31	VINYL STAIR TREAD, 12"X36", RED, TEXTURED, CIRCLE PATTERN	A	NF	100	SF
M·MAS·32	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X36", RED, TEXTURED, CIRCLE PATTERN	A	NF	100	SF
M·VCT·33	VINYL COMPOSITION TILE, 24"X24", RED, TEXTURED, CIRCLE PATTERN	A	NF	300	SF
M·MAS·34	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", RED, TEXTURED, CIRCLE PATTERN	A	NF	300	SF
M·WAB·35	WALLBASE (COVED), 6", BROWN, VINYL-LIKE	A	NF	30	SF
M·ADH·36	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 6", BROWN, VINYL-LIKE	A	NF	30	SF
M·WAB·37	WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	A	NF	100	SF
M·ADH·38	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	A	NF	100	SF
S·SAT·39	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	8,000	SF
M·GWB·40	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	8,000	SF
S·JTC·41	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	800	SF
M·APL·42	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, CHALKY, VINYL-COVER	S	NF	2,500	SF
M·TWP·43	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	S	NF	300	SF
M·QPT·44	QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	A	NF	3,000	SF
M·GRT·45	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	A	NF	300	SF
S·TOT·46	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M·GWB·47	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S·JTC·48	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M·CON·49	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	35,000	SF
M·GWT·50	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	5,400	SF
M·GWT·51	GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	600	SF
M·GRT·52	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	600	SF
M·CMT·53	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH	A	NF	4,400	SF
M·CMT·54	CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH	A	NF	550	SF
M·CMT·55	CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	A	NF	550	SF
M·GRT·56	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	A	NF	550	SF
M·SLT·57	SEALANT (DUCT), WHITE, PLIABLE	A	NF	50	SF
S·STU·58	STUCCO, GRAY, CEMENTITIOUS	A	NF	200	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building E*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CON-59	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	30,000	SF
M-SLT-60	SEALANT (WINDOWS), BLACK, PLIABLE	A	NF	10	SF
S-SAT-61	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	350	SF
M-GWB-62	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	350	SF
S-JTC-63	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	40	SF
M-GWT-64	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	600	SF
M-GWT-65	GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	A	NF	80	SF
M-GWT-66	GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	80	SF
M-GRT-67	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	80	SF
M-CMT-68	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	A	NF	300	SF
M-CMT-69	CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH, PEPPERED	A	NF	35	SF
M-CMT-70	CERAMIC MOSAIC TILE (PATTERN), 2"X2", GRAY, SMOOTH	A	NF	35	SF
M-GRT-71	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", BLUE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", GRAY, SMOOTH	A	NF	40	SF
M-CON-72	CONCRETE (EQUIPMENT PADS), GRAY, CEMENTITIOUS	A	NF	600	SF
M-BUR-73	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	28,000	SF
M-MAS-74	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	3,000	SF
M-APR-75	ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, TAN MINERAL CAP	A	NF	3,000	SF
M-SLT-76	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	50	SF
M-SLT-77	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	50	SF
M-PSL-78	PIPE SEALANT, GRAY, PLIABLE	A	NF	20	SF
M-WDB-79	WOVEN DUCT BOOT, 4", BLACK, VINYL-LIKE	A	NF	75	SF
M-BUR-80	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	3,000	SF
M-MAS-81	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	300	SF
M-SLT-82	SEALANT (DUCT), GRAY, BRITTLE	A	NF	25	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	8,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
M-GWB-03	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	1,000	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	S	NF	2,500	SF
M-WAB-06	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	300	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	300	SF
M-CPT-08	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	5,500	SF
M-MAS-09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	5,500	SF
M-FDI-10	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	504	SF
M-SLT-11	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	50	SF
M-SAC-12	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	22	SF
S-SAT-13	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	800	SF
M-GWB-14	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	800	SF
S-JTC-15	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	80	SF
M-VCT-16	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	2,500	SF
M-MAS-17	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	2,500	SF
M-WAB-18	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	200	SF
M-ADH-19	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	200	SF
M-SLT-20	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	10	SF
M-DST-21	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	75	SF
M-PSL-22	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	10	SF
M-CON-23	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	11,000	SF
M-WDB-24	WOVEN DUCT BOOT, 4", BLACK, VINYL-LIKE	A	NF	1	SF
M-TWP-25	TACKABLE WALL PANEL (MOVEABLE), BROWN, FIBROUS, VINYL-COVER	A	NF	400	SF
M-BRK-26	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	5,500	SF
M-BRK-27	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	6,500	SF
M-MRT-28	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	1,200	SF
M-EXJ-29	EXPANSION JOINT, BROWN, PLIABLE	A	NF	50	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building F*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·SLT·30	SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	A	NF	25	SF
M·CON·31	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	5,000	SF
M·QPT·32	QUARRY/PAVER TILE, 4"X8", GRAY, CEMENTITIOUS, SAND FILLED	A	NF	20	SF
M·CON·33	CONCRETE (EQUIPMENT PADS), GRAY, CEMENTITIOUS	A	NF	50	SF
S·TOT·34	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	1,500	SF
M·GWB·35	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	1,500	SF
S·JTC·36	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	150	SF
M·BUR·37	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	11,000	SF
M·MAS·38	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	500	SF
M·SLT·39	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	75	SF
M·SLT·41	SEALANT (CANOPIES), GRAY, PLIABLE	A	NF	75	SF
M·PSL·42	PIPE SEALANT, GRAY, PLIABLE	A	NF	25	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	6,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	8,000	SF
M-GWB-03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	8,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	800	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	S	NF	2,000	SF
M-WAB-06	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	200	SF
M-ADH-07	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	200	SF
M-CPT-08	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	10,000	SF
M-MAS-09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	10,000	SF
M-SLT-10	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	40	SF
M-SLT-11	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	15	SF
M-FDI-12	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	273	SF
M-SAC-13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	12	SF
M-DST-14	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	50	SF
M-PSL-15	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	20	SF
M-VCT-16	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,500	SF
M-MAS-17	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	1,500	SF
M-WAB-18	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	80	SF
M-ADH-19	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	80	SF
S-SAT-20	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	700	SF
M-GWB-21	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	700	SF
S-JTC-22	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	70	SF
M-SLT-23	SEALANT (DUCT), WHITE, PLIABLE	A	NF	50	SF
M-MRT-24	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	6	SF
S-TOT-25	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	300	SF
M-GWB-26	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	300	SF
S-JTC-27	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	30	SF
M-CON-28	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	11,000	SF
S-SAT-29	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	250	SF
M-GWB-30	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	250	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building G*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-JTC-31	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH	A	NF	25	SF
M-CON-32	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-EXJ-33	EXPANSION JOINT, GRAY, PLIABLE	A	NF	50	SF
M-BRK-34	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	4,500	SF
M-BRK-35	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	4,500	SF
M-MRT-36	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	900	SF
M-EXJ-37	EXPANSION JOINT, BROWN, PLIABLE	A	NF	50	SF
M-SLT-38	SEALANT (DOORS, WINDOWS), TAN, PLIABLE	A	NF	25	SF
S-STU-39	STUCCO, GRAY, CEMENTITIOUS	A	NF	12	SF
M-BUR-40	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	11,000	SF
M-MAS-41	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	500	SF
M-APR-42	ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, TAN MINERAL CAP	A	NF	300	SF
M-SLT-43	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	50	SF
M-SLT-44	SEALANT (FLASHING), GRAY, PLIABLE	A	NF	100	SF
M-PSL-45	PIPE SEALANT, GRAY, PLIABLE	A	NF	20	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	25,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	32,000	SF
M-GWB-03	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	32,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	3,200	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER, MECHANICALLY ATTACHED	A	NF	2,000	SF
M-TWP-06	TACKABLE WALL PANEL (MOVEABLE), WHITE, CHALKY	A	NF	7,000	SF
M-WAB-07	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	800	SF
M-ADH-08	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	800	SF
M-CPT-09	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	20,000	SF
M-MAS-10	MASTIC, YELLOW, TACKY, ASSOCIATED, WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	A	NF	20,000	SF
M-SLT-11	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	50	SF
M-FDI-12	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,218	SF
M-SAC-13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	46	SF
M-SLT-14	SEALANT (WINDOWS), BLACK, GUMMY	A	NF	12	SF
S-TOT-15	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M-GWB-16	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S-JTC-17	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M-VCT-18	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	6,500	SF
M-MAS-19	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	6,500	SF
M-DST-20	DUCT SEAM TAPE, 2", WHITE, CANVAS	S	F	150	SF
M-PSL-21	PIPE SEALANT (FIRE SPRINKLERS), WHITE, PLIABLE	A	NF	25	SF
S-SAT-22	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	4,000	SF
M-GWB-23	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	4,000	SF
S-STC-24	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	400	SF
M-GWT-25	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	5,500	SF
M-GWT-26	GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH	A	NF	400	SF
M-GWT-27	GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	400	SF
M-GRT-28	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GRAY, SMOOTH	A	NF	600	SF
M-CMT-29	CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED	A	NF	3,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Building H*

JOB NO. 08-192

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CMT-30	CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH	A	NF	150	SF
M-CMT-31	CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	A	NF	150	SF
M-GRT-32	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", WHITE, SMOOTH, PEPPERED AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT BLUE, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK BLUE, SMOOTH	A	NF	350	SF
M-BRK-33	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	6,000	SF
M-BRK-34	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	6,000	SF
M-MRT-35	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	1,200	SF
M-EXJ-36	EXPANSION JOINT, BROWN, PLIABLE	A	NF	50	SF
M-SLT-37	SEALANT (DOORS, WINDOWS, FIXTURES), TAN, PLIABLE	A	NF	25	SF
M-CBB-38	CEMENTITIOUS BUILDING BOARD, GRAY, BRITTLE	A	NF	100	SF
M-MRT-39	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	40	SF
M-QPT-40	QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH	A	NF	300	SF
M-GRT-41	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 12"X12", GRAY, SMOOTH	A	NF	30	SF
S-SAF-42	SPRAY-APPLIED FIREPROOFING, GRAY, FIBROUS	S	F	1,500	SF
M-VCT-43	VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, CIRCLE PATTERN	A	NF	100	SF
M-MAS-44	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, CIRCLE PATTERN	A	NF	100	SF
M-GWB-45	GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	500	SF
S-JTC-46	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	50	SF
M-CON-47	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	30,000	SF
M-CON-48	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	6,000	SF
S-STU-49	STUCCO, GRAY, CEMENTITIOUS	A	NF	1,800	SF
M-BUR-50	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAVEL CAP	A	NF	30,000	SF
M-MAS-51	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE, SILVER	A	NF	750	SF
M-APR-52	ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, TAN MINERAL CAP	A	NF	1,500	SF
M-SLT-53	SEALANT (FLASHINGS), BLACK, PLIABLE, SILVER	A	NF	50	SF
M-SLT-54	SEALANT (DUCT), GRAY, BRITTLE	A	NF	5	SF
M-WDB-55	WOVEN DUCT BOOT, 4", BLACK, VINYL-LIKE	A	NF	4	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Ramada*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BRK-01	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	1,500	SF
M-BRK-02	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	1,500	SF
M-MRT-03	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	300	SF
M-EXJ-04	EXPANSION JOINT, BROWN, PLIABLE	A	NF	25	SF
M-CON-05	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	1,200	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Centennial Middle School, KSD
Storage*

JOB NO. 08-192

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BRK-01	BRICK, 4"X16", TAN, CEMENTITIOUS	A	NF	1,500	SF
M-BRK-02	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	1,500	SF
M-MRT-03	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", TAN, CEMENTITIOUS AND BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	300	SF
M-CON-04	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	300	SF
M-CON-05	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	250	SF

END OF TABLE

2.7 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **NINETEEN** friable suspect ACBM (acoustical ceiling panels, duct seam tape and spray-applied fireproofing) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.8 Sample Collection

Convenience sampling was performed on select identified suspect ACBM, except for the spray-applied fireproofing, which was random sampled. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
A	42 (35 Assumed)	21
B	52 (46 Assumed)	18
C	57 (51 Assumed)	18
D	49 (43 Assumed)	18
E	82 (73 Assumed)	27
F	41 (35 Assumed)	18
G	45 (39 Assumed)	18
H	55 (52 Assumed)	11
Ramada	5 (5 Assumed)	0
Storage	5 (5 Assumed)	0
TOTAL	433	149

Suspect ACM Designation and Sample Record Forms are presented in Appendix A.

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Centennial Middle School, KSD

FM Project 08-192

2.9 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.

END OF REPORT

APPENDIX A

Suspect Asbestos-Containing Material Designation and Sample Record Forms

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x2'

Matrix/Primary Color: Gray Cover/Secondary Color: White
 Quantity of Material: 8000 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PSYCH	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	OFFICE 1	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	MAIL	NW Corner	E 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: IM-APL-02 Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Panel Size: 2' x 2'

Matrix/Primary Color: Grey Cover/Secondary Color: white

Quantity of Material: 200 Estimated By: Drawing Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	NW Corner	E 9'	S 39'	10'	F / W / C / O
B	Reception	NW Corner	E 9'	S 42'	10'	F / W / C / O
C	Reception	NW Corner	E 9'	S 48'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-03 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 9000 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PSYCH	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	OFFICE 1	NW Corner	E 0'	S 0'	10'	F/W/C/O
C	MAIL	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Michael Coleman* Date: 06/13/08
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-04 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Yes No Friable Non-Friable

General Description: Gypsum wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 9000 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PSYSLT	NW Corner	E 0'	S 0'	10'	F <input checked="" type="checkbox"/> W <input type="checkbox"/> I <input type="checkbox"/> C <input type="checkbox"/> O
B	OFFICE 1	NW Corner	E 0'	S 0'	10'	F <input checked="" type="checkbox"/> W <input type="checkbox"/> I <input type="checkbox"/> C <input type="checkbox"/> O
C	MAIL	NW Corner	E 0'	S 0'	10'	F <input checked="" type="checkbox"/> W <input type="checkbox"/> I <input type="checkbox"/> C <input type="checkbox"/> O
D		Corner				F / W / I / C / O
E		Corner				F / W / I / C / O
F		Corner				F / W / I / C / O
G		Corner				F / W / I / C / O

Comments: ASSOCIATED WITH SAT-03

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-05 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Psych	NW Corner	E 0'	SO'	10'	F/W/C/O
B	OFFICE 1	NW Corner	E 0'	SO'	10'	F/W/C/O
C	MAIL	NW Corner	E 0'	SO'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6WB-04

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BEK-DU Damaged: Yes No Friable Non-Friable
 General Description: BEICK Size: 4" x 16"

Matrix/Primary Color: TAN Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BRK-07 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 1 1/2"

Matrix/Primary Color: RED Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA Date: 06/13/08
 AHERA Certificate No.: Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-08 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MOETAE

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-BEX-06 M-BRK-07

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EX-09 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-10 Damaged: Yes No Friable Non-Friable
 General Description: TACKLE WALL PANEL Size: N/A

Matrix/Primary Color: BROWN Cover/Secondary Color: Vinyl Cove
 Quantity of Material: 600 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	NW Corner	E 0'	S 8'	4'	F/W/C/O
B	TEACHERS LOUNGE	SW Corner	E 2'	N 0'	4'	F/W/C/O
C	ISOLATED CLASSROOM	NW Corner	E 0'	S 12'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Mechanically Attached

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-11 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH GLASS BLOCK 8"x8" Clear

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-F01-12 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 714 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-13 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4"

General Description: WALLBASE (COVERED) Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A

Matrix/Primary Color: BLUE Quantity of Material: 400 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-14 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-13

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Signature: [Signature] Date: 06/13/08
 AHERA Certificate No.: D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CPT-15 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered: Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: MULTI COLORED SPECKLS
 Quantity of Material: 9.000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ornf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MA5-16 Damaged: Yes No Friable Non-Friable
 Visible Covered CPT Size: N/A

General Description: MASTIC Texture/Pattern: TACKY Cover/Secondary Color: N/A

Matrix/Primary Color: Yellow Estimated By: Drawing Field Measure
 Quantity of Material: 900 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-0PT-15

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Signature: *Paul Massey* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-17 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (Doors, Windows, Millwork, Fixtures) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA D12124 Date: 06/13/08
 AHERA Certificate No.: D12287 Signature: [Signature] State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT - 18 Damaged: Yes No Friable Non-Friable
 General Description: SEPARANT (WINDOWS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: GUMMY Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, FIXTURES) Size: N/A

Matrix/Primary Color: TAN Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *M. Coleman* Signature: *[Signature]* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-20 Damaged: Yes No Friable Non-Friable
 General Description: Duct SEAM TAPE Size: 2"

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PSY GH	NW Corner	E 6'	S 4'	11'	F / W / C / O
B	OFFICE 1	NW Corner	E 2'	S 2'	11'	F / W / C / O
C	MAIL	NW Corner	E 8'	S 3'	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PSL-21 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEWANT (Fire Sprinklers) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Signature: [Signature] Date: 06/13/08
 AHERA Certificate No.: D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-TOT-22 Damaged: Yes No Friable Non-Friable
 General Description: Traveled on texture Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FMA
GROUP INC

FM GROUP/forms/SuspACIMDesigRecord.ormf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWS-23 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-TOT-22

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Mh Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-ITC-24 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed

Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-23

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Signature: *Paul Massey* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WA-B-25 Damaged: Yes No Friable Non-Friable
 General Description: wall base (covered) Visible Covered Size: 4"

Matrix/Primary Color: Brown Texture/Pattern: Velvet-Like Cover/Secondary Color: N/A
 Quantity of Material: 150 SP / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADA-26 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-25

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Date: 06/13/08 AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-VCT-27 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: GRAY MOTTLES
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Signature: [Signature] Date: 06/13/08
 AHERA Certificate No.: D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MA S-28 Damaged: Yes No Friable Non-Friable
 Visible Covered UCT Size: N/A

General Description: MASTIC Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Matrix/Primary Color: Yellow Estimated By: Drawing Field Measure
 Quantity of Material: 1000 SFD / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-UCT-27

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA Paul Massey
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-29 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Sampled Assumed
 Quantity of Material: 3200 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-30 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 320 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-29

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: 3-SAT-31 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Spray Applied Texture
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *Michael Coleman* Signature: *Paul Massey* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-32 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-31

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC 33 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-32

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SIAC-34 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Sink Acoustical Ceiling Texture/Pattern: Rough Cover/Secondary Color: N/A

Matrix/Primary Color: Black Estimated By: Drawing Sampled
 Quantity of Material: 8 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CO-35 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 9,500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-36 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 3500 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STU-37 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Signature: *Michael Coleman* State License: EPA AHRA Certificate No.: D12124 Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUR-38 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: BUILT UP - ROOFING Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: Asphaltic Cover/Secondary Color: GRAVEL CAP
 Quantity of Material: 9500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: IM-MAS-39 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: MASTIC (PENETRATIONS + FLASHTINGS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: SILVER
 Quantity of Material: 450 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-40 Damaged: Yes No Friable Non-Friable
 General Description: SEBLANT (FLASHING) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Pliable Cover/Secondary Color: SILVER
 Quantity of Material: 50 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-41 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHING) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA D12124 Date: 06/13/08
 AHERA Certificate No.: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: A Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PES-42 Damaged: Yes No Friable Non-Friable
 General Description: PIPE END SEALANT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08 State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-AP-01 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2' x 2'

General Description: Acoustical Ceiling Panel
 Matrix/Primary Color: Grey Texture/Pattern: Pisholes + Fissures Cover/Secondary Color: White
 Quantity of Material: 17,000 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM B-13	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	CLASSROOM B-8	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	CLASSROOM B-4	NW Corner	E 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM B-13	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM B-8	NW Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASSROOM B-4	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-03 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM B-13	NW Corner	E 6'	S 0'	10'	F (W) / C / O
B	CLASSROOM B-8	NW Corner	E 0'	S 0'	10'	F (W) / C / O
C	CLASSROOM B-4	NW Corner	E 0'	S 0'	10'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: 3-JTC-04 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: JOINT COMPOUND Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By: Drawing Sampled Assumed
 Quantity of Material: 1200 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM B-13	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM B-8	NW Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASSROOM B-4	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M-6WS-03

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: Mh Coleman Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibers Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 1800 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM B-13	NW Corner	E 10'	S 0'	4'	F/W/C/O
B	CLASSROOM B-8	NW Corner	E 0'	S 4'	4'	F/W/C/O
C	CLASSROOM B-4	NW Corner	E 0'	S 12'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Mechanically Attached

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-00 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"

Matrix/Primary Color: BLUE Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-07 Visible Covered WAB Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: PLAINSPLE Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-06

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *Mh Coleman* Signature: *[Signature]* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CPT-08 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CARPET Texture/Pattern: Fibrous Cover/Secondary Color: Mult Colored Specks
 Matrix/Primary Color: Gray Estimated By: Drawing Field Measure
 Quantity of Material: 17,000 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MA5-07 Material Code: M-MA5-07
 Visible Covered Damaged: Yes No
 Friable Non-Friable

General Description: MASTIC
 Matrix/Primary Color: Yellow
 Cover/Secondary Color: N/A
 Size: N/A

Quantity of Material: 17,000
 Estimated By: Drawing Field Measure
 Textured/Pattern: Tacky
 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-08

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES) Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-11 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SEWANT (WINDOWS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: GUMM Cover/Secondary Color: N/A

Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FD1-12 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 819 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-13 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS) Size: N/A
 Matrix/Primary Color: TAN Texture/Pattern: PLUMB
 Quantity of Material: 25 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-14 Damaged: Yes No Friable Non-Friable
 General Description: S&K Acoustical Coating Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08 State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-15 Damaged: Yes No Friable Non-Friable
 General Description: DOOR SEAM TAPE Size: 2"

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Sampled Assumed
 Texture/Pattern: CANVAS Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASS ROOM B-13	NW Corner	E 6'	S 8'	11'	F / W / C / O
B	CLASS ROOM B-8	NW Corner	E 4'	S 2'	11'	F / W / C / O
C	CLASS ROOM B-4	NW Corner	E 6'	S 4'	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Signature: *Michael Coleman* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PSL-16 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT (Fire Sprinklers) Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-PLA-17 Damaged: Yes No Friable Non-Friable
 General Description: PLASTER Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CONCRETE BLOCKS Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

F/M
GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-132-K-18 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 16"

Matrix/Primary Color: TAN Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-132K-19 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 8"

Matrix/Primary Color: RED Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Signature: *Paul Massey* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-M RT-ZG Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 2400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-BRK-18, M-BRK-19

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EXJ-21 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: EXPANSION JOINT

Matrix/Primary Color: BROWN Texture/Pattern: PLASTER Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *Michael Coleman* Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: W-CON-22 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CONCRETE (FOUNDATION) Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 21,500 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-VET-23 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Grey Mottles
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-24 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MASTIC Texture/Pattern: TRACY Cover/Secondary Color: N/A
 Matrix/Primary Color: YELLOW Estimated By: Drawing Field Measure
 Quantity of Material: 1000 SF / LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VCT-23

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-25 Damaged: Yes No Friable Non-Friable
 General Description: WALLBASE (COVERED) Visible Covered Size: 4"
 Matrix/Primary Color: BROWN Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Date: 06/13/08 AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH - 2L Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: PLIATEL Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAS-25

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ome

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-27 Damaged: Yes No Friable Non-Friable
 General Description: Spray - Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: 11-GWB-28 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SAT-27

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-29 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWS-28

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-TOT-30 Damaged: Yes No Friable Non-Friable
 General Description: Traveled-on Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-31 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-TOT-30

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-5TC-32 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-6403-31

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed



SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-33 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Spray-Applied Texture
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 (SF) / LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-6WRB-34 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: GYP SUM WALLBOARD Cover/Secondary Color: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Estimated By: Drawing Field Measure
 Quantity of Material: 2000 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH J-SAT-33

Inspector: Michael Coleman State License: EPA Date: 06/13/08
Paul Massey State License: EPA Date: 06/13/08
 AHERA Certificate No.: D12287 AHERA Certificate No.: D12124
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-35 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-34

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-36 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-37 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-38 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-36, M-GWT-37

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord1.nmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CWRT-39 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2" x 2"

General Description: Ceramic Mosaic Tile Texture/Pattern: Smooth Cover/Secondary Color: Peppered
 Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 1400 Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-40 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile (Pattern) Size: 2" x 2"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-41 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile (PATTERNS) Size: 2" x 2"
 Matrix/Primary Color: Green Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8286 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-42 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CMT-39, M-CMT-40, M-CMT-41

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-43 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Size: N/A

Matrix/Primary Color: Grey Texture/Pattern: Dumbitious Cover/Secondary Color: N/A
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord1.pdf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: K-CON-44 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (COVERED) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: GRAVEL FINISH
 Quantity of Material: 3000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-32K-45 Damaged: Yes No Friable Non-Friable
 General Description: BRICK (PLASTER) Size: 4" x 6"

Matrix/Primary Color: RED Texture/Pattern: Cementitious Cover/Secondary Color: White
 Quantity of Material: 1200 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MKT-4C Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 120 (SF) / LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GRK-45

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* State License: EPA D12124 Date: 06/13/08
 Signature: *[Signature]* State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STU-47 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BULK-48 Damaged: Yes No Friable Non-Friable
 General Description: Built up Roofing Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Asphaltic Cover/Secondary Color: GRAY CAP
 Quantity of Material: 21,500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-11AS-49 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS + FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKES Cover/Secondary Color: SILVER
 Quantity of Material: 1200 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-50 Damaged: Yes No Friable Non-Friable
 General Description: SEPARATE (FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: SILVER
 Quantity of Material: SD Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-51 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Sampled
 Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: B Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PES-52 Damaged: Yes No Friable Non-Friable
 General Description: PIPE END SEALANT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: N/A
 Quantity of Material: 22 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-RPL-01 Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Tile Size: 2' x 2'
 Matrix/Primary Color: Grey Texture/Pattern: Patches + Fissures Cover/Secondary Color: White
 Quantity of Material: 19,000 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM C-12	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	CLASSROOM C-6	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	CLASSROOM C-3	NW Corner	E 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 18,500 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM C-2	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	CLASSROOM C-6	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	CLASSROOM C-3	NW Corner	E 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Gypsum Wallboard

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 18,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM C-12	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM C-6	NW Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASSROOM C-3	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH S-SAT-02

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1850 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM C-12	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM C-6	NW Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASSROOM C-3	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M-6WB-03

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: TACKABLE WALL PANEL
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER
 Quantity of Material: 2500 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM C-12	SW Corner	E 12'	N 0'	4'	F (W) / C / O
B	CLASSROOM C-6	NW Corner	E 6'	S 0'	4'	F (W) / C / O
C	CLASSROOM C-3	SE Corner	W 0'	N 4'	4'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Mechanically Attached

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHRA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CPT-06 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CARPET
 Matrix/Primary Color: GRAY Texture/Pattern: Fibrous Cover/Secondary Color: Multi Colored SPECKS
 Quantity of Material: 15,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-07 Material Code: M-MA5-07
 Visible Covered Damaged: Yes No
 Friable Non-Friable

General Description: MASTIC Size: N/A
 Matrix/Primary Color: Yellow Cover/Secondary Color: N/A

Quantity of Material: 15,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-06

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAS-08 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4"

General Description: WALLBASE (COVERED) Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Matrix/Primary Color: BLUE Estimated By: Drawing Field Measure
 Quantity of Material: 650 SF / LF / EA Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-09 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered WAS Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 650 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-08

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: SERVANT (DOORS, WINDOWS, MILLWORK, FIXTURES) Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 75 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FOC-11 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 798 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-12 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (windows) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: GUMMI Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspaACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-13 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: SINK Acoustical Ceiling Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-14 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Size: 2'

Matrix/Primary Color: White Texture/Pattern: CANVAS Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM C-12	NW Corner	E 8'	S 6'	11'	F / W / C / O
B	CLASSROOM C-6	NW Corner	E 6'	S 12'	11'	F / W / C / O
C	CLASSROOM C-3	NW Corner	E 6'	S 4'	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PSC-15 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: PIPE SEWANT (FIRE SPRINKLERS) Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 75 LF / EA Sampling

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-16 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 22,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: W-13R1C-17 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" X 16"

Matrix/Primary Color: TAN Cover/Secondary Color: N/A
 Quantity of Material: 17,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: Michael Coleman Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-1322-18 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Visible Covered Size: 4" x 16"

Matrix/Primary Color: RED Texture/Pattern: Concrete Cover/Secondary Color: N/A
 Quantity of Material: 17,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspAC/MSigRecord.cmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-19 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MORTAR Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Estimated By: Drawing Field Measure
 Quantity of Material: 3400 SF / LF / EA Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-13EK-17 M-13EK-18

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EX-20 Damaged: Yes No Friable: Non-Friable:
 General Description: EXPANSION JOINT Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: PIMBLE Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-PLA-2(Visible Damaged: Yes No Friable Non-Friable
 General Description: PLASTER Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-TOT-22 Damaged: Yes No Friable Non-Friable
 General Description: Traveled-on Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-23 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-TOT-22

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08 State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-5TC-24 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWS-23

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08 State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WA-25 Damaged: Yes No Friable Non-Friable
 General Description: WALLBASE (COVERED) Size: 4"

Matrix/Primary Color: BROWN Texture/Pattern: Viny-like Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-26 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-25

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-27 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, FIXTURES) Size: N/A
 Matrix/Primary Color: TAN Texture/Pattern: PIRSCLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Michael Coleman* Date: 06/13/08
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-VCT-28 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: GRAY MOTTLES
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-29 Damaged: Yes No Friable Non-Friable
 Visible Covered VCT Size: N/A

General Description: MASTIC
 Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated With M-VCT-28

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-30 Damaged: Yes No Friable Non-Friable

General Description: Sink Acoustical Coatings Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A

Quantity of Material: 4 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-31 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Textures Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Sampled
 Homogeneous Material Location: Ceiling Floor Wall Other Field Measure Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-82 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-31

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-33 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAFT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2SD Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-32

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8286 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-34 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D1287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-35 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"
 Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-34 Visible Covered: Damaged: Yes No Friable: Non-Friable:
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 230 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-34, M-GWT-35

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-37 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2" x 2"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: peppered
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-38 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2" x 2"

General Description: Ceramic Mosaic Tile (PARTIAL) Cover/Secondary Color: N/A

Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Estimated By: Drawing Field Measure
 Quantity of Material: 50 SF / LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-39 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2" x 2"

General Description: Ceramic Mosaic Tile (Pattern) Cover/Secondary Color: N/A
 Matrix/Primary Color: BLUE Texture/Pattern: Smooth Estimated By: Drawing Field Measure
 Quantity of Material: 50 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-40 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GROUT Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Matrix/Primary Color: Gray Estimated By: Drawing Field Measure Sampled Assumed

Quantity of Material: 200 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CMT-37, M-CMT-38, M-CMT-39

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D1287 State License: EPA D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-41 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Visible Covered Size: 4" x 4"

Matrix/Primary Color: White Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 1600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-42 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"
 Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 102 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspAC/MSigRecord.omf

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-43 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"

Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-44 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 180 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-41, M-GWT-42, M-GWT-43

Inspector: Michael Coleman State License: EPA D12287 Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Signature: [Signature] Date: 06/13/08
 AHERA Certificate No.: D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-45 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2" x 2"

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 850 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-46 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile (Pattern) Size: 2"x2"
 Matrix/Primary Color: Light Blue Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

FM GROUP INC

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-47 Damaged: Yes No Friable Non-Friable

General Description: CERAMIC MOSAIC TILE (PATTERN) Size: 2"x2"

Matrix/Primary Color: DARK BLUE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A

Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D1287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-C.R.T-48 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: GROUT
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CMT-45 M-CMT-46 M-CMT-47

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *Michael Coleman* Date: 06/13/08
 State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: IM-CON-49 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 13,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspAC/MSigRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STU-50 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Size: 1/2

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-51 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (COURTYARDS) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: GRAVEL FINISH
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BRK-SZ Damaged: Yes No Friable Non-Friable
 General Description: BRICK (PLANTERS) Size: 4x16"
 Matrix/Primary Color: RED Texture/Pattern: Cementitious Cover/Secondary Color: White
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-53 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MORTAR

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-BRK-52

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUR-54 Damaged: Yes No Friable Non-Friable
 General Description: BUILT UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY CAP
 Quantity of Material: 25,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-55 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS + FLASHING) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: SILVER
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspAC/MSigRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-56 Damaged: Yes No Friable Non-Friable

General Description: SEALANT (FRASSTINGS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Pliable Cover/Secondary Color: Silver

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-57 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: C Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PES-58 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: PIPE END SEALANT Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: PLUMB Estimated By: Drawing Field Measure
 Quantity of Material: 20 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: W-APL-01 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2' x 2'

General Description: Acoustical Ceiling Panel Texture/Pattern: P:holes + Fissures Cover/Secondary Color: white
 Matrix/Primary Color: Gray Estimated By: Drawing Sampled
 Quantity of Material: 17,000 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM D-12	Nw Corner	E 0'	S 0'	8'	F / W / C / O
B	CLASSROOM D-10	Nw Corner	E 0'	S 0'	8'	F / W / C / O
C	CLASSROOM D-3	Nw Corner	E 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SIAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Sampled
 Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM D-12	Nw Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM D-10	Nw Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASSROOM D-3	Nw Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM D-12	Nw Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM D-10	Nw Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASS ROOM D-3	Nw Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH S-SAT-02

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-ITC-04 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Sampled
 Quantity of Material: 1200 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM D-12	Nw Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM D-10	Nw Corner	E 0'	S 0'	10'	F/W/C/O
C	CLASSROOM D-3	Nw Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M-GWB-03

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM D-12	SE Corner	W 4'	N 0'	4'	F (W) C I O
B	CLASSROOM D-10	NW Corner	E 6'	S 0'	4'	F (W) C I O
C	CLASSROOM D-3	NW Corner	E 0'	S 4'	4'	F (W) C I O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Mechanically Attached

Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 AHERA Certificate No.: D12124 State License: EPA Date: 06/13/08
 Signature: *Paul Massey* Signature: *Michael Coleman* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-06 Damaged: Yes No Friable Non-Friable
 General Description: WALLPAPER (COVERED) Size: 4"

Matrix/Primary Color: BLUE Texture/Pattern: Vinyll-like Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-07 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A

Matrix/Primary Color: CLEAR Texture/Pattern: FLIPPLE Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAS-06

Inspector: Michael Coleman Inspector: Paul Massey
 AHIERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CPT-08 Damaged: Yes No Friable Non-Friable
 General Description: CAREPET Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Fibrous Cover/Secondary Color: Multi Colored Specks
 Quantity of Material: 17,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA Date: 06/13/08
 AHERA Certificate No.: D12287 Inspector: Paul Massey AHERA Certificate No.: D12124 State License: EPA Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-09 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered CPT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 17,000 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-08

Inspector: Michael Coleman State License: EPA AHIERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-10 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES) Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.cmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-11 Damaged: Yes No Friable Non-Friable
 General Description: Suspect Acoustical Ceiling Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FD1-12 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 756 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-13 Damaged: Yes No Friable Non-Friable
 General Description: DUCT SEAM TAPE Size: 2'

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM D-9	NW Corner	E 6'	SL'	11'	F/W/C/O
B	CLASSROOM D-7	NW Corner	E 4'	SZ'	11'	F/W/C/O
C	CLASSROOM D-3	NW Corner	E 6'	SU'	11'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PSL-14 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT (FIRE SPRINKLERS) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SJT-15 Damaged: Yes No Friable Non-Friable

General Description: SEARCH (windows) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: GUMMY Cover/Secondary Color: N/A

Quantity of Material: 20 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PES-16 Damaged: Yes No Friable Non-Friable

General Description: PIPE END SEALANT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 Inspector: Paul Massey AHERA Certificate No.: D12124 State License: EPA Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-17 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-PLA-18 Damaged: Yes No Friable Non-Friable
 General Description: PLASTER Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *Michael Coleman* State License: EPA D12124 Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: W-Back-19 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Visible Covered Size: 4" x 1 1/2"

Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-13216-20 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Visible Covered Size: 4" x 8"

Matrix/Primary Color: Red Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 12,000 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: 1A-MRT-21 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 2400 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-BRK-19, M-BRK-20

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EX-22 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: 2/A

Matrix/Primary Color: BROWN Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-VCT-23 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12"x12"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: GRAY MOTTLES
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MASS-24 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: 1/4

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-UCT-23

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-25 Damaged: Yes No Size: 4" Friable Non-Friable
 General Description: WALLBASE (COVERED) Visible: Covered:
 Matrix/Primary Color: BROWN Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-26 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Covered Visible Size: N/A

Matrix/Primary Color: CEMENT Texture/Pattern: Plinise Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAS-25

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *Michael Coleman* State License: EPA Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-27 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-TOT-28 Damaged: Yes No Friable Non-Friable
 General Description: Troweled on texture Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-29 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A
 Texture/Pattern: Chalky
 Estimated By: Drawing Field Measure Sampled Assumed


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-TOT-28

Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 AHERA Certificate No.: D12124 State License: EPA D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-30 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-29

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-31 Damaged: Yes No Friable Non-Friable
 General Description: SEAWALL (DOORS, WINDOWS) Size: N/A

Matrix/Primary Color: TAN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-32 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWTS-33 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-32

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-JTC-34 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAT Size: 1/4

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: NA
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-33

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-35 Damaged: Yes No Friable Non-Friable
 General Description: GUAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Sampling Sampled
 Random Convenience N/A

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-3L Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERNS) Size: 4"x4"

Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRET-37 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: C O B L E S T I O N S Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-35 M-GWT-36

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Signature: [Signature] Date: 06/13/08
 AHERA Certificate No.: D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-38 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2" x 2"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: ~~Peppered~~
 Quantity of Material: 1400 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.brmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-39 Visible Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tiles (PATTERN) Size: 2" x 2"
 Matrix/Primary Color: Pink Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-40 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE (PATTERN) Size: 2" x 2"

Matrix/Primary Color: BLUE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-41 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CMT-38, M-CMT-39, M-CMT-40

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *Michael Coleman* State License: EPA Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-42 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Covered Visible Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color:
 Quantity of Material: 10,000 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-43 Visible Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (COURTYARDS) Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: GRAY/FLUSH
 Quantity of Material: 3000 (SE) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: Date: 06/13/08 AHERA Certificate No.: Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S - STU-44 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Size: 1 1/2"

Matrix/Primary Color: GRAY Texture/Pattern: Concrete Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-13012-45 Damaged: Yes No Friable Non-Friable
 General Description: Built up Roofing Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: Green/Camp
 Quantity of Material: 22,000 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-46 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS + FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: IRRE-LIKE Cover/Secondary Color: SILVER
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-47 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Covered: Visible Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Pliable Cover/Secondary Color: SILVER
 Quantity of Material: 75 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-48 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Size: N/A

Matrix/Primary Color: GREY Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: D Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PES-49 Damaged: Yes No Friable Non-Friable
 General Description: PIPE END SEWANT Size: 1/4

Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-APL-a Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 2'
 Matrix/Primary Color: Gray Texture/Pattern: PIPLES & FISSURES Cover/Secondary Color: White
 Quantity of Material: 11,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	MUSIC STORAGE E-4	NE Corner	W 0'	S 0'	8'	F / W / C / O
C	MUSIC STORAGE E-3	SE Corner	W 0'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: D12124 AHERA Certificate No.: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: SSAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	MUSIC STORAGE E-4	NE Corner	W 0'	S 0'	10'	F / W / C / O
C	MUSIC STORAGE E-3	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWS-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Covered Visible Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 21,000 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	MUSIC SPRAIG E-4	NE Corner	W 0'	S 0'	10'	F/W/C/O
C	MUSIC SPRAIG E-3	SE Corner	W 0'	N 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSAULTED WITH G-SAT-02

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-372-04 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 2.100 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	MUSIC STORAGE E-4	NE Corner	W 0'	S 0'	10'	F/W/C/O
C	MUSIC STORAGE E-3	SE Corner	W 0'	N 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-05 Damaged: Yes No Friable Non-Friable
 General Description: SINK ACOUSTICAL CEILING Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Regrt Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAG-06 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERS) Visible Covered Size: 4"
 Matrix/Primary Color: BLUE Texture/Pattern: WOVEN-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled Assumed
 Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-07 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-06

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CPT-08 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: Multi-Color STREAKS
 Quantity of Material: 3000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 AHERA Certificate No.: D12287 Date: 06/13/08 AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-09 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: TAKEY Cover/Secondary Color: N/A
 Quantity of Material: 3000 SP / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CRT-08

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-11 Damaged: Yes No Friable: Non-Friable:
 General Description: SEALANT (Windows) Visible: Covered: Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: GUMMY Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-12 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL (MOVABLE) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: UNSYCLE COVER
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC STORAGE E-4	SW Corner	E 0'	N 0'	6"	F/W/C/O
B	MUSIC STORAGE E-3	NW Corner	E 0'	S 0'	6"	F/W/C/O
C	MUSIC STORAGE E-3	NW Corner	E 0'	S 0'	1'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.nmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FDI-13 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 1386 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-14 Damaged: Yes No Friable Non-Friable
 General Description: DUCT SEAM TAPE Visible Covered Size: 2"

Matrix/Primary Color: WHITE Texture/Pattern: CANVAS Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-12-15 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT (FIVE SPRINKLERS) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Pes-16 Damaged: Yes No Friable Non-Friable
 General Description: PIPE END SEAM Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: RAISE Cover/Secondary Color: W/A
 Quantity of Material: 50 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-17 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Size: 4"
 Matrix/Primary Color: BROWN Texture/Pattern: VINYL-LAKE Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Adh-18 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered WAB Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-V-19 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Visible Covered: Visible Covered Size: 12" x 12"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: GRAY MOTTLES
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-20 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 7500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-VGT-19, M-VGT-21

Inspector: Michael Coleman State License: EPA D12287 Inspector: Paul Massey State License: EPA D12124
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-VCT-21 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" x 12"

Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: BROWN MOTTLES
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-22 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Visible Covered Size: 6"

Matrix/Primary Color: BLUE Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-23 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-APL-24 Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Panel Size: 2' x 2'

Matrix/Primary Color: GRAY Texture/Pattern: RUBBED Cover/Secondary Color: WHITE

Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MULTI-PURPOSE	Nw Corner	E 0'	S 0'	10'	F / W / C / O
B	MULTI-PURPOSE	Sw Corner	E 0'	N 0'	10'	F / W / C / O
C	MULTI-PURPOSE	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BEK-25 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 6"

Matrix/Primary Color: TAN Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 20,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BK-26 Material Code: M-BK-26
 General Description: BRICK Material Code: M-BK-26
 Matrix/Primary Color: RED Material Code: M-BK-26
 Quantity of Material: 25.00 Material Code: M-BK-26

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A
 Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Estimated By: Drawing Field Measure
 Damaged: Yes No
 Size: 4" x 16"

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BEK-27 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Covered Visible Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 4500 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-BEK-25, M-BEK-26

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EX-28 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-5LT-29 Damaged: Yes No Friable Non-Friable
 General Description: SEAMANT (DOORS) Size: N/A

Matrix/Primary Color: TAN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MET-30 Damaged: Yes No Friable Non-Friable
 General Description: METAL Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH GLASS BLOCK, 8" x 8", CLEAR

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-USI-31 Damaged: Yes No Friable Non-Friable
 General Description: VINYL STAIR TREAD Size: 12" x 36"
 Matrix/Primary Color: RED Texture/Pattern: TEXTURED Cover/Secondary Color: CIRCLE PATTERN
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-32 Visible Covered Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 100 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-USE-31

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-U-33 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 24"x24"

Matrix/Primary Color: RED Texture/Pattern: TEXTURED Cover/Secondary Color: CIBELLE PATERN
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D1287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.nmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Mas-34 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: BENTLE Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-UCT-33

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-35 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (LOWES) Size: 6"

Matrix/Primary Color: BROWN Texture/Pattern: WYLL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Adit-36 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Covered WAS Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAS-37 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (L-SHAPED) Size: 4"

Matrix/Primary Color: BLACK Texture/Pattern: WYRE-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-38 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-37

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-39 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 8,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-40 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Covered Visible Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A

Quantity of Material: 8,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-39

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-3JC-41 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Texture/Pattern: CRACKY Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: WHITE Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 300 (SF) / LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-APL-42 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panels Size: 2' x 4'

Matrix/Primary Color: GRAY Texture/Pattern: CHALKED Cover/Secondary Color: VINYL-COVER

Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	KITCHEN	NE Corner	W 0'	S 0'	8'	F / W / C / O
C	KITCHEN	SW Corner	E 0'	N 2'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA D12124 Date: 06/13/08
 AHERA Certificate No.: D12287 Signature: [Signature] State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-43 Damaged: Yes No Friable Non-Friable
 General Description: TACKLE WALL PANEL Size: N/A
 Matrix/Primary Color: BRN Texture/Pattern: FIBROUS Cover/Secondary Color: W/PL-COVER
 Quantity of Material: 300 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STAGE	SW Corner	E 12'	N 0'	6"	F/W/C/O
B	STAGE	SW Corner	E 21'	N 0'	6"	F/W/C/O
C	STAGE	NE Corner	W 6'	S 18'	6"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: MECHANICALLY ATTACHED

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-08-44 Damaged: Yes No Friable Non-Friable
 General Description: QUARRY / POWER TILE Size: 6" x 6"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 3000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA D12287 Date: 06/13/08
 AHERA Certificate No.: D12124 State License: EPA D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Gr-46 Damaged: Yes No Friable Non-Friable
 General Description: Grout Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-Ter-46 Damaged: Yes No Friable Non-Friable
 General Description: TRAVELED - ON TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-62B-47 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered Text Size: N/A
 Matrix/Primary Color: White Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 1,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-TOT-46

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-516-48 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered: Tot Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKLY Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-47

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-49 Damaged: Yes No Friable Non-Friable
 General Description: CEMENT (FOUNDATION) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 35.000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-50 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 5400 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-51 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"
 Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-S2 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 600 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-GRT-50, M-GRT-51

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.cmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Cut-S3 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Size: 2" x 2"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 4400 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CUT-54 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE (PATTEN) Size: 2" x 2"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: SSO Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CUT-SS Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC Mosaic TILE (PATTERN) Visible Covered
 Matrix/Primary Color: GREEN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A Size: 2" x 2"
 Quantity of Material: SSD Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-SC Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 550 Estimated By: Drawing Sampled Assumed
 SF / LF / EA
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-CMT-S3, M-CMT-S4, M-CMT-S5

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SUR-57 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DUCT) Visible Covered: Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-520-58 Damaged: Yes No Friable Non-Friable
 General Description: Stucco Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-59 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 30,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SUT-60 Damaged: Yes No Friable Non-Friable
 General Description: SEALS (windows) Size: N/A
 Matrix/Primary Color: BRACK Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-61 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 350 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-62 Damaged: Yes No Friable Non-Friable
 General Description: GYP-SUM WALLBOARD Visible Covered: SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 3SD Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-61

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-12-63 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-64 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: WHITE Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* State License: EPA Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-65 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-66 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATIEN) Size: 4" x 4"
 Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GRT-67 Damaged: Yes No Friable Non-Friable
 General Description: GRT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-GWT-64, M-GWT-65, M-GWT-66

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Cut-68 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Visible: Covered: Size: 2" x 2"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: PEPPER
 Quantity of Material: 302 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-69 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE (PATTERN) Size: 2" x 2"
 Matrix/Primary Color: BLUE Texture/Pattern: SMOOTH Cover/Secondary Color: REPERED
 Quantity of Material: 35 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-70 Damaged: Yes No Friable Non-Friable

General Description: CERAMIC MOSAIC TILE (PATTERNS) Size: 2" x 2"

Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: N/A

Quantity of Material: 35 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman

AHERA Certificate No.: D12287

Signature: *[Signature]*

Inspector: Paul Massey

AHERA Certificate No.: D12124

Signature: *[Signature]*

State License: EPA

Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Cert-71 Damaged: Yes No Friable Non-Friable
 General Description: GRAY Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-Cert-68, M-Cert-69, M-Cert-70

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-72 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (EQUIPMENT PAD) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUR-73 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAVEL CAP
 Quantity of Material: 26,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-74 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS & FLASHINGS) Covered Visible Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: SILVER
 Quantity of Material: 3000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA D12124 Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-3255 fax

Project No.: 08-192 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M.A.R.R. 75 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT PREPARED ROOFING (RAILED) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: TAN MINERAL CAP
 Quantity of Material: 3000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: MSUT-76 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: FRIABLE Cover/Secondary Color: SILVER
 Quantity of Material: SD (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACimDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-77 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FRASINGS) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: PLEASLE Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecord.ornf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PL-78 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PEARLE Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WDB-79 Damaged: Yes No Friable Non-Friable
 General Description: WOVEN DUCT BOOT Size: 4"

Matrix/Primary Color: BLACK Texture/Pattern: WOVEN-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUR-80 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASBESTALIC Cover/Secondary Color: GREY MINERAL CAP
 Quantity of Material: 3000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-81 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PEPPERATIONS & FUSKINGS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAB-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SET-82 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DUCT) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-AP-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 2'
 Matrix/Primary Color: Grey Texture/Pattern: Patches & fissures Cover/Secondary Color: White
 Quantity of Material: 8000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	DRAMA	Nw Corner	E 0'	S 0'	8'	F / W / C / O
B	HOME ECONOMICS	Nw Corner	E 0'	S 0'	8'	F / W / C / O
C	ART	Nw Corner	E 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	DRAMA	Nw Corner	E 0'	S 0'	10'	F/W/C/O
B	HOME ECONOMICS	Nw Corner	E 0'	S 0'	10'	F/W/C/O
C	ART	Nw Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARDS Visible Covered SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	DRAMA	Nw Corner	E 0'	S 0'	10'	F/W/C/O
B	HOME ECONOMICS	Nw Corner	E 0'	S 0'	10'	F/W/C/O
C	ART	Nw Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH SAT-02

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STE-OH Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	DRAMA	Nw Corner	E 0'	S 0'	10'	F/W/C/O
B	HOME ECONOMICS	Nw Corner	E 0'	S 0'	10'	F/W/C/O
C	ART	Nw Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M-GWB-03

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHRA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.ornf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-OS Damaged: Yes No Friable Non-Friable
 General Description: TABLE WALL PANELS Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: JUVYL-COVER
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	DRAMA	Nw Corner	E 0'	So'	1'	F / W / C / O
B	HOME ECONOMICS	Nw Corner	E 0'	So'	1'	F / W / C / O
C	ART	Nw Corner	E 0'	So'	1'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: MECHANICALLY ATTACHED

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-06 Damaged: Yes No Friable Non-Friable
 General Description: Wall Base (covered) Size: 4' r
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-07 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Covered Visible Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: PLEASIBLE Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-0C

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CR-08 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: Multi-Color SPECKS
 Quantity of Material: 5500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-08 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A
 Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 5500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-08

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FBI-10 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING over/Secondary Color: N/A
 Quantity of Material: 504 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-11 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, HULLDOCK, FIXTURES) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-12 Damaged: Yes No Friable Non-Friable
 General Description: SINK ACOUSTICAL COATING Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 22 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-13 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: CHALKY
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CWB-14 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-13

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STE-15 Damaged: Yes No Friable Non-Friable
 General Description: JAWT COMPOUND Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-14

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-VG-16 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" x 12"
 Matrix/Primary Color: WHITE Texture/Pattern: SUBOTIA Cover/Secondary Color: GRAY MATLES
 Quantity of Material: 2500 (SF) LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-17 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VGT-16

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-1A Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Size: 4"
 Matrix/Primary Color: BROWN Texture/Pattern: UNYCL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHIERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC.

FM GROUP/forms/SuspAC/MSigRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-19 Material Code: Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: PIZABLE Cover/Secondary Color: N/A

Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-18

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SCT-20 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (WINDOWS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: GUMM Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHIERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHIERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-21 Damaged: Yes No Friable Non-Friable
 General Description: DUCT SEAM TAPE Size: 2"

Matrix/Primary Color: WHITE Texture/Pattern: CANVAS Cover/Secondary Color: N/A
 Quantity of Material: 75 (SF) LF / EA Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	STORAGE 1	SW Corner	E 2'	N 5'	11'	F / W / C / O
B	STORAGE 1	NE Corner	W 3'	S 1'	11'	F / W / C / O
C	WEIGHT ROOM	SE Corner	W 1'	N 2'	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PB-22 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT (FIRE SPRINKLERS) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-23 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 11,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WBR-24 Damaged: Yes No Friable Non-Friable
 General Description: Woven Duct Bag Size: 4"
 Matrix/Primary Color: Black Texture/Pattern: Woven Like Cover/Secondary Color: N/A
 Quantity of Material: 1 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-25 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL (MOVEABLE) Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: WHITE-COVER
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BK-26 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 6"

Matrix/Primary Color: TAN Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 5500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BK-27 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 6"

Matrix/Primary Color: RED Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 6500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MR-28 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-BRK-26, M-BRK-27

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Exs-29 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: DIAPHRAGM Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-30 Damaged: Yes No Friable Non-Friable
 General Description: SEARCH (DOORS, WINDOWS, FIXTURES) Size: N/A
 Matrix/Primary Color: TAN Texture/Pattern: PEARLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-31 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Signature: [Signature] State License: EPA Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-QTF-32 Damaged: Yes No Friable Non-Friable
 General Description: QUARRY / PAVED TILE Size: 4" x 8"
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: SAND FILLED

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.mrf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Cons-33 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (EQUIPMENT PADS) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: SD (SF) LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-TOT-34 Damaged: Yes No Friable Non-Friable
 General Description: TROWELS-ON TEXTURE Covered Visible Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GURB-35 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARDS Visible Covered: TOP Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-FOR-34

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
Paul Massey State License: D12124 EPA Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-372-36 Damaged: Yes No Friable Non-Friable
 General Description: South Corridor Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: ~~Stippled~~ Cover/Secondary Color: N/A
 Quantity of Material: 150 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-35

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUR-37 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAVEL CAP
 Quantity of Material: 11,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-38 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS & FLAKINGS) Visible Covered Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: SILVER
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Set-39 Damaged: Yes No Friable Non-Friable
 General Description: SEAGANT (FRAGMENTS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: PLIABLE Cover/Secondary Color: SILVER
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-41 Damaged: Yes No Friable Non-Friable
 General Description: SERANT (CANDIES) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PLARGE Cover/Secondary Color: N/A

Quantity of Material: 75 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124 Date: 06/13/08

Signature: *[Signature]* Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PK-42 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PEARL Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ARL-01 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2' x 2'
 Matrix/Primary Color: GRAY Texture/Pattern: PICTURES & FIGURES Cover/Secondary Color: WHITE
 Quantity of Material: 6000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SPEECH	NE Corner	W 0'	S 0'	8'	F / W / C / O
B	MUSIC	NE Corner	W 0'	S 0'	8'	F / W / C / O
C	OFFICE	NE Corner	W 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 8000 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SPEECH	NE Corner	W 0'	S 0'	10'	F/W/C/O
B	MUSIC	NE Corner	W 0'	S 0'	10'	F/W/C/O
C	OFFICE	NE Corner	W 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Covered Visible Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 8000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SPEECH	NE Corner	W 0'	S 0'	10'	F/W/C/O
B	MUSIC	NE Corner	W 0'	S 0'	10'	F/W/C/O
C	OFFICE	NE Corner	W 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH SSAT-02

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-37c-04 Damaged: Yes No Friable Non-Friable
 General Description: Sawt Contours Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 800 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SPEECH	NE Corner	W 0'	S 0'	10'	F / W / C / O
B	MUSIC	NE Corner	W 0'	S 0'	10'	F / W / C / O
C	OFFICE	NE Corner	W 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-03

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 Fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-08 Damaged: Yes No Friable Non-Friable
 General Description: TAKEABLE WALL PANEL Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER
 Quantity of Material: 2000 (SF) / LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MEDIA CENTER	Nw Corner	E 0'	S 0'	6'	F / W / C / O
B	MEDIA CENTER	SE Corner	W 0'	N 0'	6'	F / W / C / O
C	MEDIA CENTER	Sw Corner	E 0'	N 0'	6'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: MECHANICALLY ATTACHED

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-06 Damaged: Yes No Friable Non-Friable
 General Description: Wall Base (covered) Size: 4"
 Matrix/Primary Color: Blue Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-07 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CRT-08 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: _____

Matrix/Primary Color: GRAY Texture/Pattern: FIBERS Cover/Secondary Color: MULTI-COLOR SPECKS
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord1.amf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-02 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered CPT Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 10,000 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-08

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLAIN Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SGT-11 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (Windows) Visible Covered Size: N/A

Matrix/Primary Color: Black Texture/Pattern: GUMMY Cover/Secondary Color: N/A

Quantity of Material: 15 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FD1-12 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 273 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustic Ceiling Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 12 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DIST-14 Damaged: Yes No Friable Non-Friable
 General Description: DUCT SEAM TAPE Size: 2"
 Matrix/Primary Color: WHITE Texture/Pattern: CANVAS Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MEDIA WORKSHOP	NE Corner	W 6'	S 2'	11'	F / W / C / O
B	NETWORK	NW Corner	E 6'	S 1'	11'	F / W / C / O
C	COMPUTER LAB 1	SW Corner	E 4'	N 5'	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: 11-BK-15 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT (FIRE SPRINKLERS) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Vet-16 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" x 12"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: GRAY MATILES
 Quantity of Material: 1500 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MASS-17 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VCT-16

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.ome

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-18 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVER) Size: 4"

Matrix/Primary Color: BROWN Texture/Pattern: WYLL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-19 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Covered Visible Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: P L I A S T I C Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O


Comments: ASSOCIATED WITH M-WAB-18

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *Michael Coleman* State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-20 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CARBY Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-21 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARDS Covered SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKLY Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SAT-20

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-212-22 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOND Visible Covered SAI Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 70 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-21

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* State License: EPA Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-23 Damaged: Yes No Friable Non-Friable
 General Description: SEASANT (DET.) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: SD (SF) / LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-24 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH GLASS BLOCK, 8" X 8", CLEAR

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08
 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-TOT-25 Damaged: Yes No Friable Non-Friable
 General Description: TROVELED ON TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-26 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-TOT-25

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-12-27 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-26

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-28 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 11,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-29 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-30 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARDS Visible Covered SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 250 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-29

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STR-31 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWR-30

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspAC/MSigRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-32 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EXS-33 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: *[Signature]* Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BRK-34 Damaged: Yes No Friable Non-Friable
 General Description: BRK Size: 4" x 6"
 Matrix/Primary Color: RED Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BEK-35 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 6"

Matrix/Primary Color: TAW Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 4500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *Michael Coleman* Signature: *Paul Massey*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MBK-36 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-BRK-34, M-BRK-35

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Ex-37 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-38 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS) Size: N/A
 Matrix/Primary Color: TAN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-39 Damaged: Yes No Friable Non-Friable
 General Description: Stucco Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 12 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUE-40 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GREEN CAP
 Quantity of Material: 11,000 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Signature: *Paul Massey* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-41 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Mastic (Penetrations and Flashings) Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: TAR-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M. APR. 42 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT PREPARED ROOFING (ROLLED) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: TAN MINERAL CAP
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-43 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: PLAIN Cover/Secondary Color: SILVER
 Quantity of Material: 50 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: N-SET-44 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHING) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.cmf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-PL-45 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: PLASLE Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287
 Signature: *Michael Coleman* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHRA Certificate No.: D12124
 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x2'

Matrix/Primary Color: GRAY Texture/Pattern: PINHOLES & FISSURES Cover/Secondary Color: WHITE

Quantity of Material: 25000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM H-14	NW Corner	E 8'	S 12'	10'	F / W / C / O
B	CLASSROOM H-3	NW Corner	E 12'	S 10'	10'	F / W / C / O
C	CLASSROOM H-9	NW Corner	E 4'	S 8'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: SSAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 32000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 32,000 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH 5-SAT-02

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-104-04 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAI Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 3200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-03

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed
 State License: EPA Date: 06/13/08

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-OS Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Microscopically Attached

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-TWP-06 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL (MOVABLE) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 7000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-WAB-07 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERS) Visible Covered Size: 4"
 Matrix/Primary Color: GRAY Texture/Pattern: WYLL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 800 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-ADH-08 Visible Covered: Damaged: Yes No Friable: Non-Friable:
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSUMED WITH M-WAB-07

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CR-09 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBERS Cover/Secondary Color: MULTI-COLOR SPECKS
 Quantity of Material: 20,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D1287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08 State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-10 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 20,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-CPT-09

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SUR-11 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MULLIONS, FIXTURES) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHIERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* State License: EPA Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-FBI-12 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL/WOOD SLADDING Cover/Secondary Color: N/A
 Quantity of Material: 12.1'S Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Sac-13 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustic Ceiling Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Re-salt Cover/Secondary Color: N/A
 Quantity of Material: 46 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SUR-14 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (WINDOWS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: GUMFI-1 Cover/Secondary Color: N/A
 Quantity of Material: 12 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACM/DesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: 5-Tot-15 Damaged: Yes No Friable Non-Friable
 General Description: TRAVELLED-ON TEXTURE Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-16 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARDS Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-TOT-15

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-216-17 Damaged: Yes No Friable Non-Friable
 General Description: Sawt Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-6WB-16

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-8286 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-UG-18 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" x 12"
 Matrix/Primary Color: WHITE Texture/Pattern: Smooth Cover/Secondary Color: GRAY MOTTLES
 Quantity of Material: 6,500 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08
 Inspector: Paul Massey State License: EPA

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-19 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A
 Matrix/Primary Color: YELLOW Texture/Pattern: JAGGY Cover/Secondary Color: N/A
 Quantity of Material: 6,500 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VGT-18

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed
 State License: EPA Date: 06/13/08

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8286 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-DST-20 Damaged: Yes No Friable Non-Friable
 General Description: DUCT SEAL TAPE Size: 2"

Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM H-14	NW Corner	E 8'	S 10'	11'	F / W / C / O
B	CLASSROOM H-9	NW Corner	E 3'	S 10'	11'	F / W / C / O
C	CLASSROOM H-3	NW Corner	E 12'	S 16'	11'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Psl-21 Damaged: Yes No Friable Non-Friable
 General Description: PIPE SEALANT (FIRE SPRINKLERS) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAT-22 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWB-23 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Covered SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SAT-22

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-1TC-24 Damaged: Yes No Friable Non-Friable
 General Description: Same Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWB-23

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA D12124 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-05 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: SSOD Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Gwt-26 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERNS) Size: 4" x 4"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* State License: EPA Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-27 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"

Matrix/Primary Color: GRAY Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GWT-28 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-GWT-25, M-GWT-26, M-GWT-27

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CUT-29 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Size: 2" x 2"
 Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: PEPPERED
 Quantity of Material: 3000 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CMT-30 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE (PATTERN) Size: 2" x 2"
 Matrix/Primary Color: LIGHT BLUE Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CUT-31 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE (PATTERNS) Size: 2" x 2"
 Matrix/Primary Color: DARK BLUE Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CUT-32 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 3SD Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-CUT-29, M-CUT-30, M-CUT-31

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08
 Inspector: Paul Massey

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BRK-33 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 16"

Matrix/Primary Color: TAN Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 6000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BRK-34 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 6"

Matrix/Primary Color: RED Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 6000 Estimated By: Drawing Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MBT-35 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1200 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-BRK-33, M-BRK-34

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Exp-36 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-37 Damaged: Yes No Friable Non-Friable

General Description: SEALANT (DOORS, WINDOWS, FIXTURES) Size: N/A

Matrix/Primary Color: TAN Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: 25 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CES-38 Damaged: Yes No Friable Non-Friable
 General Description: CEMENTITIOUS BUILDING BOARD Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MBT-39 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 40 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH CRASS BLOCK, 8x8, CLEAR

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-QPT-40 Damaged: Yes No Friable Non-Friable
 General Description: QUARRY / PAVER TILE Size: 12" x 12"
 Matrix/Primary Color: GRAY Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-GR-41 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GR-40

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08 Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-SAF-42 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED FIREPROOFING Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Lobby	NW Corner	E 0'	S 0'	11'	F / W / C / O
B	Lobby	NE Corner	W 0'	S 0'	11'	F / W / C / O
C	Lobby	SW Corner	E 10'	N 12'	11'	F / W / C / O
D	Lobby	SE Corner	W 10'	N 12'	11'	F / W / C / O
E	Lobby	NW Corner	E 0'	S 15'	11'	F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA
 Signature: [Signature] Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-100-43 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 24" x 24"

Matrix/Primary Color: GRAY Texture/Pattern: TEXTURED Cover/Secondary Color: CIRCLE PATTERNS
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-44 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-628-45 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Sampled Field Measure Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *[Signature]* Date: 06/13/08 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-37C-46 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-6WB-45

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Signature: *[Signature]* State License: EPA D12124 Date: 06/13/08
 Signature: *[Signature]* State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-47 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 30,000 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 86260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-48 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 6000 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: S-STU-49 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BUE-50 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Visible Covered Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAVEL CAP
 Quantity of Material: 30,000 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: _____ Date: 06/13/08
 Inspector: Paul Massey
 AHERA Certificate No.: D12124 State License: EPA
 Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MAS-51 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS & FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: SILVER
 Quantity of Material: 750 Texture/Pattern: TAP-LIKE Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: D12287 State License: EPA
 Signature: _____ Date: 06/13/08
 Inspector: Paul Massey State License: EPA
 AHERA Certificate No.: D12124 State License: EPA
 Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHJERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-APP-50 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT REPAIRED ROOFING (ROLLED) Visible Covered
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALT Cover/Secondary Color: TAN MINERAL CAP Size: N/A
 Quantity of Material: 1500 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Paul Massey
 AHJERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: Date: 06/13/08 Signature: Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-53 Damaged: Yes No Friable Non-Friable
 General Description: SEAMANT (FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: PLASLE Cover/Secondary Color: SILVER
 Quantity of Material: SD (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA D12287
 AHERA Certificate No.: D12287 State License: EPA D12124
 Signature: Date: 06/13/08
 Inspector: Paul Massey State License: EPA Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-SLT-S4 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DUCT) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: BRITLE Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: _____ Date: 06/13/08 Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-W-55 Damaged: Yes No Friable Non-Friable
 General Description: WOVEN DUCT BOOT Size: 4"

Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHRA Certificate No.: D12287 Date: 06/13/08
 Signature: _____ Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Ramada Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BK-01 Damaged: Yes No Friable Non-Friable
 General Description: BRK Size: 4" x 16"

Matrix/Primary Color: TAN Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Signature: *[Signature]* Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: *[Signature]* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FMA
GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Ramada Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BRK-02 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 16"

Matrix/Primary Color: RED Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Ramada Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-03 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: 4" x 16"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH: M-BRK-01, M-BRK-02

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Ramada Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-EX-04 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Visible Covered Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Ramada Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-Gen-05 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1200 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124
 Signature: [Signature] Date: 06/13/08
 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: WA-BREL-01 Damaged: Yes No Friable Non-Friable
 General Description: Brick Size: 4" x 16"

Matrix/Primary Color: TAN Texture/Pattern: Combinations Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: *Michael Coleman* Date: 06/13/08 Signature: *Paul Massey* Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-BEK-02 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Size: 4" x 6"

Matrix/Primary Color: RED Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1500 (SF) LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Inspector: Paul Massey State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-MRT-03 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: 1/2

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-BRK-02, M-BRK-03

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-04 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CONCRETE (FOUNDATION) Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Matrix/Primary Color: GRAY Estimated By: Drawing Field Measure
 Quantity of Material: 300 LF / EA Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Paul Massey
 AHERA Certificate No.: D12287 State License: EPA AHERA Certificate No.: D12124 State License: EPA
 Signature: [Signature] Date: 06/13/08 Signature: [Signature] Date: 06/13/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 271-7877
 (602) 271-9288 fax

FM GROUP INC

Project No.: 08-192 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Storage Address: 13808 South 36th Street
 Campus Name: Kyrene Centennial Middle School Phoenix, AZ 85044

Material Code: M-CON-05 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: D12287 Date: 06/13/08
 Inspector: Paul Massey State License: EPA AHERA Certificate No.: D12124 Date: 06/13/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

APPENDIX B

Bulk-Material Sample Documents

- **Chain-of-Custody**
- **Laboratory Analysis**



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200805572

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 21 PLM Rec: 6/16/2008 Method: EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Centennial MS/Bldg A PO Number: 08-192
Report Date: 6/29/2008 Date Analyzed: 6/29/2008 Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805572

Kyrene Centennial MS/Bldg A

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-05572- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-05572- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-05572- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-02A	2008-05572- 4	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-02B	2008-05572- 5	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-02C	2008-05572- 6	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	S-SAT-03A	2008-05572- 7	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-03B	2008-05572- 8	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-03C	2008-05572- 9	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-04A	2008-05572- 10	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-04B	2008-05572- 11	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-04C	2008-05572- 12	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-05A	2008-05572- 13	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-05B	2008-05572- 14	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-05C	2008-05572- 15	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-TWP-10A	2008-05572- 16	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-10B	2008-05572- 17	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-10C	2008-05572- 18	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-DST-20A	2008-05572- 19	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-20B	2008-05572- 20	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-20C	2008-05572- 21	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805572 Kyrene Centennial MS/Bldg A

Sample M-APL-01A **Lab Number** 2008-05572- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05572- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05572- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805572 Kyrene Centennial MS/Bldg A

Sample M-APL-02A **Lab Number** 2008-05572- 4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-02B **Lab Number** 2008-05572- 5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-02C **Lab Number** 2008-05572- 6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805572 Kyrene Centennial MS/Bldg A

Sample S-SAT-03A **Lab Number** 2008-05572- 7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03B **Lab Number** 2008-05572- 8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03C **Lab Number** 2008-05572- 9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805572 Kyrene Centennial MS/Bldg A

Sample M-GWB-04A **Lab Number** 2008-05572- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-04B **Lab Number** 2008-05572- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-04C **Lab Number** 2008-05572- 12 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805572

Kyrene Centennial MS/Bldg A

Sample S-JTC-05A **Lab Number** 2008-05572- 13 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05B **Lab Number** 2008-05572- 14 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05C **Lab Number** 2008-05572- 15 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805572 **Kyrene Centennial MS/Bldg A**

Sample M-TWP-10A **Lab Number** 2008-05572- 16 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-10B **Lab Number** 2008-05572- 17 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-10C **Lab Number** 2008-05572- 18 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805572 Kyrene Centennial MS/Bldg A

Sample M-DST-20A **Lab Number** 2008-05572- 19 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Miscellaneous Fibrous Mat
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-20B **Lab Number** 2008-05572- 20 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Miscellaneous Fibrous Mat
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-20C **Lab Number** 2008-05572- 21 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/29/2008 **An?** OK **Apparent Smp Type** Miscellaneous Fibrous Mat
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper


Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon

yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 29-Jun-2008

Original Print Date: 29-Jun-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200805573

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Centennial MS/Bldg B

PO Number: 08-192

Report Date: 6/30/2008

Date Analyzed: 6/16/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805573

Kyrene Centennial MS/Bldg B

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-APL-01A Layer # 1 off-white	2008-05573- 1	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 off-white	2008-05573- 2	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 off-white	2008-05573- 3	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white	2008-05573- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white	2008-05573- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white	2008-05573- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white	2008-05573- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white	2008-05573- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white	2008-05573- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white	2008-05573- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white	2008-05573- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white	2008-05573- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05A Layer # 1 Tan	2008-05573- 13	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05B Layer # 1 Tan	2008-05573- 14	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05C Layer # 1 Tan	2008-05573- 15	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-15A Layer # 1 White	2008-05573- 16	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-15B Layer # 1 White	2008-05573- 17	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-15C Layer # 1 White	2008-05573- 18	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805573 Kyrene Centennial MS/Bldg B

Sample M-APL-01A **Lab Number** 2008-05573- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations					
								Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05573- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations					
								Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05573- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations					
								Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805573 Kyrene Centennial MS/Bldg B

Sample S-SAT-02A **Lab Number** 2008-05573- 4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-05573- 5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-05573- 6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805573 Kyrene Centennial MS/Bldg B

Sample M-GWB-03A **Lab Number** 2008-05573- 7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	>1-2%	<=1%	-	-	-	-
Total %		100	Average %		>1-2%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-05573- 8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	>1-2%	<=1%	-	-	-	-
Total %		100	Average %		>1-2%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-05573- 9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	>1-2%	<=1%	-	-	-	-
Total %		100	Average %		>1-2%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805573 Kyrene Centennial MS/Bldg B

Sample S-JTC-04A **Lab Number** 2008-05573- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-05573- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-05573- 12 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805573 Kyrene Centennial MS/Bldg B

Sample M-TWP-05A **Lab Number** 2008-05573- 13 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05B **Lab Number** 2008-05573- 14 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05C **Lab Number** 2008-05573- 15 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805573 Kyrene Centennial MS/Bldg B

Sample M-DST-15A **Lab Number** 2008-05573- 16 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-DST-15B **Lab Number** 2008-05573- 17 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.


Sample M-DST-15C **Lab Number** 2008-05573- 18 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 30-Jun-2008

Original Print Date: 30-Jun-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200805574

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Centennial MS/Bldg C **PO Number:** 08-192
Report Date: 6/30/2008 **Date Analyzed:** 6/30/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary: Job Number: **200805574** Kyrene Centennial MS/Bldg C

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-05574- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-05574- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-05574- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	S-SAT-02A	2008-05574- 4	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-02B	2008-05574- 5	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-02C	2008-05574- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-03A	2008-05574- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-03B	2008-05574- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-03C	2008-05574- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-04A	2008-05574- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-04B	2008-05574- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-04C	2008-05574- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-TWP-05A	2008-05574- 13	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-05B	2008-05574- 14	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-05C	2008-05574- 15	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-DST-14A	2008-05574- 16	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-14B	2008-05574- 17	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-14C	2008-05574- 18	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805574 Kyrene Centennial MS/Bldg C

Sample M-APL-01A **Lab Number** 2008-05574- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05574- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05574- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805574 Kyrene Centennial MS/Bldg C

Sample S-SAT-02A **Lab Number** 2008-05574- 4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-05574- 5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-05574- 6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805574

Kyrene Centennial MS/Bldg C

Sample M-GWB-03A **Lab Number** 2008-05574- 7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-05574- 8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-05574- 9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805574

Kyrene Centennial MS/Bldg C

Sample S-JTC-04A **Lab Number** 2008-05574- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-05574- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-05574- 12 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 6/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805574 Kyrene Centennial MS/Bldg C

Sample M-TWP-05A Lab Number 2008-05574- 13 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 6/30/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	2-5%	-	-	-	-
Total %		100	Average %		70-80%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05B Lab Number 2008-05574- 14 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 6/30/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	2-5%	-	-	-	-
Total %		100	Average %		70-80%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05C Lab Number 2008-05574- 15 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 6/30/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	2-5%	-	-	-	-
Total %		100	Average %		70-80%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805574 Kyrene Centennial MS/Bldg C

Sample M-DST-14A Lab Number 2008-05574- 16 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 6/30/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-DST-14B Lab Number 2008-05574- 17 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 6/30/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.


Sample M-DST-14C Lab Number 2008-05574- 18 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 6/30/2008 An? OK Apparent Smp Type Miscellaneous Fibrous Mat
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 30-Jun-2008

Original Print Date: 30-Jun-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

Job Number: 200805575

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 **PLM** **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene Centennial MS/Bldg D **PO Number:** 08-192
Report Date: 7/1/2008 **Date Analyzed:** 7/1/2008 **Routing Number:** -

Method and Analysis Information: **Fiberquant Internal SOP:** PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Polutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color	Apparent Layer Type *	Asbestos Results	
Sample # M-APL-01A Layer # 1 Tan	2008-05575- 1	Ceiling Tile ceiling tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 Tan	2008-05575- 2	Ceiling Tile ceiling tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 Tan	2008-05575- 3	Ceiling Tile ceiling tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white	2008-05575- 4	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white	2008-05575- 5	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white	2008-05575- 6	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white	2008-05575- 7	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white	2008-05575- 8	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white	2008-05575- 9	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white	2008-05575- 10	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white	2008-05575- 11	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white	2008-05575- 12	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05A Layer # 1 Tan	2008-05575- 13	Miscellaneous panel <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05B Layer # 1 Tan	2008-05575- 14	Miscellaneous panel <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05C Layer # 1 Tan	2008-05575- 15	Miscellaneous panel <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-13A Layer # 1 White	2008-05575- 16	Miscellaneous duct tape <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-13B Layer # 1 White	2008-05575- 17	Miscellaneous duct tape <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-13C Layer # 1 White	2008-05575- 18	Miscellaneous duct tape <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample M-APL-01A **Lab Number** 2008-05575- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05575- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05575- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample S-SAT-02A **Lab Number** 2008-05575-4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-05575-5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-05575-6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample M-GWB-03A **Lab Number** 2008-05575-7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-05575-8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-05575-9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample S-JTC-04A Lab Number 2008-05575- 10 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 7/1/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B Lab Number 2008-05575- 11 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 7/1/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C Lab Number 2008-05575- 12 Sampled: 6/13/2008 Condition: acceptable
 Analyzed By LSP 7/1/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample M-TWP-05A **Lab Number** 2008-05575- 13 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	5-10%	-	-	-	-
Total %		100	Average %		70-80%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05B **Lab Number** 2008-05575- 14 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	5-10%	-	-	-	-
Total %		100	Average %		70-80%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05C **Lab Number** 2008-05575- 15 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	5-10%	-	-	-	-
Total %		100	Average %		70-80%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805575

Kyrene Centennial MS/Bldg D

Sample M-DST-13A **Lab Number** 2008-05575- 16 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-DST-13B **Lab Number** 2008-05575- 17 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-DST-13C **Lab Number** 2008-05575- 18 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;


D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 01-Jul-2008

Original Print Date: 01-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200805576

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 27 PLM **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Centennial MS/Bldg E

PO Number: 08-192

Report Date: 7/1/2008

Date Analyzed: 7/1/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Polutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805576

Kyrene Centennial MS/Bldg E

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-APL-01A Layer # 1 off-white ceiling tile	2008-05576- 1	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 off-white ceiling tile	2008-05576- 2	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 off-white ceiling tile	2008-05576- 3	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white texture/joint compound	2008-05576- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white texture/joint compound	2008-05576- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white texture/joint compound	2008-05576- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white drywall core	2008-05576- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white drywall core	2008-05576- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white drywall core	2008-05576- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white texture/joint compound	2008-05576- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white texture/joint compound	2008-05576- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white texture/joint compound	2008-05576- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-12A Layer # 1 White panel	2008-05576- 13	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-12B Layer # 1 White panel	2008-05576- 14	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-12C Layer # 1 White panel	2008-05576- 15	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-14A Layer # 1 White duct tape	2008-05576- 16	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-14B Layer # 1 White duct tape	2008-05576- 17	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-14C Layer # 1 White duct tape	2008-05576- 18	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-24A Layer # 1 off-white ceiling tile	2008-05576- 19	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-24B Layer # 1 off-white ceiling tile	2008-05576- 20	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-24C Layer # 1 off-white ceiling tile	2008-05576- 21	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-42A Layer # 1 Tan ceiling tile	2008-05576- 22	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-42B Layer # 1 Tan ceiling tile	2008-05576- 23	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-42C Layer # 1 Tan ceiling tile	2008-05576- 24	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-43A Layer # 1 Tan panel	2008-05576- 25	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-43B Layer # 1 Tan panel	2008-05576- 26	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-43C Layer # 1 Tan panel	2008-05576- 27	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805576

Kyrene Centennial MS/Bldg E

Sample M-APL-01A **Lab Number** 2008-05576- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05576- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05576- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805576

Kyrene Centennial MS/Bldg E

Sample S-SAT-02A **Lab Number** 2008-05576- 4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-05576- 5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-05576- 6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805576

Kyrene Centennial MS/Bldg E

Sample M-GWB-03A **Lab Number** 2008-05576-7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-05576-8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-05576-9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805576

Kyrene Centennial MS/Bldg E

Sample S-JTC-04A **Lab Number** 2008-05576- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-05576- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-05576- 12 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805576

Kyrene Centennial MS/Bldg E

Sample M-TWP-12A **Lab Number** 2008-05576- 13 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Essentially drywall core used as a panel.

Sample M-TWP-12B **Lab Number** 2008-05576- 14 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Essentially drywall core used as a panel.

Sample M-TWP-12C **Lab Number** 2008-05576- 15 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Essentially drywall core used as a panel.

PLM Analysis Details

Job Number: 200805576 Kyrene Centennial MS/Bldg E

Sample M-DST-14A **Lab Number** 2008-05576- 16 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-14B **Lab Number** 2008-05576- 17 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-14C **Lab Number** 2008-05576- 18 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805576 Kyrene Centennial MS/Bldg E

Sample M-APL-24A **Lab Number** 2008-05576- 19 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	10-20%	-	-	-	-
Total %		100	Average %		20-30%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y										
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24B **Lab Number** 2008-05576- 20 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	10-20%	-	-	-	-
Total %		100	Average %		20-30%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y										
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24C **Lab Number** 2008-05576- 21 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	10-20%	-	-	-	-
Total %		100	Average %		20-30%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y										
2	cellulose fiber	W	F	N	N	H	+	U						
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805576 Kyrene Centennial MS/Bldg E

Sample M-APL-42A **Lab Number** 2008-05576- 22 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder, metal

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-42B **Lab Number** 2008-05576- 23 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder, metal

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-42C **Lab Number** 2008-05576- 24 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder, metal

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805576 Kyrene Centennial MS/Bldg E

Sample M-TWP-43A **Lab Number** 2008-05576- 25 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-43B **Lab Number** 2008-05576- 26 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-43C **Lab Number** 2008-05576- 27 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper


Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon

yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 01-Jul-2008

Original Print Date: 01-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

Job Number: 200805577

Client: FM GROUP INC
15974 N 77TH ST
SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Centennial MS/Bldg F **PO Number:** 08-192
Report Date: 7/1/2008 **Date Analyzed:** 7/1/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-APL-01A Layer # 1 Tan ceiling tile	2008-05577- 1	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 Tan ceiling tile	2008-05577- 2	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 Tan ceiling tile	2008-05577- 3	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white texture/joint compound	2008-05577- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white texture/joint compound	2008-05577- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white texture/joint compound	2008-05577- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white drywall core	2008-05577- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white drywall core	2008-05577- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white drywall core	2008-05577- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white texture/joint compound	2008-05577- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white texture/joint compound	2008-05577- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white texture/joint compound	2008-05577- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05A Layer # 1 Tan panel	2008-05577- 13	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05B Layer # 1 Tan panel	2008-05577- 14	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05C Layer # 1 Tan panel	2008-05577- 15	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-21A Layer # 1 White duct tape	2008-05577- 16	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-21B Layer # 1 White duct tape	2008-05577- 17	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-21C Layer # 1 White duct tape	2008-05577- 18	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample M-APL-01A **Lab Number** 2008-05577- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05577- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05577- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample S-SAT-02A **Lab Number** 2008-05577- 4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-05577- 5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-05577- 6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample M-GWB-03A **Lab Number** 2008-05577- 7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2	W	F	N	N	H	+	U	cellulose fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-05577- 8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2	W	F	N	N	H	+	U	cellulose fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-05577- 9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2	W	F	N	N	H	+	U	cellulose fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample S-JTC-04A **Lab Number** 2008-05577- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-05577- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-05577- 12 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample M-TWP-05A **Lab Number** 2008-05577- 13 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	3	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05B **Lab Number** 2008-05577- 14 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	3	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05C **Lab Number** 2008-05577- 15 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	3	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805577

Kyrene Centennial MS/Bldg F

Sample M-DST-21A **Lab Number** 2008-05577- 16 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-21B **Lab Number** 2008-05577- 17 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-21C **Lab Number** 2008-05577- 18 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;


D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 01-Jul-2008

Original Print Date: 01-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200805578

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Centennial MS/Bldg G **PO Number:** 08-192
Report Date: 7/1/2008 **Date Analyzed:** 7/1/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of <= 1 % asbestos as "negative" and > 1 % asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain <= 1% asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Polutants, Nov. 1990) in order to rely on analytical results that are <= 1%. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but <= 1% as "borderline negative", and results where asbestos was > 1 % but <= 2% as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as <=1%. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805578

Kyrene Centennial MS/Bldg G

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color	Apparent Layer Type *	Asbestos Results	
Sample # M-APL-01A Layer # 1 Tan	2008-05578- 1	Ceiling Tile ceiling tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 Tan	2008-05578- 2	Ceiling Tile ceiling tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 Tan	2008-05578- 3	Ceiling Tile ceiling tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white	2008-05578- 4	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white	2008-05578- 5	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white	2008-05578- 6	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white	2008-05578- 7	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white	2008-05578- 8	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white	2008-05578- 9	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white	2008-05578- 10	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white	2008-05578- 11	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white	2008-05578- 12	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05A Layer # 1 Tan	2008-05578- 13	Miscellaneous panel <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05B Layer # 1 Tan	2008-05578- 14	Miscellaneous panel <i>no asbestos detected</i>	Positive Layer? No
Sample # M-TWP-05C Layer # 1 Tan	2008-05578- 15	Miscellaneous panel <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-14A Layer # 1 White	2008-05578- 16	Miscellaneous duct tape <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-14B Layer # 1 White	2008-05578- 17	Miscellaneous duct tape <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-14C Layer # 1 White	2008-05578- 18	Miscellaneous duct tape <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805578 Kyrene Centennial MS/Bldg G

Sample M-APL-01A **Lab Number** 2008-05578- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2	CL	D	Y										
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05578- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2	CL	D	Y										
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05578- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2	CL	D	Y										
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805578

Kyrene Centennial MS/Bldg G

Sample S-SAT-02A **Lab Number** 2008-05578- 4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-05578- 5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-05578- 6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805578

Kyrene Centennial MS/Bldg G

Sample M-GWB-03A **Lab Number** 2008-05578- 7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-05578- 8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-05578- 9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200805578 Kyrene Centennial MS/Bldg G

Sample S-JTC-04A **Lab Number** 2008-05578- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-05578- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-05578- 12 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805578

Kyrene Centennial MS/Bldg G

Sample M-TWP-05A **Lab Number** 2008-05578- 13 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	3	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05B **Lab Number** 2008-05578- 14 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	3	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-05C **Lab Number** 2008-05578- 15 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	3	80-90%	2-5%	-	-	-	-
Total %		100	Average %		80-90%	2-5%	-	-	-	-
Fiber Identification:					cellulose fiber	synthetic fiber (extr)				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	synthetic fiber (extruded)	W	E	N	N	H	+	P					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805578

Kyrene Centennial MS/Bldg G

Sample M-DST-14A **Lab Number** 2008-05578- 16 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-14B **Lab Number** 2008-05578- 17 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.


Sample M-DST-14C **Lab Number** 2008-05578- 18 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	80-90%	-	-	-	-	-
Total %		100	Average %		80-90%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 01-Jul-2008

Original Print Date: 01-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200805579

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 11 PLM **Rec:** 6/16/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Centennial MS/Bldg H **PO Number:** 08-192
Report Date: 7/1/2008 **Date Analyzed:** 7/1/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphoto-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200805579

Kyrene Centennial MS/Bldg H

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-05579- 1	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-05579- 2	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-05579- 3	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-DST-20A	2008-05579- 4	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-20B	2008-05579- 5	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-20C	2008-05579- 6	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	S-SAF-42A	2008-05579- 7	Sprayed Material	Positive Layer? No
Layer # 1	Gray	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-42B	2008-05579- 8	Sprayed Material	Positive Layer? No
Layer # 1	Gray	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-42C	2008-05579- 9	Sprayed Material	Positive Layer? No
Layer # 1	Gray	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-42D	2008-05579- 10	Sprayed Material	Positive Layer? No
Layer # 1	Gray	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-42E	2008-05579- 11	Sprayed Material	Positive Layer? No
Layer # 1	Gray	fireproofing	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200805579

Kyrene Centennial MS/Bldg H

Sample M-APL-01A **Lab Number** 2008-05579- 1 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-05579- 2 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-05579- 3 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200805579

Kyrene Centennial MS/Bldg H

Sample M-DST-20A **Lab Number** 2008-05579-4 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	2	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-20B **Lab Number** 2008-05579-5 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	2	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-20C **Lab Number** 2008-05579-6 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	2	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200805579

Kyrene Centennial MS/Bldg H

Sample S-SAF-42A **Lab Number** 2008-05579- 7 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-42B **Lab Number** 2008-05579- 8 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-42C **Lab Number** 2008-05579- 9 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200805579

Kyrene Centennial MS/Bldg H

Sample S-SAF-42D **Lab Number** 2008-05579- 10 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Sprayed Material Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.


Sample S-SAF-42E **Lab Number** 2008-05579- 11 **Sampled:** 6/13/2008 **Condition:** acceptable
Analyzed By LSP 7/1/2008 **An?** OK **Apparent Smp Type** Sprayed Material Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 01-Jul-2008

Original Print Date: 01-Jul-2008



Larry S. Pierce, Approved Accreditation Signatory


APPENDIX C

Building Inspectors' Signature Sheet

APPENDIX D

Personnel and Laboratory Accreditations

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHRA Refresher
Building Inspector
January 4, 2008**

and successfully passed the competency exam

Date of Examination: **January 4, 2008**

Date of Expiration: **January 4, 2009**

[Signature]
 Director

[Signature]
 Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE

Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector**

May 2, 2008

and successfully passed the competency exam.

Date of Examination: **May 2, 2008**



Date of Expiration: **May 2, 2009**



Director



Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12124

THE ASBESTOS INSTITUTE

Certifies that

Paul Michael Massey

has attended the BPA approved course

**AHERA
Building Inspector
April 7-9, 2008**

and successfully passed the competency exam



Date of Examination: **April 9, 2008**

Date of Expiration: **April 9, 2009**



Director

Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12516

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

and successfully passed the competency exam

Date of Examination: **May 30, 2008**


Date of Expiration: **May 30, 2009**

[Signature]
 Director


[Signature]
 Approved Instructor

THE ASBESTOS INSTITUTE
 8102 North 23rd Avenue
 Suite A

Phoenix, AZ 85021-4962
 602-864-6564



United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:1999

NVLAP LAB CODE: 101031-0

Fiberquant, Inc.
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in
NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS

2007-07-01 through 2008-06-30

Effective dates



Dolly S. Bruce
For the National Institute of Standards and Technology

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the ten buildings comprising the Kyrene Centennial Middle School (KCMS) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of June 9, 2008 through June 13, 2008. A total of 149 bulk-material samples were collected from 433 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Three Hundred Eighty-six building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos Containing Building Material

The identified ACBM within the ten buildings at KCMS are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

1.3 Asbestos-Containing Building Materials

(Table "C" has been moved to Section 6 of the Management Plan.)

1.4 ACBM/Location Plans

(Drawings have been moved to Section 6 of the Management Plan.)

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the ten buildings at KCMS during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the ten buildings at KCMS during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the ten buildings at KCMS, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the ten buildings at the KCMS campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the ten buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 24, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 13808 South 36th Street in Phoenix, Arizona and consists of ten buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the 10 buildings.

At the request of KSD, select identified suspect ACM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of June 9, 2008 through June 13, 2008, by Michael Coleman and Paul Massey, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

2.2 Description of Construction

2.2.1 Buildings A, B, C, D, E, F, G and H

The construction date of Buildings A, B, C, D, E, F, G and H is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support concrete, wooden or metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes, stucco and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Ramada

The construction date the Ramada is unknown. The construction appears to be consistent and uniform throughout.

The structure is built with a slab on-grade foundation. Perimeter load bearing columns are of concrete masonry systems and support a metal roofing system.

2.2.3 Storage Building

The construction date of the Storage Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter load bearing walls are of concrete masonry systems and support a metal roofing system.

2.3 AHERA Inspection Procedures and Protocols

2.3.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.3.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step by step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.4 Visual Inspection

A visual inspection of the ten buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

2.5 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **NINETEEN** friable suspect ACBM (acoustical ceiling panels, duct seam tape and spray-applied fireproofing) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.6 Sample Collection

Convenience sampling was performed on select identified suspect ACBM, except for the spray-applied fireproofing, which was random sampled. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
A	42 (35 Assumed)	21
B	52 (46 Assumed)	18
C	57 (51 Assumed)	18
D	49 (43 Assumed)	18
E	82 (73 Assumed)	27
F	41 (35 Assumed)	18
G	45 (39 Assumed)	18
H	55 (52 Assumed)	11
Ramada	5 (5 Assumed)	0
Storage	5 (5 Assumed)	0
TOTAL	433	149

2.7 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

END OF REPORT

SECTION 3

DESIGNATED PERSON IDENTIFICATION

AHERA Designated Person
796.93(e)(4)

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: KYRENE CENTENNIAL MIDDLE SCHOOL

Address: 13808 SOUTH 36TH STREET
PHOENIX, ARIZONA 85044

LEA Designated Person

Print Name: Giacomo Musella, Facilities Supervisor

Address: 8700 South Kyrene Road
Tempe, Arizona 85284-2197

Phone: 480.783-4200

Training Course Name: AHERA Building Inspector Refresher

Dates of Training: October 5, 2008 **Hours of Training:** 4

Training Course Name: AHERA Management Planner Refresher

Dates of Training: October 5, 2008 **Hours of Training:** 4

Training Course Name: _____

Dates of Training: _____ **Hours of Training:** _____

Signature

Date

D 10910

THE ASBESTOS INSTITUTE

Certifies that

Giacomo Jack Musella

has attended the EPA approved course

**AHERA Refresher
Building Inspector
October 5, 2007**

and successfully passed the competency exam.

COPY

Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE
8102 North 23rd Avenue
Suite A
Phoenix, AZ 85021-4962
602-864-6564


This training meets all requirements for asbestos recertification under TSCA Title II.

D 10936

THE ASBESTOS INSTITUTE

Certifies that
Giacomo Jack Musella

has attended the EPA approved course
**AHERA Refresher
Management Planner
October 5, 2007**
and successfully passed the competency exam.



Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**

Director

Approved Instructor

THE ASBESTOS INSTITUTE
8102 North 23rd Avenue
Suite A
Phoenix, AZ 85021-4962
602-864-6564

This training meets all requirements for asbestos accreditation under TSCA Title II.

SECTION 4

RESPONSE ACTION(S)

THERE ARE NO RESPONSE ACTIONS REQUIRED AT THIS FACILITY.

SECTION 5

ACCREDITATION STATEMENTS

**Assurance of Accreditation
Under this Management Plan
763.93(e)(7)**

Inspector(s):

Name: MICHAEL COLEMAN
State of Accreditation or EPA: EPA
Accreditation Date(s): MAY 2, 2009
Accreditation Number(s): D 12287

Name: PAUL MASSEY
State of Accreditation or EPA: EPA
Accreditation Date(s): APRIL 9, 2009
Accreditation Number(s): D 12124

Name: CLIFF ROLLE
State of Accreditation or EPA: EPA
Accreditation Date(s): MAY 30, 2009
Accreditation Number(s): D 12516

Management Planner:

Name: PAUL ANGER
State of Accreditation or EPA: EPA
Accreditation Date(s): JANUARY 4, 2008
Accreditation Number(s): D 11466

Any Project Designer, Contractor/Supervisor or Worker who performs work on response actions under this Management Plan shall be accredited by either an EPA approved state contractor accreditation plan or an EPA approved course under Section 206(b) to Title II of the Toxic Substance Control Act.

D 12287

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector**

May 2, 2008

and successfully passed the competency exam



Date of Examination: **May 2, 2008**

Date of Expiration: **May 2, 2009**

[Signature]
 Director

Director

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12124

THE ASBESTOS INSTITUTE

Certifies that

Paul Michael Massey

has attended the EPA approved course

**AHERA
Building Inspector
April 7-9, 2008**

and successfully passed the competency exam



Date of Examination: **April 9, 2008**

Date of Expiration: **April 9, 2009**



Director

Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12516

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector
May 30, 2008**

and successfully passed the competency exam


Date of Examination: **May 30, 2008**

Date of Expiration: **May 30, 2009**

Cliff Rolle
Director

Director

Cliff Rolle
Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 11466

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

AHERA Refresher Management Planner January 4, 2008.

and successfully passed the competency exam.

Date of Examination: January 4, 2008

Date of Expiration: January 4, 2009

[Signature]

Director

[Signature]

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564