

# **ASBESTOS MANAGEMENT PLAN**



**at**

**Kyrene Del Cielo Elementary School**

**Prepared for:**

**Kyrene School District No. 28**

**VOLUME I OF II**

**FM GROUP INC  
FM Project 07-326**

**October 2007**

# **ASBESTOS MANAGEMENT PLAN**

**Kyrene Del Cielo Elementary School**

**October 2007**

**FM GROUP INC**

**FM Project 07-326**

## TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY .....	1-1
2	INSPECTION REPORT .....	2-1
3	DESIGNATED PERSON IDENTIFICATION .....	3-1
4	RESPONSE ACTION .....	4-1
5	ACCREDITATION STATEMENTS .....	5-1
6	REMAINING ACBM .....	6-1
7	O&M PROGRAM .....	7-1
8	INITIAL NOTIFICATIONS .....	8-1
9	COST ESTIMATION .....	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON .....	10-1
11	ANNUAL NOTIFICATIONS .....	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT .....	12-1

### APPENDIX A: ONGOING RECORDKEEPING

**SECTION 1**

**GENERAL INVENTORY**

---

**Asbestos Management Plan**  
 Kyrene Del Cielo Elementary School, KSD  
 FM Project 07-326

**General Inventory**  
 763.93(e)(1)

**Date:** OCTOBER 5, 2007

**Owner:** KYRENE SCHOOL DISTRICT NO. 28

**Address:** 8700 SOUTH KYRENE ROAD  
TEMPE, ARIZONA 85284-2197

**Property:** KYRENE DEL CIELO ELEMENTARY SCHOOL

**Address:** 1350 NORTH LAKESHORE DRIVE  
CHANDLER, ARIZONA 85226

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
Main	N/A	X	X
Cafeteria	N/A	X	X
Portable D1/D2	N/A	X	X
Portable M1/M2	N/A	X	X
Portable M3/M4	N/A	X	X
Portable R1/R2	N/A	X	X
Portable R3/R4	N/A	X	X
Portable T1/T2	N/A	X	X
Portable T3/T4	N/A	X	X

**SECTION 2**

**INSPECTION REPORT**

---

**Asbestos Management Plan**  
*Kyrene Del Cielo Elementary School, KSD*  
*FM Project 07-326*

## **INSPECTION REPORT**

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:

Report of Findings  
Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School

Prepared by: FM GROUP INC  
Project No.: 07-326  
Date: October 2007

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28  
8700 South Kyrene Road  
Tempe, Arizona 85284-2197

**REPORT OF FINDINGS**  
*(Abridged Version)*



**Comprehensive AHERA Asbestos Inspection**

**at**

**Kyrene Del Cielo Elementary School**

**Prepared for:**

**Kyrene School District No. 28**

**FM GROUP INC**  
**FM Project 07-326**

**October 2007**



TABLE OF CONTENTS

**Report of Findings**  
Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Kyrene School District No. 28

FM GROUP Project 07-326

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u> .....	1
1.1 Summary .....	1
1.2 Identified Asbestos-Containing Materials .....	1
1.3 Asbestos-Containing Building Materials (Table C) .....	2
1.4 ACBM/Location Plans .....	3
1.5 Critical Situations .....	4
1.6 Friable Asbestos-Containing Building Materials .....	4
1.7 Material Assessments .....	4
1.8 Recommendations .....	4
1.9 Qualifications of the Report.....	4
2.0 <u>PROJECT INFORMATION</u> .....	5
2.1 Background.....	5
2.2 Description of Construction .....	5
2.2.1 Main Building .....	5
2.2.2 Cafeteria Building .....	6
2.2.3 Portables D1/D2, M1/M2, M3/M4, R1/R2, R3/R4, T1/T2 and T3/T4 .....	6
2.3 Building Materials/Systems List (Table A) .....	8
2.3.1 Main Building.....	9
2.3.2 Cafeteria Building .....	53
2.3.3 Portable D1/D2.....	66
2.3.4 Portable M1/M2 .....	69
2.3.5 Portable M3/M4 .....	71
2.3.6 Portable R1/R2.....	74
2.3.7 Portable R3/R4.....	77
2.3.8 Portable T1/T2 .....	80
2.3.9 Portable T3/T4 .....	82
2.4 AHERA Inspection Procedures and Protocols.....	84
2.4.1 Inspection Procedures and Protocols .....	84
2.4.2 FM GROUP INC Inspection SOP .....	84
2.5 Visual Inspection.....	84
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B) ..	85
2.6.1 Main Building .....	86
2.6.2 Cafeteria Building .....	89
2.6.3 Portable D1/D2.....	91
2.6.4 Portable M1/M2 .....	93
2.6.5 Portable M3/M4 .....	94
2.6.6 Portable R1/R2.....	96

**Table of Contents**  
*Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School, KSD*  
*FM Project 07-326*

<u>Section</u>	<u>Page</u>
2.6.7 Portable R3/R4.....	98
2.6.8 Portable T1/T2 .....	100
2.6.9 Portable T3/T4 .....	101
2.7 Physical Assessments .....	102
2.8 Sample Collection .....	102
2.9 Material Bulk Sample Analysis .....	103

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none"><li>• Chain-of-Custody</li><li>• Laboratory Analysis</li></ul>
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

*ENV\KSD\07-326 Cielo Elm AHERA\2.0\2.3\2.3.1\TOC.doc*

**1.0 SURVEY RESULTS AND RECOMMENDATIONS**

**1.1 Summary**

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the nine buildings comprising the Kyrene Del Cielo Elementary School (KDCES) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period September 4, 2007 through September 7, 2007. A total of 153 bulk-material samples were collected from 315 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency's (EPA), AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Two hundred sixty-four building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

**1.2 Identified Asbestos-Containing Building Materials**

The identified ACBM within the nine buildings at KDCES are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

**Asbestos Material-Bulk Samples Collected**

<i>Building</i>	<i>No. of Samples</i>	<i>No. HA</i>	<i>No. Assumed</i>	<i>Total No. ACM</i>
Main Building	75	67	42	42
Cafeteria	57	52	33	33
Portable D1/D2	3	29	28	28
Portable M1/M2	3	27	26	26
Portable M3/M4	3	29	28	28
Portable R1/R2	3	33	32	32
Portable R3/R4	3	36	35	35
Portable T1/T2	3	21	20	20
Portable T3/T4	3	21	20	20

**1.3 Asbestos-Containing Building Materials**

**TABLE C**  
**ASBESTOS CONTAINING BUILDING MATERIALS**

**MAIN BUILDING**  
**CAFETERIA BUILDING**  
**PORTABLE D1/D2**  
**PORTABLE M1/M2**  
**PORTABLE M3/M4**  
**PORTABLE R1/R2**  
**PORTABLE R3/R4**  
**PORTABLE T1/T2**  
**PORTABLE T3/T4**

***TABLE C HAS BEEN MOVED TO***  
***SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

**1.4 ACBM/Location Plans**

**MAIN BUILDING  
CAFETERIA BUILDING  
PORTABLE D1/D2  
PORTABLE M1/M2  
PORTABLE M3/M4  
PORTABLE R1/R2  
PORTABLE R3/R4  
PORTABLE T1/T2  
PORTABLE T3/T4**

***ACBM/LOCATION PLANS HAVE BEEN MOVED TO  
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

## **1.5 Critical Situations**

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the nine buildings at KDCES during this inspection.**

## **1.6 Friable Asbestos-Containing Building Materials**

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the nine buildings at KDCES during this inspection.**

## **1.7 Material Assessments**

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** was identified in the nine buildings at KDCES, **NO** formal assessments are included in this report.

## **1.8 Recommendations**

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

## **1.9 Qualifications of Report**

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

## **2.0 PROJECT INFORMATION**

### **2.1 Background**

KSD intends to determine if there are any ACBM associated with the nine buildings at the KDCES campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the nine buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM Proposal P6-349, dated June 29, 2006, as evidenced by the issuance of KSD Purchase Order No. 800475, dated July 17, 2007. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 1350 North Lakeshore Drive, in Chandler, Arizona and consists of nine buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the nine buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period September 4, 2007 through September 7, 2007, by Michael Coleman and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

*Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.*

### **2.2 Description of Construction**

#### **2.2.1 Main Building**

The construction date of the Main Building is estimated to be unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support wooden and metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes, fiberglass reinforced paneling and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building, corridors and miscellaneous interior rooms.

Mechanical equipment for the building consists of roof-mounted air handler units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

### **2.2.2 Cafeteria Building**

The construction date of the Cafeteria Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support wooden and metal truss and deck systems finished with an asphalt prepared roofing system.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes, fiberglass reinforced paneling and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes, acoustical ceiling tiles and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building and miscellaneous interior rooms.

Mechanical equipment for the building consists of roof-mounted air handler units and ground level chiller components. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.



### **2.2.3 Portables D1/D2, M1/M2, M3/M4, R1/R2, R3/R4, T1/T2 and T3/T4**

The construction date of Portables D1/D2, M1/M2, M3/M4, R1/R2, R3/R4, T1/T2 and T3/T4 is unknown. The construction appears to be consistent and uniform throughout each Portable.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: carpet, vinyl composition tile and vinyl sheet flooring.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal) or tackable wall panels. Restroom walls finishes include gypsum wallboard systems with textured, painted finishes and fiberglass reinforced panels (D1/D2, M1/M2, M3/M4, R1/R2 and R3/R4). Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes or acoustical ceiling tile.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the gypsum wallboard or suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

*A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.*

**2.3 Building Materials/Systems List**

**TABLE A**  
**BUILDING MATERIAL SYSTEMS**

- MAIN BUILDING**
- CAFETERIA BUILDING**
- PORTABLE D1/D2**
- PORTABLE M1/M2**
- PORTABLE M3/M4**
- PORTABLE R1/R2**
- PORTABLE R3/R4**
- PORTABLE T1/T2**
- PORTABLE T3/T4**

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION, CEILING THROUGHOUT	S
	HALLWAY 1, CEILING THROUGHOUT	
	NURSE OFFICE, CEILING THROUGHOUT	
	NURSE RESTROOM, CEILING THROUGHOUT	
	TREATMENT ROOM, CEILING THROUGHOUT	
	HALLWAY 2, CEILING THROUGHOUT	
	PRINCIPAL, CEILING THROUGHOUT	
	FOYER, CEILING THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, CEILING THROUGHOUT	
	ASSISTANT PRINCIPAL, CEILING THROUGHOUT	
	LOUNGE, CEILING THROUGHOUT	
	WORKROOM 1, CEILING THROUGHOUT	
	STORAGE 1, CEILING THROUGHOUT	
	CORRIDOR 1, CEILING THROUGHOUT	
	CORRIDOR 2, CEILING THROUGHOUT	
	CORRIDOR 3, CEILING THROUGHOUT	
	CORRIDOR 4, CEILING THROUGHOUT	
	SPEECH ROOM, CEILING THROUGHOUT	
	CONFERENCE ROOM, CEILING THROUGHOUT	
	COMPUTER ROOM 401, CEILING THROUGHOUT	
	RESOURCE ROOM 402, CEILING THROUGHOUT	
	RESOURCE ROOM 403, CEILING THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, CEILING THROUGHOUT	
	GIFTED CLASSROOM 405, CEILING THROUGHOUT	
	K-3, CEILING THROUGHOUT	
	MEDIA CENTER, PORTION OF CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CONFERENCE ROOM 412, CEILING THROUGHOUT	
	WORKROOM 2, CEILING THROUGHOUT	
	BREAK-OUT 1, CEILING THROUGHOUT	
	BREAK-OUT 2, CEILING THROUGHOUT	
	STORAGE 2, CEILING THROUGHOUT	
	CLASSROOM 1 A1, CEILING THROUGHOUT	
	CLASSROOM 2 A12, CEILING THROUGHOUT	
	CLASSROOM 3 A2, CEILING THROUGHOUT	
	CLASSROOM 4 A11, CEILING THROUGHOUT	
	NORTH A FOYER, CEILING THROUGHOUT	
	CLASSROOM 5 A3, CEILING THROUGHOUT	
	CLASSROOM 6 A10, CEILING THROUGHOUT	
	CLASSROOM 7 A4, CEILING THROUGHOUT	
	CLASSROOM 8 A9, CEILING THROUGHOUT	
	SOUTH A FOYER, CEILING THROUGHOUT	
	KINDERGARTEN 1 A5, PORTION OF CEILING	
	KINDERGARTEN 2 A8, PORTION OF CEILING	
	CLASSROOM 1 B1, CEILING THROUGHOUT	
	CLASSROOM 2 B9, CEILING THROUGHOUT	
	CLASSROOM 3 B2, CEILING THROUGHOUT	
	CLASSROOM 4 B8, CEILING THROUGHOUT	
	NORTH B FOYER, CEILING THROUGHOUT	
	CLASSROOM 5 B3, CEILING THROUGHOUT	
	CLASSROOM 6 B7, CEILING THROUGHOUT	
	CLASSROOM 7 B4, CEILING THROUGHOUT	
	ART ROOM B6, CEILING THROUGHOUT	
	SOUTH B FOYER, CEILING THROUGHOUT	
	C1, CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	C2, CEILING THROUGHOUT	
	C3, CEILING THROUGHOUT	
	C4, CEILING THROUGHOUT	
	C FOYER, CEILING THROUGHOUT	
	C ART ROOM, CEILING THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY	HALLWAY 1, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS	S
	TREATMENT ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	HALLWAY 2, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	PSYCHOLOGIST OFFICE CLOSET, WALLS THROUGHOUT	
	FOYER, NORTH, EAST AND WEST WALLS, NORTH PLENUM WALL ABOVE CEILING	
	CORRIDOR 1, WALLS THROUGHOUT	
	CORRIDOR 2, WALLS THROUGHOUT	
	CORRIDOR 3, WALLS THROUGHOUT	
	CORRIDOR 4, WALLS THROUGHOUT	
	CLASSROOM 1 A1, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 2 A12, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 3 A2, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 4 A11, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	NORTH A FOYER, WALLS THROUGHOUT	
	CLASSROOM 5 A3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 6 A10, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 7 A4, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 8 A9, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	SOUTH A FOYER, WALLS THROUGHOUT	
	KINDERGARTEN 1 A5, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS, EAST PLENUM WALL ABOVE CEILING	
	KINDERGARTEN 2 A8, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
	CLASSROOM 1 B1, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 2 B9, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, WEST PLENUM WALL ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 3 B2, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	CLASSROOM 4 B8, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	NORTH B FOYER, WALLS THROUGHOUT	
	CLASSROOM 5 B3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 6 B7, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	CLASSROOM 7 B4, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	ART ROOM B6, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	SOUTH B FOYER, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	HALLWAY 1, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS	S
	TREATMENT ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	HALLWAY 2, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	PSYCHOLOGIST OFFICE CLOSET, WALLS THROUGHOUT	
	FOYER, NORTH, EAST AND WEST WALLS, NORTH PLENUM WALL ABOVE CEILING	
	CORRIDOR 1, WALLS THROUGHOUT	
	CORRIDOR 2, WALLS THROUGHOUT	
	CORRIDOR 3, WALLS THROUGHOUT	
	CORRIDOR 4, WALLS THROUGHOUT	
	CLASSROOM 1 A1, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 2 A12, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 3 A2, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 4 A11, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	NORTH A FOYER, WALLS THROUGHOUT	
	CLASSROOM 5 A3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 6 A10, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 7 A4, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	CLASSROOM 8 A9, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	SOUTH A FOYER, WALLS THROUGHOUT	
	KINDERGARTEN 1 A5, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS, EAST PLENUM WALL ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	KINDERGARTEN 2 A8, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
	CLASSROOM 1 B1, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 2 B9, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	CLASSROOM 3 B2, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	CLASSROOM 4 B8, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	NORTH B FOYER, WALLS THROUGHOUT	
	CLASSROOM 5 B3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	CLASSROOM 6 B7, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	CLASSROOM 7 B4, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	ART ROOM B6, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, WEST PLENUM WALL ABOVE CEILING	
	SOUTH B FOYER, WALLS THROUGHOUT	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	RECEPTION, BASE OF WALLS THROUGHOUT	S
	HALLWAY 1, BASE OF WALLS THROUGHOUT	
	NURSE OFFICE, BASE OF WALLS THROUGHOUT	
	TREATMENT ROOM, BASE OF WALLS THROUGHOUT	
	HALLWAY 2, BASE OF WALLS THROUGHOUT	
	PRINCIPAL, BASE OF WALLS THROUGHOUT	
	PRINCIPAL CLOSET, BASE OF WALLS THROUGHOUT	
	FOYER, BASE OF WALLS THROUGHOUT	
	PSYCHOLOGIST OFFICE, BASE OF WALLS THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, BASE OF WALLS THROUGHOUT	
	ASSISTANT PRINCIPAL, BASE OF WALLS THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, BASE OF WALLS THROUGHOUT	
	LOUNGE, BASE OF WALLS THROUGHOUT	
	WORKROOM 1, BASE OF WALLS THROUGHOUT	
	PHONE ROOM, BASE OF WALLS THROUGHOUT	
	STORAGE 1, BASE OF WALLS THROUGHOUT	
	CORRIDOR 1, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CORRIDOR 2, BASE OF WALLS THROUGHOUT	
	CORRIDOR 3, BASE OF WALLS THROUGHOUT	
	CORRIDOR 4, BASE OF WALLS THROUGHOUT	
	SPEECH ROOM, BASE OF WALLS THROUGHOUT	
	COMPUTER ROOM 401, BASE OF WALLS THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, BASE OF WALLS THROUGHOUT	
	404 CLOSET, BASE OF WALLS THROUGHOUT	
	GIFTED CLASSROOM 405, BASE OF WALLS THROUGHOUT	
	MEDIA CENTER, BASE OF WALLS THROUGHOUT	
	CONFERENCE ROOM 412, BASE OF WALLS THROUGHOUT	
	WORKROOM 2, BASE OF WALLS THROUGHOUT	
	ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
	BREAK-OUT 1, BASE OF WALLS THROUGHOUT	
	BREAK-OUT 2, BASE OF WALLS THROUGHOUT	
	STORAGE 2, BASE OF WALLS THROUGHOUT	
	CLASSROOM 1 A1, BASE OF WALLS THROUGHOUT	
	CLASSROOM 2 A12, BASE OF WALLS THROUGHOUT	
	CLASSROOM 3 A2, BASE OF WALLS THROUGHOUT	
	CLASSROOM 4 A11, BASE OF WALLS THROUGHOUT	
	NORTH A FOYER, BASE OF WALLS THROUGHOUT	
	CLASSROOM 5 A3, BASE OF WALLS THROUGHOUT	
	CLASSROOM 6 A10, BASE OF WALLS THROUGHOUT	
	CLASSROOM 7 A4, BASE OF WALLS THROUGHOUT	
	CLASSROOM 8 A9, BASE OF WALLS THROUGHOUT	
	SOUTH A FOYER, BASE OF WALLS THROUGHOUT	
	KINDERGARTEN 1 A5, BASE OF WALLS THROUGHOUT	
	KINDERGARTEN 2 A8, BASE OF WALLS THROUGHOUT	
	CLASSROOM 1 B1, BASE OF WALLS THROUGHOUT	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 2 B9, BASE OF WALLS THROUGHOUT	
	CLASSROOM 3 B2, BASE OF WALLS THROUGHOUT	
	CLASSROOM 4 B8, BASE OF WALLS THROUGHOUT	
	NORTH B FOYER, BASE OF WALLS THROUGHOUT	
	CLASSROOM 5 B3, BASE OF WALLS THROUGHOUT	
	CLASSROOM 6 B7, BASE OF SOUTH WALL	
	CLASSROOM 7 B4, BASE OF WALLS THROUGHOUT	
	ART ROOM B6, BASE OF NORTH WALL	
	SOUTH B FOYER, BASE OF WALLS THROUGHOUT	
	C1, BASE OF WALLS THROUGHOUT	
	C2, BASE OF WALLS THROUGHOUT	
	C3, BASE OF WALLS THROUGHOUT	
	C4, BASE OF WALLS THROUGHOUT	
	C FOYER, BASE OF WALLS THROUGHOUT	
	C ART ROOM, BASE OF WALLS THROUGHOUT	
	STORAGE, BASE OF WALLS THROUGHOUT	
	FIRE RISER, BASE OF WALLS THROUGHOUT	
	C ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	RECEPTION, BASE OF WALLS THROUGHOUT	S
	HALLWAY 1, BASE OF WALLS THROUGHOUT	
	NURSE OFFICE, BASE OF WALLS THROUGHOUT	
	TREATMENT ROOM, BASE OF WALLS THROUGHOUT	
	HALLWAY 2, BASE OF WALLS THROUGHOUT	
	PRINCIPAL, BASE OF WALLS THROUGHOUT	
	PRINCIPAL CLOSET, BASE OF WALLS THROUGHOUT	
	FOYER, BASE OF WALLS THROUGHOUT	
	PSYCHOLOGIST OFFICE, BASE OF WALLS THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ASSISTANT PRINCIPAL, BASE OF WALLS THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, BASE OF WALLS THROUGHOUT	
	LOUNGE, BASE OF WALLS THROUGHOUT	
	WORKROOM 1, BASE OF WALLS THROUGHOUT	
	PHONE ROOM, BASE OF WALLS THROUGHOUT	
	STORAGE 1, BASE OF WALLS THROUGHOUT	
	CORRIDOR 1, BASE OF WALLS THROUGHOUT	
	CORRIDOR 2, BASE OF WALLS THROUGHOUT	
	CORRIDOR 3, BASE OF WALLS THROUGHOUT	
	CORRIDOR 4, BASE OF WALLS THROUGHOUT	
	SPEECH ROOM, BASE OF WALLS THROUGHOUT	
	COMPUTER ROOM 401, BASE OF WALLS THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, BASE OF WALLS THROUGHOUT	
	404 CLOSET, BASE OF WALLS THROUGHOUT	
	GIFTED CLASSROOM 405, BASE OF WALLS THROUGHOUT	
	MEDIA CENTER, BASE OF WALLS THROUGHOUT	
	CONFERENCE ROOM 412, BASE OF WALLS THROUGHOUT	
	WORKROOM 2, BASE OF WALLS THROUGHOUT	
	ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
	BREAK-OUT 1, BASE OF WALLS THROUGHOUT	
	BREAK-OUT 2, BASE OF WALLS THROUGHOUT	
	STORAGE 2, BASE OF WALLS THROUGHOUT	
	CLASSROOM 1 A1, BASE OF WALLS THROUGHOUT	
	CLASSROOM 2 A12, BASE OF WALLS THROUGHOUT	
	CLASSROOM 3 A2, BASE OF WALLS THROUGHOUT	
	CLASSROOM 4 A11, BASE OF WALLS THROUGHOUT	
	NORTH A FOYER, BASE OF WALLS THROUGHOUT	
	CLASSROOM 5 A3, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CLASSROOM 6 A10, BASE OF WALLS THROUGHOUT	
	CLASSROOM 7 A4, BASE OF WALLS THROUGHOUT	
	CLASSROOM 8 A9, BASE OF WALLS THROUGHOUT	
	SOUTH A FOYER, BASE OF WALLS THROUGHOUT	
	KINDERGARTEN 1 A5, BASE OF WALLS THROUGHOUT	
	KINDERGARTEN 2 A8, BASE OF WALLS THROUGHOUT	
	CLASSROOM 1 B1, BASE OF WALLS THROUGHOUT	
	CLASSROOM 2 B9, BASE OF WALLS THROUGHOUT	
	CLASSROOM 3 B2, BASE OF WALLS THROUGHOUT	
	CLASSROOM 4 B8, BASE OF WALLS THROUGHOUT	
	NORTH B FOYER, BASE OF WALLS THROUGHOUT	
	CLASSROOM 5 B3, BASE OF WALLS THROUGHOUT	
	CLASSROOM 6 B7, BASE OF SOUTH WALL	
	CLASSROOM 7 B4, BASE OF WALLS THROUGHOUT	
	ART ROOM B6, BASE OF NORTH WALL	
	SOUTH B FOYER, BASE OF WALLS THROUGHOUT	
	C1, BASE OF WALLS THROUGHOUT	
	C2, BASE OF WALLS THROUGHOUT	
	C3, BASE OF WALLS THROUGHOUT	
	C4, BASE OF WALLS THROUGHOUT	
	C FOYER, BASE OF WALLS THROUGHOUT	
	C ART ROOM, BASE OF WALLS THROUGHOUT	
	STORAGE, BASE OF WALLS THROUGHOUT	
	FIRE RISER, BASE OF WALLS THROUGHOUT	
	C ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	RECEPTION, FLOOR THROUGHOUT	S
	HALLWAY 1, FLOOR THROUGHOUT	
	NURSE OFFICE, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	TREATMENT ROOM, FLOOR THROUGHOUT	
	HALLWAY 2, FLOOR THROUGHOUT	
	PRINCIPAL, FLOOR THROUGHOUT	
	PRINCIPAL CLOSET, FLOOR THROUGHOUT	
	FOYER, FLOOR THROUGHOUT	
	PSYCHOLOGIST OFFICE, FLOOR THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, FLOOR THROUGHOUT	
	ASSISTANT PRINCIPAL, FLOOR THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, FLOOR THROUGHOUT	
	LOUNGE, FLOOR THROUGHOUT	
	WORKROOM 1, FLOOR THROUGHOUT	
	PHONE ROOM, FLOOR THROUGHOUT	
	STORAGE 1, FLOOR THROUGHOUT	
	CORRIDOR 1, FLOOR THROUGHOUT	
	CORRIDOR 2, FLOOR THROUGHOUT	
	CORRIDOR 3, FLOOR THROUGHOUT	
	CORRIDOR 4, FLOOR THROUGHOUT	
	SPEECH ROOM, FLOOR THROUGHOUT	
	CONFERENCE ROOM, FLOOR THROUGHOUT	
	COMPUTER ROOM 401, FLOOR THROUGHOUT LESS ENTRY	
	RESOURCE ROOM 402, FLOOR THROUGHOUT	
	RESOURCE ROOM 403, FLOOR THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, FLOOR THROUGHOUT	
	404 CLOSET, FLOOR THROUGHOUT	
	GIFTED CLASSROOM 405, FLOOR THROUGHOUT	
	K-3, FLOOR THROUGHOUT	
	MEDIA CENTER, FLOOR THROUGHOUT	
	CONFERENCE ROOM 412, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	BREAK-OUT 1, FLOOR THROUGHOUT	
	BREAK-OUT 2, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	CLASSROOM 1 A1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 2 A12, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 3 A2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 4 A11, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 5 A3, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 6 A10, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 7 A4, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 8 A9, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	KINDERGARTEN 1 A5, FLOOR THROUGHOUT LESS WET AREA AND NORTH ENTRIES	
	KINDERGARTEN 2 A8, FLOOR THROUGHOUT LESS WET AREA AND NORTH ENTRIES	
	CLASSROOM 1 B1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 2 B9, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 3 B2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 4 B8, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 5 B3, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 6 B7, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	CLASSROOM 7 B4, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	ART ROOM B6, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
	C1, FLOOR THROUGHOUT LESS WET AREA	
	C2, FLOOR THROUGHOUT LESS WET AREA	
	C3, FLOOR THROUGHOUT LESS WET AREA	
	C4, FLOOR THROUGHOUT LESS WET AREA	
	C FOYER, FLOOR THROUGHOUT	
	C ART ROOM, PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, WHITE AND GRAY MOTTLES	RECEPTION, FLOOR THROUGHOUT	S
	HALLWAY 1, FLOOR THROUGHOUT	
	SUPPLIES, FLOOR THROUGHOUT	
	NURSE OFFICE, FLOOR THROUGHOUT	
	TREATMENT ROOM, FLOOR THROUGHOUT	
	HALLWAY 2, FLOOR THROUGHOUT	
	PRINCIPAL, FLOOR THROUGHOUT	
	PRINCIPAL CLOSET, FLOOR THROUGHOUT	
	FOYER, FLOOR THROUGHOUT	
	PSYCHOLOGIST OFFICE, FLOOR THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, FLOOR THROUGHOUT	
	ASSISTANT PRINCIPAL, FLOOR THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, FLOOR THROUGHOUT	
	LOUNGE, FLOOR THROUGHOUT	
	WORKROOM 1, FLOOR THROUGHOUT	
	PHONE ROOM, FLOOR THROUGHOUT	
	STORAGE 1, FLOOR THROUGHOUT	
	CORRIDOR 1, FLOOR THROUGHOUT	
	CORRIDOR 2, FLOOR THROUGHOUT	
	CORRIDOR 3, FLOOR THROUGHOUT	
	CORRIDOR 4, FLOOR THROUGHOUT	
	SPEECH ROOM, FLOOR THROUGHOUT	
	CONFERENCE ROOM, FLOOR THROUGHOUT	
	COMPUTER ROOM 401, FLOOR THROUGHOUT	
	RESOURCE ROOM 402, FLOOR THROUGHOUT	
	RESOURCE ROOM 403, FLOOR THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	404 CLOSET, FLOOR THROUGHOUT	
	GIFTED CLASSROOM 405, FLOOR THROUGHOUT	
	K-3, FLOOR THROUGHOUT	
	MEDIA CENTER, FLOOR THROUGHOUT	
	CONFERENCE ROOM 412, FLOOR THROUGHOUT	
	WORKROOM 2, FLOOR THROUGHOUT	
	BREAK-OUT 1, FLOOR THROUGHOUT	
	BREAK-OUT 2, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	CLASSROOM 1 A1, FLOOR THROUGHOUT	
	CLASSROOM 2 A12, FLOOR THROUGHOUT	
	CLASSROOM 3 A2, FLOOR THROUGHOUT	
	CLASSROOM 4 A11, FLOOR THROUGHOUT	
	NORTH A FOYER, FLOOR THROUGHOUT	
	CLASSROOM 5 A3, FLOOR THROUGHOUT	
	CLASSROOM 6 A10, FLOOR THROUGHOUT	
	CLASSROOM 7 A4, FLOOR THROUGHOUT	
	CLASSROOM 8 A9, FLOOR THROUGHOUT	
	SOUTH A FOYER, FLOOR THROUGHOUT	
	KINDERGARTEN 1 A5, FLOOR THROUGHOUT	
	KINDERGARTEN 2 A8, FLOOR THROUGHOUT	
	CLASSROOM 1 B1, FLOOR THROUGHOUT	
	CLASSROOM 2 B9, FLOOR THROUGHOUT	
	CLASSROOM 3 B2, FLOOR THROUGHOUT	
	CLASSROOM 4 B8, FLOOR THROUGHOUT	
	NORTH B FOYER, FLOOR THROUGHOUT	
	CLASSROOM 5 B3, FLOOR THROUGHOUT	
	CLASSROOM 6 B7, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 7 B4, FLOOR THROUGHOUT	
	ART ROOM B6, FLOOR THROUGHOUT	
	SOUTH B FOYER, FLOOR THROUGHOUT	
	C1, FLOOR THROUGHOUT	
	C2, FLOOR THROUGHOUT	
	C3, FLOOR THROUGHOUT	
	C4, FLOOR THROUGHOUT	
	C FOYER, FLOOR THROUGHOUT	
	C ART ROOM, FLOOR THROUGHOUT	
SEALANT, WHITE, PLIABLE	RECEPTION, SOUTH DOORS, NORTH WINDOWS, MILLWORK	S
	HALLWAY 1, MILLWORK	
	SUPPLIES, SOUTH DOOR, PORTION OF SOUTH WALL	
	NURSE OFFICE, SOUTH WINDOW, MILLWORK	
	NURSE RESTROOM, SOUTH DOOR, FIXTURES	
	TREATMENT ROOM, WEST DOOR	
	HALLWAY 2, NORTH DOOR AND WINDOW	
	PRINCIPAL, DOORS THROUGHOUT	
	PRINCIPAL CLOSET, WEST DOOR	
	FOYER, NORTH DOOR AND WINDOW	
	PSYCHOLOGIST OFFICE, DOORS THROUGHOUT, SOUTH WINDOW	
	PSYCHOLOGIST OFFICE CLOSET, WEST DOOR	
	ASSISTANT PRINCIPAL, DOORS THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, SOUTH DOOR	
	LOUNGE, NORTH DOOR, MILLWORK	
	WORKROOM 1, DOORS THROUGHOUT, MILLWORK	
	PHONE ROOM, PORTION OF NORTH AND SOUTH WALLS	
	STORAGE 1, EAST DOOR	
	STAFF MEN'S RESTROOM, FIXTURES	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
 Kyrene Del Cielo Elementary School  
 Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	STAFF WOMEN'S RESTROOM, MILLWORK, FIXTURES	
	CORRIDOR 1, SOUTH DOORS AND WINDOWS	
	CORRIDOR 2, NORTH AND EAST DOORS AND WINDOWS	
	CORRIDOR 3, SOUTH DOORS AND WINDOWS	
	SPEECH ROOM, EAST DOOR AND WINDOW	
	CONFERENCE ROOM, DOORS THROUGHOUT	
	COMPUTER ROOM 401, DOORS THROUGHOUT, NORTH WINDOW	
	RESOURCE ROOM 402, EAST DOOR, SOUTH WINDOW, MILLWORK	
	RESOURCE ROOM 403, DOORS THROUGHOUT, SOUTH WINDOW, MILLWORK	
	402/403 RESTROOM, FIXTURES	
	EXTENDED RESOURCE ROOM 404, DOORS THROUGHOUT, NORTH WINDOW, MILLWORK	
	404 CLOSET, WEST DOOR	
	404 RESTROOM, FIXTURES	
	GIFTED CLASSROOM 405, NORTH DOOR, MILLWORK	
	K-3, SOUTH DOOR AND WINDOW	
	MEDIA CENTER, DOORS THROUGHOUT, NORTH AND SOUTH WINDOWS	
	CONFERENCE ROOM 412, DOORS AND WINDOWS THROUGHOUT, MILLWORK	
	WORKROOM 2, DOORS THROUGHOUT, WEST WINDOW, MILLWORK	
	ELECTRICAL ROOM, EAST DOOR	
	BREAK-OUT 1, SOUTH DOOR AND WINDOW	
	BREAK-OUT 2, SOUTH DOOR AND WINDOW	
	STORAGE 2, SOUTH DOOR, MILLWORK	
	CLASSROOM 1 A1, DOORS THROUGHOUT, MILLWORK	
	A ELECTRICAL ROOM, NORTH DOOR	
	CLASSROOM 2 A12, DOORS THROUGHOUT, MILLWORK	
	CLASSROOM 3 A2, DOORS THROUGHOUT, MILLWORK	
	CLASSROOM 4 A11, DOORS THROUGHOUT, MILLWORK	
	NORTH A FOYER, DOORS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 5 A3, DOORS THROUGHOUT, MILLWORK	
	CLASSROOM 6 A10, DOORS THROUGHOUT, MILLWORK	
	CLASSROOM 7 A4, DOORS THROUGHOUT, MILLWORK	
	CLASSROOM 8 A9, DOORS THROUGHOUT, MILLWORK	
	SOUTH A FOYER, DOORS THROUGHOUT	
	KINDERGARTEN 1 A5, NORTH AND EAST DOORS, MILLWORK	
	A5 RESTROOM, EAST DOOR, FIXTURES	
	KINDERGARTEN 2 A8, EAST AND WEST DOORS, MILLWORK	
	A8 RESTROOM, WEST DOOR, FIXTURES	
	CLASSROOM 1 B1, WEST DOOR, MILLWORK	
	CLASSROOM 2 B9, EAST DOOR, MILLWORK	
	CLASSROOM 3 B2, WEST DOOR, MILLWORK	
	CLASSROOM 4 B8, EAST DOOR, MILLWORK	
	NORTH B FOYER, DOORS THROUGHOUT	
	CLASSROOM 5 B3, WEST DOOR, MILLWORK	
	CLASSROOM 6 B7, EAST DOOR, MILLWORK	
	CLASSROOM 7 B4, WEST DOOR, MILLWORK	
	ART ROOM B6, DOORS THROUGHOUT, MILLWORK	
	SOUTH B FOYER, DOORS THROUGHOUT	
	B JANITOR, NORTH DOOR, FIXTURES	
	B ELECTRICAL ROOM, NORTH DOOR	
	B BOY'S RESTROOM VESTIBULE, NORTH DOOR	
	B BOY'S RESTROOM, MILLWORK, FIXTURES	
	B GIRL'S RESTROOM VESTIBULE, NORTH DOOR	
	B GIRL'S RESTROOM, MILLWORK, FIXTURES	
	C1, WEST AND SOUTH DOORS, MILLWORK	
	C2, EAST DOOR, MILLWORK	
	C3, EAST DOOR, MILLWORK	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	C4, NORTH AND WEST DOORS, MILLWORK	
	C FOYER, DOORS THROUGHOUT	
	C ART ROOM, EAST DOOR, MILLWORK	
	STORAGE, NORTH DOOR	
	C BOY'S RESTROOM, WEST DOOR, MILLWORK, FIXTURES	
	C ELECTRICAL ROOM, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	C GIRL'S RESTROOM, WEST DOOR, MILLWORK, FIXTURES	
	EXTERIOR, PORTION OF NORTH, WEST AND SOUTH DOORS	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	NURSE RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	S
	STAFF WOMEN'S RESTROOM, EAST AND PORTION OF NORTH, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	A5 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	A8 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	B GIRL'S RESTROOM, CEILING THROUGHOUT	
	B GIRL'S RESTROOM VESTIBULE, WALLS AND CEILING THROUGHOUT	
	B BOY'S RESTROOM, CEILING THROUGHOUT	
	B BOY'S RESTROOM VESTIBULE, WALLS AND CEILING THROUGHOUT	
	B JANITOR, WEST WALL, CEILING THROUGHOUT	
	C BOY'S RESTROOM, CEILING THROUGHOUT	
	C GIRL'S RESTROOM, CEILING THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY AND SPRAY-APPLIED TEXTURES, WHITE, CHALKY	NURSE RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	S
	STAFF MEN'S RESTROOM, CEILING THROUGHOUT	
	STAFF WOMEN'S RESTROOM, EAST AND PORTION OF NORTH, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	402/403 RESTROOM, CEILING THROUGHOUT	
	404 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	A5 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	A8 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	B GIRL'S RESTROOM, CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	B GIRL'S RESTROOM VESTIBULE, WALLS AND CEILING THROUGHOUT	
	B BOY'S RESTROOM, CEILING THROUGHOUT	
	B BOY'S RESTROOM VESTIBULE, WALLS AND CEILING THROUGHOUT	
	B JANITOR, WEST WALL, CEILING THROUGHOUT	
	C BOY'S RESTROOM, CEILING THROUGHOUT	
	C GIRL'S RESTROOM, CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	NURSE RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	S
	STAFF MEN'S RESTROOM, CEILING THROUGHOUT	
	STAFF WOMEN'S RESTROOM, EAST AND PORTION OF NORTH, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	402/403 RESTROOM, CEILING THROUGHOUT	
	404 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	A5 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	A8 RESTROOM, UPPER PORTION OF WALLS THROUGHOUT, CEILING THROUGHOUT	
	B GIRL'S RESTROOM, CEILING THROUGHOUT	
	B GIRL'S RESTROOM VESTIBULE, WALLS AND CEILING THROUGHOUT	
	B BOY'S RESTROOM, CEILING THROUGHOUT	
	B BOY'S RESTROOM VESTIBULE, WALLS AND CEILING THROUGHOUT	
	B JANITOR, WEST WALL, CEILING THROUGHOUT	
	C BOY'S RESTROOM, CEILING THROUGHOUT	
	C GIRL'S RESTROOM, CEILING THROUGHOUT	
GLAZED WALL TILE, 4"X4", PINK, SMOOTH	NURSE RESTROOM, LOWER PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	STAFF MEN'S RESTROOM, WALLS THROUGHOUT	
	STAFF WOMEN'S RESTROOM, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	402/403 RESTROOM, WALLS THROUGHOUT	
	404 RESTROOM, WALLS THROUGHOUT	
	A5 RESTROOM, LOWER PORTION OF WALLS THROUGHOUT	
	A8 RESTROOM, LOWER PORTION OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH	NURSE RESTROOM, LOWER PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	STAFF MEN'S RESTROOM, WALLS THROUGHOUT	
	STAFF WOMEN'S RESTROOM, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	402/403 RESTROOM, WALLS THROUGHOUT	
	404 RESTROOM, WALLS THROUGHOUT	
	A5 RESTROOM, LOWER PORTION OF WALLS THROUGHOUT	
	A8 RESTROOM, LOWER PORTION OF WALLS THROUGHOUT	
CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, MULTI-COLORED SPECKS	NURSE RESTROOM, FLOOR THROUGHOUT	S
	STAFF MEN'S RESTROOM, FLOOR THROUGHOUT	
	STAFF WOMEN'S RESTROOM, FLOOR THROUGHOUT	
	402/403 RESTROOM, FLOOR THROUGHOUT	
	404 RESTROOM, FLOOR THROUGHOUT	
	A5 RESTROOM, FLOOR THROUGHOUT	
	A8 RESTROOM, FLOOR THROUGHOUT	
	C BOY'S RESTROOM, FLOOR THROUGHOUT	
	C GIRL'S RESTROOM, FLOOR THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, MULTI-COLORED SPECKS	NURSE RESTROOM, FLOOR THROUGHOUT	S
	STAFF MEN'S RESTROOM, FLOOR THROUGHOUT	
	STAFF WOMEN'S RESTROOM, FLOOR THROUGHOUT	
	402/403 RESTROOM, FLOOR THROUGHOUT	
	404 RESTROOM, FLOOR THROUGHOUT	
	A5 RESTROOM, FLOOR THROUGHOUT	
	A8 RESTROOM, FLOOR THROUGHOUT	
	C BOY'S RESTROOM, FLOOR THROUGHOUT	
	C GIRL'S RESTROOM, FLOOR THROUGHOUT	
QUARRY/PAVER TILE (TRANSITION STRIP), 2"X36", GRAY, SMOOTH, MARBLED	NURSE RESTROOM, ENTRY PORTION OF FLOOR	S
	STAFF MEN'S RESTROOM, ENTRY PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	STAFF WOMEN'S RESTROOM, ENTRY PORTION OF FLOOR	
	402/403 RESTROOM, ENTRY PORTION OF FLOOR	
	404 RESTROOM, ENTRY PORTION OF FLOOR	
	A5 RESTROOM, ENTRY PORTION OF FLOOR	
	A8 RESTROOM, ENTRY PORTION OF FLOOR	
SINK ACOUSTICAL COATING, GRAY, ROUGH	HALLWAY 1, WEST SINK	
	LOUNGE, WEST SINK	
	WORKROOM 1, EAST SINK	
	RESOURCE ROOM 402, SOUTH SINK	
	RESOURCE ROOM 403, SOUTH SINK	
	EXTENDED RESOURCE ROOM 404, NORTH SINK	
	GIFTED CLASSROOM 405, WEST SINK	
	WORKROOM 2, SOUTH SINK	
	C1, EAST SINK	
	C2, WEST SINK	
	C3, WEST SINK	
	C4, EAST SINK	
	C ART ROOM, EAST AND SOUTH SINKS	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	S
	SUPPLIES, WALLS AND CEILING THROUGHOUT	
	NURSE OFFICE, WALLS THROUGHOUT	
	PRINCIPAL, WALLS THROUGHOUT	
	PRINCIPAL CLOSET, WALLS AND CEILING THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, WALLS AND CEILING THROUGHOUT	
	ASSISTANT PRINCIPAL, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	ASSISTANT PRINCIPAL CLOSET, WALLS AND CEILING THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	LOUNGE, WEST AND PORTION OF NORTH, EAST AND SOUTH WALLS	
	WORKROOM 1, WALLS THROUGHOUT, PORTION OF WEST PLENUM WALL ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	PHONE ROOM, WEST AND PORTION OF NORTH, EAST AND SOUTH WALLS	
	STORAGE 1, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	SPEECH ROOM, NORTH, EAST AND PORTION OF WEST AND SOUTH WALLS	
	CONFERENCE ROOM, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	COMPUTER ROOM 401, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	RESOURCE ROOM 402, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
	RESOURCE ROOM 403, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	
	EXTENDED RESOURCE ROOM 404, NORTH, WEST AND PORTION OF EAST AND SOUTH WALLS	
	404 CLOSET, WALLS AND CEILING THROUGHOUT	
	GIFTED CLASSROOM 405, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS, WEST PLENUM WALL ABOVE CEILING	
	K-3, NORTH, SOUTH AND PORTION OF EAST AND WEST WALLS, WEST PLENUM WALL ABOVE CEILING	
	MEDIA CENTER, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, PORTION OF CEILING, WEST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	CONFERENCE ROOM 412, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	WORKROOM 2, WALLS THROUGHOUT, PORTION OF EAST PLENUM WALL ABOVE CEILING	
	ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	BREAK-OUT 1, WALLS THROUGHOUT, NORTH PLENUM WALL ABOVE CEILING	
	BREAK-OUT 2, WALLS THROUGHOUT, NORTH PLENUM WALL ABOVE CEILING	
	STORAGE 2, NORTH AND PORTION OF EAST, WEST AND SOUTH WALLS, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	KINDERGARTEN 1 A5, PORTION OF CEILING	
	KINDERGARTEN 2 A8, PORTION OF CEILING	
	C1, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C2, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C3, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C4, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C FOYER, WALLS THROUGHOUT, SOUTH PLENUM WALL ABOVE CEILING	
	C ART ROOM, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	STORAGE, WALLS AND CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	S
	SUPPLIES, WALLS AND CEILING THROUGHOUT	
	NURSE OFFICE, WALLS THROUGHOUT	
	PRINCIPAL, WALLS THROUGHOUT	
	PRINCIPAL CLOSET, WALLS AND CEILING THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, WALLS AND CEILING THROUGHOUT	
	ASSISTANT PRINCIPAL, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	ASSISTANT PRINCIPAL CLOSET, WALLS AND CEILING THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	LOUNGE, WEST AND PORTION OF NORTH, EAST AND SOUTH WALLS	
	WORKROOM 1, WALLS THROUGHOUT, PORTION OF WEST PLENUM WALL ABOVE CEILING	
	PHONE ROOM, WEST AND PORTION OF NORTH, EAST AND SOUTH WALLS	
	STORAGE 1, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	SPEECH ROOM, NORTH, EAST AND PORTION OF WEST AND SOUTH WALLS	
	CONFERENCE ROOM, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	COMPUTER ROOM 401, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	RESOURCE ROOM 402, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
	RESOURCE ROOM 403, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	
	EXTENDED RESOURCE ROOM 404, NORTH, WEST AND PORTION OF EAST AND SOUTH WALLS	
	404 CLOSET, WALLS AND CEILING THROUGHOUT	
	GIFTED CLASSROOM 405, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS, WEST PLENUM WALL ABOVE CEILING	
	K-3, NORTH, SOUTH AND PORTION OF EAST AND WEST WALLS, WEST PLENUM WALL ABOVE CEILING	
	MEDIA CENTER, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, PORTION OF CEILING, WEST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	CONFERENCE ROOM 412, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	WORKROOM 2, WALLS THROUGHOUT, PORTION OF EAST PLENUM WALL ABOVE CEILING	
	ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	BREAK-OUT 1, WALLS THROUGHOUT, NORTH PLENUM WALL ABOVE CEILING	
	BREAK-OUT 2, WALLS THROUGHOUT, NORTH PLENUM WALL ABOVE CEILING	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	STORAGE 2, NORTH AND PORTION OF EAST, WEST AND SOUTH WALLS, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	KINDERGARTEN 1 A5, PORTION OF CEILING	
	KINDERGARTEN 2 A8, PORTION OF CEILING	
	C1, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C2, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C3, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C4, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C FOYER, WALLS THROUGHOUT, SOUTH PLENUM WALL ABOVE CEILING	
	C ART ROOM, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	STORAGE, WALLS AND CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	S
	SUPPLIES, WALLS AND CEILING THROUGHOUT	
	NURSE OFFICE, WALLS THROUGHOUT	
	PRINCIPAL, WALLS THROUGHOUT	
	PRINCIPAL CLOSET, WALLS AND CEILING THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, WALLS AND CEILING THROUGHOUT	
	ASSISTANT PRINCIPAL, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	ASSISTANT PRINCIPAL CLOSET, WALLS AND CEILING THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	LOUNGE, WEST AND PORTION OF NORTH, EAST AND SOUTH WALLS	
	WORKROOM 1, WALLS THROUGHOUT, PORTION OF WEST PLENUM WALL ABOVE CEILING	
	PHONE ROOM, WEST AND PORTION OF NORTH, EAST AND SOUTH WALLS	
	STORAGE 1, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	SPEECH ROOM, NORTH, EAST AND PORTION OF WEST AND SOUTH WALLS	
	CONFERENCE ROOM, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	COMPUTER ROOM 401, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	RESOURCE ROOM 402, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
	RESOURCE ROOM 403, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	
	EXTENDED RESOURCE ROOM 404, NORTH, WEST AND PORTION OF EAST AND SOUTH WALLS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	404 CLOSET, WALLS AND CEILING THROUGHOUT	
	GIFTED CLASSROOM 405, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS, WEST PLENUM WALL ABOVE CEILING	
	K-3, NORTH, SOUTH AND PORTION OF EAST AND WEST WALLS, WEST PLENUM WALL ABOVE CEILING	
	MEDIA CENTER, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, PORTION OF CEILING, WEST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	CONFERENCE ROOM 412, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, EAST PLENUM WALL ABOVE CEILING	
	WORKROOM 2, WALLS THROUGHOUT, PORTION OF EAST PLENUM WALL ABOVE CEILING	
	ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	BREAK-OUT 1, WALLS THROUGHOUT, NORTH PLENUM WALL ABOVE CEILING	
	BREAK-OUT 2, WALLS THROUGHOUT, NORTH PLENUM WALL ABOVE CEILING	
	STORAGE 2, NORTH AND PORTION OF EAST, WEST AND SOUTH WALLS, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	KINDERGARTEN 1 A5, PORTION OF CEILING	
	KINDERGARTEN 2 A8, PORTION OF CEILING	
	C1, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C2, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C3, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C4, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	C FOYER, WALLS THROUGHOUT, SOUTH PLENUM WALL ABOVE CEILING	
	C ART ROOM, NORTH, EAST, SOUTH AND PORTION OF WEST WALLS, SOUTH PLENUM WALL ABOVE CEILING	
	STORAGE, WALLS AND CEILING THROUGHOUT	
SEALANT, BLACK, CLAY-LIKE	NURSE OFFICE, NORTH WINDOW	S
	PRINCIPAL, SOUTH WINDOW	
	PSYCHOLOGIST OFFICE, SOUTH WINDOW	
	SPEECH ROOM, EAST WINDOW	
	COMPUTER ROOM 401, NORTH AND EAST WINDOWS	
	RESOURCE ROOM 402, EAST WINDOW	
	RESOURCE ROOM 403, WEST WINDOW	
	EXTENDED RESOURCE ROOM 404, SOUTH WINDOW	
	GIFTED CLASSROOM 405, NORTH WINDOW	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	K-3, SOUTH WINDOW	
	MEDIA CENTER, NORTH AND WEST WINDOWS	
	CONFERENCE ROOM 412, EAST AND WEST WINDOWS	
	WORKROOM 2, WEST WINDOW	
	BREAK-OUT 1, SOUTH WINDOW	
	BREAK-OUT 2, SOUTH WINDOW	
FIRE DOOR INSULATION, METAL CLADDING	RECEPTION, SOUTH DOORS	S
	NURSE OFFICE, SOUTH DOOR	
	CORRIDOR 1, EAST AND SOUTH DOORS	
	CORRIDOR 2, NORTH AND EAST DOORS	
	CORRIDOR 3, SOUTH DOORS	
	CLASSROOM 2 A12, WEST DOOR	
	CLASSROOM 4 A11, WEST DOOR	
	CLASSROOM 6 A10, WEST DOOR	
	CLASSROOM 8 A9, WEST DOOR	
	KINDERGARTEN 1 A5, SOUTH DOOR	
	KINDERGARTEN 2 A8, WEST AND SOUTH DOORS	
	CLASSROOM 1 B1, EAST DOOR	
	CLASSROOM 3 B2, EAST DOOR	
	CLASSROOM 5 B3, EAST DOOR	
	CLASSROOM 7 B4, EAST DOOR	
	ART ROOM B6, SOUTH DOOR	
	B JANITOR, NORTH DOOR	
	B ELECTRICAL ROOM, NORTH DOOR	
	B BOY'S RESTROOM VESTIBULE, NORTH DOOR	
	B GIRL'S RESTROOM VESTIBULE, NORTH DOOR	
	C4, NORTH DOOR	
	C ART ROOM, EAST DOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	KILN ROOM, WEST DOOR	
	STORAGE, NORTH DOOR	
	C BOY'S RESTROOM, WEST DOOR	
	FIRE RISER, WEST DOOR	
	C ELECTRICAL ROOM, WEST DOOR	
	C GIRL'S RESTROOM, WEST DOOR	
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH DOORS	
SEALANT (DUCT), TAN, PLIABLE	RECEPTION, DUCTWORK ABOVE CEILING	S
	HALLWAY 1, DUCTWORK ABOVE CEILING	
	SUPPLIES, DUCTWORK ABOVE CEILING	
	NURSE OFFICE, DUCTWORK ABOVE CEILING	
	NURSE RESTROOM, DUCTWORK ABOVE CEILING	
	TREATMENT ROOM, DUCTWORK ABOVE CEILING	
	HALLWAY 2, DUCTWORK ABOVE CEILING	
	PRINCIPAL, DUCTWORK ABOVE CEILING	
	PRINCIPAL CLOSET, DUCTWORK ABOVE CEILING	
	FOYER, DUCTWORK ABOVE CEILING	
	PSYCHOLOGIST OFFICE, DUCTWORK ABOVE CEILING	
	PSYCHOLOGIST OFFICE CLOSET, DUCTWORK ABOVE CEILING	
	ASSISTANT PRINCIPAL, DUCTWORK ABOVE CEILING	
	ASSISTANT PRINCIPAL CLOSET, DUCTWORK ABOVE CEILING	
	LOUNGE, DUCTWORK ABOVE CEILING	
	WORKROOM 1, DUCTWORK ABOVE CEILING	
	PHONE ROOM, DUCTWORK ABOVE CEILING	
	STORAGE 1, DUCTWORK ABOVE CEILING	
	STAFF MEN'S RESTROOM, DUCTWORK ABOVE CEILING	
	STAFF WOMEN'S RESTROOM, DUCTWORK ABOVE CEILING	
	CORRIDOR 1, DUCTWORK ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CORRIDOR 2, DUCTWORK ABOVE CEILING	
	CORRIDOR 3, DUCTWORK ABOVE CEILING	
	CORRIDOR 4, DUCTWORK ABOVE CEILING	
	SPEECH ROOM, DUCTWORK ABOVE CEILING	
	CONFERENCE ROOM, DUCTWORK ABOVE CEILING	
	COMPUTER ROOM 401, DUCTWORK ABOVE CEILING	
	RESOURCE ROOM 402, DUCTWORK ABOVE CEILING	
	RESOURCE ROOM 403, DUCTWORK ABOVE CEILING	
	402/403 RESTROOM, DUCTWORK ABOVE CEILING	
	EXTENDED RESOURCE ROOM 404, DUCTWORK ABOVE CEILING	
	404 CLOSET, DUCTWORK ABOVE CEILING	
	404 RESTROOM, DUCTWORK ABOVE CEILING	
	GIFTED CLASSROOM 405, DUCTWORK ABOVE CEILING	
	K-3, DUCTWORK ABOVE CEILING	
	MEDIA CENTER, DUCTWORK ABOVE CEILING	
	CONFERENCE ROOM 412, DUCTWORK ABOVE CEILING	
	WORKROOM 2, DUCTWORK ABOVE CEILING	
	ELECTRICAL ROOM, DUCTWORK ABOVE CEILING	
	BREAK-OUT 1, DUCTWORK ABOVE CEILING	
	BREAK-OUT 2, DUCTWORK ABOVE CEILING	
	STORAGE 2, DUCTWORK ABOVE CEILING	
	CLASSROOM 1 A1, DUCTWORK ABOVE CEILING	
	A ELECTRICAL ROOM, DUCTWORK ABOVE CEILING	
	CLASSROOM 2 A12, DUCTWORK ABOVE CEILING	
	CLASSROOM 3 A2, DUCTWORK ABOVE CEILING	
	CLASSROOM 4 A11, DUCTWORK ABOVE CEILING	
	NORTH A FOYER, DUCTWORK ABOVE CEILING	
	CLASSROOM 5 A3, DUCTWORK ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 6 A10, DUCTWORK ABOVE CEILING	
	CLASSROOM 7 A4, DUCTWORK ABOVE CEILING	
	CLASSROOM 8 A9, DUCTWORK ABOVE CEILING	
	SOUTH A FOYER, DUCTWORK ABOVE CEILING	
	KINDERGARTEN 1 A5, DUCTWORK ABOVE CEILING	
	A5 RESTROOM, DUCTWORK ABOVE CEILING	
	KINDERGARTEN 2 A8, DUCTWORK ABOVE CEILING	
	A8 RESTROOM, DUCTWORK ABOVE CEILING	
	CLASSROOM 1 B1, DUCTWORK ABOVE CEILING	
	CLASSROOM 2 B9, DUCTWORK ABOVE CEILING	
	CLASSROOM 3 B2, DUCTWORK ABOVE CEILING	
	CLASSROOM 4 B8, DUCTWORK ABOVE CEILING	
	NORTH B FOYER, DUCTWORK ABOVE CEILING	
	CLASSROOM 5 B3, DUCTWORK ABOVE CEILING	
	CLASSROOM 6 B7, DUCTWORK ABOVE CEILING	
	CLASSROOM 7 B4, DUCTWORK ABOVE CEILING	
	ART ROOM B6, DUCTWORK ABOVE CEILING	
	SOUTH B FOYER, DUCTWORK ABOVE CEILING	
	B JANITOR, DUCTWORK ABOVE CEILING	
	B ELECTRICAL ROOM, DUCTWORK ABOVE CEILING	
	B BOY'S RESTROOM VESTIBULE, DUCTWORK ABOVE CEILING	
	B BOY'S RESTROOM, DUCTWORK ABOVE CEILING	
	B GIRL'S RESTROOM VESTIBULE, DUCTWORK ABOVE CEILING	
	B GIRL'S RESTROOM, DUCTWORK ABOVE CEILING	
	C1, DUCTWORK ABOVE CEILING	
	C2, DUCTWORK ABOVE CEILING	
	C3, DUCTWORK ABOVE CEILING	
	C4, DUCTWORK ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	C FOYER, DUCTWORK ABOVE CEILING	
	C ART ROOM, DUCTWORK ABOVE CEILING	
	KILN ROOM, DUCTWORK ABOVE CEILING	
	STORAGE, DUCTWORK ABOVE CEILING	
	C BOY'S RESTROOM, DUCTWORK ABOVE CEILING	
	FIRE RISER, DUCTWORK ABOVE CEILING	
	C ELECTRICAL ROOM, DUCTWORK ABOVE CEILING	
	C GIRL'S RESTROOM, DUCTWORK ABOVE CEILING	
CONCRETE (DOUBLE T'S), GRAY, CEMENTITIOUS	RECEPTION, PLENUM CEILING THROUGHOUT	S
	HALLWAY 1, PLENUM CEILING THROUGHOUT	
	SUPPLIES, PLENUM CEILING THROUGHOUT	
	NURSE OFFICE, PLENUM CEILING THROUGHOUT	
	NURSE RESTROOM, PLENUM CEILING THROUGHOUT	
	TREATMENT ROOM, PLENUM CEILING THROUGHOUT	
	HALLWAY 2, PLENUM CEILING THROUGHOUT	
	PRINCIPAL, PLENUM CEILING THROUGHOUT	
	PRINCIPAL CLOSET, PLENUM CEILING THROUGHOUT	
	FOYER, PLENUM CEILING THROUGHOUT	
	PSYCHOLOGIST OFFICE, PLENUM CEILING THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, PLENUM CEILING THROUGHOUT	
	ASSISTANT PRINCIPAL, PLENUM CEILING THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, PLENUM CEILING THROUGHOUT	
	LOUNGE, PLENUM CEILING THROUGHOUT	
	WORKROOM 1, PLENUM CEILING THROUGHOUT	
	PHONE ROOM, PLENUM CEILING THROUGHOUT	
	STORAGE 1, PLENUM CEILING THROUGHOUT	
	STAFF MEN'S RESTROOM, PLENUM CEILING THROUGHOUT	
	STAFF WOMEN'S RESTROOM, PLENUM CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CORRIDOR 1, PLENUM CEILING THROUGHOUT	
	CORRIDOR 2, PLENUM CEILING THROUGHOUT	
	CORRIDOR 3, PLENUM CEILING THROUGHOUT	
	CORRIDOR 4, PLENUM CEILING THROUGHOUT	
	SPEECH ROOM, PLENUM CEILING THROUGHOUT	
	CONFERENCE ROOM, PLENUM CEILING THROUGHOUT	
	COMPUTER ROOM 401, PLENUM CEILING THROUGHOUT	
	RESOURCE ROOM 402, PLENUM CEILING THROUGHOUT	
	RESOURCE ROOM 403, PLENUM CEILING THROUGHOUT	
	402/403 RESTROOM, PLENUM CEILING THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, PLENUM CEILING THROUGHOUT	
	404 CLOSET, PLENUM CEILING THROUGHOUT	
	404 RESTROOM, PLENUM CEILING THROUGHOUT	
	GIFTED CLASSROOM 405, PLENUM CEILING THROUGHOUT	
	K-3, PLENUM CEILING THROUGHOUT	
	MEDIA CENTER, PLENUM CEILING THROUGHOUT	
	CONFERENCE ROOM 412, PLENUM CEILING THROUGHOUT	
	WORKROOM 2, PLENUM CEILING THROUGHOUT	
	ELECTRICAL ROOM, PLENUM CEILING THROUGHOUT	
	BREAK-OUT 1, PLENUM CEILING THROUGHOUT	
	BREAK-OUT 2, PLENUM CEILING THROUGHOUT	
	STORAGE 2, PLENUM CEILING THROUGHOUT	
	CLASSROOM 1 A1, PLENUM CEILING THROUGHOUT	
	A ELECTRICAL ROOM, PLENUM CEILING THROUGHOUT	
	CLASSROOM 2 A12, PLENUM CEILING THROUGHOUT	
	CLASSROOM 3 A2, PLENUM CEILING THROUGHOUT	
	CLASSROOM 4 A11, PLENUM CEILING THROUGHOUT	
	NORTH A FOYER, PLENUM CEILING THROUGHOUT	



JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 5 A3, PLENUM CEILING THROUGHOUT	
	CLASSROOM 6 A10, PLENUM CEILING THROUGHOUT	
	CLASSROOM 7 A4, PLENUM CEILING THROUGHOUT	
	CLASSROOM 8 A9, PLENUM CEILING THROUGHOUT	
	SOUTH A FOYER, PLENUM CEILING THROUGHOUT	
	KINDERGARTEN 1 A5, PLENUM CEILING THROUGHOUT	
	A5 RESTROOM, PLENUM CEILING THROUGHOUT	
	KINDERGARTEN 2 A8, PLENUM CEILING THROUGHOUT	
	A8 RESTROOM, PLENUM CEILING THROUGHOUT	
	CLASSROOM 1 B1, PLENUM CEILING THROUGHOUT	
	CLASSROOM 2 B9, PLENUM CEILING THROUGHOUT	
	CLASSROOM 3 B2, PLENUM CEILING THROUGHOUT	
	CLASSROOM 4 B8, PLENUM CEILING THROUGHOUT	
	NORTH B FOYER, PLENUM CEILING THROUGHOUT	
	CLASSROOM 5 B3, PLENUM CEILING THROUGHOUT	
	CLASSROOM 6 B7, PLENUM CEILING THROUGHOUT	
	CLASSROOM 7 B4, PLENUM CEILING THROUGHOUT	
	ART ROOM B6, PLENUM CEILING THROUGHOUT	
	SOUTH B FOYER, PLENUM CEILING THROUGHOUT	
	B JANITOR, PLENUM CEILING THROUGHOUT	
	B ELECTRICAL ROOM, PLENUM CEILING THROUGHOUT	
	B BOY'S RESTROOM VESTIBULE, PLENUM CEILING THROUGHOUT	
	B BOY'S RESTROOM, PLENUM CEILING THROUGHOUT	
	B GIRL'S RESTROOM VESTIBULE, PLENUM CEILING THROUGHOUT	
	B GIRL'S RESTROOM, PLENUM CEILING THROUGHOUT	
	C1, PLENUM CEILING THROUGHOUT	
	C2, PLENUM CEILING THROUGHOUT	
	C3, PLENUM CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	C4, PLENUM CEILING THROUGHOUT	
	C FOYER, PLENUM CEILING THROUGHOUT	
	C ART ROOM, PLENUM CEILING THROUGHOUT	
	KILN ROOM, PLENUM CEILING THROUGHOUT	
	STORAGE, PLENUM CEILING THROUGHOUT	
	C BOY'S RESTROOM, PLENUM CEILING THROUGHOUT	
	FIRE RISER, PLENUM CEILING THROUGHOUT	
	C ELECTRICAL ROOM, PLENUM CEILING THROUGHOUT	
	C GIRL'S RESTROOM, PLENUM CEILING THROUGHOUT	
	EXTERIOR, PORTION OF NORTH, EAST AND WEST SOFFITS	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, WHITE AND GRAY MOTTLES	SUPPLIES, FLOOR THROUGHOUT	S
	STORAGE 1, WET AREA PORTION OF FLOOR	
	COMPUTER ROOM 401, WET AREA AND ENTRY PORTION OF FLOOR	
	EXTENDED RESOURCE ROOM 404, WET AREA PORTION OF FLOOR	
	WORKROOM 2, FLOOR THROUGHOUT	
	ELECTRICAL ROOM, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	CLASSROOM 1 A1, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 2 A12, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 3 A2, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 4 A11, WET AREA AND ENTRY PORTION OF FLOOR	
	NORTH A FOYER, FLOOR THROUGHOUT	
	CLASSROOM 5 A3, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 7 A4, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 8 A9, WET AREA AND ENTRY PORTION OF FLOOR	
	SOUTH A FOYER, FLOOR THROUGHOUT	
	KINDERGARTEN 1 A5, WET AREA AND ENTRY PORTION OF FLOOR	
	KINDERGARTEN 2 A8, WET AREA AND ENTRY PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 1 B1, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 2 B9, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 3 B2, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 4 B8, WET AREA AND ENTRY PORTION OF FLOOR	
	NORTH B FOYER, FLOOR THROUGHOUT	
	CLASSROOM 5 B3, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 6 B7, WET AREA AND ENTRY PORTION OF FLOOR	
	CLASSROOM 7 B4, WET AREA AND ENTRY PORTION OF FLOOR	
	ART ROOM B6, WET AREA AND ENTRY PORTION OF FLOOR	
	SOUTH B FOYER, FLOOR THROUGHOUT	
	B JANITOR, FLOOR THROUGHOUT	
	B BOY'S RESTROOM VESTIBULE, FLOOR THROUGHOUT	
	B GIRL'S RESTROOM VESTIBULE, FLOOR THROUGHOUT	
GLASS BLOCK, 8", CLEAR	RECEPTION, SOUTH WINDOW	S
	CORRIDOR 1, SOUTH WINDOW	
	CORRIDOR 2, NORTH AND EAST WINDOWS	
	CORRIDOR 3, SOUTH WINDOW	
	EXTERIOR, PORTION OF NORTH, EAST AND SOUTH WINDOWS	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8", CLEAR	RECEPTION, SOUTH WINDOW	S
	CORRIDOR 1, SOUTH WINDOW	
	CORRIDOR 2, NORTH AND EAST WINDOWS	
	CORRIDOR 3, SOUTH WINDOW	
	EXTERIOR, PORTION OF NORTH, EAST AND SOUTH WINDOWS	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	PSYCHOLOGIST OFFICE, PORTION OF WEST WALL	S
	ASSISTANT PRINCIPAL, PORTION OF SOUTH WALL	
	LOUNGE, PORTION OF EAST AND SOUTH WALLS	
	PHONE ROOM, PORTION OF NORTH, EAST AND SOUTH WALLS	
	SPEECH ROOM, PORTION OF WEST AND SOUTH WALLS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CONFERENCE ROOM, PORTION OF NORTH WALL	
	COMPUTER ROOM 401, PORTION OF NORTH AND SOUTH WALLS	
	RESOURCE ROOM 402, PORTION OF NORTH AND EAST WALLS	
	RESOURCE ROOM 403, PORTION OF NORTH AND WEST WALLS	
	EXTENDED RESOURCE ROOM 404, PORTION OF EAST AND SOUTH WALLS	
	GIFTED CLASSROOM 405, PORTION OF WEST WALL	
	K-3, PORTION OF EAST AND WEST WALLS	
	MEDIA CENTER, PORTION OF SOUTH WALL	
	CONFERENCE ROOM 412, PORTION OF NORTH AND SOUTH WALLS	
	C1, PORTION OF NORTH AND SOUTH WALLS	
	C2, PORTION OF NORTH AND SOUTH WALLS	
	C3, PORTION OF NORTH AND SOUTH WALLS	
	C4, PORTION OF NORTH AND SOUTH WALLS	
	C ART ROOM, PORTION OF WEST WALL	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	PSYCHOLOGIST OFFICE, PORTION OF WEST WALL	S
	ASSISTANT PRINCIPAL, PORTION OF SOUTH WALL	
	LOUNGE, PORTION OF EAST AND SOUTH WALLS	
	PHONE ROOM, PORTION OF NORTH, EAST AND SOUTH WALLS	
	SPEECH ROOM, PORTION OF WEST AND SOUTH WALLS	
	CONFERENCE ROOM, PORTION OF NORTH WALL	
	COMPUTER ROOM 401, PORTION OF NORTH AND SOUTH WALLS	
	RESOURCE ROOM 402, PORTION OF NORTH AND EAST WALLS	
	RESOURCE ROOM 403, PORTION OF NORTH AND WEST WALLS	
	EXTENDED RESOURCE ROOM 404, PORTION OF EAST AND SOUTH WALLS	
	GIFTED CLASSROOM 405, PORTION OF WEST WALL	
	K-3, PORTION OF EAST AND WEST WALLS	
	MEDIA CENTER, PORTION OF SOUTH WALL	
	CONFERENCE ROOM 412, PORTION OF NORTH AND SOUTH WALLS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	C1, PORTION OF NORTH AND SOUTH WALLS	
	C2, PORTION OF NORTH AND SOUTH WALLS	
	C3, PORTION OF NORTH AND SOUTH WALLS	
	C4, PORTION OF NORTH AND SOUTH WALLS	
	C ART ROOM, PORTION OF WEST WALL	
FIRE DOOR INSULATION, WOOD CLADDING	HALLWAY 2, NORTH DOOR	
	FOYER, NORTH DOOR	
	ASSISTANT PRINCIPAL, EAST DOOR	
	WORKROOM 1, WEST DOOR	
	STAFF WOMEN'S RESTROOM, SOUTH DOOR	
	CORRIDOR 1, EAST AND WEST DOORS	
	CORRIDOR 2, NORTH AND WEST DOORS	
	CORRIDOR 3, EAST AND WEST DOORS	
	CORRIDOR 4, DOORS THROUGHOUT	
	SPEECH ROOM, EAST DOOR	
	CONFERENCE ROOM, EAST DOOR	
	COMPUTER ROOM 401, DOORS THROUGHOUT	
	RESOURCE ROOM 402, EAST DOOR	
	RESOURCE ROOM 403, WEST DOOR	
	EXTENDED RESOURCE ROOM 404, SOUTH DOOR	
	GIFTED CLASSROOM 405, NORTH DOOR	
	K-3, SOUTH DOOR	
	MEDIA CENTER, NORTH AND SOUTH DOORS	
	CONFERENCE ROOM 412, SOUTH DOOR	
	WORKROOM 2, NORTH AND EAST DOORS	
	ELECTRICAL ROOM, EAST DOOR	
	BREAK-OUT 1, SOUTH DOOR	
	BREAK-OUT 2, SOUTH DOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	STORAGE 2, SOUTH DOOR	
	CLASSROOM 1 A1, EAST DOOR	
	CLASSROOM 3 A2, EAST DOOR	
	CLASSROOM 5 A3, EAST DOOR	
	CLASSROOM 7 A4, EAST DOOR	
	KINDERGARTEN 1 A5, EAST DOOR	
	CLASSROOM 2 B9, WEST DOOR	
	CLASSROOM 4 B8, WEST DOOR	
	CLASSROOM 6 B7, WEST DOOR	
	ART ROOM B6, WEST DOOR	
	C1, DOORS THROUGHOUT	
	C2, EAST DOOR	
	C3, EAST DOOR	
	C4, WEST DOOR	
	C FOYER, DOORS THROUGHOUT	
	C ART ROOM, SOUTH DOOR	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	404 RESTROOM, CEILING THROUGHOUT	S
TROWELED-ON TEXTURE, WHITE, CHALKY	STORAGE 2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	STORAGE 2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM 1 A1, SOUTH SINK	
	CLASSROOM 2 A12, SOUTH SINK	
	CLASSROOM 3 A2, NORTH SINK	
	CLASSROOM 4 A11, NORTH SINK	
	CLASSROOM 5 A3, SOUTH SINK	
	CLASSROOM 6 A10, SOUTH SINK	
	CLASSROOM 7 A4, NORTH SINK	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 8 A9, NORTH SINK	
	KINDERGARTEN 1 A5, NORTH SINK	
	KINDERGARTEN 2 A8, NORTH SINK	
	CLASSROOM 1 B1, SOUTH SINK	
	CLASSROOM 2 B9, SOUTH SINK	
	CLASSROOM 3 B2, NORTH SINK	
	CLASSROOM 4 B8, NORTH SINK	
	CLASSROOM 5 B3, SOUTH SINK	
	CLASSROOM 6 B7, SOUTH SINK	
	CLASSROOM 7 B4, NORTH SINK	
	ART ROOM B6, NORTH SINKS	
WALLBASE (COVED), 4", LIGHT BLUE, VINYL-LIKE	CLASSROOM 6 B7, BASE OF NORTH, EAST AND WEST WALLS	S
	ART ROOM B6, BASE OF EAST, WEST AND SOUTH WALLS	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", LIGHT BLUE, VINYL-LIKE	CLASSROOM 6 B7, BASE OF NORTH, EAST AND WEST WALLS	S
	ART ROOM B6, BASE OF EAST, WEST AND SOUTH WALLS	
FIBERGLASS REINFORCED PANELING, WHITE, SMOOTH	CLASSROOM 1 A1, PORTION OF SOUTH WALL	S
	CLASSROOM 2 A12, PORTION OF SOUTH WALL	
	CLASSROOM 3 A2, PORTION OF NORTH WALL	
	CLASSROOM 4 A11, PORTION OF NORTH WALL	
	CLASSROOM 5 A3, PORTION OF SOUTH WALL	
	CLASSROOM 6 A10, PORTION OF SOUTH WALL	
	CLASSROOM 7 A4, PORTION OF NORTH WALL	
	CLASSROOM 8 A9, PORTION OF NORTH WALL	
	KINDERGARTEN 1 A5, PORTION OF NORTH WALL	
	KINDERGARTEN 2 A8, PORTION OF NORTH WALL	
	CLASSROOM 1 B1, PORTION OF SOUTH WALL	
	CLASSROOM 2 B9, PORTION OF SOUTH WALL	
	CLASSROOM 3 B2, PORTION OF NORTH WALL	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CLASSROOM 4 B8, PORTION OF NORTH WALL	
	CLASSROOM 5 B3, PORTION OF SOUTH WALL	
	CLASSROOM 6 B7, PORTION OF SOUTH WALL	
	CLASSROOM 7 B4, PORTION OF NORTH WALL	
	ART ROOM B6, PORTION OF NORTH WALL	
	C1, PORTION OF EAST WALL	
	C2, PORTION OF WEST WALL	
	C3, PORTION OF WEST WALL	
	C4, PORTION OF EAST WALL	
	C ART ROOM, PORTION OF EAST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, SMOOTH	CLASSROOM 1 A1, PORTION OF SOUTH WALL	S
	CLASSROOM 2 A12, PORTION OF SOUTH WALL	
	CLASSROOM 3 A2, PORTION OF NORTH WALL	
	CLASSROOM 4 A11, PORTION OF NORTH WALL	
	CLASSROOM 5 A3, PORTION OF SOUTH WALL	
	CLASSROOM 6 A10, PORTION OF SOUTH WALL	
	CLASSROOM 7 A4, PORTION OF NORTH WALL	
	CLASSROOM 8 A9, PORTION OF NORTH WALL	
	KINDERGARTEN 1 A5, PORTION OF NORTH WALL	
	KINDERGARTEN 2 A8, PORTION OF NORTH WALL	
	CLASSROOM 1 B1, PORTION OF SOUTH WALL	
	CLASSROOM 2 B9, PORTION OF SOUTH WALL	
	CLASSROOM 3 B2, PORTION OF NORTH WALL	
	CLASSROOM 4 B8, PORTION OF NORTH WALL	
	CLASSROOM 5 B3, PORTION OF SOUTH WALL	
	CLASSROOM 6 B7, PORTION OF SOUTH WALL	
	CLASSROOM 7 B4, PORTION OF NORTH WALL	
	ART ROOM B6, PORTION OF NORTH WALL	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	C1, PORTION OF EAST WALL	
	C2, PORTION OF WEST WALL	
	C3, PORTION OF WEST WALL	
	C4, PORTION OF EAST WALL	
	C ART ROOM, PORTION OF EAST AND SOUTH WALLS	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	B BOY'S RESTROOM, WALLS THROUGHOUT	S
	B GIRL'S RESTROOM, WALLS THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH	B BOY'S RESTROOM, WALLS THROUGHOUT	S
	B GIRL'S RESTROOM, WALLS THROUGHOUT	
CERAMIC MOSAIC TILE, 1"X1", WHITE, SMOOTH, PEPPERED	B BOY'S RESTROOM, FLOOR THROUGHOUT	S
	B GIRL'S RESTROOM, FLOOR THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 1"X1", WHITE, SMOOTH, PEPPERED	B BOY'S RESTROOM, FLOOR THROUGHOUT	S
	B GIRL'S RESTROOM, FLOOR THROUGHOUT	
	A ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	S
	B ELECTRICAL ROOM, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	C ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	
	FIRE RISER, NORTH, EAST AND SOUTH WALLS, CEILING THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	S
	B ELECTRICAL ROOM, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	C ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	
	FIRE RISER, NORTH, EAST AND SOUTH WALLS, CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	S
	B ELECTRICAL ROOM, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	C ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	
	FIRE RISER, NORTH, EAST AND SOUTH WALLS, CEILING THROUGHOUT	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	B JANITOR, NORTH, EAST AND SOUTH WALLS	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	B ELECTRICAL ROOM, NORTH WALL	
	KILN ROOM, NORTH, EAST AND SOUTH WALLS	
	C ELECTRICAL ROOM, PORTION OF WEST WALL	
	FIRE RISER, WEST WALL	
	EXTERIOR, PORTION OF EAST AND SOUTH WALLS	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	KINDER PLAY AREA, EAST, WEST AND SOUTH WALLS	S
	B JANITOR, NORTH, EAST AND SOUTH WALLS	
	B ELECTRICAL ROOM, NORTH WALL	
	KILN ROOM, WALLS THROUGHOUT	
	C ELECTRICAL ROOM, PORTION OF WEST WALL	
	FIRE RISER, WEST WALL	
	EXTERIOR, WALLS THROUGHOUT	
CONCRETE, GRAY, CEMENTITIOUS	RECEPTION, FLOOR THROUGHOUT	S
	HALLWAY 1, FLOOR THROUGHOUT	
	SUPPLIES, FLOOR THROUGHOUT	
	NURSE OFFICE, FLOOR THROUGHOUT	
	NURSE RESTROOM, FLOOR THROUGHOUT	
	TREATMENT ROOM, FLOOR THROUGHOUT	
	HALLWAY 2, FLOOR THROUGHOUT	
	PRINCIPAL, FLOOR THROUGHOUT	
	PRINCIPAL CLOSET, FLOOR THROUGHOUT	
	FOYER, FLOOR THROUGHOUT	
	PSYCHOLOGIST OFFICE, FLOOR THROUGHOUT	
	PSYCHOLOGIST OFFICE CLOSET, FLOOR THROUGHOUT	
	ASSISTANT PRINCIPAL, FLOOR THROUGHOUT	
	ASSISTANT PRINCIPAL CLOSET, FLOOR THROUGHOUT	
	LOUNGE, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	WORKROOM 1, FLOOR THROUGHOUT	
	PHONE ROOM, FLOOR THROUGHOUT	
	STORAGE 1, FLOOR THROUGHOUT	
	STAFF MEN'S RESTROOM, FLOOR THROUGHOUT	
	STAFF WOMEN'S RESTROOM, FLOOR THROUGHOUT	
	CORRIDOR 1, FLOOR THROUGHOUT	
	CORRIDOR 2, FLOOR THROUGHOUT	
	CORRIDOR 3, FLOOR THROUGHOUT	
	CORRIDOR 4, FLOOR THROUGHOUT	
	SPEECH ROOM, FLOOR THROUGHOUT	
	CONFERENCE ROOM, FLOOR THROUGHOUT	
	COMPUTER ROOM 401, FLOOR THROUGHOUT	
	RESOURCE ROOM 402, FLOOR THROUGHOUT	
	RESOURCE ROOM 403, FLOOR THROUGHOUT	
	402/403 RESTROOM, FLOOR THROUGHOUT	
	EXTENDED RESOURCE ROOM 404, FLOOR THROUGHOUT	
	404 CLOSET, FLOOR THROUGHOUT	
	404 RESTROOM, FLOOR THROUGHOUT	
	GIFTED CLASSROOM 405, FLOOR THROUGHOUT	
	K-3, FLOOR THROUGHOUT	
	MEDIA CENTER, FLOOR THROUGHOUT	
	CONFERENCE ROOM 412, FLOOR THROUGHOUT	
	WORKROOM 2, FLOOR THROUGHOUT	
	ELECTRICAL ROOM, FLOOR THROUGHOUT	
	BREAK-OUT 1, FLOOR THROUGHOUT	
	BREAK-OUT 2, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	CLASSROOM 1 A1, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	A ELECTRICAL ROOM, FLOOR THROUGHOUT	
	CLASSROOM 2 A12, FLOOR THROUGHOUT	
	CLASSROOM 3 A2, FLOOR THROUGHOUT	
	CLASSROOM 4 A11, FLOOR THROUGHOUT	
	NORTH A FOYER, FLOOR THROUGHOUT	
	CLASSROOM 5 A3, FLOOR THROUGHOUT	
	CLASSROOM 6 A10, FLOOR THROUGHOUT	
	CLASSROOM 7 A4, FLOOR THROUGHOUT	
	CLASSROOM 8 A9, FLOOR THROUGHOUT	
	SOUTH A FOYER, FLOOR THROUGHOUT	
	KINDERGARTEN 1 A5, FLOOR THROUGHOUT	
	A5 RESTROOM, FLOOR THROUGHOUT	
	KINDERGARTEN 2 A8, FLOOR THROUGHOUT	
	A8 RESTROOM, FLOOR THROUGHOUT	
	CLASSROOM 1 B1, FLOOR THROUGHOUT	
	CLASSROOM 2 B9, FLOOR THROUGHOUT	
	CLASSROOM 3 B2, FLOOR THROUGHOUT	
	CLASSROOM 4 B8, FLOOR THROUGHOUT	
	NORTH B FOYER, FLOOR THROUGHOUT	
	CLASSROOM 5 B3, FLOOR THROUGHOUT	
	CLASSROOM 6 B7, FLOOR THROUGHOUT	
	CLASSROOM 7 B4, FLOOR THROUGHOUT	
	ART ROOM B6, FLOOR THROUGHOUT	
	SOUTH B FOYER, FLOOR THROUGHOUT	
	B JANITOR, FLOOR THROUGHOUT	
	B ELECTRICAL ROOM, FLOOR THROUGHOUT	
	B BOY'S RESTROOM VESTIBULE, FLOOR THROUGHOUT	
	B BOY'S RESTROOM, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	B GIRL'S RESTROOM VESTIBULE, FLOOR THROUGHOUT	
	B GIRL'S RESTROOM, FLOOR THROUGHOUT	
	C1, FLOOR THROUGHOUT	
	C2, FLOOR THROUGHOUT	
	C3, FLOOR THROUGHOUT	
	C4, FLOOR THROUGHOUT	
	C FOYER, FLOOR THROUGHOUT	
	C ART ROOM, FLOOR THROUGHOUT	
	KILN ROOM, FLOOR THROUGHOUT	
	STORAGE, FLOOR THROUGHOUT	
	C BOY'S RESTROOM, FLOOR THROUGHOUT	
	FIRE RISER, FLOOR THROUGHOUT	
	C ELECTRICAL ROOM, FLOOR THROUGHOUT	
	C GIRL'S RESTROOM, FLOOR THROUGHOUT	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	S
	B ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	S
	B ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	KINDER PLAY AREA, EAST, WEST AND SOUTH WALLS	S
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALL	
SEALANT, BROWN, PLIABLE	KILN, DOORS THROUGHOUT	S
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	C BOY'S RESTROOM, WALLS THROUGHOUT	S
	C GIRL'S RESTROOM, WALLS THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE, 4"X4", GRAY, SMOOTH	C BOY'S RESTROOM, WALLS THROUGHOUT	S
	C ELECTRICAL ROOM, PORTION OF WEST AND SOUTH WALLS	
	C GIRL'S RESTROOM, WALLS THROUGHOUT	
GLAZED WALL TILE, 4"X4", GRAY, SMOOTH	C GIRL'S RESTROOM, PORTION OF EAST WALL (PATCH)	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, METAL CAP	ROOF, PORTION OF	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF, PORTION OF	S
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE, SILVER	ROOF THROUGHOUT	S
SEALANT (FLASHING), WHITE, BRITTLE	ROOF THROUGHOUT	S
STUCCO, GRAY, CEMENTITIOUS	ROOF, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
SEALANT (EQUIPMENT), GRAY, BRITTLE	ROOF, PORTION OF HVAC EQUIPMENT	S
SEALANT (EQUIPMENT), YELLOW, CLAY-LIKE	ROOF, PORTION OF HVAC EQUIPMENT	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF, PORTION OF	S
CONCRETE MASONRY UNIT, 3"X16", GRAY, CEMENTITIOUS	KINDER PLAY AREA, EAST, WEST AND SOUTH WALLS	S
	EXTERIOR, PORTION OF EAST, WEST AND SOUTH WALLS	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S
EXPANSION JOINT, BROWN, BRITTLE	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	CAFETERIA, CEILING THROUGHOUT	S
	CAFETERIA STORAGE, CEILING THROUGHOUT	
	P.E. OFFICE, CEILING THROUGHOUT	
	P.E. STORAGE, CEILING THROUGHOUT	
	CORRIDOR, CEILING THROUGHOUT	
	CORRIDOR, CEILING THROUGHOUT	
	EAST WING, CEILING THROUGHOUT	
	SOUTH WING, CEILING THROUGHOUT	
	WEST WING, CEILING THROUGHOUT	
	ROOM 607, CEILING THROUGHOUT	
	ROOM 608, CEILING THROUGHOUT	
	INSTRUMENT 1, CEILING THROUGHOUT	
	INSTRUMENT 2, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CAFETERIA, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	CAFETERIA STORAGE, WALLS THROUGHOUT	
	WATER HEATER CLOSET, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	P.E. OFFICE, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	P.E. STORAGE, WALLS THROUGHOUT	
	CUSTODIAL, NORTH AND EAST WALLS	
	OFFICE, WALLS AND CEILING THROUGHOUT	
	STAGE, WALLS THROUGHOUT	
	STAGE STORAGE, WALLS AND CEILING THROUGHOUT	
	EAST WING, WALLS THROUGHOUT	
	SOUTH WING, WALLS THROUGHOUT	
	WEST WING, WALLS THROUGHOUT	
	SOUTH FOYER, WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	ROOM 607, SOUTH AND PORTION OF NORTH, EAST AND WEST WALLS	
	ROOM 608, NORTH AND PORTION OF EAST, WEST AND SOUTH WALLS	
	EXTERIOR STORAGE, NORTH AND WEST WALLS, CEILING THROUGHOUT	
	INSTRUMENT 1, WALLS THROUGHOUT	
	INSTRUMENT 2, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CAFETERIA, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	CAFETERIA STORAGE, WALLS THROUGHOUT	
	WATER HEATER CLOSET, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	P.E. OFFICE, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	P.E. STORAGE, WALLS THROUGHOUT	
	CUSTODIAL, NORTH AND EAST WALLS	
	OFFICE, WALLS AND CEILING THROUGHOUT	
	STAGE, WALLS THROUGHOUT	
	STAGE STORAGE, WALLS AND CEILING THROUGHOUT	
	EAST WING, WALLS THROUGHOUT	
	SOUTH WING, WALLS THROUGHOUT	
	WEST WING, WALLS THROUGHOUT	
	SOUTH FOYER, WALLS THROUGHOUT	
	ROOM 607, SOUTH AND PORTION OF NORTH, EAST AND WEST WALLS	
	ROOM 608, NORTH AND PORTION OF EAST, WEST AND SOUTH WALLS	
	INSTRUMENT 1, WALLS THROUGHOUT	
	INSTRUMENT 2, WALLS THROUGHOUT	
	EXTERIOR STORAGE, NORTH AND WEST WALLS, CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CAFETERIA, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	CAFETERIA STORAGE, WALLS THROUGHOUT	
	WATER HEATER CLOSET, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	
	P.E. OFFICE, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	P.E. STORAGE, WALLS THROUGHOUT	
	CUSTODIAL, NORTH AND EAST WALLS	
	OFFICE, WALLS AND CEILING THROUGHOUT	
	STAGE, WALLS THROUGHOUT	
	STAGE STORAGE, WALLS AND CEILING THROUGHOUT	
	EAST WING, WALLS THROUGHOUT	
	SOUTH WING, WALLS THROUGHOUT	
	WEST WING, WALLS THROUGHOUT	
	SOUTH FOYER, WALLS THROUGHOUT	
	ROOM 607, SOUTH AND PORTION OF NORTH, EAST AND WEST WALLS	
	ROOM 608, NORTH AND PORTION OF EAST, WEST AND SOUTH WALLS	
	INSTRUMENT 1, WALLS THROUGHOUT	
	INSTRUMENT 2, WALLS THROUGHOUT	
	EXTERIOR STORAGE, NORTH AND WEST WALLS, CEILING THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	P.E. OFFICE, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	ROOM 607, PORTION OF NORTH WALL	
	ROOM 608, PORTION OF WEST WALL	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	P.E. OFFICE, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	ROOM 607, PORTION OF NORTH WALL	
	ROOM 608, PORTION OF WEST WALL	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CAFETERIA, BASE OF NORTH, EAST, SOUTH AND PORTION OF WEST WALLS	S
	WATER HEATER CLOSET, BASE OF WALLS THROUGHOUT	
	P.E. OFFICE, BASE OF WALLS THROUGHOUT	
	P.E. STORAGE, BASE OF WALLS THROUGHOUT	
	CORRIDOR, BASE OF WALLS THROUGHOUT	
	CUSTODIAL, BASE OF WALLS THROUGHOUT	
	OFFICE, BASE OF WALLS THROUGHOUT	
	ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	STAGE, BASE OF WALLS THROUGHOUT	
	EAST WING, BASE OF WALLS THROUGHOUT	
	SOUTH WING, BASE OF WALLS THROUGHOUT	
	WEST WING, BASE OF WALLS THROUGHOUT	
	SOUTH FOYER, BASE OF WALLS THROUGHOUT	
	ROOM 607, BASE OF NORTH, EAST, SOUTH AND PORTION OF WEST WALLS	
	ROOM 608, BASE OF NORTH, WEST, SOUTH AND PORTION OF EAST WALLS	
	INSTRUMENT 1, BASE OF WALLS THROUGHOUT	
	INSTRUMENT 2, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CAFETERIA, BASE OF NORTH, EAST, SOUTH AND PORTION OF WEST WALLS	S
	WATER HEATER CLOSET, BASE OF WALLS THROUGHOUT	
	P.E. OFFICE, BASE OF WALLS THROUGHOUT	
	P.E. STORAGE, BASE OF WALLS THROUGHOUT	
	CORRIDOR, BASE OF WALLS THROUGHOUT	
	CUSTODIAL, BASE OF WALLS THROUGHOUT	
	OFFICE, BASE OF WALLS THROUGHOUT	
	ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
	STAGE, BASE OF WALLS THROUGHOUT	
	EAST WING, BASE OF WALLS THROUGHOUT	
	SOUTH WING, BASE OF WALLS THROUGHOUT	
	WEST WING, BASE OF WALLS THROUGHOUT	
	SOUTH FOYER, BASE OF WALLS THROUGHOUT	
	ROOM 607, BASE OF NORTH, EAST, SOUTH AND PORTION OF WEST WALLS	
	ROOM 608, BASE OF NORTH, WEST, SOUTH AND PORTION OF EAST WALLS	
	INSTRUMENT 1, BASE OF WALLS THROUGHOUT	
	INSTRUMENT 2, BASE OF WALLS THROUGHOUT	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY AND WHITE MOTTLES	ROOM 607, WET AREA AND NORTH ENTRY PORTION OF FLOOR	S
	ROOM 608, WET AREA AND SOUTH ENTRY PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	INSTRUMENT 1, FLOOR THROUGHOUT	
	INSTRUMENT 2, FLOOR THROUGHOUT	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY AND WHITE MOTTLES AND CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS AND VINYL COMPOSITION TILE, 12"X12", SMOOTH, TAN AND GRAY MOTTLES AND VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN AND GRAY MOTTLES AND VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BLUE MOTTLES AND VINYL COMPOSITION TILE, 12"X12", VARIOUS, SMOOTH, STRIP AND VINYL COMPOSITION TILE, 2"X24", VARIOUS, SMOOTH, STRIP	CAFETERIA, FLOOR THROUGHOUT	S
	CAFETERIA STORAGE, FLOOR THROUGHOUT	
	P.E. OFFICE, FLOOR THROUGHOUT	
	P.E. STORAGE, FLOOR THROUGHOUT	
	CORRIDOR, FLOOR THROUGHOUT	
	CUSTODIAL, FLOOR THROUGHOUT	
	OFFICE, FLOOR THROUGHOUT	
	STAGE, FLOOR THROUGHOUT	
	STAGE STORAGE, FLOOR THROUGHOUT	
	EAST WING, FLOOR THROUGHOUT LESS STAIRS	
	SOUTH WING, FLOOR THROUGHOUT LESS STAIRS	
	WEST WING, FLOOR THROUGHOUT LESS STAIRS	
	SOUTH FOYER, FLOOR THROUGHOUT	
	ROOM 607, FLOOR THROUGHOUT	
	ROOM 608, FLOOR THROUGHOUT	
	INSTRUMENT 1, FLOOR THROUGHOUT	
	INSTRUMENT 2, FLOOR THROUGHOUT	
SINK ACOUSTICAL COATING, GRAY, ROUGH	STAGE, NORTH SINK	S
	ROOM 607, NORTH SINK	
	ROOM 608, SOUTH SINK	
FIRE DOOR INSULATION, METAL CLADDING	CAFETERIA, EAST AND SOUTH DOORS	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CAFETERIA ELECTRICAL ROOM, SOUTH DOOR	
	KITCHEN, NORTH DOORS	
	KITCHEN PATIO, SOUTH DOORS	
	WATER HEATER CLOSET, NORTH DOOR	
	CORRIDOR, NORTH DOORS	
	ELECTRICAL ROOM, NORTH DOOR	
	ELECTRICAL YARD, EAST, WEST AND SOUTH DOORS	
	ROOM 607, SOUTH DOORS	
	ROOM 608, EAST AND WEST DOORS	
	SOUTH FOYER, SOUTH DOOR	
	EXISTING BOY'S RESTROOM, EAST DOOR	
	EXISTING GIRL'S RESTROOM, EAST DOOR	
	EXTERIOR STORAGE, EAST DOOR	
	MECHANICAL ROOM, NORTH DOOR	
	CHILLER ROOM, EAST DOOR	
	EXTERIOR, NORTH, EAST, WEST AND SOUTH DOORS	
SEALANT, WHITE, PLIABLE	CAFETERIA, DOORS THROUGHOUT, EAST WINDOWS	
	CAFETERIA ELECTRICAL ROOM, SOUTH DOOR	
	CAFETERIA STORAGE, SOUTH DOORS, MILLWORK	
	KITCHEN, SOUTH DOOR	
	WATER HEATER CLOSET, NORTH DOOR	
	P.E. STORAGE, SOUTH DOORS	
	CORRIDOR, DOORS THROUGHOUT	
	CUSTODIAL, EAST DOOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	OFFICE, EAST DOOR	
	ELECTRICAL YARD, PORTION OF NORTH WALL	
	STAGE, NORTH DOOR, MILLWORK	
	STAGE STORAGE, SOUTH DOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	EAST WING, EAST DOOR	
	SOUTH WING, EAST AND SOUTH DOORS	
	ROOM 607, EAST AND WEST DOORS, MILLWORK	
	ROOM 608, EAST, WEST AND SOUTH DOORS, MILLWORK	
	SOUTH FOYER, DOORS THROUGHOUT	
	EXISTING BOY'S RESTROOM, EAST DOOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, MILLWORK	
	EXISTING GIRL'S RESTROOM, EAST DOOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, MILLWORK	
	EXTERIOR STORAGE, EAST DOOR	
	INSTRUMENT 1, NORTH DOOR	
	INSTRUMENT 2, EAST DOOR	
GLASS BLOCK, 8"X8", CLEAR	CAFETERIA, EAST AND SOUTH WINDOWS	N
	ROOM 607, SOUTH WINDOWS	
	ROOM 608, EAST WINDOWS	
	SOUTH FOYER, SOUTH WINDOWS	
	EXTERIOR, EAST AND SOUTH WINDOWS	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	CAFETERIA, EAST AND SOUTH WINDOWS	S
	ROOM 607, SOUTH WINDOWS	
	ROOM 608, EAST WINDOWS	
	SOUTH FOYER, SOUTH WINDOWS	
	EXTERIOR, EAST AND SOUTH WINDOWS	
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	ROOM 607, PORTION OF NORTH WALL	N
	ROOM 608, PORTION OF SOUTH WALL	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	ROOM 607, PORTION OF NORTH WALL	S
	ROOM 608, PORTION OF SOUTH WALL	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	P.E. OFFICE, FLOOR THROUGHOUT	S
	STAGE, PORTION OF FLOOR	
	ROOM 607, FLOOR THROUGHOUT LESS WET AREA AND NORTH ENTRY	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	ROOM 608, FLOOR THROUGHOUT LESS WET AREA AND SOUTH ENTRY	
FIRE DOOR INSULATION, WOOD CLADDING	CAFETERIA, NORTH AND EAST DOORS	S
	CAFETERIA STORAGE, SOUTH DOORS	
	GIRL'S RESTROOM, SOUTH DOOR	
	BOY'S RESTROOM, WEST DOOR	
	KITCHEN, SOUTH DOOR	
	P.E. STORAGE, SOUTH DOORS	
	CORRIDOR, SOUTH DOORS	
	CUSTODIAL, EAST DOOR	
	OFFICE, EAST DOOR	
	STAGE STORAGE, SOUTH DOOR	
	EAST WING, EAST DOOR	
	SOUTH WING, EAST AND SOUTH DOORS	
	WEST WING, EAST DOOR	
	SOUTH FOYER, NORTH AND WEST DOORS	
	ROOM 607, EAST AND WEST DOORS	
	ROOM 608, EAST DOOR	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN AND GRAY MOTTLES	P.E. OFFICE, FLOOR THROUGHOUT	S
	STAGE, FLOOR THROUGHOUT	
	STAGE STORAGE, FLOOR THROUGHOUT	
	EAST WING, FLOOR THROUGHOUT LESS STAIRS	
	SOUTH WING, FLOOR THROUGHOUT LESS STAIRS	
	WEST WING, FLOOR THROUGHOUT LESS STAIRS	
	SOUTH FOYER, FLOOR THROUGHOUT	
VINYL STAIR TREAD, 36"X12", BROWN, TEXTURED, VINYL-LIKE, CIRCLE PATTERN	EAST WING, STAIRS	S
	SOUTH WING, STAIRS	
	WEST WING, STAIRS	
MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 36"X12", BROWN, TEXTURED, VINYL-LIKE, CIRCLE PATTERN	EAST WING, STAIRS	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	SOUTH WING, STAIRS	
	WEST WING, STAIRS	
ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	STAGE, SKYLIGHTS	S
	SOUTH FOYER, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	STAGE, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, SKYLIGHTS	S
	SOUTH FOYER, CEILING THROUGHOUT	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BLUE MOTTLES	CAFETERIA, FLOOR THROUGHOUT (MAIN)	S
	CAFETERIA STORAGE, FLOOR THROUGHOUT	
	P.E. STORAGE, FLOOR THROUGHOUT	
	CORRIDOR, FLOOR THROUGHOUT	
	CUSTODIAL, FLOOR THROUGHOUT	
	OFFICE, FLOOR THROUGHOUT	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	CAFETERIA, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	CAFETERIA ELECTRICAL ROOM, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	WATER HEATER CLOSET, NORTH WALL	
	ELECTRICAL ROOM, NORTH AND WEST WALLS	
	ELECTRICAL YARD, NORTH, EAST AND PORTION OF WEST WALLS	
	EXTERIOR STORAGE, WEST AND SOUTH WALLS	
	MECHANICAL ROOM, WALLS THROUGHOUT	
	CHILLER ROOM, WALLS THROUGHOUT	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	CAFETERIA, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	CAFETERIA ELECTRICAL ROOM, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	WATER HEATER CLOSET, NORTH WALL	
	ELECTRICAL ROOM, NORTH AND WEST WALLS	
	ELECTRICAL YARD, WALLS THROUGHOUT	
	EXTERIOR STORAGE, WEST AND SOUTH WALLS	
	MECHANICAL ROOM, WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CHILLER ROOM, WALLS THROUGHOUT	
	EXTERIOR, WALLS THROUGHOUT	
VINYL COMPOSITION TILE, 12"X12", VARIOUS, SMOOTH, STRIP	CAFETERIA, FLOOR THROUGHOUT (PATTERN)	S
VINYL COMPOSITION TILE, 2"X24", VARIOUS, SMOOTH, STRIP	CAFETERIA, FLOOR THROUGHOUT (PATTERN)	S
GYPSUM WALLBOARD, WHITE, CHALKY	CAFETERIA ELECTRICAL ROOM, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	S
	ELECTRICAL ROOM, EAST AND SOUTH WALLS, CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CAFETERIA ELECTRICAL ROOM, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, CEILING THROUGHOUT	S
	ELECTRICAL ROOM, EAST AND SOUTH WALLS, CEILING THROUGHOUT	
CONCRETE, GRAY, CEMENTITIOUS	CAFETERIA, FLOOR THROUGHOUT	S
	CAFETERIA ELECTRICAL ROOM, FLOOR THROUGHOUT	
	CAFETERIA STORAGE, FLOOR THROUGHOUT	
	GIRL'S RESTROOM, FLOOR THROUGHOUT	
	BOY'S RESTROOM, FLOOR THROUGHOUT	
	KITCHEN, FLOOR THROUGHOUT	
	KITCHEN PATIO, FLOOR THROUGHOUT	
	WATER HEATER CLOSET, FLOOR THROUGHOUT	
	P.E. OFFICE, FLOOR THROUGHOUT	
	P.E. STORAGE, FLOOR THROUGHOUT	
	CORRIDOR, FLOOR THROUGHOUT	
	CUSTODIAL, FLOOR THROUGHOUT	
	OFFICE, FLOOR THROUGHOUT	
	ELECTRICAL ROOM, FLOOR THROUGHOUT	
	ELECTRICAL YARD, FLOOR THROUGHOUT	
	STAGE, FLOOR THROUGHOUT	
	STAGE STORAGE, FLOOR THROUGHOUT	
	EAST WING, FLOOR THROUGHOUT	
	SOUTH WING, FLOOR THROUGHOUT	
	WEST WING, FLOOR THROUGHOUT	



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	SOUTH FOYER, FLOOR THROUGHOUT	
	ROOM 607, FLOOR THROUGHOUT	
	ROOM 608, FLOOR THROUGHOUT	
	EXISTING BOY'S RESTROOM, FLOOR THROUGHOUT	
	EXISTING GIRL'S RESTROOM, FLOOR THROUGHOUT	
	EXTERIOR STORAGE, FLOOR THROUGHOUT	
	INSTRUMENT 1, FLOOR THROUGHOUT	
	INSTRUMENT 2, FLOOR THROUGHOUT	
	MECHANICAL ROOM, FLOOR THROUGHOUT	
	CHILLER ROOM, FLOOR THROUGHOUT	
GLAZED WALL TILE, 4"X4", PINK, SMOOTH	GIRL'S RESTROOM, WALLS THROUGHOUT	S
	BOY'S RESTROOM, WALLS THROUGHOUT	
	KITCHEN PATIO, PORTION OF WEST AND SOUTH WALLS	
	CUSTODIAL, PORTION OF EAST AND SOUTH WALLS	
	EXISTING BOY'S RESTROOM, WALLS THROUGHOUT	
	EXISTING GIRL'S RESTROOM, WALLS THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH	GIRL'S RESTROOM, WALLS THROUGHOUT	S
	BOY'S RESTROOM, WALLS THROUGHOUT	
	KITCHEN PATIO, PORTION OF WEST AND SOUTH WALLS	
	CUSTODIAL, PORTION OF EAST AND SOUTH WALLS	
	EXISTING BOY'S RESTROOM, WALLS THROUGHOUT	
	EXISTING GIRL'S RESTROOM, WALLS THROUGHOUT	
ACOUSTICAL CEILING PANEL, 2'X2', WHITE, CHALKY, VINYL COVER	KITCHEN, CEILING THROUGHOUT	S
GYPSUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM, CEILING THROUGHOUT	S
	BOY'S RESTROOM, CEILING THROUGHOUT	
	KITCHEN, WALLS THROUGHOUT	
	EXISTING BOY'S RESTROOM, CEILING THROUGHOUT	
	EXISTING GIRL'S RESTROOM, CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM, CEILING THROUGHOUT	S
	BOY'S RESTROOM, CEILING THROUGHOUT	
	KITCHEN, WALLS THROUGHOUT	
	EXISTING BOY'S RESTROOM, CEILING THROUGHOUT	
	EXISTING GIRL'S RESTROOM, CEILING THROUGHOUT	
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	KITCHEN, WALLS THROUGHOUT	S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	KITCHEN, WALLS THROUGHOUT	S
QUARRY/PAVER TILE, 6"X6", GRAY, SMOOTH, PEPPERED	KITCHEN, FLOOR AND BASE OF WALLS THROUGHOUT	S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", GRAY, SMOOTH, PEPPERED	KITCHEN, FLOOR AND BASE OF WALLS THROUGHOUT	S
CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, PEPPERED	GIRL'S RESTROOM, FLOOR THROUGHOUT	S
	BOY'S RESTROOM, FLOOR THROUGHOUT	
	EXISTING BOY'S RESTROOM, FLOOR THROUGHOUT	
	EXISTING GIRL'S RESTROOM, FLOOR THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, PEPPERED AND QUARRY/PAVER TILE (TRANSITION STRIP), 2"X36", GRAY, SMOOTH, MARBLED	GIRL'S RESTROOM, FLOOR THROUGHOUT	S
	BOY'S RESTROOM, FLOOR THROUGHOUT	
	EXISTING BOY'S RESTROOM, FLOOR THROUGHOUT	
	EXISTING GIRL'S RESTROOM, FLOOR THROUGHOUT	
SEALANT, BROWN, PLIABLE	EXISTING BOY'S RESTROOM, EAST DOOR	S
	EXISTING GIRL'S RESTROOM, EAST DOOR	
QUARRY/PAVER TILE (TRANSITION STRIP), 2"X36", GRAY, SMOOTH, MARBLED	BOY'S RESTROOM, ENTRY PORTION OF FLOOR	S
	GIRL'S RESTROOM, ENTRY PORTION OF FLOOR	
	EXISTING BOY'S RESTROOM, ENTRY PORTION OF FLOOR	
	EXISTING GIRL'S RESTROOM, ENTRY PORTION OF FLOOR	
SEALANT, TAN, PLIABLE	ELECTRICAL ROOM, NORTH DOOR	S
	ELECTRICAL YARD, SOUTH DOOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	MECHANICAL ROOM, WEST DOOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CHILLER ROOM, EAST DOOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	EXTERIOR, NORTH, EAST, WEST AND SOUTH DOORS	
PIPE END SEALANT, WHITE, BRITTLE	MECHANICAL ROOM, PIPING THROUGHOUT	S
SEALANT (EQUIPMENT), BLACK, TAR-LIKE	CHILLER ROOM, CHILLERS	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	ELECTRICAL YARD, SOUTH AND PORTION OF WEST WALLS	S
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF THROUGHOUT	S
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
COATING, WHITE, PLIABLE	ROOF THROUGHOUT	S
SEALANT (FLASHING), WHITE, PLIABLE	ROOF, PARAPETS THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, NORTH, EAST AND SOUTH ENTRIES	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable D1/D2*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	D1, CEILING THROUGHOUT	S
	D2, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	D1, CEILING THROUGHOUT	S
	D2, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	D1, WALLS THROUGHOUT	S
	D2, WALLS THROUGHOUT	
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	D1, WALLS THROUGHOUT	S
	D2, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	D1, WALLS THROUGHOUT	S
	D2, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	D1, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	D2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	D1, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	D2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	D1, BASE OF WALLS THROUGHOUT	S
	D2, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	D1, BASE OF WALLS THROUGHOUT	S
	D2, BASE OF WALLS THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	D1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	D2, WET AREA AND ENTRY PORTIONS OF FLOOR	
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	D1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	D2, WET AREA AND ENTRY PORTIONS OF FLOOR	
CARPET, BLUE, FIBROUS, MULTI-COLORED	D1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	D2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable D1/D2*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	D1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	D2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
FIRE DOOR INSULATION, METAL CLADDING	D1, EAST DOORS	S
	D2, EAST DOORS	
	RESTROOM, NORTH DOOR	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	D1, EAST DOORS, MILLWORK	S
	D2, EAST DOORS, MILLWORK	
SINK ACOUSTICAL COATING, WHITE, ROUGH	D1, NORTH SINK	S
	D2, SOUTH SINK	
SEALANT (DUCT), WHITE, BRITTLE	D1, DUCTWORK BELOW CEILING	S
	D2, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, BLACK, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM, WALLS AND CEILING THROUGHOUT	S
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM, WALLS AND CEILING THROUGHOUT	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	RESTROOM, WALLS AND CEILING THROUGHOUT	S
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	RESTROOM, FLOOR THROUGHOUT	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	RESTROOM, FLOOR THROUGHOUT	S
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	RESTROOM, PORTION OF NORTH WALL	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	RESTROOM, PORTION OF NORTH WALL	N
SEALANT, WHITE, PLIABLE	RESTROOM, FIXTURES, MILLWORK	S
SEALANT, YELLOW, PLIABLE	RESTROOM, PORTION OF NORTH WALL	S
PANELING (METAL)	ROOF THROUGHOUT	N
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*  
*Kyrene Del Cielo Elementary School*  
*Portable D1/D2*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M1/M2*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	M1, CEILING THROUGHOUT	S
	M2, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	M1, CEILING THROUGHOUT	S
	M2, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	M1, WALLS THROUGHOUT	S
	M2, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	M1, WALLS THROUGHOUT	S
	M2, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	M1, WALLS THROUGHOUT	S
	M2, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	M1, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	S
	M2, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	M1, EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	S
	M2, WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	M1, BASE OF WALLS THROUGHOUT	S
	M2, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	M1, BASE OF WALLS THROUGHOUT	S
	M2, BASE OF WALLS THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	M1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	M2, WET AREA AND ENTRY PORTIONS OF FLOOR	
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	M1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	M2, WET AREA AND ENTRY PORTIONS OF FLOOR	
CARPET, BLUE, FIBROUS, MULTI-COLORED	M1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	M2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M1/M2*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	M1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	M2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
FIRE DOOR INSULATION, METAL CLADDING	M1, NORTH DOORS	S
	M2, NORTH DOORS	
	GIRL'S RESTROOM, EAST DOOR	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	M1, NORTH DOORS, MILLWORK	S
	M2, NORTH DOORS, MILLWORK	
SINK ACOUSTICAL COATING, WHITE, ROUGH	M1, WEST SINK	S
	M2, EAST SINK	
SEALANT (DUCT), WHITE, BRITTLE	M1, DUCTWORK BELOW CEILING	S
	M2, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, BLACK, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	GIRL'S RESTROOM, FLOOR THROUGHOUT	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	GIRL'S RESTROOM, FLOOR THROUGHOUT	S
SEALANT, WHITE, PLIABLE	GIRL'S RESTROOM, FIXTURES, MILLWORK	S
PANELING (METAL)	ROOF THROUGHOUT	N
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M3/M4*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	M3, CEILING THROUGHOUT	S
	M4, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	M3, CEILING THROUGHOUT	S
	M4, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	M3, WALLS THROUGHOUT	S
	M4, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	M3, WALLS THROUGHOUT	S
	M4, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	M3, WALLS THROUGHOUT	S
	M4, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	M3, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	M4, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	M3, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	M4, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	M3, BASE OF WALLS THROUGHOUT	S
	M4, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	M3, BASE OF WALLS THROUGHOUT	S
	M4, BASE OF WALLS THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	M3, WET AREA, ENTRIES AND PORTION OF FLOOR	S
	M3 RESTROOM, FLOOR THROUGHOUT	
	M4, WET AREA, ENTRIES AND PORTION OF FLOOR	
	M4 RESTROOM, FLOOR THROUGHOUT	
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	M3, WET AREA, ENTRIES AND PORTION OF FLOOR	S
	M3 RESTROOM, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M3/M4*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	M4, WET AREA, ENTRIES AND PORTION OF FLOOR	
	M4 RESTROOM, FLOOR THROUGHOUT	
CARPET, BLUE, FIBROUS, MULTI-COLORED	M3, PORTION OF FLOOR	S
	M4, PORTION OF FLOOR	
MASTIC, YELLOW, FIBROUS, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	M3, PORTION OF FLOOR	S
	M4, PORTION OF FLOOR	
FIRE DOOR INSULATION, METAL CLADDING	M3, SOUTH DOORS	S
	M4, SOUTH DOORS	
	BOY'S RESTROOM, EAST DOOR	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	M3, PORTION OF NORTH WALL, SOUTH DOORS, MILLWORK	S
	M3 RESTROOM, FIXTURES	
	M4, PORTION OF NORTH WALL, SOUTH DOORS, MILLWORK	
	M4 RESTROOM, FIXTURES	
SINK ACOUSTICAL COATING, WHITE, ROUGH	M3, WEST SINK	S
	M4, EAST SINK	
SEALANT (DUCT), WHITE, BRITTLE	M3, DUCTWORK BELOW CEILING	S
	M4, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, BLACK, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	M3 RESTROOM, WALLS AND CEILING THROUGHOUT	S
	M4 RESTROOM, WALLS AND CEILING THROUGHOUT	
	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	M3 RESTROOM, WALLS AND CEILING THROUGHOUT	S
	M4 RESTROOM, WALLS AND CEILING THROUGHOUT	
	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	M3 RESTROOM, WALLS AND CEILING THROUGHOUT	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M3/M4*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
	M4 RESTROOM, WALLS AND CEILING THROUGHOUT	
	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	BOY'S RESTROOM, FLOOR THROUGHOUT	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	BOY'S RESTROOM, FLOOR THROUGHOUT	S
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	BOY'S RESTROOM, PORTION OF EAST WALL	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	BOY'S RESTROOM, PORTION OF EAST WALL	S
SEALANT, WHITE, PLIABLE	BOY'S RESTROOM, FIXTURES, MILLWORK	S
SEALANT, YELLOW, PLIABLE	BOY'S RESTROOM, PORTION OF EAST WALL	S
PANELING (METAL)	ROOF THROUGHOUT	N
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R1/R2*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	R1, CEILING THROUGHOUT	S
	R2, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	R1, CEILING THROUGHOUT	S
	R2, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	R1, WALLS THROUGHOUT	S
	R2, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	R1, WALLS THROUGHOUT	S
	R2, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	R1, WALLS THROUGHOUT	S
	R2, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	R1, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	R2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	R1, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	R2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	R1, BASE OF NORTH, WEST AND PORTION OF EAST AND SOUTH WALLS	S
	R2, BASE OF NORTH, EAST AND PORTION OF WEST AND SOUTH WALLS	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	R1, BASE OF NORTH, WEST AND PORTION OF EAST AND SOUTH WALLS	S
	R2, BASE OF NORTH, EAST AND PORTION OF WEST AND SOUTH WALLS	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	R1, BASE OF PORTION OF EAST AND SOUTH WALLS	S
	R2, BASE OF PORTION OF WEST AND SOUTH WALLS	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	R1, BASE OF PORTION OF EAST AND SOUTH WALLS	S
	R2, BASE OF PORTION OF WEST AND SOUTH WALLS	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED	R1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	R2, WET AREA AND ENTRY PORTIONS OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R1/R2*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED	R1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	R2, WET AREA AND ENTRY PORTIONS OF FLOOR	
CARPET, BLUE, FIBROUS, MULTI-COLORED	R1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	R2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	R1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	R2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
FIRE DOOR INSULATION, METAL CLADDING	R1, SOUTH DOORS	S
	R2, SOUTH DOORS	
	GIRL'S RESTROOM, WEST DOOR	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	R1, SOUTH DOORS, MILLWORK	S
	R2, SOUTH DOORS, MILLWORK	
SINK ACOUSTICAL COATING, WHITE, ROUGH	R1, EAST SINK	S
	R2, WEST SINK	
SEALANT (DUCT), WHITE, BRITTLE	R1, DUCTWORK BELOW CEILING	S
	R2, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, BLACK, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE, CIRCLE PATTERN	GIRL'S RESTROOM, PORTION OF FLOOR	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE	GIRL'S RESTROOM, PORTION OF FLOOR	S
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	GIRL'S RESTROOM, PORTION OF FLOOR	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	GIRL'S RESTROOM, PORTION OF FLOOR	S
WALLBASE (COVED), 6", GRAY, VINYL-LIKE	GIRL'S RESTROOM, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R1/R2*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 6", GRAY, VINYL-LIKE	GIRL'S RESTROOM, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
SEALANT, WHITE, PLIABLE	GIRL'S RESTROOM, FIXTURES, MILLWORK	S
PANELING (METAL)	ROOF THROUGHOUT	N
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R3/R4*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	R3, CEILING THROUGHOUT	S
	R4, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	R3, CEILING THROUGHOUT	S
	R4, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	R3, WALLS THROUGHOUT	S
	R4, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	R3, WALLS THROUGHOUT	S
	R4, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	R3, WALLS THROUGHOUT	S
	R4, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	R3, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	R4, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	R3, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	R4, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	R3, BASE OF EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	S
	R4, BASE OF WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	R3, BASE OF EAST, SOUTH AND PORTION OF NORTH AND WEST WALLS	S
	R4, BASE OF WEST, SOUTH AND PORTION OF NORTH AND EAST WALLS	
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	R3, BASE OF PORTION OF NORTH AND WEST WALLS	S
	R4, BASE OF PORTION OF NORTH AND EAST WALLS	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	R3, BASE OF PORTION OF NORTH AND WEST WALLS	S
	R4, BASE OF PORTION OF NORTH AND EAST WALLS	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	R3, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	R4, WET AREA AND ENTRY PORTIONS OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R3/R4*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	R3, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	R4, WET AREA AND ENTRY PORTIONS OF FLOOR	
CARPET, BLUE, FIBROUS, MULTI-COLORED	R3, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	R4, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	R3, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	R4, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
FIRE DOOR INSULATION, METAL CLADDING	R3, NORTH DOORS	S
	R4, NORTH DOORS	
	BOY'S RESTROOM, WEST DOOR	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	R3, NORTH DOORS, MILLWORK	S
	R4, NORTH DOORS, MILLWORK	
SINK ACOUSTICAL COATING, WHITE, ROUGH	R3, WEST SINK	S
	R4, EAST SINK	
SEALANT (DUCT), WHITE, BRITTLE	R3, DUCTWORK BELOW CEILING	S
	R4, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, WHITE, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE	BOY'S RESTROOM, PORTION OF FLOOR	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE	BOY'S RESTROOM, PORTION OF FLOOR	S
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	BOY'S RESTROOM, PORTION OF FLOOR	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	BOY'S RESTROOM, PORTION OF FLOOR	S
WALLBASE (COVED), 6", GRAY, VINYL-LIKE	BOY'S RESTROOM, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH FLOORS	S



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R3/R4*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 6", GRAY, VINYL-LIKE	BOY'S RESTROOM, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH FLOORS	S
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	BOY'S RESTROOM, PORTION OF WEST WALL	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	BOY'S RESTROOM, PORTION OF WEST WALL	S
SEALANT, WHITE, PLIABLE	BOY'S RESTROOM, FIXTURES, MILLWORK	S
SEALANT, BROWN, PLIABLE	BOY'S RESTROOM, MILLWORK	S
SEALANT, YELLOW, PLIABLE	BOY'S RESTROOM, PORTION OF WEST WALL	S
PANELING (METAL)	ROOF THROUGHOUT	N
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable T1/T2*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	T1, CEILING THROUGHOUT	S
	T2, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	T1, CEILING THROUGHOUT	S
	T2, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	T1, WALLS THROUGHOUT	S
	T2, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	T1, WALLS THROUGHOUT	S
	T2, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	T1, WALLS THROUGHOUT	S
	T2, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	T1, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	T2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	T1, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	T2, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	T1, BASE OF WALLS THROUGHOUT	S
	T2, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	T1, BASE OF WALLS THROUGHOUT	S
	T2, BASE OF WALLS THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	T1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	T2, WET AREA AND ENTRY PORTIONS OF FLOOR	
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	T1, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	T2, WET AREA AND ENTRY PORTIONS OF FLOOR	
CARPET, BLUE, FIBROUS, MULTI-COLORED	T1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	T2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable T1/T2*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	T1, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	T2, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
FIRE DOOR INSULATION, METAL CLADDING	T1, NORTH DOORS	S
	T2, NORTH DOORS	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	T1, NORTH DOORS, MILLWORK	S
	T2, NORTH DOORS, MILLWORK	
SINK ACOUSTICAL COATING, WHITE, ROUGH	T1, WEST SINK	S
	T2, EAST SINK	
SEALANT (DUCT), WHITE, BRITTLE	T1, DUCTWORK BELOW CEILING	S
	T2, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, BLACK, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
PANELING (METAL)	ROOF THROUGHOUT	N
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable T3/T4*

JOB NO. 07-326

**TABLE A  
BUILDING MATERIAL SYSTEMS**

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	T3, CEILING THROUGHOUT	S
	T4, CEILING THROUGHOUT	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	T3, CEILING THROUGHOUT	S
	T4, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	T3, WALLS THROUGHOUT	S
	T4, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	T3, WALLS THROUGHOUT	S
	T4, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	T3, WALLS THROUGHOUT	S
	T4, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	T3, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	T4, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	T3, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	T4, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	T3, BASE OF WALLS THROUGHOUT	S
	T4, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	T3, BASE OF WALLS THROUGHOUT	S
	T4, BASE OF WALLS THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	T3, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	T4, WET AREA AND ENTRY PORTIONS OF FLOOR	
MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	T3, WET AREA AND ENTRY PORTIONS OF FLOOR	S
	T4, WET AREA AND ENTRY PORTIONS OF FLOOR	
CARPET, BLUE, FIBROUS, MULTI-COLORED	T3, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	T4, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable T3/T4*

JOB NO. 07-326

<b>MATERIAL DESCRIPTION</b>	<b>MATERIAL LOCATIONS</b>	<b>ACM N/S</b>
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	T3, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	S
	T4, FLOOR THROUGHOUT LESS WET AREA AND ENTRIES	
FIRE DOOR INSULATION, METAL CLADDING	T3, SOUTH DOORS	S
	T4, SOUTH DOORS	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, WHITE, PLIABLE	T3, SOUTH DOORS, MILLWORK	S
	T4, SOUTH DOORS, MILLWORK	
SINK ACOUSTICAL COATING, WHITE, ROUGH	T3, WEST SINK	S
	T4, EAST SINK	
SEALANT (DUCT), WHITE, BRITTLE	T3, DUCTWORK BELOW CEILING	S
	T4, DUCTWORK BELOW CEILING	
SIDING (METAL), PAINTED	EXTERIOR, WALLS THROUGHOUT	N
SEALANT, BLACK, PLIABLE	EXTERIOR, WINDOWS THROUGHOUT	S
PANELING (METAL)	ROOF THROUGHOUT	
	CANOPY, ROOF THROUGHOUT	
MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	ROOF THROUGHOUT	S
	CANOPY, ROOF THROUGHOUT	
COATING (DUCT), WHITE, PLIABLE	CANOPY ROOF, DUCTWORK THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S

END OF TABLE

## **2.4 AHERA Inspection Procedures and Protocols**

### **2.4.1 Inspection Procedures and Protocols**

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
  - ◊ natural friability and,
  - ◊ physical condition and,
  - ◊ if damaged or thermal systems insulation;
    - \* be identified for an immediate response action or,
    - \* be identified for possible future disturbance and
    - \* have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
  - ◊ date accomplished and,
  - ◊ identification and qualification of individuals conducting each activity.

### **2.4.2 FM GROUP INC Inspection SOP**

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

## **2.5 Visual Inspection**

A visual inspection of the nine buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

*A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.*

**2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials**

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

**MAIN BUILDING  
CAFETERIA BUILDING  
PORTABLE D1/D2  
PORTABLE M1/M2  
PORTABLE M3/M4  
PORTABLE R1/R2  
PORTABLE R3/R4  
PORTABLE T1/T2  
PORTABLE T3/T4**

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	47,000	SF
M	GWB	02	GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	36,000	SF
S	JTC	03	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	3,600	SF
M	WAB	04	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	S	NF	1,100	SF
M	ADH	05	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	S	NF	1,100	SF
M	CPT	06	CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED	S	NF	40,000	SF
M	MAS	07	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH CARPET (SELF-STICK), GRAY, FIBROUS, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, WHITE AND GRAY MOTTLES	S	NF	50,000	SF
M	SLT	08	SEALANT, WHITE, PLIABLE	A	NF	160	SF
S	SAT	09	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,500	SF
M	GWB	10	GYPSUM WALLBOARD, WHITE, CHALKY ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY AND SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	4,500	SF
S	JTC	11	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	450	SF
M	GWT	12	GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	1,500	SF
M	GRT	13	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	150	SF
M	CMT	14	CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, MULTI-COLORED SPECKS	A	NF	1,800	SF
M	GRT	15	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, MULTI-COLORED SPECKS	A	NF	180	SF
M	QPT	16	QUARRY/PAVER TILE (TRANSITION STRIP), 2"X36", GRAY, SMOOTH, MARBLED	A	NF	4	SF
M	SAC	17	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	30	SF
S	SAT	18	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	20,000	SF
M	GWB	19	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	20,000	SF
S	JTC	20	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	2,000	SF
M	SLT	21	SEALANT, BLACK, CLAY-LIKE	A	NF	20	SF
M	FDI	22	FIRE DOOR INSULATION, METAL CLADDING	A	NF	777	SF
M	SLT	23	SEALANT (DUCT), TAN, PLIABLE	A	NF	500	SF
M	CON	24	CONCRETE (DOUBLE T'S), GRAY, CEMENTITIOUS	A	NF	60,000	SF
M	VCT	25	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, WHITE AND GRAY MOTTLES	S	NF	10,000	SF
M	MRT	26	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8", CLEAR	A	NF	400	SF
M	TWP	27	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	5,000	SF
M	ADH	28	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,250	SF



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	FDI	29	FIRE DOOR INSULATION, WOOD CLADDING	A	NF	714	SF
S	SAT	30	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	35	SF
S	TOT	31	TROWELED-ON TEXTURE, WHITE, CHALKY	S	NF	200	SF
M	GWB	32	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	S	NF	200	SF
S	JTC	33	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	20	SF
M	SAC	34	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	38	SF
M	WAB	35	WALLBASE (COVED), 4", LIGHT BLUE, VINYL-LIKE	S	NF	65	SF
M	ADH	36	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", LIGHT BLUE, VINYL-LIKE	S	NF	65	SF
M	ADH	37	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, SMOOTH	A	NF	2,000	SF
M	GWT	38	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	800	SF
M	GRT	39	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	80	SF
M	CMT	40	CERAMIC MOSAIC TILE, 1"X1", WHITE, SMOOTH, PEPPERED	A	NF	400	SF
M	GRT	41	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 1"X1", WHITE, SMOOTH, PEPPERED	A	NF	40	SF
S	SAT	42	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,200	SF
M	GWB	43	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,200	SF
S	JTC	44	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	120	SF
M	CMU	45	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,600	SF
M	MRT	46	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	A	NF	2,280	SF
M	CON	47	CONCRETE, GRAY, CEMENTITIOUS	A	NF	50,000	SF
M	WAB	48	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	S	NF	20	SF
M	ADH	49	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	S	NF	20	SF
M	CMU	50	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	A	NF	20,000	SF
M	SLT	51	SEALANT, BROWN, PLIABLE	A	NF	2	SF
M	GWT	52	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	1,000	SF
M	GRT	53	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE, 4"X4", GRAY, SMOOTH	A	NF	100	SF
M	GWT	54	GLAZED WALL TILE, 4"X4", GRAY, SMOOTH	A	NF	12	SF
S	STU	55	STUCCO, GRAY, CEMENTITIOUS	A	NF	10,000	SF
M	BUR	56	BUILT-UP ROOFING, BLACK, ASPHALTIC, METAL CAP	A	NF	45,000	SF
M	BUR	57	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	10,000	SF
M	MAS	58	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE, SILVER	A	NF	2,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Main Building*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	SLT	60	SEALANT (FLASHING), WHITE, BRITTLE	A	NF	500	SF
S	STU	61	STUCCO, GRAY, CEMENTITIOUS	A	NF	4,000	SF
M	SLT	62	SEALANT (EQUIPMENT), GRAY, BRITTLE	A	NF	10	SF
M	SLT	63	SEALANT (EQUIPMENT), YELLOW, CLAY-LIKE	A	NF	5	SF
M	BUR	64	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	1,500	SF
M	CMU	65	CONCRETE MASONRY UNIT, 3"X16", GRAY, CEMENTITIOUS	A	NF	50	SF
M	EXJ	66	EXPANSION JOINT, BROWN, FIBROUS	A	NF	100	SF
M	CON	67	CONCRETE, GRAY, CEMENTITIOUS	A	NF	17,000	SF
M	EXJ	68	EXPANSION JOINT, BROWN, BRITTLE	A	NF	500	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	12,000	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	11,000	SF
M	GWB	03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	11,000	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	1,100	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	600	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	150	SF
M	WAB	07	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	S	NF	500	SF
M	ADH	08	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	S	NF	500	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY AND WHITE MOTTLES	S	NF	1,500	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, GRAY AND WHITE MOTTLES AND CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS AND VINYL COMPOSITION TILE, 12"X12", SMOOTH, TAN AND GRAY MOTTLES AND VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN AND GRAY MOTTLES AND VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BLUE MOTTLES AND VINYL COMPOSITION TILE, 12"X12", VARIOUS, SMOOTH, STRIP AND VINYL COMPOSITION TILE, 2"X24", VARIOUS, SMOOTH, STRIP	S	NF	15,000	SF
M	SAC	11	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	6	SF
M	FDI	12	FIRE DOOR INSULATION, METAL CLADDING	A	NF	567	SF
M	SLT	13	SEALANT, WHITE, PLIABLE	A	NF	53	SF
M	MRT	14	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	30	SF
M	ADH	15	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	20	SF
M	CPT	16	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	S	NF	2,700	SF
M	FDI	17	FIRE DOOR INSULATION, WOOD CLADDING	A	NF	378	SF
M	VCT	18	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN AND GRAY MOTTLES	S	NF	1,800	SF
M	VST	19	VINYL STAIR TREAD, 36"X12", BROWN, TEXTURED, VINYL-LIKE, CIRCLE PATTERN	A	NF	40	SF
M	MAS	20	MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 36"X12", BROWN, TEXTURED, VINYL-LIKE, CIRCLE PATTERN	A	NF	40	SF
M	ACT	21	ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	S	F	500	SF
M	ADH	22	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	A	NF	125	SF
M	VCT	23	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BLUE MOTTLES	S	NF	6,000	SF
M	CMU	24	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	6,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Cafeteria Building*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	MRT	25	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	A	NF	2,000	SF
M	VCT	26	VINYL COMPOSITION TILE, 12"X12", VARIOUS, SMOOTH, STRIP	S	NF	40	SF
M	VCT	27	VINYL COMPOSITION TILE, 2"X24", VARIOUS, SMOOTH, STRIP	S	NF	40	SF
M	GWB	28	GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	700	SF
S	JTC	29	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	70	SF
M	CON	30	CONCRETE, GRAY, CEMENTITIOUS	A	NF	35,000	SF
M	GWT	31	GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	2,500	SF
M	GRT	32	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	250	SF
M	APL	33	ACOUSTICAL CEILING PANEL, 2'X2', WHITE, CHALKY, VINYL COVER	S	NF	700	SF
M	GWB	34	GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	2,000	SF
S	JTC	35	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	200	SF
M	ADH	36	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	250	SF
M	QPT	37	QUARRY/PAVER TILE, 6"X6", GRAY, SMOOTH, PEPPERED	A	NF	800	SF
M	GRT	38	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", GRAY, SMOOTH, PEPPERED	A	NF	80	SF
M	CMT	39	CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, PEPPERED	A	NF	900	SF
M	GRT	40	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH, PEPPERED AND QUARRY/PAVER TILE (TRANSITION STRIP), 2"X36", GRAY, SMOOTH, MARBLED	A	NF	90	SF
M	SLT	41	SEALANT, BROWN, PLIABLE	A	NF	2	SF
M	QPT	42	QUARRY/PAVER TILE (TRANSITION STRIP), 2"X36", GRAY, SMOOTH, MARBLED	A	NF	4	SF
M	SLT	43	SEALANT, TAN, PLIABLE	A	NF	32	SF
M	PES	44	PIPE END SEALANT, WHITE, BRITTLE	A	NF	40	SF
M	SLT	45	SEALANT (EQUIPMENT), BLACK, TAR-LIKE	A	NF	20	SF
S	STU	46	STUCCO, GRAY, CEMENTITIOUS	A	NF	4,000	SF
M	CMU	47	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, VERTICAL PATTERN	A	NF	15,000	SF
M	BUR	48	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	25,000	SF
M	MAS	49	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	400	SF
M	CTG	50	COATING, WHITE, PLIABLE	A	NF	30,000	SF
M	SLT	51	SEALANT (FLASHING), WHITE, PLIABLE	A	NF	100	SF
M	CON	52	CONCRETE, GRAY, CEMENTITIOUS	A	NF	10,000	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable D1/D2*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	2,000	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	500	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	900	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	225	SF
M	WAB	08	WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	A	NF	80	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	A	NF	80	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	MAS	15	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, BLACK, PLIABLE	A	NF	6	SF
S	SAT	21	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M	GWB	22	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S	JTC	23	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M	VSF	26	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	250	SF
M	MAS	27	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	250	SF
M	ADH	30	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	16	SF
M	SLT	31	SEALANT, WHITE, PLIABLE	A	NF	9	SF
M	SLT	33	SEALANT, YELLOW, PLIABLE	A	NF	1	SF
M	MAS	34	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	35	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable D1/D2*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	CON	36	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M1/M2*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	2,000	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	500	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,000	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	250	SF
M	WAB	08	WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	MAS	15	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, BLACK, PLIABLE	A	NF	6	SF
S	SAT	21	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M	GWB	22	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S	JTC	23	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M	VSF	26	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	250	SF
M	MAS	27	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	250	SF
M	SLT	31	SEALANT, WHITE, PLIABLE	A	NF	9	SF
M	MAS	34	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	35	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF
M	CON	36	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M3/M4*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	1,800	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	450	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	750	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	190	SF
M	WAB	08	WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	300	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	300	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,700	SF
M	MAS	15	MASTIC, YELLOW, FIBROUS, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,700	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	12	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, BLACK, PLIABLE	A	NF	6	SF
S	SAT	21	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	22	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	23	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	VSF	26	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	250	SF
M	MAS	27	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	250	SF
M	ADH	30	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	16	SF
M	SLT	31	SEALANT, WHITE, PLIABLE	A	NF	9	SF
M	SLT	33	SEALANT, YELLOW, PLIABLE	A	NF	1	SF
M	MAS	34	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	35	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF



JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable M3/M4*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	CON	36	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R1/R2*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	2,000	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	500	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,000	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	250	SF
M	WAB	08	WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	A	NF	75	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", DARK BLUE, VINYL-LIKE	A	NF	75	SF
M	WAB	10	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	10	SF
M	ADH	11	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	10	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED	A	NF	100	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED	A	NF	100	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	MAS	15	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, BLACK, PLIABLE	A	NF	6	SF
S	SAT	21	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M	GWB	22	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S	JTC	23	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M	VCT	24	VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE, CIRCLE PATTERN	A	NF	80	SF
M	MAS	25	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE	A	NF	80	SF
M	VSF	26	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	170	SF
M	MAS	27	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	170	SF
M	WAB	28	WALLBASE (COVED), 6", GRAY, VINYL-LIKE	A	NF	4	SF
M	ADH	29	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 6", GRAY, VINYL-LIKE	A	NF	4	SF
M	SLT	31	SEALANT, WHITE, PLIABLE	A	NF	8	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R1/R2*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	MAS	34	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	35	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF
M	CON	36	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R3/R4*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	2,000	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	500	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,000	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	250	SF
M	WAB	08	WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	75	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	75	SF
M	WAB	10	WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	A	NF	10	SF
M	ADH	11	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	A	NF	10	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	MAS	15	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, WHITE, PLIABLE	A	NF	6	SF
S	SAT	21	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
M	GWB	22	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,000	SF
S	JTC	23	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	100	SF
M	VCT	29	VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE	A	NF	80	SF
M	MAS	25	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, TEXTURED, VINYL-LIKE	A	NF	80	SF
M	VSF	26	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	170	SF
M	MAS	27	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	170	SF
M	WAB	28	WALLBASE (COVERED), 6", GRAY, VINYL-LIKE	A	NF	4	SF
M	ADH	29	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 6", GRAY, VINYL-LIKE	A	NF	4	SF
M	ADH	30	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	16	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable R3/R4*

JOB NO. 07-326

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	SLT	31	SEALANT, WHITE, PLIABLE	A	NF	7	SF
M	SLT	32	SEALANT, BROWN, PLIABLE	A	NF	2	SF
M	SLT	33	SEALANT, YELLOW, PLIABLE	A	NF	1	SF
M	MAS	34	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	35	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF
M	CON	36	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable T1/T2*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	2,000	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	500	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,000	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	250	SF
M	WAB	08	WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	MAS	15	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	16	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	MAS	21	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	22	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF
M	CON	23	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Portable T3/T4*

JOB NO. 07-326

**TABLE B  
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	ACT	01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	S	F	2,000	SF
M	ADH	02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERS, WHITE	A	NF	500	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M	GWB	04	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,000	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	250	SF
M	WAB	08	WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	ADH	09	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", DARK BLUE, VINYL-LIKE	A	NF	80	SF
M	VSF	12	VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	MAS	13	MASTIC, CREAM, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, MARBLED, GRAY PAPER BACKING	A	NF	100	SF
M	CPT	14	CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	MAS	15	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED	A	NF	1,900	SF
M	FDI	16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	SLT	17	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	SAC	18	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	16	SF
M	SLT	19	SEALANT (DUCT), WHITE, BRITTLE	A	NF	5	SF
M	SLT	20	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	MAS	21	MASTIC (PENETRATIONS AND FLASHING), BLACK, BRITTLE	A	NF	25	SF
M	CTG	22	COATING (DUCT), WHITE, PLIABLE	A	NF	40	SF
M	CON	23	CONCRETE, GRAY, CEMENTITIOUS	A	NF	600	SF

END OF TABLE

## 2.7 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **TEN** friable suspect ACBM (acoustical ceiling panels and acoustical ceiling tile) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

## 2.8 Sample Collection

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

<b>Building</b>	<b>Suspect ACBM</b>	<b>Samples Collected</b>
Main	67 (42 Assumed)	75
Cafeteria	52 (33 Assumed)	57
Portable D1/D2	29 (28 Assumed)	3
Portable M1/M2	27 (26 Assumed)	3
Portable M3/M4	29 (28 Assumed)	3
Portable R1/R2	33 (32 Assumed)	3
Portable R3/R4	36 (35 Assumed)	3
Portable T1/T2	21 (20 Assumed)	3
Portable T3/T4	21 (20 Assumed)	3
<b>TOTAL</b>	<b>315</b>	<b>153</b>

*Suspect ACM Designation and Sample Record Forms are presented in Appendix A.*



**Report of Findings**

Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School, KSD  
FM Project 07-326

**2.9 Bulk-Material Sample Analysis**

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

*Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.*

**END OF REPORT**

## **APPENDIX A**

### **Suspect Asbestos-Containing Material Designation and Sample Record Forms**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-APL-01 Damaged:  Yes  No Friable  Non-Friable  
 General Description: Acoustical Ceiling Panel Visible  Covered   
 Matrix/Primary Color: Gray Texture/Pattern: Potholes and Fissures Cover/Secondary Color: White Size: 2'X2'  
 Quantity of Material: 12,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	P.E. Storage	SW Corner	E 2'	N 6'	8'	F/W/C/O
B	Cafeteria Storage	SW Corner	E 12'	N 10'	8'	F/W/C/O
C	Corridor	SW Corner	E 3'	N 3'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-SAT-02     Visible     Friable     Non-Friable  
 Covered  
**General Description:** Spray Applied Texture    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 11,000    SF / LF / EA    **Estimated By:**  Drawing     Sampled  
 Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Exterior Storage	NE Corner	W 6'	S 0'	1'	F (W) / C / O
B	Custodial	NE Corner	W 8'	S 0'	3'	F (W) / C / O
C	Water Heater Closet	SW Corner	E 0'	N 2'	3"	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** B9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07  
**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6wB-03 Visible Covered SAT Damaged: Yes No Friable Non-Friable  
 General Description: Gypsum Wallboard Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 11,000 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other  
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Exterior Storage	NE Corner	W 6'	S 0'	1'	F/W/C/O
B	Custodial	NE Corner	W 8'	S 0'	3'	F/W/C/O
C	Water Heater Closet	SW Corner	E 0'	N 2'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with SAT-02

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-04 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 1100 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Exterior Storage	NE Corner	W 6'	S 0'	1'	F/W/C/O
B	Custodial	NE Corner	W 8'	S 0'	3'	F/W/C/O
C	Water Heater Closet	SW Corner	E 0'	N 2'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-9288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.cmf

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-TWR-05     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Tackable Wall Panel     Covered     No     Drawing     Field Measure     Sampled     Assumed  
**Matrix/Primary Color:** Brown    **Texture/Pattern:** Fibrous    **Cover/Secondary Color:** Vinyl Cover    **Size:** N/A  
**Quantity of Material:** 600     LF / EA     Wall     Other     Ceiling     Floor     Convenience     N/A

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-06 Visible Covered  No  Yes  Damaged:  Yes  No  Friable  Non-Friable   
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: BRITTLE Cover/Secondary Color: N/A  
 Quantity of Material: 150 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-05

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 16874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-WAB-07     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Wallbase (covered)    **Damaged:**  Yes     No  
**Matrix/Primary Color:** Blue    **Texture/Pattern:** Vinyl-Like    **Cover/Secondary Color:** N/A    **Size:** 4"     Sampled  
**Quantity of Material:** 500     LF / EA    **Estimated By:**  Drawing     Field Measure    **Assumed**

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Instrument 1	NW Corner	E 1'	S 0'	3"	F / W / C / O
B	Stage	NW Corner	E 10'	S 0'	3"	F / W / C / O
C	Corridor	SW Corner	E 0'	N 0'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-08    **Visible**  Covered WAB    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Adhesive    **Size:** N/A  
**Matrix/Primary Color:** Cream    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 500     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Instrument 1	NW Corner	E 1'	S 0'	3"	F / W / C / O
B	Stage	NW Corner	E 10'	S 0'	3"	F / W / C / O
C	Corridor	SW Corner	E 0'	N 0'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-WAB-07

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-09 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Composition Tile Size: 12" X 12"  
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Gray and White Mottles  
 Quantity of Material: 1500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 608	SW Corner	E 8'	N 0'	0'	F W I C I O
B	Room 607	NW Corner	E 0'	S 2'	0'	F W I C I O
C	I	NE Corner	W 0'	S 2'	0'	F W I C I O
D		Corner				F W I C I O
E		Corner				F W I C I O
F		Corner				F W I C I O
G		Corner				F W I C I O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-MAS-10      Visible      Damaged:  Yes       No       Friable       Non-Friable  
 Covered      VCT, CPT      Size: N/A

**General Description:** Mastic      Texture/Pattern: Tacky      Cover/Secondary Color: N/A  
**Matrix/Primary Color:** Yellow      Estimated By:  Drawing       Field Measure  
**Quantity of Material:** 15,000      (SF) / LF / EA

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 608	SW Corner	E 8'	N 0'	0'	(E) W I C I O
B	Stage	NW Corner	E 12'	S 15'	0'	(E) W I C I O
C	Cafeteria	NW Corner	W 45'	S 0'	0'	(E) W I C I O
D		Corner				F / W I C I O
E		Corner				F / W I C I O
F		Corner				F / W I C I O
G		Corner				F / W I C I O

**Comments:** Associated with M-VCT-09, M-CPT-09, M-VCT-16, M-VCT-18, M-VCT-23, M-VCT-26

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SAC-11      Damaged:  Yes       No       Friable       Non-Friable  
 General Description: Sink Acoustical Coating      Size: N/A  
 Matrix/Primary Color: Gray      Texture/Pattern: Rough      Cover/Secondary Color: N/A  
 Quantity of Material: 6      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *Dane Thompson*      Date: 9-07-07      Signature: *Michael Coleman*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-FD1-12     Visible     Friable     Non-Friable  
 Covered  
**General Description:** Fire Door Insulation    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** N/A    **Texture/Pattern:** Metal Cladding    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 567     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-13 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Visible Covered   Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 53 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Signature: *[Signature]* Date: 9-07-07 Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MRT-14 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mortar Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 30 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Glass Block, 8"x8" concrete

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.omf



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD14-15 Visible Covered FRP Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 20 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Paneling, WHITE, TEXTURED

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-CP-T-16     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Carpet     Covered     No     Yes     Field Measure     Sampled Assumed  
**Matrix/Primary Color:** Gray     LF / EA     Drawing     Field Measure     Estimated By:     Drawing     Field Measure  
**Quantity of Material:** 2700     LF / EA     Drawing     Field Measure     Estimated By:     Drawing     Field Measure  
**Texture/Pattern:** Fibrous     LF / EA     Drawing     Field Measure     Estimated By:     Drawing     Field Measure  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other     Estimated By:     Drawing     Field Measure

**Manner of Sampling:**  Random     Convenience    N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 608	NE Corner	W 0'	S 1'	0'	F/W/C/O
B	I	NW Corner	E 0'	S 1'	0'	F/W/C/O
C	Room 607	SE Corner	W 0'	N 1'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHRA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-FD1-17 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Wood Cladding Cover/Secondary Color: N/A

Quantity of Material: 378 Estimated By:  Drawing  Field Measure  
 LF / EA  Sampling  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHRA Certificate No.: D9953 State License: EPA AHRA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DR* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (802) 277-7877  
 (802) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-VCT-18     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Vinyl Composition Tile    **Size:** 12" X 12"  
**Matrix/Primary Color:** White    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** Tan and Gray Mottles  
**Quantity of Material:** 1800     SF / LF / EA    **Estimated By:**  Drawing     Sampled  
 Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	West wing	NW Corner	E 2'	S 2'	0'	F/W/C/O
B	East wing	NE Corner	W 3'	S 1'	0'	F/W/C/O
C	Stage	NW Corner	E 12'	S 15'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VST-19 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Vinyl Stair Tread Size: 36" x 12"  
 Matrix/Primary Color: Brown Texture/Pattern: Textured Cover/Secondary Color: Vinyl-Like  
 Quantity of Material: 40 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: CIRCULAR PATTERN

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-30 Visible Covered  Visible  Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Broken Cover/Secondary Color: N/A  
 Quantity of Material: 40 (SF) / LF / EA Estimated By:  Drawing  Assumed  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VST-19

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ACT-21 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Acoustical Ceiling Tile Size: 1' X 1'  
 Matrix/Primary Color: Gray Texture/Pattern: P-holes and Fissures Cover/Secondary Color: White  
 Quantity of Material: 500 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Stage	NW Corner	E 12'	S 8'	12'	F/W/C/O
B	South Foyer	SE Corner	W 2'	N 0'	8'	F/W/C/O
C	I	SW Corner	E 2'	N 0'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BHA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-6288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-22    **Visible Covered:**  ACT    **Damaged:**  Yes     No    **Size:** N/A     Friable     Non-Friable  
**General Description:** Adhesive  
**Matrix/Primary Color:** Brown    **Texture/Pattern:** Brittle    **Cover/Secondary Color:** N/A     Sampled     Assumed  
**Quantity of Material:** 125     SF / LF / EA    **Estimated By:**  Drawing     Field Measure

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-ACT-21

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BJIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-4288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-23 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Composition Tile Size: 12" X 12"  
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Blue Mottles  
 Quantity of Material: 6000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Custodial	NE Corner	W 0'	S 1'	0'	(F) W / C / O
B	Cafeteria	NW Corner	E 2'	S 0'	0'	(F) W / C / O
C	Cafeteria Storage	SW Corner	E 6'	N 0'	0'	(F) W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: DR Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-CMJ-24     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Concrete Masonry Unit    **Size:** 8" x 16"  
**Matrix/Primary Color:** Gray    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 6000    **Estimated By:**  Drawing     Sampled  
 SF / LF / EA     Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MRT-25 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mortar Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMJ-24, M-CMJ-47

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-9288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Very Composition Tile Size: 12" x 12"  
 Matrix/Primary Color: Various Texture/Pattern: Smooth Cover/Secondary Color: STRIP  
 Quantity of Material: 40 Estimated By:  Drawing  Sampled  Assumed  
 SF / LF / EA  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Cafeteria	NW Corner	E 12'	S 6'	0'	F/W/C/O
B	I	NW Corner	E 24'	S 12'	0'	F/W/C/O
C	I	NW Corner	E 36'	S 12'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DR* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-27 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Composition Tile Size: 2" X 24"  
 Matrix/Primary Color: Various Texture/Pattern: Smooth Cover/Secondary Color: STEEL  Sampled  Assumed  
 Quantity of Material: 40 (SF) / LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Cafeteria	NW Corner	E 30'	S 10'	0'	(F) W I C O
B	I	NW Corner	E 35'	S 15'	0'	(F) W I C O
C	I	NW Corner	E 45'	S 20'	0'	(F) W I C O
D		Corner				F / W I C O
E		Corner				F / W I C O
F		Corner				F / W I C O
G		Corner				F / W I C O

Comments: Strip

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DR* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-328 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GWB-28 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Green Wallboard Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 700 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Electrical Room	NE Corner	W 0'	S 5'	4'	F / (W) / C / O
B	Cafeteria Electrical Room	NW Corner	E 1'	S 0'	12'	F / (W) / C / O
C	I	NW Corner	E 1'	S 4'	12'	F / (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC.**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-29 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 70 Estimated By:  Drawing  Sampled  Assumed  
 SF / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Electrical Room	NE Corner	W 0'	S 5'	4'	F / W / C / O
B	Cafeteria Electrical Room	NW Corner	E 1'	S 0'	12'	F / W / C / O
C	I	NW Corner	E 1'	S 4'	12'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-28

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-3286 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-30 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered Size: N/A

General Description: Concrete  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 35,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-GWT-31     Visible     Covered     Friable     Non-Friable  
**General Description:** Glazed Wall Tile    **Damaged:**  Yes     No    **Size:** 4" x 4"  
**Matrix/Primary Color:** Pink    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 2500    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7977  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GRT-32 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Grot Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-31

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-APL-35 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Acoustical Ceiling Panel Size: 2'x2'  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 700 Estimated By:  Drawing  Sampled  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience | N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Gypsum Wallboard Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Kitchen	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	Boys Restroom	NW Corner	E 0'	S 0'	9'	F/W/C/O
C	Girls Restroom	NE Corner	W 0'	S 0'	9'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-5TC-35     Visible     Covered     Friable     Non-Friable  
**General Description:** Joint Compound    **Damaged:**  Yes     No  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A    **Size:** N/A  
**Quantity of Material:** 200     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Kitchen	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	Boys Restroom	NW Corner	E 0'	S 0'	9'	F / W / C / O
C	Girls Restroom	NE Corner	W 0'	S 0'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-GWB-34

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD14-36 Visible Covered FRP Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 250 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Paving, white, textured

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DTC* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-01T-37     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Quarry / Paver Tile    **Size:** 6" X 6"  
**Matrix/Primary Color:** Gray    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** PEPPERED  
**Quantity of Material:** 800     SF / LF / EA    **Estimated By:**  Drawing     Sampled  
 Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** B11A040907-01    **State License:** EPA  
**Signature:** *Dane Thompson*    **Date:** 9-07-07    **Signature:** *Michael Coleman*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GR-38 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Grout Visible  Covered  Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 80 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ORT-37

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: B11A040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CMT-39 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Ceramic Mosaic Tile Size: 2" X 2"  
 Matrix/Primary Color: Pink Texture/Pattern: Smooth Cover/Secondary Color: Peppered  
 Quantity of Material: 900 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GRT-40 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: GROUT Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 90 (SF) / LF / EA Estimated By:  Drawing  Assumed  
 Sampled

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-39 AND M-087-42

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.dmf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-41 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Sealer  
 Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 2 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Size: N/A

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-07-42 Damaged:  Yes  No Friable  Non-Friable   
 General Description: QUARRY PAPER TILE (TRANSITION SERP) Size: 2" x 36"  
 Matrix/Primary Color: Gray Texture/Pattern: Smooth Cover/Secondary Color: Marbled  
 Quantity of Material: 4 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DTC* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SLT-43     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Sealant    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** Tan    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 32    **Estimated By:**  Drawing     Assumed  
 Field Measure

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-PES 44     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** PIPE END SEALANT     Covered     Field Measure  
**Matrix/Primary Color:** White     Texture/Pattern: Battle     Drawing     Assumed  
**Quantity of Material:** 40     SF / LF / EA     Estimated By:     Sampled  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other     Size: N/A     Color: N/A

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes     Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SLT-45     Visible     Covered     Friable     Non-Friable  
**General Description:** Sealant (Equipment)    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** Black    **Texture/Pattern:** Tar-Like    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 20     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8286 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-STU-46 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Stucco Visible Covered   Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 4000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CMU-47 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Concrete Masonry Unit Visible  Covered  Size: 8" x 16"  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Vertical Pattern  
 Quantity of Material: 15,000 Estimated By:  Drawing  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-BUR-48 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Built-up Roofing Visible Covered  
 Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap Size: N/A  
 Quantity of Material: 25,000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-4268 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M.M.A.S-49 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic (Penetrations And Flashing) Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 400 SF LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Cafeteria Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-CTG-50     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Coating    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 30,000     LF / EA    **Estimated By:**  Drawing     Field Measure  
 Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BJA040907.01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (802) 277-7877  
 (802) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-51 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Flashing) Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 100 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

FM GROUP INC

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Cafeteria Building      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-CON-S&A      Damaged:  Yes       No      Friable  Non-Friable   
 General Description: CONCRETE      Visible Covered       Size: N/A  
 Matrix/Primary Color: GRAY      Texture/Pattern: CEMENTitious      Cover/Secondary Color: N/A  
 Quantity of Material: 10.000      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: [Signature]      Date: 9-07-07      Signature: [Signature]      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      455 UP-100

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8286 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-APL-01     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable

**General Description:** Acoustical Ceiling Panel    **Size:** 2' X 2'    **Texture/Pattern:** Pinholes and Fissures    **Cover/Secondary Color:** White  
**Matrix/Primary Color:** Gray    **Quantity of Material:** 47,000    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	NE Corner	W 6'	S 10'	8'	F/W/C/O
B	Room B7	SW Corner	E 10'	N 1'	8'	F/W/C/O
C	Room A3	SE Corner	W 10'	N 1'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-02 Visible Covered   Damaged:  Yes  No Friable  Non-Friable   
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: White Estimated By:  Drawing  Field Measure  
 Quantity of Material: 36,000 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room B7	NE Corner	W 0'	S 0'	3"	F / (W) / C / O
B	Corridor 1	SW Corner	E 0'	N 45'	3"	F / (W) / C / O
C	Hallway 2	NE Corner	W 0'	S 20'	3"	F / (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-03 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint compound Covered  Wallpaper Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 3600 Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other Field Measure

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room B7	NE Corner	W 0'	S 0'	3"	F / (W) / C / O
B	Corridor 1	SW Corner	E 0'	N 45'	3"	F / (W) / C / O
C	Hallway 2	NE Corner	W 0'	S 20'	3"	F / (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-04 Damaged:  Yes  No Friable  Non-Friable

General Description: Wallbase (covered) Size: 4"  
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A

Quantity of Material: 1100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  Convenience  N/A

Manner of Sampling:  Random  Sample Location

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Phone Room	SW Corner	E 0'	N 2'	3"	F / W / C / O
B	Room B8	NW Corner	E 0'	S 4'	3"	F / W / C / O
C	Room A1	SE Corner	W 0'	N 4'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD4-05 Visible Covered  WAB Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 1100 Estimated By:  Drawing  Sampled  Assumed  
 LF / EA  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Phone Room	SW Corner	E 0'	N 2'	3"	F / W / C / O
B	Room B8	NW Corner	E 0'	S 4'	3"	F / W / C / O
C	Room A1	SE Corner	W 0'	N 4'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Assoc w/ M-446-04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Main Building      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-CPT-06      Damaged:  Yes       No      Friable  Non-Friable   
 General Description: Carpet (Self-Stick)      Visible Covered    
 Matrix/Primary Color: Gray      Texture/Pattern: Fibrous      Cover/Secondary Color: Multi-Colored      Size: N/A  
 Quantity of Material: 40,000      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Break-out 1	SW Corner	E 1'	N 0'	0'	E W / C / O
B	Room 401	SE Corner	W 0'	N 4'	0'	F W / C / O
C	Storage 1	SE Corner	W 0'	N 2'	0'	F W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-07 Visible Covered CPT/VCT Damaged: Yes No Friable Non-Friable  
 General Description: Mastic Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 50,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other  
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room B7	SW Corner	E 0'	N 2'	0'	F/W/C/O
B	Room A1	SE Corner	W 0'	N 2'	0'	F/W/C/O
C	Room A7	NE Corner	W 0'	S 2'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-CPT-06, M-VCT-25

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: Yes No

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.mf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-08 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Visible  Covered  Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 160 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  Yes  No Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Building Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-09 Damaged:  Yes  No  Friable  Non-Friable

General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2500 Estimated By:  Drawing  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	B Janitor	SW Corner	E 0'	N 4'	3"	F (W) C / O
B	Nurse Restroom	SE Corner	W 0'	N 2'	3'	F (W) C / O
C	A5 Restroom	SE Corner	W 0'	N 3'	4'	F (W) C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Building Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-608-10 Visible Covered SAT Damaged: Yes No Non-Friable

General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 4500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Table with columns: Sample ID, Sample Location, Points of Origin, East/West Direction, North/South Direction, Height A.F.F., Surface. Rows A-G describe samples in Janitor, Nurse Restroom, and AS Restroom.

Comments: Associated with S-SAT-09, S-SAT-30

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman
AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA
Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
Scottsdale, AZ 85280
(602) 277-7877
(602) 277-8288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Building Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-11 Visible Covered SAT Damaged: Yes No Friable Non-Friable

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 450 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other Manner of Sampling: Random Convenience N/A

Table with 7 columns: Sample ID, Sample Location, Points of Origin, East/West Direction, North/South Direction, Height A.F.F., Surface. Rows A-G contain data for various locations like Janitor, Nurse Restroom, and AS Restroom.

Comments: Associated with M-6WJB-10

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA Signature: ORZ Date: 9-07-07 Signature: Mike Cole Date: 9-07-07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street Scottsdale, AZ 85260 (602) 277-2677 (602) 277-6266 fax

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-6WT-12       Visible       Covered       Damaged:  Yes       No       Friable       Non-Friable  
**General Description:** Glazed Wall Tile      Size: 4" X 4"

**Matrix/Primary Color:** Pink      Texture/Pattern: Smooth      Cover/Secondary Color: N/A  
**Quantity of Material:** 1500       SF / LF / EA      Estimated By:  Drawing       Field Measure       Sampled       Assumed

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHJRA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GR-13 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Grout Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 150 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WT-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHJRA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: CSR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CMT-14 Damaged:  Yes  No Friable  Non-Friable

General Description: Ceramic Mosaic Tile Size: 2" X 2"  
 Matrix/Primary Color: Pink Texture/Pattern: Smooth Cover/Secondary Color: Multi-Colored Specks

Quantity of Material: 1800 Estimated By:  Drawing  Sampled  Assumed  
 SF / LF / EA  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GRT-15 Material:  Visible  Covered  Friable  Non-Friable  
 Damaged:  Yes  No

General Description: Grout Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 180 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-14

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 271-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-07-16 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Quarry Panel Tile (Transition Strip) Size: 2'x36"  
 Matrix/Primary Color: Gray Texture/Pattern: Smooth Cover/Secondary Color: Marbled  
 Quantity of Material: 4' Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Main Building      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SAC-17      Damaged:  Yes       No      Friable  Non-Friable   
 General Description: Sink Acoustical Coating      Size: N/A  
 Matrix/Primary Color: Gray      Texture/Pattern: Rough      Cover/Secondary Color: N/A  
 Quantity of Material: 30      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** S-SAT-18      **Damaged:**  Yes       No       Friable       Non-Friable  
**General Description:** Spray-Applied Texture      **Size:** N/A  
**Matrix/Primary Color:** White      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 20,000      **Estimated By:**  Drawing       Field Measure  
**Texture/Pattern:** Chalky      **Estimated By:**  Drawing       Field Measure

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Storage 1	NE Corner	W 0'	S 6'	2'	F / W / C / O
B	Storage 2	SW Corner	E 7'	N 0'	4'	F / W / C / O
C	C Art Room	SW Corner	E 6'	N 0'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **AHERA Certificate No.:** BJA040907-01      **State License:** EPA      **State License:** EPA  
**Signature:** *[Signature]*      **Signature:** *[Signature]*      **Date:** 9-07-07      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHIERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-19 Visible Covered SAT Damaged: Yes No Friable Non-Friable  
 General Description: Gypsum Wallboard  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 20,000 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed  
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Storage 1	NE Corner	W 0'	S 6'	2'	F / W / C / O
B	Storage 2	SW Corner	E 7'	N 0'	4'	F / W / C / O
C	( Art Room	SW Corner	E 6'	N 0'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-18

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHIERA Certificate No.: D9953 State License: EPA AHIERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-20 Visible Covered  SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2,000 (SF) LF / EA Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Storage 1	NE Corner	W 0'	S 6'	2'	F/W/C/O
B	Storage 2	SW Corner	E 7'	N 0'	4'	F/W/C/O
C	C Art Room	SW Corner	E 6'	N 0'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-19

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-SCT-21       Visible       Covered       Yes       No       Friable       Non-Friable  
**General Description:** Sealant      **Size:** N/A  
**Matrix/Primary Color:** Black      **Texture/Pattern:** Clay-Like      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 20       SF / LF / EA      **Estimated By:**  Drawing       Field Measure       Sampled       Assumed

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Signature:** *[Signature]*      **Date:** 9-07-07      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-FD1-22 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Fire Door Insulation Size: N/A  
 Matrix/Primary Color: N/A Texture/Pattern: Metal Claddings Cover/Secondary Color: N/A  
 Quantity of Material: 777 Estimated By:  Drawing  Assumed  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DSC* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SLT-23     Visible     Covered    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Sealant (Duct)    **Texture/Pattern:** Pliable    **Size:** N/A  
**Matrix/Primary Color:** Tan    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed  
**Quantity of Material:** 500     LF / EA     Wall     Other

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-CON-24       Visible       Covered       Friable       Non-Friable  
**General Description:** Concrete (Double T's)      **Damaged:**  Yes       No      **Size:** N/A  
**Matrix/Primary Color:** Gray      **Texture/Pattern:** Cementitious      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 60,000      **Estimated By:**  Drawing       Field Measure       Sampled       Assumed  
**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other

**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA      **State License:** EPA  
**Signature:** *[Signature]*      **Signature:** *[Signature]*      **Date:** 9-07-07      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-25 Damaged:  Yes  No Friable  Non-Friable

Size: 12" X 12"

General Description: Vinyl Composition Tile Cover/Secondary Color: White and Gray Mottles

Matrix/Primary Color: Tan Texture/Pattern: Smooth

Quantity of Material: 10,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room B6	NW Corner	E 0'	S 2'	0'	F/W/C/O
B	Electric Room	SE Corner	W 0'	N 2'	0'	F/W/C/O
C	Storage 1	NE Corner	W 2'	S 6'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MRT-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 400 (SF) LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Glass Block, 8' CLEAR

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf



**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-TWP-27       Visible       Covered       Damaged:  Yes       No       Friable       Non-Friable  
**General Description:** Tackable Wall Panel      Size: N/A

**Matrix/Primary Color:** Brown      **Texture/Pattern:** Fibrous      **Cover/Secondary Color:** Vinyl Cover  
**Quantity of Material:** 5000       SF / LF / EA       Drawing       Field Measure       Sampled       Assumed

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	EastWest Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-28 Visible Covered  TWP Damaged:  Yes  No Friable  Non-Friable

General Description: Adhesive Texture/Pattern: Beakle Cover/Secondary Color: N/A Size: N/A

Matrix/Primary Color: Brown Quantity of Material: 1250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-27

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-FDI-29 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Fire Door Insulation Size: N/A  
 Matrix/Primary Color: N/A Texture/Pattern: Wood Cladding Cover/Secondary Color: N/A  
 Quantity of Material: 714 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: 5-SAT-30 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 35 Estimated By:  Drawing  Sampled  
 Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	404 Restroom	NE Corner	W 1'	S 1'	8'	F/W (C) O
B		NE Corner	W 3'	S 2'	8'	F/W (C) O
C		NE Corner	W 4'	S 1'	8'	F/W (C) O
D		Corner				F/W / C / O
E		Corner				F/W / C / O
F		Corner				F/W / C / O
G		Corner				F/W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7577  
 (602) 277-9286 fax

**Project No.:** 07-326    **Project Name:** AHIERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-TOT-31     Visible     Covered     Friable     Non-Friable  
**General Description:** Trowled-On Texture    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 200     SF / LF / EA    **Estimated By:**  Drawing     Sampled  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other     Assumed

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Storage 2	SE Corner	W 4'	NO'	18'	F/W/C/O
B	I	SE Corner	W 4'6"	NO'	18'	F/W/C/O
C	I	SE Corner	W 5'	NO'	18'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHIERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6wb-32 Visible Covered  TOT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: White Quantity of Material: 200 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Storage 2	SE Corner	W 4'	N 0'	18'	F/W/C/O
B	I	SE Corner	W 4'6"	N 0'	18'	F/W/C/O
C		SE Corner	W 5'	N 0'	18'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-TOT-31

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHIERA Certificate No.: D9953 State License: EPA AHIERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-DTC-33 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Visible  Covered  FOT Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 20 (SF) LF / EA Estimated By:  Drawing  Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Storage 2	SE Corner	W 4'	N 0'	18'	F/W/C/O
B	I	SE Corner	W 4'6"	N 0'	18'	F/W/C/O
C		SE Corner	W 5'	N 0'	18'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-32

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-5AC-34 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sink Acoustical Coating Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A  
 Quantity of Material: 38 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-2677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Building Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-35 Damaged:  Yes  No Friable  Non-Friable

General Description: Wallbase (lowed) Size: 4"

Matrix/Primary Color: Light Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A

Quantity of Material: 65 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room B6	NW Corner	E 0'	S 4'	3"	F / W / C / O
B	Room B6	NW Corner	E 0'	S 15'	3"	F / W / C / O
C	Room B7	SW Corner	E 0'	N 4'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-36 Visible  Covered WAB Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 65 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room B6	NW Corner	E 0'	S 4'	3"	F/W/C/O
B	Room B6	NW Corner	E 0'	S 15'	3"	F/W/C/O
C	Room B7	SW Corner	E 0'	N 4'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-WAB-35

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-37 Visible Covered FRP Damaged: Yes No Friable Non-Friable

General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brickle Cover/Secondary Color: N/A  
 Quantity of Material: 2000 (SF) LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Paneling, white, smooth

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesig/Record.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WT-38 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Glazed Wall Tile Size: 4" x 4"  
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A  
 Quantity of Material: 800 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6RT-39 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered Size: N/A

General Description: Grout  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 80 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WT-38

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CMT-40 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Ceramic Mosaic Tile Size: 1" X 1"  
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Speckled  
 Quantity of Material: 400 Estimated By:  Drawing  Sampled  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7617  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6RT-41 Damaged:  Yes  No Friable  Non-Friable

General Description: Grout Size: N/A  
 Matrix/Primary Color: Gray Cover/Secondary Color: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-40

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: DR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-SAT-42     Visible     Covered     Friable     Non-Friable  
**General Description:** Spray Applied Texture    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 1200    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	B Electrical Room	SW Corner	E 0'	N 4'	4'	F / W / C / O
B	Fire Riser Room	SW Corner	E 0'	N 2'	3"	F / W / C / O
C	C Electrical Room	NW Corner	E 0'	S 2'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-43 Visible Covered  SAT Damaged:  Yes  No Friable  Non-Friable

General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 1200 Estimated By:  Drawing  Sampled  Assumed  
 LF / EA  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	B Electrical Room	SW Corner	E 0'	N 4'	4'	F (W) / C / O
B	Fire Riser Room	SW Corner	E 0'	N 2'	3"	F (W) / C / O
C	C Electrical Room	NW Corner	E 0'	S 2'	3"	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-42

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *OSR* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-44 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 120 Estimated By:  Drawing  Sampled  Assumed  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	B Electrical Room	SW Corner	E 0'	N 4'	4'	F/W/C/O
B	Fire Room	SW Corner	E 0'	N 2'	3"	F/W/C/O
C	C Electrical Room	NW Corner	E 0'	S 2'	3"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-43

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CMU-45 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Concrete Masonry Unit Size: 8" X 16"  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 1600 (SF) / LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *CSR* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MRT-46 Material Code: M-MRT-46  
 General Description: MORTAR  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A  
 Quantity of Material: 2280 (SF) LF / EA Estimated By: Drawing Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Damaged:  Yes  No  
 Visible:  Visible  Covered  
 Friable:  Friable  Non-Friable  
 Size: N/A

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMU-45, M-CMU-50

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Main Building      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-CON-47      Damaged:  Yes       No      Friable       Non-Friable   
 General Description: Concrete      Visible       Covered       Size: N/A  
 Matrix/Primary Color: Gray      Texture/Pattern: Cementitious      Cover/Secondary Color: N/A  
 Quantity of Material: 50,000      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIA040907-01      State License: EPA  
 Signature: [Signature]      Date: 9-07-07      Signature: [Signature]      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-48 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Wallbase (lowed) Visible  Covered  Size: 4"  
 Matrix/Primary Color: Brown Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A  
 Quantity of Material: 20 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	B Electric Room	NW Corner	E 3'	50'	3"	F / W / C / O
B	I	NE Corner	W 1'	50'	3"	F / W / C / O
C	A Electric Room	NE Corner	W 1'	50'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-419    **Damaged:**  Yes     No    **Visible Covered:**  WAB    **Size:** N/A  
**General Description:** Adhesive    **Texture/Pattern:** Be.Hk    **Cover/Secondary Color:** N/A  
**Matrix/Primary Color:** Brown    **Estimated By:**  Drawing     Field Measure  
**Quantity of Material:** 20     LF / EA     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	B Electric Room	NW Corner	E 3'	S 0'	3"	F / W / C / O
B	I	NE Corner	W 1'	S 0'	3"	F / W / C / O
C	A Electric Room	NE Corner	W 1'	S 0'	3"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-WAB-48

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *Dane Thompson*    **Signature:** *Michael Coleman*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CMU-50 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Concrete Masonry Unit Size: 8" X 16"  
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Vertical Pattern  
 Quantity of Material: 20,000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-51 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A  
 Matrix/Primary Color: Brown Cover/Secondary Color: N/A  
 Quantity of Material: 2 Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GWT-52 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Glazed Wall Tile Size: 4" X 4"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-GRT-53     Visible     Covered    **Damaged:**  Yes     No    **Size:** N/A  
 Friable     Non-Friable  
**General Description:** GROUT    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Matrix/Primary Color:** Gray    **Estimated By:**  Drawing     Field Measure  
**Quantity of Material:** 100     SF / LF / EA     Drawing     Field Measure  
 Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-GWT-52, M-GWT-54

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *Dane Thompson*    **Date:** 9-07-07    **Signature:** *Michael Coleman*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85250  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GWT-54 Damaged:  Yes  No Friable  Non-Friable

General Description: Glazed Wall Tile Size: 4" X 4"

Matrix/Primary Color: Gray Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 12 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-5TU-55     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Stucco    **Size:** N/A  
**Matrix/Primary Color:** Gray    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 10,000     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** B9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-BUR-SC     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Built-up Roofing    **Size:** N/A  
**Matrix/Primary Color:** Black    **Texture/Pattern:** ASPHALTIC    **Cover/Secondary Color:** Metal Cap     Sampled     Assumed  
**Quantity of Material:** 45,000     SF / LF / EA    **Estimated By:**  Drawing     Field Measure

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BJA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-BUA-57 Visible  Covered  Damaged:  Yes  No Friable  Non-Friable   
 General Description: Built-up Roofing Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: ASPHALT Cover/Secondary Color: Gray Mineral Cap  
 Quantity of Material: 10,000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Main Building      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-MAS-58      Damaged:  Yes       Friable  
 Visible       Covered       Non-Friable  
 Covered  
 General Description: Mastic (Penetrations and Flecking)      Size: N/A  
 Matrix/Primary Color: Black      Texture/Pattern: Brittle      Cover/Secondary Color: SLV/LK  
 Quantity of Material: 2000      Estimated By:  Drawing       Sampled  
 Field Measure       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-3CT-60 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Flashing) Covered  Visible   
 Matrix/Primary Color: White Texture/Pattern: Beistle Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 500 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-STU-61     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Stucco    **Size:** N/A  
**Matrix/Primary Color:** Gray    **Texture/Pattern:** Cementitious    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 4000    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-6Z Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Equipment) Visible  Covered  Size: N/A  
 Matrix/Primary Color: Gray Texture/Pattern: Beak Cover/Secondary Color: N/A  
 Quantity of Material: 10 SF / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Main Building    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SLT-63     Visible     Covered     Friable     Non-Friable  
**General Description:** Sealant (Equipment)    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** Yellow    **Texture/Pattern:** Clay-Like    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 5     SF / LF / EA    **Estimated By:**  Drawing     Field Measure  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-6288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-BUR-64 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Built-up Roofing Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: ASPHALTIC Cover/Secondary Color: Gray Mineral Cap  
 Quantity of Material: 1500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D8953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Main Building    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-CMU-65    Visible Covered      Damaged: Yes  No     Friable  Non-Friable   
 General Description: Concrete Masonry Unit    Size: 3" X 16"  
 Matrix/Primary Color: Gray    Texture/Pattern: Cementitious    Cover/Secondary Color: N/A  
 Quantity of Material: 50    Estimated By:  Drawing  Field Measure     Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *Dane Thompson*    Date: 9-07-07    Signature: *Michael Coleman*    Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-EXY-66 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Expansion Joint Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: N/A  
 Quantity of Material: 100 SF / LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-67 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Concrete Visible Covered    
 Matrix/Primary Color: Gray Texture/Pattern: Granular Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 17,000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Main Building Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-EXJ-68 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Expansion Joint Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: \_\_\_\_\_ Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ACT-01 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Acoustical Ceiling Tile Size: 1'x1'  
 Matrix/Primary Color: Gray Texture/Pattern: Craters Cover/Secondary Color: White  
 Quantity of Material: 2000 Estimated By:  Drawing  Sampled  Assumed  
 SF / LF / EA  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Nw Corner	E 0'	S 10'	8'	F / W / C / O
B		Nw Corner	E 0'	S 8'	8'	F / W / C / O
C		Sw Corner	E 0'	N 6'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 271-7877  
 (602) 271-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-02 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Visible Covered  ACT Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 500 (SF) / LF / EA Estimated By:  Drawing  Assumed  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ACT-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DR* Date: 9-07-07 Signature: *Michael Cole* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03 Damaged:  Yes  No  Friable  Non-Friable

General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6wB-04 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: White Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Quantity of Material: 2000 SF / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-05 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable

General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 200 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: OSR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-TWP-06 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Tackable Wall Panel Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 900 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *CSR* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-07 Visible Covered  TWP Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Bubble Cover/Secondary Color: N/A  
 Quantity of Material: 225 Estimated By:  Drawing  Sampled  Assumed  
 SF / LF / EA  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-DC

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-08 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Wallbox (covered) Size: 4"  
 Matrix/Primary Color: Gray Texture/Pattern: Vinyf-Like Cover/Secondary Color: N/A  
 Quantity of Material: 80 (SF) / LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-ADH-09    Visible Covered:  WAB    Damaged:  Yes     No    Friable:     Non-Friable:   
 General Description: Adhesive    Size: N/A  
 Matrix/Primary Color: Cream    Texture/Pattern: Pliable    Cover/Secondary Color: N/A  
 Quantity of Material: 80    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-D8

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *[Signature]*    Date: 9-07-07    Signature: *[Signature]*    Date: 9-07-07

Asbestos-Containing Material:  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.ortf

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable D1/D2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-USF-12     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Vinyl Sheet Flooring    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** Marbled  
**Quantity of Material:** 100     SF / LF / EA    **Estimated By:**  Drawing     Field Measure  
 Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Gray Paper Backing

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9268 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-13 Damaged:  Yes  No  Friable  Non-Friable

General Description: Mastic Visible Covered  VSF Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Tacky Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VSE-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CPT-14 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Carpet Visible  Covered  Size: N/A  
 Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored  
 Quantity of Material: 1900 Estimated By:  Drawing  Sampled   
 LF / EA  Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-15 Visible Covered  CPT Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastie Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 1900 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-14

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-0288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable D1/D2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-FDI-16     Visible     Friable  
 Covered     Non-Friable  
**General Description:** Fire Door Insulation    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** N/A    **Texture/Pattern:** Metal Cladding    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 105     Drawing     Sampled  
 SF / LF / EA     Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-SCT-17    Damaged:  Yes     No    Friable:     Non-Friable:   
 General Description: Seabert    Visible Covered:         Size: N/A  
 Matrix/Primary Color: White    Texture/Pattern: Dr.able    Cover/Secondary Color: N/A  
 Quantity of Material: 6    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *OS4*    Date: 9-07-07    Signature: *Michael Coleman*    Date: 9-07-07  
 Asbestos-Containing Material:  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf



**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable D1/D2      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-SAC-18       Visible       Damaged:  Yes       No       Friable       Non-Friable  
**General Description:** Sink Acoustical Coating       Covered       No      Size: N/A  
**Matrix/Primary Color:** White      Texture/Pattern: Rough      Cover/Secondary Color: N/A  
**Quantity of Material:** 4      (SF) / LF / EA      Estimated By:  Drawing       Field Measure       Sampled       Assumed

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other

**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SCT-19      Damaged:  Yes       No      Friable       Non-Friable   
 Visible       Covered       Size: N/A

General Description: Sealant (Duct)  
 Matrix/Primary Color: White      Texture/Pattern: Brick  
 Cover/Secondary Color: N/A  
 Quantity of Material: 5      Estimated By:  Drawing       Field Measure  
 Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-SLT-20    Damaged:  Yes     No    Friable:     Non-Friable:   
 General Description: Sealant    Visible Covered:         Size: N/A  
 Matrix/Primary Color: Black    Texture/Pattern: Pliable    Cover/Secondary Color: N/A  
 Quantity of Material: 6    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *Dane Thompson*    Date: 9-07-07    Signature: *Michael Coleman*    Date: 9-07-07  
 Asbestos-Containing Material:  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-21 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Spray-Applied Texture Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CWB-22 Visible Covered SAT Damaged: Yes No Friable Non-Friable  
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed  
 Quantity of Material: 1000 SF LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-21

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-23 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Joint Compound Visible Covered SAT Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CWB-22

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: A1-VSE-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Sheet Flooring Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Mottled  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-27 Visible Covered  VSF Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastie Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 250 (SF) LF / EA Estimated By:  Drawing  Sampled  
 Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VSF-26

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: B9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-9288 fax

**FM GROUP INC**



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADK-30 Visible Covered FRP Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 16 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Purlins, WHITE, TEXTURED

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-3288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-31 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Visible  Covered  Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 9 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-33 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 1 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAAS-34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic (Penetrations and Flashing) Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: Battle Cover/Secondary Color: N/A  
 Quantity of Material: 25 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CTG-35 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Coating (Duct) Visible  Covered   
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable D1/D2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-36 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: CONCRETE Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A  
 Quantity of Material: 600 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Date: 9-07-07

Asbestos-Containing Material:  No  Yes ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ACT-01     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable

**General Description:** Acoustical Ceiling Tile    **Size:** 1' x 1'

**Matrix/Primary Color:** Gray    **Texture/Pattern:** Craters    **Cover/Secondary Color:** White

**Quantity of Material:** 2000    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	M2	SW Corner	E 12'	N 0'	8'	F / W / C / O
B	M2	SE Corner	W 10'	N 0'	8'	F / W / C / O
C	M1	SW Corner	E 10'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-02 Visible Covered  ACT Damaged:  Yes  No Friable  Non-Friable

General Description: Adhesive Texture/Pattern: Brittle Cover/Secondary Color: N/A Size: N/A

Matrix/Primary Color: Brown Quantity of Material: 500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-Act-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03. Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 (SF) LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DJR* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-608-04      **Damaged:**  Yes       No       Friable       Non-Friable  
**General Description:** Gypsum Wallboard      **Visible Covered:** SAT      **Size:** N/A  
**Matrix/Primary Color:** White      **Texture/Pattern:** Chalky      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 2000      **Estimated By:**  Drawing       Field Measure       Sampled       Assumed  
**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other

**Manner of Sampling:**  Random       Convenience       N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with S-SAT-03

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7677  
(602) 277-8288 fax

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: S-JTC-05    Visible Covered SAT    Damaged:  Yes  No    Friable  Non-Friable   
 General Description: Joint Compound    Size: N/A

Matrix/Primary Color: White    Texture/Pattern: Chalky    Cover/Secondary Color: N/A  
 Quantity of Material: 200    Estimated By:  Drawing  Field Measure     Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-04

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *[Signature]*    Date: 9-07-07    Signature: *[Signature]*    Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-Twp-06 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Tackable Wall Panel Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 1000 Estimated By:  Drawing  Sampled  
 LF / EA  Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-07     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Adhesive     Covered    TWP    Size: N/A  
**Matrix/Primary Color:** Brown    Texture/Pattern: Brick    Cover/Secondary Color: N/A  
**Quantity of Material:** 250     LF / EA    Estimated By:  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-TWP-06

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-08 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Wallbase (covered) Size: 4"  Sampled  Assumed

Matrix/Primary Color: Dark Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A  
 Quantity of Material: 80 (SF) LF / EA Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-AD14-09      Visible      Damaged:  Yes       No      Friable      Non-Friable  
 Covered      WAB       No       Non-Friable

General Description: Adhesive      Size: N/A  
 Matrix/Primary Color: Cream      Texture/Pattern: Pliable      Cover/Secondary Color: N/A  
 Quantity of Material: 80      (SF) LF / EA      Estimated By:  Drawing       Field Measure  
 Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-08

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACIM/DesignRecord.omf

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-VSE-12    Damaged:  Yes     No     Friable     Non-Friable  
 General Description: Vinyl Sheet Flooring    Visible Covered:         Size: N/A  
 Matrix/Primary Color: White    Texture/Pattern: Smooth    Cover/Secondary Color: Marbled  
 Quantity of Material: 100    (SF) LF / EA    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: [Signature]    Date: 9-07-07    Signature: [Signature]    Date: 9-07-07

Asbestos-Containing Material:  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax





**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-MAS-13      **Damaged:**  Yes       No       Friable       Non-Friable  
**General Description:** Mastic      **Visible Covered:** USE      **Size:** N/A  
**Matrix/Primary Color:** Cream      **Texture/Pattern:** Tacky      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 100      **Estimated By:**  Drawing       Field Measure  
 SF / LF / EA       Wall       Other       Sampled       Assumed

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-VSE-12

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-CPT-14     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Carpet    **Size:** N/A

**Matrix/Primary Color:** Blue    **Texture/Pattern:** Fibrous    **Cover/Secondary Color:** Multi-Colored  
**Quantity of Material:** 1900     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *Dane Thompson*    **Date:** 9-07-07    **Signature:** *Michael Coleman*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-MAS-15    **Visible Covered:**  CPT    **Damaged:**  Yes     No    **Friable:**  **Non-Friable:**   
**General Description:** Mastic    **Size:** N/A  
**Matrix/Primary Color:** Yellow    **Texture/Pattern:** Tacky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 1900    **Estimated By:**  Drawing     Field Measure    **Sampled:**  **Assumed:**

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-CPT-14

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHIERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-F01-16 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Fire Door Insulation Size: N/A  
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A  
 Quantity of Material: 105 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHIERA Certificate No.: D9953 State License: EPA AHIERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-SCT-17       Visible       Damaged:  Yes       No       Friable       Non-Friable  
 Covered      **Size:** N/A

**General Description:** Sealant  
**Matrix/Primary Color:** White      **Texture/Pattern:** Pliable      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 6       SF / LF / EA      **Estimated By:**  Drawing       Field Measure       Sampled       Assumed

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **State License:** EPA      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Date:** 9-07-07      **Signature:** *[Signature]*      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326      Project Name: AHIERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SAC-18      Damaged:  Yes       Friable  
 Visible       Covered       Non-Friable  
 Acoustical Coating      Size: N/A  
 General Description: Sink Acoustical Coating  
 Matrix/Primary Color: White      Texture/Pattern: Rough      Cover/Secondary Color: N/A  
 Quantity of Material: 4      Estimated By:  Drawing       Sampled  
 LF / EA       Field Measure

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHIERA Certificate No.: D9953      State License: EPA      AHIERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-19 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Duct) Visible  Covered  Size: N/A

Matrix/Primary Color: White Texture/Pattern: Bubble Cover/Secondary Color: N/A  
 Quantity of Material: 5 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-20 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Seabent Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: N/A  
 Quantity of Material: 6 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesig/Record.oft



Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: S-SAT-21    Damaged:  Yes     No     Friable     Non-Friable  
 General Description: Spray-Applied Texture    Visible Covered:         Size: N/A  
 Matrix/Primary Color: White    Texture/Pattern: Chalky    Cover/Secondary Color: N/A  
 Quantity of Material: 1000    (SF) / LF / EA    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *[Signature]*    Date: 9-07-07    Signature: *[Signature]*    Date: 9-07-07

Asbestos-Containing Material:  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-22 Visible Covered SAT Damaged: Yes No Friable Non-Friable  
 General Description: Gypsum wallboard Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 1000 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other  
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with SSAT-21

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: DSTZ Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-23 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Joint Compound Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 100 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-22

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VSF-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Sheet Flooring Size: N/A

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MA5-27 Visible Covered  Visible  Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 250 (SF) LF / EA Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  Field Measure

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VsE-26

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M1/M2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SLT-31     Visible     Damaged:  Yes     No     Friable     Non-Friable  
 Covered  
**General Description:** Sealant    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 9     SF / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MA5-34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic (Penetrations and Flashing) Visible Covered  
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 25 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CTG-35 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Coating (Duct) Visible  Covered  Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M1/M2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M.CON.36 Damaged:  Yes  No Friable  Non-Friable   
 General Description: CONCRETE Visible  Covered  Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CONTINUOUS Cover/Secondary Color: N/A  
 Quantity of Material: 600 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes **ASSUMED**

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-5266 fax

Project No.: 07-326 Project Name: AHRA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ACT-01 Damaged:  Yes  No Friable  Non-Friable

General Description: Acoustical Ceiling Tile Size: 1' x 1'

Matrix/Primary Color: Gray Texture/Pattern: Craters Cover/Secondary Color: White  
 Quantity of Material: 1800 Estimated By:  Drawing  Field Measure  Sampled Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	M4	SW Corner	E 6'	N 0'	8'	F / W / C / O
B	M4	SE Corner	W 12'	N 0'	8'	F / W / C / O
C	M3	SW Corner	E 12'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHRA Certificate No.: D9953 State License: EPA AHRA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-02 Visible Covered ACT Damaged:  Yes  No Friable  Non-Friable

General Description: Adhesive Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A

Quantity of Material: 450 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ACT-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray Applied Texture Visible  Covered   
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 2000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8268 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-GWB-04 Visible Covered SAT Damaged: Yes No Friable Non-Friable  
 General Description: Gypsum Wallboard Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other  
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: CSR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-05 Visible Covered SAT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 200 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WB-04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable M3/M4

Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo

Chandler, Arizona 85226

Material Code: M-TWP-06 Damaged:  Yes  No Friable  Non-Friable

General Description: Tackable Wall Panel Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: VINYL COVEY

Quantity of Material: 750 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M3/M4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-AD14-07    **Visible**  Covered TWP    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Adhesive    **Size:** N/A

**Matrix/Primary Color:** Brown    **Texture/Pattern:** Brittle    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 190    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other     N/A

**Manner of Sampling:**  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-TWP-06

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

  
 15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M3/M4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-WAB-08     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Wallbase (covered)    Size: 4"

**Matrix/Primary Color:** Dark Blue    Texture/Pattern: Vinyl-Like    Cover/Secondary Color: N/A  
**Quantity of Material:** 80     SF / LF / EA    Estimated By:  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *DR*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M3/M4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-09    **Visible Covered:**  WAB    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Adhesive    **Size:** N/A  
**Matrix/Primary Color:** Cream    **Texture/Pattern:** Diabole    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 80    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-WAB-08

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VS-F-12 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Vinyl Sheet Flooring Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled  
 Quantity of Material: 300 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ami

**Project No.:** 07-326      **Project Name:** AHIERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M3/M4      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-MAS-13      **Visible Covered:**  **Visible:**       **Damaged:**  Yes       No      **Friable:**       **Non-Friable:**   
**General Description:** Mastic      **Size:** N/A

**Matrix/Primary Color:** Cream      **Texture/Pattern:** Tacky      **Cover/Secondary Color:** N/A  
**Quantity of Material:** 300      **Estimated By:**  Drawing       Field Measure  
**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other       Sampled       Assumed

**Manner of Sampling:**  Random       Convenience       N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-USF-12

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Signature:** *[Signature]*      **Date:** 9-07-07      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CPT-14 Damaged:  Yes  No  Friable  Non-Friable

General Description: Carpet Visible Covered   Size: N/A

Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored

Quantity of Material: 1700 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85280  
(602) 277-7877  
(602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-15 Visible Covered  CPT Damaged:  Yes  No Friable  Non-Friable

General Description: Mastic Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Fibrous Cover/Secondary Color: N/A

Quantity of Material: 1700 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other


Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-14

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: CR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed



**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-FD1-16 Damaged:  Yes  No Friable  Non-Friable

General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A

Quantity of Material: 105 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9268 fax

FM GROUP/forms/SuspAsbCMDesigRecord.ami

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-17 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A  
 Quantity of Material: 12 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A  
 Texture/Pattern: Pliable  
 Visible  Covered  
 LF / EA  SF

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SAC-18 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sink Acoustical Coating Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A  
 Quantity of Material: 4 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-19 Damaged:  Yes  No  Friable  Non-Friable  
 Visible  Covered

General Description: Sealant (Duct) Size: N/A  
 Matrix/Primary Color: White Cover/Secondary Color: N/A  
 Quantity of Material: 5 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-5CT-20 Damaged:  Yes  No  Friable  Non-Friable

General Description: Sealant Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: N/A

Quantity of Material: 6 Estimated By:  Drawing  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson

Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA

AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: *DST* Date: 9-07-07

Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable M3/M4

Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo

Chandler, Arizona 85226

Material Code: S-SAT-21 Damaged:  Yes  No  Friable  Non-Friable

General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 1900 Estimated By:  Drawing  Assumed  
 LF / EA  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson

Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA

AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: *DR* Date: 9-07-07

Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85280  
(602) 277-7877  
(602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M3/M4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-6WB-ZZ    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Gypsum Wallboard    **Visible Covered:** SAT    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalety    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 1900    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with S-SAT-Z1

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-216-23 Visible  Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Joint Compound Covered  SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 190 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-22

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable M3/M4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-VSF-26     Visible     Covered     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Vinyl Sheet Flooring    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Smooth    **Cover/Secondary Color:** Marbled  
**Quantity of Material:** 250     SP / LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Gray Paper Backing

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7677  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M.MAS-27 Visible Covered  USF Damaged:  Yes  No Friable  Non-Friable

General Description: Mastic Texture/Pattern: Tacky Size: N/A  
 Matrix/Primary Color: Yellow Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-USF-26

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-30 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Visible Covered FRP Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Br+tk Cover/Secondary Color: N/A  
 Quantity of Material: 16 SF / LF / EA Estimated By:  Drawing  Field Measure Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Paneling, white, 1259, 259

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DTC* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/Forms/SuspACMDesig/Record.oft

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SLT-31      Damaged:  Yes       No       Friable       Non-Friable  
 General Description: Sealant      Visible Covered      Size: N/A  
 Matrix/Primary Color: White      Texture/Pattern: Pliable      Cover/Secondary Color: N/A  
 Quantity of Material: 9      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-33 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 1 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MA5-34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic (Penetrations and Flashing) Visible Covered  
 Matrix/Primary Color: Black Texture/Pattern: Brk Hk Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 25 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FIM GROUP INC.**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CTG-35 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Coating (Duct) Visible Covered    
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable M3/M4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-36 Damaged:  Yes  No Friable  Non-Friable   
 General Description: CONCRETE Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A  
 Quantity of Material: 600 SFY LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes **ASSUMED**

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-Act-01 Damaged:  Yes  No Friable  Non-Friable  
 General Description: Acoustical Ceiling Tile Size: 1' X 1'

Matrix/Primary Color: Gray Texture/Pattern: Craters Cover/Secondary Color: White  
 Quantity of Material: 2000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	R1	NW Corner	E 6'	S 0'	8'	F / W / C / O
B	R1	NE Corner	W 4'	S 0'	8'	F / W / C / O
C	R2	NW Corner	E 10'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADIT-02 Damaged:  Yes  No Friable  Non-Friable

General Description: Adhesive Visible Covered ACT Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A

Quantity of Material: 500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-Act-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray-Applied Texture Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-6wB-04    **Visible:**  Covered SAT    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Gypsum Wallboard    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chertky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 2000    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with S-SAT-03

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-3TC-05 Visible Covered SAT Damaged: Yes No Friable Non-Friable  
 General Description: Joint Compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed  
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CWB-04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-TWP-06 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Tackable Wall Panel Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DR* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-07 Visible Covered TWP Damaged: Yes No Friable Non-Friable

General Description: Adhesive Texture/Pattern: Beattie Cover/Secondary Color: N/A Size: N/A

Matrix/Primary Color: Brown Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other Manner of Sampling: Random Convenience N/A

Table with columns: Sample ID, Sample Location, Points of Origin, East/West Direction, North/South Direction, Height A.F.F., Surface. Rows A-G.

Comments: Associated with M-TWP-06

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA Signature: CSR Date: 9-07-07 Signature: Michael Coleman Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM FM GROUP INC 15974 N. 77th Street Scottsdale, AZ 85260 (602) 277-7877 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-08 Damaged:  Yes  No  Friable  Non-Friable

General Description: Wallbase (low) Size: 4"

Matrix/Primary Color: Dark Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A

Quantity of Material: 75 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson

AHERA Certificate No.: D9953 State License: EPA

Signature: *DTC* Date: 9-07-07

Secondary Inspector: Michael Coleman

AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-09 Visible  Covered  WAB Damaged:  Yes  No Friable  Non-Friable

General Description: Adhesive Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: Cream Estimated By:  Drawing  Field Measure  Sampled  Assumed

Quantity of Material: 75 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  N/A  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R1/R2

Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo

Chandler, Arizona 85226

Material Code: M-WAB-10 Damaged:  Yes  No Friable  Non-Friable

General Description: Wallbox (covered) Size: 4"

Matrix/Primary Color: Brown Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson

Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953

State License: EPA

AHERA Certificate No.: BIIA040907-01

State License: EPA

Signature: *[Signature]*

Date: 9-07-07

Signature: *[Signature]*

Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-9288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-11    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Adhesive    **Visible Covered:**  WAB    **Size:** N/A  
**Matrix/Primary Color:** Cream    **Texture/Pattern:** Diable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 10    **Estimated By:**  Drawing     Field Measure  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-WAB-10

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *DTP*    **Date:** 9-07-07    **Signature:** *M. Cole*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-VSF-12     Visible     Friable  
 Covered     Damaged:  Yes     Non-Friable  
**General Description:** Vinyl Sheet Flooring     No     Drawing     Sampled  
**Matrix/Primary Color:** White     Field Measure     Assumed  
**Quantity of Material:** 100     Estimated By:     Cover/Secondary Color: Marbled  
 SF     LF / EA     Texture/Pattern: Smooth     Size: N/A

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Gray Paper Backing

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MA5-13 Visible Covered  Visible  Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic Size: N/A  
 Matrix/Primary Color: Cream Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 100 SF / LF / EA Estimated By:  Drawing  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  Field Measure

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VSF-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-6288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-CPT-14     Visible     Damaged:  Yes     No     Friable     Non-Friable  
 Covered     Other

**General Description:** Carpet    **Size:** N/A  
**Matrix/Primary Color:** Blue    **Texture/Pattern:** Fibrous    **Cover/Secondary Color:** Multi-Colored  
**Quantity of Material:** 1900     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-MAS-K      Visible Covered  CPT      Damaged:  Yes       No       Friable       Non-Friable  
 General Description: Mastic      Size: N/A  
 Matrix/Primary Color: Yellow      Texture/Pattern: Tacky      Cover/Secondary Color: N/A  
 Quantity of Material: 1900      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-14

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: DR      Date: 9-07-07      Signature: [Signature]      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-FD1-16     Visible     Covered     Friable     Non-Friable  
**General Description:** Fire Door Insulation    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** N/A    **Texture/Pattern:** Metal Cladding    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 105     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



45974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-17 Damaged:  Yes  No Friable  Non-Friable

General Description: Sealant Size: N/A  
 Matrix/Primary Color: White Cover/Secondary Color: N/A  
 Quantity of Material: 6 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SAC-18      Damaged:  Yes       No      Friable  Non-Friable   
 General Description: Sink Acoustical Coating      Size: N/A  
 Matrix/Primary Color: White      Texture/Pattern: Rough      Cover/Secondary Color: N/A  
 Quantity of Material: 4      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-DCT-19 Damaged:  Yes  No Friable  Non-Friable

General Description: Sealant (Duct) Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 5 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: DR Date: 9-07-07 Signature: Michael Coleman Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-20 Material:  Visible  Covered  Friable  Non-Friable  
 Damaged:  Yes  No Size: N/A

General Description: Sealant  
 Matrix/Primary Color: Black Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 6 (SF) / LF / EA Estimated By:  Drawing  Sampled  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-21 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Spray Applied Texture Visible Covered    
 Matrix/Primary Color: White Texture/Pattern: Chisel Size: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC.**

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-GWB-22    Damaged:  Yes     No     Friable     Non-Friable  
 General Description: Cypsum Wallboard    Visible Covered: SAT    Size: N/A  
 Matrix/Primary Color: White    Texture/Pattern: Charlley    Cover/Secondary Color: N/A  
 Quantity of Material: 1000    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with SAT-21

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: [Signature]    Date: 9-07-07    Signature: [Signature]    Date: 9-07-07

Asbestos-Containing Material:  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-JTC-23     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Joint Compound     Covered    SAT    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 100     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-GWR-22

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (802) 277-7877  
 (802) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-24 Damaged:  Yes  No  Friable  Non-Friable  
 Visible Covered

General Description: Vinyl Composition Tile Size: 24" X 24"  
 Matrix/Primary Color: Gray Texture/Pattern: TEXTURED Cover/Secondary Color: VINYL-LIKE  
 Quantity of Material: 80 Estimated By:  Drawing  Sampled  
 Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: CIRCLE PATTERNS

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-MAAS-2S     Visible     Covered    VCT    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Mastic    **Size:** N/A  
**Matrix/Primary Color:** Yellow    **Texture/Pattern:** Tacky    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 80     SF     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-VCT-24.

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** [Signature]    **Date:** 9-07-07    **Signature:** [Signature]    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-USF-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Sheet Flooring Visible  Covered   
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled Size: N/A  
 Quantity of Material: 170 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M.A.S.-27     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Mastic     Covered    VSF    Size: N/A  
**Matrix/Primary Color:** Yellow    Texture/Pattern: Tacky    Cover/Secondary Color: N/A  
**Quantity of Material:** 170     SF / LF / EA    Estimated By:  Drawing     Sampled     Assumed  
 Field Measure

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M.V.S.F.-2.6

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BJA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-28 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Wallbase (covered) Visible  Covered  Size: 6"

Matrix/Primary Color: Gray 4 Texture/Pattern: Viny-like Cover/Secondary Color: N/A  
 Quantity of Material: 4 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 86260  
 (802) 277-7877  
 (802) 277-3288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-29 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 4 Estimated By:  Drawing  Sampled  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other Field Measure  Assumed

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-28

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16574 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8286 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-31 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Plaster Cover/Secondary Color: N/A  
 Quantity of Material: 8 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MS-37 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mastic Penetrations and Flashing Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 25 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R1/R2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-CTG-35     Visible     Damaged:  Yes     No     Friable     Non-Friable  
**General Description:** Coating (Duct)     Covered    **Size:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 40     LF / EA    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIJA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable R1/R2    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M.CON-36    Damaged:  Yes     No     Friable     Non-Friable  
 General Description: CONCRETE    Visible Covered:  Visible     Covered    Size: N/A

Matrix/Primary Color: GRAY    Texture/Pattern: GRANULOUS    Cover/Secondary Color: N/A  
 Quantity of Material: 600    Estimated By:  Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:  Ceiling     Floor     Wall     Other  
 Manner of Sampling:  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *[Signature]*    Date: 9-07-07    Signature: *[Signature]*    Date: 9-07-07

Asbestos-Containing Material:  No     Yes    ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ACT-01 Damaged:  Yes  No Friable  Non-Friable

General Description: Acoustical Ceiling Tile Size: 1' x 1'  
 Matrix/Primary Color: Gray Texture/Pattern: Grates Cover/Secondary Color: White

Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A R3		SW Corner	E 8'	N 0'	8'	F / W / C / O
B R3		SW Corner	E 20'	N 0'	8'	F / W / C / O
C R4		SE Corner	W 12'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.cfm



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD4-02 Visible Covered ACT Damaged: Yes No Friable Non-Friable

General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brattle Cover/Secondary Color: N/A  
 Quantity of Material: 500 (SF) LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ACT-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03 Damaged:  Yes  No Friable  Non-Friable

General Description: Spray-Applied Texture Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DK* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street  
 Scottsdale, AZ 85280  
 (802) 277-7677  
 (802) 277-8288 fax



Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-6wB-04    Visible     Covered    SAT    Damaged:     Yes     No    Friable        Non-Friable      
 General Description: Gypsum Wallboard    Size: N/A  
 Matrix/Primary Color: White    Texture/Pattern: Chalky    Cover/Secondary Color: N/A  
 Quantity of Material: 2.000    (SF) / LF / EA    Estimated By:     Drawing     Field Measure     Sampled     Assumed

Homogeneous Material Location:     Ceiling     Floor     Wall     Other  
 Manner of Sampling:     Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-03

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *Dane Thompson*    Date: 9-07-07    Signature: *Michael Coleman*    Date: 9-07-07

Asbestos-Containing Material:     No     Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R3/R4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** S-JTC-05    **Visible Covered:** SAT    **Damaged:**  Yes     No    **Size:** N/A  
 Friable     Non-Friable

**General Description:** Joint Compound    **Texture/Pattern:** Chalky    **Cover/Secondary Color:** N/A  
**Matrix/Primary Color:** White    **Estimated By:**  Drawing     Field Measure  
**Quantity of Material:** 200     SF / LF / EA     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-GWB-CX

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R3/R4

Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo

Chandler, Arizona 85226

Material Code: M-TWP-06 Damaged:  Yes  No Friable  Non-Friable

General Description: Tackable Wall Panel Size: N/A

Matrix/Primary Color: Brown Cover/Secondary Color: Vinyl Cover

Quantity of Material: 1000 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson

Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953

AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: DR

Signature: [Signature]

Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD14-07 Visible Covered TWP Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Be-ttle Cover/Secondary Color: N/A  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-06

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-WAB-08      Visible  Covered       Damaged: Yes  No       Friable  Non-Friable   
 General Description: Wallbase (ceiling)      Size: 4' x 4'

Matrix/Primary Color: Dark Blue      Texture/Pattern: Vinyl-Like      Cover/Secondary Color: N/A  
 Quantity of Material: 75      Estimated By:      Drawing  Field Measure       Sampled  Assumed

Homogeneous Material Location: Ceiling  Floor  Wall  Other   
 Manner of Sampling: Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	EastWest Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-09 Visible Covered  WAB Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 75 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-08

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax





Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-10 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Wallbase (covered) Size: 4"

Matrix/Primary Color: Brown Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A  
 Quantity of Material: 10 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

FM GROUP/forms/SuspACMDesignRecord.orm

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-11 Visible Covered  WAB Damaged:  Yes  No Friable  Non-Friable

General Description: Adhesive Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-10

Lead Inspector: Dane Thompson

AHERA Certificate No.: D9953 State License: EPA

Signature: [Signature] Date: 9-07-07

Secondary Inspector: Michael Coleman

AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VSF-12 Damaged:  Yes  No Friable  Non-Friable

General Description: Vinyl Sheet Flooring Size: N/A

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-13 Visible Covered  VSF Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mastic Size: N/A  
 Matrix/Primary Color: Cream Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VS-F-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CPT-14 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Carpet Size: N/A  
 Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored  
 Quantity of Material: 1900 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.amf

Project No.: 07-326    Project Name: AHERA Asbestos Inspection    Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4    Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo    Chandler, Arizona 85226

Material Code: M-MAJ-15    Visible Covered:  CPT    Damaged:  Yes  No    Friable:  Non-Friable:   
 General Description: Mastic    Texture/Pattern: Tacky    Cover/Secondary Color: N/A    Size: N/A  
 Matrix/Primary Color: Yellow    Estimated By:  Drawing  Field Measure     Sampled  Assumed  
 Quantity of Material: 1900    (SF) LF / EA    Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-14

Lead Inspector: Dane Thompson    Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953    State License: EPA    AHERA Certificate No.: BIIA040907-01    State License: EPA  
 Signature: *[Signature]*    Date: 9-07-07    Signature: *[Signature]*    Date: 9-07-07

Asbestos-Containing Material:  No  Yes    Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable R3/R4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-FDI-16     Visible     Covered     Friable     Non-Friable  
**General Description:** Fire Door Insulation    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** N/A    **Texture/Pattern:** Metal Cladding    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 105    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-17 Damaged:  Yes  No Friable  Non-Friable

General Description: Sealant Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A

Quantity of Material: 6 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.cmf



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SAC-18 Damaged:  Yes  No Friable  Non-Friable

General Description: Sink Acoustical Coating Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 4 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:


Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-19 Damaged:  Yes  No Friable  Non-Friable

General Description: Sealant (Duct) Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 5 Estimated By:  Drawing  Field Measure  
 Texture/Pattern: Bottle

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-20 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 6 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-DAT-21 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Spray-Applied Texture Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 1000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-22 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Exposed Wallboard Visible Covered SAT Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chunky Cover/Secondary Color: N/A  
 Quantity of Material: 1000 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-21

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (802) 277-7877  
 (802) 277-8288 fax

Project No.: 07-326 Project Name: AHRA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: 5-JTC-23 Material Code: 5-JTC-23  
 General Description: Joint Compound  
 Matrix/Primary Color: White  
 Quantity of Material: 100  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Damaged:  Yes  No  
 Friable  Non-Friable   
 Size: N/A  
 Cover/Secondary Color: N/A  
 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with m-GWTS-22

Lead Inspector: Dane Thompson  
 AHRA Certificate No.: D9953 State License: EPA  
 Signature: [Signature] Date: 9-07-07  
 Secondary Inspector: Michael Coleman  
 AHRA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VCT-24 Material:  Visible  Covered  Friable  Non-Friable  
 General Description: Vinyl Composition Tile Size: 24" x 24"

Matrix/Primary Color: Gray Texture/Pattern: TEXTURED Cover/Secondary Color: VINYL-LIKE  
 Quantity of Material: 80 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: CIRCLES PATTERNS

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MA5-25 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic Visible Covered  VCT Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 80 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-24

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VSFR-26 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Vinyl Sheet Flooring Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled Size: N/A  
 Quantity of Material: 170 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: CSR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-27 Visible Covered  Visible Covered  Damaged:  Yes  No  Friable  Non-Friable

General Description: Mastic Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 170 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VST-26

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: MWA8-28 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Wall base (covered) Visible  Covered  Size: 6"  
 Matrix/Primary Color: Gray Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A  
 Quantity of Material: 4 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD4-29 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 4 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-28

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DTC* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD14.30 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Br.Hk Cover/Secondary Color: N/A  
 Quantity of Material: 16 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Parking, ~~with~~, ~~tested~~

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-31 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Plicke Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 7 SF LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCF-32 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 2 (SF) / LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-35 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 1 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M.A.S.34 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Asbestos (Penetrations and Flashing) Visible  Covered   
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 25 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CTG-35 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Ceiling (Duct) Visible Covered  
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07  
 Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

**FIM**  
GROUP INC

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable R3/R4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-36 Damaged:  Yes  No Friable  Non-Friable   
 General Description: CONCRETE Visible  Covered  Size: N/A  
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A  
 Quantity of Material: 400 SE/ LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ACT-01 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Acoustical Ceiling Tile Size: 1'x1'

Matrix/Primary Color: Gray Texture/Pattern: Craters Cover/Secondary Color: White  
 Quantity of Material: 2000 (SF) / LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	T2	SW Corner	E 10'	N 0'	8'	F / W / C / O
B	T2	SE Corner	W 8'	N 0'	8'	F / W / C / O
C	T1	SW Corner	E 15'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 277-7877  
 (602) 277-9288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-02 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Visible  Covered ACT Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 500 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ACT-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *DRT* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Spray-Applied Texture Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB-04 Visible Covered SAT Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Exposed Wallboard Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-326 Project Name: AHRA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-JTC-05 Visible Covered SAT Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Joint compound Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 200 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-04

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHRA Certificate No.: D9953 State License: EPA AHRA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T1/T2      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-Twp-06       Visible       Covered       Damaged:  Yes       No       Friable       Non-Friable  
**General Description:** Tackable Wall Panel      **Size:** N/A  
**Matrix/Primary Color:** Brown      **Texture/Pattern:** Fibrous      **Cover/Secondary Color:** Vinyl Cover       Sampled       Assumed  
**Quantity of Material:** 1000       SF / LF / EA      **Estimated By:**  Drawing       Field Measure  
**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other

**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Signature:** *[Signature]*      **Date:** 9-07-07      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADH-07 Visible Covered  Twp Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Bottle Cover/Secondary Color: N/A  
 Quantity of Material: 250 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-06

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T1/T2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-WAB-08     Visible     Covered    **Damaged:**  Yes     No    **Size:** 4"     Friable     Non-Friable  
**General Description:** Wallbox (loud)    **Texture/Pattern:** Vinyl-Like    **Cover/Secondary Color:** N/A     Sampled     Assumed  
**Matrix/Primary Color:** Dark Blue    80     SF /  LF / EA    **Estimated By:**  Drawing     Field Measure  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ADit-09 Visible Covered WAB Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: Green Estimated By:  Drawing  Field Measure  
 Quantity of Material: 80 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-08

Lead Inspector: Dane Thompson State License: EPA Date: 9-07-07  
 AHERA Certificate No.: D9953 State License: EPA Date: 9-07-07  
 Signature: [Signature] Signature: [Signature] Date: 9-07-07

Secondary Inspector: Michael Coleman State License: EPA Date: 9-07-07  
 AHERA Certificate No.: BIIA040907-01 State License: EPA Date: 9-07-07  
 Signature: [Signature] Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-3288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-VSF-12 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Vinyl Sheet Flooring Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled  
 Quantity of Material: 100 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-13 Visible Covered  USF Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mastic Texture/Pattern: Tacky Cover/Secondary Color: N/A Size: N/A  
 Matrix/Primary Color: Cream Estimated By:  Drawing  Field Measure  
 Quantity of Material: 100 (SF) / LF / EA

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-USF-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

**F/M**  
GROUP INC

FM GROUP/forms/SuspACIMDesignRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CPT-14 Damaged:  Yes  No Friable  Non-Friable

General Description: Carpet Size: N/A

Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored

Quantity of Material: 1900 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA

Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

### SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-15 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic Visible Covered  CPT Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 1900 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-14

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 277-7877  
 (602) 277-5288 fax





**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T1/T2    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-FDI-1G     Visible     Covered     Friable     Non-Friable  
 Damaged:  Yes     No    Size: N/A

**General Description:** Fire Door Insulation    **Texture/Pattern:** Metal Cladding    **Cover/Secondary Color:** N/A

**Matrix/Primary Color:** N/A    **Quantity of Material:** 84    **Estimated By:**  Drawing     Sampled  
 SF / LF / EA     Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

FM GROUP/forms/SuspACMDesig/Record.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-17 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant Size: N/A

Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Quantity of Material: 6 SF / LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SAC-18 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sink Acoustical Coating Size: N/A

Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A  
 Quantity of Material: 16 Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

Project No.: 07-326      Project Name: AHERA Asbestos Inspection      Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2      Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo      Chandler, Arizona 85226

Material Code: M-SCT-19      Damaged:  Yes       No      Friable       Non-Friable   
 General Description: Sealant (Duct)      Visible       Covered       Size: N/A

Matrix/Primary Color: White      Texture/Pattern: Baffle      Cover/Secondary Color: N/A  
 Quantity of Material: 5      Estimated By:  Drawing       Field Measure       Sampled       Assumed

Homogeneous Material Location:  Ceiling       Floor       Wall       Other  
 Manner of Sampling:  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: \_\_\_\_\_

Lead Inspector: Dane Thompson      Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953      State License: EPA      AHERA Certificate No.: BIIA040907-01      State License: EPA  
 Signature: *[Signature]*      Date: 9-07-07      Signature: *[Signature]*      Date: 9-07-07

Asbestos-Containing Material:  No       Yes      Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-20 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Placable Cover/Secondary Color: N/A  
 Quantity of Material: 6 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecordL.mtf

**Project No.:** 07-326      **Project Name:** AHERA Asbestos Inspection      **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T1/T2      **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo      Chandler, Arizona 85226

**Material Code:** M-MAS-21       Visible       Friable  
 Covered       Non-Friable  
**General Description:** Mastie (Penetration and Flashing)      **Damaged:**  Yes       No  
**Matrix/Primary Color:** Black      **Texture/Pattern:** Brittle      **Size:** N/A  
**Quantity of Material:** 25      **Cover/Secondary Color:** N/A  
**Estimated By:**  Drawing       Field Measure

**Homogeneous Material Location:**  Ceiling       Floor       Wall       Other  
**Manner of Sampling:**  Random       Convenience       N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson      **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953      **AHERA Certificate No.:** BIIA040907-01      **State License:** EPA  
**Signature:** *[Signature]*      **Signature:** *[Signature]*      **Date:** 9-07-07      **Date:** 9-07-07

**Asbestos-Containing Material:**  No       Yes      **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CTG-22 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Coating (Duct) Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Plicble Cover/Secondary Color: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T1/T2 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-23 Damaged:  Yes  No Friable  Non-Friable   
 General Description: CONCRETE Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A  
 Quantity of Material: 600 SP / LF / EA Estimated By:  Drawing  Field Measure  
 Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No. D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-ACT-01 Damaged:  Yes  No Friable  Non-Friable  
 General Description: Acoustical Ceiling Tile Size: 1' X 1'  
 Matrix/Primary Color: Gray Texture/Pattern: Craters Cover/Secondary Color: White  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	T4	SW Corner	E 12'	N 0'	8'	F / W / C / O
B	T3	SW Corner	E 10'	N 0'	8'	F / W / C / O
C	T3	SE Corner	W 15'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

FM GROUP/forms/SuspACM/DesignRecord.orm

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-AD14-02 Visible Covered ACT Damaged:  Yes  No Friable  Non-Friable   
 General Description: Adhesive Size: N/A  
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A  
 Quantity of Material: 500 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ACT-01

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: S-SAT-03 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Spray Applied Texture Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 (SF) LF / EA Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 277-7877  
 (602) 277-8288 fax

**FM GROUP INC**

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-6WB.04 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A  
 Quantity of Material: 2000 Estimated By:  Drawing  Field Measure  Sampled  Assumed  
 Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with SAT.03

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



16974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-5288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable T3/T4

Address: 1350 North Lakeshore Drive

Campus Name: Kyrene del Cielo

Chandler, Arizona 85226

Material Code: S-JTC-05 Visible Covered SAT Damaged: Yes No Friable Non-Friable

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Table with 7 columns: Sample ID, Sample Location, Points of Origin, East/West Direction, North/South Direction, Height A.F.F., Surface. Rows A-G.

Comments: Associated with M-GWB-04

Lead Inspector: Dane Thompson

Secondary Inspector: Michael Coleman

AHERA Certificate No.: D9953

State License: EPA

AHERA Certificate No.: BIIA040907-01

State License: EPA

Signature: [Signature]

Date: 9-07-07

Signature: [Signature]

Date: 9-07-07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street Scottsdale, AZ 85250 (602) 277-7877 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-TWP-06 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Tackable Wall Panel Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover  
 Quantity of Material: 1000 (SF) LF / EA Estimated By:  Drawing  Field Measure  
 Sampling  Sampled  
 Ceiling  Floor  Wall  Other  Assumed

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-9288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T3/T4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-07    **Damaged:**  Yes     No    **Visible:**  Covered     TWP    **Size:** N/A  
**General Description:** Adhesive    **Estimated By:**  Drawing     Field Measure  
**Matrix/Primary Color:** Brown    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 250    **Texture/Pattern:** Brittle    **Estimated By:**  Drawing     Assumed  
**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other     N/A

**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-TWP-06

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8286 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-WAB-08 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Wall base (covered) Size: 4"r

Matrix/Primary Color: Dark Blue Cover/Secondary Color: N/A  
 Quantity of Material: 80 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft



**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T3/T4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-ADH-09    **Visible Covered:**  WAB    **Damaged:**  Yes     No    **Size:** N/A  
**General Description:** Adhesive    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A  
**Matrix/Primary Color:** Cream    **Estimated By:**  Drawing     Field Measure  
**Quantity of Material:** 80    **(SF) LF / EA**

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** Associated with M-WAB-08

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    **Assumed**

**SUSPECT ASBESTOS-CONTAINING MATERIAL  
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-USF-12 Damaged:  Yes  No Friable  Non-Friable

General Description: Vinyl Sheet Flooring Size: N/A

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Marbled

Quantity of Material: 100 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other

Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: GRAY PAPER BACKING

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-9288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-13 Visible Covered  Visible  Damaged:  Yes  No  Friable  Non-Friable   
 General Description: Mastic Size: N/A  
 Matrix/Primary Color: Cream Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 100 Estimated By:  Drawing  Sampled  Assumed   
 SF / LF / EA  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-USF-12

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: DR Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes  Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CPT-14 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Carpet Visible  Covered  Size: N/A

Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored  
 Quantity of Material: 1900 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

FM GROUP/forms/SuspAspC/MSDesignRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-15 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Mastic Visible Covered  CPT Size: N/A  
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A  
 Quantity of Material: 1900 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-14

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-5288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T3/T4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-FD1-16     Visible     Covered     Friable     Non-Friable  
**General Description:** Fire Door Insulation    **Damaged:**  Yes     No    **Size:** N/A  
**Matrix/Primary Color:** N/A    **Texture/Pattern:** Metal Cladding    **Cover/Secondary Color:** N/A  
**Quantity of Material:** 84    **Estimated By:**  Drawing     Field Measure     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	EastWest Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
Scottsdale, AZ 85280  
(602) 277-7677  
(602) 277-5288 fax

Project No.: 07-326 Project Name: AHIERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SCT-17 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Sealant Size: N/A

Matrix/Primary Color: White Texture/Pattern: Plisble Cover/Secondary Color: N/A  
 Quantity of Material: 6 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHIERA Certificate No.: D9953 State License: EPA AHIERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

## SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street  
 Scottsdale, AZ 85250  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T3/T4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SAC-18     Visible     Covered     Friable     Non-Friable  
**Damaged:**  Yes     No    **Size:** N/A

**General Description:** Sink Acoustical Coating    **Cover/Secondary Color:** N/A  
**Matrix/Primary Color:** White    **Texture/Pattern:** Rough    **Estimated By:**  Drawing     Field Measure  
**Quantity of Material:** 16     SF / LF / EA     Sampled     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:** \_\_\_\_\_

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **AHERA Certificate No.:** BIIA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Signature:** *[Signature]*    **Date:** 9-07-07    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax



Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-SLT-19 Damaged:  Yes  No Friable  Non-Friable   
 General Description: Sealant (Duct) Size: N/A  
 Matrix/Primary Color: White Texture/Pattern: Bottle Cover/Secondary Color: N/A  
 Quantity of Material: 5 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA04D907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**

  
 15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

**Project No.:** 07-326    **Project Name:** AHERA Asbestos Inspection    **Owner:** Kyrene School District No. 28  
**Building No.:** Portable T3/T4    **Address:** 1350 North Lakeshore Drive  
**Campus Name:** Kyrene del Cielo    Chandler, Arizona 85226

**Material Code:** M-SCT-20     Visible     Covered    **Damaged:**  Yes     No     Friable     Non-Friable  
**General Description:** Seabert    **Size:** N/A  
**Matrix/Primary Color:** Black    **Texture/Pattern:** Pliable    **Cover/Secondary Color:** N/A     Sampled  
**Quantity of Material:** 6     LF / EA    **Estimated By:**     Drawing     Field Measure     Assumed

**Homogeneous Material Location:**  Ceiling     Floor     Wall     Other  
**Manner of Sampling:**  Random     Convenience     N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

**Comments:**

**Lead Inspector:** Dane Thompson    **Secondary Inspector:** Michael Coleman  
**AHERA Certificate No.:** D9953    **State License:** EPA    **AHERA Certificate No.:** BJA040907-01    **State License:** EPA  
**Signature:** *[Signature]*    **Date:** 9-07-07    **Signature:** *[Signature]*    **Date:** 9-07-07

**Asbestos-Containing Material:**  No     Yes    *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-MAS-21 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Mastic (Penetrations and Flashing) Size: N/A  
 Matrix/Primary Color: Black Texture/Pattern: Baffle Cover/Secondary Color: N/A  
 Quantity of Material: 25 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHRA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *[Signature]* Date: 9-07-07 Signature: *[Signature]* Date: 9-07-07

Asbestos-Containing Material:  No  Yes *Assumed*

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CTG-23 Damaged:  Yes  No  Friable  Non-Friable  
 General Description: Coating (Duct) Size: N/A  
 Matrix/Primary Color: White Cover/Secondary Color: N/A  
 Quantity of Material: 40 Estimated By:  Drawing  Assumed  
 Texture/Pattern: Pliable Cover/Secondary Color: N/A  
 Estimated By:  Drawing  Field Measure

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA  
 Signature: *Dane Thompson* Date: 9-07-07 Signature: *Michael Coleman* Date: 9-07-07

Asbestos-Containing Material:  No  Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85260  
 (602) 277-7677  
 (602) 277-6286 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-326 Project Name: AHERA Asbestos Inspection Owner: Kyrene School District No. 28  
 Building No.: Portable T3/T4 Address: 1350 North Lakeshore Drive  
 Campus Name: Kyrene del Cielo Chandler, Arizona 85226

Material Code: M-CON-23 Damaged:  Yes  No Friable  Non-Friable   
 General Description: CONCRETE Size: N/A  
 Matrix/Primary Color: GRAY Cover/Secondary Color: N/A  
 Quantity of Material: 600 Estimated By:  Drawing  Field Measure  Sampled  Assumed

Homogeneous Material Location:  Ceiling  Floor  Wall  Other  
 Manner of Sampling:  Random  Convenience  N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Coleman  
 AHERA Certificate No.: D9953 State License: EPA BIIAD04907-01 State License: EPA  
 Signature: [Signature] Date: 9-07-07 Signature: [Signature] Date: 9-07-07

Asbestos-Containing Material:  No  Yes ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street  
 Scottsdale, AZ 85280  
 (602) 277-7677  
 (602) 277-8288 fax

## **APPENDIX B**

### **Bulk-Material Sample Documents**

- **Chain-of-Custody**
- **Laboratory Analysis**



15974 N. 77<sup>th</sup> Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

# chain of custody

Date: 9/7/07  
 Project No: 07-326  
 Initials: Dore Thompson  
 Page: 1 of 1

Job: Kyrene del Cielo  
 Client: KSD  
 Address: 1350 N Lakeshore dr  
Chandler, AZ 85226

Test: PLM  
 Rush:  Normal:  Extended:   
 Stop at 1st Positive:  UNO  
 Read all samples:   
 Call with results:   
 Fax results:

Cafeteria B1g

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-APL-01	Acoustical Ceiling Panel RA	A-C	S
S-SAT-02	Spray-Applied Texture RA		
M-GWB-03	Gypsum Wallboard		
S-JTC-04	Joint Compound RA		
M-WAB-07	Wallboard		
M-ADH-08	Adhesive		
M-VCT-09	Vinyl Composition Tile		
M-MAS-10	Mastic		
M-CPT-16	Carpet		
M-VCT-18	Vinyl Composition Tile		
M-ACT-21	Acoustical Ceiling Tile RA		
M-VCT-23	Vinyl Composition Tile		
M-VCT-26			
M-VCT-27			
M-GWB-28	Gypsum Wallboard		
S-JTC-29	Joint Compound RA		
M-APL-33	Acoustical Ceiling Panel		
M-GWB-34	Gypsum Wallboard		
S-JTC-35	Joint Compound RA		

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
<u>Dore Thompson</u>	<u>9/17/07</u>	<u>MIKE RICHTER</u>	<u>9/18/07</u>
<u>MIKE RICHTER</u>	<u>9/18/07</u>	<u>TS Townsend</u>	<u>9-18-07</u>



**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708051

**Client:**

**FM GROUP INC**

15974 N 77TH ST

SCOTTSDALE, AZ

85260-0000

Office Phone:

(602) 277-7877

FAX:

(602) 277-8288

**# Samples:** 57 **PLM** **Rec:** 9/18/2007 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

**Client Job:** Kyrene del Cielo / Cafeteria Bldg

**PO Number:** 09-326

**Report Date:** 10/3/2007

**Date Analyzed:** 10/3/2007

**Routing Number:** Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be



representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708051**

Kyrene del Cielo / Cafeteria Bldg

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # <b>M-APL-01A</b> Layer # 1 Tan	2007-08051- 1	Acoustic Tile acoustical tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-01B</b> Layer # 1 Tan	2007-08051- 2	Acoustic Tile acoustical tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-01C</b> Layer # 1 Tan	2007-08051- 3	Acoustic Tile acoustical tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-02A</b> Layer # 1 white	2007-08051- 4	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-02B</b> Layer # 1 white	2007-08051- 5	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-02C</b> Layer # 1 white	2007-08051- 6	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-03A</b> Layer # 1 white	2007-08051- 7	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-03B</b> Layer # 1 white	2007-08051- 8	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-03C</b> Layer # 1 white	2007-08051- 9	Wall System drywall core <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-04A</b> Layer # 1 white	2007-08051- 10	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-04B</b> Layer # 1 white	2007-08051- 11	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-04C</b> Layer # 1 white	2007-08051- 12	Wall System texture/joint compound <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-07A</b> Layer # 1 Blue	2007-08051- 13	Miscellaneous base cove <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-07B</b> Layer # 1 Blue	2007-08051- 14	Miscellaneous base cove <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-07C</b> Layer # 1 Blue	2007-08051- 15	Miscellaneous base cove <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-08A</b> Layer # 1 Tan	2007-08051- 16	Adhesive/caulk mastic <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-08B</b> Layer # 1 Tan	2007-08051- 17	Adhesive/caulk mastic <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-08C</b> Layer # 1 Tan	2007-08051- 18	Adhesive/caulk mastic <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-09A</b> Layer # 1 Tan	2007-08051- 19	Flooring floor tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-09B</b> Layer # 1 Tan	2007-08051- 20	Flooring floor tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-09C</b> Layer # 1 Tan	2007-08051- 21	Flooring floor tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-10A</b> Layer # 1 Tan	2007-08051- 22	Adhesive/caulk mastic <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-10B</b> Layer # 1 Tan	2007-08051- 23	Adhesive/caulk mastic <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-10C</b> Layer # 1 Tan	2007-08051- 24	Adhesive/caulk mastic <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-16A</b> Layer # 1 various	2007-08051- 25	Carpet carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-16B</b> Layer # 1 various	2007-08051- 26	Carpet carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-16C</b> Layer # 1 various	2007-08051- 27	Carpet carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-18A</b> Layer # 1 White	2007-08051- 28	Flooring floor tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-18B</b> Layer # 1 White	2007-08051- 29	Flooring floor tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-18C</b> Layer # 1 White	2007-08051- 30	Flooring floor tile <i>no asbestos detected</i>	Positive Layer? No

Sample # <b>M-ACT-21A</b> Layer # 1 Tan	acoustical tile	2007-08051- 31	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ACT-21B</b> Layer # 1 Tan	acoustical tile	2007-08051- 32	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ACT-21C</b> Layer # 1 Tan	acoustical tile	2007-08051- 33	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-23A</b> Layer # 1 White	floor tile	2007-08051- 34	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-23B</b> Layer # 1 White	floor tile	2007-08051- 35	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-23C</b> Layer # 1 White	floor tile	2007-08051- 36	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-26A</b> Layer # 1 Red	floor tile	2007-08051- 37	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-26B</b> Layer # 1 Green	floor tile	2007-08051- 38	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-26C</b> Layer # 1 Yellow	floor tile	2007-08051- 39	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-27A</b> Layer # 1 Red	floor tile	2007-08051- 40	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-27B</b> Layer # 1 Blue	floor tile	2007-08051- 41	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-27C</b> Layer # 1 Black	floor tile	2007-08051- 42	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-28A</b> Layer # 1 white	drywall core	2007-08051- 43	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-28B</b> Layer # 1 white	drywall core	2007-08051- 44	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-28C</b> Layer # 1 white	drywall core	2007-08051- 45	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-29A</b> Layer # 1 white	texture/joint compound	2007-08051- 46	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-29B</b> Layer # 1 white	texture/joint compound	2007-08051- 47	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-29C</b> Layer # 1 white	texture/joint compound	2007-08051- 48	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-33A</b> Layer # 1 White	drywall core	2007-08051- 49	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-33B</b> Layer # 1 White	drywall core	2007-08051- 50	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-33C</b> Layer # 1 White	drywall core	2007-08051- 51	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-34A</b> Layer # 1 white	drywall core	2007-08051- 52	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-34B</b> Layer # 1 white	drywall core	2007-08051- 53	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-34C</b> Layer # 1 white	drywall core	2007-08051- 54	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-35A</b> Layer # 1 white	texture/joint compound	2007-08051- 55	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-35B</b> Layer # 1 white	texture/joint compound	2007-08051- 56	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-35C</b> Layer # 1 white	texture/joint compound	2007-08051- 57	Wall System <i>no asbestos detected</i>	Positive Layer? No

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number:** 200708051 Kyrene del Cielo / Cafeteria Bldg

**Sample** M-APL-01A **Lab Number** 2007-08051- 1 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/2/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	>1-2%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	>1-2%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-01B **Lab Number** 2007-08051- 2 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/2/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	>1-2%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	>1-2%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-APL-01C **Lab Number** 2007-08051- 3 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/2/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	>1-2%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	>1-2%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** S-SAT-02A **Lab Number** 2007-08051- 4 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-02B **Lab Number** 2007-08051- 5 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-02C **Lab Number** 2007-08051- 6 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-GWB-03A **Lab Number** 2007-08051- 7 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	<=1%	-	-	-	-
<b>Fiber Identification:</b>					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-03B **Lab Number** 2007-08051- 8 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	<=1%	-	-	-	-
<b>Fiber Identification:</b>					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-03C **Lab Number** 2007-08051- 9 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	<=1%	-	-	-	-
<b>Fiber Identification:</b>					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** S-JTC-04A **Lab Number** 2007-08051- 10 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-04B **Lab Number** 2007-08051- 11 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-04C **Lab Number** 2007-08051- 12 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-WAB-07A **Lab Number** 2007-08051- 13 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, debris,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Blue	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-07B **Lab Number** 2007-08051- 14 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, debris,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Blue	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-07C **Lab Number** 2007-08051- 15 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, debris,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Blue	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-ADH-08A **Lab Number** 2007-08051- 16 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-08B **Lab Number** 2007-08051- 17 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-08C **Lab Number** 2007-08051- 18 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-VCT-09A **Lab Number** 2007-08051- 19 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-09B **Lab Number** 2007-08051- 20 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-09C **Lab Number** 2007-08051- 21 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number:** 200708051 Kyrene del Cielo / Cafeteria Bldg

**Sample** M-MAS-10A **Lab Number** 2007-08051- 22 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-10B **Lab Number** 2007-08051- 23 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-MAS-10C **Lab Number** 2007-08051- 24 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number:** 200708051 Kyrene del Cielo / Cafeteria Bldg

**Sample** M-CPT-16A **Lab Number** 2007-08051- 25 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		40-50%	-	-	-	-	-

**Fiber Identification:** synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-CPT-16B **Lab Number** 2007-08051- 26 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		40-50%	-	-	-	-	-

**Fiber Identification:** synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-CPT-16C **Lab Number** 2007-08051- 27 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** polymer foam, filler, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		40-50%	-	-	-	-	-

**Fiber Identification:** synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-VCT-18A **Lab Number** 2007-08051- 28 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	White	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-18B **Lab Number** 2007-08051- 29 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	White	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-18C **Lab Number** 2007-08051- 30 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	White	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-ACT-21A **Lab Number** 2007-08051- 31 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	>1-2%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	>1-2%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-ACT-21B **Lab Number** 2007-08051- 32 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	>1-2%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	>1-2%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**Sample** M-ACT-21C **Lab Number** 2007-08051- 33 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	50-60%	>1-2%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		50-60%	>1-2%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-VCT-23A **Lab Number** 2007-08051- 34 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	White	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-23B **Lab Number** 2007-08051- 35 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	White	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-23C **Lab Number** 2007-08051- 36 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	White	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-VCT-26A **Lab Number** 2007-08051- 37 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Red	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-26B **Lab Number** 2007-08051- 38 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Green	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-26C **Lab Number** 2007-08051- 39 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Yellow	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-VCT-27A **Lab Number** 2007-08051- 40 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Red	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-27B **Lab Number** 2007-08051- 41 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Blue	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-VCT-27C **Lab Number** 2007-08051- 42 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Black	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-GWB-28A **Lab Number** 2007-08051- 43 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	<=1%	-	-	-	-
<b>Fiber Identification:</b>					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-28B **Lab Number** 2007-08051- 44 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	<=1%	-	-	-	-
<b>Fiber Identification:</b>					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-28C **Lab Number** 2007-08051- 45 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	<=1%	-	-	-	-
<b>Fiber Identification:</b>					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** S-JTC-29A **Lab Number** 2007-08051- 46 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-29B **Lab Number** 2007-08051- 47 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-29C **Lab Number** 2007-08051- 48 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-APL-33A **Lab Number** 2007-08051- 49 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	White	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>
<b>Fiber Identification:</b>					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-APL-33B **Lab Number** 2007-08051- 50 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, mlca/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	White	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>
<b>Fiber Identification:</b>					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-APL-33C **Lab Number** 2007-08051- 51 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	White	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<b>&lt;=1%</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>
<b>Fiber Identification:</b>					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** M-GWB-34A **Lab Number** 2007-08051- 52 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-34B **Lab Number** 2007-08051- 53 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**Sample** M-GWB-34C **Lab Number** 2007-08051- 54 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708051** Kyrene del Cielo / Cafeteria Bldg

**Sample** S-JTC-35A **Lab Number** 2007-08051- 55 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-35B **Lab Number** 2007-08051- 56 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.


**Sample** S-JTC-35C **Lab Number** 2007-08051- 57 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** MAC 10/3/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable  
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various  
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;  
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper  
 Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High  
 Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining  
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow;  
 vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.  
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 03-Oct-07

Original Print Date: 03-Oct-07



Larry S. Pierce, Approved Accreditation Signatory



15974 N. 77<sup>th</sup> Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

# chain of custody

Date: 9/7/07  
 Project No: 07-326  
 Initials: Dave Thompson  
 Page: 1 of 2

Job: Excess del. Cielo  
 Client: KSD  
 Address: 1350 N Lakeshore dr  
Chandler, AZ 85226

Test: PLM  
 Rush:  Normal:  Extended:   
 Stop at 1st Positive:  Y N O  
 Read all samples:   
 Call with results:   
 Fax results:

Main Btg

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-APL-01	Acoustical Ceiling Panel RA	A-C	S
M-GWB-02	Gypsum Wallboard		
S-JTC-03	Joint Compound RA		
M-WAB-04	Wallboard		
M-ADH-05	Adhesive		
M-CDT-06	Capat		
M-MAS-07	Mastic		
S-SAT-09	Spray-Applied Texture RA		
M-GWB-10	Gypsum Wallboard		
S-JTC-11	Joint Compound RA		
S-SAT-18	Spray-Applied Texture RA		
M-GWB-19	Gypsum Wallboard		
S-JTC-20	Joint Compound RA		
M-VCT-25	Vinyl Composition Tile		
S-SAT-30	Spray-Applied Texture RA		
S-TOT-31	Trowled-on Texture RA		
M-GWB-32	Gypsum Wallboard		
S-JTC-33	Joint Compound RA		
M-WAB-35	Wallboard		
M-ADH-36	Adhesive		
S-SAT-42	Spray-Applied Texture RA		
M-GWB-43	Gypsum Wallboard		

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
<u>Dave Thompson</u>	<u>9/12/07</u>	<u>MIKE RICHTER</u>	<u>9/18/07</u>
<u>MIKE RICHTER</u>	<u>9/18/07</u>	<u>K Townsend</u>	<u>9-18-07</u>



15974 N. 77<sup>th</sup> Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

# chain of custody

Date: 9/7/07  
 Project No: 07-326  
 Initials: Dave Thompson  
 Page: 2 of 2

Job: Kyrene del Cielo  
 Client: KSD  
 Address: 1350 N Lakeshore dr  
Chandler, AZ 85226

Test: PM  
 Rush: \_\_\_ Normal: \_\_\_ Extended: X  
 Stop at 1st Positive: X UND  
 Read all samples: \_\_\_  
 Call with results: \_\_\_  
 Fax results: \_\_\_

Main Btg cont.

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
S-JTC-44	Joint Compound RA	A-C	S
M-WAB-48	Wallbase	I	I
M-ADH-49	Adhesive	I	I

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
<u>Dave Thompson</u>	<u>9/17/07</u>	<u>MIKE RICHTER</u>	<u>9/18/07</u>
<u>MIKE RICHTER</u>	<u>9/18/07</u>	<u>T. Lowerson</u>	<u>9-18-07</u>





**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708050

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

**# Samples:** 75 PLM **Rec:** 9/18/2007 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp  
**Client Job:** Kyrene del Cielo / Main Bldg **PO Number:** 07-326  
**Report Date:** 10/2/2007 **Date Analyzed:** 10/2/2007 **Routing Number:** Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708050**

Kyrene del Cielo / Main Bldg

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # <b>M-APL-01A</b> Layer # 1 Off-white	2007-08050- 1	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-01B</b> Layer # 1 Off-white	2007-08050- 2	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-APL-01C</b> Layer # 1 Off-white	2007-08050- 3	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-02A</b> Layer # 1 white	2007-08050- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-02B</b> Layer # 1 white	2007-08050- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-02C</b> Layer # 1 white	2007-08050- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-03A</b> Layer # 1 white	2007-08050- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-03B</b> Layer # 1 white	2007-08050- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-03C</b> Layer # 1 white	2007-08050- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-04A</b> Layer # 1 Gray	2007-08050- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-04B</b> Layer # 1 Gray	2007-08050- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-04C</b> Layer # 1 Gray	2007-08050- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-05A</b> Layer # 1 Off-white	2007-08050- 13	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-05B</b> Layer # 1 Off-white	2007-08050- 14	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-05C</b> Layer # 1 Off-white	2007-08050- 15	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-06A</b> Layer # 1 Various	2007-08050- 16	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-06B</b> Layer # 1 Various	2007-08050- 17	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-CPT-06C</b> Layer # 1 Various	2007-08050- 18	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-07A</b> Layer # 1 tan	2007-08050- 19	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-07B</b> Layer # 1 tan	2007-08050- 20	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-MAS-07C</b> Layer # 1 tan	2007-08050- 21	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-09A</b> Layer # 1 white	2007-08050- 22	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-09B</b> Layer # 1 white	2007-08050- 23	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-09C</b> Layer # 1 white	2007-08050- 24	Sprayed Material <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-10A</b> Layer # 1 white	2007-08050- 25	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-10B</b> Layer # 1 white	2007-08050- 26	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-10C</b> Layer # 1 white	2007-08050- 27	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-11A</b> Layer # 1 white	2007-08050- 28	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-11B</b> Layer # 1 white	2007-08050- 29	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-11C</b> Layer # 1 white	2007-08050- 30	Wall System <i>no asbestos detected</i>	Positive Layer? No

Sample # <b>S-SAT-18A</b> Layer # 1 white	2007-08050- 31	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-18B</b> Layer # 1 white	2007-08050- 32	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-18C</b> Layer # 1 white	2007-08050- 33	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-19A</b> Layer # 1 white	2007-08050- 34	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-19B</b> Layer # 1 white	2007-08050- 35	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-19C</b> Layer # 1 white	2007-08050- 36	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-20A</b> Layer # 1 white	2007-08050- 37	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-20B</b> Layer # 1 white	2007-08050- 38	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-20C</b> Layer # 1 white	2007-08050- 39	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-25A</b> Layer # 1 Tan	2007-08050- 40	Flooring floor tile	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-25B</b> Layer # 1 Tan	2007-08050- 41	Flooring floor tile	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-VCT-25C</b> Layer # 1 Tan	2007-08050- 42	Flooring floor tile	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-30A</b> Layer # 1 white	2007-08050- 43	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-30B</b> Layer # 1 white	2007-08050- 44	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-30C</b> Layer # 1 white	2007-08050- 45	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-TOT-31A</b> Layer # 1 white	2007-08050- 46	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-TOT-31B</b> Layer # 1 white	2007-08050- 47	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-TOT-31C</b> Layer # 1 white	2007-08050- 48	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-32A</b> Layer # 1 white	2007-08050- 49	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-32B</b> Layer # 1 white	2007-08050- 50	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-32C</b> Layer # 1 white	2007-08050- 51	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-33A</b> Layer # 1 white	2007-08050- 52	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-33B</b> Layer # 1 white	2007-08050- 53	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-33C</b> Layer # 1 white	2007-08050- 54	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-35A</b> Layer # 1 Blue	2007-08050- 55	Wall System base cove	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-35B</b> Layer # 1 Blue	2007-08050- 56	Wall System base cove	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-WAB-35C</b> Layer # 1 Blue	2007-08050- 57	Wall System base cove	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-36A</b> Layer # 1 Off-white	2007-08050- 58	Adhesive/caulk mastic	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-36B</b> Layer # 1 Off-white	2007-08050- 59	Adhesive/caulk mastic	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-ADH-36C</b> Layer # 1 Off-white	2007-08050- 60	Adhesive/caulk mastic	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-42A</b> Layer # 1 white	2007-08050- 61	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-42B</b> Layer # 1 white	2007-08050- 62	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-SAT-42C</b> Layer # 1 white	2007-08050- 63	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-43A</b> Layer # 1 white	2007-08050- 64	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-43B</b> Layer # 1 white	2007-08050- 65	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>M-GWB-43C</b> Layer # 1 white	2007-08050- 66	Wall System drywall core	<i>no asbestos detected</i>	Positive Layer? No
Sample # <b>S-JTC-44A</b> Layer # 1 white	2007-08050- 67	Wall System texture/joint compound	<i>no asbestos detected</i>	Positive Layer? No

Sample #	<b>S-JTC-44B</b>		2007-08050- 68	Wall System		Positive Layer? No
Layer # 1	white	texture/joint compound		<i>no asbestos detected</i>		
Sample #	<b>S-JTC-44C</b>		2007-08050- 69	Wall System		Positive Layer? No
Layer # 1	white	texture/joint compound		<i>no asbestos detected</i>		
Sample #	<b>M-WAB-48A</b>		2007-08050- 70	Wall System		Positive Layer? No
Layer # 1	Brown	base cove		<i>no asbestos detected</i>		
Sample #	<b>M-WAB-48B</b>		2007-08050- 71	Wall System		Positive Layer? No
Layer # 1	Brown	base cove		<i>no asbestos detected</i>		
Sample #	<b>M-WAB-48C</b>		2007-08050- 72	Wall System		Positive Layer? No
Layer # 1	Brown	base cove		<i>no asbestos detected</i>		
Sample #	<b>M-ADH-49A</b>		2007-08050- 73	Adhesive/caulk		Positive Layer? No
Layer # 1	tan	mastic		<i>no asbestos detected</i>		
Sample #	<b>M-ADH-49B</b>		2007-08050- 74	Adhesive/caulk		Positive Layer? No
Layer # 1	tan	mastic		<i>no asbestos detected</i>		
Sample #	<b>M-ADH-49C</b>		2007-08050- 75	Adhesive/caulk		Positive Layer? No
Layer # 1	tan	mastic		<i>no asbestos detected</i>		

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** M-APL-01A **Lab Number** 2007-08050- 1 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		40-50%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-APL-01B **Lab Number** 2007-08050- 2 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		40-50%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-APL-01C **Lab Number** 2007-08050- 3 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** perlite, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		40-50%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050 Kyrene del Cielo / Main Bldg

Sample M-GWB-02A Lab Number 2007-08050- 4 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweazed apart using forceps.

Sample M-GWB-02B Lab Number 2007-08050- 5 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweazed apart using forceps.

Sample M-GWB-02C Lab Number 2007-08050- 6 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations					
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweazed apart using forceps.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** S-JTC-03A **Lab Number** 2007-08050- 7 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-03B **Lab Number** 2007-08050- 8 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-03C **Lab Number** 2007-08050- 9 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** M-WAB-04A **Lab Number** 2007-08050- 10 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-04B **Lab Number** 2007-08050- 11 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-04C **Lab Number** 2007-08050- 12 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



PLM Analysis Details

Job Number: 200708050 Kyrene del Cielo / Main Bldg

Sample M-ADH-05A Lab Number 2007-08050- 13 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-05B Lab Number 2007-08050- 14 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-05C Lab Number 2007-08050- 15 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample M-CPT-06A Lab Number 2007-08050- 16 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Carpet Fibrous Mat  
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): polymer foam, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	Various	1	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-CPT-06B Lab Number 2007-08050- 17 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Carpet Fibrous Mat  
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): polymer foam, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	Various	1	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-CPT-06C Lab Number 2007-08050- 18 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Carpet Fibrous Mat  
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): polymer foam, binder, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	Various	1	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	synthetic fiber (extruded)	W	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample M-MAS-07A Lab Number 2007-08050- 19 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	>1-2%	-	-	-	-	-
Total %		100	Average %		>1-2%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-07B Lab Number 2007-08050- 20 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	>1-2%	-	-	-	-	-
Total %		100	Average %		>1-2%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-07C Lab Number 2007-08050- 21 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Adhesive/caulk Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	>1-2%	-	-	-	-	-
Total %		100	Average %		>1-2%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample S-SAT-09A Lab Number 2007-08050- 22 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Sprayed Material Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-09B Lab Number 2007-08050- 23 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Sprayed Material Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-09C Lab Number 2007-08050- 24 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Sprayed Material Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	spray-on ceiling	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample M-GWB-10A Lab Number 2007-08050- 25 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-10B Lab Number 2007-08050- 26 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-10C Lab Number 2007-08050- 27 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample S-JTC-11A Lab Number 2007-08050- 28 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-11B Lab Number 2007-08050- 29 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-11C Lab Number 2007-08050- 30 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** S-SAT-18A **Lab Number** 2007-08050- 31 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-18B **Lab Number** 2007-08050- 32 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-SAT-18C **Lab Number** 2007-08050- 33 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample M-GWB-19A Lab Number 2007-08050- 34 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-19B Lab Number 2007-08050- 35 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-19C Lab Number 2007-08050- 36 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.



**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** S-JTC-20A **Lab Number** 2007-08050- 37 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations									
1	2	3	4	5	6	Oil	Col Par	Col Per	RI Par	RI Per								
1	none																	
2																		
3																		
4																		
5																		
6																		

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-20B **Lab Number** 2007-08050- 38 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations									
1	2	3	4	5	6	Oil	Col Par	Col Per	RI Par	RI Per								
1	none																	
2																		
3																		
4																		
5																		
6																		

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-20C **Lab Number** 2007-08050- 39 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations									
1	2	3	4	5	6	Oil	Col Par	Col Per	RI Par	RI Per								
1	none																	
2																		
3																		
4																		
5																		
6																		

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050 Kyrene del Cielo / Main Bldg

Sample M-VCT-25A Lab Number 2007-08050- 40 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Flooring Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-25B Lab Number 2007-08050- 41 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Flooring Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-25C Lab Number 2007-08050- 42 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Flooring Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample S-SAT-30A Lab Number 2007-08050- 43 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-30B Lab Number 2007-08050- 44 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-30C Lab Number 2007-08050- 45 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** S-TOT-31A **Lab Number** 2007-08050- 46 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-TOT-31B **Lab Number** 2007-08050- 47 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-TOT-31C **Lab Number** 2007-08050- 48 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050 Kyrene del Cielo / Main Bldg

Sample M-GWB-32A Lab Number 2007-08050- 49 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-32B Lab Number 2007-08050- 50 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-32C Lab Number 2007-08050- 51 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** S-JTC-33A **Lab Number** 2007-08050- 52 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-33B **Lab Number** 2007-08050- 53 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-33C **Lab Number** 2007-08050- 54 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b> none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050

Kyrene del Cielo / Main Bldg

Sample M-WAB-35A Lab Number 2007-08050- 55 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Blue	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-35B Lab Number 2007-08050- 56 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Blue	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-35C Lab Number 2007-08050- 57 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cove	100	Blue	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** M-ADH-36A **Lab Number** 2007-08050- 58 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-36B **Lab Number** 2007-08050- 59 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	<=1%	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		<=1%	-	-	-	-	-
<b>Fiber Identification:</b>					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-36C **Lab Number** 2007-08050- 60 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.



PLM Analysis Details

Job Number: 200708050 Kyrene del Cielo / Main Bldg

Sample S-SAT-42A Lab Number 2007-08050- 61 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-42B Lab Number 2007-08050- 62 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-42C Lab Number 2007-08050- 63 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708050 Kyrene del Cielo / Main Bldg

Sample M-GWB-43A Lab Number 2007-08050- 64 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-43B Lab Number 2007-08050- 65 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

Sample M-GWB-43C Lab Number 2007-08050- 66 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/2/2007 An? OK Apparent Smp Type Wall System Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** S-JTC-44A **Lab Number** 2007-08050- 67 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-44B **Lab Number** 2007-08050- 68 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** S-JTC-44C **Lab Number** 2007-08050- 69 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** M-WAB-48A **Lab Number** 2007-08050- 70 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Brown	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-48B **Lab Number** 2007-08050- 71 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Brown	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-WAB-48C **Lab Number** 2007-08050- 72 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Brown	1	n.d.	-	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**PLM Analysis Details**

**Job Number: 200708050** Kyrene del Cielo / Main Bldg

**Sample** M-ADH-49A **Lab Number** 2007-08050- 73 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-49B **Lab Number** 2007-08050- 74 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

**Sample** M-ADH-49C **Lab Number** 2007-08050- 75 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/2/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	tan	1	n.d.	-	-	-	-	-
<b>Total %</b>		100	<b>Average %</b>		n.d.	-	-	-	-	-
<b>Fiber Identification:</b>					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, slenwy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 02-Oct-07

Original Print Date: 02-Oct-07



Larry S. Pierce, Approved Accreditation Signatory



15974 N. 77<sup>th</sup> Street  
 Scottsdale, AZ 85260  
 (602) 277-7877  
 (602) 277-8288 fax

# chain of custody

Date: 9/7/07  
 Project No: 07-326  
 Initials: Dave Thompson  
 Page: 1 of 1

Job: Quinta del Cielo  
 Client: ISSI  
 Address: 1350 N Lakeshore dr  
Chandler, AZ 85226

Test: PLM  
 Rush:  Normal:  Extended:   
 Stop at 1st Positive:   
 Read all samples:   
 Call with results:   
 Fax results:

DI/02

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-ACT-01	Acoustical Ceiling Tile	A-C	S

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
Dave Thompson	9/7/07	Mike Richter	9/18/07
Mike Richter	9/18/07	K. Townsend	9-18-07



**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708052

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

# Samples: 3 PLM Rec: 9/18/2007 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene del Cielo ; D1/D2

PO Number: 07-326

Report Date: 10/3/2007

Date Analyzed: 10/3/2007

Routing Number: Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be



representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.  
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708052** Kyrene del Cielo ; D1/D2

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	<b>M-ACT-01A</b>	2007-08052- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01B</b>	2007-08052- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01C</b>	2007-08052- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number: 200708052** Kyrene del Cielo ; D1/D2

**Sample** M-ACT-01A **Lab Number** 2007-08052- 1 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01B **Lab Number** 2007-08052- 2 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01C **Lab Number** 2007-08052- 3 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, slnewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. MCCORMICK

Printed: 03-Oct-07

Original Print Date: 03-Oct-07



Larry S. Pierce, Approved Accreditation Signatory



15974 N. 77<sup>th</sup> Street  
Scottsdale, AZ 85260  
(602) 277-7877  
(602) 277-8288 fax

# chain of custody

Date: 9/7/07  
Project No: 07-326  
Initials: Dave Thompson  
Page: 1 of 1

Job: Kyrene del Cielo  
Client: KSD  
Address: 1350 W Lakeshore dr  
Chandler, AZ 85226

Test: PLM  
Rush:      Normal:      Extended: X  
Stop at 1st Positive:       
Read all samples: X  
Call with results:       
Fax results:     

M1/M2

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-ACT-01	Acoustical Ceiling Tile	A-C	S

\*\*Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
<u>Dave Thompson</u>	<u>9/17/07</u>	<u>Mike Richter</u>	<u>9/18/07</u>
<u>Mike Richter</u>	<u>9/18/07</u>	<u>X Townsend</u>	<u>9.18.07</u>



**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708053

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

# Samples: 3 PLM Rec: 9/18/2007 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene del Cielo ; M1/M2

PO Number: 07-326

Report Date: 10/3/2007

Date Analyzed: 10/3/2007

Routing Number: Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "T" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in Interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708053** Kyrene del Cielo ; M1/M2

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	<b>M-ACT-01A</b>	2007-08053- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01B</b>	2007-08053- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01C</b>	2007-08053- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number:** 200708053 Kyrene del Cielo ; M1/M2

**Sample** M-ACT-01A **Lab Number** 2007-08053- 1 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01B **Lab Number** 2007-08053- 2 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01C **Lab Number** 2007-08053- 3 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable


Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=plnk;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber. RI Par=refractive index parallel to fiber; RI Perp=refractive Index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 03-Oct-07

Original Print Date: 03-Oct-07



Larry S. Pierce, Approved Accreditation Signatory







**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708054

**Client:** FM GROUP INC  
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000  
Office Phone: (602) 277-7877  
FAX: (602) 277-8288

# Samples: 3 PLM Rec: 9/18/2007 Method: EPA 600/R-93/116 PLM analysis for asbestos in bulk smp  
Client Job: Kyrene del Cielo ; M3/M4 PO Number: 07-326  
Report Date: 10/3/2007 Date Analyzed: 10/3/2007 Routing Number: Thompson, Dane

**Method and Analysis Information: Fiberquant Internal SOP: PLMn**

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708054** Kyrene del Cielo ; M3/M4

Sample Number		Apparent Layer Type *	Lab Number	Apparent Sample Type *	Asbestos Results	Positive Layer Yes or No
Layer	Color					
Sample #	<b>M-ACT-01A</b>					
Layer # 1	Off-white	acoustical tile	2007-08054- 1	Acoustic Tile	<i>no asbestos detected</i>	Positive Layer? No
Sample #	<b>M-ACT-01B</b>					
Layer # 1	Off-white	acoustical tile	2007-08054- 2	Acoustic Tile	<i>no asbestos detected</i>	Positive Layer? No
Sample #	<b>M-ACT-01C</b>					
Layer # 1	Off-white	acoustical tile	2007-08054- 3	Acoustic Tile	<i>no asbestos detected</i>	Positive Layer? No

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number: 200708054** Kyrene del Cielo ; M3/M4

**Sample** M-ACT-01A **Lab Number** 2007-08054- 1 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01B **Lab Number** 2007-08054- 2 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.


**Sample** M-ACT-01C **Lab Number** 2007-08054- 3 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**  
**Homogeneous** Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable  
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various  
 Fiber Morphology: A=fine fibers/bundles, white, slenwy, flexible; B=fine fibers/bundles, w-br, stralght, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;  
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper  
 Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bf=birefringence - may be None, Low, Medium or High  
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining  
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.  
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 03-Oct-07

Original Print Date: 03-Oct-07



Larry S. Pierce, Approved Accreditation Signatory





**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708055

**Client:** FM GROUP INC  
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000  
Office Phone: (602) 277-7877  
FAX: (602) 277-8288

# Samples: 3 PLM Rec: 9/18/2007 Method: EPA 600/R-93/116 PLM analysis for asbestos in bulk smp  
Client Job: Kyrene del Cleo ; R1/R2 PO Number: 07-326  
Report Date: 10/3/2007 Date Analyzed: 10/3/2007 Routing Number: Thompson, Dane

**Method and Analysis Information: Fiberquant Internal SOP: PLMn**

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708055** Kyrene del Cielo ; R1/R2

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	<b>M-ACT-01A</b>	2007-08055- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01B</b>	2007-08055- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01C</b>	2007-08055- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.



PLM Analysis Details

Job Number: 200708055 Kyrene del Cielo ; R1/R2

Sample M-ACT-01A Lab Number 2007-08055- 1 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/3/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
Total %		100	Average %		60-70%	5-10%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01B Lab Number 2007-08055- 2 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/3/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
Total %		100	Average %		60-70%	5-10%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01C Lab Number 2007-08055- 3 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By RAM 10/3/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Mat  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
Total %		100	Average %		60-70%	5-10%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 03-Oct-07

Original Print Date: 03-Oct-07



Larry S. Pierce, Approved Accreditation Signatory





**Polarized Light Microscope (PLM) Analysis for Asbestos**

**Job Number:** 200708056

**Client:** FM GROUP INC  
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000  
Office Phone: (602) 277-7877  
FAX: (602) 277-8288

**# Samples:** 3 PLM **Rec:** 9/18/2007 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp  
**Client Job:** Kyrene del Cielo ; R3/R4 **PO Number:** 07-326  
**Report Date:** 10/3/2007 **Date Analyzed:** 10/3/2007 **Routing Number:** Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708056**

Kyrene del Cielo ; R3/R4

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	<b>M-ACT-01A</b>	2007-08056- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01B</b>	2007-08056- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01C</b>	2007-08056- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number: 200708056**

Kyrene del Cielo ; R3/R4

**Sample** M-ACT-01A      **Lab Number** 2007-08056- 1      **Sampled:** 9/7/2007      **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007      **An?** OK      **Apparent Smp Type** Acoustic Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01B      **Lab Number** 2007-08056- 2      **Sampled:** 9/7/2007      **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007      **An?** OK      **Apparent Smp Type** Acoustic Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01C      **Lab Number** 2007-08056- 3      **Sampled:** 9/7/2007      **Condition:** acceptable  
**Analyzed By** RAM 10/3/2007      **An?** OK      **Apparent Smp Type** Acoustic Tile      **Fibrous Mat**  
**Homogeneous** Yes      **# Layers** 1      **Pos Layer?** No      **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** glass, perlite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	5-10%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	5-10%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: ROBERT A. McCORMICK

Printed: 03-Oct-07

Original Print Date: 03-Oct-07

Larry S. Pierce, Approved Accreditation Signatory







**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708057

**Client:** FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

# Samples: 3 PLM Rec: 9/18/2007 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene del Cielo ; T1/T2

PO Number: 07-326

Report Date: 10/3/2007

Date Analyzed: 10/3/2007

Routing Number: Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

5025 S. 33rd Street Phoenix, Arizona 85040-2816 Phone: 602-276-6139 1-800-743-2687 FAX: 602-276-4558

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708057** Kyrene del Cielo ; T1/T2

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	<b>M-ACT-01A</b>	2007-08057- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01B</b>	2007-08057- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01C</b>	2007-08057- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200708057

Kyrene del Cielo ; T1/T2

Sample M-ACT-01A Lab Number 2007-08057- 1 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By DMS 10/3/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	2-5%	-	-	-	-
Total %		100	Average %		60-70%	2-5%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01B Lab Number 2007-08057- 2 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By DMS 10/3/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	2-5%	-	-	-	-
Total %		100	Average %		60-70%	2-5%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01C Lab Number 2007-08057- 3 Sampled: 9/7/2007 Condition: acceptable  
 Analyzed By DMS 10/3/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid  
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3  
 Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	2-5%	-	-	-	-
Total %		100	Average %		60-70%	2-5%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: DAVID M. SCHALLER

Printed: 03-Oct-07

Original Print Date: 03-Oct-07

Larry S. Pierce, Approved Accreditation Signatory





**Polarized Light Microscope (PLM) Analysis for Asbestos**

**JobNumber:** 200708058

**Client:** FM GROUP INC  
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000  
Office Phone: (602) 277-7877  
FAX: (602) 277-8288

**# Samples:** 3 PLM **Rec:** 9/18/2007 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp  
**Client Job:** Kyrene del Clelo ; T3/T4 **PO Number:** 07-326  
**Report Date:** 10/3/2007 **Date Analyzed:** 10/3/2007 **Routing Number:** Thompson, Dane

**Method and Analysis Information:** Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of  $\leq 1\%$  asbestos as "negative" and  $> 1\%$  asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain  $\leq 1\%$  asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are  $\leq 1\%$ . The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but  $\leq 1\%$  as "borderline negative", and results where asbestos was  $> 1\%$  but  $\leq 2\%$  as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as  $\leq 1\%$ . The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in Interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

**Job Analysis Notes:**

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

**PLM Analysis Summary:**

**Job Number: 200708058**

Kyrene del Cielo ; T3/T4

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	<b>M-ACT-01A</b>	2007-08058- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01B</b>	2007-08058- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	<b>M-ACT-01C</b>	2007-08058- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

\* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

**PLM Analysis Details**

**Job Number: 200708058** Kyrene del Cielo ; T3/T4

**Sample** M-ACT-01A **Lab Number** 2007-08058- 1 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** DMS 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01B **Lab Number** 2007-08058- 2 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** DMS 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

**Sample** M-ACT-01C **Lab Number** 2007-08058- 3 **Sampled:** 9/7/2007 **Condition:** acceptable  
**Analyzed By** DMS 10/3/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**  
**Homogeneous** No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3  
**Non-Fibrous Components (in approx. decreasing order):** filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	60-70%	2-5%	-	-	-	-
<b>Total %</b>		<b>100</b>	<b>Average %</b>		60-70%	2-5%	-	-	-	-
<b>Fiber Identification:</b>					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

**Sample Analytical Note**  
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.



Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various


Fiber Morphology: A=fine fibers/bundles, white, slenwy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.


RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: DAVID M. SCHALLER

Printed: 03-Oct-07

Original Print Date: 03-Oct-07



Larry S. Pierce, Approved Accreditation Signatory

## **APPENDIX C**

### **Building Inspectors' Signature Sheet**

BUILDING INSPECTOR'S SIGNATURE SHEET

**Report of Findings**  
Comprehensive AHERA Asbestos Inspection  
Kyrene Del Cielo Elementary School  
Kyrene School District No. 28

FM Project 07-326

The individual(s) whose signature(s) is/are shown below is/are EPA Accredited Building Inspector(s) who participated in one or more of the following activities:

- A. Visual Inspection of Facilities
- B. Identification of Homogenous Areas of Asbestos-Containing Materials
- C. Development of Sampling Plan and Protocols
- D. Bulk Sampling Activities/Material Identifications
- E. Assessing ACBM/ACM
- F. Preparing Report of Findings

<u>INSPECTOR</u>	<u>ACTIVITIES</u>	<u>DATES</u>
Paul Anger Printed Name D 9200 Accreditation No. Signature	PA Initials EPA State	F 10/5/07
Michael Coleman Printed Name BIIA040907-01 Accreditation No. Signature	mc Initials EPA State	A, B, D, E 9/4/07 – 9/14/07
Cliff Rolle Printed Name D 10203 Accreditation No. Signature	CR Initials EPA State	A, B, C, D, E, F 9/4/07 – 10/5/07
Dane Thompson Printed Name D 9953 Accreditation No. Signature	DT Initials EPA State	A, B, C, E 9/4/07 – 9/14/07

## **APPENDIX D**

### **Personnel and Laboratory Accreditations**

# THE ASBESTOS INSTITUTE

Certifies that


has attended the EPA approved course

**Paul Anger**  
AHERA Refresher  
Building Inspector

January 5, 2007  
and successfully passed the competency exam

Date of Examination: ~~January 5, 2007~~

Date of Expiration: ~~January 5, 2008~~



Director

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

# Certificate Of Training

In recognition of attendance and passing of exam

**MICHAEL B. COLEMAN**  
**4855**

The above person has completed the requisite training course for asbestos accreditation under TSCA Title II,  
Asbestos Model Accreditation Plan and the provider is accredited to provide training within the

**State of Hawaii. #T-0108**


And/or as listed below

*Building Inspector Initial*

Completed this 9<sup>th</sup> Day of April, 2007 Expires 8<sup>th</sup> Day of April, 2008

**NEIIC**


National Environmental Institute & Consulting  
Surprise, Arizona--Honolulu, Hawaii



Training Director-

Certificate # BIIA040907-01

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

and successfully passed the competency exam.

*[Signature]*  
Director

Director

Approved Instructor.

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHJERA Refresher  
Building Inspector**

**May 4, 2007**

and successfully passed the competency exam

Date of Examination: **May 4, 2007**

Date of Expiration: **May 4, 2008**

*[Signature]*  
 Director

*[Signature]*  
 Approved Instructor

**THE ASBESTOS INSTITUTE**

8102 North 23rd Avenue


Suite A

Phoenix, AZ 85021-4962

602-864-6564



United States Department of Commerce  
National Institute of Standards and Technology



---

## Certificate of Accreditation to ISO/IEC 17025:1999

---

NVLAP LAB CODE: 101031-0


**Fiberquant, Inc.**  
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in  
NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.  
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

**BULK ASBESTOS FIBER ANALYSIS**

2007-07-01 through 2008-06-30

Effective dates



*Jolly A. Bruce*  
For the National Institute of Standards and Technology

## **1.0 SURVEY RESULTS AND RECOMMENDATIONS**

### **1.1 Summary**

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the nine buildings comprising the Kyrene Del Cielo Elementary School (KDCES) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period September 4, 2007 through September 7, 2007. A total of 153 bulk-material samples were collected from 315 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency's (EPA), AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Two hundred sixty-four building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

### **1.2 Identified Asbestos Containing Building Material**

The identified ACBM within the nine buildings at KDCES are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

### **1.3 Asbestos-Containing Building Materials**

(Table "C" has been moved to Section 6 of the Management Plan.)

### **1.4 ACBM/Location Plans**

(Drawings have been moved to Section 6 of the Management Plan.)

### **1.5 Critical Situations**

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the nine buildings at KDCES during this inspection.**

## **1.6 Friable Asbestos-Containing Building Materials**

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the nine buildings at KDCES during this inspection.**

## **1.7 Material Assessments**

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** was identified in the nine buildings at KDCES, **NO** formal assessments are included in this report.

## **1.8 Recommendations**

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

## **1.9 Qualifications of Report**

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

## **2.0 PROJECT INFORMATION**

### **2.1 Background**

KSD intends to determine if there are any ACBM associated with the nine buildings at the KDCES campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the nine buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM Proposal P6-349, dated June 29, 2006, as evidenced by the issuance of KSD Purchase Order No. 800475, dated July 17, 2007. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 1350 North Lakeshore Drive, in Chandler, Arizona and consists of nine buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the nine buildings.

At the request of KSD, select identified suspect ACM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period September 4, 2007 through September 7, 2007, by Michael Coleman and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

## **2.2 Description of Construction**

### **2.2.1 Main Building**

The construction date of the Main Building is estimated to be unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support wooden and metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes, fiberglass reinforced paneling and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building, corridors and miscellaneous interior rooms.

Mechanical equipment for the building consists of roof-mounted air handler units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

### **2.2.2 Cafeteria Building**

The construction date of the Cafeteria Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support wooden and metal truss and deck systems finished with an asphalt prepared roofing system.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes, fiberglass reinforced paneling and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes, acoustical ceiling tiles and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building and miscellaneous interior rooms.

Mechanical equipment for the building consists of roof-mounted air handler units and ground level chiller components. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

### **2.2.3 Portables D1/D2, M1/M2, M3/M4, R1/R2, R3/R4, T1/T2 and T3/T4**

The construction date of Portables D1/D2, M1/M2, M3/M4, R1/R2, R3/R4, T1/T2 and T3/T4 is unknown. The construction appears to be consistent and uniform throughout each Portable.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: carpet, vinyl composition tile and vinyl sheet flooring.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal) or tackable wall panels. Restroom walls finishes include gypsum wallboard systems with textured, painted finishes and fiberglass reinforced panels (D1/D2, M1/M2, M3/M4, R1/R2 and R3/R4). Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes or acoustical ceiling tile.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the gypsum wallboard or suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

## **2.3 AHERA Inspection Procedures and Protocols**

### **2.3.1 Inspection Procedures and Protocols**

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
  - ◊ natural friability and,
  - ◊ physical condition and,
  - ◊ if damaged or thermal systems insulation;
    - \* be identified for an immediate response action or,
    - \* be identified for possible future disturbance and
    - \* have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
  - ◊ date accomplished and,
  - ◊ identification and qualification of individuals conducting each activity.

### **2.3.2 FM GROUP INC Inspection SOP**

FM's inspection procedures and protocols have been developed into a logical step by step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

## **2.4 Visual Inspection**

A visual inspection of the nine buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

## 2.5 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **TEN** friable suspect ACBM (acoustical ceiling panels and acoustical ceiling tile) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

## 2.6 Sample Collection

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples were collected from observed suspect ACBM.

<b>Building</b>	<b>Suspect ACBM</b>	<b>Samples Collected</b>
Main	67 (42 Assumed)	75
Cafeteria	52 (33 Assumed)	57
Portable D1/D2	29 (28 Assumed)	3
Portable M1/M2	27 (26 Assumed)	3
Portable M3/M4	29 (28 Assumed)	3
Portable R1/R2	33 (32 Assumed)	3
Portable R3/R4	36 (35 Assumed)	3
Portable T1/T2	21 (20 Assumed)	3
Portable T3/T4	21 (20 Assumed)	3
<b>TOTAL</b>	<b>315</b>	<b>153</b>

## 2.7 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a chain-of-custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single material bulk sample is sufficient to classify that material as an ACM. On the other hand, a minimum of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

**END OF REPORT**



**SECTION 3**

**DESIGNATED PERSON IDENTIFICATION**

---

**AHERA Designated Person**  
796.93(e)(4)

**Owner:** KYRENE SCHOOL DISTRICT NO. 28

**Address:** 8700 SOUTH KYRENE ROAD  
TEMPE, ARIZONA 85284-2197

**Property:** KYRENE DEL CIELO ELEMENTARY SCHOOL

**Address:** 1350 NORTH LAKESHORE DRIVE  
CHANDLER, ARIZONA 85226

**LEA Designated Person**

**Print Name:** Giacomo Musella, Facilities Supervisor

**Address:** 8700 South Kyrene Road  
Tempe, Arizona 85284-2197

**Phone:** 480.783-4200

**Training Course Name:** AHERA Building Inspector

**Dates of Training:** August 7-9, 2006      **Hours of Training:** 24

**Training Course Name:** AHERA Management Planner

**Dates of Training:** August 10-11, 2006      **Hours of Training:** 16

**Training Course Name:** \_\_\_\_\_

**Dates of Training:** \_\_\_\_\_      **Hours of Training:** \_\_\_\_\_

\_\_\_\_\_  
**Signature**


\_\_\_\_\_  
**Date**

D 10910

# THE ASBESTOS INSTITUTE

Certifies that  
**Giacomo Jack Musella**


has attended the EPA approved course  
**AHERA Refresher  
Building Inspector  
October 5, 2007**  
and successfully passed the competency exam.



Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**

  
\_\_\_\_\_  
Director

  
\_\_\_\_\_  
Approved Instructor

**THE ASBESTOS INSTITUTE**  
8102 North 23rd Avenue  
Suite A  
Phoenix, AZ 85021-4962  
602-864-6564

*This training meets all requirements for asbestos accreditation under TSCA Title II.*

D 10936

# THE ASBESTOS INSTITUTE


Certifies that  
**Giacomo Jack Musella**


has attended the EPA approved course  
**AHERA Refresher  
Management Planner  
October 5, 2007**  
and successfully passed the competency exam.

COPY

Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**

  
\_\_\_\_\_  
Director

  
\_\_\_\_\_  
Approved Instructor

THE ASBESTOS INSTITUTE  
8102 North 23rd Avenue  
Suite A  
Phoenix, AZ 85021-4962  
602-864-6564

*This training meets all requirements for asbestos accreditation under TSCA Title II.*

## **SECTION 4**

### **RESPONSE ACTION(S)**

---

**THERE ARE NO RESPONSE ACTIONS REQUIRED AT THIS FACILITY.**

**SECTION 5**

**ACCREDITATION STATEMENTS**

---

**Assurance of Accreditation  
Under this Management Plan  
763.93(e)(7)**

**Inspector(s):**

**Name:** MICHAEL COLEMAN  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** APRIL 8, 2008  
**Accreditation Number(s):** BIIA040907-01

**Name:** CLIFF ROLLE  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** JUNE 1, 2008  
**Accreditation Number(s):** D10203

**Name:** DANE THOMPSON  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** MAY 4, 2008  
**Accreditation Number(s):** D 9953

**Management Planner:**

**Name:** PAUL ANGER  
**State of Accreditation or EPA:** EPA  
**Accreditation Date(s):** JANUARY 5, 2008  
**Accreditation Number(s):** D 9213

Any Project Designer, Contractor/Supervisor or Worker who performs work on response actions under this Management Plan shall be accredited by either an EPA approved state contractor accreditation plan or an EPA approved course under Section 206(b) to Title II of the Toxic Substance Control Act.

# Certificate Of Training

In recognition of attendance and passing of exam

**MICHAEL D. COLLEMAN**

**4855**

The above person has completed the requisite training course for asbestos accreditation under TSCA Title II,  
Asbestos Model Accreditation Plan and the provider is accredited to provide training within the  
**State of Hawaii, #T-0108**

And/or as listed below


*Building Inspector Initial*

Completed this 9<sup>th</sup> Day of April, 2007 Expires 8<sup>th</sup> Day of April, 2008

**NEPCO**


National Environmental Institute & Consulting  
Surprise, Arizona--Honolulu, Hawaii

Certificate # BIIA040907-01

  
Training Director



# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

AHERA Refresher  
Building Inspector

June 1, 2007

and successfully passed the competency exam

Date of Examination: June 1, 2007

Date of Expiration: June 1, 2008

Director

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

ANERA Refresher  
Building Inspector

May 4, 2007

and successfully passed the competency exam

Date of Examination: May 4, 2007

Date of Expiration: May 4, 2008

Director

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

# THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

and successfully passed the competency exam

*[Signature]*  
 Director

Director

Approved Instructor

THE ASBESTOS INSTITUTE  
 8102 North 23rd Avenue  
 Suite A  
 Phoenix, AZ 85021-4962  
 602-864-6564