


ASBESTOS MANAGEMENT PLAN



at

Kyrene Middle School

Prepared for:

Kyrene School District No. 28

VOLUME I OF III

**FM GROUP INC
FM Project 08-145**

June 2008

ASBESTOS MANAGEMENT PLAN

Kyrene Middle School

June 2008

FM GROUP INC

FM Project 08-145

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY	1-1
2	INSPECTION REPORT	2-1
3	DESIGNATED PERSON IDENTIFICATION.....	3-1
4	RESPONSE ACTION.....	4-1
5	ACCREDITATION STATEMENTS	5-1
6	REMAINING ACBM.....	6-1
7	O&M PROGRAM.....	7-1
8	INITIAL NOTIFICATIONS	8-1
9	COST ESTIMATION	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON	10-1
11	ANNUAL NOTIFICATIONS	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT	12-1

APPENDIX A: ONGOING RECORDKEEPING

SECTION 1

GENERAL INVENTORY

General Inventory
763.93(e)(1)

Date: JUNE 8, 2008

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: KYRENE MIDDLE SCHOOL

Address: 1050 EAST CARVER ROAD
TEMPE, ARIZONA 85284

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
E	N/A	X	X
F	N/A	X	X
G	N/A	X	X
H	N/A	X	X
J	N/A	X	X
K	N/A	X	X
L	N/A	X	X

SECTION 2

INSPECTION REPORT

INSPECTION REPORT

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:


Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene Middle Elementary School

Prepared by: FM GROUP INC
Project No.: 08-145
Date: June 2008

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28
8700 South Kyrene Road
Tempe, Arizona 85284-2197

REPORT OF FINDINGS
(Abridged Version)



Comprehensive AHERA Asbestos Inspection

at

Kyrene Middle School

Prepared for:

Kyrene School District No. 28

FM GROUP INC
FM Project 08-145

June 2008

TABLE OF CONTENTS

Report of Findings

Comprehensive AHERA Asbestos Inspection
Kyrene Middle School
Kyrene School District No. 28

FM GROUP Project 08-145

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u>	1
1.1 Summary	1
1.2 Identified Asbestos-Containing Materials	1
1.3 Asbestos-Containing Building Materials (Table C)	2
1.4 ACBM/Location Plans	3
1.5 Critical Situations	4
1.6 Friable Asbestos-Containing Building Materials	4
1.7 Material Assessments	4
1.8 Recommendations	4
1.9 Qualifications of the Report.....	4
2.0 <u>PROJECT INFORMATION</u>	5
2.1 Background.....	5
2.2 Description of Construction	5
2.2.1 Buildings E, F, G, H, J, K and L.....	5
2.3 Building Materials/Systems List (Table A)	7
2.3.1 Building E	8
2.3.2 Building F	21
2.3.3 Building G.....	50
2.3.4 Building H.....	78
2.3.5 Building J.....	106
2.3.6 Building K.....	120
2.3.7 Building L	141
2.4 AHERA Inspection Procedures and Protocols.....	165
2.4.1 Inspection Procedures and Protocols	165
2.4.2 FM GROUP INC Inspection SOP	165
2.5 Visual Inspection.....	165
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B) .	166
2.6.1 Building E	167
2.6.2 Building F	170
2.6.3 Building G.....	173
2.3.4 Building H.....	176
2.3.5 Building J.....	179

<u>Section</u>	<u>Page</u>
2.3.6 Building K.....	181
2.3.7 Building L.....	183
2.7 Physical Assessments.....	186
2.8 Sample Collection.....	186
2.9 Material Bulk Sample Analysis.....	186

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none">• Chain-of-Custody• Laboratory Analysis
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

ENVKSD\08-145 Kyrene Middle School\2.0\2.3\2.3.1\TOC.doc

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the seven buildings comprising the Kyrene Middle School (KMS) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of May 5, 2008 through May 8, 2008. A total of 154 bulk-material samples were collected from 424 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Three Hundred Seventy-two building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos-Containing Building Materials

The identified ACBM within the seven buildings at KMS are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

Asbestos Material-Bulk Samples Collected

<i>Building</i>	<i>No. of Samples</i>	<i>No. HA</i>	<i>No. Assumed</i>	<i>Total No. ACM</i>
E	16	60	54	54
F	18	62	56	56
G	21	60	53	53
H	21	60	53	53
J	27	54	45	45
K	21	46	39	39
L	30	82	72	72

1.3 Asbestos-Containing Building Materials

TABLE C
ASBESTOS CONTAINING BUILDING MATERIALS

BUILDING E
BUILDING F
BUILDING G
BUILDING H
BUILDING J
BUILDING K
BUILDING L

TABLE C HAS BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN

1.4 ACBM/Location Plans

**BUILDING E
BUILDING F
BUILDING G
BUILDING H
BUILDING J
BUILDING K
BUILDING L**

**ACBM/LOCATION PLANS HAVE BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN**

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the seven buildings at KMS during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Miscellaneous or Surfacing Building Materials, or Asbestos-Containing Thermal System Insulation in the seven buildings at KMS during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Miscellaneous or Surfacing Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the seven buildings at KMS, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the seven buildings at the KMS campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the seven buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 808792, dated April 11, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 1050 East Carver Road, in Tempe, Arizona and consists of seven buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the seven buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period of May 5, 2008 through May 8, 2008, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.

2.2 Description of Construction

2.2.1 Buildings E, F, G, H, J, K and L

The construction date of Buildings E, F, G, H, J, K and L is unknown. The construction appears to be consistent and uniform throughout each building.

The buildings are built with slab on-grade foundations. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support a concrete deck system finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, fiberglass reinforced panel, glazed wall tile, stucco, tackable wall panels or wallpaper. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings, corridors and miscellaneous interior rooms.

Mechanical equipment for the buildings consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.

2.3 Building Materials/Systems List

TABLE A BUILDING MATERIAL SYSTEMS

**BUILDING E
BUILDING F
BUILDING G
BUILDING H
BUILDING J
BUILDING K
BUILDING L**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building E*

JOB NO. 08-145

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF	O	*	S
SEALANT (DOORS, WALLS, FLASHINGS), BROWN, PLIABLE	LOBBY	O	N, E, W	S
	GYMNASIUM	O	N, E, W	
	GYM STORAGE	O	W, S	
	MECHANICAL ROOM	O	N, W, S	
	ELECTRICAL ROOM	O	N, W	
	EXTERIOR	O	N, E, W	
	ROOF	O	*	
SEALANT (FLASHINGS), GRAY, PLIABLE	ROOF	O	*	S
BRICK, 4"X16", RED, CEMENTITIOUS	LOBBY	W	N, E, W	S
	GYMNASIUM	W	N, E, W	
	GYM STORAGE	W	W, S	
	MECHANICAL ROOM	W	N, W, S	
	ELECTRICAL ROOM	W	N, W	
	EXTERIOR	W	N, E, W	
	ROOF	O	N, E, W, S	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	ROOF	O	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH	ROOF	O	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	ROOF	O	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S
	ROOF	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	LOBBY	W	N, E	S
	GYMNASIUM	W	N, E, W	
	GYM STORAGE	W	W, S	
	MECHANICAL ROOM	W	N, W, S	
	ELECTRICAL ROOM	W	N, W	
	EXTERIOR	W	N, E, W, S	
	ROOF	O	N, E, W, S	
SEALANT (FLASHINGS), BLACK, PLIABLE	ROOF	O	*	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	ROOF	O	S	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W	S
	ROOF	O	W, S	
GLASS BLOCK, 8"X8", CLEAR	GYMNASIUM	W	N, E	N
	EXTERIOR	W	N, E	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	GYMNASIUM	W	N, E	S
	EXTERIOR	W	N, E	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES, WALLS), WHITE, PLIABLE	GYMNASIUM	O	E	S
	VESTIBULE 4	O	N, E, W, S	
	MEN'S LOCKER ROOM	O	E, W, S	
	VESTIBULE 3	O	E, W, S	
	P.E. OFFICE 1	O	N, W	
	P.E. RESTROOM 1	O	N, S	
	VESTIBULE 1	O	E, W	
	VESTIBULE 2	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	TEAM LOCKER 1	O	N, E, S	
	P.E. STORAGE	O	S	
	VESTIBULE 5	O	E, W	
	WOMEN'S SHOWERS	O	W	
	WOMEN'S LOCKER ROOM	O	W, S	
	P.E. OFFICE 2	O	N, E	
	P.E. RESTROOM 2	O	W	
	VESTIBULE 7	O	N, E	
	VESTIBULE 8	O	N, S	
	TEAM LOCKER 2	O	W	
	P.E. STORAGE 2	O	E, S	
	MECHANICAL ROOM	O	E	
	ELECTRICAL ROOM	O	E	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LOBBY	F	*	S
	GYMNASIUM	F	*	
	VESTIBULE 4	F	*	
	MEN'S SHOWERS	F	*	
	MEN'S LOCKER ROOM	F	*	
	MOP CLOSET 1	F	*	
	VESTIBULE 3	F	*	
	P.E. OFFICE 1	F	*	
	P.E. RESTROOM 1	F	*	
	VESTIBULE 1	F	*	
	VESTIBULE 2	F	*	
	TEAM LOCKER 1	F	*	
	P.E. STORAGE	F	*	
	VESTIBULE 5	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	WOMEN'S SHOWERS	F	*	
	WOMEN'S LOCKER ROOM	F	*	
	MOP CLOSET 2	F	*	
	VESTIBULE 6	F	*	
	P.E. OFFICE 2	F	*	
	P.E. RESTROOM 2	F	*	
	VESTIBULE 7	F	*	
	VESTIBULE 8	F	*	
	TEAM LOCKER 2	F	*	
	P.E. STORAGE 2	F	*	
	GYM STORAGE	F	*	
	MECHANICAL ROOM	F	*	
	ELECTRICAL ROOM	F	*	
	EXTERIOR	F	*	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOBBY	O	E, W	S
	GYMNASIUM	O	N, E, W	
	VESTIBULE 4	O	N, E	
	MEN'S LOCKER ROOM	O	W, S	
	VESTIBULE 3	O	E, W	
	VESTIBULE 1	O	E, W	
	VESTIBULE 2	O	N, W	
	TEAM LOCKER 1	O	N, E, S	
	P.E. STORAGE	O	E, S	
	VESTIBULE 5	O	E, W	
	WOMEN'S LOCKER ROOM	O	W, S	
	VESTIBULE 6	O	N	
	VESTIBULE 7	O	N	
	VESTIBULE 8	O	N, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	P.E. STORAGE 2	O	E, S	
	GYM STORAGE	O	W	
	MECHANICAL ROOM	O	E	
	ELECTRICAL ROOM	O	E, W	
SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	LOBBY	O	*	S
	GYMNASIUM	O	*	
	VESTIBULE 4	O	*	
	MEN'S SHOWERS	O	*	
	MEN'S LOCKER ROOM	O	*	
	MOP CLOSET 1	O	*	
	VESTIBULE 3	O	*	
	P.E. OFFICE 1	O	*	
	P.E. RESTROOM 1	O	*	
	VESTIBULE 1	O	*	
	VESTIBULE 2	O	*	
	TEAM LOCKER 1	O	*	
	P.E. STORAGE	O	*	
	VESTIBULE 5	O	*	
	WOMEN'S SHOWERS	O	*	
	WOMEN'S LOCKER ROOM	O	*	
	MOP CLOSET 2	O	*	
	VESTIBULE 6	O	*	
	P.E. OFFICE 2	O	*	
	P.E. RESTROOM 2	O	*	
	VESTIBULE 7	O	*	
	VESTIBULE 8	O	*	
	TEAM LOCKER 2	O	*	
	P.E. STORAGE 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	GYM STORAGE	O	*	
	MECHANICAL ROOM	O	*	
	ELECTRICAL ROOM	O	*	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	GYM STORAGE	W	S	S
	MECHANICAL ROOM	W	N, S	
	ELECTRICAL ROOM	W	N	
PIPE END SEALANT, WHITE, PLIABLE	MECHANICAL ROOM	O	*	S
DUCT SEAM TAPE, 4", WHITE, CANVAS-LIKE	MECHANICAL ROOM	O	*	S
SEALANT (DUCT), LIGHT GRAY, PLIABLE	MECHANICAL ROOM	O	*	S
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	MECHANICAL ROOM	O	*	S
GYPSUM WALLBOARD, WHITE, CHALKY	MECHANICAL ROOM	W	E	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MECHANICAL ROOM	W	E	S
SEALANT (FIRE STOP), WHITE, PLIABLE	MECHANICAL ROOM	C	*	S
TROWELED-ON TEXTURE, WHITE, CHALKY	MOP CLOSET 1	W	N, E, W, S	S
	MOP CLOSET 2	W	N, E, W, S	
	P.E. STORAGE 2	W	N, E, W, S	
	ELECTRICAL ROOM	W	E, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	MOP CLOSET 1	W	N, E, W, S	S
	MOP CLOSET 2	W	N, E, W, S	
	P.E. STORAGE 2	W	N, E, W, S	
	ELECTRICAL ROOM	W	E, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MOP CLOSET 1	W	N, E, W, S	S
	MOP CLOSET 2	W	N, E, W, S	
	P.E. STORAGE 2	W	N, E, W, S	
	ELECTRICAL ROOM	W	E, S	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	GYMNASIUM	C	*	S
	P.E. OFFICE 1	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	P.E. STORAGE	C	*	
	P.E. OFFICE 2	C	*	
	P.E. STORAGE 2	C	*	
	GYM STORAGE	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GYMNASIUM	W	N, E, W, S	S
	VESTIBULE 4	C, W	N, E, W, S	
	VESTIBULE 3	C, W	N, E, W, S	
	P.E. OFFICE 1	W	N, E, W, S	
	VESTIBULE 1	C, W	N, E, W, S	
	VESTIBULE 2	C, W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	VESTIBULE 5	C, W	N, E, W, S	
	VESTIBULE 6	C, W	N, E, W, S	
	P.E. OFFICE 2	W	N, E, W, S	
	VESTIBULE 7	C, W	N, E, W, S	
	VESTIBULE 8	C, W	N, E, W, S	
	GYM STORAGE	W	N, E	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	GYMNASIUM	W	N, E, W, S	S
	VESTIBULE 4	C, W	N, E, W, S	
	VESTIBULE 3	C, W	N, E, W, S	
	P.E. OFFICE 1	W	N, E, W, S	
	VESTIBULE 1	C, W	N, E, W, S	
	VESTIBULE 2	C, W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	VESTIBULE 5	C, W	N, E, W, S	
	VESTIBULE 6	C, W	N, E, W, S	
	P.E. OFFICE 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	VESTIBULE 7	C, W	N, E, W, S	
	VESTIBULE 8	C, W	N, E, W, S	
	GYM STORAGE	W	N, E	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY.	GYMNASIUM	W	N, E, W, S	S
	VESTIBULE 4	C, W	N, E, W, S	
	VESTIBULE 3	C, W	N, E, W, S	
	P.E. OFFICE 1	W	N, E, W, S	
	VESTIBULE 1	C, W	N, E, W, S	
	VESTIBULE 2	C, W	N, E, W, S	
	P.E. STORAGE	W	N, E, W, S	
	VESTIBULE 5	C, W	N, E, W, S	
	VESTIBULE 6	C, W	N, E, W, S	
	P.E. OFFICE 2	W	N, E, W, S	
	VESTIBULE 7	C, W	N, E, W, S	
	VESTIBULE 8	C, W	N, E, W, S	
	GYM STORAGE	W	N, E	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	GYMNASIUM	F	*	S
	VESTIBULE 4	F	*	
	MOP CLOSET 1	F	*	
	VESTIBULE 3	F	*	
	P.E. RESTROOM 1	F	*	
	VESTIBULE 1	F	*	
	VESTIBULE 2	F	*	
	P.E. STORAGE	F	*	
	VESTIBULE 5	F	*	
	VESTIBULE 6	F	*	
	P.E. RESTROOM 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	VESTIBULE 7	F	*	
	P.E. STORAGE 2	F	*	
	GYM STORAGE	F	*	
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	GYMNASIUM	F	*	S
	VESTIBULE 4	F	*	
	MOP CLOSET 1	F	*	
	VESTIBULE 3	F	*	
	P.E. RESTROOM 1	F	*	
	VESTIBULE 1	F	*	
	VESTIBULE 2	F	*	
	P.E. STORAGE	F	*	
	VESTIBULE 5	F	*	
	VESTIBULE 6	F	*	
	P.E. RESTROOM 2	F	*	
	VESTIBULE 7	F	*	
	P.E. STORAGE 2	F	*	
	GYM STORAGE	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	GYMNASIUM	O	N, E, W	S
	MOP CLOSET 1	O	N, E, W, S	
	VESTIBULE 3	O	N, E, W, S	
	P.E. OFFICE 1	O	N, E, W, S	
	P.E. RESTROOM 1	O	N, E, W, S	
	VESTIBULE 1	O	N, E, W, S	
	VESTIBULE 2	O	N, E, W, S	
	P.E. STORAGE	O	N, E, W, S	
	VESTIBULE 5	O	N, E, W, S	
	MOP CLOSET 2	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building E*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	VESTIBULE 6	O	N, E, W, S	
	P.E. OFFICE 2	O	N, E, W, S	
	P.E. RESTROOM 2	O	N, E, W, S	
	VESTIBULE 7	O	N, E, W, S	
	VESTIBULE 8	O	N, E, W, S	
	P.E. STORAGE 2	O	N, E, W, S	
	GYM STORAGE	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	GYMNASIUM	O	N, E, W	S
	MOP CLOSET 1	O	N, E, W, S	
	VESTIBULE 3	O	N, E, W, S	
	P.E. OFFICE 1	O	N, E, W, S	
	P.E. RESTROOM 1	O	N, E, W, S	
	VESTIBULE 1	O	N, E, W, S	
	VESTIBULE 2	O	N, E, W, S	
	P.E. STORAGE	O	N, E, W, S	
	VESTIBULE 5	O	N, E, W, S	
	MOP CLOSET 2	O	N, E, W, S	
	VESTIBULE 6	O	N, E, W, S	
	P.E. OFFICE 2	O	N, E, W, S	
	P.E. RESTROOM 2	O	N, E, W, S	
	VESTIBULE 7	O	N, E, W, S	
	VESTIBULE 8	O	N, E, W, S	
	P.E. STORAGE 2	O	N, E, W, S	
	GYM STORAGE	O	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S LOCKER ROOM	C, W	N, E, W, S	S
	P.E. RESTROOM 1	C, W	N, E, W, S	
	TEAM LOCKER 1	C, W	N, E, W, S	
	WOMEN'S LOCKER ROOM	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	P.E. RESTROOM 2	C, W	N, E, W, S	
	TEAM LOCKER 2	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S LOCKER ROOM	C, W	N, E, W, S	S
	P.E. RESTROOM 1	C, W	N, E, W, S	
	TEAM LOCKER 1	C, W	N, E, W, S	
	WOMEN'S LOCKER ROOM	C, W	N, E, W, S	
	P.E. RESTROOM 2	C, W	N, E, W, S	
	TEAM LOCKER 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S LOCKER ROOM	C, W	N, E, W, S	S
	P.E. RESTROOM 1	C, W	N, E, W, S	
	TEAM LOCKER 1	C, W	N, E, W, S	
	WOMEN'S LOCKER ROOM	C, W	N, E, W, S	
	P.E. RESTROOM 2	C, W	N, E, W, S	
	TEAM LOCKER 2	C, W	N, E, W, S	
GLAZED WALL TILE, 4", LIGHT GREEN, SMOOTH	MEN'S SHOWERS	W	N, E, W, S	S
	MEN'S LOCKER ROOM	W, F	N, E, W, S	
	TEAM LOCKER 1	W, F	N, E, W	
	WOMEN'S SHOWERS	W	N, E, W, S	
	WOMEN'S LOCKER ROOM	W, F	N, E, W, S	
	TEAM LOCKER 2	W, F	N, E, S	
GLAZED WALL TILE, 4", GREEN, SMOOTH	MEN'S SHOWERS	W	N, E, W, S	S
	MEN'S LOCKER ROOM	W, F	N, E, W, S	
	TEAM LOCKER 1	W, F	N, E, W	
	WOMEN'S SHOWERS	W	N, E, W, S	
	WOMEN'S LOCKER ROOM	W, F	N, E, W, S	
	TEAM LOCKER 2	W, F	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE, 4", GREEN, SMOOTH	MEN'S SHOWERS	W	N, E, W, S	S
	MEN'S LOCKER ROOM	W, F	N, E, W, S	
	TEAM LOCKER 1	W, F	N, E, W	
	WOMEN'S SHOWERS	W	N, E, W, S	
	WOMEN'S LOCKER ROOM	W, F	N, E, W, S	
	TEAM LOCKER 2	W, F	N, E, S	
GLAZED WALL TILE, 6"x8", WHITE, SMOOTH	MEN'S LOCKER ROOM	W	N, E, W, S	S
	TEAM LOCKER 1	W	N, E, W, S	
	WOMEN'S LOCKER ROOM	W	N	
	TEAM LOCKER 2	W	W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 6"x8", WHITE, SMOOTH	MEN'S LOCKER ROOM	W	N, E, W, S	S
	TEAM LOCKER 1	W	N, E, W, S	
	WOMEN'S LOCKER ROOM	W	N	
	TEAM LOCKER 2	W	W, S	
CERAMIC MOSAIC TILE, 4"x4", WHITE, SMOOTH	MEN'S LOCKER ROOM	F	*	S
	TEAM LOCKER 1	F	*	
	WOMEN'S LOCKER ROOM	F	*	
	TEAM LOCKER 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 4"x4", WHITE, SMOOTH AND CERAMIC MOSAIC TILE, 2"x2", LIGHT GREEN, SMOOTH	MEN'S LOCKER ROOM	F	*	S
	TEAM LOCKER 1	F	*	
	WOMEN'S LOCKER ROOM	F	*	
	TEAM LOCKER 2	F	*	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	P.E. OFFICE 1	F	*	S
	P.E. OFFICE 2	F	*	
CONCRETE, WHITE, CEMENTITIOUS, BLUE SPECKS	P.E. RESTROOM 1	F	*	S
	P.E. RESTROOM 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building E

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	MEN'S SHOWERS	W	N, E, W, S	S
	MEN'S LOCKER ROOM	W	N, E, W, S	
	WOMEN'S SHOWERS	W	N, E, W, S	
	WOMEN'S LOCKER ROOM	W	N, E, W, S	
FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	MOP CLOSET 1	W	E	N
	MOP CLOSET 2	W	S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	MOP CLOSET 1	W	E	S
	MOP CLOSET 2	W	S	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	VESTIBULE 4	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	VESTIBULE 4	O	N, E, W, S	S
CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	MEN'S SHOWERS	F	*	S
	WOMEN'S SHOWERS	F	*	S
CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	MEN'S SHOWERS	F	*	S
	WOMEN'S SHOWERS	F	*	S
CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH	MEN'S SHOWERS	F	*	S
	WOMEN'S SHOWERS	F	*	S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	GYMNASIUM	C	*	S
WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	GYMNASIUM	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	GYMNASIUM	O	N, E, W, S	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building F*

JOB NO. 08-145

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF	O	*	S
SEALANT (FLASHING), GRAY, PLIABLE	ROOF	O	*	S
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	CLASSROOM F100	O	*	S
	CLASSROOM F101	O	*	
	CLASSROOM F102	O	*	
	CLASSROOM F103	O	*	
	CLASSROOM F104	O	*	
	CLASSROOM F105	O	*	
	CLASSROOM F106	O	*	
	CLASSROOM F107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM F108	O	*	
	CLASSROOM F109	O	*	
	ROOM F109 RESTROOM	O	*	
	CLASSROOM F110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM F200	O	*	
	CLASSROOM F201	O	*	
	CLASSROOM F202	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM F203	O	*	
	CLASSROOM F204	O	*	
	CLASSROOM F205	O	*	
	CLASSROOM F206	O	*	
	CLASSROOM F207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM F208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
SEALANT (DUCT), GRAY, PLIABLE	CLASSROOM F100	O	*	S
	CLASSROOM F101	O	*	
	CLASSROOM F102	O	*	
	CLASSROOM F103	O	*	
	CLASSROOM F104	O	*	
	CLASSROOM F105	O	*	
	CLASSROOM F106	O	*	
	CLASSROOM F107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F108	O	*	
	CLASSROOM F109	O	*	
	ROOM F109 RESTROOM	O	*	
	CLASSROOM F110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM F200	O	*	
	CLASSROOM F201	O	*	
	CLASSROOM F202	O	*	
	CLASSROOM F203	O	*	
	CLASSROOM F204	O	*	
	CLASSROOM F205	O	*	
	CLASSROOM F206	O	*	
	CLASSROOM F207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM F208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
SEALANT (DUCT), PINK, PLIABLE	CLASSROOM F100	O	*	S
	CLASSROOM F101	O	*	
	CLASSROOM F102	O	*	
	CLASSROOM F103	O	*	
	CLASSROOM F104	O	*	
	CLASSROOM F105	O	*	
	CLASSROOM F106	O	*	
	CLASSROOM F107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM F108	O	*	
	CLASSROOM F109	O	*	
	ROOM F109 RESTROOM	O	*	
	CLASSROOM F110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM F200	O	*	
	CLASSROOM F201	O	*	
	CLASSROOM F202	O	*	
	CLASSROOM F203	O	*	
	CLASSROOM F204	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F205	O	*	
	CLASSROOM F206	O	*	
	CLASSROOM F207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM F208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
BRICK, 4"X16", RED, CEMENTITIOUS	MECHANICAL 3	W	E, W, S	S
	CORRIDOR 1	W	N, E, W, S	
	CORRIDOR 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building F*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	MECHANICAL 3	W	N	S
	EXTERIOR	W	N, E, W, S	
SEALANT (DOORS, MILLWORK, WALLS), WHITE, PLIABLE	CLASSROOM F100	O	N, E, W, S	S
	CLASSROOM F101	O	N, E, W, S	
	CLASSROOM F102	O	N, W, S	
	CLASSROOM F103	O	N, W, S	
	CLASSROOM F104	O	E, W, S	
	CLASSROOM F105	O	N, E, W, S	
	CLASSROOM F106	O	N, E, W, S	
	CLASSROOM F107	O	N, E, W, S	
	STORAGE 1	O	N, S	
	CLASSROOM F108	O	N, W	
	CLASSROOM F109	O	N, S	
	ROOM F109 RESTROOM	O	N, W	
	CLASSROOM F110	O	N, E	
	ROOM E110	O	E	
	ROOM E111	O	W	
	BOY'S RESTROOM 1	O	E	
	GIRL'S RESTROOM 1	O	W	
	CORRIDOR 1	O	E, W	
	CLASSROOM F200	O	N, W, S	
	CLASSROOM F201	O	N, W, S	
	CLASSROOM F202	O	N, W, S	
	CLASSROOM F203	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F204	O	E, W, S	
	CLASSROOM F205	O	E, W, S	
	CLASSROOM F206	O	E, W, S	
	CLASSROOM F207	O	N, E, W, S	
	STORAGE 2	O	N, S	
	MECHANICAL 2	O	S	
	STAFF MEN'S RESTROOM	O	W	
	STORAGE 3	O	W	
	WORK ROOM F208	O	N, E, W, S	
	STAFF WOMEN'S RESTROOM	O	E	
	STORAGE 4	O	E	
	ROOM E210	O	E	
	ROOM E211	O	W	
	BOY'S RESTROOM 2	O	E	
	GIRL'S RESTROOM 2	O	W	
	CORRIDOR 2	O	E, W	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	*	
SEALANT (WALLS), BROWN, PLIABLE	CORRIDOR 1	O	N, E, W, S	S
	CORRIDOR 2	O	N, E, W, S	
	EXTERIOR	O	E, W	
SEALANT (WALLS), GRAY, PLIABLE	EXTERIOR	O	N, E, W, S	S
GLASS BLOCK, 8"X8", CLEAR	CORRIDOR 1	W	E, W	N
	CORRIDOR 2	W	E, W	
	EXTERIOR	W	E, W	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	CORRIDOR 1	W	E, W	S
	CORRIDOR 2	W	E, W	
	EXTERIOR	W	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building F*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	EXTERIOR	W	N, E, W, S	S
GROUT, BROWN, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	EXTERIOR	W	N, E, W, S	S
TROWELED-ON TEXTURE, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CLASSROOM F100	F	*	S
	CLASSROOM F101	F	*	
	CLASSROOM F102	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F103	F	*	
	CLASSROOM F104	F	*	
	CLASSROOM F105	F	*	
	CLASSROOM F106	F	*	
	CLASSROOM F107	F	*	
	STORAGE 1	F	*	
	MECHANICAL 1	F	*	
	MECHANICAL 3	F	*	
	CLASSROOM F108	F	*	
	CLASSROOM F109	F	*	
	ROOM F109 RESTROOM	F	*	
	CLASSROOM F110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAIRWELL	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM F200	F	*	
	CLASSROOM F201	F	*	
	CLASSROOM F202	F	*	
	CLASSROOM F203	F	*	
	CLASSROOM F204	F	*	
	CLASSROOM F205	F	*	
	CLASSROOM F206	F	*	
	CLASSROOM F207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF MEN'S RESTROOM	F	*	
	STORAGE 3	F	*	
	WORK ROOM F208	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
	CORRIDOR 2	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	CORRIDOR 1	C	*	S
	CORRIDOR 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	CLASSROOM F100	F	*	S
	CLASSROOM F101	F	*	
	CLASSROOM F102	F	*	
	CLASSROOM F103	F	*	
	CLASSROOM F104	F	*	
	CLASSROOM F105	F	*	
	CLASSROOM F106	F	*	
	CLASSROOM F107	F	*	
	CLASSROOM F108	F	*	
	CLASSROOM F109	F	*	
	CLASSROOM F110	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building F*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CORRIDOR 1	F	*	
	CLASSROOM F200	F	*	
	CLASSROOM F201	F	*	
	CLASSROOM F202	F	*	
	CLASSROOM F203	F	*	
	CLASSROOM F204	F	*	
	CLASSROOM F205	F	*	
	CLASSROOM F206	F	*	
	CLASSROOM F207	F	*	
	WORK ROOM F208	F	*	
	CORRIDOR 2	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	CLASSROOM F100	F	*	S
	CLASSROOM F101	F	*	
	CLASSROOM F102	F	*	
	CLASSROOM F103	F	*	
	CLASSROOM F104	F	*	
	CLASSROOM F105	F	*	
	CLASSROOM F106	F	*	
	CLASSROOM F107	F	*	
	STORAGE 1	F	*	
	CLASSROOM F109	F	*	
	ROOM F109 RESTROOM	F	*	
	CLASSROOM F110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM F200	F	*	
	CLASSROOM F201	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F202	F	*	
	CLASSROOM F203	F	*	
	CLASSROOM F204	F	*	
	CLASSROOM F205	F	*	
	CLASSROOM F206	F	*	
	CLASSROOM F207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	CORRIDOR 2	F	*	
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK SPECKS	CLASSROOM F100	F	*	S
	CLASSROOM F101	F	*	
	CLASSROOM F102	F	*	
	CLASSROOM F103	F	*	
	CLASSROOM F104	F	*	
	CLASSROOM F105	F	*	
	CLASSROOM F106	F	*	
	CLASSROOM F107	F	*	
	STORAGE 1	F	*	
	CLASSROOM F109	F	*	
	ROOM F109 RESTROOM	F	*	
	CLASSROOM F110	F	*	
	ROOM E110	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM E111	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM F200	F	*	
	CLASSROOM F201	F	*	
	CLASSROOM F202	F	*	
	CLASSROOM F203	F	*	
	CLASSROOM F204	F	*	
	CLASSROOM F205	F	*	
	CLASSROOM F206	F	*	
	CLASSROOM F207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	CORRIDOR 2	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	CLASSROOM F100	O	N, E, W, S	S
	CLASSROOM F101	O	N, E, W, S	
	CLASSROOM F102	O	N, E, W, S	
	CLASSROOM F103	O	N, E, W, S	
	CLASSROOM F104	O	N, E, W, S	
	CLASSROOM F105	O	N, E, W, S	
	CLASSROOM F106	O	N, E, W, S	
	CLASSROOM F107	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CLASSROOM F108	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM F109	O	N, E, W, S	
	ROOM F109 RESTROOM	O	N, W, S	
	CLASSROOM F110	O	N, E, W, S	
	ROOM E110	O	N, E, W, S	
	ROOM E111	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM F200	O	N, E, W, S	
	CLASSROOM F201	O	N, E, W, S	
	CLASSROOM F202	O	N, E, W, S	
	CLASSROOM F203	O	N, E, W, S	
	CLASSROOM F204	O	N, E, W, S	
	CLASSROOM F205	O	N, E, W, S	
	CLASSROOM F206	O	N, E, W, S	
	CLASSROOM F207	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	MECHANICAL 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	WORK ROOM F208	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ROOM E210	O	N, E, W, S	
	ROOM E211	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	CLASSROOM F100	O	N, E, W, S	S
	CLASSROOM F101	O	N, E, W, S	
	CLASSROOM F102	O	N, E, W, S	
	CLASSROOM F103	O	N, E, W, S	
	CLASSROOM F104	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F105	O	N, E, W, S	
	CLASSROOM F106	O	N, E, W, S	
	CLASSROOM F107	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CLASSROOM F108	O	N, E, W, S	
	CLASSROOM F109	O	N, W, S	
	ROOM F109 RESTROOM	O	N, W, S	
	CLASSROOM F110	O	N, E, S	
	ROOM E110	O	N, E, W, S	
	ROOM E111	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM F200	O	N, E, W, S	
	CLASSROOM F201	O	N, E, W, S	
	CLASSROOM F202	O	N, E, W, S	
	CLASSROOM F203	O	N, E, W, S	
	CLASSROOM F204	O	N, E, W, S	
	CLASSROOM F205	O	N, E, W, S	
	CLASSROOM F206	O	N, E, W, S	
	CLASSROOM F207	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	MECHANICAL 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	WORK ROOM F208	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ROOM E210	O	N, E, W, S	
	ROOM E211	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CLASSROOM F100	O	N, W	S
	CLASSROOM F101	O	W, S	
	CLASSROOM F102	O	N, W	
	CLASSROOM F103	O	N, W, S	
	CLASSROOM F104	O	W, S	
	CLASSROOM F105	O	E, S	
	CLASSROOM F106	O	N, E, S	
	CLASSROOM F107	O	N, E, S	
	STORAGE 1	O	N, S	
	MECHANICAL 1	O	W	
	CLASSROOM F108	O	N	
	CLASSROOM F109	O	N, S	
	ROOM F109 RESTROOM	O	N	
	CLASSROOM F110	O	N	
	ROOM E110	O	E	
	ROOM E111	O	W	
	BOY'S RESTROOM 1	O	W	
	GIRL'S RESTROOM 1	O	E	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM F200	O	N, W	
	CLASSROOM F201	O	W, S	
	CLASSROOM F202	O	N, W	
	CLASSROOM F203	O	N, W, S	
	CLASSROOM F204	O	W, S	
	CLASSROOM F205	O	E, S	
	CLASSROOM F206	O	N, E, S	
	CLASSROOM F207	O	N, E, S	
	STORAGE 2	O	N, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MECHANICAL 2	O	S	
	STAFF MEN'S RESTROOM	O	N	
	STORAGE 3	O	W	
	WORK ROOM F208	O	N, E, W	
	STAFF WOMEN'S RESTROOM	O	N	
	STORAGE 4	O	E	
	ROOM E210	O	E	
	ROOM E211	O	W	
	BOY'S RESTROOM 2	O	W	
	GIRL'S RESTROOM 2	O	E	
	CORRIDOR 2	O	E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM F100	W	N, E, W, S	S
	CLASSROOM F101	W	N, E, W, S	
	CLASSROOM F102	W	N, E, W, S	
	CLASSROOM F103	W	N, E, W, S	
	CLASSROOM F104	W	N, E, W, S	
	CLASSROOM F105	W	N, E, W, S	
	CLASSROOM F106	W	N, E, W, S	
	CLASSROOM F107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM F108	W	N, E, W, S	
	CLASSROOM F109	W	N, W, S	
	CLASSROOM F110	W	N, E, S	
	CLASSROOM F200	W	N, E, W, S	
	CLASSROOM F201	W	N, E, W, S	
	CLASSROOM F202	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F203	W	N, E, W, S	
	CLASSROOM F204	W	N, E, W, S	
	CLASSROOM F205	W	N, E, W, S	
	CLASSROOM F206	W	N, E, W, S	
	CLASSROOM F207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM F208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM F100	W	N, E, W, S	S
	CLASSROOM F101	W	N, E, W, S	
	CLASSROOM F102	W	N, E, W, S	
	CLASSROOM F103	W	N, E, W, S	
	CLASSROOM F104	W	N, E, W, S	
	CLASSROOM F105	W	N, E, W, S	
	CLASSROOM F106	W	N, E, W, S	
	CLASSROOM F107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM F108	W	N, E, W, S	
	CLASSROOM F109	W	N, W, S	
	CLASSROOM F110	W	N, E, S	
	CLASSROOM F200	W	N, E, W, S	
	CLASSROOM F201	W	N, E, W, S	
	CLASSROOM F202	W	N, E, W, S	
	CLASSROOM F203	W	N, E, W, S	
	CLASSROOM F204	W	N, E, W, S	
	CLASSROOM F205	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F206	W	N, E, W, S	
	CLASSROOM F207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM F208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM F100	W	N, E, W, S	S
	CLASSROOM F101	W	N, E, W, S	
	CLASSROOM F102	W	N, E, W, S	
	CLASSROOM F103	W	N, E, W, S	
	CLASSROOM F104	W	N, E, W, S	
	CLASSROOM F105	W	N, E, W, S	
	CLASSROOM F106	W	N, E, W, S	
	CLASSROOM F107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM F108	W	N, E, W, S	
	CLASSROOM F109	W	N, W, S	
	CLASSROOM F110	W	N, E, S	
	CLASSROOM F200	W	N, E, W, S	
	CLASSROOM F201	W	N, E, W, S	
	CLASSROOM F202	W	N, E, W, S	
	CLASSROOM F203	W	N, E, W, S	
	CLASSROOM F204	W	N, E, W, S	
	CLASSROOM F205	W	N, E, W, S	
	CLASSROOM F206	W	N, E, W, S	
	CLASSROOM F207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STORAGE 3	W	N, E, W, S	
	WORK ROOM F208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM F100	C	*	S
	CLASSROOM F101	C	*	
	CLASSROOM F102	C	*	
	CLASSROOM F103	C	*	
	CLASSROOM F104	C	*	
	CLASSROOM F105	C	*	
	CLASSROOM F106	C	*	
	CLASSROOM F107	C	*	
	STORAGE 1	C	*	
	CLASSROOM F108	C	*	
	CLASSROOM F109	C	*	
	CLASSROOM F110	C	*	
	CLASSROOM F200	C	*	
	CLASSROOM F201	C	*	
	CLASSROOM F202	C	*	
	CLASSROOM F203	C	*	
	CLASSROOM F204	C	*	
	CLASSROOM F205	C	*	
	CLASSROOM F206	C	*	
	CLASSROOM F207	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	WORK ROOM F208	C	*	
	STORAGE 4	C	*	
SINK ACOUSTICAL COATING, GRAY, ROUGH	CLASSROOM F100	O	S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F101	O	N	
	CLASSROOM F102	O	S	
	CLASSROOM F103	O	N	
	CLASSROOM F104	O	S	
	CLASSROOM F105	O	N	
	CLASSROOM F108	O	W	
	CLASSROOM F110	O	W	
	CLASSROOM F200	O	S	
	CLASSROOM F201	O	N	
	CLASSROOM F202	O	S	
	CLASSROOM F203	O	N	
	CLASSROOM F204	O	S	
	CLASSROOM F205	O	N	
	WORK ROOM F208	O	N	
VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK SPECKS	CLASSROOM F100	F	*	S
	CLASSROOM F101	F	*	
	CLASSROOM F102	F	*	
	CLASSROOM F103	F	*	
	CLASSROOM F104	F	*	
	CLASSROOM F105	F	*	
	CLASSROOM F106	F	*	
	CLASSROOM F107	F	*	
	CLASSROOM F109	F	*	
	CLASSROOM F110	F	*	
	CLASSROOM F200	F	*	
	CLASSROOM F201	F	*	
	CLASSROOM F202	F	*	
	CLASSROOM F203	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F204	F	*	
	CLASSROOM F205	F	*	
	CLASSROOM F206	F	*	
	CLASSROOM F207	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM F109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM F109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	ROOM F109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	ROOM F109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	ROOM F109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	ROOM F109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	ROOM F109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	ROOM F109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH	ROOM F109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	ROOM F109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	ROOM F109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM F100	W	N, W	S
	CLASSROOM F101	W	W, S	
	CLASSROOM F102	W	N, W	
	CLASSROOM F103	W	W, S	
	CLASSROOM F104	W	N, W	
	CLASSROOM F105	W	E, S	
	CLASSROOM F106	W	N, E, W, S	
	CLASSROOM F107	W	N, E, W, S	
	CLASSROOM F200	W	N, W	
	CLASSROOM F201	W	W, S	
	CLASSROOM F202	W	N, W	
	CLASSROOM F203	W	W, S	
	CLASSROOM F204	W	N, W	
	CLASSROOM F205	W	E, S	
	CLASSROOM F206	W	N, E, W	
	CLASSROOM F207	W	E, W, S	
SEALANT (DOORS, WINDOWS), BLACK, TAR-LIKE	CORRIDOR 1	O	E, W	S
	CORRIDOR 2	O	E, W	
SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	ROOM E110	C	*	S
	ROOM E111	C	*	
	ROOM E210	C	*	
	ROOM E211	C	*	
SEALANT (FIRE STOP), GREEN, PLIABLE	CLASSROOM F100	O	*	S
	CLASSROOM F101	O	*	
	CLASSROOM F102	O	*	
	CLASSROOM F103	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM F104	O	*	
	CLASSROOM F105	O	*	
	CLASSROOM F106	O	*	
	CLASSROOM F107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	ELEVATOR	O	*	
	MECHANICAL 3	O	*	
	CLASSROOM F108	O	*	
	CLASSROOM F109	O	*	
	ROOM F109 RESTROOM	O	*	
	CLASSROOM F110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM F200	O	*	
	CLASSROOM F201	O	*	
	CLASSROOM F202	O	*	
	CLASSROOM F203	O	*	
	CLASSROOM F204	O	*	
	CLASSROOM F205	O	*	
	CLASSROOM F206	O	*	
	CLASSROOM F207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM F208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	ROOM E111	O	S	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	ROOM E111	O	S	S
VINYL STAIR TREAD, 12"X60", GRAY, VINYL-LIKE, CIRCLE PATTERN	STAIRWELL	F	*	S
MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X60", GRAY, VINYL-LIKE, CIRCLE PATTERN	STAIRWELL	F	*	S
VINYL COMPOSITION TILE, 24"X24", GRAY, SMOOTH	STAIRWELL	F	*	S
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, SMOOTH	STAIRWELL	F	*	S
PIPE END SEALANT, WHITE, PLIABLE	CLASSROOM F100	O	*	S
	CLASSROOM F101	O	*	
	CLASSROOM F102	O	*	
	CLASSROOM F103	O	*	
	CLASSROOM F104	O	*	
	CLASSROOM F105	O	*	
	CLASSROOM F106	O	*	
	CLASSROOM F107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	ELEVATOR	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MECHANICAL 3	O	*	
	CLASSROOM F108	O	*	
	CLASSROOM F109	O	*	
	ROOM F109 RESTROOM	O	*	
	CLASSROOM F110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM F200	O	*	
	CLASSROOM F201	O	*	
	CLASSROOM F202	O	*	
	CLASSROOM F203	O	*	
	CLASSROOM F204	O	*	
	CLASSROOM F205	O	*	
	CLASSROOM F206	O	*	
	CLASSROOM F207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM F208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building F

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	MECHANICAL 3	W	N	S
GASKET, 4", BLACK, RUBBER-LIKE	MECHANICAL 3	W	N	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

**TABLE A
BUILDING MATERIAL SYSTEMS**

<i>MATERIAL DESCRIPTION</i>	<i>MATERIAL LOCATION</i>	<i>MATERIAL COMPONENT</i>	<i>COMPONENT LOCATION</i>	<i>ACM N/S</i>
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF	O	*	S
SEALANT (FLASHING), GRAY, PLIABLE	ROOF	O	*	S
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	CLASSROOM G100	O	*	S
	CLASSROOM G101	O	*	
	CLASSROOM G102	O	*	
	CLASSROOM G103	O	*	
	CLASSROOM G104	O	*	
	CLASSROOM G105	O	*	
	CLASSROOM G106	O	*	
	CLASSROOM G107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM G108	O	*	
	CLASSROOM G109	O	*	
	ROOM G109 RESTROOM	O	*	
	TEST	O	*	
	CLASSROOM G110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM G200	O	*	
	CLASSROOM G201	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G202	O	*	
	CLASSROOM G203	O	*	
	CLASSROOM G204	O	*	
	CLASSROOM G205	O	*	
	CLASSROOM G206	O	*	
	CLASSROOM G207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM G208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
SEALANT (DUCT), GRAY, PLIABLE	CLASSROOM G100	O	*	S
	CLASSROOM G101	O	*	
	CLASSROOM G102	O	*	
	CLASSROOM G103	O	*	
	CLASSROOM G104	O	*	
	CLASSROOM G105	O	*	
	CLASSROOM G106	O	*	
	CLASSROOM G107	O	*	
	STORAGE 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MECHANICAL 1	O	*	
	CLASSROOM G108	O	*	
	CLASSROOM G109	O	*	
	ROOM G109 RESTROOM	O	*	
	TEST	O	*	
	CLASSROOM G110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM G200	O	*	
	CLASSROOM G201	O	*	
	CLASSROOM G202	O	*	
	CLASSROOM G203	O	*	
	CLASSROOM G204	O	*	
	CLASSROOM G205	O	*	
	CLASSROOM G206	O	*	
	CLASSROOM G207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM G208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
SEALANT (DUCT), PINK, PLIABLE	CLASSROOM G100	O	*	S
	CLASSROOM G101	O	*	
	CLASSROOM G102	O	*	
	CLASSROOM G103	O	*	
	CLASSROOM G104	O	*	
	CLASSROOM G105	O	*	
	CLASSROOM G106	O	*	
	CLASSROOM G107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM G108	O	*	
	CLASSROOM G109	O	*	
	ROOM G109 RESTROOM	O	*	
	TEST	O	*	
	CLASSROOM G110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM G200	O	*	
	CLASSROOM G201	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G202	O	*	
	CLASSROOM G203	O	*	
	CLASSROOM G204	O	*	
	CLASSROOM G205	O	*	
	CLASSROOM G206	O	*	
	CLASSROOM G207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM G208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
BRICK, 4"x16", RED, CEMENTITIOUS	CORRIDOR 1	W	N, E, W, S	S
	CORRIDOR 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
CONCRETE MASONRY UNIT, 4"x16", GRAY, CEMENTITIOUS, TAN	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"x16", GRAY, CEMENTITIOUS, ROUGH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"x16", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"x8", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	CORRIDOR 1	W	N, E, W, S	S
	CORRIDOR 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
SEALANT (DOORS, MILLWORK, WALLS), WHITE, PLIABLE	CLASSROOM G100	O	N, E, W, S	S
	CLASSROOM G101	O	N, E, W, S	
	CLASSROOM G102	O	W, S	
	CLASSROOM G103	O	N, W	
	CLASSROOM G104	O	E, W, S	
	CLASSROOM G105	O	N, E, W, S	
	CLASSROOM G106	O	N, E, W, S	
	CLASSROOM G107	O	N, E, W, S	
	STORAGE 1	O	N, S	
	CLASSROOM G108	O	N	
	CLASSROOM G109	O	N, S	
	ROOM G109 RESTROOM	O	N, W	
	CLASSROOM G110	O	N	
	ROOM E110	O	E	
	ROOM E111	O	W	
	BOY'S RESTROOM 1	O	E	
	GIRL'S RESTROOM 1	O	W	
	CORRIDOR 1	O	E, W	
	CLASSROOM G200	O	N, W	
	CLASSROOM G201	O	W, S	
	CLASSROOM G202	O	N, W	
	CLASSROOM G203	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G204	O	E, W, S	
	CLASSROOM G205	O	E, W, S	
	CLASSROOM G206	O	E, W, S	
	CLASSROOM G207	O	N, E, W, S	
	STORAGE 2	O	N, S	
	MECHANICAL 2	O	S	
	STORAGE 3	O	W	
	WORK ROOM G208	O	N, E, W, S	
	STORAGE 4	O	E	
	ROOM E210	O	E	
	ROOM E211	O	W	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	*	
SEALANT (DOORS, WALLS, FLASHING), BROWN, PLIABLE	CORRIDOR 1	O	N, E, W, S	S
	CORRIDOR 2	O	N, E, W, S	
	EXTERIOR	O	E, W	
SEALANT (WALLS), GRAY, PLIABLE	EXTERIOR	O	N, E, W, S	S
GLASS BLOCK, 8"X8", CLEAR	CORRIDOR 1	W	E, W	N
	CORRIDOR 2	W	E, W	
	EXTERIOR	W	E, W	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	CORRIDOR 1	W	E, W	S
	CORRIDOR 2	W	E, W	
	EXTERIOR	W	E, W	
GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	EXTERIOR	W	N, E, W, S	S
GROUT, BROWN, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	EXTERIOR	W	N, E, W, S	S
TROWELED-ON TEXTURE, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CLASSROOM G100	F	*	S
	CLASSROOM G101	F	*	
	CLASSROOM G102	F	*	
	CLASSROOM G103	F	*	
	CLASSROOM G104	F	*	
	CLASSROOM G105	F	*	
	CLASSROOM G106	F	*	
	CLASSROOM G107	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	STORAGE 1	F	*	
	MECHANICAL 1	F	*	
	CLASSROOM G108	F	*	
	CLASSROOM G109	F	*	
	ROOM G109 RESTROOM	F	*	
	TEST	F	*	
	CLASSROOM G110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAIRWELL	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM G200	F	*	
	CLASSROOM G201	F	*	
	CLASSROOM G202	F	*	
	CLASSROOM G203	F	*	
	CLASSROOM G204	F	*	
	CLASSROOM G205	F	*	
	CLASSROOM G206	F	*	
	CLASSROOM G207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STORAGE 3	F	*	
	WORK ROOM G208	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	STORAGE 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ROOM E210	F	*	
	ROOM E211	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
	CORRIDOR 2	F	*	
	EXTERIOR	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CORRIDOR 1	C	*	S
	CORRIDOR 2	C	*	
GYPSON WALLBOARD, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	CLASSROOM G100	F	*	S
	CLASSROOM G101	F	*	
	CLASSROOM G102	F	*	
	CLASSROOM G103	F	*	
	CLASSROOM G104	F	*	
	CLASSROOM G105	F	*	
	CLASSROOM G106	F	*	
	CLASSROOM G107	F	*	
	CLASSROOM G108	F	*	
	CLASSROOM G109	F	*	
	CLASSROOM G110	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM G200	F	*	
	CLASSROOM G201	F	*	
	CLASSROOM G202	F	*	
	CLASSROOM G203	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G204	F	*	
	CLASSROOM G205	F	*	
	CLASSROOM G206	F	*	
	CLASSROOM G207	F	*	
	WORK ROOM G208	F	*	
	CORRIDOR 2	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	CLASSROOM G101	F	*	S
	CLASSROOM G102	F	*	
	CLASSROOM G103	F	*	
	CLASSROOM G104	F	*	
	CLASSROOM G105	F	*	
	CLASSROOM G106	F	*	
	CLASSROOM G107	F	*	
	STORAGE 1	F	*	
	ROOM G109 RESTROOM	F	*	
	TEST	F	*	
	CLASSROOM G110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM G200	F	*	
	CLASSROOM G201	F	*	
	CLASSROOM G202	F	*	
	CLASSROOM G203	F	*	
	CLASSROOM G204	F	*	
	CLASSROOM G205	F	*	
	CLASSROOM G206	F	*	
	CLASSROOM G207	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	CORRIDOR 2	F	*	
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", BLUE, SMOOTH, BLACK SPECKS	CLASSROOM G100	F	*	S
	CLASSROOM G101	F	*	
	CLASSROOM G102	F	*	
	CLASSROOM G103	F	*	
	CLASSROOM G104	F	*	
	CLASSROOM G105	F	*	
	CLASSROOM G106	F	*	
	CLASSROOM G107	F	*	
	STORAGE 1	F	*	
	ROOM G109 RESTROOM	F	*	
	TEST	F	*	
	CLASSROOM G110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM G200	F	*	
	CLASSROOM G201	F	*	
	CLASSROOM G202	F	*	
	CLASSROOM G203	F	*	
	CLASSROOM G204	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G205	F	*	
	CLASSROOM G206	F	*	
	CLASSROOM G207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	CORRIDOR 2	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	CLASSROOM G100	O	N, E, W, S	S
	CLASSROOM G101	O	N, E, W, S	
	CLASSROOM G102	O	N, E, W, S	
	CLASSROOM G103	O	N, E, W, S	
	CLASSROOM G104	O	N, E, W, S	
	CLASSROOM G105	O	N, E, W, S	
	CLASSROOM G106	O	N, E, W, S	
	CLASSROOM G107	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CLASSROOM G108	O	N, E, W, S	
	CLASSROOM G109	O	N, S	
	ROOM G109 RESTROOM	O	N, W, S	
	CLASSROOM G110	O	N, E, W, S	
	ROOM E110	O	N, E, W, S	
	ROOM E111	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM G200	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	CLASSROOM G201	O	N, E, W, S	
	CLASSROOM G202	O	N, E, W, S	
	CLASSROOM G203	O	N, E, W, S	
	CLASSROOM G204	O	N, E, W, S	
	CLASSROOM G205	O	N, E, W, S	
	CLASSROOM G206	O	N, E, W, S	
	CLASSROOM G207	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	MECHANICAL 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	WORK ROOM G208	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ROOM E210	O	N, E, W, S	
	ROOM E211	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	CLASSROOM G100	O	N, E, W, S	S
	CLASSROOM G101	O	N, E, W, S	
	CLASSROOM G102	O	N, E, W, S	
	CLASSROOM G103	O	N, E, W, S	
	CLASSROOM G104	O	N, E, W, S	
	CLASSROOM G105	O	N, E, W, S	
	CLASSROOM G106	O	N, E, W, S	
	CLASSROOM G107	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CLASSROOM G108	O	N, E, W, S	
	CLASSROOM G109	O	N, S	
	ROOM G109 RESTROOM	O	N, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G110	O	N, E, W, S	
	ROOM E110	O	N, E, W, S	
	ROOM E111	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM G200	O	N, E, W, S	
	CLASSROOM G201	O	N, E, W, S	
	CLASSROOM G202	O	N, E, W, S	
	CLASSROOM G203	O	N, E, W, S	
	CLASSROOM G204	O	N, E, W, S	
	CLASSROOM G205	O	N, E, W, S	
	CLASSROOM G206	O	N, E, W, S	
	CLASSROOM G207	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	MECHANICAL 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	WORK ROOM G208	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ROOM E210	O	N, E, W, S	
	ROOM E211	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CLASSROOM G100	O	N, W	S
	CLASSROOM G101	O	W, S	
	CLASSROOM G102	O	W	
	CLASSROOM G103	O	N, W	
	CLASSROOM G104	O	W, S	
	CLASSROOM G105	O	E, S	
	CLASSROOM G106	O	N, E, S	
	CLASSROOM G107	O	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STORAGE 1	O	N, S	
	MECHANICAL 1	O	W	
	CLASSROOM G108	O	N	
	CLASSROOM G109	O	N, S	
	ROOM G109 RESTROOM	O	N	
	CLASSROOM G110	O	N	
	ROOM E110	O	E	
	ROOM E111	O	W	
	BOY'S RESTROOM 1	O	W	
	GIRL'S RESTROOM 1	O	E	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM G200	O	N, W	
	CLASSROOM G201	O	W, S	
	CLASSROOM G202	O	N, W	
	CLASSROOM G203	O	N, W, S	
	CLASSROOM G204	O	W, S	
	CLASSROOM G205	O	E, S	
	CLASSROOM G206	O	N, E, S	
	CLASSROOM G207	O	N, E, S	
	STORAGE 2	O	N, S	
	MECHANICAL 2	O	S	
	STAFF MEN'S RESTROOM	O	N	
	STORAGE 3	O	W	
	WORK ROOM G208	O	N, E, W	
	STAFF WOMEN'S RESTROOM	O	N	
	STORAGE 4	O	E	
	ROOM E210	O	E	
	ROOM E211	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BOY'S RESTROOM 2	O	W	
	GIRL'S RESTROOM 2	O	E	
	CORRIDOR 2	O	E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM G100	W	N, E, W, S	S
	CLASSROOM G101	W	N, E, W, S	
	CLASSROOM G102	W	N, E, W, S	
	CLASSROOM G103	W	N, E, W, S	
	CLASSROOM G104	W	N, E, W, S	
	CLASSROOM G105	W	N, E, W, S	
	CLASSROOM G106	W	N, E, W, S	
	CLASSROOM G107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM G108	W	N, E, W, S	
	CLASSROOM G109	W	N, E, S	
	TEST	C, W	N, E, W, S	
	CLASSROOM G110	W	N, W, S	
	CLASSROOM G200	W	N, E, W, S	
	CLASSROOM G201	W	N, E, W, S	
	CLASSROOM G202	W	N, E, W, S	
	CLASSROOM G203	W	N, E, W, S	
	CLASSROOM G204	W	N, E, W, S	
	CLASSROOM G205	W	N, E, W, S	
	CLASSROOM G206	W	N, E, W, S	
	CLASSROOM G207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WORK ROOM G208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM G100	W	N, E, W, S	S
	CLASSROOM G101	W	N, E, W, S	
	CLASSROOM G102	W	N, E, W, S	
	CLASSROOM G103	W	N, E, W, S	
	CLASSROOM G104	W	N, E, W, S	
	CLASSROOM G105	W	N, E, W, S	
	CLASSROOM G106	W	N, E, W, S	
	CLASSROOM G107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM G108	W	N, E, W, S	
	CLASSROOM G109	W	N, E, S	
	TEST	C, W	N, E, W, S	
	CLASSROOM G110	W	N, W, S	
	CLASSROOM G200	W	N, E, W, S	
	CLASSROOM G201	W	N, E, W, S	
	CLASSROOM G202	W	N, E, W, S	
	CLASSROOM G203	W	N, E, W, S	
	CLASSROOM G204	W	N, E, W, S	
	CLASSROOM G205	W	N, E, W, S	
	CLASSROOM G206	W	N, E, W, S	
	CLASSROOM G207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM G208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM G100	W	N, E, W, S	S
	CLASSROOM G101	W	N, E, W, S	
	CLASSROOM G102	W	N, E, W, S	
	CLASSROOM G103	W	N, E, W, S	
	CLASSROOM G104	W	N, E, W, S	
	CLASSROOM G105	W	N, E, W, S	
	CLASSROOM G106	W	N, E, W, S	
	CLASSROOM G107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM G108	W	N, E, W, S	
	CLASSROOM G109	W	N, E, S	
	TEST	C, W	N, E, W, S	
	CLASSROOM G110	W	N, W, S	
	CLASSROOM G200	W	N, E, W, S	
	CLASSROOM G201	W	N, E, W, S	
	CLASSROOM G202	W	N, E, W, S	
	CLASSROOM G203	W	N, E, W, S	
	CLASSROOM G204	W	N, E, W, S	
	CLASSROOM G205	W	N, E, W, S	
	CLASSROOM G206	W	N, E, W, S	
	CLASSROOM G207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM G208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM G100	C	*	S
	CLASSROOM G101	C	*	
	CLASSROOM G102	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G103	C	*	
	CLASSROOM G104	C	*	
	CLASSROOM G105	C	*	
	CLASSROOM G106	C	*	
	CLASSROOM G107	C	*	
	STORAGE 1	C	*	
	CLASSROOM G108	C	*	
	CLASSROOM G109	C	*	
	CLASSROOM G110	C	*	
	CLASSROOM G200	C	*	
	CLASSROOM G201	C	*	
	CLASSROOM G202	C	*	
	CLASSROOM G203	C	*	
	CLASSROOM G204	C	*	
	CLASSROOM G205	C	*	
	CLASSROOM G206	C	*	
	CLASSROOM G207	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	WORK ROOM G208	C	*	
	STORAGE 4	C	*	
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM G100	O	S	S
	CLASSROOM G101	O	N	
	CLASSROOM G102	O	S	
	CLASSROOM G103	O	N	
	CLASSROOM G104	O	S	
	CLASSROOM G105	O	N	
	CLASSROOM G108	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM G110	O	E	
	CLASSROOM G200	O	S	
	CLASSROOM G201	O	N	
	CLASSROOM G202	O	S	
	CLASSROOM G203	O	N	
	CLASSROOM G204	O	S	
	CLASSROOM G205	O	N	
	WORK ROOM G208	O	N	
VINYL COMPOSITION TILE, 12"X12", BLUE, SMOOTH, BLACK SPECKS	CLASSROOM G100	F	*	S
	CLASSROOM G101	F	*	
	CLASSROOM G102	F	*	
	CLASSROOM G103	F	*	
	CLASSROOM G104	F	*	
	CLASSROOM G105	F	*	
	CLASSROOM G106	F	*	
	CLASSROOM G107	F	*	
	CLASSROOM G200	F	*	
	CLASSROOM G201	F	*	
	CLASSROOM G202	F	*	
	CLASSROOM G203	F	*	
	CLASSROOM G204	F	*	
	CLASSROOM G205	F	*	
	CLASSROOM G206	F	*	
	CLASSROOM G207	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM G109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM G109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ROOM G109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	ROOM G109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	ROOM G109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building G*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	ROOM G109 RESTROOM	W	N, E, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	ROOM G109 RESTROOM	W	N, E, W, S	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	ROOM G109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH	ROOM G109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	ROOM G109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	ROOM G109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM G100	W	N, W	S
	CLASSROOM G101	W	W, S	
	CLASSROOM G102	W	N, W	
	CLASSROOM G103	W	W, S	
	CLASSROOM G104	W	N, W	
	CLASSROOM G105	W	E, S	
	CLASSROOM G106	W	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM G107	W	N, E, W, S	
	CLASSROOM G200	W	N, W	
	CLASSROOM G201	W	W, S	
	CLASSROOM G202	W	N, W	
	CLASSROOM G203	W	W, S	
	CLASSROOM G204	W	N, W	
	CLASSROOM G205	W	E, S	
	CLASSROOM G206	W	N, E, W	
	CLASSROOM G207	W	E, W, S	
SEALANT (DOORS, WINDOWS), BLACK, TAR-LIKE	CORRIDOR 1	O	E, W	S
	CORRIDOR 2	O	E, W	
SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	ROOM E110	O	*	S
	ROOM E111	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
SEALANT (FIRE STOP), GREEN, PLIABLE	CLASSROOM G100	O	*	S
	CLASSROOM G101	O	*	
	CLASSROOM G102	O	*	
	CLASSROOM G103	O	*	
	CLASSROOM G104	O	*	
	CLASSROOM G105	O	*	
	CLASSROOM G106	O	*	
	CLASSROOM G107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM G108	O	*	
	CLASSROOM G109	O	*	
	ROOM G109 RESTROOM	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	TEST	O	*	
	CLASSROOM G110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM G200	O	*	
	CLASSROOM G201	O	*	
	CLASSROOM G202	O	*	
	CLASSROOM G203	O	*	
	CLASSROOM G204	O	*	
	CLASSROOM G205	O	*	
	CLASSROOM G206	O	*	
	CLASSROOM G207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM G208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	ROOM E111	O	S	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	ROOM E111	O	S	S
VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	STAIRWELL	F	*	S
MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	STAIRWELL	F	*	S
VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	STAIRWELL	F	*	S
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	STAIRWELL	F	*	S
PIPE END SEALANT, WHITE, PLIABLE	CLASSROOM G100	O	*	S
	CLASSROOM G101	O	*	
	CLASSROOM G102	O	*	
	CLASSROOM G103	O	*	
	CLASSROOM G104	O	*	
	CLASSROOM G105	O	*	
	CLASSROOM G106	O	*	
	CLASSROOM G107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	ELEVATOR	O	*	
	MECHANICAL 3	O	*	
	CLASSROOM G108	O	*	
	CLASSROOM G109	O	*	
	ROOM G109 RESTROOM	O	*	
	TEST	O	*	
	CLASSROOM G110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building G

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM G200	O	*	
	CLASSROOM G201	O	*	
	CLASSROOM G202	O	*	
	CLASSROOM G203	O	*	
	CLASSROOM G204	O	*	
	CLASSROOM G205	O	*	
	CLASSROOM G206	O	*	
	CLASSROOM G207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM G208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	

* - *Not Applicable*

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

TABLE A
BUILDING MATERIAL SYSTEMS

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF	O	*	S
SEALANT (FLASHING), GRAY, PLIABLE	ROOF	O	*	S
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	CLASSROOM H100	O	*	S
	CLASSROOM H101	O	*	
	CLASSROOM H102	O	*	
	CLASSROOM H103	O	*	
	CLASSROOM H104	O	*	
	CLASSROOM H105	O	*	
	CLASSROOM H106	O	*	
	CLASSROOM H107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM H108	O	*	
	CLASSROOM H109	O	*	
	ROOM H109 RESTROOM	O	*	
	CLASSROOM H110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM H200	O	*	
	CLASSROOM H201	O	*	
	CLASSROOM H202	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H203	O	*	
	CLASSROOM H204	O	*	
	CLASSROOM H205	O	*	
	CLASSROOM H206	O	*	
	CLASSROOM H207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM H208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
SEALANT (DUCT), GRAY, PLIABLE	CLASSROOM H100	O	*	S
	CLASSROOM H101	O	*	
	CLASSROOM H102	O	*	
	CLASSROOM H103	O	*	
	CLASSROOM H104	O	*	
	CLASSROOM H105	O	*	
	CLASSROOM H106	O	*	
	CLASSROOM H107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H108	O	*	
	CLASSROOM H109	O	*	
	ROOM H109 RESTROOM	O	*	
	CLASSROOM H110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM H200	O	*	
	CLASSROOM H201	O	*	
	CLASSROOM H202	O	*	
	CLASSROOM H203	O	*	
	CLASSROOM H204	O	*	
	CLASSROOM H205	O	*	
	CLASSROOM H206	O	*	
	CLASSROOM H207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM H208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
SEALANT (DUCT), PINK, PLIABLE	CLASSROOM H100	O	*	S
	CLASSROOM H101	O	*	
	CLASSROOM H102	O	*	
	CLASSROOM H103	O	*	
	CLASSROOM H104	O	*	
	CLASSROOM H105	O	*	
	CLASSROOM H106	O	*	
	CLASSROOM H107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM H108	O	*	
	CLASSROOM H109	O	*	
	ROOM H109 RESTROOM	O	*	
	CLASSROOM H110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM H200	O	*	
	CLASSROOM H201	O	*	
	CLASSROOM H202	O	*	
	CLASSROOM H203	O	*	
	CLASSROOM H204	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H205	O	*	
	CLASSROOM H206	O	*	
	CLASSROOM H207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM H208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
	ROOF	O	*	
CONCRETE MASONRY UNIT, 4"X16", RED, CEMENTITIOUS	CORRIDOR 1	W	N, E, W, S	S
	CORRIDOR 2	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	EXTERIOR	W	N, E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	MECHANICAL 3	W	N	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
	EXTERIOR	C/W/F/O W	N/E/W/S N, E, W, S	N/S
SEALANT (DOORS, WINDOWS, MILLWORK, WALLS), WHITE, PLIABLE	CLASSROOM H100	O	N, E, W, S	S
	CLASSROOM H101	O	N, E, W, S	
	CLASSROOM H102	O	E, W, S	
	CLASSROOM H103	O	E, W, S	
	CLASSROOM H104	O	N, E, S	
	CLASSROOM H105	O	N, E, W, S	
	CLASSROOM H106	O	N, E, W, S	
	CLASSROOM H107	O	N, E, W, S	
	STORAGE 1	O	E, W	
	CLASSROOM H108	O	W, S	
	CLASSROOM H109	O	E, W	
	ROOM H109 RESTROOM	O	W, S	
	CLASSROOM H110	O	N, W	
	ROOM E110	O	N	
	ROOM E111	O	S	
	BOY'S RESTROOM 1	O	N	
	GIRL'S RESTROOM 1	O	S	
	CORRIDOR 1	O	N, S	
	CLASSROOM H200	O	E, S	
	CLASSROOM H201	O	E, W, S	
	CLASSROOM H202	O	E, S	
	CLASSROOM H203	O	E, W, S	
	CLASSROOM H204	O	N, E, S	
	CLASSROOM H205	O	N, E, S	
	CLASSROOM H206	O	N, E, W, S	
	CLASSROOM H207	O	N, E, W, S	
	STORAGE 2	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MECHANICAL 2	O	E	
	STAFF MEN'S RESTROOM	O	S	
	STORAGE 3	O	S	
	WORK ROOM H208	O	N, E, W, S	
	STAFF WOMEN'S RESTROOM	O	N	
	STORAGE 4	O	N	
	ROOM E210	O	N	
	ROOM E211	O	S	
	BOY'S RESTROOM 2	O	N	
	GIRL'S RESTROOM 2	O	S	
	CORRIDOR 2	O	N, S	
	EXTERIOR	O	N, E, W, S	
	ROOF	O	*	
SEALANT (WALLS), BROWN, PLIABLE	CORRIDOR 1	O	N, E, W, S	S
	CORRIDOR 2	O	N, E, W, S	
	EXTERIOR	O	N, S	
SEALANT (WALLS), GRAY, PLIABLE	EXTERIOR	O	N, E, W, S	S
GLASS BLOCK, 8"X8", CLEAR	CORRIDOR 1	W	N, S	N
	CORRIDOR 2	W	N, S	
	EXTERIOR	W	N, S	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	CORRIDOR 1	W	N, S	S
	CORRIDOR 2	W	N, S	
	EXTERIOR	W	N, S	
GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	EXTERIOR	W	N, E, W, S	S
GROUT, BROWN, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	EXTERIOR	W	N, E, W, S	S
TROWELED-ON TEXTURE, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MECHANICAL 1	W	N, E, W, S	S
	ROOM E110	W	N, E, W, S	
	ROOM E111	W	N, E, W, S	
	MECHANICAL 2	W	N, E, W, S	
	ROOM E210	W	N, E, W, S	
	ROOM E211	W	N, E, W, S	
	EXTERIOR	C	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	CLASSROOM H100	F	*	S
	CLASSROOM H101	F	*	
	CLASSROOM H102	F	*	
	CLASSROOM H103	F	*	
	CLASSROOM H104	F	*	
	CLASSROOM H105	F	*	
	CLASSROOM H106	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H107	F	*	
	STORAGE 1	F	*	
	MECHANICAL 1	F	*	
	CLASSROOM H108	F	*	
	CLASSROOM H109	F	*	
	ROOM H109 RESTROOM	F	*	
	CLASSROOM H110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAIRWELL	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM H200	F	*	
	CLASSROOM H201	F	*	
	CLASSROOM H202	F	*	
	CLASSROOM H203	F	*	
	CLASSROOM H204	F	*	
	CLASSROOM H205	F	*	
	CLASSROOM H206	F	*	
	CLASSROOM H207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STORAGE 3	F	*	
	WORK ROOM H208	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	STORAGE 4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ROOM E210	F	*	
	ROOM E211	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
	CORRIDOR 2	F	*	
	EXTERIOR	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	CORRIDOR 1	C	*	S
	CORRIDOR 2	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	CLASSROOM H100	F	*	S
	CLASSROOM H101	F	*	
	CLASSROOM H102	F	*	
	CLASSROOM H103	F	*	
	CLASSROOM H104	F	*	
	CLASSROOM H105	F	*	
	CLASSROOM H106	F	*	
	CLASSROOM H107	F	*	
	CLASSROOM H108	F	*	
	CLASSROOM H109	F	*	
	CLASSROOM H110	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM H200	F	*	
	CLASSROOM H201	F	*	
	CLASSROOM H202	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	CLASSROOM H203	F	*	
	CLASSROOM H204	F	*	
	CLASSROOM H205	F	*	
	CLASSROOM H206	F	*	
	CLASSROOM H207	F	*	
	WORK ROOM H208	F	*	
	CORRIDOR 2	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	CLASSROOM H100	F	*	S
	CLASSROOM H101	F	*	
	CLASSROOM H102	F	*	
	CLASSROOM H103	F	*	
	CLASSROOM H104	F	*	
	CLASSROOM H105	F	*	
	CLASSROOM H106	F	*	
	CLASSROOM H107	F	*	
	STORAGE 1	F	*	
	CLASSROOM H109	F	*	
	ROOM H109 RESTROOM	F	*	
	CLASSROOM H110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM H200	F	*	
	CLASSROOM H201	F	*	
	CLASSROOM H202	F	*	
	CLASSROOM H203	F	*	
	CLASSROOM H204	F	*	
	CLASSROOM H205	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	CORRIDOR 2	F	*	
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	CLASSROOM H100	F	*	S
	CLASSROOM H101	F	*	
	CLASSROOM H102	F	*	
	CLASSROOM H103	F	*	
	CLASSROOM H104	F	*	
	CLASSROOM H105	F	*	
	CLASSROOM H106	F	*	
	CLASSROOM H107	F	*	
	STORAGE 1	F	*	
	CLASSROOM H109	F	*	
	ROOM H109 RESTROOM	F	*	
	CLASSROOM H110	F	*	
	ROOM E110	F	*	
	ROOM E111	F	*	
	CORRIDOR 1	F	*	
	CLASSROOM H200	F	*	
	CLASSROOM H201	F	*	
	CLASSROOM H202	F	*	
	CLASSROOM H203	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H204	F	*	
	CLASSROOM H205	F	*	
	CLASSROOM H207	F	*	
	STORAGE 2	F	*	
	MECHANICAL 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ROOM E210	F	*	
	ROOM E211	F	*	
	CORRIDOR 2	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	CLASSROOM H100	O	N, E, W, S	S
	CLASSROOM H101	O	N, E, W, S	
	CLASSROOM H102	O	N, E, W, S	
	CLASSROOM H103	O	N, E, W, S	
	CLASSROOM H104	O	N, E, W, S	
	CLASSROOM H105	O	N, E, W, S	
	CLASSROOM H106	O	N, E, W, S	
	CLASSROOM H107	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CLASSROOM H108	O	N, E, W, S	
	CLASSROOM H109	O	E, W, S	
	ROOM H109 RESTROOM	O	E, W, S	
	CLASSROOM H110	O	N, E, W	
	ROOM E110	O	N, E, W, S	
	ROOM E111	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM H200	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H201	O	N, E, W, S	
	CLASSROOM H202	O	N, E, W, S	
	CLASSROOM H203	O	N, E, W, S	
	CLASSROOM H204	O	N, E, W, S	
	CLASSROOM H205	O	N, E, W, S	
	CLASSROOM H206	O	N, E, W, S	
	CLASSROOM H207	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	MECHANICAL 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ROOM E210	O	N, E, W, S	
	ROOM E211	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	CLASSROOM H100	O	N, E, W, S	S
	CLASSROOM H101	O	N, E, W, S	
	CLASSROOM H102	O	N, E, W, S	
	CLASSROOM H103	O	N, E, W, S	
	CLASSROOM H104	O	N, E, W, S	
	CLASSROOM H105	O	N, E, W, S	
	CLASSROOM H106	O	N, E, W, S	
	CLASSROOM H107	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	CLASSROOM H108	O	N, E, W, S	
	CLASSROOM H109	O	E, W, S	
	ROOM H109 RESTROOM	O	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H110	O	N, E, W	
	ROOM E110	O	N, E, W, S	
	ROOM E111	O	N, E, W, S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM H200	O	N, E, W, S	
	CLASSROOM H201	O	N, E, W, S	
	CLASSROOM H202	O	N, E, W, S	
	CLASSROOM H203	O	N, E, W, S	
	CLASSROOM H204	O	N, E, W, S	
	CLASSROOM H205	O	N, E, W, S	
	CLASSROOM H206	O	N, E, W, S	
	CLASSROOM H207	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	MECHANICAL 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ROOM E210	O	N, E, W, S	
	ROOM E211	O	N, E, W, S	
	CORRIDOR 2	O	N, E, W, S	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	CLASSROOM H100	O	W, S	S
	CLASSROOM H101	O	E, S	
	CLASSROOM H102	O	W, S	
	CLASSROOM H103	O	E, W, S	
	CLASSROOM H104	O	E, S	
	CLASSROOM H105	O	N, E	
	CLASSROOM H106	O	E, W, S	
	CLASSROOM H107	O	E, W, S	
	STORAGE 1	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H108	O	W	
	CLASSROOM H109	O	E, W	
	ROOM H109 RESTROOM	O	W	
	CLASSROOM H110	O	W	
	ROOM E110	O	N	
	ROOM E111	O	S	
	BOY'S RESTROOM 1	O	N	
	GIRL'S RESTROOM 1	O	S	
	CORRIDOR 1	O	N, E, W, S	
	CLASSROOM H200	O	W, S	
	CLASSROOM H201	O	E, S	
	CLASSROOM H202	O	W, S	
	CLASSROOM H203	O	E, W, S	
	CLASSROOM H204	O	E, S	
	CLASSROOM H205	O	N, E	
	CLASSROOM H206	O	E, W, S	
	CLASSROOM H207	O	E, W, S	
	STORAGE 2	O	E, W	
	MECHANICAL 2	O	E	
	STAFF MEN'S RESTROOM	O	E	
	STORAGE 3	O	S	
	WORK ROOM H208	O	N, W, S	
	STAFF WOMEN'S RESTROOM	O	W	
	STORAGE 4	O	N	
	ROOM E210	O	N	
	ROOM E211	O	S	
	BOY'S RESTROOM 2	O	S	
	GIRL'S RESTROOM 2	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR 2	O	E, W, S	
	EXTERIOR	O	N, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CORRIDOR 1	C, W	N, E, W, S	S
	CORRIDOR 2	C, W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM H100	W	N, E, W, S	S
	CLASSROOM H101	W	N, E, W, S	
	CLASSROOM H102	W	N, E, W, S	
	CLASSROOM H103	W	N, E, W, S	
	CLASSROOM H104	W	N, E, W, S	
	CLASSROOM H105	W	N, E, W, S	
	CLASSROOM H106	W	N, E, W, S	
	CLASSROOM H107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM H108	W	N, E, W, S	
	CLASSROOM H109	W	E, W, S	
	CLASSROOM H110	W	N, E, W	
	CLASSROOM H200	W	N, E, W, S	
	CLASSROOM H201	W	N, E, W, S	
	CLASSROOM H202	W	N, E, W, S	
	CLASSROOM H203	W	N, E, W, S	
	CLASSROOM H204	W	N, E, W, S	
	CLASSROOM H205	W	N, E, W, S	
	CLASSROOM H206	W	N, E, W, S	
	CLASSROOM H207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM H208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM H100	W	N, E, W, S	S
	CLASSROOM H101	W	N, E, W, S	
	CLASSROOM H102	W	N, E, W, S	
	CLASSROOM H103	W	N, E, W, S	
	CLASSROOM H104	W	N, E, W, S	
	CLASSROOM H105	W	N, E, W, S	
	CLASSROOM H106	W	N, E, W, S	
	CLASSROOM H107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM H108	W	N, E, W, S	
	CLASSROOM H109	W	E, W, S	
	CLASSROOM H110	W	N, E, W	
	CLASSROOM H200	W	N, E, W, S	
	CLASSROOM H201	W	N, E, W, S	
	CLASSROOM H202	W	N, E, W, S	
	CLASSROOM H203	W	N, E, W, S	
	CLASSROOM H204	W	N, E, W, S	
	CLASSROOM H205	W	N, E, W, S	
	CLASSROOM H206	W	N, E, W, S	
	CLASSROOM H207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM H208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM H100	W	N, E, W, S	S
	CLASSROOM H101	W	N, E, W, S	
	CLASSROOM H102	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
	CLASSROOM H103	C/W/F/O W	N/E/W/S N, E, W, S	N/S
	CLASSROOM H104	W	N, E, W, S	
	CLASSROOM H105	W	N, E, W, S	
	CLASSROOM H106	W	N, E, W, S	
	CLASSROOM H107	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	CLASSROOM H108	W	N, E, W, S	
	CLASSROOM H109	W	E, W, S	
	CLASSROOM H110	W	N, E, W	
	CLASSROOM H200	W	N, E, W, S	
	CLASSROOM H201	W	N, E, W, S	
	CLASSROOM H202	W	N, E, W, S	
	CLASSROOM H203	W	N, E, W, S	
	CLASSROOM H204	W	N, E, W, S	
	CLASSROOM H205	W	N, E, W, S	
	CLASSROOM H206	W	N, E, W, S	
	CLASSROOM H207	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	WORK ROOM H208	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM H100	C	*	S
	CLASSROOM H101	C	*	
	CLASSROOM H102	C	*	
	CLASSROOM H103	C	*	
	CLASSROOM H104	C	*	
	CLASSROOM H105	C	*	
	CLASSROOM H106	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM H107	C	*	
	STORAGE 1	C	*	
	CLASSROOM H108	C	*	
	CLASSROOM H109	C	*	
	CLASSROOM H110	C	*	
	CLASSROOM H200	C	*	
	CLASSROOM H201	C	*	
	CLASSROOM H202	C	*	
	CLASSROOM H203	C	*	
	CLASSROOM H204	C	*	
	CLASSROOM H205	C	*	
	CLASSROOM H206	C	*	
	CLASSROOM H207	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	WORK ROOM H208	C	*	
	STORAGE 4	C	*	
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM H100	O	E	S
	CLASSROOM H101	O	W	
	CLASSROOM H102	O	E	
	CLASSROOM H103	O	W	
	CLASSROOM H104	O	E	
	CLASSROOM H105	O	W	
	CLASSROOM H108	O	S	
	CLASSROOM H110	O	N	
	CLASSROOM H200	O	E	
	CLASSROOM H201	O	W	
	CLASSROOM H202	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM H203	O	W	
	CLASSROOM H204	O	E	
	CLASSROOM H205	O	W	
	WORK ROOM H208	O	W	
VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, BLACK SPECKS	CLASSROOM H100	F	*	S
	CLASSROOM H101	F	*	
	CLASSROOM H102	F	*	
	CLASSROOM H103	F	*	
	CLASSROOM H104	F	*	
	CLASSROOM H105	F	*	
	CLASSROOM H106	F	*	
	CLASSROOM H107	F	*	
	CLASSROOM H109	F	*	
	CLASSROOM H110	F	*	
	CLASSROOM H200	F	*	
	CLASSROOM H201	F	*	
	CLASSROOM H202	F	*	
	CLASSROOM H203	F	*	
	CLASSROOM H204	F	*	
	CLASSROOM H205	F	*	
	CLASSROOM H206	F	*	
	CLASSROOM H207	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM H109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM H109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ROOM H109 RESTROOM	C, W	N, E, W, S	S
	BOY'S RESTROOM 1	C, W	N, E, W, S	
	GIRL'S RESTROOM 1	C, W	N, E, W, S	
	STAFF MEN'S RESTROOM	C, W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	C, W	N, E, W, S	
	BOY'S RESTROOM 2	C, W	N, E, W, S	
	GIRL'S RESTROOM 2	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	ROOM H109 RESTROOM	W	N, E, W	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	ROOM H109 RESTROOM	W	N, E, W	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	ROOM H109 RESTROOM	W	N, E, W	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	ROOM H109 RESTROOM	W	N, E, W	S
	BOY'S RESTROOM 1	W	N, E, W, S	
	GIRL'S RESTROOM 1	W	N, E, W, S	
	STAFF MEN'S RESTROOM	W	N, E, W, S	
	STAFF WOMEN'S RESTROOM	W	N, E, W, S	
	BOY'S RESTROOM 2	W	N, E, W, S	
	GIRL'S RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	ROOM H109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	ROOM H109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	ROOM H109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	ROOM H109 RESTROOM	F	*	S
	BOY'S RESTROOM 1	F	*	
	GIRL'S RESTROOM 1	F	*	
	STAFF MEN'S RESTROOM	F	*	
	STAFF WOMEN'S RESTROOM	F	*	
	BOY'S RESTROOM 2	F	*	
	GIRL'S RESTROOM 2	F	*	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM H100	W	W, S	S
	CLASSROOM H101	W	E, W, S	
	CLASSROOM H102	W	E, S	
	CLASSROOM H103	W	S	
	CLASSROOM H104	W	W, S	
	CLASSROOM H105	W	N, E	
	CLASSROOM H106	W	N, E, W, S	
	CLASSROOM H107	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM H200	W	W, S	
	CLASSROOM H201	W	E, W, S	
	CLASSROOM H202	W	E, S	
	CLASSROOM H203	W	S	
	CLASSROOM H204	W	W, S	
	CLASSROOM H205	W	N, E	
	CLASSROOM H206	W	N, W, S	
	CLASSROOM H207	W	N, E, S	
SEALANT (DOORS, WINDOWS), BLACK, TAR-LIKE	CORRIDOR 1	O	N, S	S
	CORRIDOR 2	O	N, S	
SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	ROOM E110	C	*	S
	ROOM E111	C	*	
	ROOM E210	C	*	
	ROOM E211	C	*	
SEALANT (FIRE STOP), GREEN, PLIABLE	CLASSROOM H100	O	*	S
	CLASSROOM H101	O	*	
	CLASSROOM H102	O	*	
	CLASSROOM H103	O	*	
	CLASSROOM H104	O	*	
	CLASSROOM H105	O	*	
	CLASSROOM H106	O	*	
	CLASSROOM H107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	CLASSROOM H108	O	*	
	CLASSROOM H109	O	*	
	ROOM H109 RESTROOM	O	*	
	CLASSROOM H110	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	
	CLASSROOM H200	O	*	
	CLASSROOM H201	O	*	
	CLASSROOM H202	O	*	
	CLASSROOM H203	O	*	
	CLASSROOM H204	O	*	
	CLASSROOM H205	O	*	
	CLASSROOM H206	O	*	
	CLASSROOM H207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM H208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	
FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	ROOM E111	O	E	N

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	ROOM E111	O	E	S
VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	STAIRWELL	F	*	S
MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	STAIRWELL	F	*	S
VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	STAIRWELL	F	*	S
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	STAIRWELL	F	*	S
PIPE END SEALANT, WHITE, PLIABLE	CLASSROOM H100	O	*	S
	CLASSROOM H101	O	*	
	CLASSROOM H102	O	*	
	CLASSROOM H103	O	*	
	CLASSROOM H104	O	*	
	CLASSROOM H105	O	*	
	CLASSROOM H106	O	*	
	CLASSROOM H107	O	*	
	STORAGE 1	O	*	
	MECHANICAL 1	O	*	
	ELEVATOR	O	*	
	MECHANICAL 3	O	*	
	CLASSROOM H108	O	*	
	CLASSROOM H109	O	*	
	ROOM H109 RESTROOM	O	*	
	CLASSROOM H110	O	*	
	ROOM E110	O	*	
	ROOM E111	O	*	
	BOY'S RESTROOM 1	O	*	
	GIRL'S RESTROOM 1	O	*	
	STAIRWELL	O	*	
	CORRIDOR 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building H

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM H200	O	*	
	CLASSROOM H201	O	*	
	CLASSROOM H202	O	*	
	CLASSROOM H203	O	*	
	CLASSROOM H204	O	*	
	CLASSROOM H205	O	*	
	CLASSROOM H206	O	*	
	CLASSROOM H207	O	*	
	STORAGE 2	O	*	
	MECHANICAL 2	O	*	
	STAFF MEN'S RESTROOM	O	*	
	STORAGE 3	O	*	
	WORK ROOM H208	O	*	
	STAFF WOMEN'S RESTROOM	O	*	
	STORAGE 4	O	*	
	ROOM E210	O	*	
	ROOM E211	O	*	
	BOY'S RESTROOM 2	O	*	
	GIRL'S RESTROOM 2	O	*	
	CORRIDOR 2	O	*	

* - *Not Applicable*

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
TROWELED-ON TEXTURE, WHITE, CHALKY	STORAGE 5	C	*	S
	STORAGE 6	C	*	
	STORAGE 7	C	*	
	EXTERIOR	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	STORAGE 5	C	*	S
	STORAGE 6	C	*	
	STORAGE 7	C	*	
	EXTERIOR	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 5	C	*	S
	STORAGE 6	C	*	
	STORAGE 7	C	*	
	EXTERIOR	C	*	
STUCCO, GRAY, CEMENTITIOUS	STORAGE 5	W	N, E	S
	STORAGE 6	W	N, E	
	STORAGE 7	W	N	
	ROOF	O	*	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	STORAGE 5	W	N, E, W, S	S
	STORAGE 6	W	N, E, S	
	STORAGE 7	W	N, E, W, S	
	EXTERIOR	W	N, E, S	
BRICK, 4"X16", RED, CEMENTITIOUS	EXTERIOR	W	N, W, S	S
CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS	EXTERIOR	W	N, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	STORAGE 5	W	N, E, W, S	S
	STORAGE 6	W	N, E, S	
	STORAGE 7	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	EXTERIOR	W	N, E, S	
SEALANT (DOORS, WINDOWS, WALLS), GRAY, PLIABLE	EXTERIOR	W	N, E, W, S	S
SEALANT (DOORS), TAN, PLIABLE	STORAGE 5	O	E, S	S
	STORAGE 7	O	W, S	
	EXTERIOR	O	N, E, W, S	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	WORK ROOM	F	*	S
	DETENTION	F	*	
	PHONE	F	*	
	MEN'S RESTROOM 1	F	*	
	WOMEN'S RESTROOM 1	F	*	
	WORK ROOM STORAGE	F	*	
	MECHANICAL 1	F	*	
	PANTRY	F	*	
	STORAGE 1	F	*	
	FOOD LAB	F	*	
	RESTROOM 2	F	*	
	LAUNDRY	F	*	
	STORAGE 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	STORAGE 5	F	*	
	STORAGE 6	F	*	
	STORAGE 7	F	*	
	ART	F	*	
	CAD	F	*	
	EXTERIOR	F	*	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	STORAGE 7	W	W	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	EXTERIOR	W	E, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	STORAGE 7	W	W	S
	EXTERIOR	W	E, S	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	N, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS	EXTERIOR	W	N, W, S	S
FIRE DOOR INSULATION, WOOD/METAL CLADDING	WORK ROOM	O	E, S	S
	DETENTION	O	N, E, S	
	MEN'S RESTROOM 1	O	N	
	WOMEN'S RESTROOM 1	O	N	
	MECHANICAL 1	O	S	
	STORAGE 1	O	W	
	FOOD LAB	O	N, E, S	
	STORAGE 2	O	W	
	STORAGE 3	O	N	
	STORAGE 4	O	N	
	STORAGE 5	O	E	
	STORAGE 7	O	W	
	ART	O	N, E, W, S	
	CAD	O	N, W	
	TECH LAB	O	N, E, W, S	
	TECH SERVER	O	N, E	
	STORAGE 8	O	N	
	MECHANICAL 2	O	W	
	EXTERIOR	O	N, E, W, S	
CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS	EXTERIOR	W	N, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	WORK ROOM	C	*	S
	DETENTION	C	*	
	WORK ROOM STORAGE	C	*	
	PANTRY	C	*	
	STORAGE 1	C	*	
	FOOD LAB	C	*	
	LAUNDRY	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	STORAGE 4	C	*	
	ART	C	*	
	CAD	C	*	
	TECH SERVER	C	*	
	STORAGE 8	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WORK ROOM	W	N, E, W, S	S
	DETENTION	W	N, E, W, S	
	PHONE	W	N, E, W, S	
	WORK ROOM STORAGE	W	N, E, W, S	
	PANTRY	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	FOOD LAB	W	N, E, W, S	
	LAUNDRY	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	ART	W	N, E, W, S	
	CAD	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	WORK ROOM	W	N, E, W, S	S
	DETENTION	W	N, E, W, S	
	PHONE	W	N, E, W, S	
	WORK ROOM STORAGE	W	N, E, W, S	
	PANTRY	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	FOOD LAB	W	N, E, W, S	
	LAUNDRY	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	ART	W	N, E, W, S	
	CAD	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	WORK ROOM	W	N, E, W, S	S
	DETENTION	W	N, E, W, S	
	PHONE	W	N, E, W, S	
	WORK ROOM STORAGE	W	N, E, W, S	
	PANTRY	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	FOOD LAB	W	N, E, W, S	
	LAUNDRY	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	STORAGE 3	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	ART	W	N, E, W, S	
	CAD	W	N, E, W, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	WORK ROOM	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	DETENTION	F	*	
	FOOD LAB	F	*	
	CAD	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	WORK ROOM	F	*	S
	DETENTION	F	*	
	PHONE	F	*	
	WORK ROOM STORAGE	F	*	
	MECHANICAL 1	F	*	
	PANTRY	F	*	
	STORAGE 1	F	*	
	FOOD LAB	F	*	
	LAUNDRY	F	*	
	STORAGE 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ART	F	*	
	CAD	F	*	
	TECH SERVER	F	*	
	STORAGE 8	F	*	
	DARK ROOM	F	*	
VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK, SPECKS	WORK ROOM	F	*	S
	DETENTION	F	*	
	FOOD LAB	F	*	
	ART	F	*	
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK SPECKS	WORK ROOM	F	*	S
	DETENTION	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	PHONE	F	*	
	WORK ROOM STORAGE	F	*	
	MECHANICAL 1	F	*	
	PANTRY	F	*	
	STORAGE 1	F	*	
	FOOD LAB	F	*	
	LAUNDRY	F	*	
	STORAGE 2	F	*	
	STORAGE 3	F	*	
	STORAGE 4	F	*	
	ART	F	*	
	CAD	F	*	
	TECH SERVER	F	*	
	STORAGE 8	F	*	
	DARK ROOM	F	*	
WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	WORK ROOM	O	N, E, W, S	S
	DETENTION	O	N, E, W, S	
	PHONE	O	N, E, W, S	
	WORK ROOM STORAGE	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	PANTRY	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	FOOD LAB	O	N, E, W, S	
	LAUNDRY	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ART	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building J

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CAD	O	N, E, W, S	
	TECH LAB	O	N, E, W, S	
	TECH SERVER	O	N, E, W, S	
	STORAGE 8	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	WORK ROOM	O	N, E, W, S	S
	DETENTION	O	N, E, W, S	
	PHONE	O	N, E, W, S	
	WORK ROOM STORAGE	O	N, E, W, S	
	MECHANICAL 1	O	N, E, W, S	
	PANTRY	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	FOOD LAB	O	N, E, W, S	
	LAUNDRY	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	ART	O	N, E, W, S	
	CAD	O	N, E, W, S	
	TECH LAB	O	N, E, W, S	
	TECH SERVER	O	N, E, W, S	
	STORAGE 8	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	WORK ROOM	O	E, W, S	S
	DETENTION	O	E, W, S	
	MEN'S RESTROOM 1	O	W	
	WOMEN'S RESTROOM 1	O	E	
	WORK ROOM STORAGE	O	E	
	PANTRY	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 1	O	W	
	FOOD LAB	O	N, E, W, S	
	RESTROOM 2	O	E, W	
	LAUNDRY	O	E	
	STORAGE 2	O	W	
	STORAGE 3	O	N	
	STORAGE 4	O	N	
	ART	O	N, E, W, S	
	CAD	O	N, W, S	
	TECH LAB	O	N, E, W, S	
	TECH SERVER	O	N, E	
	STORAGE 8	O	N	
	DARK ROOM	O	N	
	MECHANICAL 2	O	W	
SINK ACOUSTICAL COATING, GRAY, ROUGH	WORK ROOM	O	W	S
	DETENTION	O	W	
	FOOD LAB	O	N, E, W	
	ART	O	N, W	
GYPSUM WALLBOARD, WHITE, CHALKY	WORK ROOM	C	*	S
	DETENTION	C	*	
	PHONE	C	*	
	MEN'S RESTROOM 1	C	*	
	WOMEN'S RESTROOM 1	C	*	
	WORK ROOM STORAGE	C	*	
	MECHANICAL 1	C	*	
	PANTRY	C	*	
	STORAGE 1	C	*	
	FOOD LAB	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	RESTROOM 2	C	*	
	LAUNDRY	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	STORAGE 4	C	*	
	ART	C	*	
	CAD	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	WORK ROOM	C	*	S
	DETENTION	C	*	
	PHONE	C	*	
	MEN'S RESTROOM 1	C	*	
	WOMEN'S RESTROOM 1	C	*	
	WORK ROOM STORAGE	C	*	
	MECHANICAL 1	C	*	
	PANTRY	C	*	
	STORAGE 1	C	*	
	FOOD LAB	C	*	
	RESTROOM 2	C	*	
	LAUNDRY	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	STORAGE 4	C	*	
	ART	C	*	
	CAD	C	*	
ADHESIVE (RESIDUAL), BROWN, BRITTLE	WORK ROOM	C	*	S
	DETENTION	C	*	
	PHONE	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building J

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	MEN'S RESTROOM 1	C	*	
	WOMEN'S RESTROOM 1	C	*	
	WORK ROOM STORAGE	C	*	
	MECHANICAL 1	C	*	
	PANTRY	C	*	
	STORAGE 1	C	*	
	FOOD LAB	C	*	
	RESTROOM 2	C	*	
	LAUNDRY	C	*	
	STORAGE 2	C	*	
	STORAGE 3	C	*	
	STORAGE 4	C	*	
	ART	C	*	
	CAD	C	*	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	WORK ROOM	W	N, E, S	S
	FOOD LAB	W	N, E, W	
	ART	W	E	
	CAD	W	E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	RESTROOM 2	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	RESTROOM 2	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM 1	C, W	N, E, W, S	S
	WOMEN'S RESTROOM 1	C, W	N, E, W, S	
	RESTROOM 2	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building J*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	RESTROOM 2	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	RESTROOM 2	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	MEN'S RESTROOM 1	W	N, E, W, S	S
	WOMEN'S RESTROOM 1	W	N, E, W, S	
	RESTROOM 2	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	MEN'S RESTROOM 1	F	*	S
	WOMEN'S RESTROOM 1	F	*	
	RESTROOM 2	F	*	
CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	MEN'S RESTROOM 1	F	*	S
	WOMEN'S RESTROOM 1	F	*	
	RESTROOM 2	F	*	
CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	MEN'S RESTROOM 1	F	*	S
	WOMEN'S RESTROOM 1	F	*	
	RESTROOM 2	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	MEN'S RESTROOM 1	F	*	S
	WOMEN'S RESTROOM 1	F	*	
	RESTROOM 2	F	*	
PIPE SEALANT, WHITE, PLIABLE	MECHANICAL 1	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building J

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
GASKET, 4", BLACK, RUBBER-LIKE	MECHANICAL 1	O	*	S
FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	STORAGE 1	W	E	N
	FOOD LAB	W	W, S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	STORAGE 1	W	E	S
	FOOD LAB	W	W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	TECH LAB	W	N, E, W, S	S
	TECH SERVER	W	N, E, W, S	
	STORAGE 8	W	N, E, W, S	
	DARK ROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	TECH LAB	W	N, E, W, S	S
	TECH SERVER	W	N, E, W, S	
	STORAGE 8	W	N, E, W, S	
	DARK ROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	TECH LAB	W	N, E, W, S	S
	TECH SERVER	W	N, E, W, S	
	STORAGE 8	W	N, E, W, S	
	DARK ROOM	C, W	N, E, W, S	
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	TECH LAB	F	*	S
	TECH SERVER	F	*	
	STORAGE 8	F	*	
	DARK ROOM	F	*	
	MECHANICAL 2	F	*	
	EXTERIOR	F	*	
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	WORK ROOM	O	*	S
	DETENTION	O	*	
	PHONE	O	*	
	MEN'S RESTROOM 1	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building J

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	WOMEN'S RESTROOM 1	O	*	
	WORK ROOM STORAGE	O	*	
	MECHANICAL 1	O	*	
	PANTRY	O	*	
	STORAGE 1	O	*	
	FOOD LAB	O	*	
	RESTROOM 2	O	*	
	LAUNDRY	O	*	
	STORAGE 2	O	*	
	STORAGE 3	O	*	
	STORAGE 4	O	*	
	STORAGE 5	O	*	
	STORAGE 6	O	*	
	STORAGE 7	O	*	
	ART	O	*	
	CAD	O	*	
	TECH LAB	O	*	
	TECH SERVER	O	*	
	STORAGE 8	O	*	
	DARK ROOM	O	*	
	MECHANICAL 2	O	*	
PLASTER, GRAY, CEMENTITIOUS	STORAGE 5	W	N, E	S
	STORAGE 6	W	N, E	
	STORAGE 7	W	N	

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF	O	*	S
SEALANT (FLASHING), GRAY, PLIABLE	ROOF	O	*	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	O	E, W, S	S
	ROOF	O	*	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	EXTERIOR	W	N, E, W, S	S
	ROOF	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	EXTERIOR	W	N, E, W, S	S
	ROOF	W	N, E, W, S	
SEALANT (WALL, FLASHING), TAN, PLIABLE	EXTERIOR	W	N, E, W, S	S
	ROOF	O	*	
SEALANT (DUCT), LIGHT GRAY, PLIABLE	RECEPTION	O	*	S
	OFFICE 1	O	*	
	CONFERENCE	O	*	
	RESTROOM	O	*	
	HALLWAY 01	O	*	
	OFFICE 2	O	*	
	OFFICE 3	O	*	
	OFFICE 4	O	*	
	OFFICE 5	O	*	
	OFFICE 6	O	*	
	OFFICE 7	O	*	
	VESTIBULE 01	O	*	
	ISS	O	*	
	ISS RESTROOM	O	*	
	SUPPLY 01	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	SUPPLY 02	O	*	
	HALL 02	O	*	
	HALL 03	O	*	
	PROFESSIONAL LIBRARY	O	*	
	VESTIBULE 02	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	COMPUTER 2	O	*	
	STORAGE 1	O	*	
	PRINTER	O	*	
	COMPUTER	O	*	
	STORAGE 2	O	*	
	MECHANICAL	O	*	
	VESTIBULE 03	O	*	
	NURSE RESTROOM	O	*	
	HEARING	O	*	
	HEALTH OFFICE	O	*	
	NURSE STORAGE	O	*	
	TREATMENT	O	*	
	NURSE OFFICE	O	*	
	PRINCIPAL	O	*	
	PRINCIPAL CLOSET	O	*	
	OPEN OFFICE	O	*	
	LIBRARY	O	*	
	JANITOR	O	*	
	AV	O	*	
	MEDIA WORK ROOM	O	*	
	CORRIDOR 01	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOF	O	*	
SEALANT (DUCT), GRAY, PLIABLE	RECEPTION	O	*	S
	OFFICE 1	O	*	
	CONFERENCE	O	*	
	RESTROOM	O	*	
	HALLWAY 01	O	*	
	OFFICE 2	O	*	
	OFFICE 3	O	*	
	OFFICE 4	O	*	
	OFFICE 5	O	*	
	OFFICE 6	O	*	
	OFFICE 7	O	*	
	VESTIBULE 01	O	*	
	ISS	O	*	
	ISS RESTROOM	O	*	
	SUPPLY 01	O	*	
	SUPPLY 02	O	*	
	HALL 02	O	*	
	HALL 03	O	*	
	PROFESSIONAL LIBRARY	O	*	
	VESTIBULE 02	O	*	
	MEN'S RESTROOM	O	*	
	WOMEN'S RESTROOM	O	*	
	COMPUTER 2	O	*	
	STORAGE 1	O	*	
	PRINTER	O	*	
	COMPUTER	O	*	
	STORAGE 2	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MECHANICAL	O	*	
	VESTIBULE 03	O	*	
	NURSE RESTROOM	O	*	
	HEARING	O	*	
	HEALTH OFFICE	O	*	
	NURSE STORAGE	O	*	
	TREATMENT	O	*	
	NURSE OFFICE	O	*	
	PRINCIPAL	O	*	
	PRINCIPAL CLOSET	O	*	
	OPEN OFFICE	O	*	
	LIBRARY	O	*	
	JANITOR	O	*	
	A/V	O	*	
	MEDIA WORK ROOM	O	*	
	CORRIDOR 01	O	*	
	ROOF	O	*	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	OFFICE 1	F	*	S
	CONFERENCE	F	*	
	RESTROOM	F	*	
	HALLWAY 01	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	OFFICE 4	F	*	
	OFFICE 5	F	*	
	OFFICE 6	F	*	
	OFFICE 7	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	VESTIBULE 01	F	*	
	ISS	F	*	
	ISS RESTROOM	F	*	
	SUPPLY 01	F	*	
	SUPPLY 02	F	*	
	HALL 02	F	*	
	HALL 03	F	*	
	PROFESSIONAL LIBRARY	F	*	
	VESTIBULE 02	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	COMPUTER 2	F	*	
	STORAGE 1	F	*	
	PRINTER	F	*	
	COMPUTER	F	*	
	STORAGE 2	F	*	
	MECHANICAL	F	*	
	VESTIBULE 03	F	*	
	NURSE RESTROOM	F	*	
	HEARING	F	*	
	HEALTH OFFICE	F	*	
	NURSE STORAGE	F	*	
	TREATMENT	F	*	
	NURSE OFFICE	F	*	
	PRINCIPAL	F	*	
	PRINCIPAL CLOSET	F	*	
	OPEN OFFICE	F	*	
	LIBRARY	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	JANITOR	F	*	
	A/V	F	*	
	MEDIA WORK ROOM	F	*	
	CORRIDOR 01	F	*	
	EXTERIOR	F	*	
SEALANT (WINDOWS), BLACK, TAR-LIKE	EXTERIOR	O	N, E, W, S	S
FIRE DOOR INSULATION, METAL/WOOD CLADDING	RECEPTION	O	N, S	S
	OFFICE 1	O	W	
	RESTROOM	O	S	
	HALLWAY 01	O	N	
	OFFICE 2	O	S	
	OFFICE 7	O	E	
	ISS	O	E	
	SUPPLY 02	O	E	
	HALL 02	O	N, S	
	PROFESSIONAL LIBRARY	O	S	
	VESTIBULE 02	O	E, W	
	MEN'S RESTROOM	O	W	
	WOMEN'S RESTROOM	O	E	
	COMPUTER 2	O	E	
	COMPUTER	O	N	
	STORAGE 2	O	S	
	MECHANICAL	O	S	
	VESTIBULE 03	O	E, W	
	HEALTH OFFICE	O	W	
	PRINCIPAL	O	W	
	OPEN OFFICE	O	N, E	
	LIBRARY	O	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	JANITOR	O	W	
	CORRIDOR 01	O	W	
	EXTERIOR	O	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION	C	*	S
	CONFERENCE	C	*	
	HALLWAY 01	C	*	
	PRINCIPAL	C	*	
	OPEN OFFICE	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	OFFICE 1	W	N, E, W, S	S
	CONFERENCE	C, W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	OFFICE 3	W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	OFFICE 5	W	N, E, W, S	
	OFFICE 6	W	N, E, W, S	
	OFFICE 7	W	N, E, W, S	
	VESTIBULE 01	W	N, E, S	
	ISS	W	N, E, W, S	
	SUPPLY 01	W	N, E, W, S	
	SUPPLY 02	W	N, E, W, S	
	PROFESSIONAL LIBRARY	W	N, E, W, S	
	COMPUTER 2	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	PRINTER	W	N, E, W, S	
	COMPUTER	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	VESTIBULE 3	C	*	
	HEALTH OFFICE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	NURSE STORAGE	W	N, E, W, S	
	TREATMENT	W	N, E, W, S	
	NURSE OFFICE	W	N, E, W, S	
	PRINCIPAL	C, W	N, E, W, S	
	PRINCIPAL CLOSET	C, W	N, E, W, S	
	LIBRARY	C	*	
	MEDIA WORK ROOM	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	OFFICE 1	W	N, E, W, S	S
	CONFERENCE	C, W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	OFFICE 3	W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	OFFICE 5	W	N, E, W, S	
	OFFICE 6	W	N, E, W, S	
	OFFICE 7	W	N, E, W, S	
	VESTIBULE 01	W	N, E, S	
	ISS	W	N, E, W, S	
	SUPPLY 01	W	N, E, W, S	
	SUPPLY 02	W	N, E, W, S	
	PROFESSIONAL LIBRARY	W	N, E, W, S	
	COMPUTER 2	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	PRINTER	W	N, E, W, S	
	COMPUTER	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	VESTIBULE 3	C	*	
	HEALTH OFFICE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	NURSE STORAGE	W	N, E, W, S	
	TREATMENT	W	N, E, W, S	
	NURSE OFFICE	W	N, E, W, S	
	PRINCIPAL	C, W	N, E, W, S	
	PRINCIPAL CLOSET	C, W	N, E, W, S	
	LIBRARY	C	*	
	MEDIA WORK ROOM	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	OFFICE 1	W	N, E, W, S	S
	CONFERENCE	C, W	N, E, W, S	
	OFFICE 2	W	N, E, W, S	
	OFFICE 3	W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	OFFICE 5	W	N, E, W, S	
	OFFICE 6	W	N, E, W, S	
	OFFICE 7	W	N, E, W, S	
	VESTIBULE 01	W	N, E, S	
	ISS	W	N, E, W, S	
	SUPPLY 01	W	N, E, W, S	
	SUPPLY 02	W	N, E, W, S	
	PROFESSIONAL LIBRARY	W	N, E, W, S	
	COMPUTER 2	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	PRINTER	W	N, E, W, S	
	COMPUTER	W	N, E, W, S	
	STORAGE 2	W	N, E, W, S	
	VESTIBULE 3	C	*	
	HEALTH OFFICE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	NURSE STORAGE	W	N, E, W, S	
	TREATMENT	W	N, E, W, S	
	NURSE OFFICE	W	N, E, W, S	
	PRINCIPAL	C, W	N, E, W, S	
	PRINCIPAL CLOSET	C, W	N, E, W, S	
	LIBRARY	C	*	
	MEDIA WORK ROOM	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	OFFICE 1	W	E	S
	CONFERENCE	W	N	
	OFFICE 2	W	W	
	OFFICE 3	W	E	
	OFFICE 4	W	E, W	
	ISS	W	N	
	COMPUTER	W	S	
	HEARING	W	E, S	
	PRINCIPAL	W	E	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	RECEPTION	F	*	S
	OFFICE 1	F	*	
	CONFERENCE	F	*	
	HALLWAY 01	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	OFFICE 4	F	*	
	OFFICE 5	F	*	
	OFFICE 6	F	*	
	OFFICE 7	F	*	
	VESTIBULE 01	F	*	
	ISS	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	HALL 03	F	*	
	PROFESSIONAL LIBRARY	F	*	
	COMPUTER 2	F	*	
	STORAGE 1	F	*	
	PRINTER	F	*	
	COMPUTER	F	*	
	STORAGE 2	F	*	
	HEARING	F	*	
	HEALTH OFFICE	F	*	
	PRINCIPAL	F	*	
	PRINCIPAL CLOSET	F	*	
	OPEN OFFICE	F	*	
	LIBRARY	F	*	
	A/V	F	*	
	MEDIA WORK ROOM	F	*	
	CORRIDOR 01	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	RECEPTION	O	N, E, W, S	S
	OFFICE 1	O	N, E, W, S	
	CONFERENCE	O	N, E, W, S	
	HALLWAY 01	O	N, E, W, S	
	OFFICE 2	O	N, E, W, S	
	OFFICE 3	O	N, E, W, S	
	OFFICE 4	O	N, E, W, S	
	OFFICE 5	O	N, E, W, S	
	OFFICE 6	O	N, E, W, S	
	OFFICE 7	O	N, E, W, S	
	VESTIBULE 01	O	N, E, W, S	
	ISS	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	SUPPLY 01	O	N, E, W, S	
	SUPPLY 02	O	N, E, W, S	
	HALL 02	O	N, E, W, S	
	HALL 03	O	N, E, W, S	
	PROFESSIONAL LIBRARY	O	N, E, W, S	
	VESTIBULE 02	O	N, E, W, S	
	COMPUTER 2	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	PRINTER	O	N, E, W, S	
	COMPUTER	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	VESTIBULE 03	O	N, E, W, S	
	HEARING	O	N, E, W, S	
	HEALTH OFFICE	O	N, E, W, S	
	NURSE STORAGE	O	N, E, W, S	
	TREATMENT	O	N, E, W, S	
	NURSE OFFICE	O	N, E, W, S	
	PRINCIPAL	O	N, E, W, S	
	PRINCIPAL CLOSET	O	N, E, W, S	
	OPEN OFFICE	O	N, E, W, S	
	LIBRARY	O	N, E, W, S	
	JANITOR	O	N, E, W	
	A/V	O	N, E, W, S	
	MEDIA WORK ROOM	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	RECEPTION	O	N, E, W, S	S
	OFFICE 1	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CONFERENCE	O	N, E, W, S	
	HALLWAY 01	O	N, E, W, S	
	OFFICE 2	O	N, E, W, S	
	OFFICE 3	O	N, E, W, S	
	OFFICE 4	O	N, E, W, S	
	OFFICE 5	O	N, E, W, S	
	OFFICE 6	O	N, E, W, S	
	OFFICE 7	O	N, E, W, S	
	VESTIBULE 01	O	N, E, W, S	
	ISS	O	N, E, W, S	
	SUPPLY 01	O	N, E, W, S	
	SUPPLY 02	O	N, E, W, S	
	HALL 02	O	N, E, W, S	
	HALL 03	O	N, E, W, S	
	PROFESSIONAL LIBRARY	O	N, E, W, S	
	VESTIBULE 02	O	N, E, W, S	
	COMPUTER 2	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	PRINTER	O	N, E, W, S	
	COMPUTER	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	VESTIBULE 03	O	N, E, W, S	
	HEARING	O	N, E, W, S	
	HEALTH OFFICE	O	N, E, W, S	
	NURSE STORAGE	O	N, E, W, S	
	TREATMENT	O	N, E, W, S	
	NURSE OFFICE	O	N, E, W, S	
	PRINCIPAL	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	PRINCIPAL CLOSET	O	N, E, W, S	
	OPEN OFFICE	O	N, E, W, S	
	LIBRARY	O	N, E, W, S	
	JANITOR	O	N, E, W	
	AV	O	N, E, W, S	
	MEDIA WORK ROOM	O	N, E, W, S	
	CORRIDOR 01	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	RECEPTION	O	N, S	S
	OFFICE 1	O	N, W	
	CONFERENCE	O	E, S	
	RESTROOM	O	E, S	
	HALLWAY 01	O	N, W, S	
	OFFICE 2	O	N, S	
	OFFICE 3	O	N, S	
	OFFICE 4	O	N, S	
	OFFICE 5	O	N, E	
	OFFICE 6	O	N	
	OFFICE 7	O	N, E	
	VESTIBULE 01	O	E, S	
	ISS	O	N, E, W, S	
	ISS RESTROOM	O	S	
	SUPPLY 01	O	E, S	
	SUPPLY 02	O	E, W	
	HALL 02	O	N, S	
	HALL 03	O	N	
	PROFESSIONAL LIBRARY	O	N, W, S	
	VESTIBULE 02	O	E, W	
	MEN'S RESTROOM	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	WOMEN'S RESTROOM	O	E	
	COMPUTER 2	O	N, W, S	
	STORAGE 1	O	W	
	PRINTER	O	E, W	
	COMPUTER	O	N, E, S	
	STORAGE 2	O	S	
	VESTIBULE 03	O	E, W	
	NURSE RESTROOM	O	N, E, S	
	HEARING	O	W	
	HEALTH OFFICE	O	E, W, S	
	NURSE STORAGE	O	E	
	TREATMENT	O	N	
	NURSE OFFICE	O	N, S	
	PRINCIPAL	O	N, E, W, S	
	PRINCIPAL CLOSET	O	N	
	OPEN OFFICE	O	N, E, W	
	LIBRARY	O	N, E, S	
	JANITOR	O	W	
	A/V	O	E	
	MEDIA WORK ROOM	O	N, E, W, S	
	CORRIDOR 01	O	W, S	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION	C	*	S
	OFFICE 1	C	*	
	OFFICE 2	C	*	
	OFFICE 3	C	*	
	OFFICE 4	C	*	
	OFFICE 5	C	*	
	OFFICE 6	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	OFFICE 7	C	*	
	ISS	C	*	
	SUPPLY 01	C	*	
	SUPPLY 02	C	*	
	HALL 03	C	*	
	COMPUTER 2	C	*	
	STORAGE 1	C	*	
	PRINTER	C	*	
	COMPUTER	C	*	
	STORAGE 2	C	*	
	MECHANICAL	C	*	
	HEARING	C	*	
	HEALTH OFFICE	C	*	
	NURSE STORAGE	C	*	
	TREATMENT	C	*	
	NURSE OFFICE	C	*	
	OPEN OFFICE	C	*	
	LIBRARY	C	*	
	A/V	C	*	
	MEDIA WORK ROOM	C	*	
	CORRIDOR 01	C	*	
WALL PAPER, TAN, CLOTH-LIKE	RECEPTION	C, W	N, E, W, S	N
	HALLWAY 01	W	N, E, W, S	
	HALL 03	W	N, E, W, S	
	VESTIBULE 02	C, W	N, E, W, S	
	VESTIBULE 03	C, W	N, E, W, S	
	HEALTH OFFICE	W	N, E, S	
	OPEN OFFICE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	A/V	W	N, E, W, S	
	CORRIDOR 01	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH WALL PAPER, TAN, CLOTH-LIKE AND SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION	C, W	N, E, W, S	S
	HALLWAY 01	W	N, E, W, S	
	HALL 03	W	N, E, W, S	
	VESTIBULE 02	C, W	N, E, W, S	
	VESTIBULE 03	C, W	N, E, W, S	
	HEALTH OFFICE	W	N, E, S	
	OPEN OFFICE	W	N, E, W, S	
	A/V	W	N, E, W, S	
	CORRIDOR 01	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION	C, W	N, E, W, S	S
	HALLWAY 01	W	N, E, W, S	
	HALL 03	W	N, E, W, S	
	VESTIBULE 02	C, W	N, E, W, S	
	VESTIBULE 03	C, W	N, E, W, S	
	HEALTH OFFICE	W	N, E, S	
	OPEN OFFICE	W	N, E, W, S	
	A/V	W	N, E, W, S	
	CORRIDOR 01	W	N, E, W, S	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	RECEPTION	F	*	S
	ISS	F	*	
	HALL 02	F	*	
	SUPPLY 01	F	*	
	SUPPLY 02	F	*	
	COMPUTER 2	F	*	
	COMPUTER	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	VESTIBULE 03	F	*	
	HEALTH OFFICE	F	*	
	TREATMENT	F	*	
	CORRIDOR 01	F	*	
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	RECEPTION	F	*	S
	ISS	F	*	
	HALL 02	F	*	
	SUPPLY 01	F	*	
	SUPPLY 02	F	*	
	COMPUTER 2	F	*	
	COMPUTER	F	*	
	VESTIBULE 03	F	*	
	HEALTH OFFICE	F	*	
	TREATMENT	F	*	
	CORRIDOR 01	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION	C, W	N, E, W, S	S
	VESTIBULE 02	C	*	
	VESTIBULE 03	C	*	
	A/V	W	N, E, W, S	
SINK ACOUSTICAL COATING, GRAY, ROUGH	ISS	O	W	S
	COMPUTER 2	O	N	
	HEALTH OFFICE	O	S	
	TREATMENT	O	W	
	MEDIA WORK ROOM	O	S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	RESTROOM	W	N, E, W, S	S
	MEN'S RESTROOM	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building K*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	NURSE RESTROOM	W	N, E, W, S	
	TREATMENT	W	N, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	RESTROOM	W	N, E, W, S	S
	MEN'S RESTROOM	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
	NURSE RESTROOM	W	N, E, W, S	
	TREATMENT	W	N, W, S	
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	RESTROOM	F	*	S
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	NURSE RESTROOM	F	*	
	TREATMENT	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	RESTROOM	F	*	S
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
	NURSE RESTROOM	F	*	
	TREATMENT	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM	C, W	N, E, W, S	S
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	NURSE RESTROOM	C, W	N, E, W, S	
	TREATMENT	C, W	N, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM	C, W	N, E, W, S	S
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	NURSE RESTROOM	C, W	N, E, W, S	
	TREATMENT	C, W	N, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RESTROOM	C, W	N, E, W, S	S
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
	NURSE RESTROOM	C, W	N, E, W, S	
	TREATMENT	C, W	N, W, S	
TROWELED-ON TEXTURE, WHITE, CHALKY	HALL 02	W	N, E, W, S	S
	MECHANICAL	W	E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	HALL 02	W	N, E, W, S	S
	MECHANICAL	W	E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	HALL 02	W	N, E, W, S	S
	MECHANICAL	W	E, W, S	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	HALL 02	C	*	S
GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	MEN'S RESTROOM	F	*	S
	WOMEN'S RESTROOM	F	*	
FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	JANITOR	W	E, S	S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	JANITOR	W	E, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building K

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
PIPE END SEALANT, WHITE, PLIABLE	MECHANICAL	O	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
MASTIC (FLASHING), GRAY, PLIABLE	ROOF	O	*	S
SEALANT (WALLS, FLASHING), BROWN, TAR-LIKE	EXTERIOR	W	N, E, W, S	S
	ROOF	O	*	
SEALANT (DOORS, WINDOWS, WALLS, FLASHINGS), BLACK, PLIABLE	ELECTRICAL	O	E	S
	JANITOR	O	E	
	VESTIBULE 2	O	E, W	
	VESTIBULE 1	O	E, W	
	MULTI-PURPOSE	O	E, W	
	OFFICE 4	O	N, E, W, S	
	SERVING	O	N, E	
	VESTIBULE 4	O	E	
	EXTERIOR	O	E, W	
	ROOF	O	*	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	MULTI-PURPOSE	W	N, E, W, S	S
	MOP SINK	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	MULTI-PURPOSE	W	N, E, W, S	S
	MOP SINK	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	N, E, W, S	
SEALANT (DOORS, FLASHING), GRAY, PLIABLE	EXTERIOR	O	E, W, S	S
	ROOF	O	*	
SEALANT (FLASHING), WHITE, TAR-LIKE	ROOF	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
SEALANT (DUCT), WHITE, TAR-LIKE	ROOF	O	*	S
SEALANT (DUCT), GRAY, BRITTLE	ROOF	O	*	S
WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	ROOF	O	*	S
SEALANT (DUCT), GRAY, TAR-LIKE	ROOF	O	*	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
	ROOF	W	E, S	
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	LOBBY	F	*	S
	VESTIBULE 3	F	*	
	ROOM L100	F	*	
	ROOM L107	F	*	
	STORAGE 3	F	*	
	ELECTRICAL	F	*	
	BAND	F	*	
	BAND STORAGE	F	*	
	OFFICE 1	F	*	
	OFFICE 2	F	*	
	OFFICE 3	F	*	
	STORAGE 2	F	*	
	CONCESSION 1	F	*	
	UNISEX RESTROOM 1	F	*	
	STAFF RESTROOM	F	*	
	HALL 1	F	*	
	JANITOR	F	*	
	VESTIBULE 2	F	*	
	ROOM L103	F	*	
	TABLE STORAGE	F	*	
	ROOM L104	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	ROOM L104 CLOSET	F	*	
	STORAGE 1	F	*	
	ROOM L105	F	*	
	VESTIBULE 1	F	*	
	MULTI-PURPOSE	F	*	
	MULTI-PURPOSE STORAGE	F	*	
	DISH WASHER	F	*	
	UNISEX RESTROOM 2	F	*	
	LOCKER ROOM	F	*	
	WALK IN 1	F	*	
	WALK IN 2	F	*	
	LAUNDRY ROOM	F	*	
	MOP SINK	F	*	
	OFFICE 4	F	*	
	SERVING	F	*	
	SERVING STORAGE	F	*	
	CONCESSION 2	F	*	
	VESTIBULE 4	F	*	
	STORAGE 4	F	*	
	BUILDING MANAGER	F	*	
	DRESSING ROOM 1	F	*	
	DRESSING ROOM 2	F	*	
	EAST WING	F	*	
	GREEN ROOM	F	*	
	STAGE	F	*	
	WEST WING	F	*	
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	EXTERIOR	F	*	
FIRE DOOR INSULATION, METAL/WOOD CLADDING	LOBBY	O	E, W	S
	VESTIBULE 3	O	E, S	
	ROOM L100	O	N, W	
	ROOM L107	O	N, E	
	STORAGE 3	O	W, S	
	ELECTRICAL	O	N, E	
	BAND	O	E, W	
	BAND STORAGE	O	W	
	STORAGE 2	O	W	
	CONCESSION 1	O	W	
	STAFF RESTROOM	O	S	
	HALL 1	O	N, E	
	JANITOR	O	E	
	VESTIBULE 2	O	N, E, W	
	ROOM L103	O	E	
	TABLE STORAGE	O	N	
	ROOM L104	O	N, W, S	
	ROOM L104 CLOSET	O	E	
	STORAGE 1	O	W	
	ROOM L105	O	N, E, W	
	VESTIBULE 1	O	N, E	
	MULTI-PURPOSE	O	E, W, S	
	MULTI-PURPOSE STORAGE	O	W	
	UNISEX RESTROOM 2	O	E	
	LOCKER ROOM	O	N	
	WALK IN 1	O	W	
	WALK IN 2	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	LAUNDRY ROOM	O	W	
	MOP SINK	O	W	
	SERVING	O	N, E, W, S	
	SERVING STORAGE	O	S	
	CONCESSION 2	O	S	
	VESTIBULE 4	O	N, E, W	
	STORAGE 4	O	W	
	BUILDING MANAGER	O	E	
	MEN'S RESTROOM	O	W	
	WOMEN'S RESTROOM	O	W	
	EXTERIOR	O	E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CONCESSION 1	W	N, E, W, S	S
	DISH WASHER	W	N, E, W, S	
	LOCKER ROOM	W	N, E, W, S	
	LAUNDRY ROOM	W	N, E, W, S	
	MOP SINK	W	N, E, W, S	
	SERVING	W	N, E, W, S	
	CONCESSION 2	W	N, E, W, S	
CONCRETE MASONRY UNIT (PATCH), 4"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	E, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT (PATCH), 4"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	E, S	S
BRICK, 4"X16", RED, CEMENTITIOUS	LOBBY	W	W	S
	EXTERIOR	W	W	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS	LOBBY	W	W	S
	EXTERIOR	W	W	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES, WALLS)	LOBBY	O	W	S
	ROOM L100	O	N, W, S	
	ROOM L107	O	N, E, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE 3	O	W, S	
	ELECTRICAL	O	N	
	BAND	O	E, W, S	
	BAND STORAGE	O	W	
	OFFICE 1	O	N, W	
	UNISEX RESTROOM 1	O	N, E	
	STAFF RESTROOM	O	E, S	
	ROOM L103	O	E	
	TABLE STORAGE	O	N	
	ROOM L104	O	W	
	ROOM L104 CLOSET	O	E	
	STORAGE 1	O	W	
	ROOM L105	O	E, W	
	MULTI-PURPOSE	O	N	
	MULTI-PURPOSE STORAGE	O	W	
	UNISEX RESTROOM 2	O	E	
	LOCKER ROOM	O	N, E	
	WALK IN 1	O	W	
	WALK IN 2	O	W	
	LAUNDRY ROOM	O	W	
	MOP SINK	O	W	
	OFFICE 4	O	W	
	SERVING	O	N, E, W, S	
	CONCESSION 2	O	S	
	VESTIBULE 4	O	N	
	STORAGE 4	O	W	
	BUILDING MANAGER	O	N, W, S	
	DRESSING ROOM 1	O	W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	DRESSING ROOM 2	O	W	
	EAST WING	O	E, W, S	
	GREEN ROOM	O	E, W	
	WEST WING	O	E	
	MEN'S RESTROOM	O	S	
	WOMEN'S RESTROOM	O	N	
	EXTERIOR	O	W	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, FLUSH	ROOM L100	C	*	S
	ROOM L107	C	*	
	STORAGE 3	C	*	
	BAND	C	*	
	BAND STORAGE	C	*	
	OFFICE 1	C	*	
	ROOM L103	C	*	
	TABLE STORAGE	C	*	
	ROOM L104	C	*	
	ROOM L104 CLOSET	C	*	
	STORAGE 1	C	*	
	ROOM L105	C	*	
	STORAGE 4	C	*	
	DRESSING ROOM 1	C	*	
	DRESSING ROOM 2	C	*	
	EAST WING	C	*	
	GREEN ROOM	C	*	
	STAGE	C	*	
	WEST WING	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM L100	W	N, E, W, S	S
	ROOM L107	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	BAND	C, W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	STORAGE 2	C	*	
	HALL 1	C, W	N, E, W, S	
	ROOM L103	W	N, E, W, S	
	TABLE STORAGE	W	N, E, W, S	
	ROOM L104	W	N, E, W, S	
	ROOM L104 CLOSET	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	ROOM L105	W	N, E, W, S	
	MULTI-PURPOSE STORAGE	C, W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	DRESSING ROOM 1	W	N, E, W, S	
	DRESSING ROOM 2	W	N, E, W, S	
	EAST WING	W	N, E, W, S	
	GREEN ROOM	W	N, E, W, S	
	STAGE	W	N, E, W, S	
	WEST WING	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ROOM L100	W	N, E, W, S	S
	ROOM L107	W	N, E, W, S	
	BAND	C, W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	STORAGE 2	C	*	
	HALL 1	C, W	N, E, W, S	
	ROOM L103	W	N, E, W, S	
	TABLE STORAGE	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ROOM L104	W	N, E, W, S	
	ROOM L104 CLOSET	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	ROOM L105	W	N, E, W, S	
	MULTI-PURPOSE STORAGE	C, W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	
	STORAGE 4	W	N, E, W, S	
	DRESSING ROOM 1	W	N, E, W, S	
	DRESSING ROOM 2	W	N, E, W, S	
	EAST WING	W	N, E, W, S	
	GREEN ROOM	W	N, E, W, S	
	STAGE	W	N, E, W, S	
	WEST WING	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ROOM L100	W	N, E, W, S	S
	ROOM L107	W	N, E, W, S	
	BAND	C, W	N, E, W, S	
	OFFICE 1	W	N, E, W, S	
	STORAGE 2	C	*	
	HALL 1	C, W	N, E, W, S	
	ROOM L103	W	N, E, W, S	
	TABLE STORAGE	W	N, E, W, S	
	ROOM L104	W	N, E, W, S	
	ROOM L104 CLOSET	W	N, E, W, S	
	STORAGE 1	W	N, E, W, S	
	ROOM L105	W	N, E, W, S	
	MULTI-PURPOSE STORAGE	C, W	N, E, W, S	
	OFFICE 4	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	STORAGE 4	W	N, E, W, S	
	DRESSING ROOM 1	W	N, E, W, S	
	DRESSING ROOM 2	W	N, E, W, S	
	EAST WING	W	N, E, W, S	
	GREEN ROOM	W	N, E, W, S	
	STAGE	W	N, E, W, S	
	WEST WING	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	ROOM L100	W	N, E, W	S
	ROOM L107	W	N, E, W	
	ROOM L103	W	N, W, S	
	ROOM L104	W	N, E, S	
	ROOM L105	W	N, E, S	
CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	LOBBY	F	*	S
	VESTIBULE 3	F	*	
	ROOM L100	F	*	
	ROOM L107	F	*	
	STORAGE 3	F	*	
	BAND	F	*	
	OFFICE 1	F	*	
	STORAGE 2	F	*	
	ROOM L103	F	*	
	ROOM L104	F	*	
	ROOM L105	F	*	
	GREEN ROOM	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	ROOM L100	F	*	S
	ROOM L107	F	*	
	ELECTRICAL	F	*	
	BAND	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	HALL 1	F	*	
	VESTIBULE 2	F	*	
	ROOM L103	F	*	
	TABLE STORAGE	F	*	
	ROOM L104	F	*	
	ROOM L104 CLOSET	F	*	
	STORAGE 1	F	*	
	ROOM L105	F	*	
	STORAGE 4	F	*	
	DRESSING ROOM 1	F	*	
	DRESSING ROOM 2	F	*	
	EAST WING	F	*	
	STAGE	F	*	
	WEST WING	F	*	
VINYL COMPOSITION TILE (PATTERN), 12"X12", GREEN, SMOOTH, BLACK SPECKS	MULTI-PURPOSE	F	*	S
VINYL COMPOSITION TILE (PATTERN), 12"X12", PINK, SMOOTH, BLACK SPECKS	MULTI-PURPOSE	F	*	S
VINYL COMPOSITION TILE (PATTERN), 12"X12", LIGHT BLUE, SMOOTH, BLACK SPECKS	MULTI-PURPOSE	F	*	S
MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE (PATTERN), 12"X12", GREEN, SMOOTH, BLACK SPECKS AND VINYL COMPOSITION TILE (PATTERN), 12"X12", PINK, SMOOTH, BLACK SPECKS AND VINYL COMPOSITION TILE (PATTERN), 12"X12", LIGHT BLUE, SMOOTH, BLACK SPECKS AND VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, TAN MOTTLES	ROOM L100	F	*	S
	ROOM L107	F	*	
	ELECTRICAL	F	*	
	BAND	F	*	
	HALL 1	F	*	
	VESTIBULE 2	F	*	
	ROOM L103	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ROOM L104	F	*	
	ROOM L104 CLOSET	F	*	
	STORAGE 1	F	*	
	ROOM L105	F	*	
	MULTI-PURPOSE	F	*	
	STORAGE 4	F	*	
	DRESSING ROOM 1	F	*	
	DRESSING ROOM 2	F	*	
	EAST WING	F	*	
	STAGE	F	*	
	WEST WING	F	*	
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	LOBBY	O	E, W, S	S
	VESTIBULE 3	O	N, E, S	
	ROOM L100	O	N, E, W, S	
	ROOM L107	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	ELECTRICAL	O	N, E, W, S	
	BAND	O	N, E, W, S	
	BAND STORAGE	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	HALL 1	O	N, E, W, S	
	VESTIBULE 2	O	N, E, W, S	
	ROOM L103	O	N, E, W, S	
	TABLE STORAGE	O	N, E, W, S	
	ROOM L104	O	N, E, W, S	
	ROOM L104 CLOSET	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ROOM L105	O	N, E, W, S	
	VESTIBULE 1	O	N, E, W, S	
	MULTI-PURPOSE	O	N, E, W, S	
	MULTI-PURPOSE STORAGE	O	N, E, W, S	
	CONCESSION 2	O	N, E, W, S	
	VESTIBULE 4	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	BUILDING MANAGER	O	N, E, W, S	
	DRESSING ROOM 1	O	N, E, W, S	
	DRESSING ROOM 2	O	N, E, W, S	
	EAST WING	O	N, E, W, S	
	GREEN ROOM	O	N, E, W, S	
	WEST WING	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	LOBBY	O	E, W, S	S
	VESTIBULE 3	O	N, E, S	
	ROOM L100	O	N, E, W, S	
	ROOM L107	O	N, E, W, S	
	STORAGE 3	O	N, E, W, S	
	ELECTRICAL	O	N, E, W, S	
	BAND	O	N, E, W, S	
	BAND STORAGE	O	N, E, W, S	
	OFFICE 1	O	N, E, W, S	
	STORAGE 2	O	N, E, W, S	
	HALL 1	O	N, E, W, S	
	VESTIBULE 2	O	N, E, W, S	
	ROOM L103	O	N, E, W, S	
	TABLE STORAGE	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM L104	O	N, E, W, S	
	ROOM L104 CLOSET	O	N, E, W, S	
	STORAGE 1	O	N, E, W, S	
	ROOM L105	O	N, E, W, S	
	VESTIBULE 1	O	N, E, W, S	
	MULTI-PURPOSE	O	N, E, W, S	
	MULTI-PURPOSE STORAGE	O	N, E, W, S	
	CONCESSION 2	O	N, E, W, S	
	VESTIBULE 4	O	N, E, W, S	
	STORAGE 4	O	N, E, W, S	
	BUILDING MANAGER	O	N, E, W, S	
	DRESSING ROOM 1	O	N, E, W, S	
	DRESSING ROOM 2	O	N, E, W, S	
	EAST WING	O	N, E, W, S	
	GREEN ROOM	O	N, E, W, S	
	WEST WING	O	N, E, W, S	
SINK ACOUSTICAL COATING, GRAY, ROUGH	ROOM L100	O	S	
	ROOM L107	O	S	
	BAND	O	S	
	ROOM L103	O	E	
	ROOM L104	O	W	
	ROOM L105	O	W	
GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	C	*	S
	VESTIBULE 3	C	*	
	ROOM L100	C	*	
	ROOM L107	C	*	
	STORAGE 3	C	*	
	ELECTRICAL	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	BAND	C	*	
	BAND STORAGE	C	*	
	OFFICE 1	C	*	
	OFFICE 2	C	*	
	OFFICE 3	C	*	
	STORAGE 2	C	*	
	CONCESSION 1	C	*	
	UNISEX RESTROOM 1	C	*	
	STAFF RESTROOM	C	*	
	HALL 1	C	*	
	JANITOR	C	*	
	VESTIBULE 2	C	*	
	ROOM L103	C	*	
	TABLE STORAGE	C	*	
	ROOM L104	C	*	
	ROOM L104 CLOSET	C	*	
	STORAGE 1	C	*	
	ROOM L105	C	*	
	VESTIBULE 1	C	*	
	MULTI-PURPOSE	C	*	
	MULTI-PURPOSE STORAGE	C	*	
	DISH WASHER	C	*	
	UNISEX RESTROOM 2	C	*	
	LOCKER ROOM	C	*	
	WALK IN 1	C	*	
	WALK IN 2	C	*	
	LAUNDRY ROOM	C	*	
	OFFICE 4	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	SERVING	C	*	
	SERVING STORAGE	C	*	
	CONCESSION 2	C	*	
	VESTIBULE 4	C	*	
	STORAGE 4	C	*	
	BUILDING MANAGER	C	*	
	DRESSING ROOM 1	C	*	
	DRESSING ROOM 2	C	*	
	EAST WING	C	*	
	GREEN ROOM	C	*	
	STAGE	C	*	
	WEST WING	C	*	
	MEN'S RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	C	*	S
	VESTIBULE 3	C	*	
	ROOM L100	C	*	
	ROOM L107	C	*	
	STORAGE 3	C	*	
	ELECTRICAL	C	*	
	BAND	C	*	
	BAND STORAGE	C	*	
	OFFICE 1	C	*	
	OFFICE 2	C	*	
	OFFICE 3	C	*	
	STORAGE 2	C	*	
	CONCESSION 1	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	UNISEX RESTROOM 1	C	*	
	STAFF RESTROOM	C	*	
	HALL 1	C	*	
	JANITOR	C	*	
	VESTIBULE 2	C	*	
	ROOM L103	C	*	
	TABLE STORAGE	C	*	
	ROOM L104	C	*	
	ROOM L104 CLOSET	C	*	
	STORAGE 1	C	*	
	ROOM L105	C	*	
	VESTIBULE 1	C	*	
	MULTI-PURPOSE	C	*	
	MULTI-PURPOSE STORAGE	C	*	
	DISH WASHER	C	*	
	UNISEX RESTROOM 2	C	*	
	LOCKER ROOM	C	*	
	WALK IN 1	C	*	
	WALK IN 2	C	*	
	LAUNDRY ROOM	C	*	
	OFFICE 4	C	*	
	SERVING	C	*	
	SERVING STORAGE	C	*	
	CONCESSION 2	C	*	
	VESTIBULE 4	C	*	
	STORAGE 4	C	*	
	BUILDING MANAGER	C	*	
	DRESSING ROOM 1	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	DRESSING ROOM 2	C	*	
	EAST WING	C	*	
	GREEN ROOM	C	*	
	STAGE	C	*	
	WEST WING	C	*	
	MEN'S RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
ADHESIVE (RESIDUAL), BROWN, BRITTLE	LOBBY	C	*	S
	VESTIBULE 3	C	*	
	ROOM L100	C	*	
	ROOM L107	C	*	
	STORAGE 3	C	*	
	ELECTRICAL	C	*	
	BAND	C	*	
	BAND STORAGE	C	*	
	OFFICE 1	C	*	
	OFFICE 2	C	*	
	OFFICE 3	C	*	
	STORAGE 2	C	*	
	CONCESSION 1	C	*	
	UNISEX RESTROOM 1	C	*	
	STAFF RESTROOM	C	*	
	HALL 1	C	*	
	JANITOR	C	*	
	VESTIBULE 2	C	*	
	ROOM L103	C	*	
	TABLE STORAGE	C	*	
	ROOM L104	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM L104 CLOSET	C	*	
	STORAGE 1	C	*	
	ROOM L105	C	*	
	VESTIBULE 1	C	*	
	MULTI-PURPOSE	C	*	
	MULTI-PURPOSE STORAGE	C	*	
	DISH WASHER	C	*	
	UNISEX RESTROOM 2	C	*	
	LOCKER ROOM	C	*	
	WALK IN 1	C	*	
	WALK IN 2	C	*	
	LAUNDRY ROOM	C	*	
	OFFICE 4	C	*	
	SERVING	C	*	
	SERVING STORAGE	C	*	
	CONCESSION 2	C	*	
	VESTIBULE 4	C	*	
	STORAGE 4	C	*	
	BUILDING MANAGER	C	*	
	DRESSING ROOM 1	C	*	
	DRESSING ROOM 2	C	*	
	EAST WING	C	*	
	GREEN ROOM	C	*	
	STAGE	C	*	
	WEST WING	C	*	
	MEN'S RESTROOM	C	*	
	WOMEN'S RESTROOM	C	*	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE, FLUSH	VESTIBULE 3	C	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Middle School, KSD
Building L

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	VESTIBULE 2	C	*	
	VESTIBULE 1	C	*	
	VESTIBULE 4	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	W	E, W, S	S
	VESTIBULE 3	W	N, E, S	
	VESTIBULE 2	W	N, E, W, S	
	VESTIBULE 1	W	N, E, W, S	
	VESTIBULE 4	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LOBBY	W	E, W, S	S
	VESTIBULE 3	W	N, E, S	
	VESTIBULE 2	W	N, E, W, S	
	VESTIBULE 1	W	N, E, W, S	
	VESTIBULE 4	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LOBBY	W	E, W, S	S
	VESTIBULE 3	W	N, E, S	
	VESTIBULE 2	W	N, E, W, S	
	VESTIBULE 1	W	N, E, W, S	
	VESTIBULE 4	W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	UNISEX RESTROOM 1	C, W	N, E, W, S	S
	STAFF RESTROOM	C, W	N, E, W, S	
	UNISEX RESTROOM 2	W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	UNISEX RESTROOM 1	C, W	N, E, W, S	S
	STAFF RESTROOM	C, W	N, E, W, S	
	UNISEX RESTROOM 2	W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WOMEN'S RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	UNISEX RESTROOM 1	C, W	N, E, W, S	S
	STAFF RESTROOM	C, W	N, E, W, S	
	UNISEX RESTROOM 2	W	N, E, W, S	
	MEN'S RESTROOM	C, W	N, E, W, S	
	WOMEN'S RESTROOM	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	STAFF RESTROOM	W	N, E, W, S	S
	MEN'S RESTROOM	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	STAFF RESTROOM	W	N, E, W, S	S
	MEN'S RESTROOM	W	N, E, W, S	
	WOMEN'S RESTROOM	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	STAFF RESTROOM	F	*	S
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	STAFF RESTROOM	F	*	S
	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
TROWELED-ON TEXTURE, WHITE, CHALKY	STORAGE 3	W	N, E, W, S	S
	ELECTRICAL	C, W	N, E, W, S	
	JANITOR	W	W	
	BUILDING MANAGER	C, W	N, E, W, S	
	UNISEX RESTROOM 2	C	*	
	LOCKER ROOM	C	*	
	LAUNDRY ROOM	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	STORAGE 3	W	N, E, W, S	S
	ELECTRICAL	C, W	N, E, W, S	
	JANITOR	W	W	
	BUILDING MANAGER	C, W	N, E, W, S	
	UNISEX RESTROOM 2	C	*	
	LOCKER ROOM	C	*	
	LAUNDRY ROOM	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 3	W	N, E, W, S	S
	ELECTRICAL	C, W	N, E, W, S	
	JANITOR	W	W	
	BUILDING MANAGER	C, W	N, E, W, S	
	UNISEX RESTROOM 2	C	*	
	LOCKER ROOM	C	*	
	LAUNDRY ROOM	C	*	
CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH	STORAGE 2	W	N, E, S	S
	JANITOR	W	N, E, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH	STORAGE 2	W	N, E, S	S
	JANITOR	W	N, E, S	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	JANITOR	F	*	S
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	JANITOR	F	*	S
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	JANITOR	O	N, E, W, S	S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	JANITOR	O	N, E, W, S	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	STORAGE 2	W	E	S
	STAGE	O	*	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	STORAGE 2	W	E	S
	STAGE	O	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
WALLBASE (COVED), 4", BLACK, VINYL-LIKE	OFFICE 2	O	N, E, W, S	S
	OFFICE 3	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	OFFICE 2	O	N, E, W, S	S
	OFFICE 3	O	N, E, W, S	
ACOUSTICAL CEILING PANEL, 2'X4', WHITE, CHALKY, VINYL COVER	CONCESSION 1	C	*	S
	DISH WASHER	C	*	
	OFFICE 4	C	*	
	SERVING	C	*	
	CONCESSION 2	C	*	
QUARRY/PAVER TILE, 6"X6", BROWN, SMOOTH	CONCESSION 1	F	*	S
	UNISEX RESTROOM 2	F	*	
	LOCKER ROOM	F	*	
	LAUNDRY ROOM	F	*	
	OFFICE 4	F	*	
	SERVING	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", BROWN, SMOOTH	CONCESSION 1	F	*	S
	UNISEX RESTROOM 2	F	*	
	LOCKER ROOM	F	*	
	LAUNDRY ROOM	F	*	
	OFFICE 4	F	*	
	SERVING	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	LOBBY	C	*	S
GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	MEN'S RESTROOM	W	N, E, W, S	S
	WOMEN'S RESTROOM	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	MEN'S RESTROOM	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Middle School, KSD
Building L*

JOB NO. 08-145

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	WOMEN'S RESTROOM	F	*	
CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	MEN'S RESTROOM	F	*	
	WOMEN'S RESTROOM	F	*	
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	MULTI-PURPOSE	C	*	S
VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, TAN MOTTLES	VESTIBULE 2	F	*	S
	VESTIBULE 1	F	*	
	MULTI-PURPOSE STORAGE	F	*	
	CONCESSION 2	F	*	
	VESTIBULE 4	F	*	
VINYL STAIR TREAD, 12"X36", BLACK, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE	F	*	S
MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X36", BLACK, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE	F	*	S
ADHESIVE (MIRROR), BROWN, BRITTLE	GREEN ROOM	W	S	S
VINYL COMPOSITION TILE, 12"X12", OFF-WHITE, SMOOTH, BROWN MOTTLES	BUILDING MANAGER	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", OFF-WHITE, SMOOTH, BROWN MOTTLES	BUILDING MANAGER	F	*	S
FIBROUS GLASS REINFORCED PANEL, WHITE, TEXTURED	BUILDING MANAGER	W	N, W, S	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBROUS GLASS REINFORCED PANEL, WHITE, TEXTURED	BUILDING MANAGER	W	N, W, S	S
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH, TAN MARBLE PATTERN	UNISEX RESTROOM 2	W	N, E, W, S	S
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH, TAN MARBLE PATTERN	UNISEX RESTROOM 2	W	N, E, W, S	S

* - **Not Applicable**

END OF TABLE

2.4 AHERA Inspection Procedures and Protocols

2.4.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.4.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.5 Visual Inspection

A visual inspection of the seven buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.

2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials

TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS

BUILDING E
BUILDING F
BUILDING G
BUILDING H
BUILDING J
BUILDING K
BUILDING L

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building E*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	22,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	100	SF
M-SLT-03	SEALANT (DOORS, WALLS, FLASHINGS), BROWN, PLIABLE	A	NF	50	SF
M-SLT-04	SEALANT (FLASHINGS), GRAY, PLIABLE	A	NF	25	SF
M-BRK-05	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	8,000	SF
M-CMU-06	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	A	NF	1,500	SF
M-CMU-07	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH	A	NF	1,500	SF
M-CMU-08	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	A	NF	1,500	SF
M-CMU-09	CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	5,000	SF
M-MRT-10	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,850	SF
M-SLT-11	SEALANT (FLASHINGS), BLACK, PLIABLE	A	NF	10	SF
M-CMU-12	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	50	SF
S-STU-13	STUCCO, GRAY, CEMENTITIOUS	A	NF	1,500	SF
M-MRT-14	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	10	SF
M-SLT-15	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES, WALLS), WHITE, PLIABLE	A	NF	32	SF
M-CON-16	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-CON-17	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	24,000	SF
M-FDI-18	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,029	SF
S-SAF-19	SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	S	F	9,000	SF
M-CMU-20	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-PES-21	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M-DST-22	DUCT SEAM TAPE, 4", WHITE, CANVAS-LIKE	S	F	25	SF
M-SLT-23	SEALANT (DUCT), LIGHT GRAY, PLIABLE	A	NF	5	SF
M-WDB-24	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	10	SF
M-GWB-25	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
S-JTC-26	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	30	SF
M-SLT-27	SEALANT (FIRE STOP), WHITE, PLIABLE	A	NF	10	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building E*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-TOT-28	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
M-GWB-29	GYPNUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,000	SF
S-JTC-30	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPNUM WALLBOARD, WHITE, CHALKY	A	NF	200	SF
M-APL-31	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,500	SF
S-SAT-32	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	4,500	SF
M-GWB-33	GYPNUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	4,500	SF
S-JTC-34	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPNUM WALLBOARD, WHITE, CHALKY	A	NF	450	SF
M-VCT-35	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	3,500	SF
M-MAS-36	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	3,500	SF
M-WAB-37	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	250	SF
M-ADH-38	ADHESIVE, CREAM, PLIABLE ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	250	SF
S-SAT-39	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	12,000	SF
M-GWB-40	GYPNUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	12,000	SF
S-JTC-41	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPNUM WALLBOARD, WHITE, CHALKY	A	NF	1,200	SF
M-GWT-42	GLAZED WALL TILE, 4", LIGHT GREEN, SMOOTH	A	NF	2,000	SF
M-GWT-43	GLAZED WALL TILE, 4", GREEN, SMOOTH	A	NF	2,000	SF
M-GRT-44	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE, 4", GREEN, SMOOTH	A	NF	400	SF
M-GWT-45	GLAZED WALL TILE, 6"X8", WHITE, SMOOTH	A	NF	3,000	SF
M-GRT-46	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 6"X8", WHITE, SMOOTH	A	NF	300	SF
M-CMT-47	CERAMIC MOSAIC TILE, 4"X4", WHITE, SMOOTH	A	NF	4,000	SF
M-GRT-48	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 4"X4", WHITE, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	A	NF	400	SF
M-CPT-49	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	A	NF	750	SF
M-CON-50	CONCRETE, WHITE, CEMENTITIOUS, BLUE SPECKS	A	NF	75	SF
M-GWT-51	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	200	SF
M-ADH-52	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	12	SF
M-WAB-53	WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	A	NF	15	SF
M-ADH-54	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	A	NF	15	SF
M-CMT-55	CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	A	NF	750	SF
M-CMT-56	CERAMIC MOSAIC TILE (PATTERN), 2"X2", GREEN, SMOOTH	A	NF	250	SF
M-CMT-57	CERAMIC MOSAIC TILE (PATTERN), 2"X2", TAN, SMOOTH	A	NF	250	SF
M-APL-58	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	S	F	500	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building E*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-WAB-59	WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	A	NF	125	SF
M-ADH-60	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (L-SHAPED), 4", BLACK, VINYL-LIKE	A	NF	125	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building F*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	20,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	100	SF
M-SLT-03	SEALANT (FLASHING), GRAY, PLIABLE	A	NF	50	SF
M-WDB-04	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	50	SF
M-SLT-05	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-SLT-06	SEALANT (DUCT), PINK, PLIABLE	A	NF	50	SF
M-BRK-07	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	5,000	SF
M-CMU-08	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	A	NF	5,000	SF
M-CMU-09	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	A	NF	1,000	SF
M-CMU-10	CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	100	SF
M-CMU-11	CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	100	SF
M-MRT-12	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,200	SF
M-SLT-13	SEALANT (DOORS, MILLWORK, WALLS), WHITE, PLIABLE	A	NF	100	SF
M-SLT-14	SEALANT (WALLS), BROWN, PLIABLE	A	NF	50	SF
M-SLT-15	SEALANT (WALLS), GRAY, PLIABLE	A	NF	50	SF
M-MRT-16	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	50	SF
M-GWT-17	GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	A	NF	100	SF
M-GRT-18	GROUT, BROWN, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	A	NF	10	SF
S-TOT-19	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
M-GWB-20	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S-JTC-21	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	250	SF
M-CON-22	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	12,500	SF
M-CON-23	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	25,000	SF
M-APL-24	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	A	F	2,500	SF
M-GWB-25	GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	3,750	SF
S-JTC-26	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	400	SF
M-CPT-27	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	A	NF	16,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building F*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VCT-28	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	7,500	SF
M-MAS-29	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK SPECKS	A	NF	8,000	SF
M-WAB-30	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	500	SF
M-ADH-31	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	500	SF
M-FDI-32	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,323	SF
S-SAT-33	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,200	SF
S-SAT-34	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	23,000	SF
M-GWB-35	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	23,000	SF
S-JTC-36	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	2,300	SF
M-APL-37	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	16,500	SF
M-SAC-38	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	30	SF
M-VCT-39	VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK SPECKS	A	NF	500	SF
S-SAT-40	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
M-GWB-41	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
S-JTC-42	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	350	SF
M-GWT-43	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	2,500	SF
M-GWT-44	GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	A	NF	250	SF
M-GWT-45	GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	A	NF	250	SF
M-GRT-46	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	A	NF	300	SF
M-CMT-47	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	A	NF	1,000	SF
M-CMT-48	CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH	A	NF	150	SF
M-CMT-49	CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	A	NF	150	SF
M-GRT-50	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	A	NF	130	SF
M-TWP-51	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	3,500	SF
M-SLT-52	SEALANT (DOORS, WINDOWS), BLACK, TAR-LIKE	A	NF	15	SF
S-SAF-53	SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	S	F	350	SF
M-SLT-54	SEALANT (FIRE STOP), GREEN, PLIABLE	A	NF	100	SF
M-ADH-55	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	A	NF	25	SF
M-VST-56	VINYL STAIR TREAD, 12"X60", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building F*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·MAS·57	MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X60", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF
M·VCT·58	VINYL COMPOSITION TILE, 24"X24", GRAY, SMOOTH	A	NF	250	SF
M·MAS·59	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, SMOOTH	A	NF	250	SF
M·PES·60	PIPE END SEALANT, WHITE, PLIABLE	A	NF	50	SF
M·CMU·61	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	100	SF
M·GAS·62	GASKET, 4", BLACK, RUBBER-LIKE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building G*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	20,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	100	SF
M-SLT-03	SEALANT (FLASHING), GRAY, PLIABLE	A	NF	50	SF
M-WDB-04	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	50	SF
M-SLT-05	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-SLT-06	SEALANT (DUCT), PINK, PLIABLE	A	NF	50	SF
M-BRK-07	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	5,000	SF
M-CMU-08	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	A	NF	5,000	SF
M-CMU-09	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	A	NF	1,000	SF
M-CMU-10	CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	100	SF
M-CMU-11	CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	100	SF
M-MRT-12	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	1,200	SF
M-SLT-13	SEALANT (DOORS, MILLWORK, WALLS), WHITE, PLIABLE	A	NF	50	SF
M-SLT-14	SEALANT (DOORS, WALLS, FLASHING), BROWN, PLIABLE	A	NF	25	SF
M-SLT-15	SEALANT (WALLS), GRAY, PLIABLE	A	NF	50	SF
M-MRT-16	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	50	SF
M-GWT-17	GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	A	NF	100	SF
M-GRT-18	GROUT, BROWN, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	A	NF	10	SF
S-TOT-19	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
M-GWB-20	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S-JTC-21	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	250	SF
M-CON-22	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	12,500	SF
M-CON-23	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	25,000	SF
M-APL-24	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,500	SF
M-GWB-25	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	3,750	SF
S-JTC-26	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	400	SF
M-CPT-27	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	A	NF	16,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building G*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VCT-28	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	5,000	SF
M-MAS-29	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", BLUE, SMOOTH, BLACK SPECKS	A	NF	6,000	SF
M-WAB-30	WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	500	SF
M-ADH-31	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	500	SF
M-FDI-32	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,302	SF
S-SAT-33	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,200	SF
S-SAT-34	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	23,000	SF
M-GWB-35	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	23,000	SF
S-JTC-36	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	2,300	SF
M-APL-37	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	16,500	SF
M-SAC-38	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	30	SF
M-VCT-39	VINYL COMPOSITION TILE, 12"X12", BLUE, SMOOTH, BLACK SPECKS	A	NF	2,000	SF
S-SAT-40	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
M-GWB-41	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
S-JTC-42	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	350	SF
M-GWT-43	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	2,500	SF
M-GWT-44	GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	A	NF	250	SF
M-GWT-45	GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	250	SF
M-GRT-46	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	300	SF
M-CMT-47	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	A	NF	1,000	SF
M-CMT-48	CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH	A	NF	150	SF
M-CMT-49	CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	A	NF	150	SF
M-GRT-50	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE (PATTERN), 2"X2", DARK GREEN, SMOOTH	A	NF	130	SF
M-TWP-51	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	3,500	SF
M-SLT-52	SEALANT (DOORS, WINDOWS), BLACK, TAR-LIKE	A	NF	15	SF
S-SAF-53	SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	S	F	350	SF
M-SLT-54	SEALANT (FIRE STOP), GREEN, PLIABLE	A	NF	50	SF
M-ADH-55	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	A	NF	25	SF
M-VST-56	VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building G*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·MAS·57	MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF
M·VCT·58	VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	A	NF	250	SF
M·MAS·59	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	A	NF	250	SF
M·PES·60	PIPE END SEALANT, WHITE, PLIABLE	A	NF	50	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building H*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	16,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	100	SF
M-SLT-03	SEALANT (FLASHING), GRAY, PLIABLE	A	NF	50	SF
M-WDB-04	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	50	SF
M-SLT-05	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-SLT-06	SEALANT (DUCT), PINK, PLIABLE	A	NF	50	SF
M-CMU-07	CONCRETE MASONRY UNIT, 4"X16", RED, CEMENTITIOUS	A	NF	5,000	SF
M-CMU-08	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	A	NF	5,000	SF
M-CMU-09	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH	A	NF	1,000	SF
M-CMU-10	CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	100	SF
M-CMU-11	CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	100	SF
M-MRT-12	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, ROUGH AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS, SMOOTH AND CONCRETE MASONRY UNIT, 8"X8", DARK GRAY, CEMENTITIOUS, SMOOTH	A	NF	1,500	SF
M-SLT-13	SEALANT (DOORS, WINDOWS, MILLWORK, WALLS), WHITE, PLIABLE	A	NF	100	SF
M-SLT-14	SEALANT (WALLS), BROWN, PLIABLE	A	NF	50	SF
M-SLT-15	SEALANT (WALLS), GRAY, PLIABLE	A	NF	50	SF
M-MRT-16	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	50	SF
M-GWT-17	GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	A	NF	100	SF
M-GRT-18	GROUT, BROWN, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", LIGHT GREEN, SMOOTH	A	NF	10	SF
S-TOT-19	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
M-GWB-20	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S-JTC-21	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	250	SF
M-CON-22	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	2,000	SF
M-CON-23	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	32,000	SF
M-APL-24	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	S	F	2,500	SF
M-GWB-25	GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	7,000	SF
S-JTC-26	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	700	SF
M-CPT-27	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	S	NF	32,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building H*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VCT-28	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	5,000	SF
M-MAS-29	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	5,500	SF
M-WAB-30	WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	1,000	SF
M-ADH-31	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	1,000	SF
M-FDI-32	FIRE DOOR INSULATION, METAL/WOOD CLADDING	A	NF	1,260	SF
S-SAT-33	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,200	SF
S-SAT-34	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	23,000	SF
M-GWB-35	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	23,000	SF
S-JTC-36	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	2,300	SF
M-APL-37	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	16,500	SF
M-SAC-38	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	30	SF
M-VCT-39	VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, BLACK SPECKS	A	NF	500	SF
S-SAT-40	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
M-GWB-41	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,500	SF
S-JTC-42	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	350	SF
M-GWT-43	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	2,500	SF
M-GWT-44	GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	A	NF	250	SF
M-GWT-45	GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	A	NF	250	SF
M-GRT-46	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", DARK GREEN, SMOOTH	A	NF	300	SF
M-CMT-47	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	A	NF	1,000	SF
M-CMT-48	CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	A	NF	150	SF
M-CMT-49	CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	150	SF
M-GRT-50	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	130	SF
M-TWP-51	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	3,500	SF
M-SLT-52	SEALANT (DOORS, WINDOWS), BLACK, TAR-LIKE	A	NF	15	SF
S-SAF-53	SPRAY-APPLIED FIREPROOFING, GRAY, CHALKY, FIBROUS	S	F	350	SF
M-SLT-54	SEALANT (FIRE STOP), GREEN, PLIABLE	A	NF	100	SF
M-ADH-55	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, TAN, TEXTURED	A	NF	25	SF
M-VST-56	VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF
M-MAS-57	MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X60", BLACK, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building H*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VCT-58	VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	A	NF	250	SF
M-MAS-59	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", BLACK, SMOOTH	A	NF	250	SF
M-PES-60	PIPE END SEALANT, WHITE, PLIABLE	A	NF	100	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building J*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S-TOT-01	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	5,000	SF
M-GWB-02	GYPNUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	5,000	SF
S-JTC-03	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPNUM WALLBOARD, WHITE, CHALKY	A	NF	500	SF
S-STU-04	STUCCO, GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-CMU-05	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	A	NF	7,000	SF
M-BRK-06	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	2,200	SF
M-CMU-07	CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS	A	NF	150	SF
M-MRT-08	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	A	NF	950	SF
M-SLT-09	SEALANT (DOORS, WINDOWS, WALLS), GRAY, PLIABLE	A	NF	50	SF
M-SLT-10	SEALANT (DOORS), TAN, PLIABLE	A	NF	16	SF
M-CON-11	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	7,000	SF
M-CON-12	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	8,000	SF
M-CMU-13	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	500	SF
M-MRT-14	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	50	SF
M-CMU-15	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	A	NF	150	SF
M-MRT-16	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS	A	NF	300	SF
M-FDI-17	FIRE DOOR INSULATION, WOOD/METAL CLADDING	A	NF	588	SF
M-CMU-18	CONCRETE MASONRY UNIT, 4"X16", DARK GRAY, CEMENTITIOUS	A	NF	50	SF
M-APL-19	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	9,000	SF
S-SAT-20	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
M-GWB-21	GYPNUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	9,000	SF
S-JTC-22	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPNUM WALLBOARD, WHITE, CHALKY	S	NF	900	SF
M-CPT-23	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	S	NF	3,500	SF
M-VCT-24	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	6,000	SF
M-VCT-25	VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK, SPECKS	A	NF	500	SF
M-MAS-26	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE, 12"X12", GREEN, SMOOTH, BLACK SPECKS	A	NF	6,500	SF
M-WAB-27	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	400	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building J*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-ADH-28	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	400	SF
M-SLT-29	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	43	SF
M-SAC-30	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	28	NF
M-GWB-31	GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	9,000	SF
S-JTC-32	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	900	SF
M-ADH-33	ADHESIVE (RESIDUAL), BROWN, BRITTLE	A	NF	3,000	SF
M-TWP-34	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	2,000	SF
S-SAT-35	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,500	SF
M-GWB-36	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,500	SF
S-JTC-37	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	150	SF
M-GWT-38	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	1,000	SF
M-GWT-39	GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	A	NF	100	SF
M-GWT-40	GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	100	SF
M-GRT-41	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	120	SF
M-CMT-42	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	A	NF	1,000	SF
M-CMT-43	CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	A	NF	100	SF
M-CMT-44	CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	100	SF
M-GRT-45	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	120	SF
M-PSL-46	PIPE SEALANT, WHITE, PLIABLE	A	NF	5	SF
M-GAS-47	GASKET, 4", BLACK, RUBBER-LIKE	A	NF	5	SF
M-ADH-48	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	25	SF
S-SAT-49	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
M-GWB-50	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
S-JTC-51	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
M-CON-52	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	4,000	SF
M-WDB-53	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	50	SF
M-PLA-54	PLASTER, GRAY, CEMENTITIOUS	A	NF	400	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building K*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	17,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	150	SF
M-SLT-03	SEALANT (FLASHING), GRAY, PLIABLE	A	NF	50	SF
S-STU-04	STUCCO, GRAY, CEMENTITIOUS	A	NF	3,000	SF
M-CMU-05	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	A	NF	9,500	SF
M-MRT-06	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, TAN	A	NF	950	SF
M-SLT-07	SEALANT (WALL, FLASHING), TAN, PLIABLE	A	NF	35	SF
M-SLT-08	SEALANT (DUCT), LIGHT GRAY, PLIABLE	A	NF	50	SF
M-SLT-09	SEALANT (DUCT), GRAY, PLIABLE	A	NF	50	SF
M-CON-10	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	7,000	SF
M-CON-11	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	17,500	SF
M-SLT-12	SEALANT (WINDOWS), BLACK, TAR-LIKE	A	NF	16	SF
M-FDI-13	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	609	SF
M-APL-14	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	4,500	SF
S-SAT-15	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	13,000	SF
M-GWB-16	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	13,000	SF
S-JTC-17	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	1,300	SF
M-TWP-18	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	700	SF
M-CPT-19	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	S	NF	13,500	SF
M-WAB-20	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	600	SF
M-ADH-21	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	600	SF
M-SLT-22	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	80	SF
M-APL-23	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	14,000	SF
M-GWB-24	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH WALL PAPER, TAN, CLOTH-LIKE AND SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	5,000	SF
S-JTC-25	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	500	SF
M-VCT-26	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	3,500	SF
M-MAS-27	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	3,500	SF
S-SAT-28	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,600	SF
S-SAC-29	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	10	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building K*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-GWT-30	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	1,000	SF
M-GRT-31	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	150	SF
M-CMT-32	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	A	NF	800	SF
M-GRT-33	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	100	SF
S-SAT-34	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
M-GWB-35	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S-JTC-36	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	250	SF
S-TOT-37	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	700	SF
M-GWB-38	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	700	SF
S-JTC-39	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	70	SF
M-APL-40	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	100	SF
M-GWT-41	GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	A	NF	250	SF
M-GWT-42	GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	250	SF
M-CMT-43	CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	A	NF	100	SF
M-CMT-44	CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	100	SF
M-ADH-45	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	15	SF
M-PES-46	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building L*

JOB NO. 08-145

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-BUR-01	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	16,000	SF
M-MAS-02	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	150	SF
M-MAS-03	MASTIC (FLASHING), GRAY, PLIABLE	A	NF	50	SF
M-SLT-04	SEALANT (WALLS, FLASHING), BROWN, TAR-LIKE	A	NF	50	SF
M-SLT-05	SEALANT (DOORS, WINDOWS, WALLS, FLASHINGS), BLACK, PLIABLE	A	NF	50	SF
M-CMU-06	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	A	NF	7,500	SF
M-MRT-07	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS	A	NF	750	SF
M-SLT-08	SEALANT (DOORS, FLASHING), GRAY, PLIABLE	A	NF	25	SF
M-SLT-09	SEALANT (FLASHING), WHITE, TAR-LIKE	A	NF	15	SF
M-SLT-10	SEALANT (DUCT), WHITE, TAR-LIKE	A	NF	10	SF
M-SLT-11	SEALANT (DUCT), GRAY, BRITTLE	A	NF	10	SF
M-WDB-12	WOVEN DUCT BOOT, 2", BLACK, RUBBER-LIKE	A	NF	10	SF
M-SLT-13	SEALANT (DUCT), GRAY, TAR-LIKE	A	NF	10	SF
S-STU-14	STUCCO, GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-CON-15	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-CON-16	CONCRETE (FOUNDATION), GRAY, CEMENTITIOUS	A	NF	16,000	SF
M-FDI-17	FIRE DOOR INSULATION, METALWOOD CLADDING	A	NF	1,596	SF
S-SAT-18	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,000	SF
M-CMU-19	CONCRETE MASONRY UNIT (PATCH), 4"X16", GRAY, CEMENTITIOUS	A	NF	500	SF
M-MRT-20	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT (PATCH), 4"X16", GRAY, CEMENTITIOUS	A	NF	50	SF
M-BRK-21	BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	2,000	SF
M-MRT-22	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS	A	NF	200	SF
M-SLT-23	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES, WALLS)	A	NF	50	SF
M-APL-24	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, FLUSH	S	F	12,500	SF
S-SAT-25	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	9,500	SF
M-GWB-26	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	9,500	SF
S-JTC-27	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	950	SF
M-TWP-28	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	S	NF	2,000	SF
M-CPT-29	CARPET, GRAY, FIBROUS, MULTI-COLORED, SELF-STICK	A	NF	7,200	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building L*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VCT-30	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED	A	NF	6,000	SF
M-VCT-31	VINYL COMPOSITION TILE (PATTERN), 12"X12", GREEN, SMOOTH, BLACK SPECKS	A	NF	500	SF
M-VCT-32	VINYL COMPOSITION TILE (PATTERN), 12"X12", PINK, SMOOTH, BLACK SPECKS	A	NF	500	SF
M-VCT-33	VINYL COMPOSITION TILE (PATTERN), 12"X12", LIGHT BLUE, SMOOTH, BLACK SPECKS	A	NF	500	SF
M-MAS-34	MASTIC, ORANGE, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, MULTI-COLORED AND VINYL COMPOSITION TILE (PATTERN); 12"X12", GREEN, SMOOTH, BLACK SPECKS AND VINYL COMPOSITION TILE (PATTERN), 12"X12", PINK, SMOOTH, BLACK SPECKS AND VINYL COMPOSITION TILE (PATTERN), 12"X12", LIGHT BLUE, SMOOTH, BLACK SPECKS AND VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, TAN MOTTLES	A	NF	7,500	SF
M-WAB-35	WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	700	SF
M-ADH-36	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLACK, VINYL-LIKE	A	NF	700	SF
M-SAC-37	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	12	SF
M-GWB-38	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	16,000	SF
S-JTC-39	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	16,000	SF
M-ADH-40	ADHESIVE (RESIDUAL), BROWN, BRITTLE	A	NF	4,000	SF
M-APL-41	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE, FLUSH	S	F	1,000	SF
S-SAT-42	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	3,750	SF
M-GWB-43	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	3,750	SF
S-JTC-44	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	375	SF
S-SAT-45	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
M-GWB-46	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
S-JTC-47	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
M-GWT-48	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	1,500	SF
M-GRT-49	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH AND GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	200	SF
M-CMT-50	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH	A	NF	1,000	SF
M-GRT-51	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH AND CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	130	SF
S-TOT-52	TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
M-GWB-53	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	A	NF	3,000	SF
S-JTC-54	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	300	SF
M-CMU-55	CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH	A	NF	300	SF
M-MRT-56	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 4"X16", GRAY, CEMENTITIOUS, SMOOTH	A	NF	300	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De La Paloma Elementary School, KSD
Building L*

JOB NO. 08-145

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-VCT-57	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	A	NF	75	SF
M-MAS-58	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, TAN MOTTLES	A	NF	75	SF
M-WAB-59	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	15	SF
M-ADH-60	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	15	SF
M-CMU-61	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,300	SF
M-MRT-62	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	130	SF
M-WAB-63	WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	30	SF
M-ADH-64	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLACK, VINYL-LIKE	A	NF	30	SF
M-APL-65	ACOUSTICAL CEILING PANEL, 2'X4', WHITE, CHALKY, VINYL COVER	S	NF	4,000	SF
M-QPT-66	QUARRY/PAVER TILE, 6"X6", BROWN, SMOOTH	A	NF	3,000	SF
M-GRT-67	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", BROWN, SMOOTH	A	NF	300	SF
M-APL-68	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE, 4"X4" SQUARE PATTERN	S	F	1,500	SF
M-GWT-69	GLAZED WALL TILE (PATTERN), 4"X4", LIGHT GREEN, SMOOTH	A	NF	250	SF
M-GWT-70	GLAZED WALL TILE (PATTERN), 4"X4", GREEN, SMOOTH	A	NF	250	SF
M-CMT-71	CERAMIC MOSAIC TILE, 2"X2", LIGHT GREEN, SMOOTH	A	NF	150	SF
M-CMT-72	CERAMIC MOSAIC TILE, 2"X2", GREEN, SMOOTH	A	NF	150	SF
M-APL-73	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	5,000	SF
M-VCT-74	VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, TAN MOTTLES	A	NF	750	SF
M-VST-75	VINYL STAIR TREAD, 12"X36", BLACK, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF
M-MAS-76	MASTIC, BROWN, BRITTLE, ASSOCIATED WITH VINYL STAIR TREAD, 12"X36", BLACK, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF
M-ADH-77	ADHESIVE (MIRROR), BROWN, BRITTLE	A	NF	150	SF
M-VCT-78	VINYL COMPOSITION TILE, 12"X12", OFF-WHITE, SMOOTH, BROWN MOTTLES	A	NF	500	SF
M-MAS-79	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", OFF-WHITE, SMOOTH, BROWN MOTTLES	A	NF	500	SF
M-ADH-80	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBROUS GLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	100	SF
M-GWT-81	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH, TAN MARBLE PATTERN	A	NF	225	SF
M-GRT-82	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH, TAN MARBLE PATTERN	A	NF	23	SF

END OF TABLE

2.7 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **TWENTY-ONE** friable suspect ACBM (acoustical ceiling panels, duct seam tape and spray-applied fireproofing) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.8 Sample Collection

Convenience sampling was performed on select identified suspect ACBM, except for the spray-applied fireproofing, which was random sampled. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

<i>Building</i>	<i>Suspect ACBM</i>	<i>Samples Collected</i>
E	60 (54 Assumed)	16*
F	62 (56 Assumed)	18
G	60 (53 Assumed)	21
H	60 (53 Assumed)	21
J	54 (45 Assumed)	27
K	46 (39 Assumed)	21
L	82 (72 Assumed)	30
TOTAL	424	154

**Multiple samples collected from select materials.*

Suspect ACM Designation and Sample Record Forms are presented in Appendix A.

2.9 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.

END OF REPORT

APPENDIX A

Suspect Asbestos-Containing Material Designation and Sample Record Forms

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-BUR-01 Damaged: Yes No Friable Non-Friable
 General Description: Built-up Roofing Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap
 Quantity of Material: 22,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: .E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-M302 Damaged: Yes No Friable Non-Friable
 General Description: Mastie (Penetrations and Flashings) Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Br.ttlh Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.ort

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-03 Damaged: Yes No Friable Non-Friable
 General Description: Suspect (DOORS, WALLS, FLASHINGS) Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-04 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (FASITESS) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-BR/KOS Damaged: Yes No Friable Non-Friable
 General Description: Brick Size: 4" x 16"

Matrix/Primary Color: Red Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 8,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-06 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Tan
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.CMU-07 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Smooth
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MCMU-08 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" X 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Rough
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6M-09 Visible Covered: Visible Damaged: Yes No Friable: Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" X 8"
 Matrix/Primary Color: Dark Gray Texture/Pattern: Laminations Cover/Secondary Color: Smooth
 Quantity of Material: 5,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MRT10 Material Code: Friable Non-Friable
 General Description: Mortar Damaged: Yes No Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1850 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-BRK-05, M-CMU-06, M-CMU-07, M-CMU-08, M-CMU-09, M-CMU-12, M-CMU-20

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 5 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-5CT-11 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (FLASHINGS) Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CM-12 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" X 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 2 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-STU-13 Damaged: Yes No Friable Non-Friable
 General Description: Shells Size: N/A

Matrix/Primary Color: Grey Texture/Pattern: Granular Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM\GROUP\forms\SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MRT-14 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: Mortar Size: N/A

Matrix/Primary Color: White Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with glassblock, 8" x 8", clear

Inspector: Dane Thompson State License: EPA D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA D10790 Date: 05/08/08
 AHERA Certificate No.: D12313 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 5 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.S.L.T. 15 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Doors, Windows, M.Uwork, Fixtures, etc.) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 32 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 12 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-16 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (ENTRACES) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FMI
GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-17 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (Foundation) Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 24000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson AHERA Certificate No.: D12313 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.FDI-18 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal/Wood Cladding Cover/Secondary Color: N/A
 Quantity of Material: 1029 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA D10790 Date: 05/08/08
 AHERA Certificate No.: D12313 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAF-19 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Fire proofing Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Chalky Cover/Secondary Color: Fiberglass
 Quantity of Material: 9,000 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Gym Storage	NE Corner	W 2'	S 1'	12'	F/W/C/O
B	Electrical Room	SW Corner	E 2'	N 0'	12'	F/W/C/O
C	PE Storage 2	NW Corner	E 0'	S 0'	12'	F/W/C/O
D	Mechanical Room	NE Corner	W 4'	S 6'	12'	F/W/C/O
E	PE Storage	SW Corner	E 6'	N 2'	12'	F/W/C/O
F	PE office 1	NW Corner	E 8'	S 6'	12'	F/W/C/O
G	PE office 2	SW Corner	E 4'	N 6'	12'	F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 State License: EPA State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.C.W.-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" X 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM
GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 6 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-PES-21 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-DST-22 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Size: 4"

Matrix/Primary Color: White Texture/Pattern: Canvas-Like Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Mechanical Room	SE Corner	W 2'	N 3'	3'	F/W/C/O
B		SE Corner	W 3'	N 5'	3'	F/W/C/O
C		SE Corner	W 3'	N 4'	3'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FMI GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 6 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-23 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: Light Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: *Ceb* Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 6 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WDB-24 Material Code: _____
 General Description: Worn Dust Boot Material Code: _____
 Matrix/Primary Color: Black Texture/Pattern: Rubber-Like Cover/Secondary Color: N/A
 Quantity of Material: 10 (SF) / LF / EA Estimated By: _____
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A
 Damaged: Yes No
 Visible Covered:
 Friable: Non-Friable
 Drawing Field Measure:
 Sampled Assumed:
 Size: 2"

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-25 Damaged: Yes No Friable Non-Friable
 General Description: Green Wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: *DM* Date: 05/08/08
 State License: EPA Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-3TC-26 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWB-25

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: CM Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 2 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SCT-27 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Firestop) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA D10790 Date: 05/08/08
 AHERA Certificate No.: Signature: Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM
GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 5 Campus Name: Kyrene Middle School Address: 1050 E. Carver Road
 Tempe, AZ 85284

Material Code: 5-TOT-28 Damaged: Yes No Friable Non-Friable
 General Description: Traveled-on Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson AHERA Certificate No.: D12313 State License: EPA
 Signature: *[Signature]* Date: 05/08/08
 Inspector: Michael Richter AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWB-29 Damaged: Yes No Friable Non-Friable
 General Description: Exposed Wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-TOT-28

Inspector: Dane Thompson AHERA Certificate No.: D12313 State License: EPA
 Inspector: Michael Richter AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-3TC-30 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WS-29

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DL* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-31 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 4'
 Matrix/Primary Color: Gray Texture/Pattern: Pinholes and Fissures Cover/Secondary Color: White
 Quantity of Material: 2500 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	PE Storage	NE Corner	W 4'	S 4'	8'	F / W / C / O
B	PE office 1	SE Corner	W 2'	N 4'	8'	F / W / C / O
C	PE office 2	NW Corner	E 5'	S 5'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.orm

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAT-32 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 4,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC.

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 1 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6wS-33 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 4,500 Estimated By: Drawing Field Measure
 SF LF EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-32

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-34 Visible Covered SAT Damaged: Yes No Friable Non-Friable

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: C-T-A-L-K-H Cover/Secondary Color: N/A

Quantity of Material: 450 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWB-33

Inspector: Dane Thompson State License: EPA D12313
 Michael Richter State License: EPA D10790
 Signature: [Signature] Date: 05/08/08
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-35 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" X 12"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Multicolor
 Quantity of Material: 3,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA
 AHERA Certificate No.: D12313 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM.GROUP/forms/SuspACMDesignRecord.0.mtf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MS-36 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered UCT Size: N/A

Matrix/Primary Color: Orange Texture/Pattern: Br. Yth Cover/Secondary Color: N/A
 Quantity of Material: 3,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-35

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.WAB.37 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (ceiling) Visible Covered Size: 4"
 Matrix/Primary Color: Black Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 250 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADH-38 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Plieble Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAS-37

Inspector: Dane Thompson State License: EPA D12313
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC.

FM GROUP/forms/SuspACMDesignRecord.omef

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 12 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAT-39 Visible Covered: Damaged: Yes No Friable: Non-Friable:

General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: ~~CHALK~~ Cover/Secondary Color: N/A

Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled: Assumed:

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DST* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 6 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.6WB.40 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 12,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated w/AL 5-SAT-39

Inspector: Dane Thompson AHERA Certificate No.: D12313 State License: EPA
 Inspector: Michael Richter AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 2 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-41 Material Code: Friable Non-Friable
 General Description: Joint Compound Damaged: Yes No Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1,200 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWB-40

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 12 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-4Z Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Size: 4" x 4"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 2,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA D12313
 Michael Richter State License: EPA D10790
 AHERA Certificate No.: Signature: Date: 05/08/08
 Signature: Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 12 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-601-43 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4"

General Description: Glazed Wall Tile Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Matrix/Primary Color: Green Estimated By: Drawing Field Measure
 Quantity of Material: 2000 LF / EA SF

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 12 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GRT-44 Material Code: M-GRT-44
 General Description: Grout Material Code: M-GRT-44
 Matrix/Primary Color: Grey Material Code: M-GRT-44
 Quantity of Material: 400 Material Code: M-GRT-44

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A
 Damaged: Yes No
 Estimated By: Drawing Field Measure
 Friable: Friable Non-Friable
 Size: N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GRT-42, M-GRT-43, M-GRT-51

Inspector: Dane Thompson State License: EPA D12313
 Michael Richter State License: EPA D10790
 Signature: CM Date: 05/08/08
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 6 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M6WT-45 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Size: 6" X 8"
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 3,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FVM
GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 15 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6RT-4C Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WT-45

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790
 Signature: [Signature] Date: 05/08/08
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 15 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MCMT-417 Damaged: Yes No Friable Non-Friable

General Description: Ceramic Mosaic Tile Size: 4" x 4"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 4,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 6 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GAT-48 Visible Covered: Visible Covered Damaged: Yes No Friable: Friable Non-Friable

General Description: Grout Size: N/A

Matrix/Primary Color: Grey Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-47

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CPT-491 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored
 Quantity of Material: 750 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: SELF-STICK

Inspector: Dane Thompson State License: EPA D12313
 Michael Richter State License: EPA D10790
 Signature: *DM* Date: 05/08/08
 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 4 Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-50 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Concrete
 Matrix/Primary Color: White Texture/Pattern: Cementitious Cover/Secondary Color: Blue Specks
 Quantity of Material: 75 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: LE Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWT-51 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Size: 4" X 4"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson AHERA Certificate No.: D12313 State License: EPA Signature: *DM* Date: 05/08/08
 Inspector: Michael Richter AHERA Certificate No.: D10790 State License: EPA Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-ASH-SZ Visible Covered FRP Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Be, Hle Cover/Secondary Color: N/A
 Quantity of Material: 12 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Panel, White, Textured

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-8286 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-WAS-53 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (covered) Size: 4"

Matrix/Primary Color: Grey Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: E **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-AD4-54 Visible Covered WAB **Damaged:** Yes No Friable Non-Friable
General Description: Adhesive **Size:** N/A

Matrix/Primary Color: Cream **Texture/Pattern:** Pliable **Cover/Secondary Color:** N/A
Quantity of Material: 15 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-53

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145E Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-SS Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Ceramic Mosaic Tile Size: 2" x 2"

Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: 1-E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-56 Damaged: Yes No Friable Non-Friable

General Description: Ceramic Mosaic Tile (Patched) Size: 2" x 2"

Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-57 Damaged: Yes No Friable Non-Friable

General Description: Ceramic Mosaic Tile (Pattern) Visible Covered Size: 2" X 2"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CM Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP, INC.

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-58 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Acoustical Ceiling Panel Size: 2' X 4'
 Matrix/Primary Color: Gray Texture/Pattern: Random one (Fissures) Cover/Secondary Color: White
 Quantity of Material: 500 SF / LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Gymnasium	NW Corner	E 6'	S 8'	8'	F/W/C/O
B		NW Corner	E 9'	S 6'	8'	F/W/C/O
C		SE Corner	W 6'	N 3'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: 4" X 4" Square Pattern

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.W.40.59 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Wall base (L-shaped) Size: 4"

Matrix/Primary Color: Black Texture/Pattern: V.ryl-like Cover/Secondary Color: N/A

Quantity of Material: 125 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: E Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.ADH-60 Damaged: Yes No Friable Non-Friable
 Visible Covered WAB Size: N/A

General Description: Adhesive Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Matrix/Primary Color: Cream Estimated By: Drawing Field Measure
 Quantity of Material: 125 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.WAB-59

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *GR* Date: 05/08/08 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-BUR-01 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Built-up Roofing Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap
 Matrix/Primary Color: Black Estimated By: Drawing Sampled
 Quantity of Material: 20,000 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12513 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MS-02 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Mastic (Pentations & Flashings) Size: N/A

Matrix/Primary Color: Black Texture/Pattern: BRITTLE Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-03 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant (Flashing) Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12513 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-WDB-04 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Woven Duct Boot Size: 2"
 Matrix/Primary Color: Black Texture/Pattern: Rubber - like Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-05 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Visible Covered Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: SQ Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-06 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant (Duct) Size: N/A

Matrix/Primary Color: Pink Cover/Secondary Color: N/A

Quantity of Material: SD Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: 012313 State License: EPA D10790 State License: EPA
 Signature: SD Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-BRK-07 Damaged: Yes No Friable Non-Friable
 General Description: Brick Size: 4" x 16"

Matrix/Primary Color: Red Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-08 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Concrete Masonry Unit Size: 4" x 16"

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Tan
 Quantity of Material: 500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-09 Visible Covered Friable Non-Friable
General Description: Concrete Masonry Unit **Size:** 4" x 16" **Damaged:** Yes No
Matrix/Primary Color: Gray **Texture/Pattern:** Cementitious **Cover/Secondary Color:** Rough Sampled Assumed
Quantity of Material: 1000 SF / LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecordL.mfm

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-10 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Dark Gray Texture/Pattern: Cementitious Cover/Secondary Color: Smooth
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-11 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Concrete Masonry Unit Size: 8" x 8"

Matrix/Primary Color: Dark Gray Texture/Pattern: Cementitious Cover/Secondary Color: Smooth

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MRT-12 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 1,200 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: 4/14 M.BRK.57, M.CMU.08, M.CMU.09, M.CMU.10, M.CMU.11 & M.CMU.61

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12315 State License: EPA D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-S LT-13 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (doors MILWAUKEE WALLS) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (walls) Visible Covered Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12312 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-15 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Sealant (walls) Texture/Pattern: Pliable Cover/Secondary Color: N/A

Matrix/Primary Color: Gray Estimated By: Drawing Field Measure
 Quantity of Material: 50

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MRT-16 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 50 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Glassblock, 8'x8', Clear

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12315 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *GR* Date: 05/08/08 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-17 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4" x 4" x 1/4"

General Description: Glazed Wall Tile

Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: *DR* Date: 05/08/08 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GRT-18 Damaged: Yes No Friable Non-Friable
 General Description: Grout Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GRT-17

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D17313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *GR* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-TOT-19 Damaged: Yes No Friable Non-Friable
 General Description: Traveled-on Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-20 Visible Covered No Yes Friable Non-Friable
 General Description: Gypsum Wall Board Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TOT-19

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.ome

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JTC-21 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WB.20

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CON-22 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Concrete (enriched) Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 12,500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: 1212313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CON-23 Damaged: Yes No Friable Non-Friable

General Description: Concrete (Foundations) Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A

Quantity of Material: 25,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: 012313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-2H Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Panel Size: 2'x4'

Matrix/Primary Color: Gray Texture/Pattern: Pinholes and Fissures Cover/Secondary Color: White

Quantity of Material: 2,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 2'	S 10'	8'	F / W / C / O
B	Corridor 1	NW Corner	E 2'	S 8'	8'	F / W / C / O
C	Corridor 2	SW Corner	E 10'	N 5'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: 4" x 4" Square Pattern

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-25 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wall Board Texture/Pattern: Chalky Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 3,750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 0'	S 20'	8' 6"	F/W/C/O
B	└	NW Corner	E 0'	S 15'	8' 6"	F/W/C/O
C	Corridor 2	NW Corner	E 0'	S 40'	8' 6"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12315 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (802) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JTC-26 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: Joint Compound **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 400 SF / LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 0'	S 20'	8' 6"	F/W/C/O
B	I	NW Corner	E 0'	S 15'	8' 6"	F/W/C/O
C	Corridor 2	NW Corner	E 0'	S 40'	8' 6"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6wD.25

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: N12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-COT-27 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Carpet
 Matrix/Primary Color: Gray Cover/Secondary Color: Multi-colored
 Quantity of Material: 16,000 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				W / C / O
B		Corner				W / C / O
C		Corner				I / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Self-Stacks

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12315 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCF-28 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Multi-colored
 Quantity of Material: 7,500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: F Address: 1050 E. Carver Rd

Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MA5-29 Material Code: M-MA5-29 Damaged: Yes No Friable Non-Friable

General Description: Mastik Visible Covered Size: N/A

Matrix/Primary Color: Orange Texture/Pattern: Brittle Cover/Secondary Color: N/A

Quantity of Material: 18.00 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.V.C.T-28, M.V.C.T-39

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter

AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA

Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-WAB-30 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Wallbase (covered) **Size:** 4'1" **Estimated By:** Drawing Field Measure Sampled Assumed
Matrix/Primary Color: Black **Texture/Pattern:** Vinyl-like **Cover/Secondary Color:** N/A
Quantity of Material: 500 SF / LF / EA **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed



SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord1.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-ADH-31 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAS-30

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: 012313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-FDI-32 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL LINED CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 1323 Estimated By: Drawing Field Measure
 Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-33 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1,200 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: 5-SAT-3H Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 23,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-35 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Gypsum Wall Board Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 23,000 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S.SAT.34

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12315 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JTC-36 **Damaged:** Yes No Friable Non-Friable
General Description: Joint Compound **Visible Covered:** SAT **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 2300 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated w/AL M-6WB-35

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-37 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x4'
 Matrix/Primary Color: Gray Texture/Pattern: Potholes and Fissures Cover/Secondary Color: White
 Quantity of Material: 16,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	F107	NE Corner	W 2'	S 10'	8'	F/W/C/O
B	F207	NE Corner	W 2'	S 10'	8'	F/W/C/O
C	F204	SW Corner	E 3'	N 8'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-5AC-38 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-39 Damaged: Yes No Friable Non-Friable

General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: Black Specks

Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-4D Visible Damaged: Yes No Friable Non-Friable
General Description: Spray Applied Texture Covered No Size: N/A
Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
Quantity of Material: 3,500 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: CR **Signature:** [Signature] **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-41 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT
 General Description: Gypsum Wall Board Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 3,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-40

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: 6-JTC-42 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 Size: N/A

General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 350 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.6WB.41

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-43 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Glazed Wall Tile **Size:** 4" x 4" **Cover/Secondary Color:** N/A
Matrix/Primary Color: Tan **Texture/Pattern:** Smooth **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 2500 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-44 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile (Pattern) Size: 4" x 4"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-45 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile (Pattern) Size: 4" x 4"
 Matrix/Primary Color: Dark Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D1233 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6RT-446 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Grout Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Matrix/Primary Color: Gray Estimated By: Drawing Field Measure
 Quantity of Material: 300 LF / EA SF LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: DR 313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-47 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Ceramic Mosaic Tile **Size:** 2" x 2"

Matrix/Primary Color: Tan **Texture/Pattern:** Smooth **Cover/Secondary Color:** N/A
Quantity of Material: 1000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D17313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-418 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile (PARTS) Size: 2" x 2"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-49 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile (Carver) Size: 2" x 2"
 Matrix/Primary Color: Dark Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: DR313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6RT-5D Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Grout Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Matrix/Primary Color: Gray Estimated By: Drawing Field Measure
 Quantity of Material: 130 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-TWP-51 Visible Damaged: Yes No Friable Non-Friable
General Description: Tackable Wall Panel **Size:** N/A
Matrix/Primary Color: Brown **Texture/Pattern:** Fibrous **Cover/Secondary Color:** Vinyl Cover
Quantity of Material: 3500 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	F106	NE Corner	W 0'	S 2'	2'	F/W/C/O
B	F102	NW Corner	E 0'	S 2'	2'	F/W/C/O
C	F200	NW Corner	E 0'	S 2'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-52 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (doors, windows) Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Tar-like Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12513 State License: EPA D10790 State License: EPA
 Signature: DR Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: 5-SAF-53 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Fireproofing Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Chalky Cover/Secondary Color: FIBROUS
 Quantity of Material: 350 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	E110	NE Corner	W 0'	S 3'	12'	F C I O
B	E111	NE Corner	W 0'	S 2'	12'	F I C I O
C	E210	NE Corner	W 0'	S 2'	12'	F I C I O
D		Corner				F I W I C I O
E		Corner				F I W I C I O
F		Corner				F I W I C I O
G		Corner				F I W I C I O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: FI Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-54 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant (Firestop) Size: N/A

Matrix/Primary Color: Green Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 State License: EPA State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: F **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-AOH-55 Visible Covered FRP Damaged: Yes No Friable Non-Friable
General Description: Adhesive Size: N/A

Matrix/Primary Color: Brown **Texture/Pattern:** Brittle **Cover/Secondary Color:** N/A
Quantity of Material: 25 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: associated with Fiberglass Reinforced Panel, Tan, Textured

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecordL.mfm

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VST-56 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Stair Tread Visible Covered Size: 12" x 60"
 Matrix/Primary Color: Gray Texture/Pattern: Vinyl-Like Cover/Secondary Color: Circle Pattern
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MA5-57 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Mastic Texture/Pattern: Brittle Cover/Secondary Color: N/A

Matrix/Primary Color: Brown Estimated By: Drawing Field Measure
 Quantity of Material: 250

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.VST-56

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-58 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 24" x 24"
 Matrix/Primary Color: Gray Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MAS-59 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-58

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F 3 Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-PES-60 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: ACMU-61 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: F Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6A5-62 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4" x 4"

General Description: Gasket
 Matrix/Primary Color: Black Texture/Pattern: Rubber-like Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-BUR-01 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Built-up Roofing **Size:** N/A
Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** Gray Mineral Cap
Quantity of Material: 20,000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: 17313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable

General Description: Mastic (Penetrations & Flashings) Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-03 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant (FLASHING) Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-WDB-04 Damaged: Yes No Friable Non-Friable
 General Description: Women, Dust Boot Size: 2"
 Matrix/Primary Color: Black Texture/Pattern: Rubber-like Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-05 Visible Damaged: Yes No Friable Non-Friable
General Description: Sealant (Duct) Covered No Size: N/A
Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
Quantity of Material: SD SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D123B **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: [Signature] **Date:** 05/08/08 **Signature:** [Signature] **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.omf

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-06 Visible Damaged: Yes No Friable Non-Friable
 Covered
General Description: Sealant (Duct) **Size:** N/A
Matrix/Primary Color: Pink **Texture/Pattern:** Pliable **Cover/Secondary Color:** N/A
Quantity of Material: 50 SF / LF / EA **Estimated By:** Drawing Field Measure
 Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7577
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-BRK-07 Damaged: Yes No Friable Non-Friable
 General Description: Bricks Size: 4" x 16"
 Matrix/Primary Color: Red Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *GR* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-08 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Concrete Masonry Unit **Size:** 4" x 16" x 11" **Cover/Secondary Color:** Tan
Matrix/Primary Color: Gray **Texture/Pattern:** Rough **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 5,000 SF / LF / EA **Homogeneous Material Location:** Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-09 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"

Matrix/Primary Color: Grey Texture/Pattern: Cementitious Cover/Secondary Color: Rough
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-ID Material: Concrete Masonry Unit
 Damaged: Yes No
 Friable Non-Friable

General Description: Visible Covered
 Size: 4" x 16"

Matrix/Primary Color: Dark Gray Texture/Pattern: Concentric Cover/Secondary Color: Smooth
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12317 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-11 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" x 8"

Matrix/Primary Color: Dark Gray Texture/Pattern: Cementitious Cover/Secondary Color: Smooth
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MRT-12 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Visible Covered Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1200 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: 4/w M. RRK.07, M. GW.08, M. GW.09, M. GW.10 & M. GW.11

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12317 State License: EPA State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-13 Damaged: Yes No Friable Non-Friable

General Description: Sealant (DOORS, MILLWORK, WALLS) Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Does, walls, flashing) Visible Covered
 Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-15 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (walls) Visible: Covered: Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12513 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *GR* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MRT-16 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Mortar Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure
 Texture/Pattern: Cementitious Sampled Assumed
 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Glass Block, 8" x 8", Clear

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-17 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Size: 4" x 4"

Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GRT-18 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-17

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord.ortf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-TOT-19 Damaged: Yes No Friable Non-Friable
 General Description: Troweled on Texture Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 2500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 AHERA Certificate No.: D10790 State License: EPA State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-20 Visible Damaged: Yes No Friable Non-Friable
General Description: Gypsum Wallboard Covered TOT **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 2500 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-TOT-19

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: 012313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JTC-21 Visible Damaged: Yes No Friable Non-Friable
General Description: Joint compound Covered TOC **Size:** N/A

Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 250 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB.20

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D17313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CON.22 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Concrete (ENTRIES) Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 12,500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CON-23 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Concrete (FOUNDATION) Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Matrix/Primary Color: Gray Estimated By: Drawing Field Measure
 Quantity of Material: 25,000 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson
 AHERA Certificate No.: D17313 State License: EPA
 Signature: *DR* Date: 05/08/08

Secondary Inspector: Michael Richter
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-24 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 4'

Matrix/Primary Color: Gray Texture/Pattern: P. holes and Fissures Cover/Secondary Color: White
 Quantity of Material: 2,500 (SF) LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 2'	S 5'	8'	F/W/C/O
B	I	NW Corner	E 2'	S 15'	8'	F/W/C/O
C	Corridor 2	NE Corner	W 3'	S 15'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12315 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M. 6.0.25 Damaged: Yes No Friable Non-Friable
 Visible Covered Wall paper / SAT Size: N/A

General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 3750 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 6'	S 15'	8'6"	F / W / C / O
B	I	NW Corner	E 0'	S 25'	8'6"	F / W / C / O
C	Corridor 2	NE Corner	W 0'	S 15'	8'6"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S.SAT-33

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-5TC-26 Damaged: Yes No Friable Non-Friable
 General Description: Joint compound Covered Visible Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 0'	S 15'	8'6"	F/W/I/C/O
B	I	NW Corner	E 0'	S 25'	8'6"	F/W/I/C/O
C	Corridor 2	NE Corner	W 0'	S 15'	8'6"	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: Associated with M-6WB-25

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-LPT-27 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Visible Covered Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-colored
 Quantity of Material: 16,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: SELF-STICK

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-28 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" X 12"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Multi-Colored
 Quantity of Material: 5,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.M.A.S. 29 Visible Covered VCT **Damaged:** Yes No Friable Non-Friable
General Description: Mastic **Size:** N/A

Matrix/Primary Color: Orange **Texture/Pattern:** Br. & flk **Cover/Secondary Color:** N/A
Quantity of Material: 6,000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.V.C.T-28, M.V.C.T-39

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D17313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.W.A.S. 30 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (covered) Size: 4"

Matrix/Primary Color: Black Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-ADH-31 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Texture/Pattern: Pliable Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: Cream Estimated By: Drawing Field Measure
 Quantity of Material: 500 SF / LF / EA Wall Other
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-30

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-145 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-FDI-32 Damaged: Yes No Friable Non-Friable

General Description: Fire Door Insulation Visible Covered Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Metal/Wood Cladding Cover/Secondary Color: N/A

Quantity of Material: 130Z Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-33 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NE Corner	W 4'	S 80'	8'	F/W/C/O
B	I	NE Corner	W 0'	S 75'	2'	F/W/C/O
C	Corridor 2	NE Corner	W 4'	S 80'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



 15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-34 Visible Covered Friable Non-Friable
General Description: Spray-Applied Texture

Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 23,000 SF / LF / EA **Estimated By:** Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GWB-35 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 23,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-34

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JTC-36 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Quantity of Material: 2300 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-35

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-37 Damaged: Yes No Friable Non-Friable

General Description: Acoustical Ceiling Panel Size: 2' x 2'

Matrix/Primary Color: Grey Texture/Pattern: Pinholes and Fissures Cover/Secondary Color: White

Quantity of Material: 16,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	F100	SW Corner	E 3'	N 8'	8'	F / W / (C) / O
B	F105	NE Corner	W 2'	S 10'	8'	F / W / (C) / O
C	F200	SW Corner	E 3'	N 8'	8'	F / W / (C) / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter

AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA

Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SAC-38 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sink Acoustical Coatings Size: N/A

Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A

Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-39 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" X 12"

Matrix/Primary Color: Blue Texture/Pattern: Smooth Cover/Secondary Color: Black Specks
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-40 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 3,500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12513 State License: EPA D10790 State License: EPA
 Signature: *CM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-41 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 3,500 LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-40

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-37C-47 Visible Covered SAT Damaged: Yes No Friable Non-Friable

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 350 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WB-41

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M. GWT-43 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Glazed Wall Tile Size: 4" x 4"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-44 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: Glazed Wall Tile (Pavers) **Size:** 4" x 4"

Matrix/Primary Color: Light Green **Texture/Pattern:** Smooth **Cover/Secondary Color:** N/A

Quantity of Material: 250 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9286 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.GWT-45 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4" x 4"

General Description: Glazed Wall Tile (AFFORD) Cover/Secondary Color: N/A
 Matrix/Primary Color: Green Texture/Pattern: Smooth
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GRT-46 Damaged: Yes No Friable Non-Friable
 General Description: Grout Visible Covered Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-43, M-GWT-44, M-GWT-45

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *GM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.CMT-47 Visible Damaged: Yes No Friable Non-Friable
General Description: Ceramic Mosaic Tile Covered **Size:** 2" X 2"

Matrix/Primary Color: Tan **Texture/Pattern:** Smooth **Cover/Secondary Color:** N/A
Quantity of Material: 1000 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.CMT.418 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Ceramic Mosaic Tile (PATTERNS) Size: 2" X 2"

Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-49 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile (Pavers) Size: 2" x 2"

Matrix/Primary Color: Dark Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GRT-50 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 130 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-47, M-CMT-48, M-CMT-49

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M.TWP.51 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Green
 Quantity of Material: 3,500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	G200	NW Corner	E 3'	S 0'	2'	F/W/C/O
B	G102	NW Corner	E 0'	S 3"	2'	F/W/C/O
C	G105	SE Corner	W 6'	N 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson
 AHERA Certificate No.: D17313 State License: EPA
 Signature: *[Signature]* Date: 05/08/08

Secondary Inspector: Michael Richter
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SCT-52 Damaged: Yes No Friable Non-Friable

General Description: Scalent (DOORS, WINDOWS) Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Tar-Like Cover/Secondary Color: N/A

Quantity of Material: 15 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAF-53 Damaged: Yes No Friable Non-Friable

General Description: Spray Applied Freestanding Visible Covered Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Chalky Cover/Secondary Color: FIBROUS

Quantity of Material: 350 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	E210	NE Corner	W 0'	S 0'	12'	F W / C / O
B	E110	NE Corner	W 0'	S 0'	12'	F W / C / O
C	E111	SE Corner	W 0'	N 0'	12'	F W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-54 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant (Firestop) Size: N/A

Matrix/Primary Color: Green Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-ADH-55 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered FRP Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Panel, Tan, Textured

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VST-56 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Vinyl Stair Tread Size: 12" X 60"

Matrix/Primary Color: Black Texture/Pattern: Vinyl-Like Cover/Secondary Color: Circle Pattern

Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MAS-57 Damaged: Yes No Friable Non-Friable
 Visible Covered VST

General Description: Mastic Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brattle Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VST-56

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: G Building **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-58 Visible Damaged: Yes Non-Friable
 Covered No

General Description: Vinyl Composition Tile **Size:** 24" X 24"

Matrix/Primary Color: Black **Texture/Pattern:** Vinyl-Like **Cover/Secondary Color:** N/A

Quantity of Material: 750 **Estimated By:** Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MAS-59 Material Description: Mastic
 Visible Covered Visible Damaged: Yes No
 Friable Non-Friable Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D17313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DN* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: G Building Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-PES-60 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Pipe End Sealant Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: 5-TOT-01 Damaged: Yes No Friable Non-Friable
 General Description: Traveled on Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 5,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Exterior	NE Corner	W 1'	S 6'	10'	F / W / C / O
B		NW Corner	E 6'	S 1'	12'	F / W / C / O
C		SW Corner	E 2'	N 3'	12'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-02 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered TOT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: \$500 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled: Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Exterior	NE Corner	W 1'	S 6'	10'	F / W / <input checked="" type="checkbox"/> O
B		NW Corner	E 6'	S 1'	12'	F / W / <input checked="" type="checkbox"/> O
C		SW Corner	E 2'	N 3'	12'	F / W / <input checked="" type="checkbox"/> O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-TOT-01

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: *DR* Date: 05/08/08 State License: EPA Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-03 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered ToT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Exterior	NE Corner	W 1'	S 6'	10'	F/W (C) / O
B		NW Corner	E 6'	S 1'	12'	F/W (C) / O
C		SW Corner	E 2'	N 3'	12'	F/W (C) / O
D		Corner				F/W / C / O
E		Corner				F/W / C / O
F		Corner				F/W / C / O
G		Corner				F/W / C / O

Comments: Associated with M-6WB-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-STU-04 Damaged: Yes No Friable Non-Friable
 General Description: Stucco Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-05 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 7,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-BRK-06 Damaged: Yes No Friable Non-Friable

General Description: Brick Size: 4" x 6"

Matrix/Primary Color: Red Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 2,200 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CM Signature: Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-07 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" x 8"
 Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-BUR-01 Damaged: Yes No Friable Non-Friable
 General Description: Built-up Roofing Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap
 Quantity of Material: 16,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MAS-02 Visible Covered Friable Non-Friable
General Description: Mastic (Penetrations + Flashings) Damaged: Yes No Drawing Field Measure
Matrix/Primary Color: Black Ceiling Floor Wall Other Sampled Assumed
Quantity of Material: 100 SF / LF / EA Estimated By: Cover/Secondary Color: N/A Size: N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 05/08/08 **Signature:** **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-03 Visible Damaged: Yes No Friable Non-Friable
General Description: Sealant (Flashing) Covered Drawing Field Measure
 Size: N/A

Matrix/Primary Color: Gray **Texture/Pattern:** Pliable **Cover/Secondary Color:** N/A
Quantity of Material: 50 SF / LF / EA Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-WDB-04 Damaged: Yes No Friable Non-Friable

General Description: Woven Duct Boat Size: 2'

Matrix/Primary Color: Black Texture/Pattern: Rubber-like Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

F/M
GROUP INC

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-05 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: Sealant (Duct) **Size:** N/A
Matrix/Primary Color: Gray **Texture/Pattern:** Pliable **Cover/Secondary Color:** N/A
Quantity of Material: 50 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-06 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Visible Covered Size: N/A
 Matrix/Primary Color: Pink Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-07 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT Visible Covered Size: 4" x 16"
 Matrix/Primary Color: Red Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-08 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Tan
 Quantity of Material: 5000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-09 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Concrete Masonry Unit **Size:** 4" x 16" **Cover/Secondary Color:** Rough
Matrix/Primary Color: Gray **Texture/Pattern:** Cementitious **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 1000 SF / LF / EA **Homogeneous Material Location:** Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMU-10 Visible Covered Friable Non-Friable
 Damaged: Yes No

General Description: Concrete Masonry Unit **Size:** 4" x 16"

Matrix/Primary Color: Dark Gray **Texture/Pattern:** Cementitious **Cover/Secondary Color:** Smooth

Quantity of Material: 100 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 05/08/08 **Signature:** **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: AA-CMU-11 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Concrete Masonry Unit **Size:** 8' x 8"

Matrix/Primary Color: Dark Gray **Texture/Pattern:** Cementitious **Cover/Secondary Color:** Smooth
Quantity of Material: 100 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 271-7877
 (602) 271-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MRT-12 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A

Quantity of Material: 1500 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-BRK-07, M-CMU-08, M-CMU-09, M-CMU-10, M-CMU-11

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-13 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Sealant Cores Windows (MILLER, WAUS) **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Friable **Cover/Secondary Color:** N/A
Quantity of Material: 100 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: HI **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-14 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Sealant (walls) **Size:** N/A
Matrix/Primary Color: Brown **Texture/Pattern:** Pliable **Cover/Secondary Color:** N/A
Quantity of Material: 50 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-15 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: Sealant (walls) **Size:** N/A

Matrix/Primary Color: Gray **Texture/Pattern:** Pliable **Cover/Secondary Color:** N/A

Quantity of Material: 50 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MRT-16 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Mortar Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure
 Texture/Pattern: Cementitious

Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: associated with glass block, 8" x 8", clear

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-17 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Visible Covered Size: 4" x 4"

Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6RT-18 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.6WT-17

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-TOT-19 Damaged: Yes No Friable Non-Friable

General Description: Traveled on texture Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 3500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GWB-20 Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wall Board Visible Covered TOT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-TOT-19

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JIC-21 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Joint Compound **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 250 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWB.20

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CAN-22 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (ENTRIES) Visible Covered Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 2000 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CON-23 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (FOUNDATION) Visible Covered
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 32,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-24 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x4'
 Matrix/Primary Color: Gray Texture/Pattern: Pits & Fissures Cover/Secondary Color: White
 Quantity of Material: 2,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NW Corner	E 10'	S 6'	8'	F/W/C/O
B	I	SW Corner	E 10'	N 6'	8'	F/W/C/O
C	Corridor 2	NW Corner	E 10'	S 6'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: 4" x 4" Square Pattern

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-25 Visible Covered **Damaged:** Yes No **Friable Non-Friable:** Friable Non-Friable
General Description: Gypsum Wallboard **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A **Size:** N/A
Matrix/Primary Color: White **Estimated By:** Drawing Field Measure **Sampled Assumed:** Sampled Assumed
Quantity of Material: 7,000 **Estimated By:** Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NW Corner	E 10'	S 6'	8' 6"	F / W / C / O
B	I	SW Corner	E 10'	N 6'	8' 6"	F / W / C / O
C	Corridor 2	NW Corner	E 10'	S 6'	8' 6"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *DM* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: 5-JTC-26 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Corridor 1	NW Corner	E 10'	S 6'	8' 6"	F W C / O
B	I	SW Corner	E 10'	N 6'	8' 6"	F W C / O
C	Corridor 2	NW Corner	E 10'	S 6'	8' 6"	F W C / O
D		Corner				F W / C / O
E		Corner				F W / C / O
F		Corner				F W / C / O
G		Corner				F W / C / O

Comments: Associated with M-GWB-25

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CPT-27 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-colored
 Quantity of Material: 32,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	H100	SW Corner	E 0'	N 4"	0'	F/W/C/O
B	Corridor 1	NE Corner	W 10'	S 10'	0'	F/W/C/O
C	H200	SW Corner	E 0'	N 4"	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Self-stick

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/Forms/SuspACM/DesigRecord1.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-28 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Multi-Colored
 Quantity of Material: 5,000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: HI Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MA5-29 Visible Covered: VCT Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A

Matrix/Primary Color: Orange Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 5,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-28

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DR* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-WAB-30 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (Coved) Visible Covered Size: 4'11"
 Matrix/Primary Color: Black Texture/Pattern: Vinyl-like Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-ADH-31 Visible Covered: Damaged: Yes No Friable: Non-Friable:
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-30

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: HI **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-FDI-32 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Fire Door Insulation **Size:** N/A
Matrix/Primary Color: N/A **Texture/Pattern:** METAL WOOD CLADDING **Cover/Secondary Color:** N/A
Quantity of Material: 1260 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: 6-SAT-33 **Damaged:** Yes No Friable Non-Friable
General Description: Spray-Applied Texture **Size:** N/A
Matrix/Primary Color: White **Cover/Secondary Color:** N/A
Quantity of Material: 1200 **Estimated By:** Drawing Field Measure
Texture/Pattern: Chalky **Cover/Secondary Color:** N/A
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-34 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 23,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DR* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H1 Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-35 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 23,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-34

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-JTC-36 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A

Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 2300 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.G.W.B-35

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter State License: EPA Date: 5/08/08
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-APL-37 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Acoustical Ceiling Panel **Size:** 2'x4'
Matrix/Primary Color: Gray **Texture/Pattern:** Pins & Fissures **Cover/Secondary Color:** White
Quantity of Material: 16,500 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	H 109	SW Corner	E 10'	N 10'	8'	F / W / C / O
B	H 105	SW Corner	E 15'	N 10'	8'	F / W / C / O
C	H 207	NE Corner	W 15'	S 2'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: HI **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SAC-38 Visible Covered Friable Non-Friable
General Description: Sink Acoustical Coating **Damaged:** Yes No **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Rough **Cover/Secondary Color:** N/A
Quantity of Material: 30 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-39 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Vinyl Composition Tile **Texture/Pattern:** Smooth **Cover/Secondary Color:** Black Specks **Size:** 12" x 12"
Matrix/Primary Color: Pink **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 500 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 05/08/08 **Signature:** **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAT-40 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 3,500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WB-41 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Gypsum Wall Board Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 3,500 SF LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-40

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: 5-JTC-42 Visible Damaged: Yes No Friable Non-Friable
General Description: Joint Compound Covered SAT **Size:** N/A
Matrix/Primary Color: White **Texture/Pattern:** Chalky **Cover/Secondary Color:** N/A
Quantity of Material: 350 LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-41

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-43 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Size: 4" x 4"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GWT-44 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile (Pattern) Size: 4" x 4"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6WT-45 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Glazed Wall Tile (Pattern) Size: 4" x 4"

Matrix/Primary Color: Dark Green Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-6RT-416 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Grout Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A

Quantity of Material: 300 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.G.W.T-43, M.G.W.T-44, M.G.W.T-45

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-47 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Ceramic Mosaic Tile **Size:** 2" x 2" **Cover/Secondary Color:** N/A
Matrix/Primary Color: Tan **Texture/Pattern:** Smooth **Estimated By:** Drawing Field Measure Sampled Assumed
Quantity of Material: 1000 LF / EA SF
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 **Project Name:** AHIERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-48 Visible Covered Friable Non-Friable
General Description: Ceramic Mosaic Tile **Size:** 2" x 2" **Damaged:** Yes No
Matrix/Primary Color: Light Green **Texture/Pattern:** Smooth **Cover/Secondary Color:** N/A
Quantity of Material: 150 **Estimated By:** Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: **Date:** 05/08/08 **Signature:** **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-CMT-49 Damaged: Yes No Friable Non-Friable
 Visible Covered
 General Description: Ceramic Mosaic Tile Size: 2"x2"
 Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-GRT-50 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 130 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-47, M-CMT-48, M-CMT-49

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-TWP-51 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Visible Covered
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover Size: N/A
 Quantity of Material: 3,500 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		NE Corner	W 0'	S 6'	2'	F / W / C / O
B		SW Corner	E 0'	N 0'	2'	F / W / C / O
C		NW Corner	E 2'	S 0'	2'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-52 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Sealant (doors, windows) Size: N/A
Matrix/Primary Color: Black Texture/Pattern: Tar-like Cover/Secondary Color: N/A
Quantity of Material: 15 Estimated By: Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: **Signature:** _____ **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: S-SAF-53 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Fireproofing Size: N/A
 Matrix/Primary Color: Gray Cover/Secondary Color: Fibrous
 Quantity of Material: 350 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: Chalky
 Estimated By: Field Measure

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	E110	NW Corner	E 1'	S 0'	12'	F/W/C/O
B	E111	SW Corner	E 0'	N 0'	12' 6"	F/W/C/O
C	E210	NW Corner	E 0'	S 0'	12'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 5/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-SLT-54 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Firestop) Visible Covered Size: N/A
 Matrix/Primary Color: Green Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-A01H-55 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Adhesive **Size:** N/A

Matrix/Primary Color: BROWN **Texture/Pattern:** BRITTLE **Cover/Secondary Color:** N/A
Quantity of Material: 25 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: associated with Fiberglass Reinforced Panel, Tan, Textured

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *DM* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-V6T-56 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Stair Tread Visible Covered Size: 12" x 60"
 Matrix/Primary Color: Black Texture/Pattern: Vinyl-like Cover/Secondary Color: Circle Pattern
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MA5-57 Damaged: Yes No Friable Non-Friable
 Visible Covered VCT Size: N/A

General Description: Mastic Cover/Secondary Color: N/A

Matrix/Primary Color: Brown Texture/Pattern: BRITTLE Estimated By: Drawing Field Measure

Quantity of Material: 250 (SF) / LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-56

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-VCT-58 Visible Damaged: Yes No Friable Non-Friable
General Description: Vinyl Composition Tile Size: 24" x 24" Drawing Assumed
Matrix/Primary Color: Black Texture/Pattern: Smooth Cover/Secondary Color: N/A Field Measure
Quantity of Material: 250 LF / EA Estimated By:

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 05/08/08 **Signature:** *[Signature]* **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: H **Address:** 1050 E. Carver Rd
Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-MAS-59 Visible Damaged: Yes No Friable Non-Friable
 Covered VCT Size: N/A
General Description: Mastic
Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A
Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-58

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D12313 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 05/08/08 **Date:** 5/08/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: H Address: 1050 E. Carver Rd
 Campus Name: Kyrene Middle School Chandler, AZ 85284

Material Code: M-PES-60 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: white Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: Pliable SP / LF / EA Field Measure

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 5/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MRT-08 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 950 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with MCM-05

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *DM* Signature: *[Signature]* Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-09 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (bases, windows, walls) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Doors) Visible Covered Size: N/A
 Matrix/Primary Color: Tan Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 16 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 State License: EPA State License: EPA
 Signature: CR Signature: [Signature] Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-11 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (CONCRETE) Visible Covered Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 7,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-12 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (Foundation) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 8,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 05/08/08 State License: EPA Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-13 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 8" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 05/08/08 State License: EPA Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WRT-14 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMU-13

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284


Material Code: M-CMM-15 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MRT-16 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-BRK-06, M-CMU-07, M-CMU-15, M-CMU-18

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-FDI-17 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Wood Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 588 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: ACMU-18 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Dark Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-19 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panels Size: 2'x4'
 Matrix/Primary Color: Gray Cover/Secondary Color: White
 Quantity of Material: 9,000 Estimated By: Drawing Sampled Assumed
 Texture/Pattern: Pits & Fissures
 LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		NE Corner	W'	S'	8'	F / W / (C) / O
B		NE Corner	W'	S'	8'	F / W / (C) / O
C		NE Corner	W'	S'	8'	F / W / (C) / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 AHERA Certificate No.: D10790 State License: EPA State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: 5-SAT-20 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: white Cover/Secondary Color: N/A
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure
 Texture/Pattern: CHALKY SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Detention	SE Corner	W 6'	N 4'	4'	F (W) / C / O
B	Workroom	NE Corner	W 0'	S 6'	3"	F (W) / C / O
C	CAD	NW Corner	E 4'	S 0'	4'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-21 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 9.00 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other N/A
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Detention	SE Corner	W 0'	N 4'	4'	F / W / C / O
B	Workroom	NE Corner	W 0'	S 6'	3'	F / W / C / O
C	CAD	NW Corner	E 4'	S 0'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-20

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JIC-22 Damaged: Yes No Friable Non-Friable
 General Description: Joint compound Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 900 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Detention	SE Corner	W 0'	N 4'	4'	F / W / C / O
B	Workroom	NE Corner	W 0'	S 6'	3"	F / W / C / O
C	CAD	NW Corner	E 4'	S 0'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with MGB.21

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-COT-23 Damaged: Yes No Friable Non-Friable

General Description: Carpet Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-colored
 Quantity of Material: 3500 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Workroom	SW Corner	E 0'	N 8'	0'	F/W/C/O
B	Detention	SE Corner	W 7'	N 0'	0'	F/W/C/O
C	CAD	NW Corner	E 0'	S 5'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Self Stick

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VLT-2H Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12"x12"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Multi-colored
 Quantity of Material: 6000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-25 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: Black Specks
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MAS-26 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A
 Matrix/Primary Color: Orange Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 6500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.V.C.T-24, M.V.C.T-25

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WAB-27 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (Coved) Visible Covered Size: 4"
 Matrix/Primary Color: Black Texture/Pattern: Vinyl-like Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADA-28 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered WAB Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.WAB-27

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-29 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Doors, Windows, Millwork, Furnics) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 43 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SAC-3D Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 28 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-31 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 9,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-32 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 900 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWS-31

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-AOH-33 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive (RESIDUAL) Visible Covered Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 3,000 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-TWP-3H Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 2,000 Estimated By: Drawing Field Measure
 SF / LF / EA Wall Other
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Work room	NE Corner	W 0'	S 0'	2'	F/W/C/O
B	Food Lab	NE Corner	W 0'	S 0'	2'	F/W/C/O
C	CAD	SE Corner	W 0'	N 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAT-35 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Texture/Pattern: Chalky SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-36 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1,500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-35

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 State License: EPA Michael Richter State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-37 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-26

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-38 Damaged: Yes No Friable Non-Friable
 General Description: Glazed wall tile Size: 4" x 4"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 1,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-39 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile (PATTERN) Size: 4" x 4"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-40 Damaged: Yes No Friable Non-Friable
 General Description: glazed wall tile (Pattern) Size: 4" x 4"
 Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6RT-41 Damaged: Yes No Friable Non-Friable
 General Description: Grout Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 120 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6RT-38, M-6RT-39, M-6RT-40

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-42 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2" x 2"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-43 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Visible Covered Size: 2" x 2"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-44 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Visible Covered Size: 2"x2"
 Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GRT-45 Damaged: Yes No Friable Non-Friable
 General Description: Grout Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 120 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-42, M-CMT-43, M-CMT-44

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-PSL-416 Damaged: Yes No Friable Non-Friable
 General Description: Pipe Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 5 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6A5-47 Damaged: Yes No Friable Non-Friable
 General Description: basket Size: 4"
 Matrix/Primary Color: Black Texture/Pattern: Rubber-like Cover/Secondary Color: N/A
 Quantity of Material: 5 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADH-48 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered FRP Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Panel, White Textured

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: 5-SAT-49 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 3,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWB-50 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 3,000 SF LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-49

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-51 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.G.W.B.S.O.

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-52 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (FOUNDATION) Size: N/A
 Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 4,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building J Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WDB-53 Damaged: Yes No Friable Non-Friable

General Description: Woven Duct Boot Size: 2"

Matrix/Primary Color: Black Texture/Pattern: Rubber-like Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FMI
 GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Kyrene Middle School Address: 1050 E. Carver Road
 Campus Name: Building J Tempe, AZ 85284

Material Code: 11-PLA-54 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: PASTER Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A

Quantity of Material: 400 Estimated By: Drawing Field Measure
 Texture/Pattern: SENSATIONOUS LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-BUR-01 Damaged: Yes No Friable Non-Friable
 General Description: Built-up Roofing Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap
 Quantity of Material: 17,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M- MAS-02 Damaged: Yes No Friable Non-Friable
 General Description: Mastic (Penetrations & Flashings) Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-03 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Flashing) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DK* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: 5-STU-04 Damaged: Yes No Friable Non-Friable
 General Description: Stucco Visible Covered: Visible Covered Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 3000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-05 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Masonry Unit Size: 4" x 16"
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: Tan
 Quantity of Material: 9500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MRT-06 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 950 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMU-05

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-07 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (wall, flashing) Size: N/A
 Matrix/Primary Color: Tan Texture/Pattern: Diabole Cover/Secondary Color: N/A
 Quantity of Material: 35 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACIMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-08 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: Light Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-09 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-LON-10 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (ENTRIES) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 7000 (SF) LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MCAN-11 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (Foundation) Size: N/A
 Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 17,500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-12 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (windows) Visible Covered Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Tac-like Cover/Secondary Color: N/A
 Quantity of Material: 16 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-FDI-13 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: METAL WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 609 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-14 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x2'
 Matrix/Primary Color: Gray Texture/Pattern: Pins & Fissures Cover/Secondary Color: White
 Quantity of Material: 4500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Open office	NW Corner	E 2'	S 6'	8'	F / W / C / O
B	Conference Room	NW Corner	E 4'	S 8'	8'	F / W / C / O
C	Reception	SE Corner	W 3'	N 3'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAT-15 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 13,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-16 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 13,000 SF LF / EA Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-15

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Col* Date: 05/08/08 Signature: *M* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-17 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WB-16

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: DM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-TWP-18 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Paper Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ISS	NE Corner	W 2'	S 0'	2'	F/W/C/O
B	Principal	NE Corner	W 0'	S 2'	2'	F/W/C/O
C	Conference	NW Corner	E 0'	S 6'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CPT-19 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Fibrous Cover/Secondary Color: Multi-colored
 Quantity of Material: 13,500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	SE Corner	W 2'	N 0'	0'	F/W/I/C/O
B	Library	SW Corner	E 6'	N 0'	0'	F/W/I/C/O
C	ISS	NE Corner	W 0'	S 6'	0'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: Self-stick

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WAB-20 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (covered) Visible Covered Size: 4"
 Matrix/Primary Color: Black Texture/Pattern: Vinyl-like Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADH-21 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 600 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAS-20

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-22 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Doors, Windows, Millwork, Fixtures) Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: *Michael Richter* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-23 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 4'
 Matrix/Primary Color: Gray Texture/Pattern: Pinstripes Cover/Secondary Color: white
 Quantity of Material: 14,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	NW Corner	E 10'	S 5'	8'	F / W / C / O
B	AN	NW Corner	E 2'	S 2'	8'	F / W / C / O
C	Office S	NW Corner	E 2'	S 2'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-2H Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered WALLPAPER, SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Open office	NW Corner	E 6'	S 8'	8' 6"	F/W/C/O
B	Reception	NE Corner	W 0'	S 2'	8' 6"	F/W/C/O
C	L	SE Corner	W 10'	N 0'	8' 6"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with 5-SAT-28 & Wallpaper, Ten, Cloth-Like

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JIC-25 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered Wall paper, SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Open office	NW Corner	E 0'	S 8'	8' 6"	F/W/C/O
B	Reception	NE Corner	W 0'	S 2'	8' 6"	F/W/C/O
C	I	SE Corner	W 10'	N 0'	8' 6"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6WB.24

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-26 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Multi-colored
 Quantity of Material: 3500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MS-27 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A
 Matrix/Primary Color: Orange Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 3500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: *DN* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: 5-SAT-28 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1600 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAC-29 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-30 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile Size: 4" x 4"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure
 Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6RT-31 Damaged: Yes No Friable Non-Friable
 General Description: Grout Visible Covered Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWT.30, M.GWT-41, M.GWT.42

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-32 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2" x 2"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6RT-33 Damaged: Yes No Friable Non-Friable
 General Description: Grout Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-32, M-CMT-43, M-CMT-44

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAT-3H Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWB-35 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-34

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: SJTC-36 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Joint compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M.GWB-35

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-TOT-37 Damaged: Yes No Friable Non-Friable
 General Description: Troweled on Texture Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WB-38 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S.TOT.37

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CR Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-JTC-39 Visible Covered TOT Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 70 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-38

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-40 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x2'
 Matrix/Primary Color: Gray Texture/Pattern: PMS & FISSURES Cover/Secondary Color: white
 Quantity of Material: 100 Estimated By: Drawing Sampled Assumed
 Visible Covered
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Hallway 02	NW Corner	E 1"	S 0'	8'	F / W / C / O
B		NE Corner	W 0'	S 1"	8'	F / W / C / O
C		SE Corner	W 1'	N 1'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-41 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile (PIECES) Size: 4" X 4"
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *GM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-6WT-42 Damaged: Yes No Friable Non-Friable
 General Description: Glazed Wall Tile (PATTERN) Size: 4" X 4"
 Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-43 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2'x2'
 Matrix/Primary Color: Light Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-44 Damaged: Yes No Friable Non-Friable
 General Description: Ceramic Mosaic Tile Size: 2" X 2"
 Matrix/Primary Color: Green Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADH-45 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered FRP Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass reinforced panel, white, Textured

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *MR* Date: 05/08/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building K Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-PES-46 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: GR Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-BUR-D1 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT UP ROOFING
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY MINERAL CAP
 Quantity of Material: 16,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MAS-02 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS & FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MAS-03 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (FLASHING) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Placab Cover/Secondary Color: A/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-04 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (WALLS, FLASHINGS) Size: N/A
 Matrix/Primary Color: BROWN Cover/Secondary Color: N/A

Quantity of Material: 50 Texture/Pattern: TAR-LIKE Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.07mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SU-05 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, WALLS, FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: PLAQUE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-00 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNITS Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Size: 4x16"
 Quantity of Material: 7,500 Cover/Secondary Color: TAN Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other Sampled Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O


Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.M.R.07 Damaged: Yes No Friable Non-Friable
 General Description: WOLFRAM Visible Covered:
 Matrix/Primary Color: CARAY Texture/Pattern: CEMENT/TIDUS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.CMU.06

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-08 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, FLASHING) Size: 1 1/4
 Matrix/Primary Color: GRAY Texture/Pattern: PULABLE Cover/Secondary Color: 1 1/4
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesigRecordL.mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SET-09 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHING) Size: N/A

Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure
 Texture/Pattern: TAR LIKE

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-10 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DUCT) Visible Covered Size: N/A
 Matrix/Primary Color: WHIT Texture/Pattern: TAR-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SLT-11 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DUCT) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: BRITTLE Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ~~ASSUMED~~

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MWDB-12 Damaged: Yes No Friable Non-Friable
 General Description: WOVEN DUCT BOOT Size: 2" Drawing Assumed

Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 10 Texture/Pattern: RUBBER LIKE Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Signature: Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-SCT-13 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DUCT) Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: FAR-LIKE Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-STU-14 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 5,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspAC/MDsigRecord1.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CON-15 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE CONTAINERS Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.CON-16 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (FOUNDATION) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1600 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.ortf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-FD1-17 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL/WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 1596 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: 5-SAT-10 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Sampled
 Field Measure Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CONSESSION 1	NW Corner	E 0'	S 0'	4'	F / W / C / O
B	CONSESSION 2	SW Corner	E 0'	N 0'	4'	F / W / C / O
C	MOP SINK	NW Corner	E 0'	S 4'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACIMDesigRecord.ornf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-19 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT (PATCH) Size: 4"x11"x1"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.MRT.20 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U. 19

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-BK-21 Damaged: Yes No Friable Non-Friable
 General Description: BRICK Visible Covered Size: 4"x10"

Matrix/Primary Color: RED Texture/Pattern: CEMENTIOUS Cover/Secondary: N/A
 Quantity of Material: 2000 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M. W.B.R. 22 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 200 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.B.R. 22

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.S.L.T. 23 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES, WALLS) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: PLASTIC Cover/Secondary Color: N/A
 Quantity of Material: SD Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-24 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: SPINDLES & FISSURES Cover/Secondary Color: WHITE Size: 2'x4'
 Quantity of Material: 12,500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	L100	NE Corner	W 0'	S 0'	10'	F / W / C / O
B	L104	SW Corner	E 0'	N 0'	10'	F / W / C / O
C	STORAGE 4	NW Corner	E 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: FLUSH

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-EAT-25 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 9500 (SF) / LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other Sampled Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspAC/MDesigRecord.ortf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWBS-26 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 9500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other Sampled Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.25

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S.J.C.27 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered: SAT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: STARKY Cover/Secondary Color: N/A
 Quantity of Material: 950 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.W.S. 26

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspAC/MDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-TWP-28 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL Visible Covered Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER

Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	L103	SE Corner	W 1'	N 0'	5'	F W / C / O
B	L100	SE Corner	W 0'	N 1'	5'	F W / C / O
C	L105	NW Corner	E 0'	S 0'	5'	F W / C / O
D		Corner				F W / C / O
E		Corner				F W / C / O
F		Corner				F W / C / O
G		Corner				F W / C / O

Comments: _____
 Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.ami

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.C.P. 29 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: MULTICOLORED
 Quantity of Material: 7,200 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: SELF-STICK

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.V.C.F.30 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12x12"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: MULTICOLORED
 Quantity of Material: 6,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ~~ASSUMED~~

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-31 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (PATTERN) Size: 12'X12"

Matrix/Primary Color: GREEN Texture/Pattern: SMUDGY Cover/Secondary Color: BLACK SPECKS
 Quantity of Material: 500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-32 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (PATTERN) Size: 12"X12"

Matrix/Primary Color: PINK Cover/Secondary Color: BLACK SPECKS
 Quantity of Material: 500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.V.C.F. 33 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (PATTERN) Size: 12"x12"

Matrix/Primary Color: LIGHT BLUE Cover/Secondary Color: BLACK SPECKS
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspAC/MSigRecord.cmf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MWAS.34 Damaged: Yes No Friable Non-Friable
 General Description: MASBIC Visible Covered YCT Size: N/A

Matrix/Primary Color: ORANGE Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 7500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MWCT.30, MWCT.31, MWCT.32, MWCT.33, MWCT.74

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WAB-35 Damaged: Yes No Friable Non-Friable
 General Description: WALLBASE (COVERED) Visible Covered
 Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MADH-30 Visible Covered NAB Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Cover/Secondary Color: N/A
 Quantity of Material: 700 Texture/Pattern: PLIABLE Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other Sampled Assumed

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.WAB-33

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspAC/MDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.SAC.37 Damaged: Yes No Friable Non-Friable
 General Description: SINK ACOUSTICAL COATING Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: ROUGH Cover/Secondary Color: N/A
 Quantity of Material: 12 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.GWB.38 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 16.00 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspAC/MDsigRecord.omf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S.J.C.39 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered

Matrix/Primary Color: WHITE Texture/Pattern: CHACKY Cover/Secondary Color: N/A
 Quantity of Material: 1600 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.W.B. 3B

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CM Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADH-4P Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE (RESIDUAL) Visible Covered
 Matrix/Primary Color: BROWN Texture/Pattern: BEETLE Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 4000 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Michael Richter State License: EPA D10790
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-41 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2x2'

Matrix/Primary Color: GRAY Cover/Secondary Color: WHITE
 Quantity of Material: 1000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	VEST 1	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	VEST 2	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	VEST 4	NE Corner	W 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: (FLUSH)

Inspector: Dane Thompson State License: EPA
 AHERA Certificate No.: D12313 State License: EPA
 Signature: [Signature] Date: 05/08/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-SAT-42 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: W/ATE Cover/Secondary Color: N/A
 Quantity of Material: 3750 Estimated By: Drawing Sampled
 Field Measure Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	VEST 1	NW Corner	E 0'	S 0'	4"	F/W/C/O
B	VEST 2	NW Corner	E 0'	S 0'	4"	F/W/C/O
C	VEST 4	NE Corner	W 0'	S 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____
 Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWB-43 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 3750 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	VEST 1	NW Corner	E 0'	S 0'	4"	F/W/C/O
B	VEST 2	NW Corner	E 0'	S 0'	4"	F/W/C/O
C	VEST 4	NE Corner	W 0'	S 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH S.SAT.4/2

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.mtf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-51C.44 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 375 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	VEST 1	NW Corner	E 0'	S 0'	4"	F/W/C/O
B	VEST 2	NW Corner	E 0'	S 0'	4"	F/W/C/O
C	VEST 4	NE Corner	W 0'	S 0'	4"	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH M.GWB.43

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790
 Signature: [Signature] State License: EPA
 Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S.SAT.HS Damaged: Yes No Friable Non-Friable
 General Description: SPRAY APPLIED TEXTURE Visible Covered
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKLY Cover/Secondary/Color: N/A Size: N/A
 Quantity of Material: 3000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.GWB-46 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.45

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S.JIC.47 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 300 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWB.46

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.GWS-4B Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALLS Size: 4" x 4"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.GWT.49 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: GRUNT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 200 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GWT.48, M.GWT.49, M.GWT.70

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Michael Richter State License: EPA D10790 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMT-50 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Size: 2"x2"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.GRT.51 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 130 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.T. SO₂ M.C.M.T. 71, M.C.M.T. 72

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: SPOT-5Z Damaged: Yes No Friable Non-Friable
 General Description: TROWELED - ON TEXTURE Size: N/A

Matrix/Primary Color: NAKED Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GWB-53 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered JOT Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 3000 (SF) LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH STOT-52

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: S-AC-54 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 300 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. GIBB'S

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *DM* Date: 05/08/08 Signature: *[Signature]* Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.C.M.U. 55 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT Size: 4"X16"
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONOUS Cover/Secondary Color: SMOKE
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.MKT.SC Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U.S.S

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-57 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION SLIC Size: 12" X 12"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: TAN MOTILES
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Michael Richter State License: EPA D10790 Date: 05/08/08
 Signature: *[Signature]*

Asbestos-Containing Material: No Yes ~~ASSUMED~~

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: W.M.A.S.S.B Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 75 (SF) / LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.V.E.T. 57

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: CD Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-WAB-SR Damaged: Yes No Friable Non-Friable
 General Description: WALCBASE (COVERED) Visible Covered
 Matrix/Primary Color: BROWN Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.ADH.60 Damaged: Yes No Friable Non-Friable
 Visible Covered WABS Size: N/A

General Description: ADHESIVE Estimated By: Drawing Field Measure
 Sampled Assumed

Matrix/Primary Color: BROWN Cover/Secondary Color: N/A
 Quantity of Material: 15 Texture/Pattern: BRITTLE

Homogeneous Material Location: Ceiling Floor Wall Other
 SF / LF / EA

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.WABS.59

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CMU-61 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT Size: 8"X16"
 Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 1300 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.MRT.602 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: WOLYAR Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A

Quantity of Material: 130 Estimated By: Drawing Field Measure
 SF / LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.U. CO

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.W.A.B. 63 Damaged: Yes No Friable Non-Friable
 General Description: WALLBASE (COVERED) Visible Covered
 Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A Size: 4"
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D12313 State License: EPA D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 05/08/08 Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M. ADH-604 Visible Covered WAB Damaged: Yes No Friable Non-Friable

General Description: ADHESIVE Size: N/A
 Matrix/Primary Color: CREAM Cover/Secondary Color: N/A

Quantity of Material: 30 Estimated By: Drawing Field Measure
 Texture/Pattern: FLAKY

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. WAB-63

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-APL-605 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2x4x4
 Matrix/Primary Color: WHITE Texture/Pattern: CHECKED Cover/Secondary Color: VINYL-COATED
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SERVING	SE Corner	W 0'	N 0'	10'	F / W / C / O
B	CONSESSION 2	NW Corner	E 0'	S 0'	10'	F / W / C / O
C	CONSESSION 1	SW Corner	E 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.amf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.O.P.T. 666 Damaged: Yes No Friable Non-Friable
 General Description: QUARRY/PAVER YICE Size: 6" x 6"

Matrix/Primary Color: BROWN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GRT-607 Damaged: Yes No Friable Non-Friable
 General Description: GRAYS Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.O.P.F. COLO

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: W-ARK-COB Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x4'

Matrix/Primary Color: GRAY Texture/Pattern: LINEAR & FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 1500 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LOBBY	SW Corner	E 0'	N 0'	15'	F / W / C / O
B	LOBBY	SE Corner	W 0'	N 0'	15'	F / W / C / O
C	LOBBY	NE Corner	W 0'	S 0'	15'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: 4"X4" SQUARE PATTERN

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M. GWS. 609 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" X 4"
 Matrix/Primary Color: LIGHT GREEN Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: SMOOTH LF / EA SF / EA

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-GND-70 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE (PATTERN) Size: 4" x 4"

Matrix/Primary Color: GREEN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8286 fax

FM GROUP/forms/SuspACMDesigRecord1.amf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.C.M.A.-71 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC Tiles Size: 2' x 2'

Matrix/Primary Color: LIGHT GREEN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.pdf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-CM7-72 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Size: 2'x2'

Matrix/Primary Color: GREEN Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: W-APL-73 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: ACOUSTICAL CEILING PANEL Size: 2'x4'
 Matrix/Primary Color: GRAY Texture/Pattern: PICTHOLS & FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 5000 Estimated By: Drawing Field Measure
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	<u>MULTI PURPOSE</u>	<u>NE Corner</u>	<u>W 0'</u>	<u>S 0'</u>	<u>16'</u>	<u>F/W/C/O</u>
B	<u>MULTI PURPOSE</u>	<u>SW Corner</u>	<u>E 0'</u>	<u>N 0'</u>	<u>16'</u>	<u>F/W/C/O</u>
C	<u>MULTI PURPOSE</u>	<u>SE Corner</u>	<u>W 0'</u>	<u>N 0'</u>	<u>16'</u>	<u>F/W/C/O</u>
D		<u>Corner</u>				<u>F/W/C/O</u>
E		<u>Corner</u>				<u>F/W/C/O</u>
F		<u>Corner</u>				<u>F/W/C/O</u>
G		<u>Corner</u>				<u>F/W/C/O</u>

Comments: 2'X2' PATTERN

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-109-714 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" X 12"
 Matrix/Primary Color: PINK Cover/Secondary Color: TAN MOTILES
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D12313 Date: 05/08/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 05/08/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VST-75 Damaged: Yes No Friable Non-Friable
 General Description: VINYL STAIR TREADS Size: 12" X 36"

Matrix/Primary Color: BLACK Texture/Pattern: VINYL-LIKE Cover/Secondary Color: CIRCLE PATTERN
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-MAS-76 Visible Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Covered VST Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITCLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.S.T. 75

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

F/M
GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-ADH-77 Visible Covered MIRROR Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE (MIRROR) Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M-VCT-78 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" X 12"

Matrix/Primary Color: OFF-WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: BROWN MOTTLES
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.M.A.S.79 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: STACKY Cover/Secondary Color: N/A
 Quantity of Material: 500 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.S.T.7B

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: MADH-80 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered FRP
 Matrix/Primary Color: BROWN Texture/Pattern: BRITCLE Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH FIBROUS GLASS REINFORCED PANEL, WHITE, TEXTURED

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M.G.W.F.81 Damaged: Yes No Friable Non-Friable
 General Description: GRADED WALL TILE Size: 4" X 4"

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: Tan Marble Pattern
 Quantity of Material: 225 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8286 fax

Project No.: 08-145 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Building L Address: 1050 E. Carver Road
 Campus Name: Kyrene Middle School Tempe, AZ 85284

Material Code: M. GRI. B2 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered:
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 23 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. GWT. B1

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D12313 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 05/08/08 Signature: [Signature] Date: 05/08/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecordl.pdf

APPENDIX B

Bulk-Material Sample Documents

- **Chain-of-Custody**
- **Laboratory Analysis**



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804296

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 16 PLM Rec: 5/12/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Middle School/Bldg E

PO Number: 08-145

Report Date: 5/26/2008

Date Analyzed: 5/26/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200804296

Kyrene Middle School/Bldg E

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	S-SAF-19A	2008-04296- 1	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-19B	2008-04296- 2	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-19C	2008-04296- 3	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-19D	2008-04296- 4	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-19E	2008-04296- 5	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-19F	2008-04296- 6	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	S-SAF-19G	2008-04296- 7	Sprayed Material	Positive Layer? No
Layer # 1	Off-white	fireproofing	<i>no asbestos detected</i>	
Sample #	M-DST-22A	2008-04296- 8	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-22B	2008-04296- 9	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-DST-22C	2008-04296- 10	Miscellaneous	Positive Layer? No
Layer # 1	White	duct tape	<i>no asbestos detected</i>	
Sample #	M-APL-31A	2008-04296- 11	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-31B	2008-04296- 12	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-31C	2008-04296- 13	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-58A	2008-04296- 14	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-58B	2008-04296- 15	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-58C	2008-04296- 16	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number:

200804296

Kyrene Middle School/Bldg E

Sample S-SAF-19A **Lab Number** 2008-04296- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-19B **Lab Number** 2008-04296- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-19C **Lab Number** 2008-04296- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804296 Kyrene Middle School/Bldg E

Sample S-SAF-19D **Lab Number** 2008-04296- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-19E **Lab Number** 2008-04296- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-19F **Lab Number** 2008-04296- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804296 Kyrene Middle School/Bldg E

Sample S-SAF-19G **Lab Number** 2008-04296- 7 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	fireproofing	100	Off-white	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-DST-22A **Lab Number** 2008-04296- 8 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	70-80%	-	-	-	-	-
Total %		100	Average %		70-80%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-22B **Lab Number** 2008-04296- 9 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	70-80%	-	-	-	-	-
Total %		100	Average %		70-80%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200804296 Kyrene Middle School/Bldg E

Sample M-DST-22C **Lab Number** 2008-04296- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	70-80%	-	-	-	-	-
Total %		100	Average %		70-80%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-APL-31A **Lab Number** 2008-04296- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-31B **Lab Number** 2008-04296- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804296 Kyrene Middle School/Bldg E

Sample M-APL-31C **Lab Number** 2008-04296- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-58A **Lab Number** 2008-04296- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-58B **Lab Number** 2008-04296- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804296

Kyrene Middle School/Bldg E


Sample M-APL-58C **Lab Number** 2008-04296- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 26-May-08

Original Print Date: 26-May-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804297

Client:

FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ

85260-0000

Office Phone:

(602) 277-7877

FAX:

(602) 277-8288

Samples: 18 PLM **Rec:** 5/12/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Middle School/Bldg F

PO Number: 08-145

Report Date: 5/26/2008

Date Analyzed: 5/26/2008

Routing Number: -

Method and Analysis Information:

Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200804297

Kyrene Middle School/Bldg F

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-24A	2008-04297- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-24B	2008-04297- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-24C	2008-04297- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-GWB-25A	2008-04297- 4	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-25B	2008-04297- 5	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-25C	2008-04297- 6	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-26A	2008-04297- 7	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-26B	2008-04297- 8	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-26C	2008-04297- 9	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-APL-37A	2008-04297- 10	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-37B	2008-04297- 11	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-37C	2008-04297- 12	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-TWP-51A	2008-04297- 13	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-51B	2008-04297- 14	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-51C	2008-04297- 15	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	S-SAF-53A	2008-04297- 16	Sprayed Material	Positive Layer? No
Layer # 1	White	beam spray	<i>no asbestos detected</i>	
Sample #	S-SAF-53B	2008-04297- 17	Sprayed Material	Positive Layer? No
Layer # 1	White	beam spray	<i>no asbestos detected</i>	
Sample #	S-SAF-53C	2008-04297- 18	Sprayed Material	Positive Layer? No
Layer # 1	White	beam spray	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number:

200804297

Kyrene Middle School/Bldg F

Sample M-APL-24A **Lab Number** 2008-04297- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24B **Lab Number** 2008-04297- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24C **Lab Number** 2008-04297- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number:

200804297

Kyrene Middle School/Bldg F

Sample M-GWB-25A **Lab Number** 2008-04297- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-25B **Lab Number** 2008-04297- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-25C **Lab Number** 2008-04297- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200804297

Kyrene Middle School/Bldg F

Sample S-JTC-26A **Lab Number** 2008-04297- 7 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-26B **Lab Number** 2008-04297- 8 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-26C **Lab Number** 2008-04297- 9 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804297

Kyrene Middle School/Bldg F

Sample M-APL-37A **Lab Number** 2008-04297- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37B **Lab Number** 2008-04297- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37C **Lab Number** 2008-04297- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804297 Kyrene Middle School/Bldg F

Sample M-TWP-51A **Lab Number** 2008-04297- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber						
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6	
1	panel	100	Tan	1	90-100%	-	-	-	-	-	
Total %		100	Average %			90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber						

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-51B **Lab Number** 2008-04297- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber						
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6	
1	panel	100	Tan	1	90-100%	-	-	-	-	-	
Total %		100	Average %			90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber						

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-51C **Lab Number** 2008-04297- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber						
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6	
1	panel	100	Tan	1	90-100%	-	-	-	-	-	
Total %		100	Average %			90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber						

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804297

Kyrene Middle School/Bldg F

Sample S-SAF-53A **Lab Number** 2008-04297- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	White	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-53B **Lab Number** 2008-04297- 17 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	White	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-53C **Lab Number** 2008-04297- 18 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	White	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;


D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 26-May-08

Original Print Date: 26-May-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804298

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 21 **PLM** **Rec:** 5/12/2008 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene Middle School/Bldg G **PO Number:** 08-145
Report Date: 5/26/2008 **Date Analyzed:** 5/26/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $>1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $>1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200804298

Kyrene Middle School/Bldg G

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-24A	2008-04298- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-24B	2008-04298- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-24C	2008-04298- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-GWB-25A	2008-04298- 4	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-25B	2008-04298- 5	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-25C	2008-04298- 6	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-26A	2008-04298- 7	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-26B	2008-04298- 8	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-26C	2008-04298- 9	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-33A	2008-04298- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-33B	2008-04298- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-33C	2008-04298- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-APL-37A	2008-04298- 13	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-37B	2008-04298- 14	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-37C	2008-04298- 15	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-TWP-51A	2008-04298- 16	Wall System	Positive Layer? No
Layer # 1	White	surface	no asbestos detected	
Layer # 2	Tan	panel	no asbestos detected	
Sample #	M-TWP-51B	2008-04298- 17	Wall System	Positive Layer? No
Layer # 1	White	surface	no asbestos detected	
Layer # 2	Tan	panel	no asbestos detected	
Sample #	M-TWP-51C	2008-04298- 18	Wall System	Positive Layer? No
Layer # 1	White	surface	no asbestos detected	
Layer # 2	Tan	panel	no asbestos detected	
Sample #	S-SAF-53A	2008-04298- 19	Sprayed Material	Positive Layer? No
Layer # 1	Gray	beam spray	no asbestos detected	
Sample #	S-SAF-53B	2008-04298- 20	Sprayed Material	Positive Layer? No
Layer # 1	Gray	beam spray	no asbestos detected	
Sample #	S-SAF-53C	2008-04298- 21	Sprayed Material	Positive Layer? No
Layer # 1	Gray	beam spray	no asbestos detected	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number:

200804298

Kyrene Middle School/Bldg G

Sample M-APL-24A **Lab Number** 2008-04298- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24B **Lab Number** 2008-04298- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24C **Lab Number** 2008-04298- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804298 Kyrene Middle School/Bldg G

Sample M-GWB-25A **Lab Number** 2008-04298- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Procedure: tweased apart using forceps.

Sample M-GWB-25B **Lab Number** 2008-04298- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Procedure: tweased apart using forceps.

Sample M-GWB-25C **Lab Number** 2008-04298- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804298 Kyrene Middle School/Bldg G

Sample S-JTC-26A **Lab Number** 2008-04298- 7 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-26B **Lab Number** 2008-04298- 8 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-26C **Lab Number** 2008-04298- 9 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804298

Kyrene Middle School/Bldg G

Sample S-SAT-33A **Lab Number** 2008-04298- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-33B **Lab Number** 2008-04298- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-33C **Lab Number** 2008-04298- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804298 Kyrene Middle School/Bldg G

Sample M-APL-37A **Lab Number** 2008-04298- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37B **Lab Number** 2008-04298- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37C **Lab Number** 2008-04298- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804298 Kyrene Middle School/Bldg G

Sample M-TWP-51A **Lab Number** 2008-04298- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous No **# Layers** 2 **Pos Layer?** No **# Sub-Samples** 4
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	80	White	1	10-20%	-	-	-	-	-
2	panel	20	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		10-20%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

Sample M-TWP-51B **Lab Number** 2008-04298- 17 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous No **# Layers** 2 **Pos Layer?** No **# Sub-Samples** 4
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	80	White	1	10-20%	-	-	-	-	-
2	panel	20	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		10-20%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

Sample M-TWP-51C **Lab Number** 2008-04298- 18 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous No **# Layers** 2 **Pos Layer?** No **# Sub-Samples** 4
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	surface	80	White	1	10-20%	-	-	-	-	-
2	panel	20	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		10-20%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose fiber	W	F	N	N	H	+	U						
2														
3														
4														
5														
6														

PLM Analysis Details

Job Number: 200804298 Kyrene Middle School/Bldg G

Sample S-SAF-53A **Lab Number** 2008-04298- 19 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-53B **Lab Number** 2008-04298- 20 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-53C **Lab Number** 2008-04298- 21 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	Gray	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 26-May-08

Original Print Date: 26-May-08

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804299

Client:

FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ

85260-0000

Office Phone:

(602) 277-7877

FAX:

(602) 277-8288

Samples: 21 PLM Rec: 5/12/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Middle School/Bldg H

PO Number: 08-145

Report Date: 5/26/2008

Date Analyzed: 5/26/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200804299

Kyrene Middle School/Bldg H

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-24A	2008-04299- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-24B	2008-04299- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-24C	2008-04299- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-GWB-25A	2008-04299- 4	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-25B	2008-04299- 5	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-25C	2008-04299- 6	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-26A	2008-04299- 7	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-26B	2008-04299- 8	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-26C	2008-04299- 9	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-CPT-27A	2008-04299- 10	Carpet	Positive Layer? No
Layer # 1	various	carpet	<i>no asbestos detected</i>	
Sample #	M-CPT-27B	2008-04299- 11	Carpet	Positive Layer? No
Layer # 1	various	carpet	<i>no asbestos detected</i>	
Sample #	M-CPT-27C	2008-04299- 12	Carpet	Positive Layer? No
Layer # 1	various	carpet	<i>no asbestos detected</i>	
Sample #	M-APL-37A	2008-04299- 13	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-37B	2008-04299- 14	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-37C	2008-04299- 15	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-TWP-51A	2008-04299- 16	Wall System	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-51B	2008-04299- 17	Wall System	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-51C	2008-04299- 18	Wall System	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	S-SAF-53A	2008-04299- 19	Sprayed Material	Positive Layer? No
Layer # 1	White	beam spray	<i>no asbestos detected</i>	
Sample #	S-SAF-53B	2008-04299- 20	Sprayed Material	Positive Layer? No
Layer # 1	White	beam spray	<i>no asbestos detected</i>	
Sample #	S-SAF-53C	2008-04299- 21	Sprayed Material	Positive Layer? No
Layer # 1	White	beam spray	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number:

200804299

Kyrene Middle School/Bldg H

Sample M-APL-24A **Lab Number** 2008-04299- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile Fibrous Mat
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24B **Lab Number** 2008-04299- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile Fibrous Mat
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24C **Lab Number** 2008-04299- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile Fibrous Mat
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number:

200804299

Kyrene Middle School/Bldg H

Sample M-GWB-25A **Lab Number** 2008-04299- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-25B **Lab Number** 2008-04299- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-25C **Lab Number** 2008-04299- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804299

Kyrene Middle School/Bldg H

Sample S-JTC-26A Lab Number 2008-04299- 7 Sampled: 5/8/2008 Condition: acceptable
 Analyzed By LSP 5/26/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-26B Lab Number 2008-04299- 8 Sampled: 5/8/2008 Condition: acceptable
 Analyzed By LSP 5/26/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-26C Lab Number 2008-04299- 9 Sampled: 5/8/2008 Condition: acceptable
 Analyzed By LSP 5/26/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804299 Kyrene Middle School/Bldg H

Sample M-CPT-27A **Lab Number** 2008-04299- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	V	E	N	N	H	+	P						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-27B **Lab Number** 2008-04299- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	V	E	N	N	H	+	P						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-27C **Lab Number** 2008-04299- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	V	E	N	N	H	+	P						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804299 Kyrene Middle School/Bldg H

Sample M-APL-37A **Lab Number** 2008-04299- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37B **Lab Number** 2008-04299- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-37C **Lab Number** 2008-04299- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804299 Kyrene Middle School/Bldg H

Sample M-TWP-51A **Lab Number** 2008-04299- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	-	-	-	-	-
Total %		100	Average %		70-80%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-51B **Lab Number** 2008-04299- 17 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	-	-	-	-	-
Total %		100	Average %		70-80%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-51C **Lab Number** 2008-04299- 18 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	70-80%	-	-	-	-	-
Total %		100	Average %		70-80%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200804299 Kyrene Middle School/Bldg H

Sample S-SAF-53A **Lab Number** 2008-04299- 19 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	White	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-53B **Lab Number** 2008-04299- 20 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	White	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAF-53C **Lab Number** 2008-04299- 21 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Sprayed Material **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, powder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	beam spray	100	White	3	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper


Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon

yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 26-May-08

Original Print Date: 26-May-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804300

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 27 PLM Rec: 5/12/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Middle School/Bldg J

PO Number: 08-145

Report Date: 5/26/2008

Date Analyzed: 5/26/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $>1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $>1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200804300

Kyrene Middle School/Bldg J

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	S-TOT-01A	2008-04300- 1	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-TOT-01B	2008-04300- 2	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-TOT-01C	2008-04300- 3	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-02A	2008-04300- 4	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-02B	2008-04300- 5	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-02C	2008-04300- 6	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-03A	2008-04300- 7	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-03B	2008-04300- 8	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-03C	2008-04300- 9	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-APL-19A	2008-04300- 10	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	no asbestos detected	
Sample #	M-APL-19B	2008-04300- 11	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	no asbestos detected	
Sample #	M-APL-19C	2008-04300- 12	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	no asbestos detected	
Sample #	S-SAT-20A	2008-04300- 13	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-20B	2008-04300- 14	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-20C	2008-04300- 15	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-21A	2008-04300- 16	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-21B	2008-04300- 17	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-21C	2008-04300- 18	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-22A	2008-04300- 19	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-22B	2008-04300- 20	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-22C	2008-04300- 21	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-CPT-23A	2008-04300- 22	Carpet	Positive Layer? No
Layer # 1	various	carpet	no asbestos detected	
Sample #	M-CPT-23B	2008-04300- 23	Carpet	Positive Layer? No
Layer # 1	various	carpet	no asbestos detected	
Sample #	M-CPT-23C	2008-04300- 24	Carpet	Positive Layer? No
Layer # 1	various	carpet	no asbestos detected	
Sample #	M-TWP-34A	2008-04300- 25	Wall System	Positive Layer? No
Layer # 1	Tan	panel	no asbestos detected	
Sample #	M-TWP-34B	2008-04300- 26	Wall System	Positive Layer? No
Layer # 1	Tan	panel	no asbestos detected	
Sample #	M-TWP-34C	2008-04300- 27	Wall System	Positive Layer? No
Layer # 1	Tan	panel	no asbestos detected	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number:

200804300

Kyrene Middle School/Bldg J

Sample S-TOT-01A **Lab Number** 2008-04300- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-TOT-01B **Lab Number** 2008-04300- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-TOT-01C **Lab Number** 2008-04300- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804300

Kyrene Middle School/Bldg J

Sample M-GWB-02A **Lab Number** 2008-04300- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-02B **Lab Number** 2008-04300- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-02C **Lab Number** 2008-04300- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804300 Kyrene Middle School/Bldg J

Sample S-JTC-03A **Lab Number** 2008-04300- 7 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-03B **Lab Number** 2008-04300- 8 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-03C **Lab Number** 2008-04300- 9 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804300 Kyrene Middle School/Bldg J

Sample M-APL-19A **Lab Number** 2008-04300- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-19B **Lab Number** 2008-04300- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-19C **Lab Number** 2008-04300- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804300

Kyrene Middle School/Bldg J

Sample S-SAT-20A **Lab Number** 2008-04300- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-20B **Lab Number** 2008-04300- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-20C **Lab Number** 2008-04300- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number:

200804300

Kyrene Middle School/Bldg J

Sample M-GWB-21A **Lab Number** 2008-04300- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-21B **Lab Number** 2008-04300- 17 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-21C **Lab Number** 2008-04300- 18 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804300

Kyrene Middle School/Bldg J

Sample S-JTC-22A **Lab Number** 2008-04300- 19 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-22B **Lab Number** 2008-04300- 20 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-22C **Lab Number** 2008-04300- 21 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804300 Kyrene Middle School/Bldg J

Sample M-CPT-23A **Lab Number** 2008-04300- 22 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-23B **Lab Number** 2008-04300- 23 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-23C **Lab Number** 2008-04300- 24 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-

Fiber Identification: synthetic fiber (extr)

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804300 Kyrene Middle School/Bldg J

Sample M-TWP-34A **Lab Number** 2008-04300- 25 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-34B **Lab Number** 2008-04300- 26 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-TWP-34C **Lab Number** 2008-04300- 27 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/26/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 26-May-08

Original Print Date: 26-May-08

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804301

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 21 PLM **Rec:** 5/12/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Middle School/Bldg K

PO Number: 08-145

Report Date: 5/30/2008

Date Analyzed: 5/30/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Polutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200804301

Kyrene Middle School/Bldg K

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-14A	2008-04301- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-14B	2008-04301- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-14C	2008-04301- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-TWP-18A	2008-04301- 4	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-18B	2008-04301- 5	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-TWP-18C	2008-04301- 6	Miscellaneous	Positive Layer? No
Layer # 1	Tan	panel	<i>no asbestos detected</i>	
Sample #	M-CPT-19A	2008-04301- 7	Carpet	Positive Layer? No
Layer # 1	various	carpet	<i>no asbestos detected</i>	
Sample #	M-CPT-19B	2008-04301- 8	Carpet	Positive Layer? No
Layer # 1	various	carpet	<i>no asbestos detected</i>	
Sample #	M-CPT-19C	2008-04301- 9	Carpet	Positive Layer? No
Layer # 1	various	carpet	<i>no asbestos detected</i>	
Sample #	M-APL-23A	2008-04301- 10	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-23B	2008-04301- 11	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-23C	2008-04301- 12	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-GWB-24A	2008-04301- 13	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-24B	2008-04301- 14	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-24C	2008-04301- 15	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-25A	2008-04301- 16	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-25B	2008-04301- 17	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-25C	2008-04301- 18	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-APL-40A	2008-04301- 19	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-40B	2008-04301- 20	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-40C	2008-04301- 21	Ceiling Tile	Positive Layer? No
Layer # 1	Tan	ceiling tile	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number:

200804301

Kyrene Middle School/Bldg K

Sample M-APL-14A **Lab Number** 2008-04301- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-14B **Lab Number** 2008-04301- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-14C **Lab Number** 2008-04301- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804301 Kyrene Middle School/Bldg K

Sample M-TWP-18A **Lab Number** 2008-04301- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-18B **Lab Number** 2008-04301- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-18C **Lab Number** 2008-04301- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804301 Kyrene Middle School/Bldg K

Sample M-CPT-19A **Lab Number** 2008-04301- 7 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-19B **Lab Number** 2008-04301- 8 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-CPT-19C **Lab Number** 2008-04301- 9 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer foam, polymer, filler

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804301 Kyrene Middle School/Bldg K

Sample M-APL-23A **Lab Number** 2008-04301- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-23B **Lab Number** 2008-04301- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-23C **Lab Number** 2008-04301- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804301

Kyrene Middle School/Bldg K

Sample M-GWB-24A **Lab Number** 2008-04301- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-24B **Lab Number** 2008-04301- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-24C **Lab Number** 2008-04301- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804301 Kyrene Middle School/Bldg K

Sample S-JTC-25A **Lab Number** 2008-04301- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-25B **Lab Number** 2008-04301- 17 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-25C **Lab Number** 2008-04301- 18 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804301 Kyrene Middle School/Bldg K

Sample M-APL-40A **Lab Number** 2008-04301- 19 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-40B **Lab Number** 2008-04301- 20 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.


Sample M-APL-40C **Lab Number** 2008-04301- 21 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: LARRY S. PIERCE

Printed: 30-May-08

Original Print Date: 30-May-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200804302

Client:

FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ

85260-0000

Office Phone:

(602) 277-7877

FAX:

(602) 277-8288

Samples: 30 PLM Rec: 5/12/2008 Method: EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Middle School/Bldg L

PO Number: 08-145

Report Date: 5/30/2008

Date Analyzed: 5/30/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200804302

Kyrene Middle School/Bldg L

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # S-SAT-18A Layer # 1 Pink	2008-04302- 1	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # S-SAT-18B Layer # 1 White	2008-04302- 2	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # S-SAT-18C Layer # 1 White	2008-04302- 3	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-24A Layer # 1 off-white	2008-04302- 4	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-24B Layer # 1 off-white	2008-04302- 5	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-24C Layer # 1 off-white	2008-04302- 6	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-TWP-28A Layer # 1 Tan	2008-04302- 7	Miscellaneous panel	Positive Layer? No <i>no asbestos detected</i>
Sample # M-TWP-28B Layer # 1 Tan	2008-04302- 8	Miscellaneous panel	Positive Layer? No <i>no asbestos detected</i>
Sample # M-TWP-28C Layer # 1 Tan	2008-04302- 9	Miscellaneous panel	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-41A Layer # 1 Tan	2008-04302- 10	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-41B Layer # 1 Tan	2008-04302- 11	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-41C Layer # 1 Tan	2008-04302- 12	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # S-SAT-42A Layer # 1 white	2008-04302- 13	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # S-SAT-42B Layer # 1 white	2008-04302- 14	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # S-SAT-42C Layer # 1 white	2008-04302- 15	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # M-GWB-43A Layer # 1 white	2008-04302- 16	Wall System drywall core	Positive Layer? No <i>no asbestos detected</i>
Sample # M-GWB-43B Layer # 1 white	2008-04302- 17	Wall System drywall core	Positive Layer? No <i>no asbestos detected</i>
Sample # M-GWB-43C Layer # 1 white	2008-04302- 18	Wall System drywall core	Positive Layer? No <i>no asbestos detected</i>
Sample # S-JTC-44A Layer # 1 white	2008-04302- 19	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # S-JTC-44B Layer # 1 white	2008-04302- 20	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # S-JTC-44C Layer # 1 white	2008-04302- 21	Wall System texture/joint compound	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-65A Layer # 1 White	2008-04302- 22	Wall System panel	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-65B Layer # 1 White	2008-04302- 23	Wall System panel	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-65C Layer # 1 White	2008-04302- 24	Wall System panel	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-68A Layer # 1 off-white	2008-04302- 25	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-68B Layer # 1 off-white	2008-04302- 26	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-68C Layer # 1 off-white	2008-04302- 27	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-73A Layer # 1 Tan	2008-04302- 28	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-73B Layer # 1 Tan	2008-04302- 29	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>
Sample # M-APL-73C Layer # 1 Tan	2008-04302- 30	Ceiling Tile ceiling tile	Positive Layer? No <i>no asbestos detected</i>

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200804302 Kyrene Middle School/Bldg L

Sample S-SAT-18A **Lab Number** 2008-04302- 1 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	Pink	3	2-5%	-	-	-	-	-
Total %		100	Average %		2-5%	-	-	-	-	-

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-18B **Lab Number** 2008-04302- 2 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	White	3	2-5%	-	-	-	-	-
Total %		100	Average %		2-5%	-	-	-	-	-

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-18C **Lab Number** 2008-04302- 3 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	White	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804302

Kyrene Middle School/Bldg L

Sample M-APL-24A **Lab Number** 2008-04302- 4 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24B **Lab Number** 2008-04302- 5 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-24C **Lab Number** 2008-04302- 6 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804302 Kyrene Middle School/Bldg L

Sample M-TWP-28A **Lab Number** 2008-04302-7 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-28B **Lab Number** 2008-04302-8 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-TWP-28C **Lab Number** 2008-04302-9 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	Tan	1	90-100%	-	-	-	-	-
Total %		100	Average %		90-100%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804302 Kyrene Middle School/Bldg L

Sample M-APL-41A **Lab Number** 2008-04302- 10 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-41B **Lab Number** 2008-04302- 11 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-41C **Lab Number** 2008-04302- 12 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804302 Kyrene Middle School/Bldg L

Sample S-SAT-42A **Lab Number** 2008-04302- 13 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-42B **Lab Number** 2008-04302- 14 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-42C **Lab Number** 2008-04302- 15 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804302

Kyrene Middle School/Bldg L

Sample M-GWB-43A **Lab Number** 2008-04302- 16 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	CL	D	Y											
2	W	F	N	N	H	+	U							
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-43B **Lab Number** 2008-04302- 17 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	CL	D	Y											
2	W	F	N	N	H	+	U							
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-43C **Lab Number** 2008-04302- 18 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	CL	D	Y											
2	W	F	N	N	H	+	U							
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200804302 Kyrene Middle School/Bldg L

Sample S-JTC-44A **Lab Number** 2008-04302- 19 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-44B **Lab Number** 2008-04302- 20 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-44C **Lab Number** 2008-04302- 21 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200804302 Kyrene Middle School/Bldg L

Sample M-APL-65A **Lab Number** 2008-04302- 22 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	1	>1-2%	<=1%	-	-	-	-
Total %		100	Average %		>1-2%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Analysis includes the paper wrap. This is essentially a piece of drywall.

Sample M-APL-65B **Lab Number** 2008-04302- 23 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	1	>1-2%	<=1%	-	-	-	-
Total %		100	Average %		>1-2%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Analysis includes the paper wrap. This is essentially a piece of drywall.

Sample M-APL-65C **Lab Number** 2008-04302- 24 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	panel	100	White	1	>1-2%	<=1%	-	-	-	-
Total %		100	Average %		>1-2%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Analysis includes the paper wrap. This is essentially a piece of drywall.

PLM Analysis Details

Job Number: 200804302

Kyrene Middle School/Bldg L

Sample M-APL-68A **Lab Number** 2008-04302- 25 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-68B **Lab Number** 2008-04302- 26 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-68C **Lab Number** 2008-04302- 27 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	W	F	N	N	H	+	U						
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200804302

Kyrene Middle School/Bldg L

Sample M-APL-73A **Lab Number** 2008-04302- 28 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-73B **Lab Number** 2008-04302- 29 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-73C **Lab Number** 2008-04302- 30 **Sampled:** 5/8/2008 **Condition:** acceptable
Analyzed By LSP 5/30/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	Tan	3	20-30%	-	-	-	-	-
Total %		100	Average %		20-30%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black; BL=blue; BR=brown; CL=clear; G=Green; GY=gray; OR=orange; OW=off-white; PN=pink; PU=purple; R=red; TN=tan; W=white; Y=yellow; V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;

D=fine to coarse fibers, CL-B, brittle; E=coarse fibers, CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon

yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: LARRY S. PIERCE

Printed: 30-May-08

Original Print Date: 30-May-08

Larry S. Pierce, Approved Accreditation Signatory

APPENDIX C

Building Inspectors' Signature Sheet

BUILDING INSPECTOR'S SIGNATURE SHEET

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene Middle School
Kyrene School District No. 28

FM Project 08-145

The individual(s) whose signature(s) is/are shown below is/are EPA Accredited Building Inspector(s) who participated in one or more of the following activities:


- A. Visual Inspection of Facilities
- B. Identification of Homogenous Areas of Asbestos-Containing Materials
- C. Development of Sampling Plan and Protocols
- D. Bulk Sampling Activities/Material Identifications
- E. Assessing ACBM/ACM
- F. Preparing Report of Findings

<u>INSPECTOR</u>	<u>ACTIVITIES</u>	<u>DATES</u>
Paul Anger Printed Name D 11441 Accreditation No. Signature	PA Initials EPA State	F 6/8/08
Michael Richter Printed Name D 10790 Accreditation No. Signature	MR Initials EPA State	A, B, D, E 5/5/08 – 5/12/08
Cliff Rolle Printed Name D 12516 Accreditation No. Signature	CR Initials EPA State	C, F 5/5/08 – 6/8/08
Dane Thompson Printed Name D 12313 Accreditation No. Signature	DT Initials EPA State	A, B, D, E 5/5/08 – 5/12/08

APPENDIX D

Personnel and Laboratory Accreditations

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector
January 4, 2008**

and successfully passed the competency exam.

Date of Examination: **January 4, 2008**

Date of Expiration: **January 4, 2009**

[Signature]
 Director

[Signature]
 Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE

Certifies that

Michael Allen Richter

has attended the EPA approved course

**AHERA
Building Inspector**

September 10-12, 2007


and successfully passed the competency exam.

Date of Examination: **September 12, 2007**

Date of Expiration: **September 12, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector
May 30, 2008**


and successfully passed the competency exam.

Date of Examination: **May 30, 2008**


Date of Expiration: **May 30, 2009**



Director



Approved Instructor



THE ASBESTOS INSTITUTE

8102 North 23rd Avenue



Suite A

Phoenix, AZ 85021-4962

602-864-6564

D 12313

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector**

May 2, 2008

and successfully passed the competency exam.

Date of Examination: **May 2, 2008**

Date of Expiration: **May 2, 2009**

[Signature]

Director

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:1999

NVLAP LAB CODE: 101031-0

Fiberquant, Inc.
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in
NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS



2007-07-01 through 2008-06-30

Effective dates

Dolly S. Bruce
For the National Institute of Standards and Technology