

ASBESTOS MANAGEMENT PLAN



at

Kyrene De Los Ninos Elementary School

Prepared for:

Kyrene School District No. 28

VOLUME I OF II

**FM GROUP INC
FM Project 07-367**

March 2008

ASBESTOS MANAGEMENT PLAN

Kyrene De Los Ninos Elementary School

March 2008

FM GROUP INC

FM Project 07-367

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY	1-1
2	INSPECTION REPORT	2-1
3	DESIGNATED PERSON IDENTIFICATION	3-1
4	RESPONSE ACTION	4-1
5	ACCREDITATION STATEMENTS	5-1
6	REMAINING ACBM.....	6-1
7	O&M PROGRAM.....	7-1
8	INITIAL NOTIFICATIONS	8-1
9	COST ESTIMATION	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON	10-1
11	ANNUAL NOTIFICATIONS	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT	12-1

APPENDIX A: ONGOING RECORDKEEPING

SECTION 1

GENERAL INVENTORY

General Inventory
763.93(e)(1)

Date: MARCH 4, 2008

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: KYRENE DE LOS NINOS ELEMENTARY SCHOOL

Address: 1330 EAST DAVA DRIVE
TEMPE, ARIZONA 85284

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
MAIN	N/A	X	X
MULTI-PURPOSE	N/A	X	X
PORTABLE R1/R3	N/A	X	X
PORTABLE R2/R4	N/A	X	X
PORTABLE R5/R7	N/A	X	X
PORTABLE R6/R8	N/A	X	X
PORTABLE R9/R11	N/A	X	X
PORTABLE R10/R12	N/A	X	X

SECTION 2

INSPECTION REPORT

INSPECTION REPORT

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:


Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School

Prepared by: FM GROUP INC
Project No.: 07-367
Date: March 2008

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28
8700 South Kyrene Road
Tempe, Arizona 85284-2197

REPORT OF FINDINGS
(Abridged Version)



Comprehensive AHERA Asbestos Inspection

at

Kyrene De Los Ninos Elementary School

Prepared for:

Kyrene School District No. 28

FM GROUP INC
FM Project 07-367

March 2008

TABLE OF CONTENTS

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School
Kyrene School District No. 28

FM GROUP Project 07-367

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u>	1
1.1 Summary	1
1.2 Identified Asbestos-Containing Materials	1
1.3 Asbestos-Containing Building Materials (Table C)	2
1.4 ACBM/Location Plans	3
1.5 Critical Situations	4
1.6 Friable Asbestos-Containing Building Materials	4
1.7 Material Assessments	4
1.8 Recommendations	4
1.9 Qualifications of the Report.....	4
2.0 <u>PROJECT INFORMATION</u>	5
2.1 Background.....	5
2.2 Description of Construction	5
2.2.1 Main Building	5
2.2.2 Multi-Purpose Building.....	6
2.2.3 Portables R1/R3, R2/R4, R5/R7, R6/R8, R9/R11 and R10/R12	6
2.3 Building Materials/Systems List (Table A).....	8
2.3.1 Main Building	9
2.3.2 Multi-Purpose Building.....	54
2.3.3 Portable R1/R3.....	72
2.3.4 Portable R2/R4.....	74
2.3.5 Portable R5/R7	76
2.3.6 Portable R6/R8.....	78
2.3.7 Portable R9/R11	80
2.3.8 Portable R10/R12.....	83
2.4 AHERA Inspection Procedures and Protocols.....	86
2.4.1 Inspection Procedures and Protocols	86
2.4.2 FM GROUP INC Inspection SOP	86
2.5 Visual Inspection.....	86
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B) .	87
2.6.1 Main Building.....	88
2.6.2 Multi-Purpose Building.....	91
2.6.3 Portable R1/R3.....	94
2.6.4 Portable R2/R4.....	95
2.6.5 Portable R5/R7	96
2.6.6 Portable R6/R8.....	97

Table of Contents
Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
FM Project 07-367

<u>Section</u>	<u>Page</u>
2.6.7 Portable R9/R11	98
2.6.8 Portable R10/R12	99
2.7 Physical Assessments	100
2.8 Sample Collection	100
2.9 Material Bulk Sample Analysis	100

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none">• Chain-of-Custody• Laboratory Analysis
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

ENVKSD\07-367 Ninos Elm AHERA\2.0\2.3\2.3.1\TOC.doc

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the eight buildings comprising the Kyrene De Los Ninos Elementary School (KDLNES) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period of February 4, 2008 through February 6, 2008. A total of 150 bulk-material samples were collected from 262 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Two hundred twelve building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos-Containing Building Materials

The identified ACBM within the eight buildings at KDLNES are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

Asbestos Material-Bulk Samples Collected

Building	No. of Samples	No. HA	No. Assumed	Total No. ACM
Main	36	62	50	50
Multi-Purpose	36	71	59	59
Portable R1/R3	18	19	13	13
Portable R2/R4	18	19	13	13
Portable R5/P7	3	19	18	18
Portable R6/R8	3	19	18	18
Portable P9/R11	18	27	21	21
Portable R10/R12	18	26	20	20

1.3 Asbestos-Containing Building Materials

**TABLE C
ASBESTOS CONTAINING BUILDING MATERIALS**

**MAIN BUILDING
MULTI-PURPOSE BUILDING
PORTABLE R1/R3
PORTABLE R2/R4
PORTABLE R5/R7
PORTABLE R6/R8
PORTABLE R9/R11
PORTABLE R10/R12**

***TABLE C HAS BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

1.4 ACBM/Location Plans

**MAIN BUILDING
MULTI-PURPOSE BUILDING
PORTABLE R1/R3
PORTABLE R2/R4
PORTABLE R5/R7
PORTABLE R6/R8
PORTABLE R9/R11
PORTABLE R10/R12**

***ACBM/LOCATION PLANS HAVE BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the eight buildings at KDLNES during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the eight buildings at KDLNES during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** were identified in the eight buildings at KDLNES, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the eight buildings at the KDLNES campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the eight buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM's correspondence for Fee Revision, dated January 16, 2008, as evidenced by the issuance of KSD Purchase Order No. 805886, dated February 8, 2008. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 1330 East Dava Drive, in Chandler, Arizona and consists of eight buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the eight buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period February 4, 2008 through February 6, 2008, by Michael Coleman and Michael Richter, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.

2.2 Description of Construction

2.2.1 Main Building

The construction date of the Main Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support a concrete deck system finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, paneling (wood), plaster, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building, corridors and miscellaneous interior rooms.

Mechanical equipment for the building consists of roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Multi-Purpose Building

The construction date of the Multi-Purpose Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support a masonry deck system finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, quarry/paver tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes, acoustical ceiling tile and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building, corridors and miscellaneous interior rooms.

Mechanical equipment for the building consists of ground and roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.3 Portables R1/R3, R2/R4, R5/R7, R6/R8, R9/R11 and R10/R12

The construction date of Portables R1/R3, R2/R4, R5/R7, R6/R8, R9/R11 and R10/R12 is unknown. The construction appears to be consistent and uniform throughout each Portable.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: carpet, unfinished concrete, vinyl composition tile and vinyl sheet flooring.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal) or tackable wall panels. Original ceilings are wood or metal-framed and support gypsum wallboard systems, acoustical ceiling tile and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.

2.3 Building Materials/Systems List

TABLE A BUILDING MATERIAL SYSTEMS

**MAIN BUILDING
MULTI-PURPOSE BUILDING
PORTABLE R1/R3
PORTABLE R2/R4
PORTABLE R5/R7
PORTABLE R6/R8
PORTABLE R9/R11
PORTABLE R10/R12**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION B01	C	*	S
	SECRETARY B02	C	*	
	LOUNGE B04	C	*	
	TELEPHONE B07	C	*	
	WORK ROOM B08	C	*	
	STORAGE B09	C	*	
	ALCOVE B12	C	*	
	PRINCIPAL B13	C	*	
	ROOM B13A	C	*	
	STUDENT B14	C	*	
	SUPPLIES B15	C	*	
	NURSE B16	C	*	
	TREATMENT B19	C	*	
	PSYCH. B21	C	*	
	ASSISTANT PRINCIPAL B22	C	*	
	CONF/CLRM B27	C	*	
	WORK ROOM B28	C	*	
	A.V. STORAGE B29	C	*	
	BREAK-OUT B30	C	*	
	MEDIA CENTER B35	C	*	
	CONTROL B36	C	*	
	COMPUTER B40	C	*	
	RESOURCE 1 B41	C	*	
	TIME OUT ROOM B41A	C	*	
	RESOURCE 2 B42	C	*	
	RESOURCE 3 B43	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM B45	C	*	
	CLASSROOM B46	C	*	
	STORAGE B46A	C	*	
	CLASSROOM E1	C	*	
	CLASSROOM E2	C	*	
	CLASSROOM E3	C	*	
	CLASSROOM E4	C	*	
	CLASSROOM E9	C	*	
	CLASSROOM E10	C	*	
	CLASSROOM E11	C	*	
	CLASSROOM E12	C	*	
	WORK ROOM E110	C	*	
	WORK ROOM E114	C	*	
	CLASSROOM N1	C	*	
	WORK ROOM N1A	C	*	
	CLASSROOM N2	C	*	
	CLASSROOM N3	C	*	
	CLASSROOM N4	C	*	
	ART ROOM N5	C	*	
	CLASSROOM W1	C	*	
	CLASSROOM W2	C	*	
	CLASSROOM W3	C	*	
	CLASSROOM W4	C	*	
	CLASSROOM W5	C	*	
	CLASSROOM W7	C	*	
	CLASSROOM W8	C	*	
	CLASSROOM W9	C	*	
	CLASSROOM W10	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM W11	C	*	
	WORK ROOM W105	C	*	
	WORK ROOM W108	C	*	
	CORRIDOR B17	C	*	
	CORRIDOR B24	C	*	
	CORRIDOR B32	C	*	
	CORRIDOR B33	C	*	
	CORRIDOR B44	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION B01	C, W	E, W, S	S
	SECRETARY B02	C, W	N, W	
	LOUNGE B04	W	N, E, W, S	
	TELEPHONE B07	C, W	N, E, W, S	
	WORK ROOM B08	W	N, E, W, S	
	ALCOVE B12	W	N, E, W, S	
	PRINCIPAL B13	W	N, E, W, S	
	ROOM B13A	C, W	N, E, W, S	
	STUDENT B14	W	N, E, W, S	
	PSYCH. B21	W	N, E, W, S	
	ROOM B21A	C, W	N, E, W, S	
	ASSISTANT PRINCIPAL B22	W	N, E, W, S	
	ROOM B22A	C, W	N, E, W, S	
	CONF/CLRM B27	W	N, E, W, S	
	WORK ROOM B28	W	N, E, W, S	
	A.V. STORAGE B29	W	N, E, W, S	
	BREAK-OUT B30	W	N, E, W, S	
	MEDIA CENTER B35	C, W	N, E, W, S	
	CONTROL B36	C, W	N, E, W, S	
	COMPUTER B40	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	RESOURCE 1 B41	W	N, E, W, S	
	TIME OUT ROOM B41A	W	N, E, W, S	
	RESOURCE 2 B42	W	N, E, W, S	
	RESOURCE 3 B43	W	N, E, W, S	
	CLASSROOM B45	W	N, E, W, S	
	STORAGE B45B	C, W	N, E, W, S	
	CLASSROOM B46	W	N, E, W, S	
	STORAGE B46A	W	N, E, W, S	
	CLASSROOM E1	W	N, E, W, S	
	CLASSROOM E2	W	W, S	
	CLASSROOM E3	W	N, W	
	CLASSROOM E4	W	N, E, W, S	
	CLASSROOM E9	W	N, E, W, S	
	CLASSROOM E10	W	N, E	
	CLASSROOM E11	W	E, S	
	CLASSROOM E12	W	N, E, W, S	
	WORK ROOM E110	W	N, E, W, S	
	WORK ROOM E114	W	N, E, W, S	
	CLASSROOM N1	W	N, E, W, S	
	WORK ROOM N1A	W	N, E, W, S	
	CLASSROOM N2	W	N, E, W, S	
	CLASSROOM N3	W	N, E, W, S	
	CLASSROOM N4	W	N, E, W, S	
	ART ROOM N5	W	N, E, W, S	
	CLASSROOM W1	C, W	N, E, W, S	
	CLASSROOM W2	W	N, E, W, S	
	CLASSROOM W3	W	W, S	
	CLASSROOM W4	W	N, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM W5	W	N, E, W, S	
	CLASSROOM W7	W	N, E, W, S	
	CLASSROOM W8	W	N, E	
	CLASSROOM W9	W	E, S	
	CLASSROOM W10	W	N, E, W, S	
	CLASSROOM W11	C, W	N, E, W, S	
	WORK ROOM W105	W	N, E, W, S	
	WORK ROOM W108	W	N, E, W, S	
	CORRIDOR B24	C	*	
	CORRIDOR B32	C	*	
	CORRIDOR B33	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION B01	C, W	N, E, W, S	S
	SECRETARY B02	C, W	N, E, W, S	
	LOUNGE B04	W	N, E, W, S	
	TELEPHONE B07	C, W	N, E, W, S	
	WORK ROOM B08	W	N, E, W, S	
	ALCOVE B12	W	N, E, W, S	
	PRINCIPAL B13	W	N, E, W, S	
	ROOM B13A	C, W	N, E, W, S	
	STUDENT B14	W	N, E, W, S	
	PSYCH. B21	W	N, E, W, S	
	ROOM B21A	C, W	N, E, W, S	
	ASSISTANT PRINCIPAL B22	W	N, E, W, S	
	ROOM B22A	C, W	N, E, W, S	
	CONF/CLRM B27	W	N, E, W, S	
	WORK ROOM B28	W	N, E, W, S	
	A.V. STORAGE B29	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BREAK-OUT B30	W	N, E, W, S	
	MEDIA CENTER B35	C, W	N, E, W, S	
	CONTROL B36	C, W	N, E, W, S	
	COMPUTER B40	W	N, E, W, S	
	RESOURCE 1 B41	W	N, E, W, S	
	TIME OUT ROOM B41A	W	N, E, W, S	
	RESOURCE 2 B42	W	N, E, W, S	
	RESOURCE 3 B43	W	N, E, W, S	
	CLASSROOM B45	W	N, E, W, S	
	STORAGE B45B	C, W	N, E, W, S	
	CLASSROOM B46	W	N, E, W, S	
	STORAGE B46A	W	N, E, W, S	
	CLASSROOM E1	W	N, E, W, S	
	CLASSROOM E2	W	W, S	
	CLASSROOM E3	W	N, W	
	CLASSROOM E4	W	N, E, W, S	
	CLASSROOM E9	W	N, E, W, S	
	CLASSROOM E10	W	N, E	
	CLASSROOM E11	W	E, S	
	CLASSROOM E12	W	N, E, W, S	
	WORK ROOM E110	W	N, E, W, S	
	WORK ROOM E114	W	N, E, W, S	
	CLASSROOM N1	W	N, E, W, S	
	WORK ROOM N1A	W	N, E, W, S	
	CLASSROOM N2	W	N, E, W, S	
	CLASSROOM N3	W	N, E, W, S	
	CLASSROOM N4	W	N, E, W, S	
	ART ROOM N5	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	CLASSROOM W1	C, W	N, E, W, S	
	CLASSROOM W2	W	N, E, W, S	
	CLASSROOM W3	W	W, S	
	CLASSROOM W4	W	N, W	
	CLASSROOM W5	W	N, E, W, S	
	CLASSROOM W7	W	N, E, W, S	
	CLASSROOM W8	W	N, E	
	CLASSROOM W9	W	E, S	
	CLASSROOM W10	W	N, E, W, S	
	CLASSROOM W11	C, W	N, E, W, S	
	WORK ROOM W105	W	N, E, W, S	
	WORK ROOM W108	W	N, E, W, S	
	CORRIDOR B24	C	*	
	CORRIDOR B32	C	*	
	CORRIDOR B33	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION B01	C, W	N, E, W, S	S
	SECRETARY B02	C, W	N, E, W, S	
	LOUNGE B04	W	N, E, W, S	
	TELEPHONE B07	C, W	N, E, W, S	
	WORK ROOM B08	W	N, E, W, S	
	ALCOVE B12	W	N, E, W, S	
	PRINCIPAL B13	W	N, E, W, S	
	ROOM B13A	C, W	N, E, W, S	
	STUDENT B14	W	N, E, W, S	
	PSYCH. B21	W	N, E, W, S	
	ROOM B21A	C, W	N, E, W, S	
	ASSISTANT PRINCIPAL B22	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ROOM B22A	C, W	N, E, W, S	
	CONF/CLRM B27	W	N, E, W, S	
	WORK ROOM B28	W	N, E, W, S	
	A.V. STORAGE B29	W	N, E, W, S	
	BREAK-OUT B30	W	N, E, W, S	
	MEDIA CENTER B35	C, W	N, E, W, S	
	CONTROL B36	C, W	N, E, W, S	
	COMPUTER B40	W	N, E, W, S	
	RESOURCE 1 B41	W	N, E, W, S	
	TIME OUT ROOM B41A	W	N, E, W, S	
	RESOURCE 2 B42	W	N, E, W, S	
	RESOURCE 3 B43	W	N, E, W, S	
	CLASSROOM B45	W	N, E, W, S	
	STORAGE B45B	C, W	N, E, W, S	
	CLASSROOM B46	W	N, E, W, S	
	STORAGE B46A	W	N, E, W, S	
	CLASSROOM E1	W	N, E, W, S	
	CLASSROOM E2	W	W, S	
	CLASSROOM E3	W	N, W	
	CLASSROOM E4	W	N, E, W, S	
	CLASSROOM E9	W	N, E, W, S	
	CLASSROOM E10	W	N, E	
	CLASSROOM E11	W	E, S	
	CLASSROOM E12	W	N, E, W, S	
	WORK ROOM E110	W	N, E, W, S	
	WORK ROOM E114	W	N, E, W, S	
	CLASSROOM N1	W	N, E, W, S	
	WORK ROOM N1A	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM N2	W	N, E, W, S	
	CLASSROOM N3	W	N, E, W, S	
	CLASSROOM N4	W	N, E, W, S	
	ART ROOM N5	W	N, E, W, S	
	CLASSROOM W1	C, W	N, E, W, S	
	CLASSROOM W2	W	N, E, W, S	
	CLASSROOM W3	W	W, S	
	CLASSROOM W4	W	N, W	
	CLASSROOM W5	W	N, E, W, S	
	CLASSROOM W7	W	N, E, W, S	
	CLASSROOM W8	W	N, E	
	CLASSROOM W9	W	E, S	
	CLASSROOM W10	W	N, E, W, S	
	CLASSROOM W11	C, W	N, E, W, S	
	WORK ROOM W105	W	N, E, W, S	
	WORK ROOM W108	W	N, E, W, S	
	CORRIDOR B24	C	*	
	CORRIDOR B32	C	*	
	CORRIDOR B33	C	*	
CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	RECEPTION B01	F	*	S
	SECRETARY B02	F	*	
	LOUNGE B04	F	*	
	WORK ROOM B08	F	*	
	ALCOVE B12	F	*	
	PRINCIPAL B13	F	*	
	ROOM B13A	F	*	
	STUDENT B14	F	*	
	NURSE B16	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	TREATMENT B19	F	*	
	PSYCH. B21	F	*	
	ROOM B21A	F	*	
	ASSISTANT PRINCIPAL B22	F	*	
	ROOM B22A	F	*	
	CONF/CLRM B27	F	*	
	BREAK-OUT B30	F	*	
	MEDIA CENTER B35	F	*	
	CONTROL B36	F	*	
	COMPUTER B40	F	*	
	RESOURCE 1 B41	F	*	
	TIME OUT ROOM B41A	F	*	
	RESOURCE 2 B42	F	*	
	RESOURCE 3 B43	F	*	
	CLASSROOM B45	F	*	
	CLASSROOM B46	F	*	
	STORAGE B46A	F	*	
	CLASSROOM E1	F	*	
	CLASSROOM E2	F	*	
	CLASSROOM E3	F	*	
	CLASSROOM E4	F	*	
	CLASSROOM E9	F	*	
	CLASSROOM E10	F	*	
	CLASSROOM E11	F	*	
	CLASSROOM E12	F	*	
	CLASSROOM N1	F	*	
	WORK ROOM N1A	F	*	
	CLASSROOM N2	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM N3	F	*	
	CLASSROOM N4	F	*	
	CLASSROOM W1	F	*	
	CLASSROOM W2	F	*	
	CLASSROOM W3	F	*	
	CLASSROOM W4	F	*	
	CLASSROOM W5	F	*	
	CLASSROOM W7	F	*	
	CLASSROOM W8	F	*	
	CLASSROOM W9	F	*	
	CLASSROOM W10	F	*	
	CLASSROOM W11	F	*	
	CORRIDOR B17	F	*	
	CORRIDOR B24	F	*	
	CORRIDOR B32	F	*	
	CORRIDOR B33	F	*	
	CORRIDOR B44	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	RECEPTION B01	F	*	S
	SECRETARY B02	F	*	
	LOUNGE B04	F	*	
	WORK ROOM B08	F	*	
	ALCOVE B12	F	*	
	PRINCIPAL B13	F	*	
	ROOM B13A	F	*	
	STUDENT B14	F	*	
	NURSE B16	F	*	
	TREATMENT B19	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	PSYCH. B21	F	*	
	ROOM B21A	F	*	
	ASSISTANT PRINCIPAL B22	F	*	
	ROOM B22A	F	*	
	CONF/CLRM B27	F	*	
	BREAK-OUT B30	F	*	
	MEDIA CENTER B35	F	*	
	CONTROL B36	F	*	
	COMPUTER B40	F	*	
	RESOURCE 1 B41	F	*	
	TIME OUT ROOM B41A	F	*	
	RESOURCE 2 B42	F	*	
	RESOURCE 3 B43	F	*	
	CLASSROOM B45	F	*	
	CLASSROOM B46	F	*	
	STORAGE B46A	F	*	
	CLASSROOM E1	F	*	
	CLASSROOM E2	F	*	
	CLASSROOM E3	F	*	
	CLASSROOM E4	F	*	
	CLASSROOM E9	F	*	
	CLASSROOM E10	F	*	
	CLASSROOM E11	F	*	
	CLASSROOM E12	F	*	
	CLASSROOM N1	F	*	
	WORK ROOM N1A	F	*	
	CLASSROOM N2	F	*	
	CLASSROOM N3	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM N4	F	*	
	CLASSROOM W1	F	*	
	CLASSROOM W2	F	*	
	CLASSROOM W3	F	*	
	CLASSROOM W4	F	*	
	CLASSROOM W5	F	*	
	CLASSROOM W7	F	*	
	CLASSROOM W8	F	*	
	CLASSROOM W9	F	*	
	CLASSROOM W10	F	*	
	CLASSROOM W11	F	*	
	CORRIDOR B17	F	*	
	CORRIDOR B24	F	*	
	CORRIDOR B32	F	*	
	CORRIDOR B33	F	*	
	CORRIDOR B44	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	SUPPLIES B15	F	*	S
	ELECTRICAL ROOM B25	F	*	
	WORK ROOM B28	F	*	
	A.V. STORAGE B29	F	*	
	COMPUTER B40	F	*	
	RESOURCE 1 B41	F	*	
	RESOURCE 2 B42	F	*	
	RESOURCE 3 B43	F	*	
	CLASSROOM B45	F	*	
	STORAGE B45B	F	*	
	CLASSROOM B46	F	*	
	CLASSROOM E1	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM E2	F	*	
	CLASSROOM E3	F	*	
	CLASSROOM E4	F	*	
	CLASSROOM E9	F	*	
	CLASSROOM E10	F	*	
	CLASSROOM E11	F	*	
	CLASSROOM E12	F	*	
	JANITOR E101	F	*	
	VESTIBULE E103	F	*	
	VESTIBULE E105	F	*	
	WORK ROOM E110	F	*	
	WORK ROOM E114	F	*	
	CLASSROOM N1	F	*	
	CLASSROOM N2	F	*	
	CLASSROOM N3	F	*	
	CLASSROOM N4	F	*	
	CLASSROOM W1	F	*	
	CLASSROOM W2	F	*	
	CLASSROOM W3	F	*	
	CLASSROOM W4	F	*	
	CLASSROOM W5	F	*	
	CLASSROOM W7	F	*	
	CLASSROOM W8	F	*	
	CLASSROOM W9	F	*	
	CLASSROOM W10	F	*	
	CLASSROOM W11	F	*	
	WORK ROOM W105	F	*	
	WORK ROOM W108	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CORRIDOR B24	F	*	
	CORRIDOR B32	F	*	
	CORRIDOR B33	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	SUPPLIES B15	F	*	S
	ELECTRICAL ROOM B25	F	*	
	WORK ROOM B28	F	*	
	A.V. STORAGE B29	F	*	
	COMPUTER B40	F	*	
	RESOURCE 1 B41	F	*	
	RESOURCE 2 B42	F	*	
	RESOURCE 3 B43	F	*	
	CLASSROOM B45	F	*	
	STORAGE B45B	F	*	
	CLASSROOM B46	F	*	
	CLASSROOM E1	F	*	
	CLASSROOM E2	F	*	
	CLASSROOM E3	F	*	
	CLASSROOM E4	F	*	
	CLASSROOM E9	F	*	
	CLASSROOM E10	F	*	
	CLASSROOM E11	F	*	
	CLASSROOM E12	F	*	
	JANITOR E101	F	*	
	VESTIBULE E103	F	*	
	VESTIBULE E105	F	*	
	WORK ROOM E110	F	*	
	WORK ROOM E114	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM N1	F	*	
	CLASSROOM N2	F	*	
	CLASSROOM N3	F	*	
	CLASSROOM N4	F	*	
	CLASSROOM W1	F	*	
	CLASSROOM W2	F	*	
	CLASSROOM W3	F	*	
	CLASSROOM W4	F	*	
	CLASSROOM W5	F	*	
	CLASSROOM W7	F	*	
	CLASSROOM W8	F	*	
	CLASSROOM W9	F	*	
	CLASSROOM W10	F	*	
	CLASSROOM W11	F	*	
	WORK ROOM W105	F	*	
	WORK ROOM W108	F	*	
	CORRIDOR B24	F	*	
	CORRIDOR B32	F	*	
	CORRIDOR B33	F	*	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	ART ROOM N5	O	N, E, W, S	S
	CLASSROOM W1	O	N, E, W, S	
	CLASSROOM W11	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	ART ROOM N5	O	N, E, W, S	S
	CLASSROOM W1	O	N, E, W, S	
	CLASSROOM W11	O	N, E, W, S	
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM E1	O	N	S
	CLASSROOM E2	O	S	
	CLASSROOM E3	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM E4	O	S	
	CLASSROOM E9	O	S	
	CLASSROOM E10	O	N	
	CLASSROOM E11	O	S	
	CLASSROOM E12	O	N	
	CLASSROOM W1	O	N	
	CLASSROOM W2	O	N	
	CLASSROOM W3	O	S	
	CLASSROOM W4	O	N	
	CLASSROOM W5	O	S	
	CLASSROOM W7	O	S	
	CLASSROOM W8	O	N	
	CLASSROOM W9	O	S	
	CLASSROOM W10	O	N	
	CLASSROOM W11	O	N	
SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	RECEPTION B01	O	N, W, S	S
	SECRETARY B02	O	N, W	
	LOUNGE B04	O	N, E, W	
	MEN'S RESTROOM B05	O	N, E	
	TELEPHONE B07	O	E, W	
	WORK ROOM B08	O	E, S	
	STORAGE B09	O	E	
	WOMEN'S RESTROOM B10	O	E, W, S	
	ALCOVE B12	O	N, W, S	
	PRINCIPAL B13	O	N, E	
	ROOM B13A	O	W	
	STUDENT B14	O	N, E, W	
	SUPPLIES B15	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	NURSE B16	O	N, E, S	
	TOILET B18	O	N, W, S	
	TREATMENT B19	O	W	
	PSYCH. B21	O	E, S	
	ROOM B21A	O	W	
	ASSISTANT PRINCIPAL B22	O	N, E, W	
	ROOM B22A	O	S	
	ELECTRICAL ROOM B25	O	E	
	CONF/CLRM B27	O	E, W, S	
	WORK ROOM B28	O	N, E, W	
	A.V. STORAGE B29	O	S	
	BREAK-OUT B30	O	S	
	MEDIA CENTER B35	O	N, W, S	
	CONTROL B36	O	N, E, S	
	COMPUTER B40	O	N, E, S	
	RESOURCE 1 B41	O	N, E, S	
	TIME OUT ROOM B41A	O	S	
	RESOURCE 2 B42	O	S	
	RESOURCE 3 B43	O	N, S	
	RESTROOM B43A	O	N, W, S	
	CLASSROOM B45	O	E, W, S	
	RESTROOM B45A	O	N, W, S	
	STORAGE B45B	O	W	
	CLASSROOM B46	O	N, W	
	STORAGE B46A	O	S	
	CLASSROOM E1	O	E, W, S	
	CLASSROOM E2	O	E, W	
	CLASSROOM E3	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM E4	O	E, W	
	CLASSROOM E9	O	E, W	
	CLASSROOM E10	O	E, W	
	CLASSROOM E11	O	E, W	
	CLASSROOM E12	O	E, W	
	JANITOR E101	O	N, W, S	
	ELECTRICAL ROOM E102	O	N	
	VESTIBULE E103	O	N	
	BOY'S RESTROOM E104	O	N	
	VESTIBULE E105	O	N	
	GIRL'S RESTROOM E106	O	N	
	WORK ROOM E110	O	N, E, W, S	
	WORK ROOM E114	O	N, E, W, S	
	CLASSROOM N1	O	N, E, W	
	WORK ROOM N1A	O	E, W, S	
	ELECTRICAL ROOM N1B	O	N	
	CLASSROOM N2	O	N, E, W	
	CLASSROOM N3	O	E, W, S	
	CLASSROOM N4	O	E, W, S	
	ART ROOM N5	O	E, S	
	KILN ROOM N5A	O	N	
	GIRL'S RESTROOM N6	O	N, E, W	
	ELECTRICAL ROOM N7	O	W, S	
	JANITOR N8	O	W	
	BOY'S RESTROOM N9	O	N, E, W	
	CLASSROOM W1	O	E, W, S	
	CLASSROOM W2	O	E, W	
	CLASSROOM W3	O	E, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM W4	O	E, W	
	CLASSROOM W5	O	E, W	
	CLASSROOM W7	O	E, W	
	CLASSROOM W8	O	E, W	
	CLASSROOM W9	O	E, W	
	CLASSROOM W10	O	E, W	
	CLASSROOM W11	O	E, W, S	
	ELECTRICAL ROOM W102	O	N	
	WORK ROOM W105	O	N, E, W, S	
	WORK ROOM W108	O	N, E, W, S	
	RESTROOM W113	O	E, W	
	RESTROOM W114	O	E, W	
	CORRIDOR B17	O	N, E, S	
	CORRIDOR B24	O	N, E, W, S	
	CORRIDOR B32	O	N, E, S	
	CORRIDOR B33	O	E, W, S	
	CORRIDOR B44	O	N, S	S
SEALANT (MILLWORK), BROWN, PLIABLE	CLASSROOM E1	O	N	
	CLASSROOM E2	O	S	
	CLASSROOM E3	O	N	
	CLASSROOM E4	O	S	
	CLASSROOM E9	O	S	
	CLASSROOM E10	O	N	
	CLASSROOM E11	O	S	
	CLASSROOM E12	O	N	
	CLASSROOM W1	O	N	
	CLASSROOM W2	O	N	
	CLASSROOM W3	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLASSROOM W4	O	N	
	CLASSROOM W5	O	S	
	CLASSROOM W7	O	S	
	CLASSROOM W8	O	N	
	CLASSROOM W9	O	S	
	CLASSROOM W10	O	N	
	CLASSROOM W11	O	N	
FIRE DOOR INSULATION, WOOD CLADDING	WOMEN'S RESTROOM B10	O	S	S
	ALCOVE B12	O	N	
	STUDENT B14	O	N	
	ASSISTANT PRINCIPAL B22	O	E	
	ELECTRICAL ROOM B25	O	E	
	CONF/CLRM B27	O	S	
	WORK ROOM B28	O	N, E	
	A.V. STORAGE B29	O	S	
	BREAK-OUT B30	O	S	
	MEDIA CENTER B35	O	N, S	
	CONTROL B36	O	N	
	COMPUTER B40	O	E	
	RESOURCE 1 B41	O	E	
	RESOURCE 3 B43	O	S	
	CLASSROOM B45	O	W	
	CLASSROOM B46	O	W	
	CLASSROOM E1	O	W	
	CLASSROOM E2	O	W	
	CLASSROOM E3	O	W	
	CLASSROOM E4	O	W	
	CLASSROOM N1	O	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	WORK ROOM N1A	O	E, W, S	
	CLASSROOM N2	O	W	
	CLASSROOM N3	O	E, S	
	CLASSROOM N4	O	W, S	
	ART ROOM N5	O	S	
	CLASSROOM W7	O	E	
	CLASSROOM W8	O	E	
	CLASSROOM W9	O	E	
	CLASSROOM W10	O	E	
	CLASSROOM W11	O	E	
	CORRIDOR B24	O	N, E, W	
	CORRIDOR B32	O	N, S	
	CORRIDOR B33	O	N, E, W	
	CORRIDOR B44	O	N, S	
FIRE DOOR INSULATION, METAL CLADDING	RECEPTION B01	O	S	S
	NURSE B16	O	S	
	CLASSROOM E1	O	S	
	CLASSROOM E9	O	E	
	CLASSROOM E10	O	E	
	CLASSROOM E11	O	E	
	CLASSROOM E12	O	E	
	JANITOR E101	O	N	
	ELECTRICAL ROOM E102	O	N	
	VESTIBULE E103	O	N	
	VESTIBULE E105	O	N	
	CLASSROOM N1	O	N	
	ELECTRICAL ROOM N1B	O	N	
	CLASSROOM N2	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ART ROOM N5	O	N, E	
	KILN ROOM N5A	O	W	
	GIRL'S RESTROOM N6	O	W	
	ELECTRICAL ROOM N7	O	W	
	JANITOR N8	O	W	
	BOY'S RESTROOM N9	O	W	
	CLASSROOM W1	O	W, S	
	CLASSROOM W2	O	W	
	CLASSROOM W3	O	W	
	CLASSROOM W4	O	W	
	CLASSROOM W5	O	W	
	CLASSROOM W11	O	S	
	ELECTRICAL ROOM W102	O	N	
	CORRIDOR B24	O	S	
	CORRIDOR B32	O	N, E	
	CORRIDOR B33	O	S	
	EXTERIOR	O	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM B05	C	*	S
	WOMEN'S RESTROOM B10	C, W	N, E, S	
	TOILET B18	C, W	N, E, W, S	
	RESTROOM B43A	C	*	
	RESTROOM B45A	C	*	
	JANITOR E101	C, W	E, S	
	VESTIBULE E103	C, W	N, E, W, S	
	BOY'S RESTROOM E104	C	*	
	VESTIBULE E105	C, W	N, E, W, S	
	GIRL'S RESTROOM E106	C	*	
	GIRL'S RESTROOM N6	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection .
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	JANITOR N8	C, W	N, E, S	
	BOY'S RESTROOM N9	C	*	
	RESTROOM W113	C, W	N, E, W, S	
	RESTROOM W114	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	MEN'S RESTROOM B05	C	*	S
	WOMEN'S RESTROOM B10	C, W	N, E, S	
	TOILET B18	C, W	N, E, W, S	
	RESTROOM B43A	C	*	
	RESTROOM B45A	C	*	
	JANITOR E101	C, W	E, S	
	VESTIBULE E103	C, W	N, E, W, S	
	BOY'S RESTROOM E104	C	*	
	VESTIBULE E105	C, W	N, E, W, S	
	GIRL'S RESTROOM E106	C	*	
	GIRL'S RESTROOM N6	C	*	
	JANITOR N8	C, W	N, E, S	
	BOY'S RESTROOM N9	C	*	
	RESTROOM W113	C, W	N, E, W, S	
	RESTROOM W114	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	MEN'S RESTROOM B05	C	*	S
	WOMEN'S RESTROOM B10	C, W	N, E, S	
	TOILET B18	C, W	N, E, W, S	
	RESTROOM B43A	C	*	
	RESTROOM B45A	C	*	
	JANITOR E101	C, W	E, S	
	VESTIBULE E103	C, W	N, E, W, S	
	BOY'S RESTROOM E104	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	VESTIBULE E105	C, W	N, E, W, S	
	GIRL'S RESTROOM E106	C	*	
	GIRL'S RESTROOM N6	C	*	
	JANITOR N8	C, W	N, E, S	
	BOY'S RESTROOM N9	C	*	
	RESTROOM W113	C, W	N, E, W, S	
	RESTROOM W114	C, W	N, E, W, S	
WALLPAPER	WOMEN'S RESTROOM B10	W	N, E, S	N
	ALCOVE B12	W	N, E, W, S	
	STUDENT B14	W	N, E, W, S	
	TREATMENT B19	W	N, E, W, S	
	CLASSROOM E1	W	N, E, W, S	
	CLASSROOM E2	W	W, S	
	CLASSROOM E3	W	N, W	
	CLASSROOM E4	W	N, E, W, S	
	CLASSROOM E9	W	N, E, W, S	
	CLASSROOM E10	W	N, E	
	CLASSROOM E11	W	E, S	
	CLASSROOM E12	W	N, E, W, S	
	CLASSROOM W2	W	N, E, W, S	
	CLASSROOM W3	W	W, S	
	CLASSROOM W4	W	N, W	
	CLASSROOM W5	W	N, E, W, S	
	CLASSROOM W7	W	N, E, W, S	
	CLASSROOM W8	W	E	
	CLASSROOM W9	W	E, S	
	CLASSROOM W10	W	N, E, W, S	
	WORK ROOM W105	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	WORK ROOM W108	W	N, E, W, S	
	RESTROOM W113	W	N, E, W, S	
	RESTROOM W114	W	N, E, W, S	
	CORRIDOR B17	W	N, E, W, S	
	CORRIDOR B24	C, W	N, E, W, S	
	CORRIDOR B32	C, W	N, E, W, S	
	CORRIDOR B33	C, W	N, E, W, S	
	CORRIDOR B44	C, W	N, E, W, S	
GLAZED WALL TILE, 4"X4", TAN, SMOOTH	RESTROOM W113	W	N, E, W, S	S
	RESTROOM W114	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH	RESTROOM W113	W	N, E, W, S	S
	RESTROOM W114	W	N, E, W, S	
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	MEN'S RESTROOM B05	F	*	S
	WOMEN'S RESTROOM B10	F	*	
	TOILET B18	F	*	
	RESTROOM B43A	F	*	
	RESTROOM B45A	F	*	
	BOY'S RESTROOM E104	F	*	
	GIRL'S RESTROOM E106	F	*	
	GIRL'S RESTROOM N6	F	*	
	BOY'S RESTROOM N9	F	*	
	RESTROOM W113	F	*	
	RESTROOM W114	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	MEN'S RESTROOM B05	F	*	S
	WOMEN'S RESTROOM B10	F	*	
	TOILET B18	F	*	
	RESTROOM B43A	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	RESTROOM B45A	F	*	
	BOY'S RESTROOM E104	F	*	
	GIRL'S RESTROOM E106	F	*	
	GIRL'S RESTROOM N6	F	*	
	BOY'S RESTROOM N9	F	*	
	RESTROOM W113	F	*	
	RESTROOM W114	F	*	
WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	RECEPTION B01	O	N, E, W, S	S
	SECRETARY B02	O	N, E, W, S	
	LOUNGE B04	O	N, E, W, S	
	TELEPHONE B07	O	N, E, W, S	
	WORK ROOM B08	O	N, E, W, S	
	STORAGE B09	O	N, E, W, S	
	ALCOVE B12	O	N, E, W, S	
	PRINCIPAL B13	O	N, E, W, S	
	ROOM B13A	O	N, E, W, S	
	STUDENT B14	O	N, E, W, S	
	SUPPLIES B15	O	N, E, W, S	
	NURSE B16	O	N, E, W, S	
	TREATMENT B19	O	N, E, W, S	
	PSYCH. B21	O	N, E, W, S	
	ROOM B21A	O	N, E, W, S	
	ASSISTANT PRINCIPAL B22	O	N, E, W, S	
	ROOM B22A	O	N, E, W, S	
	ELECTRICAL ROOM B25	O	N, E, W, S	
	CONF/CLRM B27	O	N, E, W, S	
	WORK ROOM B28	O	N, E, W, S	
	A.V. STORAGE B29	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	BREAK-OUT B30	O	N, E, W, S	
	MEDIA CENTER B35	O	N, E, W, S	
	CONTROL B36	O	N, E, W, S	
	COMPUTER B40	O	N, E, W, S	
	RESOURCE 1 B41	O	N, E, W, S	
	TIME OUT ROOM B41A	O	N, E, W, S	
	RESOURCE 2 B42	O	N, E, W, S	
	RESOURCE 3 B43	O	N, E, W, S	
	CLASSROOM B45	O	N, E, W, S	
	STORAGE B45B	O	N, E, W, S	
	CLASSROOM B46	O	N, E, W, S	
	STORAGE B46A	O	N, E, W, S	
	CLASSROOM E1	O	N, E, W, S	
	CLASSROOM E2	O	N, E, W, S	
	CLASSROOM E3	O	N, E, W, S	
	CLASSROOM E4	O	N, E, W, S	
	CLASSROOM E9	O	N, E, W, S	
	CLASSROOM E10	O	N, E, W, S	
	CLASSROOM E11	O	N, E, W, S	
	CLASSROOM E12	O	N, E, W, S	
	JANITOR E101	O	N, E, W, S	
	ELECTRICAL ROOM E102	O	N, E, W, S	
	VESTIBULE E103	O	N, E, W, S	
	VESTIBULE E105	O	N, E, W, S	
	WORK ROOM E110	O	N, E, W, S	
	WORK ROOM E114	O	N, E, W, S	
	CLASSROOM N1	O	N, E, W, S	
	WORK ROOM N1A	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ELECTRICAL ROOM N1B	O	N, E, W, S	
	CLASSROOM N2	O	N, E, W, S	
	CLASSROOM N3	O	N, E, W, S	
	CLASSROOM N4	O	N, E, W, S	
	ELECTRICAL ROOM N7	O	N, E, W, S	
	CLASSROOM W2	O	N, E, W, S	
	CLASSROOM W3	O	N, E, W, S	
	CLASSROOM W4	O	N, E, W, S	
	CLASSROOM W5	O	N, E, W, S	
	CLASSROOM W7	O	N, E, W, S	
	CLASSROOM W8	O	N, E, W, S	
	CLASSROOM W9	O	N, E, W, S	
	CLASSROOM W10	O	N, E, W, S	
	ELECTRICAL ROOM W102	O	N, E, W, S	
	WORK ROOM W105	O	N, E, W, S	
	WORK ROOM W108	O	N, E, W, S	
	CORRIDOR B17	O	N, E, W, S	
	CORRIDOR B24	O	N, E, W, S	
	CORRIDOR B32	O	N, E, W, S	
	CORRIDOR B33	O	N, E, W, S	
	CORRIDOR B44	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", GRAY, VINYL-LIKE	RECEPTION B01	O	N, E, W, S	S
	SECRETARY B02	O	N, E, W, S	
	LOUNGE B04	O	N, E, W, S	
	TELEPHONE B07	O	N, E, W, S	
	WORK ROOM B08	O	N, E, W, S	
	STORAGE B09	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ALCOVE B12	O	N, E, W, S	
	PRINCIPAL B13	O	N, E, W, S	
	ROOM B13A	O	N, E, W, S	
	STUDENT B14	O	N, E, W, S	
	SUPPLIES B15	O	N, E, W, S	
	NURSE B16	O	N, E, W, S	
	TREATMENT B19	O	N, E, W, S	
	PSYCH. B21	O	N, E, W, S	
	ROOM B21A	O	N, E, W, S	
	ASSISTANT PRINCIPAL B22	O	N, E, W, S	
	ROOM B22A	O	N, E, W, S	
	ELECTRICAL ROOM B25	O	N, E, W, S	
	CONF/CLRM B27	O	N, E, W, S	
	WORK ROOM B28	O	N, E, W, S	
	A.V. STORAGE B29	O	N, E, W, S	
	BREAK-OUT B30	O	N, E, W, S	
	MEDIA CENTER B35	O	N, E, W, S	
	CONTROL B36	O	N, E, W, S	
	COMPUTER B40	O	N, E, W, S	
	RESOURCE 1 B41	O	N, E, W, S	
	TIME OUT ROOM B41A	O	N, E, W, S	
	RESOURCE 2 B42	O	N, E, W, S	
	RESOURCE 3 B43	O	N, E, W, S	
	CLASSROOM B45	O	N, E, W, S	
	STORAGE B45B	O	N, E, W, S	
	CLASSROOM B46	O	N, E, W, S	
	STORAGE B46A	O	N, E, W, S	
	CLASSROOM E1	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	CLASSROOM E2	O	N, E, W, S	
	CLASSROOM E3	O	N, E, W, S	
	CLASSROOM E4	O	N, E, W, S	
	CLASSROOM E9	O	N, E, W, S	
	CLASSROOM E10	O	N, E, W, S	
	CLASSROOM E11	O	N, E, W, S	
	CLASSROOM E12	O	N, E, W, S	
	JANITOR E101	O	N, E, W, S	
	ELECTRICAL ROOM E102	O	N, E, W, S	
	VESTIBULE E103	O	N, E, W, S	
	VESTIBULE E105	O	N, E, W, S	
	WORK ROOM E110	O	N, E, W, S	
	WORK ROOM E114	O	N, E, W, S	
	CLASSROOM N1	O	N, E, W, S	
	WORK ROOM N1A	O	N, E, W, S	
	ELECTRICAL ROOM N1B	O	N, E, W, S	
	CLASSROOM N2	O	N, E, W, S	
	CLASSROOM N3	O	N, E, W, S	
	CLASSROOM N4	O	N, E, W, S	
	ELECTRICAL ROOM N7	O	N, E, W, S	
	CLASSROOM W2	O	N, E, W, S	
	CLASSROOM W3	O	N, E, W, S	
	CLASSROOM W4	O	N, E, W, S	
	CLASSROOM W5	O	N, E, W, S	
	CLASSROOM W7	O	N, E, W, S	
	CLASSROOM W8	O	N, E, W, S	
	CLASSROOM W9	O	N, E, W, S	
	CLASSROOM W10	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection,
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ELECTRICAL ROOM W102	O	N, E, W, S	
	WORK ROOM W105	O	N, E, W, S	
	WORK ROOM W108	O	N, E, W, S	
	CORRIDOR B17	O	N, E, W, S	
	CORRIDOR B24	O	N, E, W, S	
	CORRIDOR B32	O	N, E, W, S	
	CORRIDOR B33	O	N, E, W, S	
	CORRIDOR B44	O	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, TAN, VINYL COVER	RECEPTION B01	W	E	S
	LOUNGE B04	W	E, S	
	TELEPHONE B07	W	N, E, S	
	WORK ROOM B08	W	W	
	ALCOVE B12	W	W	
	PRINCIPAL B13	W	W	
	PSYCH. B21	W	W	
	ASSISTANT PRINCIPAL B22	W	E	
	CONF./CLRM B27	W	N, S	
	MEDIA CENTER B35	W	N, E, W, S	
	COMPUTER B40	W	N, S	
	RESOURCE 1 B41	W	N, W	
	RESOURCE 2 B42	W	N, E, W	
	RESOURCE 3 B43	W	N, E	
	CLASSROOM B45	W	N, S	
	CLASSROOM B46	W	N, E, W	
	CLASSROOM E1	W	E	
	CLASSROOM E2	W	N, E	
	CLASSROOM E3	W	E, S	
	CLASSROOM E4	W	E	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLASSROOM E9	W	W	
	CLASSROOM E10	W	W, S	
	CLASSROOM E11	W	N, W	
	CLASSROOM E12	W	W	
	CLASSROOM N1	W	N, S	
	CLASSROOM N2	W	N, S	
	CLASSROOM N3	W	N, S	
	CLASSROOM N4	W	N, S	
	ART ROOM N5	W	W	
	CLASSROOM W2	W	E	
	CLASSROOM W3	W	N, E	
	CLASSROOM W4	W	E, S	
	CLASSROOM W5	W	E	
	CLASSROOM W7	W	W	
	CLASSROOM W8	W	W, S	
	CLASSROOM W9	W	N, W	
	CLASSROOM W10	W	W	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, TAN, VINYL COVER	RECEPTION B01	W	E	S
	LOUNGE B04	W	E, S	
	TELEPHONE B07	W	N, E, S	
	WORK ROOM B08	W	W	
	ALCOVE B12	W	W	
	PRINCIPAL B13	W	W	
	PSYCH. B21	W	W	
	ASSISTANT PRINCIPAL B22	W	E	
	CONF./CLRM B27	W	N, S	
	MEDIA CENTER B35	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	COMPUTER B40	W	N, S	
	RESOURCE 1 B41	W	N, W	
	RESOURCE 2 B42	W	N, E, W	
	RESOURCE 3 B43	W	N, E	
	CLASSROOM B45	W	N, S	
	CLASSROOM B46	W	N, E, W	
	CLASSROOM E1	W	E	
	CLASSROOM E2	W	N, E	
	CLASSROOM E3	W	E, S	
	CLASSROOM E4	W	E	
	CLASSROOM E9	W	W	
	CLASSROOM E10	W	W, S	
	CLASSROOM E11	W	N, W	
	CLASSROOM E12	W	W	
	CLASSROOM N1	W	N, S	
	CLASSROOM N2	W	N, S	
	CLASSROOM N3	W	N, S	
	CLASSROOM N4	W	N, S	
	ART ROOM N5	W	W	
	CLASSROOM W2	W	E	
	CLASSROOM W3	W	N, E	
	CLASSROOM W4	W	E, S	
	CLASSROOM W5	W	E	
	CLASSROOM W7	W	W	
	CLASSROOM W8	W	W, S	
	CLASSROOM W9	W	N, W	
	CLASSROOM W10	W	W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE B09	W	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ELECTRICAL ROOM B25	C, W	E, W	
	ELECTRICAL ROOM E102	C, W	E, W	
	ELECTRICAL ROOM N1B	C, W	N, E, W, S	
	ELECTRICAL ROOM N7	C, W	N, E, S	
	ELECTRICAL ROOM W102	C, W	N, E, W, S	
	CORRIDOR B32	W	N, W, S	
	CORRIDOR B33	W	N, E, W	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE B09	W	N, E, W, S	S
	ELECTRICAL ROOM B25	C, W	E, W	
	ELECTRICAL ROOM E102	C, W	E, W	
	ELECTRICAL ROOM N1B	C, W	N, E, W, S	
	ELECTRICAL ROOM N7	C, W	N, E, S	
	ELECTRICAL ROOM W102	C, W	N, E, W, S	
	CORRIDOR B32	W	N, W, S	
	CORRIDOR B33	W	N, E, W	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE B09	W	N, E, W, S	S
	ELECTRICAL ROOM B25	C, W	E, W	
	ELECTRICAL ROOM E102	C, W	E, W	
	ELECTRICAL ROOM N1B	C, W	N, E, W, S	
	ELECTRICAL ROOM N7	C, W	N, E, S	
	ELECTRICAL ROOM W102	C, W	N, E, W, S	
	CORRIDOR B32	W	N, W, S	
	CORRIDOR B33	W	N, E, W	
CONCRETE, GRAY, CEMENTITIOUS	RECEPTION B01	F	*	S
	SECRETARY B02	F	*	
	LOUNGE B04	F	*	
	MEN'S RESTROOM B05	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	TELEPHONE B07	F	*	
	WORK ROOM B08	F	*	
	STORAGE B09	F	*	
	WOMEN'S RESTROOM B10	F	*	
	ALCOVE B12	F	*	
	PRINCIPAL B13	F	*	
	ROOM B13A	F	*	
	STUDENT B14	F	*	
	SUPPLIES B15	F	*	
	NURSE B16	F	*	
	TOILET B18	F	*	
	TREATMENT B19	F	*	
	PSYCH. B21	F	*	
	ROOM B21A	F	*	
	ASSISTANT PRINCIPAL B22	F	*	
	ROOM B22A	F	*	
	ELECTRICAL ROOM B25	F	*	
	CONF/CLRM B27	F	*	
	WORK ROOM B28	F	*	
	A.V. STORAGE B29	F	*	
	BREAK-OUT B30	F	*	
	MEDIA CENTER B35	F	*	
	CONTROL B36	F	*	
	COMPUTER B40	F	*	
	RESOURCE 1 B41	F	*	
	TIME OUT ROOM B41A	F	*	
	RESOURCE 2 B42	F	*	
	RESOURCE 3 B43	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	RESTROOM B43A	F	*	
	CLASSROOM B45	F	*	
	RESTROOM B45A	F	*	
	STORAGE B45B	F	*	
	CLASSROOM B46	F	*	
	STORAGE B46A	F	*	
	CLASSROOM E1	F	*	
	CLASSROOM E2	F	*	
	CLASSROOM E3	F	*	
	CLASSROOM E4	F	*	
	CLASSROOM E9	F	*	
	CLASSROOM E10	F	*	
	CLASSROOM E11	F	*	
	CLASSROOM E12	F	*	
	JANITOR E101	F	*	
	ELECTRICAL ROOM E102	F	*	
	VESTIBULE E103	F	*	
	BOY'S RESTROOM E104	F	*	
	VESTIBULE E105	F	*	
	GIRL'S RESTROOM E106	F	*	
	WORK ROOM E110	F	*	
	WORK ROOM E114	F	*	
	CLASSROOM N1	F	*	
	WORK ROOM N1A	F	*	
	ELECTRICAL ROOM N1B	F	*	
	CLASSROOM N2	F	*	
	CLASSROOM N3	F	*	
	CLASSROOM N4	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ART ROOM N5	F	*	
	KILN ROOM N5A	F	*	
	SERVICE YARD	F	*	
	GIRL'S RESTROOM N6	F	*	
	ELECTRICAL ROOM N7	F	*	
	JANITOR N8	F	*	
	BOY'S RESTROOM N9	F	*	
	CLASSROOM W1	F	*	
	CLASSROOM W2	F	*	
	CLASSROOM W3	F	*	
	CLASSROOM W4	F	*	
	CLASSROOM W5	F	*	
	CLASSROOM W7	F	*	
	CLASSROOM W8	F	*	
	CLASSROOM W9	F	*	
	CLASSROOM W10	F	*	
	CLASSROOM W11	F	*	
	ELECTRICAL ROOM W102	F	*	
	WORK ROOM W105	F	*	
	WORK ROOM W108	F	*	
	RESTROOM W113	F	*	
	RESTROOM W114	F	*	
	CORRIDOR B17	F	*	
	CORRIDOR B24	F	*	
	CORRIDOR B32	F	*	
	CORRIDOR B33	F	*	
	CORRIDOR B44	F	*	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	JANITOR E101	W	N, E	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	ELECTRICAL ROOM E102	W	N, S	
	ELECTRICAL ROOM N7	W	W	
	JANITOR N8	W	E	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	JANITOR E101	W	N, E	S
	ELECTRICAL ROOM E102	W	N, S	
	ELECTRICAL ROOM N7	W	W	
	JANITOR N8	W	E	
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	JANITOR E101	W	W, S	N
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	JANITOR E101	W	W, S	S
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	BOY'S RESTROOM E104	W	N, E, W, S	S
	GIRL'S RESTROOM E106	W	N, E, W, S	
	GIRL'S RESTROOM N8	W	N, E, W, S	
	ELECTRICAL ROOM N7	W	W, S	
	BOY'S RESTROOM N9	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	BOY'S RESTROOM E104	W	N, E, W, S	S
	GIRL'S RESTROOM E106	W	N, E, W, S	
	GIRL'S RESTROOM N8	W	N, E, W, S	
	ELECTRICAL ROOM N7	W	W, S	
	BOY'S RESTROOM N9	W	N, E, W, S	
SEALANT (WINDOWS), BLACK, TAR-LIKE	PRINCIPAL B13	O	N, S	S
	STUDENT B14	O	N	
	NURSE B16	O	N	
	PSYCH. B21	O	S	
	CONF./CLRM B27	O	E, W	
	WORK ROOM B28	O	W	
	BREAK-OUT B30	O	S	
	MEDIA CENTER B35	O	N, W	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	COMPUTER B40	O	N	
	CLASSROOM N3	O	E	
	CLASSROOM N4	O	W	
GLAZED WALL TILE, 4"x4", PINK, SMOOTH	MEN'S RESTROOM B05	W	N, E, W, S	S
	WOMEN'S RESTROOM B10	W	N, E, W, S	
	TOILET B16	W	N, E, W, S	
	RESTROOM B43A	W	N, E, W, S	
	RESTROOM B45A	W	N, E, W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"x4", PINK, SMOOTH	MEN'S RESTROOM B05	W	N, E, W, S	S
	WOMEN'S RESTROOM B10	W	N, E, W, S	
	TOILET B16	W	N, E, W, S	
	RESTROOM B43A	W	N, E, W, S	
	RESTROOM B45A	W	N, E, W, S	
GLASS BLOCK, 8"x8", CLEAR	RECEPTION B01	W	S	N
	CORRIDOR B24	W	S	
	CORRIDOR B32	W	N, E	
	CORRIDOR B33	W	S	
	EXTERIOR	W	N, E, S	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"x8", CLEAR	RECEPTION B01	W	S	S
	CORRIDOR B24	W	S	
	CORRIDOR B32	W	N, E	
	CORRIDOR B33	W	S	
	EXTERIOR	W	N, E, S	
SINK ACOUSTICAL COATING, GRAY, ROUGH	LOUNGE B04	O	W	S
	WORK ROOM B08	O	E	
	CONF./CLRM B27	O	N	
	WORK ROOM B28	O	E	
	COMPUTER B40	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	RESOURCE 1 B41	O	S	
	RESOURCE 2 B42	O	S	
	CLASSROOM B45	O	S	
	CLASSROOM B46	O	N	
	CLASSROOM N1	O	W	
	CLASSROOM N2	O	E	
	CLASSROOM N3	O	W	
	CLASSROOM N4	O	E	
	ART ROOM N5	O	E, S	
PANELING (WOOD), PAINTED	TIME OUT ROOM B41A	W	N, E, W, S	N
SEALANT (FIRE STOP), RED, PLIABLE	ELECTRICAL ROOM B25	O	N	S
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	ART ROOM N5	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	ART ROOM N5	F	*	S
GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR B24	C, W	N, E, W, S	S
	CORRIDOR B32	C, W	N, E, S	
	CORRIDOR B33	C, W	E, W, S	
	CORRIDOR B44	C, W	N, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CORRIDOR B24	C, W	N, E, W, S	S
	CORRIDOR B32	C, W	N, E, S	
	CORRIDOR B33	C, W	E, W, S	
	CORRIDOR B44	C, W	N, S	
CONCRETE (DOUBLE T'S), GRAY, CEMENTITIOUS	RECEPTION B01	C	*	S
	SECRETARY B02	C	*	
	LOUNGE B04	C	*	
	MEN'S RESTROOM B05	C	*	
	TELEPHONE B07	C	*	
	WORK ROOM B08	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		<i>C/W/F/O</i>	<i>N/E/W/S</i>	<i>N/S</i>
	STORAGE B09	C	*	
	WOMEN'S RESTROOM B10	C	*	
	ALCOVE B12	C	*	
	PRINCIPAL B13	C	*	
	ROOM B13A	C	*	
	STUDENT B14	C	*	
	SUPPLIES B15	C	*	
	NURSE B16	C	*	
	TOILET B18	C	*	
	TREATMENT B19	C	*	
	PSYCH. B21	C	*	
	ROOM B21A	C	*	
	ASSISTANT PRINCIPAL B22	C	*	
	ROOM B22A	C	*	
	ELECTRICAL ROOM B25	C	*	
	CONF/CLRM B27	C	*	
	WORK ROOM B28	C	*	
	A.V. STORAGE B29	C	*	
	BREAK-OUT B30	C	*	
	MEDIA CENTER B35	C	*	
	CONTROL B36	C	*	
	COMPUTER B40	C	*	
	RESOURCE 1 B41	C	*	
	TIME OUT ROOM B41A	C	*	
	RESOURCE 2 B42	C	*	
	RESOURCE 3 B43	C	*	
	RESTROOM B43A	C	*	
	CLASSROOM B45	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	RESTROOM B45A	C	*	
	STORAGE B45B	C	*	
	CLASSROOM B46	C	*	
	STORAGE B46A	C	*	
	CLASSROOM E1	C	*	
	CLASSROOM E2	C	*	
	CLASSROOM E3	C	*	
	CLASSROOM E4	C	*	
	CLASSROOM E9	C	*	
	CLASSROOM E10	C	*	
	CLASSROOM E11	C	*	
	CLASSROOM E12	C	*	
	JANITOR E101	C	*	
	ELECTRICAL ROOM E102	C	*	
	VESTIBULE E103	C	*	
	BOY'S RESTROOM E104	C	*	
	VESTIBULE E105	C	*	
	GIRL'S RESTROOM E106	C	*	
	WORK ROOM E110	C	*	
	WORK ROOM E114	C	*	
	CLASSROOM N1	C	*	
	WORK ROOM N1A	C	*	
	ELECTRICAL ROOM N1B	C	*	
	CLASSROOM N2	C	*	
	CLASSROOM N3	C	*	
	CLASSROOM N4	C	*	
	ART ROOM N5	C	*	
	KILN ROOM N5A	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	SERVICE YARD	C	*	
	GIRL'S RESTROOM N6	C	*	
	ELECTRICAL ROOM N7	C	*	
	JANITOR N8	C	*	
	BOY'S RESTROOM N9	C	*	
	CLASSROOM W1	C	*	
	CLASSROOM W2	C	*	
	CLASSROOM W3	C	*	
	CLASSROOM W4	C	*	
	CLASSROOM W5	C	*	
	CLASSROOM W7	C	*	
	CLASSROOM W8	C	*	
	CLASSROOM W9	C	*	
	CLASSROOM W10	C	*	
	CLASSROOM W11	C	*	
	ELECTRICAL ROOM W102	C	*	
	WORK ROOM W105	C	*	
	WORK ROOM W108	C	*	
	RESTROOM W113	C	*	
	RESTROOM W114	C	*	
	CORRIDOR B17	C	*	
	CORRIDOR B24	C	*	
	CORRIDOR B32	C	*	
	CORRIDOR B33	C	*	
	CORRIDOR B44	C	*	
PLASTER, GRAY, CEMENTITIOUS	CORRIDOR B24	W	E, W, S	S
	CORRIDOR B32	W	N, E, W, S	
	CORRIDOR B33	W	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Main Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR B44	W	S	
PIPE END SEALANT, WHITE, PLIABLE	CORRIDOR B24	O	*	S
	CORRIDOR B32	O	*	
	CORRIDOR B33	O	*	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, METAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
PAINT (PENETRATIONS AND FLASHINGS), SILVER, PLIABLE	ROOF	O	*	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, SILVER COATING	ROOF	O	*	
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
	ROOF	W	N, E, W, S	
SEALANT (PARAPET WALLS, FLASHINGS), WHITE, BRITTLE	ROOF	O	*	S
PIPE END SEALANT, WHITE, BRITTLE	ROOF	O	*	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
SEALANT (DOORS), TAN, PLIABLE	EXTERIOR	O	N, E, W, S	S
EXPANSION JOINT, BROWN, PLIABLE	EXTERIOR	O	N, E, W, S	S
GASKET, 8", BLACK, PAPER-LIKE	JANITOR N8	O	S	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	MULTI-PURPOSE E01	C	*	S
	VESTIBULE E01A	C	*	
	WING E03	C	*	
	INSTRUMENTS STORAGE E08	C	*	
	MUSIC E09	C	*	
	INSTRUMENTS STORAGE E09A	C	*	
	ART ROOM E10	C	*	
	STAGE E11	C	*	
	ROOM E11A	C	*	
	ROOM E11B	C	*	
	P.E. STORAGE E16	C	*	
	OFFICE E19	C	*	
	STORAGE E20	C	*	
	CORRIDOR E02A	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LIVING ROOM A02	C, W	N, E, W, S	S
	KITCHEN A03	C, W	N, E, W, S	
	DINING A04	C, W	N, E, S	
	HALL A05	C, W	N, E, W, S	
	BEDROOM A07	C, W	N, E, W, S	
	CLOSET A08	C, W	N, E, W, S	
	HALL A10	C, W	N, E, W, S	
	PANTRY A11	C, W	N, E, W, S	
	CLOSET A12	C, W	N, E, W, S	
	BEDROOM A14	C, W	N, E, W, S	
	CLOSET A15	C, W	N, E, W, S	
	MULTI-PURPOSE E01	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	WING E03	W	N, E, W, S	
	STORAGE E06	C, W	N, E	
	STORAGE E07	C, W	E, S	
	INSTRUMENTS STORAGE E08	W	N, E, W, S	
	MUSIC E09	W	N, E, W, S	
	INSTRUMENTS STORAGE E09A	W	N, E, W, S	
	ART ROOM E10	W	N, E, W	
	STAGE E11	C, W	N, E, W, S	
	ROOM E11A	W	N, E, W, S	
	ROOM E11B	W	N, E	
	STORAGE E12	C	*	
	OFFICE E15	C, W	N, E, W, S	
	P.E. STORAGE E16	W	N, E, W, S	
	OFFICE E19	W	N, E, W, S	
	STORAGE E20	W	N, E, W, S	
	CUSTODIAN E26	C, W	E, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	LIVING ROOM A02	C, W	N, E, W, S	S
	KITCHEN A03	C, W	N, E, W, S	
	DINING A04	C, W	N, E, S	
	HALL A05	C, W	N, E, W, S	
	BEDROOM A07	C, W	N, E, W, S	
	CLOSET A08	C, W	N, E, W, S	
	HALL A10	C, W	N, E, W, S	
	PANTRY A11	C, W	N, E, W, S	
	CLOSET A12	C, W	N, E, W, S	
	BEDROOM A14	C, W	N, E, W, S	
	CLOSET A15	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	MULTI-PURPOSE E01	C	*	
	WING E03	W	N, E, W, S	
	STORAGE E06	C, W	N, E	
	STORAGE E07	C, W	E, S	
	INSTRUMENTS STORAGE E08	W	N, E, W, S	
	MUSIC E09	W	N, E, W, S	
	INSTRUMENTS STORAGE E09A	W	N, E, W, S	
	ART ROOM E10	W	N, E, W	
	STAGE E11	C, W	N, E, W, S	
	ROOM E11A	W	N, E, W, S	
	ROOM E11B	W	N, E	
	STORAGE E12	C	*	
	OFFICE E15	C, W	N, E, W, S	
	P.E. STORAGE E16	W	N, E, W, S	
	OFFICE E19	W	N, E, W, S	
	STORAGE E20	W	N, E, W, S	
	CUSTODIAN E26	C, W	E, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	LIVING ROOM A02	C, W	N, E, W, S	S
	KITCHEN A03	C, W	N, E, W, S	
	DINING A04	C, W	N, E, S	
	HALL A05	C, W	N, E, W, S	
	BEDROOM A07	C, W	N, E, W, S	
	CLOSET A08	C, W	N, E, W, S	
	HALL A10	C, W	N, E, W, S	
	PANTRY A11	C, W	N, E, W, S	
	CLOSET A12	C, W	N, E, W, S	
	BEDROOM A14	C, W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CLOSET A15	C, W	N, E, W, S	
	MULTI-PURPOSE E01	C	*	
	WING E03	W	N, E, W, S	
	STORAGE E06	C, W	N, E	
	STORAGE E07	C, W	E, S	
	INSTRUMENTS STORAGE E08	W	N, E, W, S	
	MUSIC E09	W	N, E, W, S	
	INSTRUMENTS STORAGE E09A	W	N, E, W, S	
	ART ROOM E10	W	N, E, W	
	STAGE E11	C, W	N, E, W, S	
	ROOM E11A	W	N, E, W, S	
	ROOM E11B	W	N, E	
	STORAGE E12	C	*	
	OFFICE E15	C, W	N, E, W, S	
	P.E. STORAGE E16	W	N, E, W, S	
	OFFICE E19	W	N, E, W, S	
	STORAGE E20	W	N, E, W, S	
	CUSTODIAN E26	C, W	E, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	ART ROOM E10	W	N	S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	ART ROOM E10	W	N	S
CARPET, GRAY, FIBROUS, BLUE AND YELLOW SPACES	MUSIC E09	F	*	S
	ART ROOM E10	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND YELLOW SPACES	MUSIC E09	F	*	S
	ART ROOM E10	F	*	
VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, WHITE AND BROWN MOTTLES	INSTRUMENTS STORAGE E08	F	*	S
	MUSIC E09	F	*	
	ART ROOM E10	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM E11A	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, WHITE AND BROWN MOTTLES	INSTRUMENTS STORAGE E08	F	*	S
	MUSIC E09	F	*	
	ART ROOM E10	F	*	
	ROOM E11A	F	*	
WALLBASE (COVED), 4", GRAY, VINYL-LIKE	WING E03	O	N, E, W, S	S
	STORAGE E06	O	N, E, W, S	
	STORAGE E07	O	N, E, W, S	
	INSTRUMENTS STORAGE E08	O	N, E, W, S	
	MUSIC E09	O	N, E, W, S	
	INSTRUMENTS STORAGE E09A	O	N, E, W, S	
	ART ROOM E10	O	N, E, W, S	
	OFFICE E15	O	N, E, W, S	
	P.E. STORAGE E16	O	N, E, W, S	
	ELECTRICAL E25	O	N, E, W, S	
	CUSTODIAN E26	O	N, E, W, S	
	CORRIDOR E02	O	N, E, W, S	
	CORRIDOR E02A	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	WING E03	O	N, E, W, S	S
	STORAGE E06	O	N, E, W, S	
	STORAGE E07	O	N, E, W, S	
	INSTRUMENTS STORAGE E08	O	N, E, W, S	
	MUSIC E09	O	N, E, W, S	
	INSTRUMENTS STORAGE E09A	O	N, E, W, S	
	ART ROOM E10	O	N, E, W, S	
	OFFICE E15	O	N, E, W, S	
	P.E. STORAGE E16	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	ELECTRICAL E25	O	N, E, W, S	
	CUSTODIAN E26	O	N, E, W, S	
	CORRIDOR E02	O	N, E, W, S	
	CORRIDOR E02A	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	LIVING ROOM A02	O	W	S
	KITCHEN A03	O	N, W, S	
	DINING A04	O	N, E	
	HALL A05	O	S	
	BEDROOM A07	O	N, W, S	
	BATHROOM A09	O	N, E, W	
	HALL A10	O	N, W	
	PANTRY A11	O	S	
	CLOSET A12	O	S	
	BATH A13	O	E, W, S	
	BEDROOM A14	O	N, S	
	MULTI-PURPOSE E01	O	N, E, W, S	
	VESTIBULE E01A	O	E, S	
	WING E03	O	W, S	
	BOY'S RESTROOM E04	O	W, S	
	GIRL'S RESTROOM E05	O	E, S	
	STORAGE E06	O	S	
	STORAGE E07	O	W	
	INSTRUMENTS STORAGE E08	O	E	
	MUSIC E09	O	N, E, W, S	
	INSTRUMENTS STORAGE E09A	O	S	
	ART ROOM E10	O	W, S	
	STAGE E11	O	E	
	ROOM E11A	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	ROOM E11B	O	S	
	STORAGE E12	O	W	
	OFFICE E15	O	S	
	P.E. STORAGE E16	O	W, S	
	KITCHEN E18	O	E, W	
	OFFICE E19	O	N	
	WATER HEATER CLOSET E19	O	E	
	BOY' RESTROOM E21	O	N, W, S	
	GIRL'S RESTROOM E22	O	N, E	
	ELECTRICAL E25	O	W	
	CUSTODIAN E26	O	N, W, S	
	CORRIDOR E02	O	N, E, W, S	
	CORRIDOR E02A	O	N, E, W	
SINK ACOUSTICAL COATING, WHITE, ROUGH	MUSIC E09	O	E	S
	ART ROOM E10	O	W	
	STAGE E11	P	E	
FIRE DOOR INSULATION, WOOD CLADDING	MULTI-PURPOSE E01	O	N, E	S
	VESTIBULE E01A	O	E, S	
	WING E003	O	W, S	
	MUSIC E09	O	N, S	
	ART ROOM E10	O	S	
	STAGE E11	O	E	
	ROOM E11A	O	N	
	ROOM E11B	O	S	
	OFFICE E15	O	S	
	P.E. STORAGE E16	O	W, S	
	KITCHEN E18	O	W	
	OFFICE E19	O	N	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
	STORAGE E20	O	W	
	BOY'S RESTROOM E21	O	W	
	GIRL'S RESTROOM E22	O	N	
	CUSTODIAN E26	O	S	
	CORRIDOR E02	O	N, S	
	CORRIDOR E02A	O	N, W	
FIRE DOOR INSULATION, METAL CLADDING	MULTI-PURPOSE E01	O	W, S	S
	BOY'S RESTROOM E04	O	S	
	GIRL'S RESTROOM E05	O	S	
	STORAGE E06	O	S	
	STORAGE E07	O	W	
	MUSIC E09	O	W	
	ART ROOM E10	O	N	
	KITCHEN E18	O	E	
	KITCHEN YARD	O	W	
	WATER HEATER CLOSET E19	O	E	
	ELECTRICAL E25	O	W	
	ELECTRICAL E27	O	E	
	COOLING TOWER YARD	O	S	
	MECHANICAL PLANT	O	N, E	
	ELECTRICAL YARD	O	W	
	CORRIDOR E02	O	W	
	CORRIDOR E02A	O	E	
	EXTERIOR	O	N, E, W, S	
GLASS BLOCK, 8"X8", CLEAR	LIVING ROOM A02	O	W	N
	MULTI-PURPOSE E01	O	W, S	
	MUSIC E09	O	W	
	ART ROOM E10	O	S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CORRIDOR E02	O	W	
	EXTERIOR	O	W, S	
MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	LIVING ROOM A02	O	W	S
	MULTI-PURPOSE E01	O	W, S	
	MUSIC E09	O	W	
	ART ROOM E10	O	S	
	CORRIDOR E02	O	W	
	EXTERIOR	O	W, S	
VINYL STAIR TREAD, 12"X36", BROWN, VINYL-LIKE, CIRCLE PATTERN	WING E03	F	*	S
	ROOM E11A	F	*	
	ROOM E11B	F	*	
ADHESIVE, YELLOW, TACKY, ASSOCIATED WITH VINYL STAIR TREAD, 12"X36", BROWN, VINYL-LIKE, CIRCLE PATTERN	WING E03	F	*	S
	ROOM E11A	F	*	
	ROOM E11B	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	KITCHEN A03	F	*	S
	DINING A04	F	*	
	HALL A05	F	*	
	LAUNDRY A06	F	*	
	BATHROOM A09	F	*	
	HALL A10	F	*	
	PANTRY A11	F	*	
	CLOSET A12	F	*	
	BATH A13	F	*	
	WING E03	F	*	
	STAGE E11	F	*	
	STORAGE E12	F	*	
	OFFICE E15	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection,
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	P.E. STORAGE E16	F	*	
	STORAGE E20	F	*	
	CUSTODIAN E26	F	*	
	CORRIDOR E02	F	*	
	CORRIDOR E02A	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	KITCHEN A03	F	*	S
	DINING A04	F	*	
	HALL A05	F	*	
	LAUNDRY A06	F	*	
	BATHROOM A09	F	*	
	HALL A10	F	*	
	PANTRY A11	F	*	
	CLOSET A12	F	*	
	BATH A13	F	*	
	WING E03	F	*	
	STAGE E11	F	*	
	STORAGE E12	F	*	
	OFFICE E15	F	*	
	P.E. STORAGE E16	F	*	
	STORAGE E20	F	*	
	CUSTODIAN E26	F	*	
	CORRIDOR E02	F	*	
	CORRIDOR E02A	F	*	
ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	STAGE E11	C, W	N, E, W, S	S
	CORRIDOR E02	C	*	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	STAGE E11	C, W	N, E, W, S	S
	CORRIDOR E02	C	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	STAGE E11	W	S	
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	MULTI-PURPOSE E01	W	N, E, W, S	S
	STORAGE E06	W	W, S	
	STORAGE E07	W	N, W	
	ELECTRICAL E25	W	N, E	
	CUSTODIAN E26	W	N, E	
	ELECTRICAL E27	W	N	
	COOLING TOWER YARD	W	N, E, W, S	
	MECHANICAL PLANT	W	N, E, W, S	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 2"X8" SQUARE PATTERN AND CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS	MULTI-PURPOSE E01	W	N, E, W, S	S
	STORAGE E06	W	W, S	
	STORAGE E07	W	N, W	
	STAGE E11	W	S	
	KITCHEN YARD	W	N, E, W, S	
	WATER HEATER CLOSET E19	W	W	
	ELECTRICAL E25	W	N, E	
	CUSTODIAN E26	W	N, E	
	ELECTRICAL E27	W	W, S	
	COOLING TOWER YARD	W	N, E, W, S	
	MECHANICAL PLANT	W	N, E, W, S	
	ELECTRICAL YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	N, E, W, S	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL E25	C, W	W, S	S
	ELECTRICAL E27	C, W	W, S	
	CORRIDOR E02	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection,
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	CORRIDOR E02A	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL E25	C, W	W, S	S
	ELECTRICAL E27	C, W	W, S	
	CORRIDOR E02	W	N, E, W, S	
	CORRIDOR E02A	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	ELECTRICAL E25	C, W	W, S	S
	ELECTRICAL E27	C, W	W, S	
	CORRIDOR E02	W	N, E, W, S	
	CORRIDOR E02A	W	N, E, W, S	
PIPE END SEALANT, WHITE, PLIABLE	MECHANICAL PLANT	O	*	S
GASKET, 6", BLACK, VINYL LIKE	COOLING TOWER YARD	O	*	S
	MECHANICAL PLANT	O	*	
GASKET, 8", BLACK, VINYL-LIKE	COOLING TOWER YARD	O	*	S
	MECHANICAL PLANT	O	*	
CONCRETE, GRAY, CEMENTITIOUS	LIVING ROOM A02	F	*	S
	KITCHEN A03	F	*	
	DINING A04	F	*	
	HALL A05	F	*	
	LAUNDRY A06	F	*	
	BEDROOM A07	F	*	
	CLOSET A08	F	*	
	BATHROOM A09	F	*	
	HALL A10	F	*	
	PANTRY A11	F	*	
	CLOSET A12	F	*	
	BATH A13	F	*	
	BEDROOM A14	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	CLOSET A15	F	*	
	MULTI-PURPOSE E01	F	*	
	VESTIBULE E01A	F	*	
	WING E03	F	*	
	BOY'S RESTROOM E04	F	*	
	GIRL'S RESTROOM E05	F	*	
	STORAGE E06	F	*	
	STORAGE E07	F	*	
	INSTRUMENTS STORAGE E08	F	*	
	MUSIC E09	F	*	
	INSTRUMENTS STORAGE E09A	F	*	
	ART ROOM E10	F	*	
	STAGE E11	F	*	
	ROOM E11A	F	*	
	ROOM E11B	F	*	
	STORAGE E12	F	*	
	OFFICE E15	F	*	
	P.E. STORAGE E16	F	*	
	KITCHEN E18	F	*	
	KITCHEN YARD	F	*	
	OFFICE E19	F	*	
	WATER HEATER CLOSET E19	F	*	
	STORAGE E20	F	*	
	BOY' RESTROOM E21	F	*	
	GIRL'S RESTROOM E22	F	*	
	ELECTRICAL E25	F	*	
	CUSTODIAN E26	F	*	
	ELECTRICAL E27	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection,
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	COOLING TOWER YARD	F	*	
	MECHANICAL PLANT	F	*	
	ELECTRICAL YARD	F	*	
	CORRIDOR E02	F	*	
	CORRIDOR E02A	F	*	
SEALANT (DOORS, EXPANSION), TAN, PLIABLE	ELECTRICAL E27	O	E	S
	KITCHEN YARD	O	E, W	
	COOLING TOWER YARD	O	N, E, W, S	
	MECHANICAL PLANT	O	N, E, W, S	
	ELECTRICAL YARD	O	N, E, W, S	
	EXTERIOR	O	N, E, W, S	
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR	W	N, E, W, S	S
SEALANT (EQUIPMENT), BLACK, TAR-LIKE	COOLING TOWER YARD	O	*	S
CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 2"X8" SQUARE PATTERN	WATER HEATER CLOSET E19	W	W	S
	ELECTRICAL E25	W	E, S	
	ELECTRICAL E27	W	W	
	KITCHEN YARD	W	N, E, W, S	
	ELECTRICAL YARD	W	N, E, W, S	
	EXTERIOR	W	N, E, W, S	
	ROOF	W	N, E, W, S	
CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS	ELECTRICAL YARD	W	N, S	S
	ROOF	W	N, E, W, S	
GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	BATHROOM A09	W	N, W, S	S
	BATH A13	W	N, W, S	
	VESTIBULE E01A	W	N, E, W, S	
	BOY'S RESTROOM E04	W	N, E, W, S	
	GIRL'S RESTROOM E05	W	N, E, W, S	
	BOY'S RESTROOM E21	W	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
	GIRL'S RESTROOM E22	W	N, E, W, S	
	CUSTODIAN E26	W	W, S	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE, 2"X2", BROWN, SMOOTH	BATHROOM A09	W	N, W, S	S
	BATH A13	W	N, W, S	
	VESTIBULE E01A	W	N, E, W, S	
	BOY'S RESTROOM E04	W	N, E, W, S	
	GIRL'S RESTROOM E05	W	N, E, W, S	
	BOY'S RESTROOM E21	W	N, E, W, S	
	GIRL'S RESTROOM E22	W	N, E, W, S	
	CUSTODIAN E26	W	W, S	
SEALANT (MECHANICAL), WHITE, PLIABLE	KITCHEN E18	O	*	S
ACOUSTICAL CEILING PANEL, 2'X2', WHITE, CHALKY, VINYL COVER	KITCHEN E18	C	*	S
FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	KITCHEN E18	W	N, E, W, S	S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	KITCHEN E18	W	N, E, W, S	S
QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	LIVING ROOM A02	F	*	S
	KITCHEN E18	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	LIVING ROOM A02	F	*	S
	KITCHEN E18	F	*	
CARPET, BROWN, FIBROUS	LIVING ROOM A02	F	*	S
	BEDROOM A07	F	*	
	CLOSET A08	F	*	
	BEDROOM A14	F	*	
	CLOSET A15	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BROWN, FIBROUS	LIVING ROOM A02	F	*	S
	BEDROOM A07	F	*	
	CLOSET A08	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
	BEDROOM A14	F	*	
	CLOSET A15	F	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BATHROOM A09	C, W	N, E, W, S	S
	BATH A13	C, W	N, E, W, S	
	BOY'S RESTROOM E04	C	*	
	GIRL'S RESTROOM E05	C	*	
	WATER HEATER CLOSET E19	C, W	N, W, S	
	BOY'S RESTROOM E21	C	*	
	GIRL'S RESTROOM E22	C	*	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BATHROOM A09	C, W	N, E, W, S	S
	BATH A13	C, W	N, E, W, S	
	BOY'S RESTROOM E04	C	*	
	GIRL'S RESTROOM E05	C	*	
	WATER HEATER CLOSET E19	C, W	N, W, S	
	BOY'S RESTROOM E21	C	*	
	GIRL'S RESTROOM E22	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	BATHROOM A09	C, W	N, E, W, S	S
	BATH A13	C, W	N, E, W, S	
	BOY'S RESTROOM E04	C	*	
	GIRL'S RESTROOM E05	C	*	
	WATER HEATER CLOSET E19	C, W	N, W, S	
	BOY'S RESTROOM E21	C	*	
	GIRL'S RESTROOM E22	C	*	
GLAZED WALL TILE, 2"X2", BROWN, SMOOTH	BATHROOM A09	W	N, W, S	S
SINK ACOUSTICAL COATING, GRAY, ROUGH	KITCHEN A03	O	S	S
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	MULTI-PURPOSE E01	F	*	S
VINYL COMPOSITION TILE (STRIP), 2"X24", BLACK, SMOOTH	MULTI-PURPOSE E01	F	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S
VINYL COMPOSITION TILE (STRIP), 2"X24", RED, SMOOTH	MULTI-PURPOSE E01	F	*	S
VINYL COMPOSITION TILE (STRIP), 2"X24", BLUE, SMOOTH	MULTI-PURPOSE E01	F	*	S
VINYL COMPOSITION TILE (STRIP), 2"X24", GREEN, SMOOTH	MULTI-PURPOSE E01	F	*	S
VINYL COMPOSITION TILE (STRIP), 2"X24", YELLOW, SMOOTH	MULTI-PURPOSE E01	F	*	S
VINYL COMPOSITION TILE, 24"X24", RED, VINYL-LIKE, CIRCLE PATTERN	VESTIBULE E01A	F	*	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES AND VINYL COMPOSITION TILE (STRIP), 2"X24", BLACK, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", RED, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", BLUE, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", GREEN, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", GREEN, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", YELLOW, SMOOTH AND VINYL COMPOSITION TILE, 24"X24", RED, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE E01	F	*	S
	VESTIBULE E01A	F	*	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	MULTI-PURPOSE E01	O	N, E, W, S	S
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	MULTI-PURPOSE E01	O	N, E, W, S	S
CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	BOY'S RESTROOM E04	F	*	S
	GIRL'S RESTROOM E05	F	*	
	BOY' RESTROOM E21	F	*	
	GIRL'S RESTROOM E22	F	*	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	BOY'S RESTROOM E04	F	*	S
	GIRL'S RESTROOM E05	F	*	
	BOY' RESTROOM E21	F	*	
	GIRL'S RESTROOM E22	F	*	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (FLASHINGS), WHITE, PLIABLE	ROOF	O	*	S
PAINT (PENETRATIONS AND FLASHINGS), WHITE, PLIABLE	ROOF	O	*	S
PAINT (PENETRATIONS AND FLASHINGS), SILVER, PLIABLE	ROOF	O	*	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
 Kyrene De Los Ninos Elementary School, KSD
 Multi-Purpose Building*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
CONCRETE, GRAY, CEMENTITIOUS	COOLING TOWER YARD	F	*	S
	MECHANICAL PLANT	F	*	
	ELECTRICAL YARD	F	*	
WALLBASE (STRAIGHT), 12", BROWN, VINYL-LIKE	WING E03	O	E, W	S
	ROOM E11A	O	N, S	
	ROOM E11B	O	N, S	

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R1/R3*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/I/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM R1	C	*	S
	CLASSROOM R3	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R1	W	N, E, W, S	S
	CLASSROOM R3	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R1	W	N, E, W, S	S
	CLASSROOM R3	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R1	W	N, E, W, S	S
	CLASSROOM R3	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R1	W	N, E, S	S
	CLASSROOM R3	W	N, W, S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R1	W	N, E, S	S
	CLASSROOM R3	W	N, W, S	
CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	CLASSROOM R1	F	*	S
	CLASSROOM R3	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	CLASSROOM R1	F	*	S
	CLASSROOM R3	F	*	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	CLASSROOM R1	F	*	S
	CLASSROOM R3	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	CLASSROOM R1	F	*	S
	CLASSROOM R3	F	*	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	CLASSROOM R1	O	N, E, W, S	S
	CLASSROOM R3	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	CLASSROOM R1	O	N, E, W, S	S
	CLASSROOM R3	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R1/R3*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
FIRE DOOR INSULATION, METAL CLADDING	CLASSROOM R1	O	S	S
	CLASSROOM R3	O	S	
	EXTERIOR	O	S	
SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	CLASSROOM R1	O	W, S	S
	CLASSROOM R3	O	E, S	
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM R1	O	W	S
	CLASSROOM R3	O	E	
GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R1	C	*	S
	CLASSROOM R3	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R1	C	*	S
	CLASSROOM R3	C	*	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
PANELING (METAL), FACTORY FINISH	ROOF	W	*	N
SEALANT (PENETRATIONS, FLASHINGS AND SEAMS OF METAL ROOF), WHITE, PLIABLE	ROOF	O	*	S
CONCRETE (SIDEWALKS AND ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R2/R4*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/I/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM R2	C	*	S
	CLASSROOM R4	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R2	W	N, E, W, S	S
	CLASSROOM R4	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R2	W	N, E, W, S	S
	CLASSROOM R4	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R2	W	N, E, W, S	S
	CLASSROOM R4	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R2	W	N, E, S	S
	CLASSROOM R4	W	N, W, S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R2	W	N, E, S	S
	CLASSROOM R4	W	N, W, S	
CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	CLASSROOM R2	F	*	S
	CLASSROOM R4	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	CLASSROOM R2	F	*	S
	CLASSROOM R4	F	*	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	CLASSROOM R2	F	*	S
	CLASSROOM R4	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	CLASSROOM R2	F	*	S
	CLASSROOM R4	F	*	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	CLASSROOM R2	O	N, E, W, S	S
	CLASSROOM R4	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	CLASSROOM R2	O	N, E, W, S	S
	CLASSROOM R4	O	N, E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R2/R4*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
FIRE DOOR INSULATION, METAL CLADDING	CLASSROOM R2	O	N	S
	CLASSROOM R4	O	N	
	EXTERIOR	O	N	
SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	CLASSROOM R2	O	N, W	S
	CLASSROOM R4	O	N, E	
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM R2	O	W	S
	CLASSROOM R4	O	E	
GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R2	C	*	S
	CLASSROOM R4	C	*	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R2	C	*	S
	CLASSROOM R4	C	*	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
PANELING (METAL), FACTORY FINISH	ROOF	O	*	N
SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	ROOF	O	*	S
CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S

* - **Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R5/R7*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM R5	C	*	S
	CLASSROOM R7	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY.	CLASSROOM R5	W	N, E, W, S	S
	CLASSROOM R7	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R5	W	N, E, W, S	S
	CLASSROOM R7	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R5	W	N, E, W, S	S
	CLASSROOM R7	W	N, E, W, S	
CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	CLASSROOM R5	F	*	S
	CLASSROOM R7	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	CLASSROOM R5	F	*	S
	CLASSROOM R7	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R5	F	*	S
	CLASSROOM R7	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R5	F	*	S
	CLASSROOM R7	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK) WHITE, PLIABLE	CLASSROOM R5	O	E, S	S
	CLASSROOM R7	O	N, E	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM R5	O	N, E, W, S	S
	CLASSROOM R7	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM R5	O	N, E, W, S	S
	CLASSROOM R7	O	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R5	W	N, E, W	S
	CLASSROOM R7	W	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R5/R7*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R5	W	N, E, W	S
	CLASSROOM R7	W	E, W, S	
SINK ACOUSTICAL COATING, WHITE, ROUGH	CLASSROOM R5	O	S	S
	CLASSROOM R7	O	N	
FIRE DOOR INSULATION, METAL CLADDING	CLASSROOM R5	O	E	S
	CLASSROOM R7	O	E	
	EXTERIOR	O	E	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
PANELING (METAL), FACTORY FINISH	ROOF	O	*	N
SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	ROOF	O	*	S
CONCRETE, GRAY, CEMENTITIOUS	MECHANICAL R5A	F	*	S
	MECHANICAL R7A	F	*	
CONCRETE (SIDEWALKS AND ENTRIES), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
SEALANT (MECHANICAL), GRAY, PLIABLE	ROOF	O	*	S

* - *Not Applicable*

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R6/R8*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	CLASSROOM R6	C	*	S
	CLASSROOM R8	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R6	W	N, E, W, S	S
	CLASSROOM R8	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R6	W	N, E, W, S	S
	CLASSROOM R8	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R6	W	N, E, W, S	S
	CLASSROOM R8	W	N, E, W, S	
CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	CLASSROOM R6	F	*	S
	CLASSROOM R8	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	CLASSROOM R6	F	*	S
	CLASSROOM R8	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R6	F	*	S
	CLASSROOM R8	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R6	F	*	S
	CLASSROOM R8	F	*	
SEALANT (DOORS, WINDOWS, MILLWORK) WHITE, PLIABLE	CLASSROOM R6	O	W, S	S
	CLASSROOM R8	O	N, W	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	CLASSROOM R6	O	N, E, W, S	S
	CLASSROOM R8	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	CLASSROOM R6	O	N, E, W, S	S
	CLASSROOM R8	O	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R6	W	N, E, W	S
	CLASSROOM R8	W	E, W, S	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R6/R8*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R6	W	N, E, W	S
	CLASSROOM R8	W	E, W, S	
SINK ACOUSTICAL COATING, GRAY, ROUGH	CLASSROOM R6	O	S	S
	CLASSROOM R8	O	N	
FIRE DOOR INSULATION, METAL CLADDING	CLASSROOM R6	O	W	S
	CLASSROOM R8	O	W	
	EXTERIOR	O	W	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
PANELING (METAL), FACTORY FINISH	ROOF	O	*	N
SEALANT (PENETRATIONS, FLASHINGS), WHITE, PLIABLE	ROOF	O	*	S
CONCRETE, GRAY, CEMENTITIOUS	MECHANICAL R6A	F	*	S
	MECHANICAL R8A	F	*	
CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
SEALANT (MECHANICAL), GRAY, PLIABLE	ROOF	O	*	S

* - *Not Applicable*

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R9/R11*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	CLASSROOM R9	C	*	S
	CLASSROOM R11	C	*	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	CLASSROOM R9	C	*	S
	CLASSROOM R11	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R9	W	N, E, W, S	S
	CLASSROOM R11	W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R9	W	N, E, W, S	S
	CLASSROOM R11	W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R9	W	N, E, W, S	S
	CLASSROOM R11	W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R9	W	N, E, W	S
	CLASSROOM R11	W	E, W, S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R9	W	N, E, W	S
	CLASSROOM R11	W	E, W, S	
CARPET, GRAY, FIBROUS, RED AND BROWN SPECKS	CLASSROOM R9	F	*	S
	CLASSROOM R11	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, RED AND BROWN SPECKS	CLASSROOM R9	F	*	S
	CLASSROOM R11	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R9	F	*	S
	RESTROOM R9A	F	*	
	CLASSROOM R11	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R9	F	*	S
	RESTROOM R9A	F	*	
	CLASSROOM R11	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R9/R11*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM R9	O	N, E, W, S	S
	RESTROOM R9A	O	N, E, W, S	
	CLASSROOM R11	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	CLASSROOM R9	O	N, E, W, S	S
	RESTROOM R9A	O	N, E, W, S	
	CLASSROOM R11	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, FIXTURES, MILLWORK), WHITE, PLIABLE	CLASSROOM R9	O	N, E, W, S	S
	RESTROOM R9A	O	E, S	
	BOY'S RESTROOM	O	N	
	CLASSROOM R11	O	N, E	
SINK ACOUSTICAL COATING, BLACK, ROUGH	CLASSROOM R9	O	S	S
	CLASSROOM R11	O	N	
FIRE DOOR INSULATION, METAL CLADDING	CLASSROOM R9	O	E	S
	BOY'S RESTROOM	O	N	
	CLASSROOM R11	O	E	
	EXTERIOR	O	N, E	
SEALANT (WINDOWS), BLACK, TAR-LIKE	CLASSROOM R9	O	E	S
	CLASSROOM R11	O	E	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM R9A	C, W	N, E, W, S	S
	BOY'S RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM R9A	C, W	N, E, W, S	S
	BOY'S RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RESTROOM R9A	C, W	N, E, W, S	S
	BOY'S RESTROOM	C, W	N, E, W, S	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	ROOF	O	*	S
VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	BOY'S RESTROOM	O, F	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Portable R9/R11

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	BOY'S RESTROOM	O, F	N, E, W, S	S
CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS, FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S
SEALANT (MECHANICAL), GRAY, PLIABLE	ROOF	O	*	S

*** - Not Applicable**

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R10/R12*

JOB NO. 07-367

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	CLASSROOM R10	C	*	S
	CLASSROOM R12	C	*	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	CLASSROOM R10	C	*	S
	CLASSROOM R12	C	*	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R10	C, W	N, E, W, S	S
	CLASSROOM R12	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	CLASSROOM R10	C, W	N, E, W, S	S
	CLASSROOM R12	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	CLASSROOM R10	C, W	N, E, W, S	S
	CLASSROOM R12	C, W	N, E, W, S	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R10	W	N, E, W	S
	CLASSROOM R12	W	E, W, S	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	CLASSROOM R10	W	N, E, W	S
	CLASSROOM R12	W	E, W, S	
CARPET, BLUE, FIBROUS, RED AND BROWN SPECKS	CLASSROOM R10	F	*	S
	CLASSROOM R12	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, RED AND BROWN SPECKS	CLASSROOM R10	F	*	S
	CLASSROOM R12	F	*	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R10	F	*	S
	RESTROOM R10A	F	*	
	CLASSROOM R12	F	*	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	CLASSROOM R10	F	*	S
	RESTROOM R10A	F	*	
	CLASSROOM R12	F	*	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R10/R12*

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT C/W/F/O	COMPONENT LOCATION N/E/W/S	ACM N/S N/S
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	CLASSROOM R10	O	N, E, W, S	S
	RESTROOM R10A	O	N, E, W, S	
	CLASSROOM R12	O	N, E, W, S	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	CLASSROOM R10	O	N, E, W, S	S
	RESTROOM R10A	O	N, E, W, S	
	CLASSROOM R12	O	N, E, W, S	
SEALANT (DOORS, WINDOWS, FIXTURES, MILLWORK), WHITE, PLIABLE	CLASSROOM R10	O	N, W, S	S
	RESTROOM R10A	O	W, S	
	GIRL'S RESTROOM	O	N	
	CLASSROOM R12	O	N, W	
SINK ACOUSTICAL COATING, BLACK, ROUGH	CLASSROOM R10	O	S	S
	CLASSROOM R12	O	N	
FIRE DOOR INSULATION, METAL CLADDING	CLASSROOM R10	O	W	S
	GIRL'S RESTROOM	O	N	
	CLASSROOM R1	O	W	
	EXTERIOR	O	N, W	
SEALANT (WINDOWS), BLACK, TAR-LIKE	CLASSROOM R10	O	W	S
	CLASSROOM R12	O	W	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM R10A	C, W	N, E, W, S	S
	GIRL'S RESTROOM	C, W	N, E, W, S	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RESTROOM R10A	C, W	N, E, W, S	S
	GIRL'S RESTROOM	C, W	N, E, W, S	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RESTROOM R10A	C, W	N, E, W, S	S
	GIRL'S RESTROOM	C, W	N, E, W, S	
SIDING (METAL), PAINTED	EXTERIOR	W	N, E, W, S	N
SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	ROOF	O		S
VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	GIRL'S RESTROOM	F, O	N, E, W, S	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene De Los Ninos Elementary School, KSD
Portable R10/R12

JOB NO. 07-367

MATERIAL DESCRIPTION	MATERIAL LOCATION	MATERIAL COMPONENT	COMPONENT LOCATION	ACM N/S
		C/W/F/O	N/E/W/S	N/S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	GIRL'S RESTROOM	F, O	N, E, W, S	S
CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	EXTERIOR	F	*	S
ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF	O	*	S
MASTIC (PENETRATIONS, FLASHINGS), BLACK, TAR-LIKE	ROOF	O	*	S

* - **Not Applicable**

END OF TABLE

2.4 AHERA Inspection Procedures and Protocols

2.4.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.4.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.5 Visual Inspection

A visual inspection of the eight buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.

2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials

TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS

MAIN BUILDING
MULTI-PURPOSE BUILDING
PORTABLE R1/R3
PORTABLE R2/R4
PORTABLE R5/R7
PORTABLE R6/R8
PORTABLE R9/R11
PORTABLE R10/R12

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	43,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	36,000	SF
M-GWB-03	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	36,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	S	NF	3,600	SF
M-CPT-05	CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	A	NF	40,000	SF
M-MAS-06	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	A	NF	20,000	SF
M-VCT-07	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	4,000	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	4,000	SF
M-WAB-09	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-ADH-10	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-SAC-11	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	36	SF
M-SLT-12	SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	A	NF	250	SF
M-SLT-13	SEALANT (MILLWORK), BROWN, PLIABLE	A	NF	25	SF
M-FDI-14	FIRE DOOR INSULATION, WOOD CLADDING	A	NF	672	SF
M-FDI-15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	756	SF
S-SAT-16	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,000	SF
M-GWB-17	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,000	SF
S-JTC-18	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	S	NF	200	SF
M-GWT-19	GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	200	SF
M-GRT-20	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", TAN, SMOOTH	A	NF	20	SF
M-CMT-21	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	A	NF	900	SF
M-GRT-22	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	A	NF	100	SF
M-WAB-23	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	1,500	SF
M-ADH-24	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	1,500	SF
M-TWP-25	TACKABLE WALL PANEL, BROWN, FIBROUS, TAN, VINYL COVER	A	NF	800	SF
M-ADH-26	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, TAN, VINYL COVER	A	NF	800	SF
S-SAT-27	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,500	SF
M-GWB-28	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,500	SF
S-JTC-29	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	S	NF	250	SF
M-CON-30	CONCRETE, GRAY, CEMENTITIOUS	A	NF	45,000	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-CMU-31	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	500	SF
M-MRT-32	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	50	SF
M-ADH-33	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	50	SF
M-GWT-34	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	1,500	SF
M-GRT-35	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	150	SF
M-SLT-36	SEALANT (WINDOWS), BLACK, TAR-LIKE	A	NF	20	SF
M-SLT-36	SEALANT (WINDOWS), BLACK, TAR-LIKE	A	NF	500	SF
M-GRT-38	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH	A	NF	50	SF
M-MRT-39	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	100	SF
M-MRT-39	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	30	SF
M-SLT-41	SEALANT (FIRE STOP), RED, PLIABLE	A	NF	5	SF
M-VCT-42	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	A	NF	350	SF
M-MAS-43	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, BROWN MOTTLES	A	NF	350	SF
M-GWB-44	GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	7,500	SF
S-JTC-45	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	750	SF
M-CON-46	CONCRETE (DOUBLE T'S), GRAY, CEMENTITIOUS	A	NF	130,000	SF
S-PLA-47	PLASTER, GRAY, CEMENTITIOUS	A	NF	4,000	SF
M-PES-48	PIPE END SEALANT, WHITE, PLIABLE	A	NF	50	SF
M-BUR-49	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	3,500	SF
M-BUR-50	BUILT-UP ROOFING, BLACK, ASPHALTIC, METAL CAP	A	NF	40,000	SF
M-MAS-51	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	1,000	SF
M-PNT-52	PAINT (PENETRATIONS AND FLASHINGS), SILVER, PLIABLE	A	NF	1,000	SF
M-BUR-53	BUILT-UP ROOFING, BLACK, ASPHALTIC, SILVER COATING	A	NF	500	SF
S-STU-54	STUCCO, GRAY, CEMENTITIOUS	A	NF	10,000	SF
M-SLT-55	SEALANT (PARAPET WALLS, FLASHINGS), WHITE, BRITTLE	A	NF	500	SF
M-PES-56	PIPE END SEALANT, WHITE, BRITTLE	A	NF	50	SF
M-CMU-57	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	10,000	SF
M-MRT-58	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	1,000	SF
M-CON-59	CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	A	NF	20,000	SF
M-SLT-60	SEALANT (DOORS), TAN, PLIABLE	A	NF	35	SF
M-EXJ-61	EXPANSION JOINT, BROWN, PLIABLE	A	NF	500	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Main Building*

JOB NO. 07-367

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-GAS-62	GASKET, 8", BLACK, PAPER-LIKE	A	NF	2	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	5,500	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
M-GWB-03	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	10,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	1,000	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	200	SF
M-ADH-06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	200	SF
M-CPT-07	CARPET, GRAY, FIBROUS, BLUE AND YELLOW SPACES	A	NF	1,700	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND YELLOW SPACES	A	NF	1,700	SF
M-VCT-09	VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, WHITE AND BROWN MOTTLES	A	NF	700	SF
M-MAS-10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", PINK, SMOOTH, WHITE AND BROWN MOTTLES	A	NF	700	SF
M-WAB-11	WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	400	SF
M-ADH-12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", GRAY, VINYL-LIKE	A	NF	400	SF
M-SLT-13	SEALANT (DOORS, WINDOWS, MILLWORK, FIXTURES), WHITE, PLIABLE	A	NF	100	SF
M-SAC-14	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	6	SF
M-FDI-15	FIRE DOOR INSULATION, WOOD CLADDING	A	NF	357	SF
M-FDI-16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	525	SF
M-MRT-17	MORTAR, WHITE, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	100	SF
M-VST-18	VINYL STAIR TREAD, 12"X36", BROWN, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF
M-ADH-19	ADHESIVE, YELLOW, TACKY, ASSOCIATED WITH VINYL STAIR TREAD, 12"X36", BROWN, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF
M-VCT-20	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	2,600	SF
M-MAS-21	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	2,600	SF
M-ACT-22	ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	S	F	300	SF
M-ADH-23	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, PINHOLES AND FISSURES, WHITE	A	NF	300	SF
M-CMU-24	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-MRT-25	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS AND CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 2"X8" SQUARE PATTERN AND CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS	A	NF	1,000	SF
S-SAT-26	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,300	SF
M-GWB-27	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,300	SF
S-JTC-28	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	130	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-PES-29	PIPE END SEALANT, WHITE, PLIABLE	A	NF	10	SF
M-GAS-30	GASKET, 6", BLACK, VINYL LIKE	A	NF	8	SF
M-GAS-31	GASKET, 8", BLACK, VINYL-LIKE	A	NF	2	SF
M-CON-32	CONCRETE, GRAY, CEMENTITIOUS	A	NF	17,700	SF
M-SLT-33	SEALANT (DOORS, EXPANSION), TAN, PLIABLE	A	NF	50	SF
S-STU-34	STUCCO, GRAY, CEMENTITIOUS	A	NF	5,000	SF
M-SLT-35	SEALANT (EQUIPMENT), BLACK, TAR-LIKE	A	NF	10	SF
M-CMU-36	CONCRETE MASONRY UNIT, 8"X16", GRAY, CEMENTITIOUS, 2"X8" SQUARE PATTERN	A	NF	14,700	SF
M-CMU-37	CONCRETE MASONRY UNIT, 8"X8", GRAY, CEMENTITIOUS	A	NF	20	SF
M-GWT-38	GLAZED WALL TILE, 4"X4", WHITE, SMOOTH	A	NF	2,500	SF
M-GRT-39	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", WHITE, SMOOTH AND GLAZED WALL TILE, 2"X2", BROWN, SMOOTH	A	NF	250	SF
M-SLT-40	SEALANT (MECHANICAL), WHITE, PLIABLE	A	NF	10	SF
M-APL-41	ACOUSTICAL CEILING PANEL, 2'X2', WHITE, CHALKY, VINYL COVER	S	NF	500	SF
M-ADH-42	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED	A	NF	500	SF
M-QPT-43	QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	A	NF	50	SF
M-GRT-44	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH QUARRY/PAVER TILE, 6"X6", TAN, SMOOTH	A	MF	50	SF
M-CPT-45	CARPET, BROWN, FIBROUS	A	NF	300	SF
M-MAS-46	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BROWN, FIBROUS	A	NF	300	SF
S-SAT-47	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,300	SF
M-GWB-48	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	1,300	SF
S-JTC-49	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	130	SF
M-GWT-50	GLAZED WALL TILE, 2"X2", BROWN, SMOOTH	A	NF	5	SF
M-SAC-51	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	2	SF
M-VCT-52	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	2,000	SF
M-VCT-53	VINYL COMPOSITION TILE (STRIP), 2"X24", BLACK, SMOOTH	A	NF	50	SF
M-VCT-54	VINYL COMPOSITION TILE (STRIP), 2"X24", RED, SMOOTH	A	NF	50	SF
M-VCT-55	VINYL COMPOSITION TILE (STRIP), 2"X24", BLUE, SMOOTH	A	NF	50	SF
M-VCT-56	VINYL COMPOSITION TILE (STRIP), 2"X24", GREEN, SMOOTH	A	NF	50	SF
M-VCT-57	VINYL COMPOSITION TILE (STRIP), 2"X24", YELLOW, SMOOTH	A	NF	50	SF
M-VCT-58	VINYL COMPOSITION TILE, 24"X24", RED, VINYL-LIKE, CIRCLE PATTERN	A	NF	50	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Multi-Purpose Building*

JOB NO. 07-367

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·MAS·59	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES AND VINYL COMPOSITION TILE (STRIP), 2"X24", BLACK, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", RED, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", BLUE, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", GREEN, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", GREEN, SMOOTH AND VINYL COMPOSITION TILE (STRIP), 2"X24", YELLOW, SMOOTH AND VINYL COMPOSITION TILE, 24"X24", RED, VINYL-LIKE, CIRCLE PATTERN	A	NF	2,300	SF
M·WAB·60	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M·ADH·61	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M·CMT·62	CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	A	NF	700	SF
M·GRT·63	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", TAN, SMOOTH, PEPPERED	A	NF	70	SF
M·BUR·64	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	17,000	SF
M·MAS·65	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, TAR-LIKE	A	NF	750	SF
M·SLT·66	SEALANT (FLASHINGS), WHITE, PLIABLE	A	NF	50	SF
M·PNT·67	PAINT (PENETRATIONS AND FLASHINGS), WHITE, PLIABLE	A	NF	750	SF
M·PNT·68	PAINT (PENETRATIONS AND FLASHINGS), SILVER, PLIABLE	A	NF	750	SF
M·CON·69	CONCRETE (ENTRIES), GRAY, CEMENTITIOUS	A	NF	15,000	SF
M·CON·70	CONCRETE, GRAY, CEMENTITIOUS	A	NF	1,000	SF
M·WAB·71	WALLBASE (STRAIGHT), 12", BROWN, VINYL-LIKE	A	NF	12	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R1/R3*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,700	SF
M-GWB-03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,700	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	270	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-ADH-06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-CPT-07	CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	A	NF	2,100	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	A	NF	2,100	SF
M-VCT-09	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	150	SF
M-MAS-10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	150	SF
M-WAB-11	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-ADH-12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-FDI-13	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M-SLT-14	SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	A	NF	20	SF
M-SAC-15	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M-GWB-16	GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	2,250	SF
S-JTC-17	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	225	SF
M-SLT-18	SEALANT (PENETRATIONS, FLASHINGS AND SEAMS OF METAL ROOF), WHITE, PLIABLE	A	NF	200	SF
M-CON-19	CONCRETE (SIDEWALKS AND ENTRIES), GRAY, CEMENTITIOUS	A	NF	750	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R2/R4*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,000	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,000	SF
M-GWB-03	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,000	SF
S-JTC-04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	S	NF	200	SF
M-TWP-05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-ADH-06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-CPT-07	CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	A	NF	2,100	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, BLUE AND TAN SPECKS	A	NF	2,100	SF
M-VCT-09	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	150	SF
M-MAS-10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, GRAY MOTTLES	A	NF	150	SF
M-WAB-11	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-ADH-12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	100	SF
M-FDI-13	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M-SLT-14	SEALANT (DOORS, WINDOWS, MILLWORK), WHITE, PLIABLE	A	NF	20	SF
M-SAC-15	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M-GWB-16	GYPSON WALLBOARD, WHITE, CHALKY	S	NF	2,250	SF
S-JTC-17	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	S	NF	225	SF
M-SLT-18	SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	A	NF	200	SF
M-CON-19	CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	A	NF	750	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R5/R7*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M·APL·01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S·SAT·02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,400	SF
M·GWB·03	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,400	SF
S·JTC·04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	240	SF
M·CPT·05	CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	A	NF	1,800	SF
M·MAS·06	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	A	NF	1,800	SF
M·VCT·07	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	200	SF
M·MAS·08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	200	SF
M·SLT·09	SEALANT (DOORS, WINDOWS, MILLWORK) WHITE, PLIABLE	A	NF	20	SF
M·WAB·10	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M·ADH·11	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M·TWP·12	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,200	SF
M·ADH·13	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,200	SF
M·SAC·14	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	4	SF
M·FDI·15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M·SLT·16	SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	A	NF	200	SF
M·CON·17	CONCRETE, GRAY, CEMENTITIOUS	A	NF	120	SF
M·CON·18	CONCRETE (SIDEWALKS AND ENTRIES), GRAY, CEMENTITIOUS	A	NF	750	SF
M·SLT·19	SEALANT (MECHANICAL), GRAY, PLIABLE	A	NF	5	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R6/R8*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-APL-01	ACOUSTICAL CEILING PANEL, 2'X4', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S-SAT-02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,400	SF
M-GWB-03	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,400	SF
S-JTC-04	JOINT COMPOUND, WHITE; CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	240	SF
M-CPT-05	CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	A	NF	1,600	SF
M-MAS-06	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, RED AND TAN SPECKS	A	NF	1,600	SF
M-VCT-07	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	200	SF
M-MAS-08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	200	SF
M-SLT-09	SEALANT (DOORS, WINDOWS, MILLWORK) WHITE, PLIABLE	A	NF	20	SF
M-WAB-10	WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-ADH-11	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-TWP-12	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,200	SF
M-ADH-13	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,200	SF
M-SAC-14	SINK ACOUSTICAL COATING, GRAY, ROUGH	A	NF	4	SF
M-FDI-15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M-SLT-16	SEALANT (PENETRATIONS, FLASHINGS), WHITE, PLIABLE	A	NF	200	SF
M-CON-17	CONCRETE, GRAY, CEMENTITIOUS	A	NF	100	SF
M-CON-18	CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	A	NF	750	SF
M-SLT-19	SEALANT (MECHANICAL), GRAY, PLIABLE	A	NF	5	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R9/R11*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-ACT-01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	S	F	1,900	SF
M-ADH-02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	A	NF	200	SF
S-SAT-03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,200	SF
M-GWB-04	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,200	SF
S-JTC-05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	S	NF	220	SF
M-TWP-06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-ADH-07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-CPT-08	CARPET, GRAY, FIBROUS, RED AND BROWN SPECKS	A	NF	1,800	SF
M-MAS-09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, RED AND BROWN SPECKS	A	NF	1,800	SF
M-VCT-10	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	150	SF
M-MAS-11	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	150	SF
M-WAB-12	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-ADH-13	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-SLT-14	SEALANT (DOORS, WINDOWS, FIXTURES, MILLWORK), WHITE, PLIABLE	A	NF	25	SF
M-SAC-15	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M-FDI-16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M-SLT-17	SEALANT (WINDOWS), BLACK, TAR-LIKE	A	NF	10	SF
S-SAT-18	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,250	SF
M-GWB-19	GYPSTUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,250	SF
S-JTC-20	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSTUM WALLBOARD, WHITE, CHALKY	A	NF	125	SF
M-SLT-21	SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	A	NF	200	SF
M-VSF-22	VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	S	NF	300	SF
M-MAS-23	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	S	NF	300	SF
M-CON-24	CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	A	NF	750	SF
M-APR-25	ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	1,800	SF
M-MAS-26	MASTIC (PENETRATIONS, FLASHINGS), BLACK, TAR-LIKE	A	NF	180	SF
M-SLT-27	SEALANT (MECHANICAL), GRAY, PLIABLE	A	NF	5	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
Portable R10/R12*

JOB NO. 07-367

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MATERIAL CODE	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M-ACT-01	ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	S	F	1,600	SF
M-ADH-02	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH ACOUSTICAL CEILING TILE, 1'X1', GRAY, CRATERED, WHITE	A	NF	1,600	SF
S-SAT-03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,500	SF
M-GWB-04	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	2,500	SF
S-JTC-05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	S	NF	250	SF
M-TWP-06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-ADH-07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL COVER	A	NF	1,400	SF
M-CPT-08	CARPET, BLUE, FIBROUS, RED AND BROWN SPECKS	A	NF	1,800	SF
M-MAS-07	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, RED AND BROWN SPECKS	A	NF	1,800	SF
M-VCT-10	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	150	SF
M-MAS-11	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN AND WHITE MOTTLES	A	NF	150	SF
M-WAB-12	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-ADH-13	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	100	SF
M-SLT-14	SEALANT (DOORS, WINDOWS, FIXTURES, MILLWORK), WHITE, PLIABLE	A	NF	25	SF
M-SAC-15	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M-FDI-16	FIRE DOOR INSULATION, METAL CLADDING	A	NF	105	SF
M-SLT-17	SEALANT (WINDOWS), BLACK, TAR-LIKE	A	NF	10	SF
S-SAT-18	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,250	SF
M-GWB-19	GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,250	SF
S-JTC-20	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	A	NF	125	SF
M-SLT-21	SEALANT (PENETRATIONS, FLASHINGS, SEAMS), WHITE, PLIABLE	A	NF	200	SF
M-VSF-22	VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	S	NF	300	SF
M-MAS-23	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLE PATTERN, GRAY PAPER BACKING	S	NF	300	SF
M-CON-24	CONCRETE (SIDEWALKS), GRAY, CEMENTITIOUS	A	NF	750	SF
M-APR-25	ASPHALT PREPARED ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	180	SF
M-MAS-26	MASTIC (PENETRATIONS, FLASHINGS), BLACK, TAR-LIKE	A	NF	1,800	SF

END OF TABLE

2.7 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **NINE** friable suspect ACBM (acoustical ceiling panels and acoustical ceiling tile) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.8 Sample Collection

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
Main	62 (50 Assumed)	36
Multi-Purpose	71 (59 Assumed)	36
Portable R1/R3	19 (13 Assumed)	18
Portable R2/R4	19 (13 Assumed)	18
Portable R5/R7	19 (18 Assumed)	3
Portable R6/R8	19 (18 Assumed)	3
Portable R9/R11	27 (21 Assumed)	18
Portable R10/R12	26 (20 Assumed)	18
TOTAL	262	150

Suspect ACM Designation and Sample Record Forms are presented in Appendix A.

2.9 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

Report of Findings

Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School, KSD
FM Project 07-367

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.

END OF REPORT

APPENDIX A

Suspect Asbestos-Containing Material Designation and Sample Record Forms

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MAR-01 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x2'

Matrix/Primary Color: GRAY Texture/Pattern: FLATTENED AND FLAKES Cover/Secondary Color: WHITE
 Quantity of Material: 43,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A <u>B30</u>		NE Corner	0' W	0' S	10'	F / W / C / O
B <u>B21</u>		SW Corner	0' E	0' N	10'	F / W / C / O
C <u>B53</u>		NW Corner	0' E	20' S	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: 5-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 36,000 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	NZ	NE Corner	Z'W	0'S	2'	F/W/C/O
B	B45	NW Corner	7'E	0'S	10'	F/W/C/O
C	B1A	NE Corner	0'W	0'S	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____
 Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: 41-GNB-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALLBOARD Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 36,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	NZ	NE Corner	2' W	0' S	2'	F/W/C/O
B	B45	NW Corner	7' E	0' S	10'	F/W/C/O
C	B19	NE Corner	0' W	0' S	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH S.SAF.02

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-1111-04 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 3600 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	N2	NE Corner	2' W	0' S	2'	F / W / C / O
B	B45	NW Corner	7' E	0' S	10'	F / W / C / O
C	B19	NE Corner	0' W	0' S	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.G.N.S.-03

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: B11A040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.C.A.05 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FIBROUS Cover/Secondary Color: BLUE AND TAN SPECKS
 Quantity of Material: 40,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.M.B.O.C. Damaged: Yes No Friable Non-Friable
 General Description: WASTE Visible Covered Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 2000 (SF) LF / EA Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P. 05

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VET-07 Damaged: Yes No Friable Non-Friable
 General Description: SINGLE COMPOSITION TILE Size: 12" X 12"
 Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: BROWN MOTICLES
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA Michael Richter State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes *ASSUMED*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-11A-08 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A

Matrix/Primary Color: Yellow Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure
 Texture/Pattern: TACKY

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.E.I.07

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MWAB-09 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Size: 4"

Matrix/Primary Color: BLUE Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Richter Inspector: Michael Richter
 AHERA Certificate No.: BJA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.A.D.H. 10 Visible Covered WAB Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.W.A.B. OR

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIJA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MSAC.11 Damaged: Yes No Friable Non-Friable
 General Description: SINK ACOUSTICAL COATING Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 36 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-515-12 Damaged: Yes No Friable Non-Friable

General Description: SEAMANT (DOORS/WINDOWS/MILLWORK) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: 250 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.S.L.T. 13 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (MILLWORK) Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MFD-14 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Visible Covered Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 672 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WFDI-15 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 756 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-16 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	W14	SE Corner	0'W	3'N	4'	F/W/C/O
B	E100	SW Corner	0'E	0'N	10'	F/W/C/O
C	B05	NW Corner	0'E	0'S	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MGWB-17 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wall Board Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	W14	SE Corner	0' W	3' N	4'	F/W/C/O
B	Z104	SW Corner	0' E	0' N	10'	F/W/C/O
C	B05	NW Corner	0' E	0' S	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH SSAT.10

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S.JTC.18 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled Assumed
 LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	W14	SE Corner	0'W	3'N	4'	F/W/C/O
B	E100	SW Corner	0'E	0'N	10'	F/W/C/O
C	B05	NW Corner	0'E	0'S	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH W.GWB.17

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MGR-19 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4" x 4"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MGR-20 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 20 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.GUST. 19

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790 AHERA Certificate No.: State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MCMR-21 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSAIC TILE Size: 2" X 2"

Matrix/Primary Color: TAN Cover/Secondary Color: PEPPERED
 Quantity of Material: 900 Estimated By: Drawing Field Measure
 Texture/Pattern: SMOOTH

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GRS-22 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.F. Z1

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: W-WAB-23 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Visible Covered Size: 4"

Matrix/Primary Color: GRAY Texture/Pattern: VIAJAL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FMA
GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WADH.24 Damaged: Yes No Friable Non-Friable
 Visible Covered WAB Size: N/A

General Description: ADHESIVE

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A

Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other


Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH WADH.23

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED



SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-TWR-25 Damaged: Yes No Friable Non-Friable
 General Description: TACKABLE WALL PANEL Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: Fibrous Cover/Secondary Color: VINYL COVER
 Quantity of Material: 800 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FMA
GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.A.D.H. 26 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 800 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.T.W.P.-25

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-27 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	W10Z	SE Corner	0' W	0' N	10'	F (W) / C / O
B	E10Z	NW Corner	0' E	0' S	10'	F (W) / C / O
C	N1B	NE Corner	0' W	0' S	10'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.GNB.2B Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wall board Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	W102	SE Corner	0'	0'	10'	F/W/C/O
B	E102	NW Corner	0'	0'	10'	F/W/C/O
C	N1B	NE Corner	0'	0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: ASSOCIATED WITH S.SAF.27

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-29 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	W102	SE Corner	0' W	0' N	10'	F / W / C / O
B	E102	NW Corner	0' E	0' S	10'	F / W / C / O
C	N1B	NE Corner	0' W	0' S	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. GUNB. 2B

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MCON30 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 45.000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MICINA: 31 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT Size: 8" x 16"
 Visible Covered

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.M.B.32 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.CMU.31

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 2/06/08 Signature: _____ Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MADH33 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered FRP Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.G. 07.34 Damaged: Yes No Friable Non-Friable
 General Description: GRAZED WALL TILE Size: 4' x 4'

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GR-35 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GUST-34

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MBT-30 Damaged: Yes No Friable Non-Friable
 General Description: SEAMANT (WINDOWS) Visible Covered Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 20 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.G.W.G. 37 Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL VICE Size: 4"x4"

Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: W.G.R. 38 Damaged: Yes No Friable Non-Friable
 General Description: GRout Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W.G.W.F. 37

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.M.R. 39 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH GLASS BLOCK, 8'x8", CLEAR

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax



FIM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: W.SAC.40 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SINK ACOUSTICAL COATING Cover/Secondary Color: N/A

Matrix/Primary Color: GRAY Texture/Pattern: ROUGH Estimated By: Drawing Field Measure
 Quantity of Material: 30 SE / LF / EA Sampling Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-507-41 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FIRE STOP) Size: N/A

Matrix/Primary Color: RED Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: [Signature] Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: NA 100-42 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION FLOOR Size: 2'x12'

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: BROWN MARBLES
 Quantity of Material: 350 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MWAS-43 Damaged: Yes No Friable Non-Friable
 General Description: MASIC Visible Covered Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 350 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.C.T. 42

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MGRB-44 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 7500 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR B24	SE Corner	0' W	0' N	12'	F / W / C / O
B	CORRIDOR B33	SW Corner	0' E	0' N	12'	F / W / C / O
C	CORRIDOR B44	SE Corner	10' W	0' N	12'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 Date: 2/06/08
 Michael Richter State License: EPA Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FMA
GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-3TC-45 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR B24	SE Corner	0' W	0' N	12'	F / W / C / O
B	CORRIDOR B33	SW Corner	0' E	0' N	12'	F / W / C / O
C	CORRIDOR B44	SE Corner	10' W	0' N	12'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M. GUNB. 44

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: [Signature] Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-46 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (DOUBLE T'S) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A
 Quantity of Material: 130,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 Date: 2/06/08
 Michael Richter State License: EPA AHERA Certificate No.: D10Z90 Date: 2/06/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: SPLA-47 Damaged: Yes No Friable Non-Friable
 General Description: PLASTER Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTARIOUS Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.P.E.S.A.B Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.BOL-49 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY MINERAL CAP
 Quantity of Material: 3500 Estimated By: Drawing Field Measure
 Sampling Random Convenience N/A

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10799 State License: EPA
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.BUR.50 Damaged: Yes No Friable Non-Friable
 General Description: BUILT UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: METAL CAP
 Quantity of Material: 40,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M11A5.S1 Damaged: Yes No Friable Non-Friable
 General Description: MASONIC (PENETRATIONS AND FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 1002 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-AT-52 Damaged: Yes No Friable Non-Friable
 General Description: PAINT (PENETRATIONS AND FLASINGS) Size: N/A

Matrix/Primary Color: SILVER Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.BUR.53 Damaged: Yes No Friable Non-Friable
 General Description: BUILDUP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPLASTIC Cover/Secondary Color: SILVER COATING
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-STU-S4 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 10000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-5LX-55 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (PARAPET WALLS/FASHING) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: BUBBLE Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MPES-50 Damaged: Yes No Friable Non-Friable
 General Description: FRE END SEALANT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: SPITTLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CMU-57 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY WORK Size: 8" x 16"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color:
 Quantity of Material: 10000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M1.MR.58 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.A. 57

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: McCon 59 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (SIDEWALKS) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A

Quantity of Material: 20000 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman

Inspector: Michael Richter

AHERA Certificate No.: BIIA040907-01

AHERA Certificate No.: D10790

State License: EPA

Signature: *Michael Coleman*

Date: 2/06/08

Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SIT-60 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS) Visible Covered Size: N/A

Matrix/Primary Color: TAN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 35 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: [Signature] Date: 2/06/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 Fax

FVM
GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: W. EXS. 601 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M. GAS Col Damaged: Yes No Friable Non-Friable
 General Description: GASKETS Visible Covered Size: 8"

Matrix/Primary Color: BLACK Texture/Pattern: PAPER LIKE Cover/Secondary Color: N/A

Quantity of Material: 2 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-AP-01 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x2'

Matrix/Primary Color: GRAY Texture/Pattern: PINHOLES AND FISSURES Cover/Secondary Color: WHITE

Quantity of Material: 5500 Estimated By: Drawing Sampled Assumed
 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ART ROOM E10	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	PE STORAGE E16	NW Corner	E 0'	S 0'	8'	F / W / C / O
C	STORAGE E20	SE Corner	W 0'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAF-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 10000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC EO9	NE Corner	W 0'	S 2'	4'	F/W/C/O
B	STORAGE E2L	NW Corner	E 0'	S 0'	8'	F/W/C/O
C	STORAGE E2D	NW Corner	E 0'	S 8'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GNB-03 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 10,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC EO9	NE Corner	W 0'	S 2'	4'	F / W / C / O
B	STORAGE E24	NW Corner	E 0'	S 0'	8'	F / W / C / O
C	STORAGE E20	NW Corner	E 0'	S 8'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S-SAT-02

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-VTC-04 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPARTMENT Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1 DOO (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MUSIC E09	NE Corner	W 0'	S 2'	4'	F / W / C / O
B	Storage E26	NW Corner	E 0'	S 0'	8'	F / W / C / O
C	STORAGE E20	NW Corner	E 0'	S 8'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GUYS-03

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-TN-POS Damaged: Yes No Friable Non-Friable
 General Description: TACKLE WALL PANEL Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WADH06 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BEETLE Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH WADH05

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MCR-07 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: BLUE AND YELLOW STRIPS
 Quantity of Material: 1700 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC.

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M1MAS08 Damaged: Yes No Friable Non-Friable
 General Description: MASATC Visible Covered CPG Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 1700 (SF) LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MCPY.07

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BJIA040907-01 State License: EPA AHERA Certificate No.: D10799 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" X 12"

Matrix/Primary Color: PINK Texture/Pattern: SMOOTH Cover/Secondary Color: WHITE AND BROWN MOTIFES
 Quantity of Material: 700 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-NAS-10 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 700 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VCT-03

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MWAB-1 Visible Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Covered Size: 4"

Matrix/Primary Color: GRAY Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A
 Quantity of Material: 400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MADH-12 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered WAB Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: P/BLE Cover/Secondary Color: N/A

Quantity of Material: 400 Estimated By: Drawing Sampled
 LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-WAB-11

Inspector: Michael Coleman Inspector: Michael Richter

AHERA Certificate No.: B11A040907-01 State License: EPA

State License: EPA

Signature: *Michael Coleman* Date: 2/06/08

Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SE-13 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (Doors, windows, millwork, fixtures) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FLAKE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MSAC-14 Visible Damaged: Yes No Friable Non-Friable
 General Description: SINK ACOUSTICAL COATING Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: ROUGH Cover/Secondary Color: N/A
 Quantity of Material: 0 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MF01-15 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: WOOD CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 357 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MFD1-10 Visible Damaged: Yes No Friable Non-Friable
 Covered Size: N/A

General Description: FIRE DOOR INSULATION

Matrix/Primary Color: N/A Texture/Pattern: METAL CLADD. NS Cover/Secondary Color: N/A

Quantity of Material: 525 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B1A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.M.R. 17 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 100 (SP) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH GLASS BLOCK, 8" X 8", CLEAR

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-15418 Damaged: Yes No Friable Non-Friable
 General Description: VINYL STAIR TREAD Visible Covered Size: 12" x 36"

Matrix/Primary Color: BROWN Texture/Pattern: VINYL LIXE Cover/Secondary Color: CIRCLE PATTERN
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.ADX-19 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered VST Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FLOCKY Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.VST.18 and M-WAIB-71

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCF-20 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" X 12"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: BROWN MATTE
 Quantity of Material: 2600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MMAAS-21 Damaged: Yes No Friable Non-Friable
 General Description: MASIC Visible Covered Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.C.S. 20

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: B11A040907-01 State License: EPA
 Signature: [Signature] Date: 2/06/08 Inspector: Michael Richter State License: EPA
 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ACT-22 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING TILES Size: 1'x1'

Matrix/Primary Color: GRAY Texture/Pattern: PINKHOLES AND FISSURES Cover/Secondary Color: WHITE
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR EOZ	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	CORRIDOR EOZ	SE Corner	W 0'	N 0'	8'	F / W / C / O
C	STAGE E 11	NW Corner	E 10'	S 12'	16'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MADH23 Damaged: Yes No Friable Non-Friable
 Visible Covered ACT Size: N/A

General Description: ADHESIVE Estimated By: Drawing Field Measure Sampled Assumed
 Matrix/Primary Color: BROWN Cover/Secondary Color: N/A

Quantity of Material: 300 Texture/Pattern: BRITTLE
 Homogeneous Material Location: Ceiling Floor Wall Other
 SF / LF / EA Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH WALLS

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CMK-24 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE MASONRY UNIT Size: 8" X 16"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 5000 (SF) / LF / EA Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: _____ Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-NR-25 Damaged: Yes No Friable Non-Friable
 General Description: MORTAR Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.CMU-24, M.CMU-36, M.CMU-37

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAG-20 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY APPLIED TEXTURE Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1300 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR E02A	SW Corner	E 0'	N 0'	8'	F/W/C/O
B	ELECTRICAL E27	SW Corner	E 7'	N 0'	4'	F/W/C/O
C	ELECTRICAL E25	SW Corner	E 0'	N 0'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.GWB.27 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKL Cover/Secondary Color: N/A
 Quantity of Material: 1300 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR E02A	SW Corner	E 0'	N 0'	8'	F / W / C / O
B	ELECTRICAL E27	SW Corner	E 7'	N 0'	4'	F / W / C / O
C	ELECTRICAL E25	SW Corner	E 0'	N 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.26

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-KC-28 Visible Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 130 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR EOZA	SW Corner	E 0'	N 6'	8'	F / W / C / O
B	ELECTRICAL E 27	SW Corner	E 7'	N 6'	4'	F / W / C / O
C	ELECTRICAL E 25	SW Corner	E 0'	N 6'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.N.S.B. 27

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-Pes-29 Damaged: Yes No Friable Non-Friable
 General Description: PIPE END SEALANT Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 10 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GAS-30 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: GASKET Size: 6"

Matrix/Primary Color: BLACK Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A
 Quantity of Material: 8 Estimated By: Drawing Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.GAS.31 Damaged: Yes No Friable Non-Friable
 General Description: GASKET Visible Covered Size: 8" N

Matrix/Primary Color: BLACK Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: 41-CON-3Z Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE Size: N/A
 Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 17,100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Tempe, AZ 85284

Material Code: M-SLT-33 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SEALANT (DOORS / EXPANSION) Size: N/A

Matrix/Primary Color: TAN Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: 550034 Damaged: Yes No Friable Non-Friable
 General Description: STUCCO Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A

Quantity of Material: 5000 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter

AHERA Certificate No.: BIIA040907-01 State License: EPA

State License: EPA

Signature: *Michael Coleman* Date: 2/06/08

Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-35 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (EQUIPMENT) Visible Covered Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: FLAKE LIKE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MCM-30 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 8" x 16"

General Description: CONCRETE MASONRY UNIT Cover/Secondary Color: 2" x 8" SQUARE PATTERN
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Estimated By: Drawing Field Measure
 Quantity of Material: 14,700 (SF) / LF / EA Sampling Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.C.M.U. 37 Damaged: Yes No Friable Non-Friable

General Description: CONCRETE MASONRY W/IKR Size: 8" X 8" 1"

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A

Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWT-38 Visible Damaged: Yes No Friable Non-Friable
 General Description: GLAZED WALL TILE Size: 4"x4"

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Assumed
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWT-39 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 250 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-38, M-GWT-50

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.SLT.40 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (MECHANICAL) Size: N/A
 Matrix/Primary Color: WHITE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790
 Signature: *Michael Richter* Date: 2/06/08
 Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MAPL-41 Damaged: Yes No Friable Non-Friable
 General Description: ACOUSTICAL CEILING PANEL Size: 2'x2'
 Visible Covered

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: INKY COVER

Quantity of Material: 500 Estimated By: Drawing Field Measure
 Sampling Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Kitchen E18	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	Kitchen E18	SW Corner	E 0'	N 0'	8'	F / W / C / O
C	Kitchen E18	NE Corner	W 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter

AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA

Signature: *[Signature]* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MADK-LZ Visible Covered FRP Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH FIBERGLASS REINFORCED PANELING, WHITE, TEXTURED

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.Q.P.A. 43 Visible Covered: Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: QUARRY/PAVER TILE Size: 6" X 6"

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampling Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.GRT.44 Damaged: Yes No Friable Non-Friable
 General Description: GRAB Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATION Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.O.P. 43

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED



SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.C.P. 445 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: FIBROUS Cover/Secondary Color: N/A

Quantity of Material: 300 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter

AHERA Certificate No.: B11A040907-01 State License: EPA

State License: EPA

Signature: *[Signature]* Date: 2/06/08

Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.MAS-460 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASOTC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: YACKY Cover/Secondary Color: N/A
 Quantity of Material: 300 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.R. 45

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: 55AT.417 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Boys Restroom E04	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	Girls Restroom EZZ	NW Corner	E 0'	S 0'	8'	F / W / C / O
C	Bathroom A09	NE Corner	W 0'	E 2'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MGRB.48 Damaged: Yes No Friable Non-Friable
 General Description: GYPSUM WALL BOARD Visible Covered Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1300 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Boys Restroom E04	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	GIRLS Restroom EZZ	NW Corner	E 0'	S 0'	8'	F / W / C / O
C	Bathroom A09	NE Corner	W 0'	E 2'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH SSAT.47

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: SJTC-49 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Visible Covered SAK Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 130 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Boys Restroom E04	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	Girls Restroom E22	NW Corner	E 0'	S 0'	8'	F / W / C / O
C	Bathroom A09	NE Corner	W 0'	E 2'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.G.W.B. 4B

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWT-50 Damaged: Yes No Friable Non-Friable
 General Description: GRADED WALL TILE Size: 2" X 2"

Matrix/Primary Color: BROWN Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SAC-SI Damaged: Yes No Friable Non-Friable
 General Description: SINK ACOUSTICAL COATING Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Richter Inspector: Michael Richter
 AHERA Certificate No.: BJJ1040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-52 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" x 12"

Matrix/Primary Color: WHITE Texture/Pattern: SMOOTH Cover/Secondary Color: GRAY MOTILES
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-101-53 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (STRIP) Size: 2'x24"

Matrix/Primary Color: BLACK Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCS-54 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (SHEAP) Size: 2'x2'4"

Matrix/Primary Color: RED Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VT-55 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (SIPAR) Size: 2" X 24"

Matrix/Primary Color: BLUE Texture/Pattern: SMOOTH Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-50 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (STRIP) Size: 2' X 24"

Matrix/Primary Color: GREEN Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-57 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE (SCRIP) Size: 2'x24"

Matrix/Primary Color: Yellow Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-5B Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 24" x 24"

Matrix/Primary Color: RED Texture/Pattern: VINYL-LIKE Cover/Secondary Color: CIRCLE PATTERN
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-59 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FLAKES Cover/Secondary Color: N/A
 Quantity of Material: 2300 Estimated By: Drawing Sampling Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.V.C.T. 52, M.V.C.T. 53, M.V.C.T. 54, M.V.C.T. 55, M.V.C.T. 56, M.V.C.T. 57, M.V.C.T. 58

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9286 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAB-00 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Visible: Covered: Size: 4"

Matrix/Primary Color: BLUE Texture/Pattern: VINYL LIKE Cover/Secondary Color: N/A
 Quantity of Material: 100 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH:G1 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FRIABLE Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.WAB.CO

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.C.M.T. 002 Damaged: Yes No Friable Non-Friable
 General Description: CERAMIC MOSIAC TILE Visible Covered Size: 2' X 2'

Matrix/Primary Color: TAN Texture/Pattern: SMOOTH Cover/Secondary Color: PEPPERED

Quantity of Material: 700 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.G.R.T. 603 Damaged: Yes No Friable Non-Friable
 General Description: GRUITS Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTitious Cover/Secondary Color: N/A
 Quantity of Material: 70 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.M.T. 62

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



FM GROUP/forms/SuspACMDesignRecord.ortf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M. BURLCOY Material Code: Visible Damaged: Yes No Friable Non-Friable
 General Description: BUILT UP ROOFING Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: GRAY MINERAL CAP
 Quantity of Material: 17000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-65 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS AND FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 7SD Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10799 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-606 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHINGS) Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 50 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-PNF-67 Damaged: Yes No Friable Non-Friable
 General Description: PAINT PENETRATIONS AND FLAKINGS Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.A.T.-CB Damaged: Yes No Friable Non-Friable
 General Description: PAINT PENETRATIONS AND FLASHINGS Size: N/A
 Matrix/Primary Color: SILVER Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-COV-69 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE (ENTRIES) Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 15000 Estimated By: Drawing Field Measure
 Texture/Pattern: CEMENTITIOUS

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D19790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MC070 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTATIONS Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Multi-Purpose Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Tempe, AZ 85284

Material Code: M-WAB.71 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 12"

General Description: WALL BASE (STRAIGHT) Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Matrix/Primary Color: BROWN Estimated By: Drawing Field Measure
 Quantity of Material: 12 SF / LF / EA Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-AP-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 4'
 Matrix/Primary Color: GRAY Texture/Pattern: P.Holes + Fissures Cover/Secondary Color: White
 Quantity of Material: 2000 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-1	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	Classroom R-1	SW Corner	E 0'	N 0'	8'	F / W / C / O
C	Classroom R-3	NW Corner	E 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2700 Estimated By: Drawing Field Measure Sampled Assumed
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-1	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	Classroom R-1	SE Corner	W 0'	N 0'	10'	F/W/C/O
C	Classroom R-3	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Mich Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWS-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2700 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-1	NW Corner	E 0'	S 0'	10'	F/W/C/O
B	CLASSROOM R-1	SE Corner	W 0'	N 0'	10'	F/W/C/O
C	CLASSROOM R-3	NW Corner	E 0'	S 0'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-SAT-02

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-04 Material: Visible Covered SAT Damaged: Yes No Friable Non-Friable

General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 270 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-1	NW Corner	EO'	SO'	10'	F / W / C / O
B	Class room R-1	SE Corner	WO'	NO'	10'	F / W / C / O
C	Class room R-1	NW Corner	EO'	SO'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Visible Covered Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 400 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790
 Signature: *Michael Coleman* Date: 2/06/08
 State License: EPA Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-06 Material Description: Adhesive
 Visible Covered TWP Damaged: Yes No Friable Non-Friable
 Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 1400 Estimated By: Drawing Field Measure Sampled Assumed
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-04

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: 2 1/4'

Matrix/Primary Color: Grey Texture/Pattern: Fibrous Cover/Secondary Color: Blue + Tan Spacks
 Quantity of Material: 2100 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered CPT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACIMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Visible Covered Size: 12 x 12

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Gray Mottles
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.0mf

Project No.: 07-367 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-10 Visible Covered VCT Damaged: Yes No Friable Non-Friable
 General Description: Mastic Texture/Pattern: Tacky Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: Yellow Estimated By: Drawing Field Measure
 Quantity of Material: 150 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Michael Richter Inspector: Michael Richter
 AHRA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (cont) Visible Covered Size: 4"

Matrix/Primary Color: Brown Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-12 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A

Matrix/Primary Color: cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 100 (SF / LF / EA) Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Coleman Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord1.omf

Project No.: 07-367 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-F01-13 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Fire Door Insulation
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHIERA Certificate No.: BIIA040907-01 State License: EPA AHIERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord1.cmf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Doors/Windows/Millwork) Visible Covered
 Matrix/Primary Color: White Texture/Pattern: Plaster Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B1A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesigRecord1.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SAC-15 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecordL.mf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWB-16 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Gypsum wallboard
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 2250 Estimated By: Drawing Sampled Assumed
 Texture/Pattern: Chalky
 SF / LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-1	SW Corner	E 0'	N 0'	10'	F / W / C / O
B	CLASSROOM R-1	NE Corner	W 0'	S 0'	10'	F / W / C / O
C	CLASS ROOM R-3	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-17 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Joint Compound
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 225 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-1	SW Corner	E 0'	N 0'	10'	F / W / C / O
B	Classroom R-1	NE Corner	W 0'	S 0'	10'	F / W / C / O
C	Classroom R-3	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-16

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9286 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (PENETRATIONS/FLASHINGS/SEAMS) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.orm

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-1/R-3 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: N-CON-19 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (SIDEWALKS) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 750 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2 x 4

Matrix/Primary Color: GRAY Texture/Pattern: Pishes + Fissures Cover/Secondary Color: White

Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-2	NW Corner	E 0'	SO'	8'	F / W / C / O
B	CLASSROOM R-2	SW Corner	E 0'	NO'	8'	F / W / C / O
C	CLASSROOM R-4	NW Corner	E 0'	SO'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 Date: 2/06/08
 Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 2/06/08
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-2	NW Corner	E 0'	S 0'	10'	F (W) / C / O
B	Classroom R-2	SE Corner	W 0'	N 0'	10'	F (W) / C / O
C	Classroom R-4	NW Corner	E 0'	S 0'	10'	F (W) / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-LWB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-2	NW Corner	EO	SO	10'	F/W/C/O
B	CLASSROOM R-2	SE Corner	WO	NO	10'	F/W/C/O
C	CLASSROOM R-4	NW Corner	EO	SO	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-SAT-02

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D40790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-STC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 200 SE / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-2	NW Corner	E 0'	S 0'	10'	F / W / C / O
B	Classroom R-2	SE Corner	W 0'	N 0'	10'	F / W / C / O
C	Classroom R-4	NW Corner	E 0'	S 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Michael Coleman State License: EPA BIIA040907-01 Date: 2/06/08
 Michael Richter State License: EPA D10790 Date: 2/06/08
 AHERA Certificate No.: BIIA040907-01 Signature: [Signature] State License: EPA
 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: W-TWP-08 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Visible Covered Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: VINYL-COVER
 Quantity of Material: 1400 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-02 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Browns Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 1400 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-05

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: B11A040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08

Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed
 Date: 2/06/08

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Visible Covered Size: N/A

Matrix/Primary Color: Grey Texture/Pattern: Fibrous Cover/Secondary Color: Blue + Tan Specks
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered CPT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Michael Coleman State License: EPA BIIA040907-01
 Michael Richter State License: EPA D10790
 Signature: *Michael Coleman* Date: 2/06/08
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Visible Covered Size: 12 x 12

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Gray Mottles
 Quantity of Material: 150 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9286 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-10 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered YCT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ami

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (cove) Visible Covered Size: 4"
 Matrix/Primary Color: Brown Texture/Pattern: Vinyl-like Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Sampled
 Field Measure Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: B1A040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10799 State License: EPA
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85250
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord.rmf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-12 Damaged: Yes No Friable Non-Friable
 General Description: Asbestos Visible Covered WAB Size: N/A

Matrix/Primary Color: cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-FDI-13 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A

Quantity of Material: 84 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (doors/windows/mill work) Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *ASSEMCD*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SAC-15 Damaged: Yes No Friable Non-Friable
 General Description: Silk Acoustical Coating Size: N/A

Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWS-16 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-2	SW Corner	E 0'	N 0'	10'	F / W / C / O
B	Classroom R-2	NE Corner	W 0'	S 0'	10'	F / W / C / O
C	Classroom R4	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: B11A040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D149790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-17 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A

Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 225 S / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-2	SW Corner	E 0'	N 0'	10'	F / W / C / O
B	Classroom R-2	NE Corner	W 0'	S 6'	10'	F / W / C / O
C	Classroom R-4	SE Corner	W 0'	N 0'	10'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWS-16

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Coleman Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-18 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant (PENETRATIONS/FRACTIONS/SEAMS) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-2/R-4 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-19 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (SIDEWALKS) Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure
 Texture/Pattern: Cementitious

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-APL-01 Visible Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x4'

Matrix/Primary Color: GRAY Texture/Pattern: Patches & Fissures Cover/Secondary Color: White
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-5	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	Classroom R-5	SE Corner	W 0'	N 0'	8'	F / W / C / O
C	Classroom R-7	NW Corner	E 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: Michael Coleman Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Richter Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Spray Applied Texture
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2400 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 2/06/08
 Signature: *Michael Coleman* Signature: *Michael Richter*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-6WB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Cover/Secondary Color: N/A
 Quantity of Material: 2400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 240 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Michael Coleman Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CPT-05 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Visible Covered Size: 5/A

Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Red + Tan Specks
 Quantity of Material: 1800 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-06 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered CPT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Jacky Cover/Secondary Color: N/A
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-05

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-07 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: TAN Cover/Secondary Color: Beige + White Mottles
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A
 Texture/Pattern: Smooth
 (SF) / LF / EA

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ornf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-DS Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-07

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assemd*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Staircase (Doors/Windows/Millwork) Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D19790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAB-10 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (covered) Visible Covered Size: 4"

Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-11 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered WAB Size: N/A
 Matrix/Primary Color: Green Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-10

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesigRecord.ortf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-TWP-12 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Visible Covered Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: NINYL COVER
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-13 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered TWP Size: N/A

Matrix/Primary Color: Browns Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-12

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SAC-14 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Visible Covered Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-FDI-15 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Sampled
 SF / LF / EA Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10799 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes *ASSUMED*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FMI
GROUP INC

Project No.: 07-367 Project Name: ASHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (PENETRATIONS/FLASHINGS/SEAMS) Size: N/A
 Matrix/Primary Color: White Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Texture/Pattern: Flake LF / EA LF / EA N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 ASHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-17 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 120 Estimated By: Drawing Field Measure
 Texture/Pattern: Cementitious

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-19 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (SIDEWALKS) Size: N/A

Matrix/Primary Color: Grey Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-5/R-7 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (MECHANICAL) Visible Covered
 Matrix/Primary Color: GRAY Texture/Pattern: RIABLE Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x4'

Matrix/Primary Color: Gray Texture/Pattern: Pinholes and fissures Cover/Secondary Color: White
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-6	NW Corner	E 2'	S 4'	8'	F / W / C / O
B	Classroom R-6	SE Corner	W 2'	N 4'	8'	F / W / C / O
C	Classroom R-8	NW Corner	E 2'	S 4'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED CEILING TEXTURE Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 2400 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord1.mrf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: 41-GAJB-03 Damaged: Yes No Friable Non-Friable
 General Description: GIPSUM WALL BOARD Visible Covered SAT Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 2400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH S.SAT.02

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

16874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-DIC-04 Damaged: Yes No Friable Non-Friable
 General Description: DIRT COMPOUND Visible Covered Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: CRACKY Cover/Secondary Color: N/A
 Quantity of Material: 240 Estimated By: Drawing Sampled Assumed
 LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M'GNB-03

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.P.R.05 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Visible Covered Size: N/A

Matrix/Primary Color: BLUE Texture/Pattern: FIBROUS Cover/Secondary Color: RED AND TAN SPECKS
 Quantity of Material: 1600 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-NAS-00 Damaged: Yes No Friable Non-Friable
 General Description: MASIC Visible Covered CP Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M.C.P.O.S

Inspector: Michael Coleman Inspector: Michael Richter
 AHRA Certificate No.: BIIA040907-01 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.VCF.07 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 12" X 12"

Matrix/Primary Color: TAN Texture/Pattern: SMOOGEA Cover/Secondary Color: BROWN AND WHITE MOTTLES
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WAS-08 Damaged: Yes No Friable Non-Friable
 General Description: WAS-08 Visible Covered Size: N/A

Matrix/Primary Color: YELLOW Texture/Pattern: FLACKY Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH MNCST-07

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.S.T.09 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (DOORS/WINDOWS/MILLWORK) Size: N/A
 Matrix/Primary Color: WHITE Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAB-10 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Visible Covered Size: 4"

Matrix/Primary Color: BLUE Texture/Pattern: VINYL-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WADH.11 Damaged: Yes No Friable Non-Friable
 General Description: ADHESIVE Visible Covered WAB Size: N/A

Matrix/Primary Color: CREAM Texture/Pattern: FLAKE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH W. WAB. 10

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MTAP.12 Damaged: Yes No Friable Non-Friable
 General Description: TACKLE WALL PANEL Visible Covered Size: N/A

Matrix/Primary Color: DOWN Texture/Pattern: FIBROUS Cover/Secondary Color: VINYL COVER
 Quantity of Material: 1200 Estimated By: Drawing Sampled Assumed
 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADA-13 Damaged: Yes No Friable Non-Friable
 General Description: ADAE BIVE Covered Visible Size: N/A

Matrix/Primary Color: BROWN Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 1200 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-TWR.12

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.SAC-14 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Bulk Acoustical Coating

Matrix/Primary Color: GRAY Texture/Pattern: ROUGH Cover/Secondary Color: N/A

Quantity of Material: 4 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10799 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WFDI.15 Damaged: Yes No Friable Non-Friable
 General Description: FIRE DOOR INSULATION Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: METAL CLADDING Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: B11A040907-01 State License: EPA
 Signature: [Signature] Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SET-14 Damaged: Yes No Friable Non-Friable

General Description: SEALANT (PENETRATIONS/FLASHING) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: PULVER Cover/Secondary Color: N/A

Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-17 Damaged: Yes No Friable Non-Friable
 General Description: CONCRETE Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-18 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (Sidelwalks) Visible Covered Size: N/A

Matrix/Primary Color: Gray Cover/Secondary Color: N/A
 Quantity of Material: 750 Texture/Pattern: Cementitious Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: P10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-6/R-8 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: WSET-19 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (MECHANICAL) Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: FLAKY Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ACI-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Tile Size: 1' x 1'

Matrix/Primary Color: GRAY Texture/Pattern: Cracked Cover/Secondary Color: White
 Quantity of Material: 1900 Estimated By: Drawing Sampled Assumed
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-9	NW Corner	E 0'	S 0'	8'	F / W / C / O
B	CLASSROOM R-9	SE Corner	W 0'	N 0'	8'	F / W / C / O
C	CLASSROOM R-11	NW Corner	E 0'	S 0'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA D10790
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-02 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered ACT Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-ACT-01

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assembled*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-03 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Visible Covered Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-9	NW Corner	E 2'	S 0'	1'	F/W/C/O
B	Classroom R-9	SE Corner	W 6'	N 0'	1'	F/W/C/O
C	Classroom R-11	NW Corner	E 2'	S 0'	1'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Mich Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWS-04 Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 2200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-9	NW Corner	E 2'	S 0'	1'	F/W/C/O
B	Classroom R-9	SE Corner	W 6'	N 0'	1'	F/W/C/O
C	Classroom R-11	NW Corner	E 2'	S 0'	1'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with J-SAT-04

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Coleman Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9286 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: D-372-05 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-9	NW Corner	E21	S0'	1'	F/W/C/O
B	Classroom R-9	SE Corner	W6'	N0'	1'	F/W/C/O
C	Classroom R-11	NW Corner	E21	S0'	1'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-06

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-TWP-06 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Visible Covered Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: VINYL COVER
 Quantity of Material: 1400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7677
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADA-07 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered TWP Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 1400 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-08

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CPT-08 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Visible Covered Size: N/A

Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Red + Brown Specks
 Quantity of Material: 1800 (SF / LF / EA) Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord1.pdf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-09 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered CPT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-08

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-UCF-10 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: Brown & White Mattes
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAS-11 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-10

Inspector: Michael Coleman Inspector: Michael Richter
 AHRA Certificate No.: B11A040907-01 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: _____ Signature: _____ Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WA13-12 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Visible Covered Size: 4"

Matrix/Primary Color: BLUE Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-13 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Covered Visible Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-12

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assessed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SGF-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (DOORS/WINDOWS/FIXTURES/MILLWORK) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: W-SAC-15 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Ceiling Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Coleman Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FVM
 GROUP INC

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-FD-16 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 105 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (windows) Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHRA Certificate No.: BIIA040907-01 State License: EPA AHRA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-18 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes *Assembled*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWB-19 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-18

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-20 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 125 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6WB-19

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-21 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (PENETRATIONS FLASHINGS SEAMS) Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHRA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-USF-22 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Sheet Flooring Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Gray Marble Pattern
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Boys Restroom	NW Corner	E 0'	S 0'	0'	F/W/C/O
B	Boys Restroom	NE Corner	W 0'	S 0'	0'	F/W/C/O
C	Boys Rest Room	SE Corner	W 0'	N 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: GRAY Paper Backing

Inspector: Michael Coleman Inspector: Michael Richter
 AHRA Certificate No.: BIIA040907-01 State License: EPA D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-23 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered VSF Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 300 SP / LF / EA Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Boys Restroom	NW Corner	E 0'	S 0'	0'	F / W / C / O
B	Boys Restroom	NE Corner	W 0'	S 0'	0'	F / W / C / O
C	Boys Restroom	SE Corner	W 0'	N 0'	0'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VSF-22

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-24 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (sidewalks) Visible Covered Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACM/DesignRecord.0mf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.A.P.E. 25 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT PAVED ROOFING (ROLLED) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: ASBESTIC Cover/Secondary Color: GRAY MINERAL CAP
 Quantity of Material: 1000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-NAS-26 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS AND FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAR-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 180 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-9/R-11 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-27 Damaged: Yes No Friable Non-Friable
 General Description: SEAM (MECHANICAL) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: FRIABLE Cover/Secondary Color: N/A
 Quantity of Material: 5 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ACI-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Tile Size: 1' x 1'

Matrix/Primary Color: Gray Texture/Pattern: Cracked Cover/Secondary Color: White
 Quantity of Material: 1600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-10	NW Corner	E 1'	S 0'	8'	F/W/I/O
B	Classroom R-10	SW Corner	E 1'	S 0'	8'	F/W/I/O
C	Classroom R-12	NW Corner	E 1'	S 0'	8'	F/W/I/O
D		Corner				F/W/I/O
E		Corner				F/W/I/O
F		Corner				F/W/I/O
G		Corner				F/W/I/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 2/06/08
 Signature: *Michael Coleman* Signature: *Michael Richter*

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-02 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 1600 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-Act-01

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assembled*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-SAT-03 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-10	NW Corner	E 4'	SO'	1'	F/W/C/O
B	Classroom R-10	SW Corner	E 10'	NO'	1'	F/W/C/O
C	Classroom R-12	NW Corner	E 8'	SO'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 Date: 2/06/08

Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 2/06/08

Signature: *Michael Coleman* Signature: *Michael Richter*

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWB-04 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Covered: SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CLASSROOM R-10	NW Corner	E 4'	SO'	1'	F/W/C/O
B	CLASSROOM R-10	SW Corner	E 10'	NO'	1'	F/W/C/O
C	CLASSROOM R-12	NW Corner	E 8'	SO'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-SAT-03

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-5TC-05 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Sampled Assumed
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Classroom R-10	NW Corner	E 4'	S 0'	1'	F/W/I/C/O
B	Classroom R-10	SW Corner	E 10'	N 0'	1'	F/W/I/C/O
C	Classroom R-12	NW Corner	E 8'	S 0'	4'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: Associated with M-GWB-04

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACM/DesignRecord1.omf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-TWP-06 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: JINYL-COVER
 Quantity of Material: 1400 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-ADH-07 Visible Covered TWP Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Bri.Hle Cover/Secondary Color: N/A
 Quantity of Material: 1400 LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-06

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Coleman Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85280
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CPT-08 Damaged: Yes No Friable Non-Friable
 General Description: Carpet + Size: N/A

Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Red + Brown Specks
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIA040907-01 Date: 2/06/08
 Michael Richter State License: EPA AHERA Certificate No.: D10790 Date: 2/06/08
 Signature: *Michael Coleman* Signature: *Michael Richter*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord1.pdf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MRS-07 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Covered Visible CPT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 1800 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-08

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: Michael Coleman Signature: [Signature] Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-VCT-10 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition tile Size: 12" x 12"

Matrix/Primary Color: Tan Cover/Secondary Color: Beige + White Mottles
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP/forms/SuspACM/DesignRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-11 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-10

Inspector: Michael Coleman State License: EPA
 AHERA Certificate No.: B11A040907-01 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-WAB-12 Damaged: Yes No Friable Non-Friable
 General Description: Wallbase (covered) Visible Covered Size: 4"
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 100 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-AD4-13 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered WAB Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 100 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-12

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (doors/windows/fixtures/millwork) Size: N/A

Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SAC-15 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A

Matrix/Primary Color: Black Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-FDI-14 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 105 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (windows) Size: N/A

Matrix/Primary Color: Black Texture/Pattern: TAR Like Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman State License: EPA AHERA Certificate No.: BIIA040907-01 State License: EPA
 Signature: *Michael Coleman* Date: 2/06/08
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Richter* Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACMDesignRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: P-SAT-18 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-GWB-19 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-18

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: B11A040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

FM GROUP/forms/SuspAC/MDesig/Record.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: S-JTC-20 Visible Covered SAT Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 125 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-19

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assessed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-SCT-21 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (PENETRATIONS/FLASHINGS/SEAMS) Size: N/A

Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-USF-22 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Sleet Flooring Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Gray Marble Pattern
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	GIRLS RESTROOM	NW Corner	E 0'	S 0'	0'	F/W/C/O
B	GIRLS RESTROOM	SE Corner	W 0'	N 0'	0'	F/W/C/O
C	GIRLS RESTROOM	NE Corner	W 0'	S 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: GRAY PAPER BACKING

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspAC/MDesigRecord.0.mtf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-MAS-23 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered USF Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	GIRLS Restroom	NW Corner	E 0'	S 0'	0'	F/W/C/O
B	GIRLS Restroom	SE Corner	W 0'	N 0'	0'	F/W/C/O
C	GIRLS Restroom	NE Corner	W 0'	S 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-USF-22

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *Michael Richter* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M-CON-24 Damaged: Yes No Friable Non-Friable
 General Description: Concrete (sidewalks) Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *Michael Coleman* Signature: *[Signature]* Date: 2/06/08 Date: 2/06/08

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



18974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.oft

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: MARR-25 Damaged: Yes No Friable Non-Friable
 General Description: ASPHALT PEEPA BED ROOFING (ROLLED) Size: N/A

Matrix/Primary Color: BLACK Cover/Secondary Color: GRAY MINERAL CAP
 Quantity of Material: 180 Estimated By: Drawing Field Measure
 Texture/Pattern: ASPHALTIC

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP/forms/SuspACMDesigRecord.ormf

Project No.: 07-367 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable R-10/R-12 Address: 1330 East Dava Drive
 Campus Name: Kyrene de los Ninos Elementary School Tempe, AZ 85284

Material Code: M.MAS-26 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS AND FLASHINGS) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Michael Coleman Inspector: Michael Richter
 AHERA Certificate No.: BIIA040907-01 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 2/06/08 Signature: [Signature] Date: 2/06/08

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FIM GROUP/forms/SuspACMDesigRecord.ormf

APPENDIX B

Bulk-Material Sample Documents

- **Chain-of-Custody**
- **Laboratory Analysis**



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801254

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 36 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: 07-367/Kyrene de los Ninos/Main **PO Number:** 07-367
Report Date: 2/27/2008 **Date Analyzed:** 2/27/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200801254

07-367/Kyrene de los Ninos/Main

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-01254- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-01B	2008-01254- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-01C	2008-01254- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	S-SAT-02A	2008-01254- 4	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-02B	2008-01254- 5	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-02C	2008-01254- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-03A	2008-01254- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-03B	2008-01254- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-03C	2008-01254- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-04A	2008-01254- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-04B	2008-01254- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-04C	2008-01254- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-16A	2008-01254- 13	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-16B	2008-01254- 14	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-16C	2008-01254- 15	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-17A	2008-01254- 16	Wall System	Positive Layer? No
Layer # 1	Tan	drywall core	no asbestos detected	
Sample #	M-GWB-17B	2008-01254- 17	Wall System	Positive Layer? No
Layer # 1	Tan	drywall core	no asbestos detected	
Sample #	M-GWB-17C	2008-01254- 18	Wall System	Positive Layer? No
Layer # 1	Tan	drywall core	no asbestos detected	
Sample #	S-JTC-18A	2008-01254- 19	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-18B	2008-01254- 20	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-18C	2008-01254- 21	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-27A	2008-01254- 22	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-27B	2008-01254- 23	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-27C	2008-01254- 24	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-28A	2008-01254- 25	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-28B	2008-01254- 26	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-28C	2008-01254- 27	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-29A	2008-01254- 28	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-29B	2008-01254- 29	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-29C	2008-01254- 30	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	

Sample #	<u>M-GWB-44A</u>	2008-01254-	31	Wall System	Positive Layer?	No
Layer #	1	white		<i>no asbestos detected</i>		
Sample #	<u>M-GWB-44B</u>	2008-01254-	32	Wall System	Positive Layer?	No
Layer #	1	white		<i>no asbestos detected</i>		
Sample #	<u>M-GWB-44C</u>	2008-01254-	33	Wall System	Positive Layer?	No
Layer #	1	white		<i>no asbestos detected</i>		
Sample #	<u>S-JTC-45A</u>	2008-01254-	34	Wall System	Positive Layer?	No
Layer #	1	white		<i>no asbestos detected</i>		
Sample #	<u>S-JTC-45B</u>	2008-01254-	35	Wall System	Positive Layer?	No
Layer #	1	white		<i>no asbestos detected</i>		
Sample #	<u>S-JTC-45C</u>	2008-01254-	36	Wall System	Positive Layer?	No
Layer #	1	white		<i>no asbestos detected</i>		

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2008-01254- 1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	40-50%	5-10%	-	-	-	-
Total %		100	Average %		40-50%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U				
2	glass fiber	CL	D	Y								
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-01254- 2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	40-50%	5-10%	-	-	-	-
Total %		100	Average %		40-50%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U				
2	glass fiber	CL	D	Y								
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-01254- 3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	40-50%	5-10%	-	-	-	-
Total %		100	Average %		40-50%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U				
2	glass fiber	CL	D	Y								
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample S-SAT-02A **Lab Number** 2008-01254- 4 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-01254- 5 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-01254- 6 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-GWB-03A **Lab Number** 2008-01254- 7 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	>1-2%	-	-	-	-	-
Total %		100	Average %		>1-2%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-01254- 8 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	>1-2%	-	-	-	-	-
Total %		100	Average %		>1-2%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-01254- 9 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	>1-2%	-	-	-	-	-
Total %		100	Average %		>1-2%	-	-	-	-	-
Fiber Identification:					cellulose					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample S-JTC-04A **Lab Number** 2008-01254- 10 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-01254- 11 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-01254- 12 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-16A **Lab Number** 2008-01254- 13 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-16B **Lab Number** 2008-01254- 14 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-16C **Lab Number** 2008-01254- 15 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample M-GWB-17A **Lab Number** 2008-01254- 16 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	Tan	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-17B **Lab Number** 2008-01254- 17 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	Tan	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-17C **Lab Number** 2008-01254- 18 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	Tan	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample S-JTC-18A **Lab Number** 2008-01254- 19 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-18B **Lab Number** 2008-01254- 20 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-18C **Lab Number** 2008-01254- 21 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample S-SAT-27A **Lab Number** 2008-01254- 22 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-27B **Lab Number** 2008-01254- 23 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-27C **Lab Number** 2008-01254- 24 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample M-GWB-28A **Lab Number** 2008-01254- 25 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-28B **Lab Number** 2008-01254- 26 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-28C **Lab Number** 2008-01254- 27 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample S-JTC-29A **Lab Number** 2008-01254- 28 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-29B **Lab Number** 2008-01254- 29 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-29C **Lab Number** 2008-01254- 30 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801254 07-367/Kyrene de los Ninos/Main

Sample M-GWB-44A **Lab Number** 2008-01254- 31 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-44B **Lab Number** 2008-01254- 32 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-44C **Lab Number** 2008-01254- 33 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200801254

07-367/Kyrene de los Ninos/Main

Sample S-JTC-45A **Lab Number** 2008-01254- 34 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-45B **Lab Number** 2008-01254- 35 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-45C **Lab Number** 2008-01254- 36 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: ROBERT A. McCORMICK

Printed: 27-Feb-08

Original Print Date: 27-Feb-08

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801255

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 36 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: 07-367/Kyrene de los Ninos/MP

PO Number: 07-367

Report Date: 2/27/2008

Date Analyzed: 2/27/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200801255

07-367/Kyrene de los Ninos/MP

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-01255- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-01B	2008-01255- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-01C	2008-01255- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	S-SAT-02A	2008-01255- 4	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-02B	2008-01255- 5	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-02C	2008-01255- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-03A	2008-01255- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-03B	2008-01255- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-03C	2008-01255- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-04A	2008-01255- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-04B	2008-01255- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-04C	2008-01255- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-ACT-22A	2008-01255- 13	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-ACT-22B	2008-01255- 14	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-ACT-22C	2008-01255- 15	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	no asbestos detected	
Sample #	M-APL-41A	2008-01255- 16	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-APL-41B	2008-01255- 17	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-APL-41C	2008-01255- 18	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-SAT-47A	2008-01255- 19	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-47B	2008-01255- 20	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-47C	2008-01255- 21	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	M-GWB-48A	2008-01255- 22	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-48B	2008-01255- 23	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	M-GWB-48C	2008-01255- 24	Wall System	Positive Layer? No
Layer # 1	white	drywall core	no asbestos detected	
Sample #	S-JTC-49A	2008-01255- 25	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-49B	2008-01255- 26	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-JTC-49C	2008-01255- 27	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-26A	2008-01255- 28	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-26B	2008-01255- 29	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	
Sample #	S-SAT-26C	2008-01255- 30	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	no asbestos detected	

Sample # M-GWB-27A		2008-01255- 31	Wall System	Positive Layer? No
Layer # 1 white	drywall core		<i>no asbestos detected</i>	
Sample # M-GWB-27B		2008-01255- 32	Wall System	Positive Layer? No
Layer # 1 white	drywall core		<i>no asbestos detected</i>	
Sample # M-GWB-27C		2008-01255- 33	Wall System	Positive Layer? No
Layer # 1 white	drywall core		<i>no asbestos detected</i>	
Sample # S-JTC-28A		2008-01255- 34	Wall System	Positive Layer? No
Layer # 1 white	texture/joint compound		<i>no asbestos detected</i>	
Sample # S-JTC-28B		2008-01255- 35	Wall System	Positive Layer? No
Layer # 1 white	texture/joint compound		<i>no asbestos detected</i>	
Sample # S-JTC-28C		2008-01255- 36	Wall System	Positive Layer? No
Layer # 1 white	texture/joint compound		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2008-01255- 1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	<=1%	-	-	-	-
Total %		100	Average %		10-20%	<=1%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-01255- 2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	<=1%	-	-	-	-
Total %		100	Average %		10-20%	<=1%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-01255- 3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	10-20%	<=1%	-	-	-	-
Total %		100	Average %		10-20%	<=1%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample S-SAT-02A **Lab Number** 2008-01255- 4 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-01255- 5 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-01255- 6 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number:

200801255

07-367/Kyrene de los Ninos/MP

Sample M-GWB-03A **Lab Number** 2008-01255- 7 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-01255- 8 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-01255- 9 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample S-JTC-04A Lab Number 2008-01255- 10 Sampled: 2/6/2008 Condition: acceptable
 Analyzed By DMS 2/27/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B Lab Number 2008-01255- 11 Sampled: 2/6/2008 Condition: acceptable
 Analyzed By DMS 2/27/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C Lab Number 2008-01255- 12 Sampled: 2/6/2008 Condition: acceptable
 Analyzed By DMS 2/27/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample M-ACT-22A **Lab Number** 2008-01255- 13 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	5-10%	-	-	-	-
Total %		100	Average %		20-30%	5-10%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-ACT-22B **Lab Number** 2008-01255- 14 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	5-10%	-	-	-	-
Total %		100	Average %		20-30%	5-10%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-ACT-22C **Lab Number** 2008-01255- 15 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	5-10%	-	-	-	-
Total %		100	Average %		20-30%	5-10%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample M-APL-41A **Lab Number** 2008-01255- 16 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-APL-41B **Lab Number** 2008-01255- 17 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-APL-41C **Lab Number** 2008-01255- 18 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, mica/vermiculite,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample S-SAT-47A Lab Number 2008-01255- 19 Sampled: 2/6/2008 Condition: acceptable
 Analyzed By DMS 2/27/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-47B Lab Number 2008-01255- 20 Sampled: 2/6/2008 Condition: acceptable
 Analyzed By DMS 2/27/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-47C Lab Number 2008-01255- 21 Sampled: 2/6/2008 Condition: acceptable
 Analyzed By DMS 2/27/2008 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample M-GWB-48A **Lab Number** 2008-01255- 22 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-48B **Lab Number** 2008-01255- 23 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-48C **Lab Number** 2008-01255- 24 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y									
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample S-JTC-49A **Lab Number** 2008-01255- 25 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-49B **Lab Number** 2008-01255- 26 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-49C **Lab Number** 2008-01255- 27 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample S-SAT-26A **Lab Number** 2008-01255- 28 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-26B **Lab Number** 2008-01255- 29 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-26C **Lab Number** 2008-01255- 30 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-GWB-27A **Lab Number** 2008-01255- 31 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-27B **Lab Number** 2008-01255- 32 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-27C **Lab Number** 2008-01255- 33 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200801255 07-367/Kyrene de los Ninos/MP

Sample S-JTC-28A **Lab Number** 2008-01255- 34 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-28B **Lab Number** 2008-01255- 35 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-28C **Lab Number** 2008-01255- 36 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: DAVID M. SCHALLER

Printed: 27-Feb-08

Original Print Date: 27-Feb-08

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801256

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 **PLM** **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene de los Ninos/Portable R1/R3 **PO Number:** 07-367
Report Date: 2/27/2008 **Date Analyzed:** 2/27/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200801256

Kyrene de los Ninos/Portable R1/R3

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-01256- 1	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-01256- 2	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-01256- 3	Ceiling Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	S-SAT-02A	2008-01256- 4	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-02B	2008-01256- 5	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-02C	2008-01256- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-03A	2008-01256- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-03B	2008-01256- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-03C	2008-01256- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-04A	2008-01256- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-04B	2008-01256- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-04C	2008-01256- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-16A	2008-01256- 13	Wall System	Positive Layer? No
Layer # 1	White	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-16B	2008-01256- 14	Wall System	Positive Layer? No
Layer # 1	White	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-16C	2008-01256- 15	Wall System	Positive Layer? No
Layer # 1	White	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-17A	2008-01256- 16	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-17B	2008-01256- 17	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-17C	2008-01256- 18	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2008-01256- 1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	5-10%	-	-	-	-
Total %		100	Average %		30-40%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-01256- 2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	5-10%	-	-	-	-
Total %		100	Average %		30-40%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-01256- 3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	5-10%	-	-	-	-
Total %		100	Average %		30-40%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number:

200801256

Kyrene de los Ninos/Portable R1/R3

Sample S-SAT-02A

Lab Number 2008-01256- 4

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B

Lab Number 2008-01256- 5

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C

Lab Number 2008-01256- 6

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-GWB-03A **Lab Number** 2008-01256- 7 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-01256- 8 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-01256- 9 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200801256

Kyrene de los Ninos/Portable R1/R3

Sample S-JTC-04A

Lab Number 2008-01256- 10

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B

Lab Number 2008-01256- 11

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C

Lab Number 2008-01256- 12

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number:

200801256

Kyrene de los Ninos/Portable R1/R3

Sample M-GWB-16A **Lab Number** 2008-01256- 13 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	White	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-16B **Lab Number** 2008-01256- 14 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	White	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-16C **Lab Number** 2008-01256- 15 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	White	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200801256

Kyrene de los Ninos/Portable R1/R3

Sample S-JTC-17A

Lab Number 2008-01256- 16

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-17B

Lab Number 2008-01256- 17

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-17C

Lab Number 2008-01256- 18

Sampled: 2/6/2008

Condition: acceptable

Analyzed By RAM 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: ROBERT A. McCORMICK

Printed: 27-Feb-08

Original Print Date: 27-Feb-08

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801257

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene de los Ninos/Portable R2/R4

PO Number: 07-367

Report Date: 2/27/2008

Date Analyzed: 2/27/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200801257

Kyrene de los Ninos/Portable R2/R4

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-APL-01A Layer # 1 off-white ceiling tile	2008-01257- 1	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 off-white ceiling tile	2008-01257- 2	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 off-white ceiling tile	2008-01257- 3	Ceiling Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02A Layer # 1 white texture/joint compound	2008-01257- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02B Layer # 1 white texture/joint compound	2008-01257- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-02C Layer # 1 white texture/joint compound	2008-01257- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03A Layer # 1 white drywall core	2008-01257- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03B Layer # 1 white drywall core	2008-01257- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-03C Layer # 1 white drywall core	2008-01257- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04A Layer # 1 white texture/joint compound	2008-01257- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04B Layer # 1 white texture/joint compound	2008-01257- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-04C Layer # 1 white texture/joint compound	2008-01257- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-16A Layer # 1 white drywall core	2008-01257- 13	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-16B Layer # 1 white drywall core	2008-01257- 14	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-16C Layer # 1 white drywall core	2008-01257- 15	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-17A Layer # 1 white texture/joint compound	2008-01257- 16	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-17B Layer # 1 white texture/joint compound	2008-01257- 17	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-17C Layer # 1 white texture/joint compound	2008-01257- 18	Wall System <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2008-01257-1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	5-10%	-	-	-	-
Total %		100	Average %		30-40%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-01257-2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	5-10%	-	-	-	-
Total %		100	Average %		30-40%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2008-01257-3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Ceiling Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	30-40%	5-10%	-	-	-	-
Total %		100	Average %		30-40%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample S-SAT-02A **Lab Number** 2008-01257- 4 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02B **Lab Number** 2008-01257- 5 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-02C **Lab Number** 2008-01257- 6 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-GWB-03A **Lab Number** 2008-01257-7 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03B **Lab Number** 2008-01257-8 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-03C **Lab Number** 2008-01257-9 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample S-JTC-04A **Lab Number** 2008-01257- 10 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04B **Lab Number** 2008-01257- 11 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-04C **Lab Number** 2008-01257- 12 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-GWB-16A **Lab Number** 2008-01257- 13 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-16B **Lab Number** 2008-01257- 14 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-16C **Lab Number** 2008-01257- 15 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose					
2	CL	D	Y					glass fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200801257

Kyrene de los Ninos/Portable R2/R4

Sample S-JTC-17A **Lab Number** 2008-01257- 16 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-17B **Lab Number** 2008-01257- 17 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-17C **Lab Number** 2008-01257- 18 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By RAM 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: ROBERT A. McCORMICK

Printed: 27-Feb-08

Original Print Date: 27-Feb-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801258

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 3 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene de los Ninos/Portable R5/R7 **PO Number:** 07-367
Report Date: 2/22/2008 **Date Analyzed:** 2/22/2008 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200801258

Kyrene de los Ninos/Portable R5/R7

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-01258- 1	Acoustic Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-01258- 2	Acoustic Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-01258- 3	Acoustic Tile	Positive Layer? No
Layer # 1	off-white	ceiling tile	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2008-01258- 1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DJF 2/22/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	5-10%	-	-	-	-
Total %		100	Average %		20-30%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2008-01258- 2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DJF 2/22/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	5-10%	-	-	-	-
Total %		100	Average %		20-30%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.


Sample M-APL-01C **Lab Number** 2008-01258- 3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DJF 2/22/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, powder, binder

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	ceiling tile	100	off-white	3	20-30%	5-10%	-	-	-	-
Total %		100	Average %		20-30%	5-10%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; BI=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: DANIEL J. COLEY

Printed: 22-Feb-08

Original Print Date: 22-Feb-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801259

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 3 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene de los Ninos/Portable R6/R8

PO Number: 07-367

Report Date: 2/27/2008

Date Analyzed: 2/27/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample analysis as per client request. Any material or layer other than that indicated on the chain of custody was not analyzed, even if a suspect material.

PLM Analysis Summary:

Job Number: 200801259

Kyrene de los Ninos/Portable R6/R8

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2008-01259- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white	acoustical tile	<i>no asbestos detected</i>	
Sample #	M-APL-01B	2008-01259- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white	acoustical tile	<i>no asbestos detected</i>	
Sample #	M-APL-01C	2008-01259- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white	acoustical tile	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2008-01259- 1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2	W	F	N	N	H	+	U	cellulose fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01B **Lab Number** 2008-01259- 2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2	W	F	N	N	H	+	U	cellulose fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01C **Lab Number** 2008-01259- 3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2	W	F	N	N	H	+	U	cellulose fiber					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: DAVID M. SCHALLER

Printed: 27-Feb-08

Original Print Date: 27-Feb-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801260

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene de los Ninos/Portable R9/R11

PO Number: 07-367

Report Date: 2/27/2008

Date Analyzed: 2/27/2008

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-poi microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200801260

Kyrene de los Ninos/Portable R9/R11

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-ACT-01A	2008-01260- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white	acoustical tile	<i>no asbestos detected</i>	
Sample #	M-ACT-01B	2008-01260- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white	acoustical tile	<i>no asbestos detected</i>	
Sample #	M-ACT-01C	2008-01260- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white	acoustical tile	<i>no asbestos detected</i>	
Sample #	S-SAT-03A	2008-01260- 4	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-03B	2008-01260- 5	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-03C	2008-01260- 6	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-04A	2008-01260- 7	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-04B	2008-01260- 8	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-04C	2008-01260- 9	Wall System	Positive Layer? No
Layer # 1	white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-05A	2008-01260- 10	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-05B	2008-01260- 11	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-05C	2008-01260- 12	Wall System	Positive Layer? No
Layer # 1	white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-VSF-22A	2008-01260- 13	Flooring	Positive Layer? No
Layer # 1	Off-white	sheet flooring	<i>no asbestos detected</i>	
Sample #	M-VSF-22B	2008-01260- 14	Flooring	Positive Layer? No
Layer # 1	Off-white	sheet flooring	<i>no asbestos detected</i>	
Sample #	M-VSF-22C	2008-01260- 15	Flooring	Positive Layer? No
Layer # 1	Off-white	sheet flooring	<i>no asbestos detected</i>	
Sample #	M-MAS-23A	2008-01260- 16	Adhesive/caulk	Positive Layer? No
Layer # 1	Yellow	mastic	<i>no asbestos detected</i>	
Sample #	M-MAS-23B	2008-01260- 17	Adhesive/caulk	Positive Layer? No
Layer # 1	Yellow	mastic	<i>no asbestos detected</i>	
Sample #	M-MAS-23C	2008-01260- 18	Adhesive/caulk	Positive Layer? No
Layer # 1	Yellow	mastic	<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-ACT-01A **Lab Number** 2008-01260-1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
Total %		100	Average %		40-50%	2-5%	-	-	-	-

Fiber Identification: glass fiber cellulose fiber

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01B **Lab Number** 2008-01260-2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
Total %		100	Average %		40-50%	2-5%	-	-	-	-

Fiber Identification: glass fiber cellulose fiber

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01C **Lab Number** 2008-01260-3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
Total %		100	Average %		40-50%	2-5%	-	-	-	-

Fiber Identification: glass fiber cellulose fiber

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number:

200801260

Kyrene de los Ninos/Portable R9/R11

Sample S-SAT-03A **Lab Number** 2008-01260- 4 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03B **Lab Number** 2008-01260- 5 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03C **Lab Number** 2008-01260- 6 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %			n.d.	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-GWB-04A **Lab Number** 2008-01260- 7 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-

Fiber Identification: cellulose glass fiber

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-GWB-04B **Lab Number** 2008-01260- 8 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-

Fiber Identification: cellulose glass fiber

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-GWB-04C **Lab Number** 2008-01260- 9 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-

Fiber Identification: cellulose glass fiber

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200801260

Kyrene de los Ninos/Portable R9/R11

Sample S-JTC-05A

Lab Number 2008-01260- 10

Sampled: 2/6/2008

Condition: acceptable

Analyzed By DMS 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05B

Lab Number 2008-01260- 11

Sampled: 2/6/2008

Condition: acceptable

Analyzed By DMS 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05C

Lab Number 2008-01260- 12

Sampled: 2/6/2008

Condition: acceptable

Analyzed By DMS 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-VSF-22A **Lab Number** 2008-01260- 13 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sheet flooring	100	Off-white	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-VSF-22B **Lab Number** 2008-01260- 14 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sheet flooring	100	Off-white	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-VSF-22C **Lab Number** 2008-01260- 15 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sheet flooring	100	Off-white	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-MAS-23A **Lab Number** 2008-01260- 16 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Sticky
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Yellow	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-23B **Lab Number** 2008-01260- 17 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Sticky
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Yellow	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-23C **Lab Number** 2008-01260- 18 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Sticky
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Yellow	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: DAVID M. SCHALLER

Printed: 27-Feb-08

Original Print Date: 27-Feb-08



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200801261

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 18 PLM **Rec:** 2/8/2008 **Method:** EPA 600/R-93/116
Client Job: Kyrene de los Ninos/Portable R10/R12
Report Date: 2/27/2008 **Date Analyzed:** 2/27/2008

PLM analysis for asbestos in bulk smp

PO Number: 07-367

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant Identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200801261

Kyrene de los Ninos/Portable R10/R12

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-ACT-01A Layer # 1 Off-white acoustical tile	2008-01261- 1	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ACT-01B Layer # 1 Off-white acoustical tile	2008-01261- 2	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ACT-01C Layer # 1 Off-white acoustical tile	2008-01261- 3	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-03A Layer # 1 white texture/joint compound	2008-01261- 4	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-03B Layer # 1 white texture/joint compound	2008-01261- 5	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-03C Layer # 1 white texture/joint compound	2008-01261- 6	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-04A Layer # 1 white drywall core	2008-01261- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-04B Layer # 1 white drywall core	2008-01261- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-04C Layer # 1 white drywall core	2008-01261- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-05A Layer # 1 white texture/joint compound	2008-01261- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-05B Layer # 1 white texture/joint compound	2008-01261- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-05C Layer # 1 white texture/joint compound	2008-01261- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-VSF-22A Layer # 1 Off-white sheet flooring	2008-01261- 13	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # M-VSF-22B Layer # 1 Off-white sheet flooring	2008-01261- 14	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # M-VSF-22C Layer # 1 Off-white sheet flooring	2008-01261- 15	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-23A Layer # 1 Off-white mastic	2008-01261- 16	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-23B Layer # 1 Off-white mastic	2008-01261- 17	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-23C Layer # 1 Off-white mastic	2008-01261- 18	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-ACT-01A **Lab Number** 2008-01261- 1 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
Total %		100	Average %		40-50%	2-5%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	CL	D	Y											
2	W	F	N	N	H	+	U							
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01B **Lab Number** 2008-01261- 2 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
Total %		100	Average %		40-50%	2-5%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	CL	D	Y											
2	W	F	N	N	H	+	U							
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-ACT-01C **Lab Number** 2008-01261- 3 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	40-50%	2-5%	-	-	-	-
Total %		100	Average %		40-50%	2-5%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	CL	D	Y											
2	W	F	N	N	H	+	U							
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03A **Lab Number** 2008-01261- 4 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03B **Lab Number** 2008-01261- 5 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03C **Lab Number** 2008-01261- 6 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number:

200801261

Kyrene de los Ninos/Portable R10/R12

Sample M-GWB-04A **Lab Number** 2008-01261- 7 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-04B **Lab Number** 2008-01261- 8 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-04C **Lab Number** 2008-01261- 9 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number:

200801261

Kyrene de los Ninos/Portable R10/R12

Sample S-JTC-05A

Lab Number 2008-01261- 10

Sampled: 2/6/2008

Condition: acceptable

Analyzed By DMS 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05B

Lab Number 2008-01261- 11

Sampled: 2/6/2008

Condition: acceptable

Analyzed By DMS 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05C

Lab Number 2008-01261- 12

Sampled: 2/6/2008

Condition: acceptable

Analyzed By DMS 2/27/2008

An? OK

Apparent Smp Type Wall System

Non-fibrous Solid

Homogeneous Yes

Layers 1

Pos Layer? No

Sub-Samples 3

Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-VSF-22A **Lab Number** 2008-01261- 13 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Flooring **Rubbery**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sheet flooring	100	Off-white	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VSF-22B **Lab Number** 2008-01261- 14 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Flooring **Rubbery**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sheet flooring	100	Off-white	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VSF-22C **Lab Number** 2008-01261- 15 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Flooring **Rubbery**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sheet flooring	100	Off-white	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-23A **Lab Number** 2008-01261- 16 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Sticky
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-23B **Lab Number** 2008-01261- 17 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Sticky
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-23C **Lab Number** 2008-01261- 18 **Sampled:** 2/6/2008 **Condition:** acceptable
Analyzed By DMS 2/27/2008 **An?** OK **Apparent Smp Type** Adhesive/caulk Sticky
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweazed apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be +, - or B (both); Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: DAVID M. SCHALLER

Printed: 27-Feb-08

Original Print Date: 27-Feb-08



Larry S. Pierce, Approved Accreditation Signatory

APPENDIX C

Building Inspectors' Signature Sheet

BUILDING INSPECTOR'S SIGNATURE SHEET

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene De Los Ninos Elementary School
Kyrene School District No. 28

FM Project 07-367

The individual(s) whose signature(s) is/are shown below is/are EPA Accredited Building Inspector(s) who participated in one or more of the following activities:


- A. Visual Inspection of Facilities
- B. Identification of Homogenous Areas of Asbestos-Containing Materials
- C. Development of Sampling Plan and Protocols
- D. Bulk Sampling Activities/Material Identifications
- E. Assessing ACBM/ACM
- F. Preparing Report of Findings

<u>INSPECTOR</u>	<u>ACTIVITIES</u>	<u>DATES</u>
Paul Anger Printed Name D 11441 Accreditation No. Signature	PA Initials EPA State	F 3/4/08
Michael Coleman Printed Name BIIA040907-01 Accreditation No. Signature	MC Initials EPA State	A, B, D, E 2/4/08 – 2/8/08
Michael Richter Printed Name D 10790 Accreditation No. Signature	MR Initials EPA State	A, B, D, E 2/4/08 – 2/8/08
Cliff Rolle Printed Name D 10203 Accreditation No. Signature	CR Initials EPA State	A, B, C, D, E, F 2/4/08 – 3/4/08

APPENDIX D

Personnel and Laboratory Accreditations

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHRA Refresher
Building Inspector
January 4, 2008**

and successfully passed the competency exam.

Date of Examination: **January 4, 2008**

Date of Expiration: **January 4, 2009**

Director

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

Certificate Of Training

In recognition of attendance and passing of exam

MICHAEL D. COLLEMAN
4855

The above person has completed the requisite training course for asbestos accreditation under TSCA Title II, Asbestos Model Accreditation Plan and the provider is accredited to provide training within the

State of Hawaii. #T-0108

And/or as listed below


Building Inspector Initial

Completed this 9th Day of April, 2007 Expires 8th Day of April, 2008

NVEIC

National Environmental Institute & Consulting


Surprise, Arizona--Honolulu, Hawaii



Training Director-

Certificate # BIIA040907-01

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

AHERA


Building Inspector

September 10-12, 2007


and successfully passed the competency exam

Date of Examination: **September 12, 2007**

Date of Expiration: **September 12, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

and successfully passed the competency exam

[Signature]
 Director

Director

Date of Examination: June 1, 2007

Date of Expiration: June 1, 2008

[Signature]
 Approved Instructor

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:1999

NVLAP LAB CODE: 101031-0

Fiberquant, Inc.
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in
NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS



2007-07-01 through 2008-06-30

Effective dates

Dolly S. Bruce
For the National Institute of Standards and Technology