

ASBESTOS MANAGEMENT PLAN



at

Kyrene Del Sureno Elementary School

Prepared for:

Kyrene School District No. 28

VOLUME I OF II

**FM GROUP INC
FM Project 07-345**

November 2007

ASBESTOS MANAGEMENT PLAN

Kyrene Del Sureno Elementary School

November 2007

FM GROUP INC

FM Project 07-345

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	GENERAL INVENTORY	1-1
2	INSPECTION REPORT	2-1
3	DESIGNATED PERSON IDENTIFICATION	3-1
4	RESPONSE ACTION	4-1
5	ACCREDITATION STATEMENTS	5-1
6	REMAINING ACBM.....	6-1
7	O&M PROGRAM.....	7-1
8	INITIAL NOTIFICATIONS	8-1
9	COST ESTIMATION	9-1
10	SIGNED STATEMENT BY DESIGNATED PERSON	10-1
11	ANNUAL NOTIFICATIONS	11-1
12	ACCREDITATION STATEMENT FOR ADDITIONAL CONSULTANT	12-1

APPENDIX A: ONGOING RECORDKEEPING

SECTION 1

GENERAL INVENTORY

General Inventory
763.93(e)(1)

Date: NOVEMBER 7, 2007

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: KYRENE DEL SURENO ELEMENTARY SCHOOL

Address: 3375 WEST GALVESTON STREET
CHANDLER, ARIZONA 85226

Building Name	Friable ACM	Non-Friable ACM	Assumed ACM
Main	N/A	X	X
Portable 50/51	N/A	X	X
Portable 52/53	N/A	X	X
Portable 54/55	N/A	X	X
Portable 56/57	N/A	X	X
Portable 58/59	N/A	X	X
Portable 60/61	N/A	X	X
Restroom Portable	N/A	X	X

SECTION 2

INSPECTION REPORT

INSPECTION REPORT

The information presented in the following section is an abridgment of the facilities inspection report. This report, for purposes of recordkeeping, was identified as:

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School

Prepared by: FM GROUP INC
Project No.: 07-345
Date: November 2007

A complete copy of this Report of Findings can be found on file with the District's Designated Person at:

Kyrene School District No. 28
8700 South Kyrene Road
Tempe, Arizona 85284-2197

REPORT OF FINDINGS
(Abridged Version)



Comprehensive AHERA Asbestos Inspection

at

Kyrene Del Sureno Elementary School

Prepared for:

Kyrene School District No. 28

FM GROUP INC
FM Project 07-345

November 2007

TABLE OF CONTENTS

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Kyrene School District No. 28

FM GROUP Project 07-345

<u>Section</u>	<u>Page</u>
1.0 <u>SURVEY RESULTS AND RECOMMENDATIONS</u>	1
1.1 Summary	1
1.2 Identified Asbestos-Containing Materials	1
1.3 Asbestos-Containing Building Materials (Table C)	2
1.4 ACBM/Location Plans	3
1.5 Critical Situations	4
1.6 Friable Asbestos-Containing Building Materials	4
1.7 Material Assessments	4
1.8 Recommendations	4
1.9 Qualifications of the Report.....	4
2.0 <u>PROJECT INFORMATION</u>	5
2.1 Background.....	5
2.2 Description of Construction	5
2.2.1 Main Building.....	5
2.2.2 Portable Buildings 50/51, 52/53, 54/55, 56/57, 58/59 and 60/61.....	6
2.2.3 Restroom Portable	6
2.3 Building Materials/Systems List (Table A)	8
2.3.1 Main Building.....	9
2.3.2 Portable 50/51	60
2.3.3 Portable 52/53	62
2.3.4 Portable 54/55	64
2.3.5 Portable 56/57	66
2.3.6 Portable 58/59	68
2.3.7 Portable 60/61	70
2.3.8 Restroom Portable	72
2.4 AHERA Inspection Procedures and Protocols.....	74
2.4.1 Inspection Procedures and Protocols	74
2.4.2 FM GROUP INC Inspection SOP	74
2.5 Visual Inspection.....	74
2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials (Table B) .	75
2.6.1 Main Building.....	76
2.6.2 Portable 50/51	79
2.6.3 Portable 52/53	80
2.6.4 Portable 54/55	81
2.6.5 Portable 56/57	82
2.6.6 Portable 58/59	83

Table of Contents
Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School, KSD
FM Project 07-345

<u>Section</u>	<u>Page</u>
2.6.7 Portable 60/61	84
2.6.8 Restroom Portable	85
2.7 Physical Assessments	86
2.8 Sample Collection	86
2.9 Material Bulk Sample Analysis	87

Appendices

Appendix A	Suspect Asbestos-Containing Material Designation and Sample Record Forms
Appendix B	Bulk-Material Sample Documents <ul style="list-style-type: none">• Chain-of-Custody• Laboratory Analysis
Appendix C	Building Inspectors' Signature Sheet
Appendix D	Personnel and Laboratory Accreditations

ENV\KSD\07-345 Sureno Elm AHERA\2.0\2.3\2.3.1\TOC.doc

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the eight buildings comprising the Kyrene Del Sureno Elementary School (KDSSES) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period October 8, 2007 through October 12, 2007. A total of 150 bulk-material samples were collected from 256 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Two hundred and six building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos-Containing Building Materials

The identified ACBM within the eight buildings at KDSSES are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

Asbestos Material-Bulk Samples Collected

<i>Building</i>	<i>No. of Samples</i>	<i>No. HA</i>	<i>No. Assumed</i>	<i>Total No. ACM</i>
Main Building	114	77	39	39
Portable 50/51	6	26	24	24
Portable 52/53	6	27	25	25
Portable 54/55	6	26	24	24
Portable 56/57	6	27	25	25
Portable 58/59	6	26	24	24
Portable 60/61	6	27	25	25
Restroom Portable	0	20	20	20

1.3 Asbestos-Containing Building Materials

**TABLE C
ASBESTOS CONTAINING BUILDING MATERIALS**

**MAIN BUILDING
PORTABLE 50/51
PORTABLE 52/53
PORTABLE 54/55
PORTABLE 56/57
PORTABLE 58/59
PORTABLE 60/61
RESTROOM PORTABLE**

***TABLE C HAS BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

1.4 ACBM/Location Plans

**MAIN BUILDING
PORTABLE 50/51
PORTABLE 52/53
PORTABLE 54/55
PORTABLE 56/57
PORTABLE 58/59
PORTABLE 60/61
RESTROOM PORTABLE**

***ACBM/LOCATION PLANS HAVE BEEN MOVED TO
SECTION 6 OF ASBESTOS MANAGEMENT PLAN***

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the eight buildings at KDSSES during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the eight buildings at KDSSES during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** was identified in the eight buildings at KDSSES, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the eight buildings at the KDSES campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the eight buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM Proposal P6-349, dated June 29, 2006, as evidenced by the issuance of KSD Purchase Order No. 800475, dated July 17, 2007. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 3375 West Galveston Street, in Chandler, Arizona and consists of eight buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the eight buildings.

At the request of KSD, select identified suspect ACBM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period October 8, 2007 through October 12, 2007, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

Copies of Personnel and Laboratory Accreditations are presented in Appendix D. The Accreditations included are for the current calendar time period only.

2.2 Description of Construction

2.2.1 Main Building

The construction date of the Main Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support wooden and metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building, corridors and miscellaneous interior rooms.

Mechanical equipment for the building consists of ground and roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Portables 50/51, 52/53, 54/55, 56/57, 58/59 and 60/61

The construction date of Portables 50/51, 52/53, 54/55, 56/57, 58/59 and 60/61 is unknown. The construction appears to be consistent and uniform throughout each Portable.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: carpet and vinyl composition tile.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal) or tackable wall panels. Original ceilings are wood or metal-framed and support suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.3 Restroom Portable

The construction date of the Restroom Portable is unknown. The construction appears to be consistent and uniform throughout each Portable.

Report of Findings

Comprehensive AHERA Asbestos Inspection

Kyrene Del Sureno Elementary School, KSD

FM Project 07-345

The building is built of wood or metal-framed foundations and is believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: vinyl composition tile and vinyl sheet flooring.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal). Restroom walls finishes include gypsum wallboard systems with textured, painted finishes. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the building consists of roof-mounted air handler units. The ductwork distribution systems run above the gypsum wallboard ~~or suspended~~ ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

A detailed description of the building material systems observed in this facility is presented as Table A in Section 2.3.

2.3 Building Materials/Systems List

TABLE A BUILDING MATERIAL SYSTEMS

**MAIN BUILDING
PORTABLE 50/51
PORTABLE 52/53
PORTABLE 54/55
PORTABLE 56/57
PORTABLE 58/59
PORTABLE 60/61
RESTROOM PORTABLE**

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES (HEAVY), WHITE, HEAVY	RECEPTION, CEILING THROUGHOUT (MAIN)	S
	TREATMENT, CEILING THROUGHOUT (MAIN)	
	NURSE'S OFFICE, CEILING THROUGHOUT (MAIN)	
	HEARING, CEILING THROUGHOUT	
	HALL 1, CEILING THROUGHOUT	
	NORTH FOYER, CEILING THROUGHOUT	
	PRINCIPAL OFFICE, CEILING THROUGHOUT (MAIN)	
	PRINCIPAL OFFICE CLOSET, CEILING THROUGHOUT	
	COUNSELOR, CEILING THROUGHOUT (MAIN)	
	PSY/CONF. , CEILING THROUGHOUT (MAIN)	
	FACULTY WORK, CEILING THROUGHOUT	
	FACULTY LOUNGE, PORTION OF CEILING	
	STORAGE 2, CEILING THROUGHOUT (MAIN)	
	JANITOR, CEILING THROUGHOUT (MAIN)	
	ELEC. CLOSET, CEILING THROUGHOUT	
	LIBRARY, PORTION OF CEILING	
	LIBRARY WORKROOM, CEILING THROUGHOUT	
	COMPUTER, CEILING THROUGHOUT	
	SERVER ROOM, CEILING THROUGHOUT (MAIN)	
	SPEECH, CEILING THROUGHOUT	
	STORAGE 3, CEILING THROUGHOUT	
	SPECIAL ED. 1, CEILING THROUGHOUT (MAIN)	
	SPECIAL ED. 2, CEILING THROUGHOUT	
	SPECIAL ED. 3, CEILING THROUGHOUT	
	ROOM 10, CEILING THROUGHOUT (MAIN)	
	ROOM 11, CEILING THROUGHOUT (MAIN)	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 12, CEILING THROUGHOUT (MAIN)	
	ROOM 13, CEILING THROUGHOUT (MAIN)	
	ROOM 14, CEILING THROUGHOUT (MAIN)	
	ROOM 15, CEILING THROUGHOUT (MAIN)	
	ROOM 16, CEILING THROUGHOUT (MAIN)	
	ROOM 17, CEILING THROUGHOUT	
	ROOM 18, CEILING THROUGHOUT (MAIN)	
	ROOM 19, CEILING THROUGHOUT (MAIN)	
	ROOM 20, CEILING THROUGHOUT (MAIN)	
	ROOM 21, CEILING THROUGHOUT (MAIN)	
	ROOM 22, CEILING THROUGHOUT (MAIN)	
	ROOM 23, CEILING THROUGHOUT (MAIN)	
	ROOM 24, CEILING THROUGHOUT	
	ROOM 25, CEILING THROUGHOUT (MAIN)	
	ROOM 26, CEILING THROUGHOUT (MAIN)	
	ROOM 27, CEILING THROUGHOUT (MAIN)	
	ROOM 28, CEILING THROUGHOUT (MAIN)	
	ROOM 29, CEILING THROUGHOUT (MAIN)	
	ROOM 30, CEILING THROUGHOUT (MAIN)	
	ROOM 31, CEILING THROUGHOUT (MAIN)	
	MUSIC, CEILING THROUGHOUT	
	STAGE, CEILING THROUGHOUT	
	NORTH WING, CEILING THROUGHOUT	
	SOUTH WING, CEILING THROUGHOUT (MAIN)	
	MULTI-PURPOSE, PORTION OF CEILING (MAIN)	
	STORAGE 4, CEILING THROUGHOUT (MAIN)	
	STORAGE 5, CEILING THROUGHOUT (MAIN)	
	P.E. OFFICE, CEILING THROUGHOUT (MAIN)	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 1, CEILING THROUGHOUT (MAIN)	
	CORRIDOR 2, CEILING THROUGHOUT (MAIN)	
	CORRIDOR 3, CEILING THROUGHOUT LESS CLASSROOM ENTRY	
	CORRIDOR 4, CEILING THROUGHOUT LESS CLASSROOM ENTRIES	
	CORRIDOR 5, CEILING THROUGHOUT LESS CLASSROOM ENTRIES	
	CORRIDOR 6, CEILING THROUGHOUT LESS CLASSROOM ENTRIES	
	WEST FOYER, CEILING THROUGHOUT LESS CLASSROOM ENTRY	
	CORRIDOR 7, CEILING THROUGHOUT	
	CORRIDOR 8, CEILING THROUGHOUT LESS CLASSROOM ENTRY	
	CORRIDOR 9, CEILING THROUGHOUT LESS CLASSROOM ENTRY	
	CORRIDOR 10, CEILING THROUGHOUT LESS CLASSROOM ENTRIES	
	EAST FOYER, CEILING THROUGHOUT LESS CLASSROOM ENTRY	
	CORRIDOR 11, CEILING THROUGHOUT LESS CLASSROOM ENTRIES	
	CORRIDOR 12, CEILING THROUGHOUT LESS CLASSROOM ENTRIES	
	CORRIDOR 13, CEILING THROUGHOUT	
	CORRIDOR 14, PORTION OF CEILING	
	CORRIDOR 15, PORTION OF CEILING	
	CORRIDOR 16, PORTION OF CEILING	
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	RECEPTION, CEILING THROUGHOUT (REPLACEMENT)	S
	TREATMENT, CEILING THROUGHOUT (REPLACEMENT)	
	NURSE'S OFFICE, CEILING THROUGHOUT (REPLACEMENT)	
	PRINCIPAL OFFICE, CEILING THROUGHOUT (REPLACEMENT)	
	COUNSELOR, CEILING THROUGHOUT (REPLACEMENT)	
	PSY/CONF. , CEILING THROUGHOUT (REPLACEMENT)	
	STORAGE 2, CEILING THROUGHOUT (REPLACEMENT)	
	JANITOR, CEILING THROUGHOUT (REPLACEMENT)	
	SERVER ROOM, CEILING THROUGHOUT (REPLACEMENT)	
	SPECIAL ED. 1, CEILING THROUGHOUT (REPLACEMENT)	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 10, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 11, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 12, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 13, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 14, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 15, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 16, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 18, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 19, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 20, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 21, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 22, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 23, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 25, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 26, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 27, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 28, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 29, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 30, CEILING THROUGHOUT (REPLACEMENT)	
	ROOM 31, CEILING THROUGHOUT (REPLACEMENT)	
	SOUTH WING, CEILING THROUGHOUT (REPLACEMENT)	
	MULTI-PURPOSE, PORTION OF CEILING (REPLACEMENT)	
	STORAGE 4, CEILING THROUGHOUT (REPLACEMENT)	
	STORAGE 5, CEILING THROUGHOUT (REPLACEMENT)	
	P.E. OFFICE, CEILING THROUGHOUT (REPLACEMENT)	
	CORRIDOR 1, CEILING THROUGHOUT (REPLACEMENT)	
	CORRIDOR 2, CEILING THROUGHOUT (REPLACEMENT)	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	TREATMENT, WALLS THROUGHOUT	
	NURSE'S OFFICE, WALLS THROUGHOUT	
	PRINCIPAL OFFICE, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	PSY/CONF., WALLS THROUGHOUT	
	FACULTY WORK, WALLS THROUGHOUT	
	FACULTY LOUNGE, EAST, WEST AND SOUTH WALLS	
	STORAGE 2, WALLS THROUGHOUT	
	JANITOR, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	LIBRARY, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	LIBRARY WORKROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	COMPUTER, WALLS THROUGHOUT, WEST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SERVER ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	SPEECH, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	STORAGE 3, WALLS THROUGHOUT	
	TEST ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	SPECIAL ED. 1, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST, SOUTH AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SPECIAL ED. 2, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, EAST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SPECIAL ED. 3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	TIMEOUT ROOM, WALLS THROUGHOUT	
	ROOM 10, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 11, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 12, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 13, WALLS THROUGHOUT, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 14, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 15, WALLS THROUGHOUT, SOUTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 16, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 17, WALLS THROUGHOUT, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 18, WALLS THROUGHOUT, PORTION OF EAST AND SOUTH PLENUM WALLS ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 19, WALLS THROUGHOUT, EAST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 20, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 21, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 22, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 23, WALLS THROUGHOUT, SOUTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	ROOM 24, WALLS THROUGHOUT, NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 25, WALLS THROUGHOUT, PORTION OF NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 26, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 27, WALLS THROUGHOUT, PORTION OF WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 28, WALLS THROUGHOUT, NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 29, WALLS THROUGHOUT, NORTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	ROOM 30, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 31, WALLS THROUGHOUT, SOUTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	MUSIC, NORTH, WEST, SOUTH AND PORTION OF EAST WALLS, NORTH AND PORTION OF EAST AND WEST PLENUM WALLS ABOVE CEILING	
	STORAGE 6, WALLS THROUGHOUT	
	MULTI-PURPOSE, PORTION OF WEST WALL	
	STORAGE 4, WALLS THROUGHOUT	
	STORAGE 5, WALLS THROUGHOUT	
	P.E. OFFICE, WALLS THROUGHOUT	
	CORRIDOR 14, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	CORRIDOR 15, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	CORRIDOR 16, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	RECEPTION, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	S
	TREATMENT, WALLS THROUGHOUT	
	NURSE'S OFFICE, WALLS THROUGHOUT	
	PRINCIPAL OFFICE, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	PSY/CONF., WALLS THROUGHOUT	
	FACULTY WORK, WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	FACULTY LOUNGE, EAST, WEST AND SOUTH WALLS	
	STORAGE 2, WALLS THROUGHOUT	
	JANITOR, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	LIBRARY, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	LIBRARY WORKROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	COMPUTER, WALLS THROUGHOUT, WEST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SERVER ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	SPEECH, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	STORAGE 3, WALLS THROUGHOUT	
	TEST ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	SPECIAL ED. 1, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST, SOUTH AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SPECIAL ED. 2, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, EAST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SPECIAL ED. 3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	TIMEOUT ROOM, WALLS THROUGHOUT	
	ROOM 10, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 11, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 12, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 13, WALLS THROUGHOUT, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 14, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 15, WALLS THROUGHOUT, SOUTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 16, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 17, WALLS THROUGHOUT, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 18, WALLS THROUGHOUT, PORTION OF EAST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 19, WALLS THROUGHOUT, EAST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 20, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 21, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 22, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 23, WALLS THROUGHOUT, SOUTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 24, WALLS THROUGHOUT, NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 25, WALLS THROUGHOUT, PORTION OF NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 26, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 27, WALLS THROUGHOUT, PORTION OF WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 28, WALLS THROUGHOUT, NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 29, WALLS THROUGHOUT, NORTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	ROOM 30, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 31, WALLS THROUGHOUT, SOUTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	MUSIC, NORTH, WEST, SOUTH AND PORTION OF EAST WALLS, NORTH AND PORTION OF EAST AND WEST PLENUM WALLS ABOVE CEILING	
	STORAGE 6, WALLS THROUGHOUT	
	MULTI-PURPOSE, PORTION OF WEST WALL	
	STORAGE 4, WALLS THROUGHOUT	
	STORAGE 5, WALLS THROUGHOUT	
	P.E. OFFICE, WALLS THROUGHOUT	
	CORRIDOR 14, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	CORRIDOR 15, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	CORRIDOR 16, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	RECEPTION, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	S
	TREATMENT, WALLS THROUGHOUT	
	NURSE'S OFFICE, WALLS THROUGHOUT	
	PRINCIPAL OFFICE, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	PSY/CONF., WALLS THROUGHOUT	
	FACULTY WORK, WALLS THROUGHOUT	
	FACULTY LOUNGE, EAST, WEST AND SOUTH WALLS	
	STORAGE 2, WALLS THROUGHOUT	
	JANITOR, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	LIBRARY, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	LIBRARY WORKROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	COMPUTER, WALLS THROUGHOUT, WEST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SERVER ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	SPEECH, WALLS THROUGHOUT, WEST PLENUM WALL ABOVE CEILING	
	STORAGE 3, WALLS THROUGHOUT	
	TEST ROOM, WALLS THROUGHOUT, EAST PLENUM WALL ABOVE CEILING	
	SPECIAL ED. 1, EAST, WEST, SOUTH AND PORTION OF NORTH WALLS, EAST, SOUTH AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SPECIAL ED. 2, EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS, EAST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	SPECIAL ED. 3, NORTH, EAST, WEST AND PORTION OF SOUTH WALLS, EAST AND PORTION OF NORTH PLENUM WALLS ABOVE CEILING	
	TIMEOUT ROOM, WALLS THROUGHOUT	
	ROOM 10, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 11, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 12, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 13, WALLS THROUGHOUT, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 14, WALLS THROUGHOUT, SOUTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 15, WALLS THROUGHOUT, SOUTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 16, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 17, WALLS THROUGHOUT, NORTH AND EAST PLENUM WALLS ABOVE CEILING	
	ROOM 18, WALLS THROUGHOUT, PORTION OF EAST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 19, WALLS THROUGHOUT, EAST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 20, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 21, WALLS THROUGHOUT, NORTH AND PORTION OF EAST PLENUM WALLS ABOVE CEILING	
	ROOM 22, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 23, WALLS THROUGHOUT, SOUTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	ROOM 24, WALLS THROUGHOUT, NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 25, WALLS THROUGHOUT, PORTION OF NORTH AND WEST PLENUM WALLS ABOVE CEILING	
	ROOM 26, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 27, WALLS THROUGHOUT, PORTION OF WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 28, WALLS THROUGHOUT, NORTH AND WEST PLENUM WALLS ABOVE CEILING	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 29, WALLS THROUGHOUT, NORTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	ROOM 30, WALLS THROUGHOUT, WEST AND SOUTH PLENUM WALLS ABOVE CEILING	
	ROOM 31, WALLS THROUGHOUT, SOUTH AND PORTION OF WEST PLENUM WALLS ABOVE CEILING	
	MUSIC, NORTH, WEST, SOUTH AND PORTION OF EAST WALLS, NORTH AND PORTION OF EAST AND WEST PLENUM WALLS ABOVE CEILING	
	STORAGE 6, WALLS THROUGHOUT	
	MULTI-PURPOSE, PORTION OF WEST WALL	
	STORAGE 4, WALLS THROUGHOUT	
	STORAGE 5, WALLS THROUGHOUT	
	P.E. OFFICE, WALLS THROUGHOUT	
	CORRIDOR 14, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	CORRIDOR 15, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	CORRIDOR 16, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	RECEPTION, PORTION OF WEST WALL	S
	HALL 1, PORTION OF EAST WALL	
	PRINCIPAL OFFICE, PORTION OF EAST AND SOUTH WALLS	
	PSY/CONF., PORTION OF SOUTH WALL	
	FACULTY LOUNGE, PORTION OF NORTH AND WEST WALLS	
	COMPUTER, PORTION OF NORTH, EAST AND WEST WALLS	
	SPEECH, PORTION OF NORTH AND WEST WALLS	
	SPECIAL ED. 1, PORTION OF SOUTH WALL	
	SPECIAL ED. 2, PORTION OF EAST WALL	
	SPECIAL ED. 3, PORTION OF NORTH WALL	
	ROOM 10, PORTION OF NORTH AND WEST WALLS	
	ROOM 11, PORTION OF NORTH WALL	
	ROOM 12, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 13, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 14, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 15, PORTION OF NORTH, WEST AND SOUTH WALLS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 16, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 17, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 18, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 19, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 20, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 21, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 22, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 23, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 24, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 25, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 26, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 27, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 28, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 29, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 30, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 31, PORTION OF NORTH, EAST AND SOUTH WALLS	
	MUSIC, PORTION OF WEST WALL	
	MULTI-PURPOSE, PORTION OF WEST WALL	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	RECEPTION, PORTION OF WEST WALL	S
	HALL 1, PORTION OF EAST WALL	
	PRINCIPAL OFFICE, PORTION OF EAST AND SOUTH WALLS	
	PSY/CONF., PORTION OF SOUTH WALL	
	FACULTY LOUNGE, PORTION OF NORTH AND WEST WALLS	
	COMPUTER, PORTION OF NORTH, EAST AND WEST WALLS	
	SPEECH, PORTION OF NORTH AND WEST WALLS	
	SPECIAL ED. 1, PORTION OF SOUTH WALL	
	SPECIAL ED. 2, PORTION OF EAST WALL	
	SPECIAL ED. 3, PORTION OF NORTH WALL	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 10, PORTION OF NORTH AND WEST WALLS	
	ROOM 11, PORTION OF NORTH WALL	
	ROOM 12, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 13, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 14, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 15, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 16, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 17, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 18, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 19, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 20, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 21, PORTION OF NORTH, WEST AND SOUTH WALLS	
	ROOM 22, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 23, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 24, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 25, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 26, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 27, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 28, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 29, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 30, PORTION OF NORTH, EAST AND SOUTH WALLS	
	ROOM 31, PORTION OF NORTH, EAST AND SOUTH WALLS	
	MUSIC, PORTION OF WEST WALL	
	MULTI-PURPOSE, PORTION OF WEST WALL	
CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	RECEPTION, FLOOR THROUGHOUT	S
	TREATMENT, FLOOR THROUGHOUT	
	NURSE'S OFFICE, FLOOR THROUGHOUT	
	PRINCIPAL OFFICE, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	COUNSELOR, FLOOR THROUGHOUT	
	PSY/CONF., FLOOR THROUGHOUT	
	FACULTY LOUNGE, FLOOR THROUGHOUT LESS WET AREA	
	LIBRARY, FLOOR THROUGHOUT	
	COMPUTER, FLOOR THROUGHOUT LESS WET AREA	
	SPEECH, FLOOR THROUGHOUT	
	STORAGE 3, FLOOR THROUGHOUT	
	SPECIAL ED. 1, FLOOR THROUGHOUT LESS WET AREA	
	SPECIAL ED. 2, FLOOR THROUGHOUT LESS WET AREA	
	SPECIAL ED. 3, FLOOR THROUGHOUT LESS WET AREA	
	ROOM 10, FLOOR THROUGHOUT LESS SOUTH ENTRY AND WET AREA	
	ROOM 11, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	
	ROOM 12, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 13, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 14, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 15, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 16, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 17, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 18, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 19, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 20, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 21, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 22, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 23, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 24, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 25, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 26, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 27, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 28, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 29, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 30, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 31, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	MUSIC, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	STAGE, FLOOR THROUGHOUT	
	NORTH WING, FLOOR THROUGHOUT	
	SOUTH WING, FLOOR THROUGHOUT	
	MULTI-PURPOSE, PORTION OF FLOOR	
	CORRIDOR 1, FLOOR THROUGHOUT	
	CORRIDOR 2, FLOOR THROUGHOUT	
	CORRIDOR 3, FLOOR THROUGHOUT	
	CORRIDOR 4, FLOOR THROUGHOUT	
	CORRIDOR 5, FLOOR THROUGHOUT	
	CORRIDOR 6, FLOOR THROUGHOUT	
	WEST FOYER, FLOOR THROUGHOUT	
	CORRIDOR 7, FLOOR THROUGHOUT	
	CORRIDOR 8, FLOOR THROUGHOUT	
	CORRIDOR 9, FLOOR THROUGHOUT	
	CORRIDOR 10, FLOOR THROUGHOUT	
	EAST FOYER, FLOOR THROUGHOUT	
	CORRIDOR 11, FLOOR THROUGHOUT	
	CORRIDOR 12, FLOOR THROUGHOUT	
	CORRIDOR 13, FLOOR THROUGHOUT	
	CORRIDOR 14, FLOOR THROUGHOUT	
	CORRIDOR 15, FLOOR THROUGHOUT	
	CORRIDOR 16, FLOOR THROUGHOUT	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	RECEPTION, FLOOR THROUGHOUT	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	TREATMENT, FLOOR THROUGHOUT	
	NURSE'S OFFICE, FLOOR THROUGHOUT	
	PRINCIPAL OFFICE, FLOOR THROUGHOUT	
	COUNSELOR, FLOOR THROUGHOUT	
	PSY/CONF., FLOOR THROUGHOUT	
	FACULTY LOUNGE, FLOOR THROUGHOUT LESS WET AREA	
	LIBRARY, FLOOR THROUGHOUT	
	COMPUTER, FLOOR THROUGHOUT LESS WET AREA	
	SPEECH, FLOOR THROUGHOUT	
	STORAGE 3, FLOOR THROUGHOUT	
	SPECIAL ED. 1, FLOOR THROUGHOUT LESS WET AREA	
	SPECIAL ED. 2, FLOOR THROUGHOUT LESS WET AREA	
	SPECIAL ED. 3, FLOOR THROUGHOUT LESS WET AREA	
	ROOM 10, FLOOR THROUGHOUT LESS SOUTH ENTRY AND WET AREA	
	ROOM 11, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	
	ROOM 12, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 13, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 14, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 15, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 16, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 17, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 18, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 19, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 20, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 21, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 22, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 23, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 24, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 25, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 26, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 27, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 28, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 29, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 30, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	ROOM 31, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	MUSIC, FLOOR THROUGHOUT LESS ENTRY AND WET AREA	
	STAGE, FLOOR THROUGHOUT	
	NORTH WING, FLOOR THROUGHOUT	
	SOUTH WING, FLOOR THROUGHOUT	
	MULTI-PURPOSE, PORTION OF FLOOR	
	CORRIDOR 1, FLOOR THROUGHOUT	
	CORRIDOR 2, FLOOR THROUGHOUT	
	CORRIDOR 3, FLOOR THROUGHOUT	
	CORRIDOR 4, FLOOR THROUGHOUT	
	CORRIDOR 5, FLOOR THROUGHOUT	
	CORRIDOR 6, FLOOR THROUGHOUT	
	WEST FOYER, FLOOR THROUGHOUT	
	CORRIDOR 7, FLOOR THROUGHOUT	
	CORRIDOR 8, FLOOR THROUGHOUT	
	CORRIDOR 9, FLOOR THROUGHOUT	
	CORRIDOR 10, FLOOR THROUGHOUT	
	EAST FOYER, FLOOR THROUGHOUT	
	CORRIDOR 11, FLOOR THROUGHOUT	
	CORRIDOR 12, FLOOR THROUGHOUT	
	CORRIDOR 13, FLOOR THROUGHOUT	
	CORRIDOR 14, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 15, FLOOR THROUGHOUT	
	CORRIDOR 16, FLOOR THROUGHOUT	
GLASS BLOCK, 8"X8", CLEAR	RECEPTION, NORTH WINDOW	N
	TREATMENT, NORTH WINDOW	
	NURSE'S OFFICE, NORTH AND EAST WINDOWS	
	PSY/CONF., EAST WINDOWS	
	FACULTY WORK, EAST WINDOW	
	COMPUTER, WEST WINDOW	
	SPECIAL ED. 1, EAST WINDOW	
	SPECIAL ED. 2, EAST WINDOW	
	SPECIAL ED. 3, EAST WINDOW	
	ROOM 10, SOUTH WINDOW	
	ROOM 11, EAST WINDOW	
	ROOM 12, NORTH WINDOW	
	ROOM 13, NORTH WINDOW	
	ROOM 14, SOUTH WINDOW	
	ROOM 15, SOUTH WINDOW	
	ROOM 16, NORTH WINDOW	
	ROOM 17, NORTH WINDOW	
	ROOM 18, SOUTH WINDOW	
	ROOM 19, SOUTH WINDOW	
	ROOM 20, NORTH WINDOW	
	ROOM 21, NORTH WINDOW	
	ROOM 22, SOUTH WINDOW	
	ROOM 23, SOUTH WINDOW	
	ROOM 24, NORTH WINDOW	
	ROOM 25, NORTH WINDOW	
	ROOM 26, SOUTH WINDOW	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 27, SOUTH WINDOW	
	ROOM 28, NORTH WINDOW	
	ROOM 29, NORTH WINDOW	
	ROOM 30, SOUTH WINDOW	
	ROOM 31, SOUTH WINDOW	
	MULTI-PURPOSE, SOUTH WINDOW	
	CORRIDOR 3, NORTH AND WEST WINDOWS	
	CORRIDOR 4, NORTH AND SOUTH WINDOWS	
	CORRIDOR 5, NORTH AND SOUTH WINDOWS	
	CORRIDOR 6, NORTH AND SOUTH WINDOWS	
	WEST FOYER, EAST AND SOUTH WINDOWS	
	CORRIDOR 7, SOUTH WINDOW	
	CORRIDOR 8, WEST WINDOW	
	CORRIDOR 9, NORTH AND EAST WINDOWS	
	CORRIDOR 10, WEST WINDOWS	
	EAST FOYER, SOUTH WINDOW	
	CORRIDOR 11, NORTH AND SOUTH WINDOWS	
	CORRIDOR 12, WINDOWS THROUGHOUT	
	CORRIDOR 13, NORTH WINDOW	
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WINDOWS	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	RECEPTION, NORTH WINDOW	S
	TREATMENT, NORTH WINDOW	
	NURSE'S OFFICE, NORTH AND EAST WINDOWS	
	PSY/CONF., EAST WINDOWS	
	FACULTY WORK, EAST WINDOW	
	COMPUTER, WEST WINDOW	
	SPECIAL ED. 1, EAST WINDOW	
	SPECIAL ED. 2, EAST WINDOW	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	SPECIAL ED. 3, EAST WINDOW	
	ROOM 10, SOUTH WINDOW	
	ROOM 11, EAST WINDOW	
	ROOM 12, NORTH WINDOW	
	ROOM 13, NORTH WINDOW	
	ROOM 14, SOUTH WINDOW	
	ROOM 15, SOUTH WINDOW	
	ROOM 16, NORTH WINDOW	
	ROOM 17, NORTH WINDOW	
	ROOM 18, SOUTH WINDOW	
	ROOM 19, SOUTH WINDOW	
	ROOM 20, NORTH WINDOW	
	ROOM 21, NORTH WINDOW	
	ROOM 22, SOUTH WINDOW	
	ROOM 23, SOUTH WINDOW	
	ROOM 24, NORTH WINDOW	
	ROOM 25, NORTH WINDOW	
	ROOM 26, SOUTH WINDOW	
	ROOM 27, SOUTH WINDOW	
	ROOM 28, NORTH WINDOW	
	ROOM 29, NORTH WINDOW	
	ROOM 30, SOUTH WINDOW	
	ROOM 31, SOUTH WINDOW	
	MULTI-PURPOSE, SOUTH WINDOW	
	CORRIDOR 3, NORTH AND WEST WINDOWS	
	CORRIDOR 4, NORTH AND SOUTH WINDOWS	
	CORRIDOR 5, NORTH AND SOUTH WINDOWS	
	CORRIDOR 6, NORTH AND SOUTH WINDOWS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Del Sureno Elementary School
Main Building

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	WEST FOYER, EAST AND SOUTH WINDOWS	
	CORRIDOR 7, SOUTH WINDOW	
	CORRIDOR 8, WEST WINDOW	
	CORRIDOR 9, NORTH AND EAST WINDOWS	
	CORRIDOR 10, WEST WINDOWS	
	EAST FOYER, SOUTH WINDOW	
	CORRIDOR 11, NORTH AND SOUTH WINDOWS	
	CORRIDOR 12, WINDOWS THROUGHOUT	
	CORRIDOR 13, NORTH WINDOW	
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WINDOWS	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	RECEPTION, BASE OF WALLS THROUGHOUT	S
	TREATMENT, BASE OF WALLS THROUGHOUT	
	NURSE'S OFFICE, BASE OF WALLS THROUGHOUT	
	HEARING, BASE OF WALLS THROUGHOUT	
	STORAGE 1, BASE OF WALLS THROUGHOUT	
	HALL 1, BASE OF WALLS THROUGHOUT	
	NORTH FOYER, BASE OF WALLS THROUGHOUT	
	PRINCIPAL OFFICE, BASE OF WALLS THROUGHOUT	
	COUNSELOR, BASE OF WALLS THROUGHOUT	
	PSY/CONF. , BASE OF WALLS THROUGHOUT	
	FACULTY WORK, BASE OF WALLS THROUGHOUT	
	FACULTY LOUNGE, BASE OF WALLS THROUGHOUT	
	MEN'S RESTROOM, BASE OF WALLS THROUGHOUT	
	WOMEN'S RESTROOM, BASE OF WALLS THROUGHOUT	
	UNISEX RESTROOM, BASE OF WALLS THROUGHOUT	
	JANITOR, BASE OF NORTH AND PORTION EAST AND SOUTH WALLS	
	LIBRARY, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	COMPUTER, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	SPEECH, BASE OF WALLS THROUGHOUT	
	STORAGE 3, BASE OF WALLS THROUGHOUT	
	TEST ROOM, BASE OF WALLS THROUGHOUT	
	SPECIAL ED. 1, BASE OF EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	SPECIAL ED. 2, BASE OF EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	SPECIAL ED. 3, BASE OF NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	ROOM 10, BASE OF WALLS THROUGHOUT	
	ROOM 11, BASE OF WALLS THROUGHOUT	
	ROOM 12, BASE OF WALLS THROUGHOUT	
	ROOM 13, BASE OF WALLS THROUGHOUT	
	ROOM 14, BASE OF WALLS THROUGHOUT	
	ROOM 15, BASE OF WALLS THROUGHOUT	
	ROOM 16, BASE OF WALLS THROUGHOUT	
	ROOM 17, BASE OF WALLS THROUGHOUT	
	ROOM 18, BASE OF WALLS THROUGHOUT	
	ROOM 19, BASE OF WALLS THROUGHOUT	
	ROOM 20, BASE OF WALLS THROUGHOUT	
	ROOM 21, BASE OF WALLS THROUGHOUT	
	ROOM 22, BASE OF WALLS THROUGHOUT	
	ROOM 23, BASE OF WALLS THROUGHOUT	
	ROOM 24, BASE OF WALLS THROUGHOUT	
	ROOM 25, BASE OF WALLS THROUGHOUT	
	ROOM 26, BASE OF WALLS THROUGHOUT	
	ROOM 27, BASE OF WALLS THROUGHOUT	
	ROOM 28, BASE OF WALLS THROUGHOUT	
	ROOM 29, BASE OF WALLS THROUGHOUT	
	ROOM 30, BASE OF WALLS THROUGHOUT	
	ROOM 31, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	MUSIC, BASE OF WALLS THROUGHOUT	
	NORTH WING, BASE OF WALLS THROUGHOUT	
	MULTI-PURPOSE, BASE OF NORTH, WEST AND SOUTH WALLS	
	KITCHEN WATER HEATER CLOSET, BASE OF WALLS THROUGHOUT	
	P.E. OFFICE, BASE OF WALLS THROUGHOUT	
	CORRIDOR 1, BASE OF WALLS THROUGHOUT	
	CORRIDOR 2, BASE OF WALLS THROUGHOUT	
	CORRIDOR 3, BASE OF WALLS THROUGHOUT	
	CORRIDOR 4, BASE OF WALLS THROUGHOUT	
	CORRIDOR 5, BASE OF WALLS THROUGHOUT	
	CORRIDOR 6, BASE OF WALLS THROUGHOUT	
	WEST FOYER, BASE OF WALLS THROUGHOUT	
	CORRIDOR 7, BASE OF WALLS THROUGHOUT	
	CORRIDOR 8, BASE OF WALLS THROUGHOUT	
	CORRIDOR 9, BASE OF WALLS THROUGHOUT	
	CORRIDOR 10, BASE OF WALLS THROUGHOUT	
	EAST FOYER, BASE OF WALLS THROUGHOUT	
	CORRIDOR 11, BASE OF WALLS THROUGHOUT	
	CORRIDOR 12, BASE OF WALLS THROUGHOUT	
	CORRIDOR 13, BASE OF WALLS THROUGHOUT	
	CORRIDOR 14, BASE OF WALLS THROUGHOUT	
	CORRIDOR 15, BASE OF WALLS THROUGHOUT	
	CORRIDOR 16, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	RECEPTION, BASE OF WALLS THROUGHOUT	S
	TREATMENT, BASE OF WALLS THROUGHOUT	
	NURSE'S OFFICE, BASE OF WALLS THROUGHOUT	
	HEARING, BASE OF WALLS THROUGHOUT	
	STORAGE 1, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	HALL 1, BASE OF WALLS THROUGHOUT	
	NORTH FOYER, BASE OF WALLS THROUGHOUT	
	PRINCIPAL OFFICE, BASE OF WALLS THROUGHOUT	
	COUNSELOR, BASE OF WALLS THROUGHOUT	
	PSY/CONF. , BASE OF WALLS THROUGHOUT	
	FACULTY WORK, BASE OF WALLS THROUGHOUT	
	FACULTY LOUNGE, BASE OF WALLS THROUGHOUT	
	MEN'S RESTROOM, BASE OF WALLS THROUGHOUT	
	WOMEN'S RESTROOM, BASE OF WALLS THROUGHOUT	
	UNISEX RESTROOM, BASE OF WALLS THROUGHOUT	
	JANITOR, BASE OF NORTH AND PORTION EAST AND SOUTH WALLS	
	LIBRARY, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	COMPUTER, BASE OF WALLS THROUGHOUT	
	SPEECH, BASE OF WALLS THROUGHOUT	
	STORAGE 3, BASE OF WALLS THROUGHOUT	
	TEST ROOM, BASE OF WALLS THROUGHOUT	
	SPECIAL ED. 1, BASE OF EAST, WEST, SOUTH AND PORTION OF NORTH WALLS	
	SPECIAL ED. 2, BASE OF EAST, WEST AND PORTION OF NORTH AND SOUTH WALLS	
	SPECIAL ED. 3, BASE OF NORTH, EAST, WEST AND PORTION OF SOUTH WALLS	
	ROOM 10, BASE OF WALLS THROUGHOUT	
	ROOM 11, BASE OF WALLS THROUGHOUT	
	ROOM 12, BASE OF WALLS THROUGHOUT	
	ROOM 13, BASE OF WALLS THROUGHOUT	
	ROOM 14, BASE OF WALLS THROUGHOUT	
	ROOM 15, BASE OF WALLS THROUGHOUT	
	ROOM 16, BASE OF WALLS THROUGHOUT	
	ROOM 17, BASE OF WALLS THROUGHOUT	
	ROOM 18, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 19, BASE OF WALLS THROUGHOUT	
	ROOM 20, BASE OF WALLS THROUGHOUT	
	ROOM 21, BASE OF WALLS THROUGHOUT	
	ROOM 22, BASE OF WALLS THROUGHOUT	
	ROOM 23, BASE OF WALLS THROUGHOUT	
	ROOM 24, BASE OF WALLS THROUGHOUT	
	ROOM 25, BASE OF WALLS THROUGHOUT	
	ROOM 26, BASE OF WALLS THROUGHOUT	
	ROOM 27, BASE OF WALLS THROUGHOUT	
	ROOM 28, BASE OF WALLS THROUGHOUT	
	ROOM 29, BASE OF WALLS THROUGHOUT	
	ROOM 30, BASE OF WALLS THROUGHOUT	
	ROOM 31, BASE OF WALLS THROUGHOUT	
	MUSIC, BASE OF WALLS THROUGHOUT	
	NORTH WING, BASE OF WALLS THROUGHOUT	
	MULTI-PURPOSE, BASE OF NORTH, WEST AND SOUTH WALLS	
	KITCHEN WATER HEATER CLOSET, BASE OF WALLS THROUGHOUT	
	P.E. OFFICE, BASE OF WALLS THROUGHOUT	
	CORRIDOR 1, BASE OF WALLS THROUGHOUT	
	CORRIDOR 2, BASE OF WALLS THROUGHOUT	
	CORRIDOR 3, BASE OF WALLS THROUGHOUT	
	CORRIDOR 4, BASE OF WALLS THROUGHOUT	
	CORRIDOR 5, BASE OF WALLS THROUGHOUT	
	CORRIDOR 6, BASE OF WALLS THROUGHOUT	
	WEST FOYER, BASE OF WALLS THROUGHOUT	
	CORRIDOR 7, BASE OF WALLS THROUGHOUT	
	CORRIDOR 8, BASE OF WALLS THROUGHOUT	
	CORRIDOR 9, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 10, BASE OF WALLS THROUGHOUT	
	EAST FOYER, BASE OF WALLS THROUGHOUT	
	CORRIDOR 11, BASE OF WALLS THROUGHOUT	
	CORRIDOR 12, BASE OF WALLS THROUGHOUT	
	CORRIDOR 13, BASE OF WALLS THROUGHOUT	
	CORRIDOR 14, BASE OF WALLS THROUGHOUT	
	CORRIDOR 15, BASE OF WALLS THROUGHOUT	
	CORRIDOR 16, BASE OF WALLS THROUGHOUT	
FIRE DOOR INSULATION, METAL CLADDING	RECEPTION, NORTH DOORS	S
	TREATMENT, NORTH DOOR	
	WEST BOY'S RESTROOM, WEST DOOR	
	WEST VESTIBULE, WEST DOOR	
	ROOM 10, NORTH DOOR	
	ROOM 11, NORTH DOOR	
	MULTI-PURPOSE, EAST AND PORTION OF SOUTH DOORS	
	KITCHEN, SOUTH DOORS	
	CORRIDOR 3, NORTH DOORS	
	CORRIDOR 4, WEST DOORS	
	CORRIDOR 5, WEST DOORS	
	CORRIDOR 6, WEST DOORS	
	CORRIDOR 7, SOUTH DOORS	
	CORRIDOR 8, WEST DOORS	
	CORRIDOR 9, EAST DOORS	
	CORRIDOR 11, EAST DOORS	
	CORRIDOR 12, EAST DOORS	
	CORRIDOR 13, NORTH DOORS	
	EXTERIOR, NORTH, WEST AND PORTION OF EAST AND SOUTH DOORS	
FIRE DOOR INSULATION, WOOD CLADDING	RECEPTION, WEST DOOR	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	NURSE'S RESTROOM, NORTH DOOR	
	STORAGE 1, WEST DOOR	
	NORTH FOYER, EAST AND SOUTH DOORS	
	MEN'S RESTROOM, NORTH DOOR	
	WOMEN'S RESTROOM, NORTH DOOR	
	JANITOR, NORTH DOOR	
	LIBRARY WORKROOM, SOUTH DOOR	
	SERVER ROOM, NORTH DOOR	
	SPEECH, WEST DOOR	
	SPECIAL ED. 3, EAST DOOR	
	TEST ROOM, EAST DOOR	
	SPECIAL ED. 2, EAST DOOR	
	SPECIAL ED. 1, EAST DOOR	
	SOUTH BOY'S RESTROOM, SOUTH DOOR	
	SOUTH GIRL'S RESTROOM HALL, SOUTH DOOR	
	ROOM 10, SOUTH DOOR	
	ROOM 11, SOUTH DOOR	
	ROOM 12, NORTH DOOR	
	ROOM 13, NORTH DOOR	
	ROOM 14, SOUTH DOOR	
	ROOM 15, SOUTH DOOR	
	ROOM 16, NORTH DOOR	
	ROOM 17, NORTH DOOR	
	ROOM 18, SOUTH DOOR	
	ROOM 19, SOUTH DOOR	
	ROOM 20, NORTH DOOR	
	ROOM 21, NORTH DOOR	
	ROOM 22, SOUTH DOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Del Sureno Elementary School
Main Building

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 23, SOUTH DOOR	
	ROOM 24, NORTH DOOR	
	ROOM 25, NORTH DOOR	
	ROOM 26, SOUTH DOOR	
	ROOM 27, SOUTH DOOR	
	ROOM 28, NORTH DOOR	
	ROOM 29, NORTH DOOR	
	ROOM 30, SOUTH DOOR	
	ROOM 31, DOORS THROUGHOUT	
	MUSIC, NORTH AND SOUTH DOORS	
	STORAGE 6, NORTH DOOR	
	MULTI-PURPOSE, NORTH AND SOUTH DOORS	
	KITCHEN WATER HEATER CLOSET, NORTH DOOR	
	STORAGE 4, NORTH DOORS	
	STORAGE 5, DOORS THROUGHOUT	
	KITCHEN, NORTH DOOR	
	EAST BOY'S RESTROOM, SOUTH DOOR	
	EAST GIRL'S RESTROOM, NORTH DOOR	
	CORRIDOR 1, SOUTH DOOR	
	CORRIDOR 2, DOORS THROUGHOUT	
	CORRIDOR 3, EAST AND WEST DOORS	
	CORRIDOR 4, NORTH AND SOUTH DOORS	
	CORRIDOR 5, NORTH AND SOUTH DOORS	
	CORRIDOR 6, NORTH AND SOUTH DOORS	
	WEST FOYER, SOUTH DOOR	
	CORRIDOR 7, EAST DOOR	
	CORRIDOR 8, NORTH AND SOUTH DOORS	
	CORRIDOR 9, NORTH DOORS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Del Sureno Elementary School
Main Building

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 10, WEST DOORS	
	EAST FOYER, SOUTH DOOR	
	CORRIDOR 11, NORTH AND SOUTH DOORS	
	CORRIDOR 12, NORTH AND SOUTH DOORS	
SEALANT, WHITE, PLIABLE	RECEPTION, DOORS THROUGHOUT, NORTH WINDOW	S
	TREATMENT, DOORS THROUGHOUT	
	NURSE'S RESTROOM, NORTH DOOR	
	HEARING, WEST DOOR	
	STORAGE 1, WEST DOOR	
	HALL 1, NORTH DOOR	
	NORTH FOYER, EAST AND SOUTH DOORS	
	PRINCIPAL OFFICE, DOORS THROUGHOUT	
	PRINCIPAL OFFICE CLOSET, WEST DOOR	
	COUNSELOR, WEST DOOR	
	PSY/CONF., WEST DOOR	
	FACULTY WORK, DOORS THROUGHOUT, MILLWORK	
	FACULTY LOUNGE, WEST DOOR	
	MEN'S RESTROOM, NORTH DOOR, MILLWORK, FIXTURES	
	WOMEN'S RESTROOM, NORTH DOOR, MILLWORK, FIXTURES	
	STORAGE 2, EAST DOOR	
	UNISEX RESTROOM, WEST DOOR, FIXTURES	
	JANITOR, NORTH AND SOUTH DOORS	
	ELEC. CLOSET, NORTH DOOR	
	LIBRARY, SOUTH DOORS, MILLWORK	
	LIBRARY WORKROOM, DOORS THROUGHOUT, MILLWORK	
	COMPUTER, WEST DOOR, MILLWORK	
	SERVER ROOM, NORTH DOOR	
	SPEECH, DOORS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	STORAGE 3, WEST DOOR	
	TEST ROOM, EAST DOOR	
	SPECIAL ED. 1, EAST DOOR	
	SPECIAL ED. 2, EAST DOOR	
	SPECIAL ED. 3, EAST DOOR	
	SOUTH BOY'S RESTROOM, MILLWORK, FIXTURES	
	SOUTH GIRL'S RESTROOM, MILLWORK, FIXTURES	
	SOUTH GIRL'S RESTROOM HALL, DOORS THROUGHOUT	
	ROOM 10, SOUTH DOORS	
	ROOM 10 TOILET, NORTH DOOR	
	ROOM 11, EAST AND SOUTH DOORS	
	ROOM 11 TOILET, NORTH DOOR	
	ROOM 12, NORTH DOOR, MILLWORK	
	ROOM 13, NORTH DOOR, MILLWORK	
	ROOM 14, SOUTH DOOR, MILLWORK	
	ROOM 15, SOUTH DOOR, MILLWORK	
	WEST BOY'S RESTROOM, MILLWORK, FIXTURES	
	WEST GIRL'S RESTROOM, MILLWORK, FIXTURES	
	WEST GIRL'S RESTROOM HALL, DOORS THROUGHOUT	
	ROOM 16, NORTH DOOR, MILLWORK	
	ROOM 17, NORTH DOOR, MILLWORK	
	ROOM 18, SOUTH DOOR, MILLWORK	
	ROOM 19, SOUTH DOOR, MILLWORK	
	ROOM 20, NORTH DOOR, MILLWORK	
	ROOM 21, NORTH DOOR, MILLWORK	
	ROOM 22, SOUTH DOOR, MILLWORK	
	ROOM 23, SOUTH DOOR, MILLWORK	
	ROOM 24, NORTH DOOR, MILLWORK	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 25, NORTH DOOR, MILLWORK	
	ROOM 26, SOUTH DOOR, MILLWORK	
	ROOM 27, SOUTH DOOR, MILLWORK	
	ROOM 28, NORTH DOOR, MILLWORK	
	ROOM 29, NORTH DOOR, MILLWORK	
	ROOM 30, SOUTH DOOR, MILLWORK	
	ROOM 31, SOUTH DOOR, MILLWORK	
	MUSIC, DOORS THROUGHOUT, MILLWORK	
	NORTH WING, DOORS THROUGHOUT	
	MULTI-PURPOSE, NORTH AND SOUTH DOORS	
	KITCHEN WATER HEATER CLOSET, NORTH DOOR	
	STORAGE 4, DOORS THROUGHOUT	
	STORAGE 5, SOUTH DOOR	
	P.E. OFFICE, WEST DOOR	
	KITCHEN, DOORS THROUGHOUT, MILLWORK	
	EAST BOY'S RESTROOM, SOUTH DOOR, MILLWORK, FIXTURES	
	EAST GIRL'S RESTROOM, NORTH DOOR, MILLWORK, FIXTURES	
	CORRIDOR 1, DOORS THROUGHOUT	
	CORRIDOR 2, DOORS THROUGHOUT	
	CORRIDOR 3, EAST DOOR	
	CORRIDOR 5, EAST AND SOUTH DOORS	
	WEST FOYER, NORTH DOORS	
	CORRIDOR 7, EAST DOOR	
	CORRIDOR 8, NORTH DOOR	
	EAST FOYER, NORTH DOORS	
	CORRIDOR 12, SOUTH DOORS	
	CORRIDOR 13, WEST DOORS	
	CORRIDOR 14, DOORS THROUGHOUT, MILLWORK	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 15, DOORS THROUGHOUT, MILLWORK	
	CORRIDOR 16, DOORS THROUGHOUT	
GLAZED WALL TILE, 6"X6", WHITE, SMOOTH, VARIOUS	RECEPTION, PORTION OF SOUTH WALL	S
	CORRIDOR 14, PORTION OF WEST WALL	
	CORRIDOR 15, PORTION OF EAST WALL	
	CORRIDOR 16, PORTION OF SOUTH WALL	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 6"X6", WHITE, SMOOTH, VARIOUS	RECEPTION, PORTION OF SOUTH WALL	S
	CORRIDOR 14, PORTION OF WEST WALL	
	CORRIDOR 15, PORTION OF EAST WALL	
	CORRIDOR 16, PORTION OF SOUTH WALL	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	TREATMENT, EAST WALL	S
	NURSE'S OFFICE, WEST WALL	
	HALL 1, PORTION OF SOUTH WALL	
	COUNSELOR, NORTH WALL	
	FACULTY LOUNGE, NORTH WALL	
	SPEECH, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, PORTION OF CEILING	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	TREATMENT, EAST WALL	S
	NURSE'S OFFICE, WEST WALL	
	HALL 1, PORTION OF SOUTH WALL	
	COUNSELOR, NORTH WALL	
	FACULTY LOUNGE, NORTH WALL	
	SPEECH, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, PORTION OF CEILING	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	TREATMENT, EAST WALL	S
	NURSE'S OFFICE, WEST WALL	
	HALL 1, PORTION OF SOUTH WALL	
	COUNSELOR, NORTH WALL	
	FACULTY LOUNGE, NORTH WALL	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	SPEECH, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS, PORTION OF CEILING	
VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, TAN MOTTLES	HEARING, FLOOR THROUGHOUT	S
	STORAGE 1, FLOOR THROUGHOUT	
	NORTH FOYER, FLOOR THROUGHOUT	
	FACULTY WORK, FLOOR THROUGHOUT	
	FACULTY LOUNGE, WET AREA PORTION OF FLOOR	
	MEN'S RESTROOM, FLOOR THROUGHOUT	
	WOMEN'S RESTROOM, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	UNISEX RESTROOM, FLOOR THROUGHOUT	
	JANITOR, FLOOR THROUGHOUT	
	ELEC. CLOSET, FLOOR THROUGHOUT	
	LIBRARY WORKROOM, FLOOR THROUGHOUT	
	COMPUTER, WET AREA PORTION OF FLOOR	
	SERVER ROOM, FLOOR THROUGHOUT	
	SPECIAL ED. 3, WET AREA PORTION OF FLOOR	
	SPECIAL ED 2, WET AREA PORTION OF FLOOR	
	SPECIAL ED. 1, WET AREA PORTION OF FLOOR	
	SOUTH GIRL'S RESTROOM HALL, FLOOR THROUGHOUT	
	ROOM 10, SOUTH ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 11, EAST ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 12, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 13, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 14, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 15, ENTRY AND WET AREA PORTION OF FLOOR	
	WEST GIRL'S RESTROOM HALL, FLOOR THROUGHOUT	
	ROOM 16, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 17, ENTRY AND WET AREA PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 18, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 19, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 20, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 21, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 22, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 23, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 24, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 25, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 26, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 27, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 28, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 29, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 30, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 31, ENTRY AND WET AREA PORTION OF FLOOR	
	MUSIC, ENTRY AND WET AREA PORTION OF FLOOR	
	STORAGE 6, FLOOR THROUGHOUT	
	MULTI-PURPOSE, FLOOR THROUGHOUT	
	STORAGE 4, FLOOR THROUGHOUT	
	STORAGE 5, FLOOR THROUGHOUT	
	KITCHEN, FLOOR THROUGHOUT	
MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, TAN MOTTLES AND VINYL COMPOSITION TILE, 2"X24", BLACK, SMOOTH, YELLOW, RED, GREEN, BLUE, STRIP	HEARING, FLOOR THROUGHOUT	S
	STORAGE 1, FLOOR THROUGHOUT	
	NORTH FOYER, FLOOR THROUGHOUT	
	FACULTY WORK, FLOOR THROUGHOUT	
	FACULTY LOUNGE, WET AREA PORTION OF FLOOR	
	MEN'S RESTROOM, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	WOMEN'S RESTROOM, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	UNISEX RESTROOM, FLOOR THROUGHOUT	
	JANITOR, FLOOR THROUGHOUT	
	ELEC. CLOSET, FLOOR THROUGHOUT	
	LIBRARY WORKROOM, FLOOR THROUGHOUT	
	COMPUTER, WET AREA PORTION OF FLOOR	
	SERVER ROOM, FLOOR THROUGHOUT	
	SPECIAL ED. 3, WET AREA PORTION OF FLOOR	
	SPECIAL ED 2, WET AREA PORTION OF FLOOR	
	SPECIAL ED. 1, WET AREA PORTION OF FLOOR	
	SOUTH GIRL'S RESTROOM HALL, FLOOR THROUGHOUT	
	ROOM 10, SOUTH ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 11, EAST ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 12, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 13, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 14, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 15, ENTRY AND WET AREA PORTION OF FLOOR	
	WEST GIRL'S RESTROOM HALL, FLOOR THROUGHOUT	
	ROOM 16, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 17, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 18, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 19, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 20, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 21, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 22, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 23, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 24, ENTRY AND WET AREA PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 25, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 26, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 27, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 28, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 29, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 30, ENTRY AND WET AREA PORTION OF FLOOR	
	ROOM 31, ENTRY AND WET AREA PORTION OF FLOOR	
	MUSIC, ENTRY AND WET AREA PORTION OF FLOOR	
	STORAGE 6, FLOOR THROUGHOUT	
	MULTI-PURPOSE, FLOOR THROUGHOUT	
	STORAGE 4, FLOOR THROUGHOUT	
	STORAGE 5, FLOOR THROUGHOUT	
	KITCHEN, FLOOR THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 1, WALLS AND CEILING THROUGHOUT	S
	ELEC. CLOSET, WALLS THROUGHOUT	
	KITCHEN WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	STORAGE 1, WALLS AND CEILING THROUGHOUT	S
	ELEC. CLOSET, WALLS THROUGHOUT	
	KITCHEN WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	STORAGE 1, WALLS AND CEILING THROUGHOUT	S
	ELEC. CLOSET, WALLS THROUGHOUT	
	KITCHEN WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
GASKET, 8", RED, RUBBER-LIKE	STORAGE 1, PORTION OF PIPING	S
PANELING (WOOD), FACTORY FINISH	HEARING, WALLS THROUGHOUT	N
	TIMEOUT ROOM, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	STORAGE BUILDING, NORTH AND WEST WALLS	
GYPSUM WALLBOARD, WHITE, CHALKY	HALL 1, NORTH WALL	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	NORTH FOYER, WALLS THROUGHOUT	
	STAGE, PORTION OF NORTH, EAST AND SOUTH WALLS	
	NORTH WING, WALLS THROUGHOUT	
	SOUTH WING, PORTION OF NORTH AND WEST WALLS	
	CORRIDOR 1, WALLS THROUGHOUT	
	CORRIDOR 2, WALLS THROUGHOUT	
	CORRIDOR 3, WALLS THROUGHOUT, CLASSROOM ENTRY CEILING	
	CORRIDOR 4, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 5, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 6, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	WEST FOYER, WALLS THROUGHOUT, CLASSROOM ENTRY CEILING	
	CORRIDOR 7, WALLS THROUGHOUT	
	CORRIDOR 8, NORTH WALL, CLASSROOM ENTRY CEILING	
	CORRIDOR 9, NORTH WALL, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 10, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	EAST FOYER, WALLS THROUGHOUT, CLASSROOM ENTRY CEILING	
	CORRIDOR 11, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 12, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 13, WALLS THROUGHOUT	
	CORRIDOR 14, EAST WALL	
	CORRIDOR 15, WEST WALL	
	CORRIDOR 16, NORTH WALL	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	HALL 1, NORTH WALL	S
	NORTH FOYER, WALLS THROUGHOUT	
	STAGE, PORTION OF NORTH, EAST AND SOUTH WALLS	
	NORTH WING, WALLS THROUGHOUT	
	SOUTH WING, PORTION OF NORTH AND WEST WALLS	
	CORRIDOR 1, WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 2, WALLS THROUGHOUT	
	CORRIDOR 3, WALLS THROUGHOUT, CLASSROOM ENTRY CEILING	
	CORRIDOR 4, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 5, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 6, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	WEST FOYER, WALLS THROUGHOUT, CLASSROOM ENTRY CEILING	
	CORRIDOR 7, WALLS THROUGHOUT	
	CORRIDOR 8, NORTH WALL, CLASSROOM ENTRY CEILING	
	CORRIDOR 9, NORTH WALL, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 10, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	EAST FOYER, WALLS THROUGHOUT, CLASSROOM ENTRY CEILING	
	CORRIDOR 11, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 12, WALLS THROUGHOUT, CLASSROOM ENTRY CEILINGS THROUGHOUT	
	CORRIDOR 13, WALLS THROUGHOUT	
	CORRIDOR 14, EAST WALL	
	CORRIDOR 15, WEST WALL	
	CORRIDOR 16, NORTH WALL	
SINK ACOUSTICAL COATING, WHITE, ROUGH	NORTH FOYER, EAST SINK	S
	FACULTY LOUNGE, SOUTH SINK	
	LIBRARY WORKROOM, EAST SINK	
	COMPUTER, SOUTH SINK	
	SPECIAL ED. 1, WEST SINK	
	SPECIAL ED. 2, WEST SINK	
	SPECIAL ED. 3, WEST SINK	
	ROOM 12, EAST SINK	
	ROOM 13, EAST SINK	
	ROOM 14, EAST SINK	
	ROOM 15, EAST SINK	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 16, EAST SINK	
	ROOM 17, EAST SINK	
	ROOM 18, EAST SINK	
	ROOM 19, EAST SINK	
	ROOM 20, EAST SINK	
	ROOM 21, EAST SINK	
	ROOM 22, WEST SINK	
	ROOM 23, WEST SINK	
	ROOM 24, WEST SINK	
	ROOM 25, WEST SINK	
	ROOM 26, WEST SINK	
	ROOM 27, WEST SINK	
	ROOM 28, WEST SINK	
	ROOM 29, WEST SINK	
	ROOM 30, WEST SINK	
	ROOM 31, WEST SINK	
	MUSIC, NORTH SINK	
GYPSUM WALLBOARD, WHITE, CHALKY	NURSE'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
	MEN'S RESTROOM, WALLS AND CEILING THROUGHOUT	
	WOMEN'S RESTROOM, WALLS AND CEILING THROUGHOUT	
	SOUTH BOY'S RESTROOM, CEILING THROUGHOUT	
	SOUTH VESTIBULE, CEILING THROUGHOUT	
	SOUTH GIRL'S RESTROOM, CEILING THROUGHOUT	
	SOUTH WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
	SOUTH GIRL'S RESTROOM HALL, WALLS AND CEILING THROUGHOUT	
	ROOM 10 TOILET, WALLS AND CEILING THROUGHOUT	
	ROOM 11 TOILET, WALLS AND CEILING THROUGHOUT	
	WEST BOY'S RESTROOM, CEILING THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection*
Kyrene Del Sureno Elementary School
Main Building

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	WEST VESTIBULE, CEILING THROUGHOUT	
	WEST GIRL'S RESTROOM, CEILING THROUGHOUT	
	WEST GIRL'S RESTROOM HALL, WALLS AND CEILING THROUGHOUT	
	WEST WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
	KITCHEN, WALLS THROUGHOUT	
	EAST BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	
	EAST GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	NURSE'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
	MEN'S RESTROOM, WALLS AND CEILING THROUGHOUT	
	WOMEN'S RESTROOM, WALLS AND CEILING THROUGHOUT	
	SOUTH BOY'S RESTROOM, CEILING THROUGHOUT	
	SOUTH VESTIBULE, CEILING THROUGHOUT	
	SOUTH GIRL'S RESTROOM, CEILING THROUGHOUT	
	SOUTH WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
	SOUTH GIRL'S RESTROOM HALL, WALLS AND CEILING THROUGHOUT	
	ROOM 10 TOILET, WALLS AND CEILING THROUGHOUT	
	ROOM 11 TOILET, WALLS AND CEILING THROUGHOUT	
	WEST BOY'S RESTROOM, CEILING THROUGHOUT	
	WEST VESTIBULE, CEILING THROUGHOUT	
	WEST GIRL'S RESTROOM, CEILING THROUGHOUT	
	WEST GIRL'S RESTROOM HALL, WALLS AND CEILING THROUGHOUT	
	WEST WATER HEATER CLOSET, WALLS AND CEILING THROUGHOUT	
	KITCHEN, WALLS THROUGHOUT	
	EAST BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	
	EAST GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY	PRINCIPAL OFFICE, SKYLIGHT	S
	FACULTY LOUNGE, SKYLIGHTS	
	COMPUTER, SKYLIGHTS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	SPEECH, SKYLIGHTS	
	SPECIAL ED. 1, SKYLIGHTS	
	SPECIAL ED. 2, SKYLIGHTS	
	SPECIAL ED. 3, SKYLIGHTS	
	ROOM 10, SKYLIGHTS	
	ROOM 11, SKYLIGHTS	
	ROOM 12, SKYLIGHTS	
	ROOM 13, SKYLIGHTS	
	ROOM 14, SKYLIGHTS	
	ROOM 15, SKYLIGHTS	
	ROOM 16, SKYLIGHTS	
	ROOM 17, SKYLIGHTS	
	ROOM 18, SKYLIGHTS	
	ROOM 19, SKYLIGHTS	
	ROOM 20, SKYLIGHTS	
	ROOM 21, SKYLIGHTS	
	ROOM 22, SKYLIGHTS	
	ROOM 23, SKYLIGHTS	
	ROOM 24, SKYLIGHTS	
	ROOM 25, SKYLIGHTS	
	ROOM 26, SKYLIGHTS	
	ROOM 27, SKYLIGHTS	
	ROOM 28, SKYLIGHTS	
	ROOM 29, SKYLIGHTS	
	ROOM 30, SKYLIGHTS	
	ROOM 31, SKYLIGHTS	
	MUSIC, SKYLIGHTS	
	STAGE, SKYLIGHT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	WEST FOYER, SKYLIGHT	
	EAST FOYER, SKYLIGHT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	PRINCIPAL OFFICE, SKYLIGHT	S
	FACULTY LOUNGE, SKYLIGHTS	
	COMPUTER, SKYLIGHTS	
	SPEECH, SKYLIGHTS	
	SPECIAL ED. 3, SKYLIGHTS	
	SPECIAL ED. 2, SKYLIGHTS	
	SPECIAL ED. 1, SKYLIGHTS	
	ROOM 10, SKYLIGHTS	
	ROOM 11, SKYLIGHTS	
	ROOM 12, SKYLIGHTS	
	ROOM 13, SKYLIGHTS	
	ROOM 14, SKYLIGHTS	
	ROOM 15, SKYLIGHTS	
	ROOM 16, SKYLIGHTS	
	ROOM 17, SKYLIGHTS	
	ROOM 18, SKYLIGHTS	
	ROOM 19, SKYLIGHTS	
	ROOM 20, SKYLIGHTS	
	ROOM 21, SKYLIGHTS	
	ROOM 22, SKYLIGHTS	
	ROOM 23, SKYLIGHTS	
	ROOM 24, SKYLIGHTS	
	ROOM 25, SKYLIGHTS	
	ROOM 26, SKYLIGHTS	
	ROOM 27, SKYLIGHTS	
	ROOM 28, SKYLIGHTS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOM 29, SKYLIGHTS	
	ROOM 30, SKYLIGHTS	
	ROOM 31, SKYLIGHTS	
	MUSIC, SKYLIGHTS	
	STAGE, SKYLIGHT	
	WEST FOYER, SKYLIGHT	
	EAST FOYER, SKYLIGHT	
WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	PRINCIPAL OFFICE CLOSET, BASE OF WALLS THROUGHOUT	S
	STORAGE 2, BASE OF WALLS THROUGHOUT	
	ELEC. CLOSET, BASE OF WALLS THROUGHOUT	
	LIBRARY WORKROOM, BASE OF WALLS THROUGHOUT	
	SERVER ROOM, BASE OF WALLS THROUGHOUT	
	SOUTH GIRL'S RESTROOM HALL, BASE OF WALLS THROUGHOUT	
	WEST GIRL'S RESTROOM HALL, BASE OF WALLS THROUGHOUT	
	STORAGE 6, BASE OF WALLS THROUGHOUT	
	KITCHEN WATER HEATER CLOSET, BASE OF WALLS THROUGHOUT	
	STORAGE 4, BASE OF WALLS THROUGHOUT	
	KITCHEN, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, BRITTLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BROWN, VINYL-LIKE	PRINCIPAL OFFICE CLOSET, BASE OF WALLS THROUGHOUT	S
	STORAGE 2, BASE OF WALLS THROUGHOUT	
	ELEC. CLOSET, BASE OF WALLS THROUGHOUT	
	LIBRARY WORKROOM, BASE OF WALLS THROUGHOUT	
	SERVER ROOM, BASE OF WALLS THROUGHOUT	
	SOUTH GIRL'S RESTROOM HALL, BASE OF WALLS THROUGHOUT	
	WEST GIRL'S RESTROOM HALL, BASE OF WALLS THROUGHOUT	
	STORAGE 6, BASE OF WALLS THROUGHOUT	
	KITCHEN WATER HEATER CLOSET, BASE OF WALLS THROUGHOUT	
	STORAGE 4, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	KITCHEN, BASE OF WALLS THROUGHOUT	
FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	JANITOR, PORTION OF EAST AND SOUTH WALLS	N
	KITCHEN, PORTION OF NORTH, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	JANITOR, PORTION OF EAST AND SOUTH WALLS	S
	KITCHEN, PORTION OF NORTH, WEST AND SOUTH WALLS	
VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN MOTTLES	MEN'S RESTROOM, PORTION OF FLOOR	S
	WOMEN'S RESTROOM, PORTION OF FLOOR	
	STORAGE 5, ENTRY PORTION OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN MOTTLES	MEN'S RESTROOM, PORTION OF FLOOR	S
	WOMEN'S RESTROOM, PORTION OF FLOOR	
	STORAGE 5, ENTRY PORTION OF FLOOR	
BRICK, 4"X16", RED, CEMENTITIOUS	LIBRARY, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	MULTI-PURPOSE, PORTION OF NORTH, EAST AND SOUTH WALLS	
	CORRIDOR 8, SOUTH AND PORTION OF EAST AND WEST WALLS	
	CORRIDOR 9, SOUTH WALL	
	CORRIDOR 14, PORTION OF NORTH AND WEST WALLS	
	CORRIDOR 15, PORTION OF NORTH AND EAST WALLS	
	CORRIDOR 16, SOUTH WALL	
	EQUIPMENT PAD, WALLS THROUGHOUT	
	STORAGE BUILDING, EAST AND SOUTH WALLS	
	CANOPY, NORTH WALL	
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	ROOF, PARAPET WALLS THROUGHOUT	
MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS	LIBRARY, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	MULTI-PURPOSE, PORTION OF NORTH, EAST AND SOUTH WALLS	
	CORRIDOR 8, SOUTH AND PORTION OF EAST AND WEST WALLS	
	CORRIDOR 9, SOUTH WALL	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 14, PORTION OF NORTH AND WEST WALLS	
	CORRIDOR 15, PORTION OF NORTH AND EAST WALLS	
	CORRIDOR 16, SOUTH WALL	
	EQUIPMENT PAD, WALLS THROUGHOUT	
	STORAGE BUILDING, EAST AND SOUTH WALLS	
	CANOPY, NORTH WALL	
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	ROOF, PARAPET WALLS THROUGHOUT	
SEALANT, BROWN, PLIABLE	LIBRARY, PORTION OF NORTH, EAST AND WEST WALLS	S
	MULTI-PURPOSE, NORTH AND SOUTH DOORS	
	CORRIDOR 8, SOUTHWEST CORNER, SOUTH DOORS	
	CORRIDOR 9, SOUTHEAST CORNER	
	EXTERIOR, DOORS THROUGHOUT	
SEALANT, BLACK, TAR-LIKE	LIBRARY, SOUTH WINDOWS	S
	CORRIDOR 5, EAST AND SOUTH WINDOWS	
	CORRIDOR 13, WEST AND SOUTH WINDOWS	
	CORRIDOR 15, SOUTH WINDOW	
GLAZED WALL TILE, 4"X4", PINK, SMOOTH, BLACK AND WHITE	SOUTH VESTIBULE, WALLS THROUGHOUT	S
	SOUTH GIRL'S RESTROOM, WALLS THROUGHOUT	
	WEST VESTIBULE, WALLS THROUGHOUT	
	WEST GIRL'S RESTROOM, WALLS THROUGHOUT	
	EAST GIRL'S RESTROOM, WALLS THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH, BLACK AND WHITE	SOUTH VESTIBULE, WALLS THROUGHOUT	S
	SOUTH GIRL'S RESTROOM, WALLS THROUGHOUT	
	WEST VESTIBULE, WALLS THROUGHOUT	
	WEST GIRL'S RESTROOM, WALLS THROUGHOUT	
	EAST GIRL'S RESTROOM, WALLS THROUGHOUT	
CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	SOUTH VESTIBULE, FLOOR THROUGHOUT	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	SOUTH GIRL'S RESTROOM, FLOOR THROUGHOUT	
	ROOM 10 TOILET, FLOOR THROUGHOUT	
	ROOM 11 TOILET, FLOOR THROUGHOUT	
	WEST VESTIBULE, FLOOR THROUGHOUT	
	WEST GIRL'S RESTROOM, FLOOR THROUGHOUT	
	EAST GIRL'S RESTROOM, FLOOR THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	SOUTH VESTIBULE, FLOOR THROUGHOUT	S
	SOUTH GIRL'S RESTROOM, FLOOR THROUGHOUT	
	ROOM 10 TOILET, FLOOR THROUGHOUT	
	ROOM 11 TOILET, FLOOR THROUGHOUT	
	WEST VESTIBULE, FLOOR THROUGHOUT	
	WEST GIRL'S RESTROOM, FLOOR THROUGHOUT	
	EAST GIRL'S RESTROOM, FLOOR THROUGHOUT	
GLAZED WALL TILE, 4"X4", BLUE, SMOOTH, BLACK AND WHITE	SOUTH BOY'S RESTROOM, WALLS THROUGHOUT	S
	WEST BOY'S RESTROOM, WALLS THROUGHOUT	
	EAST BOY'S RESTROOM, WALLS THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", BLUE, SMOOTH, BLACK AND WHITE	SOUTH BOY'S RESTROOM, WALLS THROUGHOUT	S
	WEST BOY'S RESTROOM, WALLS THROUGHOUT	
	EAST BOY'S RESTROOM, WALLS THROUGHOUT	
CERAMIC MOSAIC TILE, 2"X2", BLUE, SMOOTH	SOUTH BOY'S RESTROOM, FLOOR THROUGHOUT	S
	WEST BOY'S RESTROOM, FLOOR THROUGHOUT	
	EAST BOY'S RESTROOM, FLOOR THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", BLUE, SMOOTH	SOUTH BOY'S RESTROOM, FLOOR THROUGHOUT	S
	WEST BOY'S RESTROOM, FLOOR THROUGHOUT	
	EAST BOY'S RESTROOM, FLOOR THROUGHOUT	
TROWELED-ON TEXTURE, WHITE, CHALKY	EXTERIOR ELECTRICAL CLOSET, WALLS AND CEILING THROUGHOUT	S
	SOUTH WING, EAST AND PORTION OF SOUTH WALLS	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	EXTERIOR ELECTRICAL CLOSET, WALLS AND CEILING THROUGHOUT	S
	SOUTH WING, EAST AND PORTION OF SOUTH WALLS	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	EXTERIOR ELECTRICAL CLOSET, WALLS AND CEILING THROUGHOUT	S
	SOUTH WING, EAST AND PORTION OF SOUTH WALLS	
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	STAGE, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
ADHESIVE, BROWN, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	STAGE, BASE OF PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
VINYL STAIR TREAD, 10"X36", GRAY, VINYL-LIKE, CIRCLE PATTERN	NORTH WING, STAIRS	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL STAIR TREAD, 10"X36", GRAY, VINYL-LIKE, CIRCLE PATTERN	NORTH WING, STAIRS	S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, SQUARE PATTERN, TAN	MULTI-PURPOSE, PORTION OF CEILING	S
VINYL COMPOSITION TILE, 24"X24", GRAY, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE, SOUTHWEST ENTRY PORTION OF FLOOR	S
	CORRIDOR 3, NORTH ENTRY PORTION OF FLOOR	
	CORRIDOR 4, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 5, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 6, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 7, SOUTH ENTRY PORTION OF FLOOR	
	CORRIDOR 8, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 9, EAST ENTRY PORTION OF FLOOR	
	CORRIDOR 11, EAST ENTRY PORTION OF FLOOR	
	CORRIDOR 12, EAST ENTRY PORTION OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, VINYL-LIKE, CIRCLE PATTERN	MULTI-PURPOSE, SOUTHWEST ENTRY PORTION OF FLOOR	S
	CORRIDOR 3, NORTH ENTRY PORTION OF FLOOR	
	CORRIDOR 4, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 5, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 6, WEST ENTRY PORTION OF FLOOR	
	CORRIDOR 7, SOUTH ENTRY PORTION OF FLOOR	
	CORRIDOR 8, WEST ENTRY PORTION OF FLOOR	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	CORRIDOR 9, EAST ENTRY PORTION OF FLOOR	
	CORRIDOR 11, EAST ENTRY PORTION OF FLOOR	
	CORRIDOR 12, EAST ENTRY PORTION OF FLOOR	
VINYL COMPOSITION TILE, 2"X24", BLACK, VINYL-LIKE, YELLOW, RED, GREEN, BLUE, STRIP	MULTI-PURPOSE, FLOOR THROUGHOUT (MAIN) LESS SOUTHWEST ENTRY	S
ACOUSTICAL CEILING PANEL, 2'X4', WHITE, CHALKY, VINYL COVER	KITCHEN, CEILING THROUGHOUT	S
GLAZED WALL TILE, 4"X6", PINK, SMOOTH	ROOM 10 TOILET, BASE OF WALLS THROUGHOUT	S
	ROOM 11 TOILET, BASE OF WALLS THROUGHOUT	
GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X6", PINK, SMOOTH	ROOM 10 TOILET, BASE OF WALLS THROUGHOUT	S
	ROOM 11 TOILET, BASE OF WALLS THROUGHOUT	
CONCRETE, GRAY, CEMENTITIOUS	RECEPTION, FLOOR THROUGHOUT	S
	TREATMENT, FLOOR THROUGHOUT	
	NURSE'S OFFICE, FLOOR THROUGHOUT	
	NURSE'S RESTROOM, FLOOR THROUGHOUT	
	HEARING, FLOOR THROUGHOUT	
	STORAGE 1, FLOOR THROUGHOUT	
	HALL 1, FLOOR THROUGHOUT	
	NORTH FOYER, FLOOR THROUGHOUT	
	PRINCIPAL OFFICE, FLOOR THROUGHOUT	
	PRINCIPAL'S CLOSET, FLOOR THROUGHOUT	
	COUNSELOR, FLOOR THROUGHOUT	
	PSY/CONF. , FLOOR THROUGHOUT	
	FACULTY WORK, FLOOR THROUGHOUT	
	FACULTY LOUNGE, FLOOR THROUGHOUT	
	MEN'S RESTROOM, FLOOR THROUGHOUT	
	WOMEN'S RESTROOM, FLOOR THROUGHOUT	
	STORAGE 2, FLOOR THROUGHOUT	
	UNISEX RESTROOM, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	JANITOR, FLOOR THROUGHOUT	
	ELEC. CLOSET, FLOOR THROUGHOUT	
	LIBRARY, FLOOR THROUGHOUT	
	LIBRARY WORKROOM, FLOOR THROUGHOUT	
	COMPUTER, FLOOR THROUGHOUT	
	SERVER ROOM, FLOOR THROUGHOUT	
	SPEECH, FLOOR THROUGHOUT	
	STORAGE 3, FLOOR THROUGHOUT	
	SPECIAL ED. 3, FLOOR THROUGHOUT	
	TEST ROOM, FLOOR THROUGHOUT	
	SPECIAL ED. 2, FLOOR THROUGHOUT	
	SPECIAL ED. 1, FLOOR THROUGHOUT	
	TIMEOUT ROOM, FLOOR THROUGHOUT	
	SOUTH BOY'S RESTROOM, FLOOR THROUGHOUT	
	SOUTH VESTIBULE, FLOOR THROUGHOUT	
	SOUTH GIRL'S RESTROOM, FLOOR THROUGHOUT	
	SOUTH WATER HEATER CLOSET, FLOOR THROUGHOUT	
	EXTERIOR ELECTRICAL CLOSET, FLOOR THROUGHOUT	
	SOUTH GIRL'S RESTROOM HALL, FLOOR THROUGHOUT	
	ROOM 10, FLOOR THROUGHOUT	
	ROOM 10 TOILET, FLOOR THROUGHOUT	
	ROOM 11, FLOOR THROUGHOUT	
	ROOM 11 TOILET, FLOOR THROUGHOUT	
	ROOM 12, FLOOR THROUGHOUT	
	ROOM 13, FLOOR THROUGHOUT	
	ROOM 14, FLOOR THROUGHOUT	
	ROOM 15, FLOOR THROUGHOUT	
	WEST BOY'S RESTROOM, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	WEST VESTIBULE, FLOOR THROUGHOUT	
	WEST GIRL'S RESTROOM, FLOOR THROUGHOUT	
	WEST GIRL'S RESTROOM HALL, FLOOR THROUGHOUT	
	WEST WATER HEATER CLOSET, FLOOR THROUGHOUT	
	ROOM 16, FLOOR THROUGHOUT	
	ROOM 17, FLOOR THROUGHOUT	
	ROOM 18, FLOOR THROUGHOUT	
	ROOM 19, FLOOR THROUGHOUT	
	ROOM 20, FLOOR THROUGHOUT	
	ROOM 21, FLOOR THROUGHOUT	
	ROOM 22, FLOOR THROUGHOUT	
	ROOM 23, FLOOR THROUGHOUT	
	ROOM 24, FLOOR THROUGHOUT	
	ROOM 25, FLOOR THROUGHOUT	
	ROOM 26, FLOOR THROUGHOUT	
	ROOM 27, FLOOR THROUGHOUT	
	ROOM 28, FLOOR THROUGHOUT	
	ROOM 29, FLOOR THROUGHOUT	
	ROOM 30, FLOOR THROUGHOUT	
	ROOM 31, FLOOR THROUGHOUT	
	MUSIC, FLOOR THROUGHOUT	
	STORAGE 6, FLOOR THROUGHOUT	
	STAGE, FLOOR THROUGHOUT	
	NORTH WING, FLOOR THROUGHOUT	
	SOUTH WING, FLOOR THROUGHOUT	
	MULTI-PURPOSE, FLOOR THROUGHOUT	
	KITCHEN WATER HEATER CLOSET, FLOOR THROUGHOUT	
	STORAGE 4, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	STORAGE 5, FLOOR THROUGHOUT	
	P.E. OFFICE, FLOOR THROUGHOUT	
	KITCHEN, FLOOR THROUGHOUT	
	EAST BOY'S RESTROOM, FLOOR THROUGHOUT	
	EAST GIRL'S RESTROOM, FLOOR THROUGHOUT	
	CORRIDOR 1, FLOOR THROUGHOUT	
	CORRIDOR 2, FLOOR THROUGHOUT	
	CORRIDOR 3, FLOOR THROUGHOUT	
	CORRIDOR 4, FLOOR THROUGHOUT	
	CORRIDOR 5, FLOOR THROUGHOUT	
	CORRIDOR 6, FLOOR THROUGHOUT	
	WEST FOYER, FLOOR THROUGHOUT	
	CORRIDOR 7, FLOOR THROUGHOUT	
	CORRIDOR 8, FLOOR THROUGHOUT	
	CORRIDOR 9, FLOOR THROUGHOUT	
	CORRIDOR 10, FLOOR THROUGHOUT	
	EAST FOYER, FLOOR THROUGHOUT	
	CORRIDOR 11, FLOOR THROUGHOUT	
	CORRIDOR 12, FLOOR THROUGHOUT	
	CORRIDOR 13, FLOOR THROUGHOUT	
	CORRIDOR 14, FLOOR THROUGHOUT	
	CORRIDOR 15, FLOOR THROUGHOUT	
	CORRIDOR 16, FLOOR THROUGHOUT	
	EQUIPMENT PAD, FLOOR THROUGHOUT	
	STORAGE BUILDING, FLOOR THROUGHOUT	
	CANOPY, FLOOR THROUGHOUT	
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S
STUCCO, GRAY, CEMENTITIOUS	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
	ROOF, PORTION OF NORTH, EAST, WEST AND SOUTH PARAPET WALLS	
EXPANSION JOINT, RED, PLIABLE	LIBRARY, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	S
	MULTI-PURPOSE, PORTION OF NORTH, EAST AND SOUTH WALLS	
	CORRIDOR 8, PORTION OF EAST, WEST AND SOUTH WALLS	
	CORRIDOR 9, PORTION OF SOUTH WALL	
	CORRIDOR 14, PORTION OF NORTH AND WEST WALLS	
	CORRIDOR 15, PORTION OF NORTH AND EAST WALLS	
	CORRIDOR 16, PORTION OF SOUTH WALL	
	EQUIPMENT PAD, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	EXTERIOR, PORTION OF NORTH, EAST, WEST AND SOUTH WALLS	
	ROOF, PORTION OF NORTH, EAST, WEST AND SOUTH PARAPET WALLS	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF, PORTION OF	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF, PORTION OF	S
SEALANT (FLASHING), GRAY, PLIABLE	ROOF, PORTION OF	S
GASKET, 8", WHITE, PAPER-LIKE	EQUIPMENT PAD, PORTION OF PIPING	S
SEALANT (EQUIPMENT), BLACK, TAR-LIKE	EQUIPMENT PAD, PORTION OF MECHANICAL EQUIPMENT	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, WHITE COATING	CANOPY, ROOF THROUGHOUT	S
ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	STORAGE BUILDING, ROOF THROUGHOUT	S
VAPOR BARRIER FELT, BLACK, ASPHALTIC	STORAGE BUILDING, ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 50/51*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	P50, CEILING THROUGHOUT	S
	P51, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P50, WALLS THROUGHOUT	S
	P51, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P50, WALLS THROUGHOUT	S
	P51, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	P50, WALLS THROUGHOUT	S
	P51, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P50, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	P51, PORTION OF NORTH, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P50, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	P51, PORTION OF NORTH, WEST AND SOUTH WALLS	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P50, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	S
	P51, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P50, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	S
	P51, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P50, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P51, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P50, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P51, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P50, BASE OF WALLS THROUGHOUT	S
	P51, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P50, BASE OF WALLS THROUGHOUT	S
	P51, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 50/51*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	P50, WEST SINK	S
	P51, EAST SINK	
SEALANT, WHITE, PLIABLE	P50, SOUTH DOORS, MILLWORK	S
	P51, SOUTH DOORS, MILLWORK	
FIRE DOOR INSULATION, METAL CLADDING	P50, SOUTH DOORS	S
	P51, SOUTH DOORS	
	EXTERIOR, DOORS THROUGHOUT	
DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	P50, DUCTWORK ABOVE CEILING	S
	P51, DUCTWORK ABOVE CEILING	
SEALANT (DUCT), GRAY, PLIABLE	P50, DUCTWORK ABOVE CEILING	S
	P51, DUCTWORK ABOVE CEILING	
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	S
SEALANT, BLACK, PLIABLE	EXTERIOR, SOUTH WINDOWS	S
SEALANT, BROWN, PLIABLE	EXTERIOR, SOUTH DOORS	S
CONCRETE, GRAY, CEMENTITIOUS	EAST MECHANICAL, FLOOR THROUGHOUT	S
	WEST MECHANICAL, FLOOR THROUGHOUT	
	EXTERIOR, ENTRIES THROUGHOUT	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
PIPE END SEALANT, WHITE, PLIABLE	P50, SPRINKLER PIPING ABOVE CEILING	S
	P51, SPRINKLER PIPING ABOVE CEILING	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	ROOF THROUGHOUT	S
SEALANT (EQUIPMENT), WHITE, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
SEALANT (EQUIPMENT), BLACK, PLIABLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 52/53*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	P52, CEILING THROUGHOUT	S
	P53, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P52, WALLS THROUGHOUT	S
	P53, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P52, WALLS THROUGHOUT	S
	P53, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	P52, WALLS THROUGHOUT	S
	P53, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P52, PORTION OF NORTH, WEST AND SOUTH WALLS	S
	P53, PORTION OF NORTH, EAST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P52, PORTION OF NORTH, WEST AND SOUTH WALLS	S
	P53, PORTION OF NORTH, EAST AND SOUTH WALLS	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P52, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	S
	P53, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P52, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	S
	P53, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P52, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P53, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P52, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P53, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P52, BASE OF WALLS THROUGHOUT	S
	P53, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P52, BASE OF WALLS THROUGHOUT	S
	P53, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 52/53*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	P52, EAST SINK	S
	P53, WEST SINK	
SEALANT, WHITE, PLIABLE	P52, NORTH DOORS, MILLWORK	S
	P53, NORTH DOORS, MILLWORK	
FIRE DOOR INSULATION, METAL CLADDING	P52, NORTH DOORS	S
	P53, NORTH DOORS	
	EXTERIOR, NORTH DOORS	
DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	P52, DUCTWORK ABOVE CEILING	S
	P53, DUCTWORK ABOVE CEILING	
SEALANT (DUCT), GRAY, PLIABLE	P52, DUCTWORK ABOVE CEILING	S
	P53, DUCTWORK ABOVE CEILING	
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	S
SEALANT, BLACK, PLIABLE	EXTERIOR, NORTH WINDOWS	S
SEALANT, BROWN, PLIABLE	EXTERIOR, NORTH DOORS	S
CONCRETE, GRAY, CEMENTITIOUS	EAST MECHANICAL, FLOOR THROUGHOUT	S
	WEST MECHANICAL, FLOOR THROUGHOUT	
	EXTERIOR, ENTRIES THROUGHOUT	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
PIPE END SEALANT, WHITE, PLIABLE	P52, SPRINKLER PIPING ABOVE CEILING	S
	P53, SPRINKLER PIPING ABOVE CEILING	
GASKET, 10", WHITE, PAPER-LIKE	WEST MECHANICAL, PORTION OF PIPING	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	ROOF THROUGHOUT	S
SEALANT (EQUIPMENT), WHITE, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
SEALANT (EQUIPMENT), BLACK, PLIABLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 54/55*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	P54, CEILING THROUGHOUT	S
	P55, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P54, WALLS THROUGHOUT	S
	P55, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P54, WALLS THROUGHOUT	S
	P55, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	P54, WALLS THROUGHOUT	S
	P55, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P54, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	P55, PORTION OF NORTH, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P54, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	P55, PORTION OF NORTH, WEST AND SOUTH WALLS	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P54, FLOOR THROUGHOUT LESS ENTRIES AND WET AREA	S
	P55, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P54, FLOOR THROUGHOUT LESS ENTRIES AND WET AREA	S
	P55, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P54, ENTRIES AND WET AREA PORTIONS OF FLOOR	S
	P55, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P54, ENTRIES AND WET AREA PORTIONS OF FLOOR	S
	P55, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	P54, BASE OF WALLS THROUGHOUT	S
	P55, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	P54, BASE OF WALLS THROUGHOUT	S
	P55, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 54/55*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	P54, WEST SINK	S
	P55, EAST SINK	
SEALANT, WHITE, PLIABLE	P54, SOUTH DOORS, MILLWORK	S
	P55, SOUTH DOORS, MILLWORK	
FIRE DOOR INSULATION, METAL CLADDING	P54, SOUTH DOORS	S
	P55, SOUTH DOORS	
	EXTERIOR, SOUTH DOORS	
DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	P54, DUCTWORK ABOVE CEILING	S
	P55, DUCTWORK ABOVE CEILING	
SEALANT (DUCT), GRAY, PLIABLE	P54, DUCTWORK ABOVE CEILING	S
	P55, DUCTWORK ABOVE CEILING	
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	S
SEALANT, BLACK, PLIABLE	EXTERIOR, SOUTH WINDOWS	S
SEALANT, BROWN, PLIABLE	EXTERIOR, SOUTH DOORS	S
CONCRETE, GRAY, CEMENTITIOUS	EAST MECHANICAL, FLOOR THROUGHOUT	S
	WEST MECHANICAL, FLOOR THROUGHOUT	
	EXTERIOR, ENTRIES THROUGHOUT	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
PIPE END SEALANT, WHITE, PLIABLE	P54, SPRINKLER PIPING ABOVE CEILING	S
	P55, SPRINKLER PIPING ABOVE CEILING	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	ROOF THROUGHOUT	S
SEALANT (EQUIPMENT), WHITE, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
SEALANT (EQUIPMENT), BLACK, PLIABLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 56/57*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	P56, CEILING THROUGHOUT	S
	P57, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P56, WALLS THROUGHOUT	S
	P57, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P56, WALLS THROUGHOUT	S
	P57, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	P56, WALLS THROUGHOUT	S
	P57, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P56, PORTION OF NORTH, WEST AND SOUTH WALLS	S
	P57, PORTION OF NORTH, EAST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P56, PORTION OF NORTH, WEST AND SOUTH WALLS	S
	P57, PORTION OF NORTH, EAST AND SOUTH WALLS	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P56, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	S
	P57, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P56, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	S
	P57, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P56, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P57, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P56, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P57, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P56, BASE OF WALLS THROUGHOUT	S
	P57, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P56, BASE OF WALLS THROUGHOUT	S
	P57, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 56/57*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	P56, EAST SINK	S
	P57, WEST SINK	
SEALANT, WHITE, PLIABLE	P56, NORTH DOORS, MILLWORK	S
	P57, NORTH DOORS, MILLWORK	
FIRE DOOR INSULATION, METAL CLADDING	P56, NORTH DOORS	S
	P57, NORTH DOORS	
	EXTERIOR, NORTH DOORS	
DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	P56, DUCTWORK ABOVE CEILING	S
	P57, DUCTWORK ABOVE CEILING	
SEALANT (DUCT), GRAY, PLIABLE	P56, DUCTWORK ABOVE CEILING	S
	P57, DUCTWORK ABOVE CEILING	
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	S
SEALANT, BLACK, PLIABLE	EXTERIOR, NORTH WINDOWS	S
SEALANT, BROWN, PLIABLE	EXTERIOR, NORTH DOORS	S
CONCRETE, GRAY, CEMENTITIOUS	WEST MECHANICAL, FLOOR THROUGHOUT	S
	EAST MECHANICAL, FLOOR THROUGHOUT	
	EXTERIOR, ENTRIES THROUGHOUT	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
PIPE END SEALANT, WHITE, PLIABLE	P56, SPRINKLER PIPING ABOVE CEILING	S
	P57, SPRINKLER PIPING ABOVE CEILING	
GASKET, 10", WHITE, PAPER-LIKE	EAST MECHANICAL, PORTION OF PIPING	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	ROOF THROUGHOUT	S
SEALANT (EQUIPMENT), WHITE, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
SEALANT (EQUIPMENT), BLACK, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 58/59*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	P58, CEILING THROUGHOUT	S
	P59, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P58, WALLS THROUGHOUT	S
	P59, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P58, WALLS THROUGHOUT	S
	P59, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	P58, WALLS THROUGHOUT	S
	P59, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P58, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	P59, PORTION OF NORTH, WEST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P58, PORTION OF NORTH, EAST AND SOUTH WALLS	S
	P59, PORTION OF NORTH, WEST AND SOUTH WALLS	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P58, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	S
	P59, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA WET AREA	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P58, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA WET AREA	S
	P59, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA WET AREA	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P58, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P59, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P58, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P59, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	
WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P58, BASE OF WALLS THROUGHOUT	S
	P59, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	P58, BASE OF WALLS THROUGHOUT	S
	P59, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 58/59*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	P58, WEST SINK	S
	P59, EAST SINK	
SEALANT, WHITE, PLIABLE	P58, SOUTH DOORS, MILLWORK	S
	P59, SOUTH DOORS, MILLWORK	
FIRE DOOR INSULATION, METAL CLADDING	P58, SOUTH DOORS	S
	P59, SOUTH DOORS	
	EXTERIOR, SOUTH DOORS	
DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	P58, DUCTWORK ABOVE CEILING	S
	P59, DUCTWORK ABOVE CEILING	
SEALANT (DUCT), GRAY, PLIABLE	P58, DUCTWORK ABOVE CEILING	S
	P59, DUCTWORK ABOVE CEILING	
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	S
SEALANT, BLACK, PLIABLE	EXTERIOR, SOUTH WINDOWS	S
SEALANT, BROWN, PLIABLE	EXTERIOR, SOUTH DOORS	S
CONCRETE, GRAY, CEMENTITIOUS	EAST MECHANICAL, FLOOR THROUGHOUT	S
	WEST MECHANICAL, FLOOR THROUGHOUT	
	EXTERIOR, ENTRIES THROUGHOUT	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
PIPE END SEALANT, WHITE, PLIABLE	P58, SPRINKLER PIPING ABOVE CEILING	S
	P59, SPRINKLER PIPING ABOVE CEILING	
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	ROOF THROUGHOUT	S
SEALANT (EQUIPMENT), WHITE, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
SEALANT (EQUIPMENT), BLACK, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 60/61*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	P60, CEILING THROUGHOUT	S
	P61, CEILING THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P60, WALLS THROUGHOUT	S
	P61, WALLS THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	P60, WALLS THROUGHOUT	S
	P61, WALLS THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	P60, WALLS THROUGHOUT	S
	P61, WALLS THROUGHOUT	
TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P60, PORTION OF NORTH, WEST AND SOUTH WALLS	S
	P61, PORTION OF NORTH, EAST AND SOUTH WALLS	
ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	P60, PORTION OF NORTH, WEST AND SOUTH WALLS	S
	P61, PORTION OF NORTH, EAST AND SOUTH WALLS	
CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P60, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	S
	P61, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	P60, FLOOR THROUGHOUT LESS EAST ENTRY AND WET AREA	S
	P61, FLOOR THROUGHOUT LESS WEST ENTRY AND WET AREA	
VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P60, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P61, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	P60, EAST ENTRY AND WET AREA PORTIONS OF FLOOR	S
	P61, WEST ENTRY AND WET AREA PORTIONS OF FLOOR	
WALLBASE (COVED), 4", BLUE, VINYL-LIKE	P60, BASE OF WALLS THROUGHOUT	S
	P61, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	P60, BASE OF WALLS THROUGHOUT	S
	P61, BASE OF WALLS THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 60/61*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SINK ACOUSTICAL COATING, BLACK, ROUGH	P60, EAST SINK	S
	P61, WEST SINK	
SEALANT, WHITE, PLIABLE	P60, NORTH DOORS, MILLWORK	S
	P61, NORTH DOORS, MILLWORK	
FIRE DOOR INSULATION, METAL CLADDING	P60, NORTH DOORS	S
	P61, NORTH DOORS	
	EXTERIOR, NORTH DOORS	
DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	P60, DUCTWORK ABOVE CEILING	S
	P61, DUCTWORK ABOVE CEILING	
SEALANT (DUCT), GRAY, PLIABLE	P60, DUCTWORK ABOVE CEILING	S
	P61, DUCTWORK ABOVE CEILING	
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	S
SEALANT, BLACK, PLIABLE	EXTERIOR, NORTH WINDOWS	S
SEALANT, BROWN, PLIABLE	EXTERIOR, NORTH DOORS	S
CONCRETE, GRAY, CEMENTITIOUS	EAST MECHANICAL, FLOOR THROUGHOUT	S
	WEST MECHANICAL, FLOOR THROUGHOUT	
	EXTERIOR, ENTRIES THROUGHOUT	
EXPANSION JOINT, BROWN, FIBROUS	EXTERIOR, ENTRIES THROUGHOUT	S
PIPE END SEALANT, WHITE, PLIABLE	P60, SPRINKLER PIPING ABOVE CEILING	S
	P61, SPRINKLER PIPING ABOVE CEILING	
GASKET, 10", WHITE, PAPER-LIKE	EAST MECHANICAL, PORTION OF PIPING	S
BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	ROOF THROUGHOUT	S
SEALANT (EQUIPMENT), WHITE, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
SEALANT (EQUIPMENT), BLACK, BRITTLE	ROOF-MOUNTED MECHANICAL EQUIPMENT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Restroom Portable*

JOB NO. 07-345

**TABLE A
BUILDING MATERIAL SYSTEMS**

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
	JANITOR, WALLS AND CEILING THROUGHOUT	
	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	
GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
	JANITOR, WALLS AND CEILING THROUGHOUT	
	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	BOY'S RESTROOM, WALLS AND CEILING THROUGHOUT	S
	JANITOR ROOM, WALLS AND CEILING THROUGHOUT	
	GIRL'S RESTROOM, WALLS AND CEILING THROUGHOUT	
VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLED, GRAY PAPER BACKING	BOY'S RESTROOM, BASE OF WALLS AND FLOOR THROUGHOUT	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLED, GRAY PAPER BACKING	BOY'S RESTROOM, BASE OF WALLS AND FLOOR THROUGHOUT	S
SEALANT, WHITE, PLIABLE	BOY'S RESTROOM, SOUTH DOOR, FIXTURES	S
	JANITOR ROOM, DOORS THROUGHOUT	
	ELECTRICAL ROOM, WEST DOOR	
	GIRL'S RESTROOM, WEST DOOR, FIXTURES	
FIRE DOOR INSULATION, METAL CLADDING	BOY'S RESTROOM, SOUTH DOOR	S
	JANITOR ROOM, DOORS THROUGHOUT	
	ELECTRICAL ROOM, WEST DOOR	
	GIRL'S RESTROOM, WEST DOOR	
	EXTERIOR, DOORS THROUGHOUT	
VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, BROWN MOTTLES	JANITOR ROOM, FLOOR THROUGHOUT	S
	ELECTRICAL ROOM, FLOOR THROUGHOUT	
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, BROWN MOTTLES	JANITOR ROOM, FLOOR THROUGHOUT	S
	ELECTRICAL ROOM, FLOOR THROUGHOUT	

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Restroom Portable*

JOB NO. 07-345

MATERIAL DESCRIPTION	MATERIAL LOCATIONS	ACM N/S
WALLBASE (COVED), 4", BROWN, VINYL-LIKE	JANITOR ROOM, BASE OF WALLS THROUGHOUT	S
	ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	JANITOR ROOM, BASE OF WALLS THROUGHOUT	S
	ELECTRICAL ROOM, BASE OF WALLS THROUGHOUT	
SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	S
GYPHUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	S
JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPHUM WALLBOARD, WHITE, CHALKY	ELECTRICAL ROOM, WALLS AND CEILING THROUGHOUT	S
VINYL SHEET FLOORING, BROWN, SMOOTH, WHITE MARBLED, GRAY PAPER BACKING	GIRL'S RESTROOM, BASE OF WALLS AND FLOOR THROUGHOUT	S
MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, BROWN, SMOOTH, WHITE MARBLED, GRAY PAPER BACKING	GIRL'S RESTROOM, BASE OF WALLS AND FLOOR THROUGHOUT	S
SEALANT, BROWN, PLIABLE	EXTERIOR, DOORS THROUGHOUT	S
CONCRETE, GRAY, CEMENTITIOUS	EXTERIOR, ENTRIES THROUGHOUT	S
SIDING (METAL), FACTORY FINISH	EXTERIOR, WALLS THROUGHOUT	N
BUILT-UP ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	ROOF THROUGHOUT	S
MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	ROOF THROUGHOUT	S

END OF TABLE

2.4 AHERA Inspection Procedures and Protocols

2.4.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.4.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step-by-step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.5 Visual Inspection

A visual inspection of the eight buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

A detailed description of HA's of suspect ACBM's is presented as Table B in Section 2.6.

2.6 Homogeneous Areas of Suspect Asbestos-Containing Building Materials

TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS

MAIN BUILDING
PORTABLE 50/51
PORTABLE 52/53
PORTABLE 54/55
PORTABLE 56/57
PORTABLE 58/59
PORTABLE 60/61
RESTROOM PORTABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES (HEAVY), WHITE, HEAVY	S	F	40,000	SF
M	APL	02	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	2,000	SF
S	SAT	03	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	35,000	SF
M	GWB	04	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	35,000	SF
S	JTC	05	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	3,500	SF
M	TWP	06	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	14,000	SF
M	ADH	07	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	3,500	SF
M	CPT	08	CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	S	NF	33,000	SF
M	MAS	09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, GRAY, FIBROUS, MULTI-COLORED SPECKS	S	NF	33,000	SF
M	MRT	10	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLASS BLOCK, 8"X8", CLEAR	A	NF	100	SF
M	WAB	11	WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	S	NF	2,000	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	S	NF	2,000	SF
M	FDI	13	FIRE DOOR INSULATION, METAL CLADDING	A	NF	693	SF
M	FDI	14	FIRE DOOR INSULATION, WOOD CLADDING	A	NF	1,050	SF
M	SLT	15	SEALANT, WHITE, PLIABLE	S	NF	150	SF
M	GWT	16	GLAZED WALL TILE, 6"X6", WHITE, SMOOTH, VARIOUS	A	NF	70	SF
M	GRT	17	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 6"X6", WHITE, SMOOTH, VARIOUS	A	NF	7	SF
S	SAT	18	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	450	SF
M	GWB	19	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	450	SF
S	JTC	20	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	45	SF
M	VCT	21	VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, TAN MOTTLES	S	NF	15,000	SF
M	MAS	22	MASTIC, BLACK, BRITTLE, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, TAN MOTTLES AND VINYL COMPOSITION TILE, 2"X24", BLACK, SMOOTH, YELLOW, RED, GREEN, BLUE, STRIP	S	NF	15,000	SF
S	SAT	23	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	800	SF
M	GWB	24	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	S	NF	800	SF
S	JTC	25	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	80	SF
M	GAS	26	GASKET, 8", RED, RUBBER-LIKE	A	NF	1	SF
M	GWB	27	GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	15,000	SF
S	JTC	28	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	1,500	SF
M	SAC	29	SINK ACOUSTICAL COATING, WHITE, ROUGH	A	NF	56	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	GWB	30	GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	5,000	SF
S	JTC	31	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	500	SF
M	GWB	32	GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	10,000	SF
S	JTC	33	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	1,000	SF
M	WAB	34	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	S	NF	170	SF
M	ADH	35	ADHESIVE, CREAM, BRITTLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	S	NF	170	SF
M	ADH	36	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH FIBERGLASS REINFORCED PANEL, WHITE, TEXTURED	A	NF	150	SF
M	VCT	37	VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN MOTTLES	S	NF	15	SF
M	MAS	38	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", WHITE, SMOOTH, TAN MOTTLES	S	NF	15	SF
M	BRK	39	BRICK, 4"X16", RED, CEMENTITIOUS	S	NF	30,000	SF
M	MRT	40	MORTAR, GRAY, CEMENTITIOUS, ASSOCIATED WITH BRICK, 4"X16", RED, CEMENTITIOUS	S	NF	3,000	SF
M	SLT	41	SEALANT, BROWN, PLIABLE	S	NF	30	SF
M	SLT	42	SEALANT, BLACK, TAR-LIKE	A	NF	7	SF
M	GWT	43	GLAZED WALL TILE, 4"X4", PINK, SMOOTH, BLACK AND WHITE	A	NF	2,000	SF
M	GRT	44	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", PINK, SMOOTH, BLACK AND WHITE	A	NF	200	SF
M	CMT	45	CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	A	NF	550	SF
M	GRT	46	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", PINK, SMOOTH	A	NF	55	SF
M	GWT	47	GLAZED WALL TILE, 4"X4", BLUE, SMOOTH, BLACK AND WHITE	A	NF	2,000	SF
M	GRT	48	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X4", BLUE, SMOOTH, BLACK AND WHITE	A	NF	200	SF
M	CMT	49	CERAMIC MOSAIC TILE, 2"X2", BLUE, SMOOTH	A	NF	550	SF
M	GRT	50	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH CERAMIC MOSAIC TILE, 2"X2", BLUE, SMOOTH	A	NF	55	SF
S	TOT	51	TROWELED-ON TEXTURE, WHITE, CHALKY	S	NF	550	SF
M	GWB	52	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH TROWELED-ON TEXTURE, WHITE, CHALKY	S	NF	550	SF
S	JTC	53	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	S	NF	55	SF
M	WAB	54	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	S	NF	20	SF
M	ADH	55	ADHESIVE, BROWN, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	S	NF	20	SF
M	VST	56	VINYL STAIR TREAD, 10"X36", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	30	SF
M	MAS	57	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL STAIR TREAD, 10"X36", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	30	SF
M	APL	58	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, SQUARE PATTERN, TAN	S	F	750	SF
M	VCT	59	VINYL COMPOSITION TILE, 24"X24", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF
M	MAS	60	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 24"X24", GRAY, VINYL-LIKE, CIRCLE PATTERN	A	NF	250	SF

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Main Building*

JOB NO. 07-345

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	VCT	61	VINYL COMPOSITION TILE, 2"X24", BLACK, VINYL-LIKE, YELLOW, RED, GREEN, BLUE, STRIP	S	NF	70	SF
M	APL	62	ACOUSTICAL CEILING PANEL, 2'X4', WHITE, CHALKY, VINYL COVER	A	NF	500	SF
M	GWB	63	GLAZED WALL TILE, 4"X6", PINK, SMOOTH	A	NF	10	SF
M	GRT	64	GROUT, GRAY, CEMENTITIOUS, ASSOCIATED WITH GLAZED WALL TILE, 4"X6", PINK, SMOOTH	A	NF	1	SF
M	CON	65	CONCRETE, GRAY, CEMENTITIOUS	A	NF	45,000	SF
M	CON	66	CONCRETE, GRAY, CEMENTITIOUS	A	NF	18,000	SF
M	STU	67	STUCCO, GRAY, CEMENTITIOUS	A	NF	4,000	SF
M	EXJ	68	EXPANSION JOINT, RED, PLIABLE	A	NF	100	SF
M	EXJ	69	EXPANSION JOINT, BROWN, FIBROUS	A	NF	500	SF
M	BUR	70	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	42,000	SF
M	MAS	71	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	100	SF
M	SLT	72	SEALANT (FLASHING), GRAY, PLIABLE	A	NF	25	SF
M	GAS	73	GASKET, 8", WHITE, PAPER-LIKE	A	NF	5	SF
M	SLT	74	SEALANT (EQUIPMENT), BLACK, TAR-LIKE	A	NF	10	SF
M	BUR	75	BUILT-UP ROOFING, BLACK, ASPHALTIC, WHITE COATING	A	NF	200	SF
M	APR	76	ASPHALT PREPARED ROOFING (SHINGLES), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	300	SF
M	VBF	77	VAPOR BARRIER FELT, BLACK, ASPHALTIC	A	NF	300	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 50/51*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,300	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	325	SF
M	CPT	07	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	MAS	08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	WAB	11	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	80	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	80	SF
M	SAC	13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M	SLT	14	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	FDI	15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	DST	16	DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	S	F	8	SF
M	SLT	17	SEALANT (DUCT), GRAY, PLIABLE	A	NF	20	SF
M	SLT	18	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	SLT	19	SEALANT, BROWN, PLIABLE	A	NF	4	SF
M	CON	20	CONCRETE, GRAY, CEMENTITIOUS	A	NF	1,300	SF
M	EXJ	21	EXPANSION JOINT, BROWN, FIBROUS	A	NF	60	SF
M	PES	22	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M	BUR	24	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	A	NF	1,800	SF
M	SLT	25	SEALANT (EQUIPMENT), WHITE, BRITTLE	A	NF	2	SF
M	SLT	26	SEALANT (EQUIPMENT), BLACK, PLIABLE	A	NF	2	SF
M	MAS	27	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 52/53*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	03	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,300	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	325	SF
M	CPT	07	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	MAS	08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	WAB	11	WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVERED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	SAC	13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M	SLT	14	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	FDI	15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	DST	16	DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	S	F	8	SF
M	SLT	17	SEALANT (DUCT), GRAY, PLIABLE	A	NF	20	SF
M	SLT	18	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	SLT	19	SEALANT, BROWN, PLIABLE	A	NF	4	SF
M	CON	20	CONCRETE, GRAY, CEMENTITIOUS	A	NF	1,500	SF
M	EXJ	21	EXPANSION JOINT, BROWN, FIBROUS	A	NF	75	SF
M	PES	22	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M	GAS	23	GASKET, 10", WHITE, PAPER-LIKE	A	NF	1	SF
M	BUR	24	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	A	NF	1,800	SF
M	SLT	25	SEALANT (EQUIPMENT), WHITE, BRITTLE	A	NF	2	SF
M	SLT	26	SEALANT (EQUIPMENT), BLACK, PLIABLE	A	NF	2	SF
M	MAS	27	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 54/55*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,300	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	325	SF
M	CPT	07	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,450	SF
M	MAS	08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,450	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	350	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	350	SF
M	WAB	11	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	SAC	13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M	SLT	14	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	FDI	15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	DST	16	DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	S	F	8	SF
M	SLT	17	SEALANT (DUCT), GRAY, PLIABLE	A	NF	20	SF
M	SLT	18	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	SLT	19	SEALANT, BROWN, PLIABLE	A	NF	4	SF
M	CON	20	CONCRETE, GRAY, CEMENTITIOUS	A	NF	2,100	SF
M	EXJ	21	EXPANSION JOINT, BROWN, FIBROUS	A	NF	105	SF
M	PES	22	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M	BUR	24	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	A	NF	1,800	SF
M	SLT	25	SEALANT (EQUIPMENT), WHITE, BRITTLE	A	NF	2	SF
M	SLT	26	SEALANT (EQUIPMENT), BLACK, PLIABLE	A	NF	2	SF
M	MAS	27	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 56/57*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	03	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,300	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	325	SF
M	CPT	07	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	MAS	08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	WAB	11	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	SAC	13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M	SLT	14	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	FDI	15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	DST	16	DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	S	F	8	SF
M	SLT	17	SEALANT (DUCT), GRAY, PLIABLE	A	NF	20	SF
M	SLT	18	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	SLT	19	SEALANT, BROWN, PLIABLE	A	NF	4	SF
M	CON	20	CONCRETE, GRAY, CEMENTITIOUS	A	NF	2,100	SF
M	EXJ	21	EXPANSION JOINT, BROWN, FIBROUS	A	NF	105	SF
M	PES	22	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M	GAS	23	GASKET, 10", WHITE, PAPER-LIKE	A	NF	1	SF
M	BUR	24	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	A	NF	1,800	SF
M	SLT	25	SEALANT (EQUIPMENT), WHITE, BRITTLE	A	NF	2	SF
M	SLT	26	SEALANT (EQUIPMENT), BLACK, BRITTLE	A	NF	2	SF
M	MAS	27	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 58/59*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,300	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	325	SF
M	CPT	07	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	MAS	08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	WAB	11	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	SAC	13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M	SLT	14	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	FDI	15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	DST	16	DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	S	F	8	SF
M	SLT	17	SEALANT (DUCT), GRAY, PLIABLE	A	NF	20	SF
M	SLT	18	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	SLT	19	SEALANT, BROWN, PLIABLE	A	NF	4	SF
M	CON	20	CONCRETE, GRAY, CEMENTITIOUS	A	NF	1,100	SF
M	EXJ	21	EXPANSION JOINT, BROWN, FIBROUS	A	NF	55	SF
M	PES	22	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M	BUR	24	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	A	NF	1,800	SF
M	SLT	25	SEALANT (EQUIPMENT), WHITE, BRITTLE	A	NF	2	SF
M	SLT	26	SEALANT (EQUIPMENT), BLACK, BRITTLE	A	NF	2	SF
M	MAS	27	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	2	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Portable 60/61*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
M	APL	01	ACOUSTICAL CEILING PANEL, 2'X2', GRAY, PINHOLES AND FISSURES, WHITE	S	F	1,800	SF
S	SAT	02	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
M	GWB	03	GYPSUM WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	1,900	SF
S	JTC	04	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSUM WALLBOARD, WHITE, CHALKY	A	NF	190	SF
M	TWP	05	TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	1,300	SF
M	ADH	06	ADHESIVE, BROWN, BRITTLE, ASSOCIATED WITH TACKABLE WALL PANEL, BROWN, FIBROUS, VINYL-COVER	A	NF	325	SF
M	CPT	07	CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	MAS	08	MASTIC, YELLOW, TACKY, ASSOCIATED WITH CARPET, BLUE, FIBROUS, MULTI-COLORED SPECKS	A	NF	1,500	SF
M	VCT	09	VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	MAS	10	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", TAN, SMOOTH, BROWN MOTTLES	A	NF	300	SF
M	WAB	11	WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	ADH	12	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BLUE, VINYL-LIKE	A	NF	60	SF
M	SAC	13	SINK ACOUSTICAL COATING, BLACK, ROUGH	A	NF	4	SF
M	SLT	14	SEALANT, WHITE, PLIABLE	A	NF	6	SF
M	FDI	15	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	DST	16	DUCT SEAM TAPE, 2", WHITE, PAPER-LIKE	S	F	8	SF
M	SLT	17	SEALANT (DUCT), GRAY, PLIABLE	A	NF	20	SF
M	SLT	18	SEALANT, BLACK, PLIABLE	A	NF	6	SF
M	SLT	19	SEALANT, BROWN, PLIABLE	A	NF	4	SF
M	CON	20	CONCRETE, GRAY, CEMENTITIOUS	A	NF	2,000	SF
M	EXJ	21	EXPANSION JOINT, BROWN, FIBROUS	A	NF	100	SF
M	PES	22	PIPE END SEALANT, WHITE, PLIABLE	A	NF	2	SF
M	GAS	23	GASKET, 10", WHITE, PAPER-LIKE	A	NF	1	SF
M	BUR	24	BUILT-UP ROOFING, BLACK, ASPHALTIC, GRAY GRAVEL CAP	A	NF	1,800	SF
M	SLT	25	SEALANT (EQUIPMENT), WHITE, BRITTLE	A	NF	2	SF
M	SLT	26	SEALANT (EQUIPMENT), BLACK, BRITTLE	A	NF	2	SF
M	MAS	27	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	10	SF

END OF TABLE

JOB NAME: *Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Restroom Portable*

JOB NO. 07-345

**TABLE B
HOMOGENEOUS AREAS OF SUSPECT CONTAINING BUILDING MATERIALS**

MTL TYPE	MTL AVB	SEQ NO	MATERIAL DESCRIPTION	CLSS MTHD	F/NF	MTL QUAN	UNITS
S	SAT	01	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
M	GWB	02	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	2,500	SF
S	JTC	03	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	250	SF
M	VSF	04	VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLED, GRAY PAPER BACKING	A	NF	260	SF
M	MAS	05	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, WHITE, SMOOTH, GRAY MARBLED, GRAY PAPER BACKING	A	NF	260	SF
M	SLT	06	SEALANT, WHITE, PLIABLE	A	NF	20	SF
M	FDI	07	FIRE DOOR INSULATION, METAL CLADDING	A	NF	84	SF
M	VCT	08	VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, BROWN MOTTLES	A	NF	150	SF
M	MAS	09	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL COMPOSITION TILE, 12"X12", BROWN, SMOOTH, BROWN MOTTLES	A	NF	150	SF
M	WAB	10	WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	25	SF
M	ADH	11	ADHESIVE, CREAM, PLIABLE, ASSOCIATED WITH WALLBASE (COVED), 4", BROWN, VINYL-LIKE	A	NF	25	SF
S	SAT	12	SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	300	SF
M	GWB	13	GYPSON WALLBOARD, WHITE, CHALKY, ASSOCIATED WITH SPRAY-APPLIED TEXTURE, WHITE, CHALKY	A	NF	300	SF
S	JTC	14	JOINT COMPOUND, WHITE, CHALKY, ASSOCIATED WITH GYPSON WALLBOARD, WHITE, CHALKY	A	NF	30	SF
M	VSF	15	VINYL SHEET FLOORING, BROWN, SMOOTH, WHITE MARBLED, GRAY PAPER BACKING	A	NF	1,200	SF
M	MAS	16	MASTIC, YELLOW, TACKY, ASSOCIATED WITH VINYL SHEET FLOORING, BROWN, SMOOTH, WHITE MARBLED, GRAY PAPER BACKING	A	NF	1,200	SF
M	SLT	17	SEALANT, BROWN, PLIABLE	A	NF	3	SF
M	CON	18	CONCRETE, GRAY, CEMENTITIOUS	A	NF	250	SF
M	BUR	19	BUILT-UP ROOFING (ROLLED), BLACK, ASPHALTIC, GRAY MINERAL CAP	A	NF	800	SF
M	MAS	20	MASTIC (PENETRATIONS AND FLASHINGS), BLACK, BRITTLE	A	NF	10	SF

END OF TABLE

2.7 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **FIFTEEN** friable suspect ACBM (acoustical ceiling panels and duct seam tape) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.8 Sample Collection

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples was collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
Main	77 (39 Assumed)	114
Portable 50/51	26 (24 Assumed)	6
Portable 52/53	27 (25 Assumed)	6
Portable 54/55	26 (24 Assumed)	6
Portable 56/57	27 (25 Assumed)	6
Portable 58/59	26 (24 Assumed)	6
Portable 60/61	27 (25 Assumed)	6
Restroom Portable	20 (20 Assumed)	0
TOTAL	256	150

Suspect ACM Designation and Sample Record Forms are presented in Appendix A.

2.9 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a Chain-of-Custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single bulk-material sample is sufficient to classify that material as an ACM. On the other hand, a *minimum* of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

Bulk-Material Sample Documentation is presented in Appendix C. These forms identify the samples analytically tested by the laboratory. These laboratory records denote layer identification and material composition by sample percentage.

END OF REPORT

APPENDIX A

Suspect Asbestos-Containing Material Designation and Sample Record Forms

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x2'
 Matrix/Primary Color: Gray Texture/Pattern: Patches & Fissures (Heavy) Cover/Secondary Color: White
 Quantity of Material: 40,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 26	NE Corner	W 10'	S 8'	8'	F / W / C / O
B	PE STORAGE	NE Corner	W 8'	S 4'	8'	F / W / C / O
C	Reception	NE Corner	W 6'	S 14'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-APL-02 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2x2'
 Matrix/Primary Color: Gray Texture/Pattern: Patches & Fissures Cover/Secondary Color: White
 Quantity of Material: 2000 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 26	NE Corner	W 2'	S 18'	8'	F / W / C / O
B	PE STORAGE	NE Corner	W 10'	S 12'	8'	F / W / C / O
C	Reception	NE Corner	W 14'	S 8'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

F M
GROUP INC

FM GROUP/forms/SuspACM/DesignRecord1.omf

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-SAT-03 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chisel Cover/Secondary Color: N/A
 Quantity of Material: 55,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Library	SE Corner	W 20'	N 0'	2'	F/W/C/O
B	Faculty Work Room	NE Corner	W 8'	S 0'	2'	F/W/C/O
C	Gifted Room	NE Corner	W 6'	S 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GRV13-04 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wall board Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 35,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Library	SE Corner	W 20'	N 0'	2'	F / W / C / O
B	Faculty Work Room	NE Corner	W 8'	S 0'	2'	F / W / C / O
C	Gifted Room	NE Corner	W 6'	S 0'	2'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-03

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

FIM GROUP/forms/SuspAC/MSigRecord.0mf

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-05 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 3500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Library	SE Corner	W 20'	N 0'	2'	F/W/C/O
B	Faculty Work Room	NE Corner	W 8'	S 0'	2'	F/W/C/O
C	Gifted Room	NE Corner	W 6'	S 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6WB-04

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-TWP-06 Damaged: Yes No Friable Non-Friable

General Description: Tackable Wall Panel Size: N/A

Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Unexposed

Quantity of Material: 14000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter

AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-02 Damaged: Yes No Friable Non-Friable
 Visible Covered TWP Size: N/A

General Description: Adhesive Cover/Secondary Color: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Br.Hk
 Quantity of Material: 3500 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TAP-06

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-CPT-08 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Fibers Cover/Secondary Color: Multi-colored specks
 Quantity of Material: 33,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	NW Corner	E 4'	S 2"	0'	F/W/C/O
B	Library	NW Corner	E 2"	S 0'	0'	F/W/C/O
C	Corridor 6	NW Corner	E 0'	S 0'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP/forms/SuspACM/DesignRecord.omf

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-09 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 33,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Reception	NW Corner	E 4'	S 2"	0'	F/W/I/C/O
B	Library	NW Corner	E 2"	S 0'	0'	F/W/I/C/O
C	Corridor G	NW Corner	E 0'	S 0'	0'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: Associated with M-CPT-08

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MRT-10 Damaged: Yes No Friable Non-Friable

General Description: Mortar Size: N/A

Matrix/Primary Color: GRAY Cover/Secondary Color: N/A

Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ALL GLASS BLOCK, 8x8", CLEAR

Inspector: Dane Thompson Michael Richter
AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A

Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Special EP 1	SW Corner	E 4'	N 0'	4"	F / W / C / O
B	Room 27	NW Corner	E 2'	S 0'	4"	F / W / C / O
C	Room 15	NW Corner	E 10'	S 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D-10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-ADH-1A Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Covered WAB3 Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Special EP 1	SW Corner	E 4'	N 0'	4"	F / W / C / O
B	Room 27	NW Corner	E 2'	S 0'	4"	F / W / C / O
C	Room 15	NW Corner	E 10'	S 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790
 Signature: [Signature] Date: 10/9/07
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-FD1-13 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 693 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10799 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesigRecord1.omf

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-FDI-14 Damaged: Yes No Friable Non-Friable

General Description: Fire Door Insulation Size: N/A

Matrix/Primary Color: N/A Texture/Pattern: Wood Cladding Cover/Secondary Color: N/A

Quantity of Material: 1050 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter

AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SCT-15 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 10	SE Corner	W 2'	N 0'	7'	F / W / C / O
B	Room 22	SW Corner	E 2'	N 0'	7'	F / W / C / O
C	Room 30	SW Corner	E 2'	N 0'	7'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWT-16 Damaged: Yes No Friable Non-Friable
 General Description: Glazed wall tile Size: 6" x 6"
 Matrix/Primary Color: White Texture/Pattern: SMOOTH Cover/Secondary Color: Various
 Quantity of Material: 70 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D-10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GRT-17 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 7 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-16

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-SAT-18 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Visible Covered
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 450 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Treatment Room	NE Corner	W 0'	S 8'	2'	F/W/C/O
B	Nurse's Office	NW Corner	E 0'	S 1'	2'	F/W/C/O
C	Faculty Lounge	NW Corner	E 6'	S 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-19 Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 450 Estimated By: Drawing Field Measure Sampled Assumed

Texture/Pattern: Chalky

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Treatment Room	NE Corner	W 0'	S 8'	2'	F/W/C/O
B	Nurse's Office	NW Corner	E 0'	S 1'	2'	F/W/C/O
C	Faculty Lounge	NW Corner	E 0'	S 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-SAT-18

Inspector: Dane Thompson Michael Richter

AHERA Certificate No: D 9953 State License: EPA AHERA Certificate No: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-JTC-20 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 45 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Treatment Room	NE Corner	W 0'	S 8'	2'	F/W/C/O
B	Nurses Office	NW Corner	E 0'	S 1'	2'	F/W/C/O
C	Faculty Lounge	NW Corner	E 0'	S 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-6413-19

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-VCT-21 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: Brown Texture/Pattern: Smooth Cover/Secondary Color: Tan Nettles

Quantity of Material: 15,000 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 10	SW Corner	E 1'	N 4'	0'	F / I / C / O
B	Room 22	SW Corner	E 4'	N 1'	0'	F / I / C / O
C	Room 30	SW Corner	E 4'	N 1'	0'	F / I / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MA S- 22 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: BATH Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 10	SW Corner	E 1'	N 4'	0'	F/W/C/O
B	Room 22	SW Corner	E 4'	N 1'	0'	F/W/C/O
C	Room 30	SW Corner	E 4'	N 1'	0'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-VCT-21 & M-VCT-61

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-SAT-23 Damaged: Yes No Friable Non-Friable

General Description: Spray-Applied Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN WATER HEATER CLOSET	NW Corner	E 0'	S 2'	4"	F/W/C/O
B	JANITOE ELECTRIC CLOSET	NE Corner	W 5'	S 0'	4'	F/W/C/O
C	STORAGE 1	NW Corner	E 4'	S 0'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Michael Richter

AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWB-24 Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboard Visible Covered SAT Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN WATER HEATER CLOSET	NW Corner	E 0'	S 2'	4"	F/W/C/O
B	JANITOR ELECTRIC CLOSET	NE Corner	W 5'	S 0'	4'	F/W/C/O
C	STORAGE 1	NW Corner	E 4'	S 0'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-SAT-23

Inspector: Dane Thompson

Inspector: Michael Richter

AHERA Certificate No.: D 9953

State License: EPA

AHERA Certificate No.: D 10790

State License: EPA

Signature: [Signature]

Date: 10/9/07

Signature: [Signature]

Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTR-25 Damaged: Yes No Friable Non-Friable
 General Description: JOINT COMPOUND Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN WATER HEATER CLOSET	NW Corner	E 0'	S 2'	4"	F/W/C/O
B	HALLWAY ELECTRIC CLOSET	NE Corner	W 5'	S 0'	4'	F/W/C/O
C	STORAGE 1	NW Corner	E 4'	S 0'	4'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-24

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GAS-26 Damaged: Yes No Friable Non-Friable
 General Description: GASKET Size: 8"

Matrix/Primary Color: Red Texture/Pattern: Rubber-Like Cover/Secondary Color: N/A
 Quantity of Material: 1 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWB-27 Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboard Texture/Pattern: Chalky Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 15,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	NORTH WING	NW Corner	E 2'	S 0'	8'	F/W/C/O
B	SOUTH WING	NW Corner	E 8'	S 0'	8'	F/W/C/O
C	STAGE	NE Corner	W 2'	S 0'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson

AHERA Certificate No.: D 9953 State License: EPA

Signature: [Signature] Date: 10/9/07

Inspector: Michael Richter

AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-28 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	NORTH WING	NW Corner	E 2'	S 0'	8'	F/W/C/O
B	SOUTH WING	NW Corner	E 8'	S 0'	8'	F/W/C/O
C	STAGE	NE Corner	W 2'	S 0'	8'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-27

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-6288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SAC-29 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 56 Estimated By: Drawing Field Measure
 Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWB-30 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 5000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN	NW Corner	E 4'	S 0'	8'	F/W/C/O
B	WOMENS REST ROOM	NE Corner	W 0'	S 2'	2'	F/W/C/O
C	MEN'S REST ROOM	NW Corner	E 0'	S 2'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-31 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: JOINT COMPOUND Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN	NW Corner	E 4'	S 0'	8'	F/W/C/O
B	WOMENS REST ROOM	NE Corner	W 0'	S 2'	2'	F/W/C/O
C	MENS REST ROOM	NW Corner	E 0'	S 2'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWRS-30

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No: D 9953 AHERA Certificate No: D 10790 State License: EPA State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-6WB-3Z Damaged: Yes No Friable Non-Friable

General Description: Gypsum Wallboard Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 10,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 10	NE Corner	W 8'	S 8'	9'	F/W/C/O
B	Room 23	NE Corner	W 8'	S 8'	9'	F/W/C/O
C	Room 20	NE Corner	W 8'	S 8'	9'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Michael Richter

AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-5TC-33 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1000 Estimated By: Drawing Sampled
 Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 10	NE Corner	W 8'	S 8'	9'	F/W/C/O
B	Room 23	NE Corner	W 8'	S 8'	9'	F/W/C/O
C	Room 20	NE Corner	W 8'	S 8'	9'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-32

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-34 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: Brown Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 170 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other Convenience N/A

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN	NW Corner	E 3'	S 0'	4"	F I C I O
B	P.E. STORAGE	SW Corner	E 1'	N 0'	4"	F I C I O
C	KITCHEN WATER HEATER CLOSET	NW Corner	E 1'	S 0'	4"	F I C I O
D		Corner				F I W I C I O
E		Corner				F I W I C I O
F		Corner				F I W I C I O
G		Corner				F I W I C I O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-ADH-35 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered WAB Size: N/A

Matrix/Primary Color: Cream Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 170 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	KITCHEN	NW Corner	E 3'	S 0'	4"	F / W / C / O
B	P.E. STORAGE	SW Corner	E 1'	N 0'	4"	F / W / C / O
C	KITCHEN WATER HEATER CLOSET	NW Corner	E 1'	S 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-34

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-ADH-36 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 150 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with Fiberglass Reinforced Paneling, white, textured

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-VCT-37 Damaged: Yes No Friable Non-Friable

General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: TAN MOTTLES

Quantity of Material: 15 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	WOMAN'S REST ROOM	NE Corner	W Z'	S 8'	0'	F/W/I/C/O
B	WOMAN'S REST ROOM	NE Corner	W Z'	S 8'	0'	F/W/I/C/O
C	WOMAN'S REST ROOM	NE Corner	W Z'	S 8'	0'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments:

Inspector: Dane Thompson

AHERA Certificate No: D 9953 State License: EPA

Signature: [Signature] Date: 10/9/07

Inspector: Michael Richter

AHERA Certificate No: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-38 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered VCT Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 15 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	WOMAN'S REST ROOM	NE Corner	W 2'	S 8'	0'	F/W/I/C/O
B	WOMAN'S REST ROOM	NE Corner	W 2'	S 8'	0'	F/W/I/C/O
C	WOMAN'S REST ROOM	NE Corner	W 2'	S 8'	0'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: Associated with M-VCT-37

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-BRK-39 Damaged: Yes No Friable Non-Friable
 General Description: Brick Size: 4" x 16"

Matrix/Primary Color: Red Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 30,000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LIBRARY	NE Corner	W 2'	S 0'	8"	F/W/C/O
B	EXTERIOR	NE Corner	W 10'	S 0'	2'	F/W/C/O
C	EXTERIOR	SW Corner	E 8'	N 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston Chandler, Az
 Campus Name: Kyrene del Sureno

Material Code: M-MKT-40 Damaged: Yes No Friable Non-Friable
 General Description: Mortar Size: N/A

Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	LIBRARY	NE Corner	W 2'	S 0'	8"	F/W/C/O
B	EXTERIOR	NE Corner	W 10'	S 0'	2'	F/W/C/O
C	EXTERIOR	SW Corner	E 8'	N 0'	2'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-BRK-39

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: Michael Richter Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-41 Damaged: Yes No Friable Non-Friable

General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Plaque Cover/Secondary Color: N/A

Quantity of Material: 30 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	CORRIDOR 9	SE Corner	W 0'	N 0'	4'	F / W / C / O
B	CORRIDOR 8	SW Corner	E 0'	N 0'	4'	F / W / C / O
C	CORRIDOR 15	SE Corner	W 2'	N 4'	4'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SCT-42 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: TPE-LIKE Cover/Secondary Color: N/A
 Quantity of Material: 7 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWT-43 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: GLAZED WALL TILE Size: 4" x 4"
 Matrix/Primary Color: PINK Texture/Pattern: Smooth Cover/Secondary Color: BLACK + White

Quantity of Material: 2000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWT-44 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: GROUT Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-43

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-CMT-45 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Ceramic Mosaic Tile Size: 2" x 2"
 Matrix/Primary Color: Pink Texture/Pattern: Smooth Cover/Secondary Color: N/A

Quantity of Material: 550 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GRET-46 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 55 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-45

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWT-47 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 4" x 4"

General Description: GLAZED WALL TILE Texture/Pattern: SMOOTH Cover/Secondary Color: BLACK + white
 Matrix/Primary Color: BLUE Estimated By: Drawing Field Measure
 Quantity of Material: 2000 (SF / LF / EA) Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA
 AHRA Certificate No.: D 9953 State License: EPA
 Signature: [Signature] Date: 10/9/07
 Inspector: Michael Richter State License: EPA
 AHRA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes As-umed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-6 RT-48 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Size: N/A
 Matrix/Primary Color: GRAY Cover/Secondary Color: N/A
 Quantity of Material: 200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWT-47

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



19974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CMT-49 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2" x 2"

General Description: Ceramic Mosaic Tile Texture/Pattern: Smooth Cover/Secondary Color: N/A
 Matrix/Primary Color: Blue Estimated By: Drawing Field Measure
 Quantity of Material: 550 (SF / LF / EA)

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No. D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GRT-50 Damaged: Yes No Friable Non-Friable
 General Description: GROUT Visible Covered Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 55 Estimated By: Drawing Sampled Assumed
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CMT-49

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 Date: 10/9/07
 Michael Richter State License: EPA AHERA Certificate No.: D 10790 Date: 10/9/07
 Signature: *[Signature]*

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-TOT-51 Damaged: Yes No Friable Non-Friable
 General Description: Traveled - on Texture Size: N/A

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 550 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SOUTH WING	SE Corner	W 1'	N 0'	5'	F/W/C/O
B	SOUTH WING	NE Corner	W 0'	S 3'	5'	F/W/C/O
C	SOUTH WING	SE Corner	W 1'	N 0'	5'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-52 Damaged: Yes No Friable Non-Friable

General Description: Gypsum wall board Size: N/A

Matrix/Primary Color: White Cover/Secondary Color: N/A

Quantity of Material: 550 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SOUTH WING	SE Corner	W 1'	N 0'	5'	F/W/C/O
B	SOUTH WING	NE Corner	W 0'	S 3'	5'	F/W/C/O
C	SOUTH WING	SE Corner	W 1'	N 0'	5'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with S-TOT-51

Inspector: Dane Thompson Michael Richter
AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Main Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-JTC-53 Damaged: Yes No Friable Non-Friable

Size: N/A

General Description: Joint Compound

Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A

Quantity of Material: SS Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SOUTH WING	SE Corner	W 1'	N 0'	5'	F/W/C/O
B	SOUTH WING	NE Corner	W 0'	S 3'	5'	F/W/C/O
C	SOUTH WING	SE Corner	W 1'	N 0'	5'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: Associated with M-GWB-52

Inspector: Dane Thompson

AHERA Certificate No.: D 9953 State License: EPA

Signature: [Signature]

Date: 10/9/07

Inspector: Michael Richter

AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-54 Damaged: Yes No Friable Non-Friable
 General Description: WALL BASE (COVERED) Size: 4"

Matrix/Primary Color: Brown Texture/Pattern: Vinyl - Like Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SOUTH WING	NW Corner	E 0'	S 1'	4"	F / W / C / O
B	STAGE	NW Corner	E 6'	S 0'	4"	F / W / C / O
C	STAGE	SW Corner	E 6'	N 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson State License: EPA
 Michael Richter State License: EPA
 AHERA Certificate No.: D 9953 Date: 10/9/07
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-ADH-55 Damaged: Yes No Friable Non-Friable
 Visible Covered WAB Size: N/A

General Description: Adhesive Matrix/Primary Color: Brown Cover/Secondary Color: N/A
 Texture/Pattern: Pliable Estimated By: Drawing Field Measure
 Quantity of Material: 20 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	SOUTH WING	NW Corner	E 0'	S 1'	4"	F / W / C / O
B	STAGE	NW Corner	E 6'	S 0'	4"	F / W / C / O
C	STAGE	SW Corner	E 6'	N 0'	4"	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-54

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston Chandler, AZ
 Campus Name: Kyrene del Sureno

Material Code: M-VST-56 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Stair Tread Size: 10" x 36"
 Matrix/Primary Color: GRAY Texture/Pattern: Vinyl-Like Cover/Secondary Color: Circle Pattern
 Quantity of Material: 30 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA
 AHERA Certificate No.: D 9953 State License: EPA
 Signature: [Signature] Date: 10/9/07
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MAS-57 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VST-56

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-APL-58 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2X2
 Matrix/Primary Color: GRAY Texture/Pattern: SQUARE PATTERN Cover/Secondary Color: TAN
 Quantity of Material: 750 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MULTI PURPOSE	NW Corner	E 12'	S 4'	10'	F/W/C/O
B	MULTI PURPOSE	NE Corner	W 8'	S 4'	10'	F/W/C/O
C	MULTI PURPOSE	SE Corner	W 8'	N 4'	10'	F/W/C/O
D		Corner				F/W/C/O
E		Corner				F/W/C/O
F		Corner				F/W/C/O
G		Corner				F/W/C/O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-VCT-59 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: VINYL COMPOSITION TILE Size: 24x24"
 Matrix/Primary Color: GRAY Cover/Secondary Color: CYCLE PATTERNS

Quantity of Material: 250 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

EM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-600 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered Size: N/A
 Matrix/Primary Color: YELLOW Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-VCT-59

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston Chandler, AZ
 Campus Name: Kyrene del Sureno

Material Code: M-VCT-601 Damaged: Yes No Friable Non-Friable
 General Description: VINYL COMPOSITION TILE Size: 2" x 24"

Matrix/Primary Color: BLACK Texture/Pattern: SMOOTH Cover/Secondary Color: YELLOW, RED, GREEN, BLUE
 Quantity of Material: 70 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	MULTI PURPOSE ROOM	SE Corner	W 27'	N 4'	0'	F/W/I/C/O
B	MULTI PURPOSE ROOM	SE Corner	W 27'	N 24'	0'	F/W/I/C/O
C	MULTI PURPOSE ROOM	SE Corner	W 32'	N 24'	0'	F/W/I/C/O
D		Corner				F/W/I/C/O
E		Corner				F/W/I/C/O
F		Corner				F/W/I/C/O
G		Corner				F/W/I/C/O

Comments: Strip

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-APL-402 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 2X4

General Description: ACOUSTICAL CEILING PANEL
 Matrix/Primary Color: WHITE Texture/Pattern: CHALKY Cover/Secondary Color: VINYL COVER
 Quantity of Material: 500 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWTF-603 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: GLAZED WALL TILE Size: 4x6
 Matrix/Primary Color: PINK Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By: Drawing Field Measure
 Sampling: Random Convenience N/A

Homogeneous Material Location: Ceiling Floor Wall Other

Texture/Pattern: SMOOTH
 SF / LF / EA

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GRY-64 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: GIBBOUT Size: N/A

Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 1 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: ASSOCIATED WITH M-GWT-63

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-605 Damaged: Yes No Friable Non-Friable

General Description: CONCRETE Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A

Quantity of Material: 45,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-CON-006 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CONCRETE
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTIOUS Cover/Secondary Color: N/A
 Quantity of Material: 18000 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

EM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-STU-67 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: STUCCO
 Matrix/Primary Color: GRAY Texture/Pattern: CEMENTITIOUS Cover/Secondary Color: N/A
 Quantity of Material: 4000 Estimated By: Drawing Field Measure
 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-EXS-608 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: EXPANSION JOINT Compound Texture/Pattern: PUABLE Cover/Secondary Color: N/A
 Matrix/Primary Color: Red Estimated By: Drawing Field Measure
 Quantity of Material: 100 (SF) / LF / EA Sampling Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-BUR-70 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: BUILT UP ROOFING Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC Cover/Secondary Color: Gray Mineral Cap
 Quantity of Material: 42,000 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

F/M GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MA5-71 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC (PENETRATIONS AND FLASHING) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Signature: *[Signature]* Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Gaiveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-7Z Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (FLASHING) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 25 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

EM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GAS-73 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 8"

General Description: GASKET Texture/Pattern: PAPER-LIKE Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Estimated By: Drawing Field Measure
 Quantity of Material: 5 SF / LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-6288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-5LT-74 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (EQUIPMENT) Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: TAP LIKE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Main Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-BUE-75 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT-UP ROOFING Cover/Secondary Color: WHITE COATING
 Matrix/Primary Color: BLACK Texture/Pattern: ASPHALTIC
 Quantity of Material: 200 (SF) LF / EA Estimated By: Drawing Field Measure
 Sampling Random Convenience N/A Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Main **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-APC-76 Visible Covered Damaged: Yes No Friable Non-Friable
General Description: Asphalt Prepared Roofing (Shingles) **Size:** N/A
Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** Gray Mineral Cap
Quantity of Material: 300 SF LF EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 10/9/07 **Signature:** *[Signature]* **Date:** 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Main **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-VSF-77 Visible Covered APR **Damaged:** Yes No Friable Non-Friable
General Description: Vapor Barrier Felt **Size:** N/A

Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** N/A
Quantity of Material: 300 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other **Manner of Sampling:** Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-APR-76

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 10/9/07 **Signature:** [Signature] **Date:** 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP forms/SuspACMDesignRecord.omf

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 2'
 Matrix/Primary Color: Gray Texture/Pattern: Pinholes & Fissures Cover/Secondary Color: White
 Quantity of Material: 1800 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 50	NE Corner	W 2'	S 8'	8'	F / W / C / O
B	Room 50	NW Corner	E 2'	S 12'	8'	F / W / C / O
C	Room 51	NW Corner	E 2'	S 12'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D-9953 State License: EPA AHERA Certificate No.: D-10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Charley Cover/Secondary Color: N/A
 Quantity of Material: 1900 (SF) LF / EA Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D.9953 State License: EPA AHERA Certificate No.: D.10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wall Board Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 (SF) LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with 5-SAT-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-04 Visible Covered SAT Damaged: Yes No Size: N/A Friable Non-Friable
 General Description: Joint Compound Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 190 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Core
 Quantity of Material: 1300 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-06 Visible Covered TWP Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 325 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TAP-05

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A
 Matrix/Primary Color: Blue Texture/Pattern: Fibrous Cover/Secondary Color: Multi-colored Speckles
 Quantity of Material: 1500 (SF) / LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tracks Cover/Secondary Color: N/A
 Quantity of Material: 1500 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-101-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" X 12"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: Brown Mottles
 Quantity of Material: 300 (SF) LF / EA Estimated By: Drawing Field Measure
 Sampled
 Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MA5-10 Visible Covered No Yes Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VET-09

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: Blue Texture/Pattern: Wing-Like Cover/Secondary Color: N/A
 Quantity of Material: 80 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-12 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Texture/Pattern: Flakely Cover/Secondary Color: N/A Size: N/A
 Matrix/Primary Color: Green Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 80 (SF) LF / EA Other Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Ceiling Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 Date: 10/9/07
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790 Date: 10/9/07
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Plank Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assured

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-FDI-15 Damaged: Yes No Friable Non-Friable
 General Description: Five Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Chording Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-DST-16 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Size: 2"
 Matrix/Primary Color: White Texture/Pattern: Paper Like Cover/Secondary Color: N/A
 Quantity of Material: 8 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ROOM 50	NE Corner	W6'	S10'	9'	F / W / C / O
B	ROOM 50	Corner				F / W / C / O
C	ROOM 51	Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 20 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Puckled Cover/Secondary Color: N/A
 Quantity of Material: 4 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D.9953 State License: EPA AHERA Certificate No.: D.10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Concentric Cover/Secondary Color: N/A
 Quantity of Material: 1300 SF / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-EVJ-21 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M- PFS-22 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Spout Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Diabole Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SUR-24 Damaged: Yes No Friable Non-Friable
 General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray gravel C/P
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M1-SLT-25 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (Equipment) Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Matrix/Primary Color: WHITE Estimated By: Drawing Field Measure
 Quantity of Material: 2 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 50/51 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-5LT-26 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: SEALANT (Equipment) **Size:** N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** PLIABLE **Cover/Secondary Color:** N/A
Quantity of Material: 2 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 10/9/07 **Signature:** *[Signature]* **Date:** 10/9/07

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 50/51 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MA5-ZZ Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MASTIC (PENETRATIONS AND FLASHINGS) Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Matrix/Primary Color: BLACK Estimated By: Drawing Field Measure Sampled Assumed
 Quantity of Material: 10

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2'x2'
 Matrix/Primary Color: Grey Texture/Pattern: Potholes + Fissures Cover/Secondary Color: White
 Quantity of Material: 1800 Estimated By: Drawing Sampled
 Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 52	NE Corner	W 2'	S 8'	8'	F / W / C / O
B	Room 52	NW Corner	E 2'	S 12'	8'	F / W / C / O
C	Room 53	NW Corner	E 2'	S 12'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A
 General Description: Gypsum Wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Sampled
 Quantity of Material: 1900 (SF) LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 190 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWR-03

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-TWP-OS Damaged: Yes No Friable Non-Friable
 General Description: Trackable Wall Panel Visible Covered
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover Size: N/A
 Quantity of Material: 1300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: *ODA* Date: 10/9/07 Signature: *Michael Richter* Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADIT 06 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 325 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-05

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Carpet Texture/Pattern: Fibres Cover/Secondary Color: Multi-Colored Specks
 Matrix/Primary Color: Blue Estimated By: Drawing Field Measure
 Quantity of Material: 1500 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O


Comments:

Inspector: Michael Richter
 AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered CPT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 1500 (SF) LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Brown Mottles
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MAS-10 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered VCT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Flaky Cover/Secondary Color: N/A
 Quantity of Material: 300 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-12 Damaged: Yes No Friable Non-Friable
 General Description: Adhesion Visible Covered WAB Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 500 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SCT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-FDI-15 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D.9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-DST-16 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Size: 2" Sampled Assumed
 Matrix/Primary Color: White Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 8 (SF) LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 52	NE Corner	W 6'	S 10'	9'	F / W / C / O
B	Room 52	NE Corner	W 22'	S 10'	9'	F / W / C / O
C	Room 53	NE Corner	W 6'	S 10'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 107907 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SCT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (DUCT) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 2.0 Estimated By: Drawing Sampled
 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 State License: EPA
 Signature: [Signature] Date: 10/9/07
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SCT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: Co Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 4 SF LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-EXJ-21 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: BROWN Texture/Pattern: Fibrous Cover/Secondary Color: N/A
 Quantity of Material: 75 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 State License: EPA Michael Richter State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-PES-22 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GAS-23 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: 10"

General Description: GASKET Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Sampled
 Quantity of Material: 1 (SF) / LF / EA Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-BUR-24 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT-UP ROOFING Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Gravel Cap
 Matrix/Primary Color: Black Quantity of Material: 1800 Estimated By: Drawing Field Measure
 (SF) LF / EA Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-25 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (EQUIPMENT) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 52/53 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-2LD Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (EQUIPMENT) Texture/Pattern: PLIABLE Cover/Secondary Color: N/A

Matrix/Primary Color: BLACK Quantity of Material: 2 Estimated By: Drawing Field Measure
 SF / LF / EA Wall Other

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHRA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable 52/53 Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: W-MAS-27 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: MASTIC (PENETRATIONS AND FLASHINGS) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: BRITTLE Cover/Secondary Color: N/A

Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-APC-01 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Acoustical Ceiling Panel Size: 2'x2'
 Matrix/Primary Color: GRAY Texture/Pattern: Holes & Fissures Cover/Secondary Color: white
 Quantity of Material: 1800 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 54	NE Corner	W 2'	S 8'	8'	F / W / C / O
B	Room 54	NW Corner	E 2'	S 12'	8'	F / W / C / O
C	Room 55	NW Corner	E 2'	S 12'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHRA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 Visible Covered SAT Size: N/A

General Description: Gypsum wallboard Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Matrix/Primary Color: White Estimated By: Drawing Field Measure
 Quantity of Material: 1900

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 190 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Size: NA
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 1300 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA Signature: *[Signature]* Date: 10/9/07
 Michael Richter State License: EPA Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-06 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Bubble Cover/Secondary Color: N/A
 Quantity of Material: 325 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-05

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D.9953 State License: EPA AHERA Certificate No.: D.10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 General Description: CARPET Size: _____

Matrix/Primary Color: BLUE Texture/Pattern: Fibrous Cover/Secondary Color: Multi-Colored Specks
 Quantity of Material: 1450 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM


 15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MA5-08 Visible Covered CPT Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 1450 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 Date: 10/9/07
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790 Date: 10/9/07
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: 11-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: Brown Mattes
 Quantity of Material: 350 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-10 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered VCT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 350 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: BLUE Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-12 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: SINK Acoustical Coating Size: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SCT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-FD1-15 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-DST-16 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Size: 2"
 Matrix/Primary Color: White Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 8 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 54	NE Corner	W 6'	S 10'	9'	F / W / C / O
B	Room 54	NE Corner	W 22'	S 10'	9'	F / W / C / O
C	Room 55	NE Corner	W 6'	S 10'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 6 (SF) LF / EA Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Sampled Assumed
 LF / EA Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: Concentric Cover/Secondary Color: N/A
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10799 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-EXJ-21 Damaged: Yes No Friable Non-Friable
 General Description: Expansion Joint Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: N/A
 Quantity of Material: 105 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-PES-22 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 2 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 54/55 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-348-24 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: Built-up Roofing **Size:** N/A

Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** Gray Gravel Cap
Quantity of Material: 1800 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A


Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Date:** 10/9/07 **Signature:** *[Signature]* **Date:** 10/9/07

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-5LT-25 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (Equipment) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ~~ASSUMED~~

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 54/55 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-5LT-20 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: SEALANT (Equipment) Size: N/A

Matrix/Primary Color: BLACK Texture/Pattern: FRIABLE Cover/Secondary Color: N/A

Quantity of Material: 2 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 54/55 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-27 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: MASTIC (PENETRATIONS AND FLASHINGS) **Size:** N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** BEETLE **Cover/Secondary Color:** N/A
Quantity of Material: 10 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 10/9/07 **Signature:** *[Signature]* **Date:** 10/9/07

Asbestos-Containing Material: No Yes **ASSUMED**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 2'
 Matrix/Primary Color: Gray Texture/Pattern: Pinholes + Fissures Cover/Secondary Color: White
 Quantity of Material: 1800 (SF) LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 56	NE Corner	W 2'	S 8'	8'	F / W / C / O
B	Room 56	NW Corner	E 2'	S 12'	8'	F / W / C / O
C	Room 57	NW Corner	E 2'	S 12'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-JTC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 190 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: Tackable wall panel Visible Covered Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 1300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-06 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brite Cover/Secondary Color: N/A
 Quantity of Material: 325 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-05

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: CARPET Texture/Pattern: Fibrous Cover/Secondary Color: Multi-colored Specks
 Matrix/Primary Color: BLUE Estimated By: Drawing Field Measure
 Quantity of Material: 1500 (SF) LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Michael Richter
 AHERA Certificate No.: D.9953 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered CPT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Flaky Cover/Secondary Color: N/A
 Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: CSR Signature: Michael Richter Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: Brown Mottles
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8286 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-10 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered VCT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Jacky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Visible Covered
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A Size: 4"
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA 10790
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-ADH-12 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Visible Covered WAB Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Pebble Cover/Secondary Color: N/A
 Quantity of Material: 60 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: *[Signature]* Date: 10/9/07 Signature: *[Signature]* Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Visible Covered
 Matrix/Primary Color: BLACK Texture/Pattern: Rough Cover/Secondary Color: N/A Size: N/A
 Quantity of Material: 4 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D-10799 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Flakable Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-FDI-15 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Sampled Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D.9953 State License: EPA AHERA Certificate No.: D-10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-DST-16 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Visible Covered Size: 2"
 Matrix/Primary Color: White Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 8 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 56	NE Corner	W 6'	S 10'	9'	F / W / C / O
B	Room 56	NE Corner	W 22'	S 10'	9'	F / W / C / O
C	Room 57	NE Corner	W 6'	S 10'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson State License: EPA
 AHERA Certificate No.: D 9953 State License: EPA
 Signature: [Signature] Date: 10/9/07
 Inspector: Michael Richter State License: EPA
 AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLF-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (DUCT) Visible Covered Size: N/A
 Matrix/Primary Color: GRAY Texture/Pattern: PLIABLE Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SCT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealed Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-CON-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Visible Covered Size: N/A
 Matrix/Primary Color: Grey Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 2100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-EXJ-21 Damaged: Yes No Friable Non-Friable
 General Description: Expansion Joint Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: N/A
 Quantity of Material: 105 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA
 Signature: [Signature] Date: 10/9/07
 AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-PES-22 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 2 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 Date: 10/9/07
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790 Date: 10/9/07
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GAS-23 Damaged: Yes No Friable Non-Friable
 General Description: GASKET Visible Covered Size: 10"
 Matrix/Primary Color: White Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 1 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 56/57 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-BUE-24 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: BUILT-UP ROOFING **Size:** N/A
Matrix/Primary Color: Black **Texture/Pattern:** Asphaltic **Cover/Secondary Color:** Gray Gravel Cap
Quantity of Material: 1800 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 10/9/07 **Signature:** *[Signature]* **Date:** 10/9/07

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-25 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (Equipment) Size: N/A

Matrix/Primary Color: WHITE Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 2 (SF) / LF / EA Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 56/57 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-5LT-240 Damaged: Yes No Friable Non-Friable
 General Description: SEALANT (Equipment) Size: N/A
 Matrix/Primary Color: BLACK Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 56/57 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, Az

Material Code: W1-MAS-27 Visible Damaged: Yes No Friable Non-Friable
 Covered

General Description: MASTIC (PENETRATIONS AND FLASHINGS) **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** BEETLE **Cover/Secondary Color:** N/A
Quantity of Material: 10 **Estimated By:** Drawing Field Measure Sampled Assumed
 SF / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: [Signature] **Date:** 10/9/07 **Signature:** [Signature] **Date:** 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15574 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-APL-D1 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Size: 2' x 2'
 Matrix/Primary Color: Gray Texture/Pattern: Pinholes + Fissures Cover/Secondary Color: White
 Quantity of Material: 1800 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ROOM 58	NE Corner	W 2'	S 8'	8'	F / W / C / O
B	ROOM 58	NW Corner	E 2'	S 12'	8'	F / W / C / O
C	ROOM 59	NW Corner	E 2'	S 12'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790
 Signature: [Signature] Date: 10/9/07
 Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

FM GROUP/forms/SuspACMDesignRecord.omf

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-SAT-02 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Charley Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-3TC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 190 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-03

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 1300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-ADH-06 Visible Covered TWP Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brattle Cover/Secondary Color: N/A
 Quantity of Material: 305 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A
 Matrix/Primary Color: Blue Cover/Secondary Color: Multi-Colored Spots
 Quantity of Material: 1500 Estimated By: Drawing Sampled Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable 58/59 Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MA5-08 Damaged: Yes No Friable Non-Friable

General Description: Washi Size: N/A

Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A

Quantity of Material: 1500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Dane Thompson Inspector: Michael Richter
AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12x12"
 Matrix/Primary Color: Tan Texture/Pattern: Smooth Cover/Secondary Color: Brown Mottles
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-105-10 Visible Covered VCT Damaged: Yes No
 General Description: Mastic Size: N/A Friable Non-Friable
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 300 SF LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: Blue Cover/Secondary Color: N/A
 Quantity of Material: 500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-12 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with m-WAB-11

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax



Project No.: 07-345 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: Sink Acoustical Coating Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHRA Certificate No.: D 9953 State License: EPA AHRA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



16974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Diabolo Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-FDE-15 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Chalking Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28

Building No.: Portable 58/59 Address: 3375 West Galveston

Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-DST-16 Damaged: Yes No Friable Non-Friable

General Description: Duct Seam TAPE Size: 2"

Matrix/Primary Color: white Texture/Pattern: Paper-Like Cover/Secondary Color: N/A

Quantity of Material: 8 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 58	NE Corner	W 6'	S 10'	9'	F / W / C / O
B	Room 58	NE Corner	W 22'	S 10'	9'	F / W / C / O
C	Room 59	NE Corner	W 6'	S 10'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson

AHERA Certificate No.: D 9953 State License: EPA

Signature: [Signature] Date: 10/9/07

Inspector: Michael Richter

AHERA Certificate No.: D 10790 State License: EPA

Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Diabolo Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

F M
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 1106 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FIM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-EJ-21 Damaged: Yes No Friable Non-Friable
 General Description: EXPANSION JOINT Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: N/A
 Quantity of Material: SS Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: DR Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-PES-22 Damaged: Yes No Friable Non-Friable
 General Description: Pipe Encl Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 2 SF / LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 Date: 10/9/07
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790 Date: 10/9/07
 Signature: [Signature] Signature: [Signature]

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 58/59 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-BWR-24 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: BUILT-UP ROOFING Cover/Secondary Color: Gray Gravel - Leg
 Matrix/Primary Color: Black Texture/Pattern: Asphaltic Estimated By: Drawing Field Measure
 Quantity of Material: 1800 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 58/59 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: W-SUT-ZS Visible Damaged: Yes No Friable Non-Friable
General Description: SEALANT (Equipment) Covered **Size:** N/A
Matrix/Primary Color: WHITE **Texture/Pattern:** BRITTLE **Cover/Secondary Color:** N/A
Quantity of Material: 2 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 10/9/07 **Date:** 10/9/07

Asbestos-Containing Material: No Yes **ASSUMED**

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 58/59 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: MAS-26 Visible Covered **Damaged:** Yes No Friable Non-Friable

General Description: MASTIC (PENETRATIONS AND FLASHINGS) **Size:** N/A
Matrix/Primary Color: BLACK **Texture/Pattern:** BRITTLE **Cover/Secondary Color:** N/A

Quantity of Material: 10 SF / LF / EA **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **AHERA Certificate No.:** D10790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 10/9/07 **Date:** 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
Scottsdale, AZ 85260
(602) 277-7877
(602) 277-8288 fax

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 58/59 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-27 Visible Damaged: Yes No Friable Non-Friable
General Description: SEALANT (EQUIPMENT) Covered No Yes Drawing Field Measure
 Size: N/A Cover/Secondary Color: N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** PLIABLE **Estimated By:** Drawing Field Measure
Quantity of Material: 2 (SF) / LF / EA

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **AHERA Certificate No.:** D40790 **State License:** EPA **State License:** EPA
Signature: *[Signature]* **Signature:** *[Signature]* **Date:** 10/9/07 **Date:** 10/9/07

Asbestos-Containing Material: No Yes **ASSUMED**

**SUSPECT ASBESTOS-CONTAINING MATERIAL
 DESIGNATION AND SAMPLE RECORD FORM**



15874 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-APL-01 Damaged: Yes No Friable Non-Friable
 General Description: Acoustical Ceiling Panel Visible Covered Size: 2' x 2'
 Matrix/Primary Color: Gray Texture/Pattern: Potholes & Fossiles Cover/Secondary Color: White
 Quantity of Material: 1800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	ROOM 60	NE Corner	W 2'	S 8'	8'	F / W / C / O
B	ROOM 60	NW Corner	E 2'	S 12'	8'	F / W / C / O
C	ROOM 61	NW Corner	E 2'	S 12'	8'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-SAT-02 Visible Covered Damaged: Yes No Friable Non-Friable
 General Description: Spray Applied Texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: CHALKY Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-03 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wall board Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 1900 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-04 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 190 Estimated By: Drawing Sampled
 Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-FWB-03

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 19790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-TWP-05 Damaged: Yes No Friable Non-Friable
 General Description: Tackable Wall Panel Visible Covered Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: Vinyl Cover
 Quantity of Material: 1300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-06 Visible Covered TWP Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Brittle Cover/Secondary Color: N/A
 Quantity of Material: 3LS Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-TWP-05

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CPT-07 Damaged: Yes No Friable Non-Friable
 General Description: Carpet Size: N/A
 Matrix/Primary Color: Blue Texture/Pattern: Fibers Cover/Secondary Color: Multi-colored Specks
 Quantity of Material: 1500 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D-10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-08 Damaged: Yes No Friable Non-Friable
 General Description: MASTIC Visible Covered CPT Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: TACKY Cover/Secondary Color: N/A
 Quantity of Material: 1500 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-CPT-07

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-VCT-09 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Composition Tile Size: 12" x 12"
 Matrix/Primary Color: TAN Texture/Pattern: Smooth Cover/Secondary Color: Brown Mottles
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-10 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-09

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 19790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-6288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-11 Damaged: Yes No Friable Non-Friable
 General Description: wall base (covered) Size: 4"
 Matrix/Primary Color: Blue Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 60 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-ADH-12 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 60 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-11

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SAC-13 Damaged: Yes No Friable Non-Friable
 General Description: Silk Acoustical Coating Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Rough Cover/Secondary Color: N/A
 Quantity of Material: 4 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-14 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Diabolo Cover/Secondary Color: N/A
 Quantity of Material: 6 (SF) LF / EA Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-6288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-FDE-15 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-DST-16 Damaged: Yes No Friable Non-Friable
 General Description: Duct Seam Tape Size: 2"
 Matrix/Primary Color: White Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 8 Estimated By: Drawing Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A	Room 60	NE Corner	W 6'	S 10'	9'	F / W / C / O
B	Room 60	NE Corner	W 22'	S 10'	9'	F / W / C / O
C	Room 61	NE Corner	W 6'	S 10'	9'	F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____
 Inspector: Dane Thompson State License: EPA AHERA Certificate No.: D 9953 Date: 10/9/07
 Inspector: Michael Richter State License: EPA AHERA Certificate No.: D 10790 Date: 10/9/07
 Signature: _____ Signature: _____

Asbestos-Containing Material: No Yes

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-17 Damaged: Yes No Friable Non-Friable
 General Description: Sealant (Duct) Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Friable Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-18 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: Pebble Cover/Secondary Color: N/A
 Quantity of Material: 6 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes *Assumed*

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-19 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 4 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-20 Damaged: Yes No Friable Non-Friable
 General Description: Concrete Size: N/A
 Matrix/Primary Color: Gray Texture/Pattern: Connections Cover/Secondary Color: N/A
 Quantity of Material: 2000 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-EAS-21 Damaged: Yes No Friable Non-Friable
 General Description: Expansion Joint Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Fibrous Cover/Secondary Color: N/A
 Quantity of Material: 100 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-5288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-PES-22 Damaged: Yes No Friable Non-Friable
 General Description: Pipe End Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 2 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHIERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GAS-23 Damaged: Yes No Friable Non-Friable
 General Description: GASKET Size: 10"
 Matrix/Primary Color: White Texture/Pattern: Paper-Like Cover/Secondary Color: N/A
 Quantity of Material: 1 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHRA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-BAR-241 Visible Covered Damaged: Yes No Friable Non-Friable

General Description: BUILT-UP ROOFING Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Gravel Cap
 Quantity of Material: 1800 (SF) / LF / EA Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-25 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: SEALANT (EQUIPMENT) Texture/Pattern: BEATLE Cover/Secondary Color: N/A

Matrix/Primary Color: WHITE Quantity of Material: 2 Estimated By: Drawing Field Measure

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes ASSUMED

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-9288 fax

FM
GROUP INC

Project No.: 07-345 **Project Name:** AHERA-Compliance Asbestos Inspection **Owner:** Kyrene School District No. 28
Building No.: Portable 60/61 **Address:** 3375 West Galveston
Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SLT-24 Visible Covered **Damaged:** Yes No Friable Non-Friable
General Description: SEALANT (Equipment) **Size:** N/A

Matrix/Primary Color: BLACK **Texture/Pattern:** BRITTLE **Cover/Secondary Color:** N/A
Quantity of Material: 2 **Estimated By:** Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson **Secondary Inspector:** Michael Richter
AHERA Certificate No.: D9953 **State License:** EPA **AHERA Certificate No.:** D10790 **State License:** EPA
Signature: *[Signature]* **Date:** 10/9/07 **Signature:** *[Signature]* **Date:** 10/9/07

Asbestos-Containing Material: No Yes **Assumed**

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Portable 60/61 Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-27 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: MASTIC (PENETRATIONS AND FLASHINGS) Cover/Secondary Color: N/A
 Matrix/Primary Color: BLACK Texture/Pattern: BRITTLE Estimated By: Drawing Field Measure
 Quantity of Material: 10 (SF) LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Lead Inspector: Dane Thompson Secondary Inspector: Michael Richter
 AHERA Certificate No.: D9953 State License: EPA AHERA Certificate No.: D10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM
GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: S-SAT-01 Damaged: Yes No Friable Non-Friable
 General Description: SPRAY-APPLIED TEXTURE Visible Covered Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-GWB-02 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum Wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 2500 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-01

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-03 Damaged: Yes No Friable Non-Friable
 General Description: Joint Compound Visible Covered SAT Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-6013-02

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: _____ Date: 10/9/07 Signature: *Michael Richter* Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-VSF-04 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Sheet Flooring Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Smooth Cover/Secondary Color: Gray Marbled
 Quantity of Material: 260 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-05 Damaged: Yes No Friable Non-Friable
 Visible Covered VSF Size: N/A

General Description: MASTIC Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 260 Estimated By: Drawing Field Measure
 Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VSF-04

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Signature: [Signature] Date: 10/9/07 Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-SUT-06 Damaged: Yes No Friable Non-Friable
 General Description: Sealant Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 20 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-FDI-07 Damaged: Yes No Friable Non-Friable
 General Description: Fire Door Insulation Size: N/A
 Matrix/Primary Color: N/A Texture/Pattern: Metal Cladding Cover/Secondary Color: N/A
 Quantity of Material: 84 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-VCT-08 Visible Visible Covered Damaged: Yes No Friable Non-Friable

General Description: Vinyl Composition Tile Size: 12" x 12"

Matrix/Primary Color: Brown Texture/Pattern: Smooth Cover/Secondary Color: Brown Mottles

Quantity of Material: 150 Estimated By: Drawing Sampled Field Measure Assumed

Homogeneous Material Location: Ceiling Floor Wall Other N/A
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MAS-09 Damaged: Yes No Friable Non-Friable
 Visible Covered VCT Size: N/A

General Description: MASTIC Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Matrix/Primary Color: Yellow Estimated By: Drawing Field Measure
 Quantity of Material: 150 SF / LF / EA Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VCT-08

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-WAB-10 Visible Damaged: Yes No Friable Non-Friable
 General Description: Wall base (covered) Size: 4"
 Matrix/Primary Color: Brown Texture/Pattern: Vinyl-Like Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: _____

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-AQH-11 Damaged: Yes No Friable Non-Friable
 General Description: Adhesive Size: N/A
 Matrix/Primary Color: Cream Texture/Pattern: Pliable Cover/Secondary Color: N/A
 Quantity of Material: 25 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-WAB-10

Inspector: Dane Thompson Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA D 10790
 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-SAT-12 Damaged: Yes No Friable Non-Friable
 General Description: Spray-Applied texture Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-GWB-13 Damaged: Yes No Friable Non-Friable
 General Description: Gypsum wallboard Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 300 Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with S-SAT-12

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: S-JTC-14 Material Code: Friable Non-Friable
 General Description: Joint Compound Damaged: Yes No Size: N/A
 Matrix/Primary Color: White Texture/Pattern: Chalky Cover/Secondary Color: N/A
 Quantity of Material: 30 Estimated By: Drawing Field Measure
 LF / EA Wall Other
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-GWB-13

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-USF-15 Damaged: Yes No Friable Non-Friable
 General Description: Vinyl Sheet Flooring Size: N/A
 Matrix/Primary Color: Brown Texture/Pattern: Smooth Cover/Secondary Color: white marbled
 Quantity of Material: 1200 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Gray Paper Backing

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-MA5-16 Damaged: Yes No Friable Non-Friable
 General Description: Mastic Visible Covered VSF Size: N/A
 Matrix/Primary Color: Yellow Texture/Pattern: Tacky Cover/Secondary Color: N/A
 Quantity of Material: 1200 SF / LF / EA Estimated By: Drawing Field Measure
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments: Associated with M-VSF-15

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-SLT-17 Damaged: Yes No Friable Non-Friable
 Visible Covered

General Description: Sealant Size: N/A
 Matrix/Primary Color: Brown Cover/Secondary Color: N/A
 Quantity of Material: 3 Estimated By: Drawing Field Measure
 Texture/Pattern: Friable

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

FM GROUP INC

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, AZ

Material Code: M-CON-18 Damaged: Yes No Friable Non-Friable
 Visible Covered Size: N/A

General Description: Concrete
 Matrix/Primary Color: Gray Texture/Pattern: Cementitious Cover/Secondary Color: N/A
 Quantity of Material: 250 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-BUR-19 Damaged: Yes No Friable Non-Friable
 General Description: Built-up Roofing (Rounded) Size: N/A

Matrix/Primary Color: Black Texture/Pattern: Asphaltic Cover/Secondary Color: Gray Mineral Cap
 Quantity of Material: 800 Estimated By: Drawing Field Measure Sampled Assumed

Homogeneous Material Location: Ceiling Floor Wall Other
 Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM

15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax



Project No.: 07-345 Project Name: AHERA-Compliance Asbestos Inspection Owner: Kyrene School District No. 28
 Building No.: Restroom Portable Address: 3375 West Galveston
 Campus Name: Kyrene del Sureno Chandler, Az

Material Code: M-MAS-20 Damaged: Yes No Friable Non-Friable
 General Description: Mastic (Penetrations + Flashings) Size: N/A
 Matrix/Primary Color: Black Texture/Pattern: BRITTLE Cover/Secondary Color: N/A
 Quantity of Material: 10 Estimated By: Drawing Field Measure Sampled Assumed
 Homogeneous Material Location: Ceiling Floor Wall Other

Manner of Sampling: Random Convenience N/A

Sample ID	Sample Location	Points of Origin	East/West Direction	North/South Direction	Height A.F.F.	Surface
A		Corner				F / W / C / O
B		Corner				F / W / C / O
C		Corner				F / W / C / O
D		Corner				F / W / C / O
E		Corner				F / W / C / O
F		Corner				F / W / C / O
G		Corner				F / W / C / O

Comments:

Inspector: Dane Thompson Inspector: Michael Richter
 AHERA Certificate No.: D 9953 State License: EPA AHERA Certificate No.: D 10790 State License: EPA
 Signature: [Signature] Date: 10/9/07 Signature: [Signature] Date: 10/9/07

Asbestos-Containing Material: No Yes Assumed

SUSPECT ASBESTOS-CONTAINING MATERIAL DESIGNATION AND SAMPLE RECORD FORM



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

APPENDIX B

Bulk-Material Sample Documents

- **Chain-of-Custody**
- **Laboratory Analysis**



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

chain of custody

Date: 10/10/07 Job: Kyrene Del Surano
 Project No: 07-345 Client: KSD
 Initials: Michael Richter Address: 3375 W Galveston
 Page: 1 of 2 Chandler, AZ

Test: PLM 10-15
 Rush: Normal: Extended:
 Stop at 1st Positive: UNO
 Read all samples:
 Call with results:
 Fax results:

MAIN BLDG

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-APL-01	Acoustical Ceiling Panel	A-C RA	S
M-APL-02	Acoustical Ceiling Panel	RA	
S-SAT-03	Spray-Applied Texture	RA	
M-GWB-04	Gypsum Wallboard	RA	
S-JTC-05	Joint Compound	RA	
M-CPT-08	Carpet		
M-MAS-09	Mastic		
M-WAB-11	Wallbase		
M-ADH-12	Adhesive		
M-SLT-15	Sealant		
S-SAT-18	Spray-Applied Texture	RA	
M-GWB-19	Gypsum Wallboard	RA	
S-JTC-20	Joint Compound	RA	
M-VCT-21	Vinyl Composition Tile		
M-MAS-22	Mastic		
S-SAT-23	Spray-Applied Texture	RA	
M-GWB-24	Gypsum Wallboard	RA	
S-JTC-25	Joint Compound	RA	
M-GWB-27	Gypsum Wallboard	RA	
S-JTC-28	Joint Compound	RA	
M-GWB-30	Gypsum Wallboard	RA	
S-JTC-31	Joint Compound	✓ RA	✓

**Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
MICHAEL RICHTER	10/11/07	K Johnson	GISU 10-11-07



15974 N. 77th Street
 Scottsdale, AZ 85260
 (602) 277-7877
 (602) 277-8288 fax

chain of custody

Date: 10/10/07
 Project No: 07-345
 Initials: Michael Richter
 Page: 2 of 2

Job: Kyrene Del Suren
 Client: KSD
 Address: 3375 W Galveston
Chandler, AZ

Test: PLM 10-15
 Rush: Normal: Extended:
 Stop at 1st Positive: UNO
 Read all samples:
 Call with results:
 Fax results:

Main BLDG

MATERIAL CODE	MATERIAL DESCRIPTION	MATERIAL SAMPLE NO.	LAYERS**
M-GWB-32	Gypsum Wallboard	A-C RA	S
S-JTC-33	Joint Compound	RA	
M-WAB-34	Wallbase		
M-ADH-35	Adhesive		
M-VCT-37	Vinyl Composition Tile		
M-MAS-38	Mastic		
M-BRK-39	Brick		
M-MRT-40	Mortar		
M-SLT-41	Sealant		
S-TOT-51	Traveled-ON Texture	RA	
M-GWB-52	Gypsum Wallboard	RA	
S-JTC-53	Joint Compound	RA	
M-WAB-54	Wallbase		
M-ADH-55	Adhesive		
M-APL-58	Acoustical Ceiling Panel	RA	
M-VCT-61	Vinyl Composition Tile		

**Sample Layers - M-MULTIPLE, S-SINGLE

RELINQUISHED BY:	DATE:	RECEIVED BY:	DATE:
Michael Richter	10/11/07	Kyrene Del Suren KSD	10-11-07

2.2.2
07.345



Polarized Light Microscope (PLM) Analysis for Asbestos

Job Number: 200708756

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 114 PLM **Rec:** 10/11/2007 **Method:** EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Del Sureno Main Bldg **PO Number:** 07-345
Report Date: 10/24/2007 **Date Analyzed:** 10/24/2007 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.

Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color	Apparent Layer Type *	Asbestos Results	
Sample # M-APL-01A Layer # 1 Tan	2007-08756- 1	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 Tan	2007-08756- 2	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 Tan	2007-08756- 3	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-02A Layer # 1 Tan	2007-08756- 4	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-02B Layer # 1 Tan	2007-08756- 5	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-02C Layer # 1 Tan	2007-08756- 6	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-03A Layer # 1 white	2007-08756- 7	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-03B Layer # 1 white	2007-08756- 8	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-SAT-03C Layer # 1 white	2007-08756- 9	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-04A Layer # 1 white	2007-08756- 10	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-04B Layer # 1 white	2007-08756- 11	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-04C Layer # 1 white	2007-08756- 12	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-05A Layer # 1 white	2007-08756- 13	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-05B Layer # 1 white	2007-08756- 14	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-05C Layer # 1 white	2007-08756- 15	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-CPT-08A Layer # 1 various	2007-08756- 16	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # M-CPT-08B Layer # 1 various	2007-08756- 17	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # M-CPT-08C Layer # 1 various	2007-08756- 18	Carpet <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-09A Layer # 1 Tan	2007-08756- 19	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-09B Layer # 1 Tan	2007-08756- 20	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-09C Layer # 1 Tan	2007-08756- 21	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-11A Layer # 1 Blue	2007-08756- 22	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-11B Layer # 1 Blue	2007-08756- 23	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-11C Layer # 1 Blue	2007-08756- 24	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ADH-12A Layer # 1 Tan	2007-08756- 25	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ADH-12B Layer # 1 Tan	2007-08756- 26	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ADH-12C Layer # 1 Tan	2007-08756- 27	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-SLT-15A Layer # 1 White	2007-08756- 28	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-SLT-15B Layer # 1 White	2007-08756- 29	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-SLT-15C Layer # 1 White	2007-08756- 30	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No

Sample #	S-SAT-18A	2007-08756- 31	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-18B	2007-08756- 32	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-18C	2007-08756- 33	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-19A	2007-08756- 34	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-19B	2007-08756- 35	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-19C	2007-08756- 36	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-20A	2007-08756- 37	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-20B	2007-08756- 38	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-20C	2007-08756- 39	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-VCT-21A	2007-08756- 40	Flooring	Positive Layer? No
	Layer # 1 off-white	floor tile	<i>no asbestos detected</i>	
Sample #	M-VCT-21B	2007-08756- 41	Flooring	Positive Layer? No
	Layer # 1 off-white	floor tile	<i>no asbestos detected</i>	
Sample #	M-VCT-21C	2007-08756- 42	Flooring	Positive Layer? No
	Layer # 1 off-white	floor tile	<i>no asbestos detected</i>	
Sample #	M-MAS-22A	2007-08756- 43	Adhesive/caulk	Positive Layer? No
	Layer # 1 Black	mastic	<i>no asbestos detected</i>	
Sample #	M-MAS-22B	2007-08756- 44	Adhesive/caulk	Positive Layer? No
	Layer # 1 Black	mastic	<i>no asbestos detected</i>	
Sample #	M-MAS-22C	2007-08756- 45	Adhesive/caulk	Positive Layer? No
	Layer # 1 Black	mastic	<i>no asbestos detected</i>	
Sample #	S-SAT-23A	2007-08756- 46	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-23B	2007-08756- 47	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-SAT-23C	2007-08756- 48	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-24A	2007-08756- 49	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-24B	2007-08756- 50	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-24C	2007-08756- 51	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-25A	2007-08756- 52	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-25B	2007-08756- 53	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-25C	2007-08756- 54	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-27A	2007-08756- 55	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-27B	2007-08756- 56	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-27C	2007-08756- 57	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-28A	2007-08756- 58	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-28B	2007-08756- 59	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-28C	2007-08756- 60	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-30A	2007-08756- 61	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-30B	2007-08756- 62	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	M-GWB-30C	2007-08756- 63	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	
Sample #	S-JTC-31A	2007-08756- 64	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-31B	2007-08756- 65	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	S-JTC-31C	2007-08756- 66	Wall System	Positive Layer? No
	Layer # 1 white	texture/joint compound	<i>no asbestos detected</i>	
Sample #	M-GWB-32A	2007-08756- 67	Wall System	Positive Layer? No
	Layer # 1 white	drywall core	<i>no asbestos detected</i>	

Sample # M-GWB-32B Layer # 1 white	drywall core	2007-08756- 68	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-32C Layer # 1 white	drywall core	2007-08756- 69	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-33A Layer # 1 white	texture/joint compound	2007-08756- 70	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-33B Layer # 1 white	texture/joint compound	2007-08756- 71	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-33C Layer # 1 white	texture/joint compound	2007-08756- 72	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-34A Layer # 1 Gray	base cove	2007-08756- 73	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-34B Layer # 1 Gray	base cove	2007-08756- 74	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-34C Layer # 1 Gray	base cove	2007-08756- 75	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ADH-35A Layer # 1 Tan	mastic	2007-08756- 76	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ADH-35B Layer # 1 Tan	mastic	2007-08756- 77	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-ADH-35C Layer # 1 Tan	mastic	2007-08756- 78	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-VCT-37A Layer # 1 off-white	floor tile	2007-08756- 79	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # M-VCT-37B Layer # 1 off-white	floor tile	2007-08756- 80	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # M-VCT-37C Layer # 1 off-white	floor tile	2007-08756- 81	Flooring <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-38A Layer # 1 Black	mastic	2007-08756- 82	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-38B Layer # 1 Black	mastic	2007-08756- 83	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MAS-38C Layer # 1 Black	mastic	2007-08756- 84	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-BRK-39A Layer # 1 Red	brick	2007-08756- 85	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # M-BRK-39B Layer # 1 Red	brick	2007-08756- 86	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # M-BRK-39C Layer # 1 Red	brick	2007-08756- 87	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MRT-40A Layer # 1 Brown	mortar	2007-08756- 88	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MRT-40B Layer # 1 Brown	mortar	2007-08756- 89	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # M-MRT-40C Layer # 1 Brown	mortar	2007-08756- 90	Cementitious <i>no asbestos detected</i>	Positive Layer? No
Sample # M-SLT-41A Layer # 1 Brown	caulk	2007-08756- 91	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-SLT-41B Layer # 1 Brown	caulk	2007-08756- 92	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # M-SLT-41C Layer # 1 Brown	caulk	2007-08756- 93	Adhesive/caulk <i>no asbestos detected</i>	Positive Layer? No
Sample # S-TOT-51A Layer # 1 white	texture/joint compound	2007-08756- 94	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-TOT-51B Layer # 1 white	texture/joint compound	2007-08756- 95	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-TOT-51C Layer # 1 white	texture/joint compound	2007-08756- 96	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-52A Layer # 1 white	drywall core	2007-08756- 97	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-52B Layer # 1 white	drywall core	2007-08756- 98	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-GWB-52C Layer # 1 white	drywall core	2007-08756- 99	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-53A Layer # 1 white	texture/joint compound	2007-08756- 100	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-53B Layer # 1 white	texture/joint compound	2007-08756- 101	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # S-JTC-53C Layer # 1 white	texture/joint compound	2007-08756- 102	Wall System <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-54A Layer # 1 Black	base cove	2007-08756- 103	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-WAB-54B Layer # 1 Black	base cove	2007-08756- 104	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No

Sample #	<u>M-WAB-54C</u>		2007-08756- 105	Miscellaneous	Positive Layer?	No
	Layer # 1	Black		<i>no asbestos detected</i>		
Sample #	<u>M-ADH-55A</u>	base cove	2007-08756- 106	Adhesive/caulk	Positive Layer?	No
	Layer # 1	Tan		<i>no asbestos detected</i>		
Sample #	<u>M-ADH-55B</u>	mastic	2007-08756- 107	Adhesive/caulk	Positive Layer?	No
	Layer # 1	Tan		<i>no asbestos detected</i>		
Sample #	<u>M-ADH-55C</u>	mastic	2007-08756- 108	Adhesive/caulk	Positive Layer?	No
	Layer # 1	Tan		<i>no asbestos detected</i>		
Sample #	<u>M-APL-58A</u>	acoustical tile	2007-08756- 109	Acoustic Tile	Positive Layer?	No
	Layer # 1	Off-white		<i>no asbestos detected</i>		
Sample #	<u>M-APL-58B</u>	acoustical tile	2007-08756- 110	Acoustic Tile	Positive Layer?	No
	Layer # 1	Off-white		<i>no asbestos detected</i>		
Sample #	<u>M-APL-58C</u>	acoustical tile	2007-08756- 111	Acoustic Tile	Positive Layer?	No
	Layer # 1	Off-white		<i>no asbestos detected</i>		
Sample #	<u>M-VCT-61A</u>	floor tile	2007-08756- 112	Flooring	Positive Layer?	No
	Layer # 1	Black		<i>no asbestos detected</i>		
Sample #	<u>M-VCT-61B</u>	floor tile	2007-08756- 113	Flooring	Positive Layer?	No
	Layer # 1	Green		<i>no asbestos detected</i>		
Sample #	<u>M-VCT-61C</u>	floor tile	2007-08756- 114	Flooring	Positive Layer?	No
	Layer # 1	Yellow		<i>no asbestos detected</i>		

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-APL-01A **Lab Number** 2007-08756- 1 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y								
2	cellulose fiber	W	F	N	N	H	+	U				
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2007-08756- 2 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y								
2	cellulose fiber	W	F	N	N	H	+	U				
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2007-08756- 3 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y								
2	cellulose fiber	W	F	N	N	H	+	U				
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-APL-02A Lab Number 2007-08756- 4 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-02B Lab Number 2007-08756- 5 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-02C Lab Number 2007-08756- 6 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample S-SAT-03A **Lab Number** 2007-08756- 7 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03B **Lab Number** 2007-08756- 8 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-03C **Lab Number** 2007-08756- 9 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-GWB-04A **Lab Number** 2007-08756- 10 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-04B **Lab Number** 2007-08756- 11 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-04C **Lab Number** 2007-08756- 12 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample S-JTC-05A **Lab Number** 2007-08756- 13 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05B **Lab Number** 2007-08756- 14 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-05C **Lab Number** 2007-08756- 15 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-CPT-08A **Lab Number** 2007-08756- 16 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-CPT-08B **Lab Number** 2007-08756- 17 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-CPT-08C **Lab Number** 2007-08756- 18 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Carpet **Fibrous Mat**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	carpet	100	various	1	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					synthetic fiber (extr)					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	synthetic fiber (extruded)	V	E	N	N	H	+	P					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-MAS-09A **Lab Number** 2007-08756- 19 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-09B **Lab Number** 2007-08756- 20 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-09C **Lab Number** 2007-08756- 21 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-WAB-11A **Lab Number** 2007-08756- 22 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cov	100	Blue	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-11B **Lab Number** 2007-08756- 23 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cov	100	Blue	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-11C **Lab Number** 2007-08756- 24 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cov	100	Blue	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-ADH-12A **Lab Number** 2007-08756- 25 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-12B **Lab Number** 2007-08756- 26 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-12C **Lab Number** 2007-08756- 27 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-SLT-15A **Lab Number** 2007-08756- 28 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sealant	100	White	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-SLT-15B **Lab Number** 2007-08756- 29 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sealant	100	White	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-SLT-15C **Lab Number** 2007-08756- 30 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	sealant	100	White	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample S-SAT-18A **Lab Number** 2007-08756- 31 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-18B **Lab Number** 2007-08756- 32 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-18C **Lab Number** 2007-08756- 33 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-GWB-19A **Lab Number** 2007-08756- 34 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-19B **Lab Number** 2007-08756- 35 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-19C **Lab Number** 2007-08756- 36 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					glass fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	CL	D	Y										
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample S-JTC-20A **Lab Number** 2007-08756-37 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-20B **Lab Number** 2007-08756-38 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-20C **Lab Number** 2007-08756-39 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-VCT-21A **Lab Number** 2007-08756- 40 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-21B **Lab Number** 2007-08756- 41 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-21C **Lab Number** 2007-08756- 42 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-MAS-22A **Lab Number** 2007-08756- 43 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Black	1	2-5%	-	-	-	-	-
Total %		100	Average %		2-5%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U					
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-22B **Lab Number** 2007-08756- 44 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Black	1	2-5%	-	-	-	-	-
Total %		100	Average %		2-5%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U					
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-22C **Lab Number** 2007-08756- 45 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Black	1	5-10%	-	-	-	-	-
Total %		100	Average %		5-10%	-	-	-	-	-

Fiber Identification: cellulose fiber

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U					
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample S-SAT-23A **Lab Number** 2007-08756- 46 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-23B **Lab Number** 2007-08756- 47 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-SAT-23C **Lab Number** 2007-08756- 48 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-GWB-24A **Lab Number** 2007-08756- 49 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-24B **Lab Number** 2007-08756- 50 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-24C **Lab Number** 2007-08756- 51 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: glass fiber

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y					glass fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample S-JTC-25A **Lab Number** 2007-08756- 52 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-25B **Lab Number** 2007-08756- 53 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-25C **Lab Number** 2007-08756- 54 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-GWB-27A **Lab Number** 2007-08756- 55 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: cellulose

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-GWB-27B **Lab Number** 2007-08756- 56 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: cellulose

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-GWB-27C **Lab Number** 2007-08756- 57 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: cellulose

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample S-JTC-28A **Lab Number** 2007-08756- 58 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-28B **Lab Number** 2007-08756- 59 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-28C **Lab Number** 2007-08756- 60 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-GWB-30A **Lab Number** 2007-08756- 61 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-30B **Lab Number** 2007-08756- 62 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-30C **Lab Number** 2007-08756- 63 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	cellulose	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample S-JTC-31A **Lab Number** 2007-08756- 64 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-31B **Lab Number** 2007-08756- 65 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-31C **Lab Number** 2007-08756- 66 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-GWB-32A Lab Number 2007-08756- 67 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: cellulose

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-GWB-32B Lab Number 2007-08756- 68 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-

Fiber Identification: cellulose glass fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-GWB-32C Lab Number 2007-08756- 69 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-

Fiber Identification: cellulose

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample S-JTC-33A Lab Number 2007-08756- 70 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-33B Lab Number 2007-08756- 71 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-33C Lab Number 2007-08756- 72 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-WAB-34A **Lab Number** 2007-08756- 73 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-34B **Lab Number** 2007-08756- 74 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-34C **Lab Number** 2007-08756- 75 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base covc	100	Gray	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-ADH-35A **Lab Number** 2007-08756- 76 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-35B **Lab Number** 2007-08756- 77 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-35C **Lab Number** 2007-08756- 78 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers										Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per		
1	none													
2														
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-VCT-37A **Lab Number** 2007-08756- 79 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-37B **Lab Number** 2007-08756- 80 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-37C **Lab Number** 2007-08756- 81 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	off-white	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-MAS-38A **Lab Number** 2007-08756- 82 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Black	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-38B **Lab Number** 2007-08756- 83 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Black	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-MAS-38C **Lab Number** 2007-08756- 84 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Black	1	<=1%	-	-	-	-	-
Total %		100	Average %		<=1%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-BRK-39A **Lab Number** 2007-08756- 85 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Cementitious Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	brick	100	Red	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-BRK-39B **Lab Number** 2007-08756- 86 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Cementitious Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	brick	100	Red	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-BRK-39C **Lab Number** 2007-08756- 87 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Cementitious Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	brick	100	Red	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-MRT-40A **Lab Number** 2007-08756- 88 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Cementitious Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mortar	100	Brown	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-MRT-40B **Lab Number** 2007-08756- 89 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Cementitious Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mortar	100	Brown	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-MRT-40C **Lab Number** 2007-08756- 90 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Cementitious Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, rock,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mortar	100	Brown	2	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-SLT-41A **Lab Number** 2007-08756- 91 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Brown	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-SLT-41B **Lab Number** 2007-08756- 92 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Brown	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-SLT-41C **Lab Number** 2007-08756- 93 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	caulk	100	Brown	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample S-TOT-51A Lab Number 2007-08756- 94 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-TOT-51B Lab Number 2007-08756- 95 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-TOT-51C Lab Number 2007-08756- 96 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/24/2007 An? OK Apparent Smp Type Wall System Non-fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-

Fiber Identification: none

Fibers								Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	none											
2												
3												
4												
5												
6												

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756 Kyrene Del Sureno Main Bldg

Sample M-GWB-52A **Lab Number** 2007-08756- 97 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-52B **Lab Number** 2007-08756- 98 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-GWB-52C **Lab Number** 2007-08756- 99 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	drywall core	100	white	3	<=1%	<=1%	-	-	-	-
Total %		100	Average %		<=1%	<=1%	-	-	-	-
Fiber Identification:					cellulose	glass fiber				

Fibers									Refractive Index Determinations				
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample S-JTC-53A **Lab Number** 2007-08756- 100 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-53B **Lab Number** 2007-08756- 101 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample S-JTC-53C **Lab Number** 2007-08756- 102 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Wall System Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	texture/joint compound	100	white	3	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-WAB-54A **Lab Number** 2007-08756- 103 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cov	100	Black	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-54B **Lab Number** 2007-08756- 104 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cov	100	Black	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-WAB-54C **Lab Number** 2007-08756- 105 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Non-fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	base cov	100	Black	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-ADH-55A **Lab Number** 2007-08756- 106 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-55B **Lab Number** 2007-08756- 107 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-ADH-55C **Lab Number** 2007-08756- 108 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Adhesive/caulk Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	mastic	100	Tan	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification: none										

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-APL-58A **Lab Number** 2007-08756- 109 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations					
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-58B **Lab Number** 2007-08756- 110 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations					
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-58C **Lab Number** 2007-08756- 111 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers								Refractive Index Determinations					
		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

PLM Analysis Details

Job Number: 200708756

Kyrene Del Sureno Main Bldg

Sample M-VCT-61A **Lab Number** 2007-08756- 112 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Black	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-VCT-61B **Lab Number** 2007-08756- 113 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Green	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.


Sample M-VCT-61C **Lab Number** 2007-08756- 114 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/24/2007 **An?** OK **Apparent Smp Type** Flooring Non-fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	floor tile	100	Yellow	1	n.d.	-	-	-	-	-
Total %		100	Average %		n.d.	-	-	-	-	-
Fiber Identification:					none					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per	
1	none												
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow;
 vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 24-Oct-07

Original Print Date: 24-Oct-07



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200708757

Client: FM GROUP INC
15974 N 77TH ST
SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 **PLM** **Rec:** 10/11/2007 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene Del Sureno Portable 50/51 **PO Number:** 07-345
Report Date: 10/22/2007 **Date Analyzed:** 10/22/2007 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708757

Kyrene Del Sureno Portable 50/51

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2007-08757- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2007-08757- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2007-08757- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-DST-16A	2007-08757- 4	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16B	2007-08757- 5	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16C	2007-08757- 6	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200708757

Kyrene Del Sureno Portable 50/51

Sample M-APL-01A Lab Number 2007-08757- 1 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B Lab Number 2007-08757- 2 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C Lab Number 2007-08757- 3 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-DST-16A **Lab Number** 2007-08757- 4 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16B **Lab Number** 2007-08757- 5 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16C **Lab Number** 2007-08757- 6 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Miscellaneous **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 22-Oct-07

Original Print Date: 22-Oct-07



Larry S. Pierce, Approved Accreditation Signatory



FAX Report - PLM Analysis of Asbestos in Bulk Sample

JobNumber: 200708757

Attention:

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 PLM Rec: 10/11/2007 Method: EPA 600/R-93/116 PLM analysis for asbestos in bulk smp
Client Job: Kyrene Del Sureno Portable 50/ PO Number: 07-345 Routing Number: -

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

Analysis Summary:

Sample Number	Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer Color Apparent Layer Type *	Asbestos Results		
Sample # M-APL-01A Layer # 1 Tan acoustical tile	2007-08757- 1	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01B Layer # 1 Tan acoustical tile	2007-08757- 2	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-APL-01C Layer # 1 Tan acoustical tile	2007-08757- 3	Acoustic Tile <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-16A Layer # 1 Off-white duct tape	2007-08757- 4	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-16B Layer # 1 Off-white duct tape	2007-08757- 5	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No
Sample # M-DST-16C Layer # 1 Off-white duct tape	2007-08757- 6	Miscellaneous <i>no asbestos detected</i>	Positive Layer? No

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Fr=Friability: 1=NESHAP non-friable category I; 2=NESHAP non-friable category II; 3=friable; 4=highly friable

Preliminary FAX Report - No Signature

22-Oct-07

Analyst: MICHAEL A. COOK

5025 S. 33rd Street Phoenix, Arizona 85040-2816 Phone: 602-276-6139 1-800-743-2687 FAX: 602-276-4558

DISCLAIMER:

This communication, along with any documents, files or attachments, is intended only for the use of the addressee and may contain legally privileged and confidential information. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of any information contained in or attached to this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately and destroy the original communication and its attachments without reading, printing or saving in any manner. This communication does not form any contractual obligation on behalf of the sender or, the sender's employer, or the employer's parent company, affiliates or subsidiaries.



2.2.2
07345

Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200708759

Client: FM GROUP INC
15974 N 77TH ST
SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 **PLM Rec:** 10/11/2007 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene Del Sureno-Portable 53/52 **PO Number:** 07-345
Report Date: 10/22/2007 **Date Analyzed:** 10/22/2007 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708759

Kyrene Del Sureno-Portable 53/52

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2007-08759- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2007-08759- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2007-08759- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-DST-16A	2007-08759- 4	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16B	2007-08759- 5	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16C	2007-08759- 6	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A Lab Number 2007-08759- 1 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B Lab Number 2007-08759- 2 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C Lab Number 2007-08759- 3 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Acoustic Tile Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	30-40%	20-30%	-	-	-	-
Total %		100	Average %		30-40%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2	glass fiber	CL	D	Y									
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-DST-16A Lab Number 2007-08759- 4 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Miscellaneous Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16B Lab Number 2007-08759- 5 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Miscellaneous Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16C Lab Number 2007-08759- 6 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By MAC 10/22/2007 An? OK Apparent Smp Type Miscellaneous Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various


Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 22-Oct-07

Original Print Date: 22-Oct-07



Larry S. Pierre, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200708758

Client: FM GROUP INC
15974 N 77TH ST
SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 **PLM Rec:** 10/11/2007 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene Del Sureno Portable 54/55 **PO Number:** 07-345
Report Date: 10/22/2007 **Date Analyzed:** 10/22/2007 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708758

Kyrene Del Sureno Portable 54/55

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2007-08758- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2007-08758- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2007-08758- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Tan		<i>no asbestos detected</i>	
Sample #	M-DST-16A	2007-08758- 4	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16B	2007-08758- 5	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16C	2007-08758- 6	Miscellaneous	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2007-08758- 1 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01B **Lab Number** 2007-08758- 2 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-APL-01C **Lab Number** 2007-08758- 3 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): perlite, binder,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Tan	3	20-30%	20-30%	-	-	-	-
Total %		100	Average %		20-30%	20-30%	-	-	-	-
Fiber Identification:					cellulose fiber	glass fiber				

Fibers										Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U						
2	glass fiber	CL	D	Y										
3														
4														
5														
6														

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using acid.

Sample M-DST-16A **Lab Number** 2007-08758- 4 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Miscellaneous Fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16B **Lab Number** 2007-08758- 5 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Miscellaneous Fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.


Sample M-DST-16C **Lab Number** 2007-08758- 6 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By MAC 10/22/2007 **An?** OK **Apparent Smp Type** Miscellaneous Fibrous Solid
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): binder, filler,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	Off-white	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable
 Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various
 Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends;
 D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper
 Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High
 Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining
 Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.
 RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: MICHAEL A. COOK

Printed: 22-Oct-07

Original Print Date: 22-Oct-07



Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200708760

Client: FM GROUP INC
15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000
Office Phone: (602) 277-7877
FAX: (602) 277-8288

Samples: 6 **PLM Rec:** 10/11/2007 **Method:** EPA 600/R-93/116 **PLM analysis for asbestos in bulk smp**
Client Job: Kyrene Del Sureno-Portable 57/56 **PO Number:** 07-345
Report Date: 10/24/2007 **Date Analyzed:** 10/24/2007 **Routing Number:** -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of <=1 % asbestos as "negative" and >1 % asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain <= 1% asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are <= 1%. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but <= 1% as "borderline negative", and results where asbestos was >1 % but <= 2% as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as <=1%. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708760

Kyrene Del Sureno-Portable 57/56

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2007-08760- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2007-08760- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2007-08760- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16A	2007-08760- 4	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	
Sample #	M-DST-16B	2007-08760- 5	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	
Sample #	M-DST-16C	2007-08760- 6	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2007-08760- 1 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	20-30%	10-20%	-	-	-	-
Total %		100	Average %		20-30%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01B **Lab Number** 2007-08760- 2 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	20-30%	10-20%	-	-	-	-
Total %		100	Average %		20-30%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01C **Lab Number** 2007-08760- 3 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	20-30%	10-20%	-	-	-	-
Total %		100	Average %		20-30%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	CL	D	Y										
2	W	F	N	N	H	+	U						
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708760

Kyrene Del Sureno-Portable 57/56

Sample M-DST-16A Lab Number 2007-08760- 4 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By DMS 10/24/2007 An? OK Apparent Smp Type TSI Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-16B Lab Number 2007-08760- 5 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By DMS 10/24/2007 An? OK Apparent Smp Type TSI Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Sample M-DST-16C Lab Number 2007-08760- 6 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By DMS 10/24/2007 An? OK Apparent Smp Type TSI Fibrous Solid
 Homogeneous Yes # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): powder, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: DAVID M. SCHALLER

Printed: 24-Oct-07

Original Print Date: 24-Oct-07

Larry S. Pierce, Approved Accreditation Signatory



Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200708761

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 6 PLM **Rec:** 10/11/2007 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Del Sureno-Portable 58/59

PO Number: 07-345

Report Date: 10/24/2007

Date Analyzed: 10/24/2007

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services. Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708761 Kyrene Del Sureno-Portable 58/59

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2007-08761- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2007-08761- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2007-08761- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16A	2007-08761- 4	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	
Sample #	M-DST-16B	2007-08761- 5	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	
Sample #	M-DST-16C	2007-08761- 6	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

PLM Analysis Details

Job Number: 200708761

Kyrene Del Sureno-Portable 58/59

Sample M-APL-01A **Lab Number** 2007-08761- 1 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01B **Lab Number** 2007-08761- 2 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01C **Lab Number** 2007-08761- 3 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers		Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Refractive Index Determinations				
									Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-DST-16A **Lab Number** 2007-08761- 4 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** TSI **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16B **Lab Number** 2007-08761- 5 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** TSI **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Sample M-DST-16C **Lab Number** 2007-08761- 6 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** TSI **Fibrous Solid**
Homogeneous Yes **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 3
Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	30-40%	-	-	-	-	-
Total %		100	Average %		30-40%	-	-	-	-	-
Fiber Identification:					cellulose fiber					

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	W	F	N	N	H	+	U	cellulose fiber					
2													
3													
4													
5													
6													

Sample Analytical Note
 Procedure: tweased apart using forceps. Procedure: dissolution of matrix using solvent.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber

Analyst: DAVID M. SCHALLER

Printed: 24-Oct-07

Original Print Date: 24-Oct-07

Larry S. Pierce, Approved Accreditation Signatory



2.2.2
07.345

Polarized Light Microscope (PLM) Analysis for Asbestos

JobNumber: 200708762

Client: FM GROUP INC

15974 N 77TH ST

SCOTTSDALE, AZ 85260-0000

Office Phone: (602) 277-7877

FAX: (602) 277-8288

Samples: 6 PLM **Rec:** 10/11/2007 **Method:** EPA 600/R-93/116

PLM analysis for asbestos in bulk smp

Client Job: Kyrene Del Sureno-Portable 61/60

PO Number: 07-345

Report Date: 10/24/2007

Date Analyzed: 10/24/2007

Routing Number: -

Method and Analysis Information: Fiberquant Internal SOP: PLMn

Each bulk sample is first dissected under a 7-30x magnification stereo-microscope. This examination is used to determine the general type of sample, how many and what type of layers it has, and initial estimates of fiber types and quantities. Second, liquid media mounts are made of each layer - such mounts may be of selected fibers (used solely for identification purposes) or may be representative of the layer as a whole (used for quantitation purposes). The mounts may be made in a synthetic Canadian balsam, one of several solvents, or in refractive index oils (media of known refractive index). Generally, a variety of different mounts are made: some optimized for fiber visibility, some optimized for fiber identification, and some optimized for fiber quantitation. The mounted slides are then examined at 50-400x magnification on a Nikon Labphot-pol microscope. Optical characteristics are used to identify each observed fiber type; the optical data are contained for each sample on its detail analysis sheet, attached.

Current EPA, NESHAP and OSHA regulations designate a result of $\leq 1\%$ asbestos as "negative" and $> 1\%$ asbestos as "positive". Samples containing layers that have been determined to be "positive" may have to be handled differently during a renovation or demolition than samples whose layers have been determined to be "negative."

The method of fiber analysis and identification is the EPA Method 600/R-93/116. The method of fiber quantitation is an estimation technique in which the analysts quantitation is routinely calibrated by reference quantitation standards, and which has been shown to be equivalent in precision and accuracy to point counting. Friability is estimated for the purposes of deciding when to point count. Friabilities determined in the field take precedence over those determined in the laboratory. Those sample layers which are friable and estimated by the analyst to contain $\leq 1\%$ asbestos are point counted using 400 points. Such point counting is required by NESHAP (National Emission Standards for Hazardous Air Pollutants, Nov. 1990) in order to rely on analytical results that are $\leq 1\%$. The coefficient of variation for the estimation quantitation technique is 100% in the range 0-5%. This means that PLM analysis is not capable of conclusively determining whether a layer containing close to 1% asbestos is actually "positive" or "negative". For this reason, Fiberquant refers to results where asbestos was detected but $\leq 1\%$ as "borderline negative", and results where asbestos was $> 1\%$ but $\leq 2\%$ as "borderline positive" to indicate the uncertainty in assigning a "positive" or "negative" label. In the sample summary, "ND" means that no asbestos was detected during the analysis. A "Tr" or "Trace" of asbestos reported is defined for our purposes as the detection of several asbestos fibers during the analysis; this level would be right at the limit of detection for the method. Trace is only reported on the analysis detail - in the summary a trace would be reported as $\leq 1\%$. The limit of detection (the smallest % of asbestos that can be detected) varies greatly depending on the matrix in which the asbestos is found. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 1% stated in the method. During the analysis, the analyst, for Fiberquant identification purposes only, determines the "apparent sample type" and "apparent layer types." It must be emphasized that these types are only what is apparent. Often, different materials appear similar or identical after sampling, so the analyst may assign a type other than what was sampled.

Floor tiles present a special problem for PLM asbestos analysis. Floor tile can contain chrysotile fibers so thin that they cannot be resolved by optical methods. In such a case, we may observe a percentage of asbestos which is lower than the actual percentage, or not observe asbestos at all when some is present. For this reason, floor tiles reported as negative should be confirmed to be negative using transmission electron microscope (TEM) analysis. Likewise, vermiculite insulation materials containing traces of asbestiform asbestos present a problem for routine PLM analysis - the amphiboles are sometimes present in trace amounts inhomogeneously distributed. We recommend a hydro-separation technique for such samples.

Vermiculite-containing samples may contain trace amounts of asbestiform amphibole that may or may not be detected during routine PLM analysis. For this reason, loose vermiculite samples reported as negative should be confirmed to contain no amphibole using hydroseparation techniques.

The samples were analyzed under the following ongoing quality assurance program: Blank samples are routinely analyzed to maintain contamination-free materials. Each analyst has at least a bachelor's degree in physical science, and has also completed extensive training specific to asbestos analysis for 1-3 months before being allowed to analyze client samples. Qualitative reference samples are routinely analyzed to assure that analysts can identify asbestos and asbestos-look-alike fibers. Quantitative reference samples are routinely analyzed to calibrate and characterize the estimation procedure. Microscope alignment is checked each day. Refractive index oils are calibrated at least quarterly. At least 10% of client samples are re-analyzed from scratch by a different analyst than the original, and any discrepancies are resolved for the sample and similar sample types before the results are reported. All quality checks performed for these samples were in control except as detailed in the "Analytical Notes" below. All analysts participate in interlab round robins and proficiency testing to assure competence. Fiberquant is accredited by NVLAP (#101031) for the analysis of bulk samples for asbestos using PLM. Accreditation does not imply endorsement by the EPA, any other United States governmental agency or any private agency or association. Each lab analysis refers only to the sample tested, and may not, due to the sampling process, be

representative of the material sampled. This report may not be reproduced except in full, without the approval of Fiberquant Analytical Services.
 Some results may have been calculated using client supplied data, such as volume or area sampled, for which Fiberquant assumes no liability for accuracy.

Job Analysis Notes:

Single layer sample and "Analyze Until Positive Found" criteria were followed where requested by the client on the chain of custody.

PLM Analysis Summary:

Job Number: 200708762

Kyrene Del Sureno-Portable 61/60

Sample Number		Lab Number	Apparent Sample Type *	Positive Layer Yes or No
Layer	Color	Apparent Layer Type *	Asbestos Results	
Sample #	M-APL-01A	2007-08762- 1	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01B	2007-08762- 2	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-APL-01C	2007-08762- 3	Acoustic Tile	Positive Layer? No
Layer # 1	Off-white		<i>no asbestos detected</i>	
Sample #	M-DST-16A	2007-08762- 4	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	
Sample #	M-DST-16B	2007-08762- 5	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	
Sample #	M-DST-16C	2007-08762- 6	TSI	Positive Layer? No
Layer # 1	White		<i>no asbestos detected</i>	

* Apparent Sample Types and Apparent Layer Types are as they appeared to the analyst. Since many types of materials appear similar after sampling damage, the apparent type of material may not be the actual type of material.

Sample M-APL-01A **Lab Number** 2007-08762- 1 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 4
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01B **Lab Number** 2007-08762- 2 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 4
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

Sample M-APL-01C **Lab Number** 2007-08762- 3 **Sampled:** 10/10/2007 **Condition:** acceptable
Analyzed By DMS 10/24/2007 **An?** OK **Apparent Smp Type** Acoustic Tile **Fibrous Solid**
Homogeneous No **# Layers** 1 **Pos Layer?** No **# Sub-Samples** 4
Non-Fibrous Components (in approx. decreasing order): filler, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	acoustical tile	100	Off-white	3	10-20%	10-20%	-	-	-	-
Total %		100	Average %		10-20%	10-20%	-	-	-	-
Fiber Identification:					glass fiber	cellulose fiber				

Fibers									Refractive Index Determinations				
#	Layer Type	Color	Mrph	Iso	Pleo	Bi	Elg	Ext	Oil	Col Par	Col Per	RI Par	RI Per
1	glass fiber	CL	D	Y									
2	cellulose fiber	W	F	N	N	H	+	U					
3													
4													
5													
6													

Sample Analytical Note
 Procedure: teased apart using forceps. Procedure: dissolution of matrix using dilute HCl acid.

PLM Analysis Details

Job Number: 200708762

Kyrene Del Sureno-Portable 61/60

Sample M-DST-16A Lab Number 2007-08762- 4 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By DMS 10/24/2007 An? OK Apparent Smp Type TSI Fibrous Solid
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-

Fiber Identification:

cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-DST-16B Lab Number 2007-08762- 5 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By DMS 10/24/2007 An? OK Apparent Smp Type TSI Fibrous Solid
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	40-50%	-	-	-	-	-
Total %		100	Average %		40-50%	-	-	-	-	-

Fiber Identification:

cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Sample M-DST-16C Lab Number 2007-08762- 6 Sampled: 10/10/2007 Condition: acceptable
 Analyzed By DMS 10/24/2007 An? OK Apparent Smp Type TSI Fibrous Solid
 Homogeneous No # Layers 1 Pos Layer? No # Sub-Samples 3
 Non-Fibrous Components (in approx. decreasing order): polymer, ,

Layers					Percents of Each Fiber					
#	Layer Type	%	Color	Friability	Fib 1	Fib 2	Fib 3	Fib 4	Fib 5	Fib 6
1	duct tape	100	White	3	50-60%	-	-	-	-	-
Total %		100	Average %		50-60%	-	-	-	-	-

Fiber Identification:

cellulose fiber

Fibers									Refractive Index Determinations				
#	Color	Mrph	Iso	Pleo	Bi	Elg	Ext		Oil	Col Par	Col Per	RI Par	RI Per
1	cellulose fiber	W	F	N	N	H	+	U					
2													
3													
4													
5													
6													

Sample Analytical Note

Procedure: tweased apart using forceps.

Fr=Friability: 1=very non-friable; 2= non-friable; 3=friable; 4=highly friable

Colors: B=black;BL=blue;BR=brown;CL=clear;G=Green;GY=gray;OR=orange;OW=off-white;PN=pink;PU=purple;R=red;TN=tan;W=white;Y=yellow;V=various

Fiber Morphology: A=fine fibers/bundles, white, sinewy, flexible; B=fine fibers/bundles, w-br, straight, broomed ends; C=fine fibers/bundles, blue, straight, broomed ends; D=fine to coarse fibers, CL-B, brittle; E=coarse fibers,CL or dyed, striated; F=coarse fibers or splinters, W-BR, ribbon-like; G=lath-like or shards, low aspect ratio, may taper

Iso=Isotropism - may be yes or no; Pleo=pleochroism - may be yes or no; Bi=birefringence - may be None, Low, Medium or High

Elg=sign of elongation - may be + or -; Ext=extinction - may be Parallel, Oblique, None or Undulating; Oil=medium used to for dispersion staining

Col Par=dispersion staining colors parallel to the fiber (fiber/halo): b/w=black/white; dg/py=dark gray/pale yellow; vg/y=violet gray/yellow; db/ly=dark blue/lemon yellow; vb/g= vivid blue/gold; sb/o=sky blue/orange; pb/r=pale blue/red; gb/dr=gray blue/dark red; w/b=white/black. Col Perp=same only perpendicular to fiber.

RI Par=refractive index parallel to fiber; RI Perp=refractive index perpendicular to fiber



Analyst: DAVID M. SCHALLER

Printed: 24-Oct-07

Original Print Date: 24-Oct-07



Larry S. Pierce, Approved Accreditation Signatory

APPENDIX C

Building Inspectors' Signature Sheet

BUILDING INSPECTOR'S SIGNATURE SHEET

Report of Findings
Comprehensive AHERA Asbestos Inspection
Kyrene Del Sureno Elementary School
Kyrene School District No. 28

FM Project 07-345

The individual(s) whose signature(s) is/are shown below is/are EPA Accredited Building Inspector(s) who participated in one or more of the following activities:


- A. Visual Inspection of Facilities
- B. Identification of Homogenous Areas of Asbestos-Containing Materials
- C. Development of Sampling Plan and Protocols
- D. Bulk Sampling Activities/Material Identifications
- E. Assessing ACBM/ACM
- F. Preparing Report of Findings

<u>INSPECTOR</u>	<u>ACTIVITIES</u>	<u>DATES</u>
Paul Anger Printed Name D 9200 Accreditation No. Signature	<u>FR</u> Initials EPA State	<u>F</u> <u>11/07/07</u>
Michael Richter Printed Name D 10790 Accreditation No. Signature	<u>MR</u> Initials EPA State	<u>A, B, D, E</u> <u>10/08/07 – 10/12/07</u>
Cliff Rolle Printed Name D 10203 Accreditation No. Signature	<u>CR</u> Initials EPA State	<u>A, B, C, D, E, F</u> <u>10/08/07 – 11/0707</u>
Dane Thompson Printed Name D 9953 Accreditation No. Signature	<u>DT</u> Initials EPA State	<u>A, B, D, E</u> <u>10/08/07 – 10/12/07</u>

APPENDIX D

Personnel and Laboratory Accreditations

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**HERA Refresher
Building Inspector**

January 5, 2007

and successfully passed the competency exam

Date of Examination: January 5, 2007

Date of Expiration: January 5, 2008

Director

Approved Instructor

THE ASBESTOS INSTITUTE

8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE

Certifies that

Michael Allen Richter

has attended the EPA approved course

AHERA

Building Inspector

September 10-12, 2007


and successfully passed the competency exam.

Date of Examination: **September 12, 2007**

Date of Expiration: **September 12, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

Asbestos Refresher
Building Inspector

June 1, 2007

and successfully passed the competency exam.

Date of Examination: June 1, 2007

Date of Expiration: June 1, 2008

Director

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHERA Refresher
Building Inspector**

May 4, 2007


and successfully passed the competency exam.

Date of Examination: **May 4, 2007**

Date of Expiration: **May 4, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:1999

NVLAP LAB CODE: 101031-0


Fiberquant, Inc.
Phoenix, AZ

is recognized by the National Voluntary Laboratory Accreditation Program for conformance with criteria set forth in
NIST Handbook 150:2001 and all requirements of ISO/IEC 17025:1999.
Accreditation is granted for specific services, listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS

2007-07-01 through 2008-06-30

Effective dates



Dolly S. Bruce

For the National Institute of Standards and Technology

1.0 SURVEY RESULTS AND RECOMMENDATIONS

1.1 Summary

At the authorization of Kyrene School District No. 28 (KSD), FM GROUP INC (FM), has conducted a Comprehensive Asbestos Hazard Emergency Response Act (AHERA)-Compliant Asbestos Inspection for the eight buildings comprising the Kyrene Del Sureno Elementary School (KDSES) campus. This inspection was intended to provide information regarding the presence, location and condition of identified Asbestos-Containing Building Materials (ACBM) at the subject facility.

The field portion of the inspection was performed at the subject facility during the period October 8, 2007 through October 12, 2007. A total of 150 bulk-material samples were collected from 256 suspect ACBM located within the facility. Sampling was conducted in general accordance with the protocols set forth in the Environmental Protection Agency (EPA) AHERA Regulation 40 CFR 763.86. Samples were delivered to Fiberquant Analytical Services (FAS) for analysis by the Polarized Light Microscopy (PLM) methodology.

Two hundred and six building materials within the inspected facility have been assumed to be asbestos-containing. The identified ACBM were physically assessed to be non-friable and in good condition.

1.2 Identified Asbestos Containing Building Material

The identified ACBM within the eight buildings at KDSES are presented in tabular form (Table C) in Section 1.3. These tables are organized to show material code, general material description, material locations, laboratory analysis, friability and material quantities. Additionally, ACBM location plans that graphically identify the known extent of these materials by floor plan locations are presented in Section 1.4.

1.3 Asbestos-Containing Building Materials

(Table "C" has been moved to Section 6 of the Management Plan.)

1.4 ACBM/Location Plans

(Drawings have been moved to Section 6 of the Management Plan.)

1.5 Critical Situations

Critical situations are those areas in which the condition of existing ACBM are such as they represent an immediate danger to human health and the environment. **There were NO critical situations observed in the eight buildings at KDSES during this inspection.**

1.6 Friable Asbestos-Containing Building Materials

A friable material is one that when dry can be crumbled, pulverized, or reduced to powder by hand pressure. **There were NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation identified in the eight buildings at KDSES during this inspection.**

1.7 Material Assessments

Due to the fact that **NO friable Asbestos-Containing Surfacing or Miscellaneous Building Materials, or Asbestos-Containing Thermal System Insulation** was identified in the eight buildings at KDSES, **NO** formal assessments are included in this report.

1.8 Recommendations

There are ACBM that have the potential to become damaged during future Operations and Maintenance (O&M) and renovation activities. FM, therefore, recommends that a Management Plan following EPA and Occupational Safety and Health Administration (OSHA) guidelines be developed to address the in-place management of the identified ACBM. In accordance with EPA regulations, a Management Plan must be developed by an EPA Accredited Management Planner.

1.9 Qualifications of Report

FM has endeavored to investigate the existing conditions within the subject facility using that degree of care and skill ordinarily exercised under similar circumstances by asbestos consultants practicing in this, or similar localities. The information contained in this Report is relevant to the dates of FM's site work, and should not be relied on to represent conditions at a substantially later date.

This Report has been prepared on behalf of and exclusively for the use of KSD. This Report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party or be used or relied upon by any other party, in whole or in part, without FM's prior written consent.

2.0 PROJECT INFORMATION

2.1 Background

KSD intends to determine if there are any ACBM associated with the eight buildings at the KDSES campus. Based on the presumed age of the subject facility, it is likely that ACBM's were included in its construction. In compliance with EPA requirements, specifically its AHERA mandated inspections (40 CFR 763.85), KSD has contracted FM to perform a Comprehensive AHERA Compliant-Asbestos Inspection of the eight buildings at the subject facility.

FM was formally engaged by KSD through the acceptance of FM Proposal P6-349, dated June 29, 2006, as evidenced by the issuance of KSD Purchase Order No. 800475, dated July 17, 2007. The project was coordinated for KSD by Mr. Giacomo Musella, Facilities Supervisor.

The subject facility is located at 3375 West Galveston Street, in Chandler, Arizona and consists of eight buildings. The subject facility was occupied and operational at the time of the inspection with access provided by KSD personnel. This inspection was comprehensive by design, including interior and exterior building components and exterior mechanical systems associated with the eight buildings.

At the request of KSD, select identified suspect ACM were sampled, and remaining suspect materials were assumed to be asbestos-containing. No previous asbestos inspections were available for review.

The inspection was performed during the period October 8, 2007 through October 12, 2007, by Michael Richter and Dane Thompson, both of whom are EPA accredited Building Inspectors. Bulk-material samples were delivered to FAS for analysis by the PLM methodology. FAS is accredited under the American Industrial Hygiene Association's (AIHA) National Institute of Standards and Technology (NIST) National Voluntary Laboratory Accreditation Program (NVLAP).

2.2 Description of Construction

2.2.1 Main Building

The construction date of the Main Building is unknown. The construction appears to be consistent and uniform throughout.

The building is built with a slab on-grade foundation. Perimeter and interior load bearing walls are of concrete masonry systems and wood or metal-framed construction, and support wooden and metal truss and deck systems finished with asphalt prepared roofing systems.

Floor finishes observed include: carpet, ceramic mosaic tile, unfinished concrete and vinyl composition tile.

Original walls are concrete masonry systems and wood or metal-framed, gypsum wallboard systems with textured, painted finishes, glazed wall tile, fiberglass reinforced paneling, stucco or tackable wall panels. Restroom walls are finished with gypsum wallboard systems with textured, painted finishes and glazed wall tiles. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes and suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the building, corridors and miscellaneous interior rooms.

Mechanical equipment for the building consists of ground and roof-mounted mechanical units. The ductwork distribution systems run above the gypsum wallboard and suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.2 Portables 50/51, 52/53, 54/55, 56/57, 58/59 and 60/61

The construction date of Portables 50/51, 52/53, 54/55, 56/57, 58/59 and 60/61 is unknown. The construction appears to be consistent and uniform throughout each Portable.

The buildings are built of wood or metal-framed foundations and are believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: carpet and vinyl composition tile.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal) or tackable wall panels. Original ceilings are wood or metal-framed and support suspended ceiling systems.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the buildings consists of roof-mounted air handler units. The ductwork distribution systems run above the suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.2.3 Restroom Portable

The construction date of the Restroom Portable is unknown. The construction appears to be consistent and uniform throughout each Portable.

The building is built of wood or metal-framed foundations and is believed to be supported by masonry piers. Perimeter and interior load bearing walls are of wood or metal-framed construction and support wooden truss and deck systems finished with metal roofing panels.

Floor finishes observed include: vinyl composition tile and vinyl sheet flooring.

Original walls are wood or metal framed, gypsum wallboard systems with textured, painted finishes, siding (metal). Restroom walls finishes include gypsum wallboard systems with textured, painted finishes. Original ceilings are wood or metal-framed and support gypsum wallboard systems with textured, painted finishes.

Fire doors were observed to be associated with exterior entrances into the buildings.

Mechanical equipment for the building consists of roof-mounted air handler units. The ductwork distribution systems run above the gypsum wallboard or suspended ceiling systems and are routed into the individual rooms through ceiling or wall-mounted supply registers.

2.3 AHERA Inspection Procedures and Protocols

2.3.1 Inspection Procedures and Protocols

The EPA's AHERA inspection procedures and sampling protocols as called-out in the AHERA Regulations (40 CFR Part 763) requires that all Asbestos-Containing Materials (ACM) utilized within the structure of a regulated "school" building which are called ACBM:

- be identified and located
- be classified as an assumed ACBM or,
- be sampled and analyzed to prove they are NOT ACBM
- be assessed for;
 - ◊ natural friability and,
 - ◊ physical condition and,
 - ◊ if damaged or thermal systems insulation;
 - * be identified for an immediate response action or,
 - * be identified for possible future disturbance and
 - * have preventative measures to reduce potential damage identified.
- have all the forgoing activities conducted and recorded in such a manner as to be able to track;
 - ◊ date accomplished and,
 - ◊ identification and qualification of individuals conducting each activity.

2.3.2 FM GROUP INC Inspection SOP

FM's inspection procedures and protocols have been developed into a logical step by step process designated to accomplish both EPA's AHERA and OSHA's mandates. During inspections, FM will always endeavor to identify all ACM in a structure, whether ACBM or not, so as to limit the possibilities of accidental exposure to contractors or employees during future maintenance or remodeling activities.

2.4 Visual Inspection

A visual inspection of the eight buildings was conducted to locate and identify Homogeneous Areas (HA) of suspect ACBM. A HA is defined as an area in which the suspect material appears to be uniform in texture, color, and wear and believed to have been applied during the same general time period. All materials excluding wood; glass; metal; fibrous glass, glass foam and rubber thermal insulation were considered suspect.

2.5 Physical Assessments

A physical assessment of each identified HA of suspect ACBM was conducted to determine what, if any, damage the area has sustained and to determine whether the material should be classified as either friable or non-friable.

The EPA defines a friable material to be one which, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Based on this definition of friability, FM ascertained if a material was friable by physically touching each material surface.

At the time of this inspection, **FIFTEEN** friable suspect ACBM (acoustical ceiling panels and duct seam tape) were observed. Since **NONE** of these materials were analytically identified or assumed to contain asbestos, **NO** formal assessments are included in this report.

2.6 Sample Collection

Convenience sampling was performed on select identified suspect ACBM. Destructive sampling activities to access materials within ceiling, floor or wall systems were not utilized. Inspection personnel performing sampling activities utilized proper personnel protection. Additionally, inspection procedures included the use of engineering controls to minimize the release of airborne fibers during sample collection.

Based on FM's sampling strategy, the following number of bulk-material samples were collected from observed suspect ACBM.

Building	Suspect ACBM	Samples Collected
Main	77 (39 Assumed)	114
Portable 50/51	26 (24 Assumed)	6
Portable 52/53	27 (25 Assumed)	6
Portable 54/55	26 (24 Assumed)	6
Portable 56/57	27 (25 Assumed)	6
Portable 58/59	26 (24 Assumed)	6
Portable 60/61	27 (25 Assumed)	6
Restroom Portable	20 (20 Assumed)	0
TOTAL	256	150

2.7 Bulk-Material Sample Analysis

Upon completion of the on-site portion of the work, bulk-material samples accompanied by a chain-of-custody form were delivered to FAS for analysis. Samples were analyzed using PLM coupled with dispersion staining as detailed in the EPA's "Interim Method for the Determination of Asbestos Material Insulation Samples" (EPA-66/M4-82-020, December 1982).

PLM is the EPA recommended method for bulk sample analysis and utilizes the unique optical and crystallographic properties of the various constituents of the sample for material identification purposes. These properties, refractive indices, birefringence, sign of elongation, and extinction angle, are characteristically unique to each asbestos form and were used to identify asbestos types present in the samples. Under existing EPA guidelines, the identification of asbestos-form minerals in a single material bulk sample is sufficient to classify that material as an ACM. On the other hand, a minimum of three samples must be identified as not containing asbestos-form minerals to classify that material as non-ACM. All samples of a specific suspect ACM were analyzed until the first sample containing an asbestos-form mineral was found.

END OF REPORT

SECTION 3

DESIGNATED PERSON IDENTIFICATION

AHERA Designated Person
796.93(e)(4)

Owner: KYRENE SCHOOL DISTRICT NO. 28

Address: 8700 SOUTH KYRENE ROAD
TEMPE, ARIZONA 85284-2197

Property: KYRENE DEL SURENO ELEMENTARY SCHOOL

Address: 3375 WEST GALVESTON STREET
CHANDLER, ARIZONA 85226

LEA Designated Person

Print Name: Giacomo Musella, Facilities Supervisor

Address: 8700 South Kyrene Road
Tempe, Arizona 85284-2197

Phone: 480.783-4200

Training Course Name: AHERA Building Inspector

Dates of Training: August 7-9, 2006 **Hours of Training:** 24

Training Course Name: AHERA Management Planner

Dates of Training: August 10-11, 2006 **Hours of Training:** 16

Training Course Name: _____

Dates of Training: _____ **Hours of Training:** _____

Signature


Date

D 10910

THE ASBESTOS INSTITUTE

Certifies that
Giacomo Jack Musella

has attended the EPA approved course
**AHERA Refresher
Building Inspector
October 5, 2007**
and successfully passed the competency exam.




Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE
8102 North 23rd Avenue
Suite A
Phoenix, AZ 85021-4962
602-864-6564

This training meets all requirements for asbestos accreditation under TSCA Title II.

D 10936

THE ASBESTOS INSTITUTE


Certifies that
Giacomo Jack Musella

has attended the EPA approved course
**AHERA Refresher
Management Planner
October 5, 2007**
and successfully passed the competency exam.

COPY

Date of Examination: **October 5, 2007**

Date of Expiration: **October 5, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE
8102 North 23rd Avenue
Suite A
Phoenix, AZ 85021-4962
602-864-6564

This training meets all requirements for asbestos accreditation under TSCA Title II.

SECTION 4

RESPONSE ACTION(S)

THERE ARE NO RESPONSE ACTIONS REQUIRED AT THIS FACILITY.

SECTION 5

ACCREDITATION STATEMENTS

Assurance of Accreditation
Under this Management Plan
763.93(e)(7)

Inspector(s):

Name: MICHAEL RICHTER
State of Accreditation or EPA: EPA
Accreditation Date(s): SEPTEMBER 12, 2008
Accreditation Number(s): D 10790

Name: CLIFF ROLLE
State of Accreditation or EPA: EPA
Accreditation Date(s): JUNE 1, 2008
Accreditation Number(s): D10203

Name: DANE THOMPSON
State of Accreditation or EPA: EPA
Accreditation Date(s): MAY 4, 2008
Accreditation Number(s): D 9953

Management Planner:

Name: PAUL ANGER
State of Accreditation or EPA: EPA
Accreditation Date(s): JANUARY 5, 2008
Accreditation Number(s): D 9213

Any Project Designer, Contractor/Supervisor or Worker who performs work on response actions under this Management Plan shall be accredited by either an EPA approved state contractor accreditation plan or an EPA approved course under Section 206(b) to Title II of the Toxic Substance Control Act.

THE ASBESTOS INSTITUTE

Certifies that

Michael Allen Richter

has attended the EPA approved course

AHERA

Building Inspector

September 10-12, 2007


and successfully passed the competency exam.

Date of Examination: **September 12, 2007**

Date of Expiration: **September 12, 2008**



Director



Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

AHJERA Refresher
Building Inspector

June 1, 2007

and successfully passed the competency exam

Date of Examination: June 1, 2007

Date of Expiration: June 1, 2008

Director

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHJERA Refresher
Building Inspector**

May 4, 2007

and successfully passed the competency exam

Date of Examination: **May 4, 2007**

Date of Expiration: **May 4, 2008**

Director

Approved Instructor

THE ASBESTOS INSTITUTE


8102 North 23rd Avenue

Suite A

Phoenix, AZ 85021-4962

602-864-6564

THE ASBESTOS INSTITUTE



Certifies that

has attended the EPA approved course

**AHRA Refresher
Management Planner**

January 5, 2007

and successfully passed the competency exam

Date of Examination: January 5, 2007

Date of Expiration: January 5, 2008

[Signature]

 Director

[Signature]

 Approved Instructor

THE ASBESTOS INSTITUTE
 8102 North 23rd Avenue
 Suite A
 Phoenix, AZ 85021-4962
 602-864-6564